C. K. McCey Vice President Vogtle Project Southern Nuclear Operating Company, Inc. 40 Inverness Center Parkway P.O. Box 1295 Birmingham, Alabama 35201

Tel 205.992.7122 Fax 205.992.0403



February 12, 1998

Docket Nos. 50-424, 425

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555

LCV-1167

Ladies and Gentlemen:

VOGTLE ELECTRIC GENERATING PLANT LICENSEE EVENT REPORT 1-98-2 SOLID STATE PROTECTION SYSTEM SURVEILLANCE TESTING INADEQUATE

Southern Nuclear Operating Company hereby submits a licensee event report for Vogtle Electric Generating Plant in accordance with 10 CFR 50.73 concerning a condition that was determined to be reportable on January 22, 1998.

Please contact this office if you have any questions.

Sincerely,

C. K. McCoy

CKM/TEW/afs

Enclosure: LER 1-98-2

Mr. J. B. Beasley, Jr.
Mr. M. Sheibani
NORMS

U. S. Nuclear Regulatory Commission
Mr. L. A. Reyes, Regional Administrator

Mr. D. H. Jaffe, Senior Project Manager, NRP.

Mr. J. Zeiler, Senior Resident Inspector, Vogtle

TERRY!

9802190144 980212 PDR ADOCK 05000424 PDR

U.S.NUCLEAR REGULATORY COMMISSION (4-95) LICENSEE EVENT REPORT (LER)										APPROVED OMB NO. \$180-0104 EXPIRES: 04/30/99 ESTIMATI, "BURDEN PER RESPONSE TO COMPLY WITH TH MANDATO, INFORMATION COLLECTION REQUEST: 50.0 HR REQUIRED																		
Vogtle Electric Generating Plant - Unit 1											DOCKE					creven	**************************************	F	-	PAGE	434							
CONTRACTOR STATE	Ele	ctric	(i	enera	itin	g Pla	ınt -	Un	it 1	are sense and the			MINESC REPUBLISHED	A MARKETON A		5	0	0	0	4	2	4	1 0)F	4	1		
SOLII	D ST	ATI	P	ROT	EC	TIO	NS	YS	TEM		EILL		TES	IIN	GINA	DE	OL	JA	TE		****			AL NOTE OF	_	-		
CANADA MARKATANA PARA	DAY	YEAR	+	YEAR	TERRI	BEOUT		(e)	REVISION MARKER	MONTH	DAY	YEAR	FACILITY	YNAN	OTHER FACILITIES INVOLVED (8) ME DOCKET NUMBER(5)													
-		-	†		-		DER	-	I MARKER						GP.J	INI	ГЭ			- 2				14	121	4		
01.		01.	. 1	010	-	010		-	010	0.10	1 10	0.10	FACILITY	Y NAN	AE	'de Stabus	-	enero e e							-	*		
0 1 2	matering	91	4			0 0	in the latest the late	-	Acceptance of the same	0 2	the second second	9 8	_	-	PERMIT	NAME AND ADDRESS OF THE OWNER, TH	minor		-	0	5	0 0	0 0					
	OPERATING THIS REPORT IS SUBMITTED PURSUA					URBUANT							3(a)(2)(i)						3(a)(2)	(viii)	-	*****	-					
POWER	POWER LEVAIL (10) 1 0 0			20.2203(a)(1)											73(a)(2)(ii)							50.73(a)(2)(x)						
LEVEL (10)				A STATE OF THE PARTY OF THE PAR					20.2035(a)(3)(ii) 50.75					3(a)(2)(iii)	5(a)(2)(iii)						73.71							
20.2203(a)(2)(ii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii)				(a)(2)(iii)	(Hi) 50.36(c)(1)					(1) 50.7			3(a)(2)(v) 3(a)(2)(v) 3(a)(2)(vii)						-	7		tract below						
CALMINICANUS NASA	MACRICAN PA	HOMES A	eal.	ARCOR STURM	NOMES OF THE PERSON	MALE SURVEYOR	PRODUKEY:	SANGRANGE	NOME OF TAXABLE PARTY.	ACTUAL PROPERTY AND	ACCUSED NAMED IN	ACT FOR TH	IIS LER (1	-	E SECTION STREET	NO SECURE	, NATHORN	WATER STORY	menced	Terrore	MANAGE	NUMBER 186	enseene	DOMESTIC .	TOTAL DESIGNATION NO.	MI		
NAME	Meh	ndi S	hei	bani,	N	ıclea	r Sa	fety	and C	Compl	iance						ARE	A CC	DOE	-		6		**********	101	9		
						C	OMPL	ETE O	NE LINE F	OR EACH	COMPON	ENT FAILU	RE DESCR	RIBED	IN THIS RE	PORT	(13)	NAMES AND	reserved.	or mentals	mentani.	manus mon		nodratina resources	dennice of co	-		
JAUSE	SE SYSTEM		SYSTEM		CO	MPONE	VT	MANU	FACTU	RER		PRTABLE NPRDS			CAUS	SE	SYSTEM	CC	OMPO	MENC	IT	MAN	IUFAC	TURE	R		PRDS	
	П		1		上	L	1	1											Ц	1								
NO. LYANGESCHICK			1		_			1		THE PERSON NAMED IN		Page 100 East Winter								1	1	1			-	-		
-T	-	****	-	-	-	SUPP	LEME	NYAL	REPORTE	XPECTED	(14)	EXPECT SUBMISS						-	MONT	н	DAY	YEA	R					
YES (M	YES (M yes, complete EXPECTED SUBMISSION DATE)								X NO				DATE (1						1		1	1						

On November 14, 1997, it was found that solid state protection system (SSPS) functions may have been inadequately tested. As a precaution, changes were made to the appropriate procedures and testing of circuits for the three functions was completed in both Unit 1 and Unit 2.

Following receipt of information from the vendor, discussions held on January 22 and 23, 1998, determined that some of the untested circuits are solely relied on to initiate a feedwater isolation under certain conditions. Therefore, the failure to previously test these functions represents inadequately performed surveillance testing.

The cause of this event is that the original testing design was inadequate because it did not fully verify proper operation of the SSPS logic circuits. When surveillance testing procedures were initially written during plant startup, these procedures were also deficient.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)				
		YEAR SEQUENTIAL REVISION	PAGE (3)				
Vogtle Electric Generating Plant - Unit 1		NUMBER NUMBER					
rogue Dicette Generating Flant - Clift 1	0 5 0 0 0 4 2 4	9 8 - 0 0 2 - 0 0	12 OF 14				

A. REQUIREMENT FOR REPORT

This report is required per 10 CFR 50.73 (a)(2)(i) because the unit operated in a condition prohibited by the Technical Specifications (TS) when surveillance testing was inadequate.

B. UNIT STATUS AT TIME OF EVENT

At the time of the discovery of this event, both Unit 1 and Unit 2 were operating in Mode 1 (power operation) at 100 percent of rated thermal power. Other than that described herein, there was no inoperable equipment that contributed to the occurrence of this event.

C. DESCEJPTION OF EVENT

On November 14, 1997, an instruments and controls assistant team leader (ATL) received E-mail information of a condition that existed at another nuclear plant. This condition concerned inadequate surveillance testing of Westinghouse type solid state protection system (SSPS) functions. Specifically, these were: source range automatic P-10 block, feedwater isolation (FWI) on P-14 steam generator (SG) high-high level, and FWI on safety injection. The ATL believed that testing of these same functions at the Vogtle Electric Generating Plant's SSPS may also be inadequate. The control room was notified at 1500 EST. As a precaution, changes were made to the appropriate procedures and testing of circuits for the three functions was completed in both Unit 1 and Unit 2 by 1744 EST.

Westinghouse was contacted and plant personnel were advised that a letter would be issued to explain this issue. On January 6, 1998, Westinghouse Technical Bulletin #ESBU-TB-97-09-R0 was received. Although the issue was clarified to a degree, it remained unclear if the failure to test these functions represented inadequate surveillance testing. Additional guidance was received at a Westinghouse owners group meeting on January 13 and 14, 1998. During follow-up discussions held on January 22 and 23, 1998, it was determined that at least some of the untested circuits are relied on to provide FWI signals under certain conditions. Therefore, the failure to test these functions represents inadequately performed surveillance testing.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

PACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)											
North Floris Constitut Plant Hair 1		YEAR SEQUENTIAL REVISION NUMBER											
Vogtle Electric Generating Plant - Unit 1	0 5 0 0 0 4 2 4	918 - 01012 - 010	13 OF 14										

ace is required, use additional copies of NRC Furm 366AX(17)

D. CAUSE OF EVENT

The cause of this event is that the original testing design was inadequate because it did not fully verify proper operation of the SSPS logic circuits. When surveillance testing procedures were initially written during plant startup, these procedures were also deficient.

E. ANALYSIS OF EVENT

Two of the three untested circuits represent inadequately performed surveillances as described below:

- 1) Upon receipt of a safety injection (SI) signal, a unique FWI signal would not be sent if the untested circuit failed in both trains. However, SI also initiates a P4 reactor trip signal, and this P4 signal will, in turn, initiate the FWI signal. Therefore, the FWI would occur, but at a slightly later time. Per the Westinghouse Technical Bulletin #ESBU-TB-97-09-R0, this additional time delay does not have significant impact on the results of the transient analysis.
- 2) Upon receipt of a SG high-high water level while less than 50 percent reactor power, a FWI signal would not be sent if the untested circuit failed in both trains. However, the main feedwater pumps would stop, effectively negating the failure of the main feedwater valves to isolate.

Based on these considerations, there has been no adverse affect on plant safety or on the health and safety of the public as a result of this event.

F. CORRECTIVE ACTION

- 1) Procedures were changed and testing of the circuits for the three functions was completed.
- 2) The SSPS universal logic boards were evaluated and no similar conditions of untested circuits were found.

MR				
66-1				

U.S.NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)				DOCKET NUMBER (2)							LER NUMBER (6)											(8)
Vogtle Electric Generating Plant - Unit 1										YEAR	1		SEC	UEN	R		REVI	SION				
		5	10	0	10	14	12	14	9	18			0	0	2	-	0	0		14	OF	14

TEXT (If more space is required, use additional copies of NRC Form 365A)(17)

G. ADDITIONAL INFORMATION

- Failed Components:
 None
- 2) Previous Similar Events: None
- Energy Industry Identification System Code: Solid State Protection System - JG