

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) **Callaway Plant Unit 1** DOCKET NUMBER (2) **050004831** PAGE (3) **CF 04**

TITLE (4) **ESF Actuations Due to Spurious Radiation Monitor Signals**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
03	18	86	86	006	000	04	17	86		050000
										050000

OPERATING MODE (9) **6** THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

POWER LEVEL (10) <b>01010</b>	20.402(b)	20.405(i)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)
	20.405(a)(1)(i)	50.38(c)(1)		50.73(a)(2)(v)	73.71(c)
	20.405(a)(1)(ii)	50.38(c)(2)		50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)	
	20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)	
	20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME **John D. Blosser - Assistant Manager, Operations & Maintenance** TELEPHONE NUMBER **314 676-1819**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPPDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPPDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO  EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

Between the dates of 3/18/86 and 4/6/86, four incidents of unplanned Engineered Safety Feature (ESF) actuations occurred with the plant in Mode 6, Refueling, and Mode 5, Cold Shutdown.

The first resulted in a Fuel Building Ventilation Isolation, Containment Purge Isolation, and Control Room Ventilation Isolation (CRVI), and was caused by ESF cabinet cleaning. An I&C technician inadvertently loosened the connector which provides a cross-train trip resulting in a single train actuation. I&C technicians have been informed of this incident and cautioned to use care during cleaning evolutions.

The other three incidents resulted in CRVIs and were caused by spurious signals generated during gas sampling evolutions. Based on a review of previous CRVIs, directions have been given to appropriate personnel to place these monitors in bypass when performing evolutions that have historically resulted in spurious signals.

Since these incidents were not caused by actual radiation levels, the public health and safety were not endangered.

8604240175 860417  
PDR ADOCK 05000483  
S PDR

LEW  
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Callaway Plant Unit 1	DOCKET NUMBER (2)  0   5     0   0   4   8   3	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8   6	-   0   0   6	-   0   0	0   2	OF

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Between the dates of 3/18/86 and 4/6/86, four incidents of unplanned Engineered Safety Feature (ESF) actuations occurred.

The first two incidents occurred on 3/18/86 while in Mode 6 (Refueling). The first incident resulted in an 'A' Train Fuel Building Ventilation Isolation (FBVI), Containment Purge Isolation (CPI), and Control Room Ventilation Isolation (CRVI). At the time of the incident, I&C technicians were performing scheduled cleaning in a 'B' Train ESF cabinet<sup>(1)</sup> as part of a preventative maintenance program. At 0136 CST, the 'A' Train FBVI, CPI, and CRVI occurred due to a connector loosened during the cleaning in the cabinet. The connector, discovered unlocked and loose during subsequent troubleshooting, carries a cross-train trip signal from the 'B' Train ESF cabinet to the 'A' Train ESF cabinet.

Evidence which supports the conclusion that the loose connector caused the actuation is that the computer points associated with field inputs to the ESF Actuation System did not alarm. This implies that the actuation originated internal to the ESF cabinets. Also, during troubleshooting the connector was moved from a locked to an unlocked position which resulted in an 'A' Train FBVI, CPI, and CRVI and the same alarms received during the previous 0136 actuation. This troubleshooting was performed on 3/19/86.

The ESF actuation signals were reset at 0155 on 3/18/86 after the actuation was determined to be spurious and not the result of abnormal radiation levels. After identifying the loose connector as the probable cause, all connectors were verified to be in a locked position in the ESF cabinets. To prevent recurrence, I&C technicians were cautioned to use care during cleaning evolutions and a precaution statement was added to the preventative maintenance work authorizing document.

The second incident occurred at 0253 on 3/18/86 while restoring a containment atmosphere radiation monitor<sup>(2)</sup> to service and resulted in a CPI and CRVI signal. However, when the actuation signal occurred, the safeguard line-up was already present from the previous actuation. Flow to the containment atmosphere radiation monitor had been isolated for Local Leak Rate Testing (LLRT) of containment isolation valves<sup>(3)</sup> downstream of the radiation monitor. At 0228, during restoration from the LLRT with the isolation valves still closed, the sample pump for the radiation monitor was started but automatically shut down due to a low vacuum resulting from the valves being closed.

Health Physics technicians were contacted to troubleshoot the problem, but before troubleshooting began, the CPI and CRVI initiated by the containment atmosphere radiation monitor occurred. The sample pump was restarted, the radiation monitor returned to service, and the CPI and CRVI signals were reset at 0334. Although the abnormal line-up cannot

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Callaway Plant Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 4 8 3	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 6	- 0 0 6	- 0 0	0 3	OF 0 4

TEXT (If more space is required, use additional NRC Form 365A's) (17)

be conclusively identified as the cause of the event, it is believed the unstable flow condition was a principle contributor.

Corrective actions include 1) a review of the CRVIs experienced at Callaway to determine if additional actions can practicably be taken to reduce the frequency of these occurrences and 2) directing Operations personnel to place radiation monitors in bypass if the monitor (including sample pump and valves) is to be placed in other than its normal configuration. Operations Department Night Orders were issued on 4/6/86 to inform the Operators to place the radiation monitors in bypass.

The third and fourth incidents occurred at 2113 on 4/1/86 and at 1330 on 4/6/86, respectively, while in Mode 5 (Cold Shutdown) and resulted in CRVIs. Each CRVI occurred when the sample pump for a Control Room HVAC (Heating, <sup>(4)</sup>Ventilation, and Air Conditioning) radiation monitor GK-RE-05, was stopped for replacement of filter media. Prior to each actuation, the filter media was <sup>(4)</sup>replaced for the redundant Control Room HVAC radiation monitor GK-RE-04 <sup>(4)</sup> without any abnormal conditions noted. After each actuation, I&C technicians performed troubleshooting of the monitor and returned it to service without observing any additional abnormal behavior.

The root cause of these spurious actuations is believed to be due to a fault in the vacuum sensing circuitry in the sampling line. This circuitry sends a signal to the alarm/protection circuitry to correct the output signal of the radiation detector for the density of the sample gas. It is believed a faulty vacuum transducer <sup>(5)</sup> in this circuitry resulted in a spurious signal during pressure changes in the sampling line, i.e., stopping the sample pump. The resultant spurious signal coupled with the increased sample activity, due to the decrease in vacuum and increase in gas density, could result in a signal of sufficient magnitude to initiate the ESF actuations.

Further testing required to verify the vacuum transducer as the cause of these actuations is pending receipt of a replacement transducer. The corrective action taken to prevent recurrence is to place the Control Room HVAC radiation monitor (as well as other radiation monitors that initiate protective actions) in bypass, if the monitor is to be placed in other than its normal configuration. Operations Department Night Orders were issued on 4/6/86 to implement this corrective action.

Additionally, the review conducted of previous CRVIs indicated that further preventive measures could be taken to reduce the probability of spurious CRVIs, CPIs, and FBVIs. This would involve removing the downscale trips from the radiation monitors that provide protective actions. Although unrelated to these four events, such an action would

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Callaway Plant Unit 1	DOCKET NUMBER (2)  0   5   0   0   0   4   8   3   8   6   -   0   0   6   -   0   0   0   4   OF   0   4	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

have prevented several previously reported actuations. An evaluation of the feasibility of the elimination of the downscale trip is being conducted under Request for Resolution (RFR) 2214. It is noted that downscale alarms already exist for these radiation monitors.

These incidents did not threaten the public health and safety since the actuations were spurious and not the result of actual abnormal radiation levels.

Previous occurrences: none from these specific causes, however the review included these Callaway Licensee Event Reports concerning previous CRVIs, CPIs, and/or FBVIs: 84-003-00, 84-004-03, 84-011-00, 84-018-00, 84-019-00, 84-025-01, 84-027-00, 84-032-00, 84-036-00, 84-062-00, 84-063-00, 84-067-00, 85-003-01, 85-004-01, 85-006-00, 85-008-00, 85-014-00, 85-023-00, 85-050-00, 86-001-00, and 86-005-00.

Footnotes

The system codes below are from IEEE Standard 805-1983 and the component codes below are from IEEE Standard 803A-1983.

- (1) System - JE, Component - CAB
- (2) System - IK, Component - RE
- (3) System - IK, Component - ISV
- (4) System - IL, Component - RE
- (5) System - IL, Component - TD



UNION ELECTRIC COMPANY

Callaway Plant

April 17, 1986

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

ULNRC-1297

Gentlemen:

DOCKET NUMBER 50-483  
CALLAWAY PLANT UNIT 1  
FACILITY OPERATING LICENSE NPF-30  
LICENSEE EVENT REPORT 86-006-00  
ESF ACTUATIONS DUE TO SPURIOUS RADIATION MONITOR SIGNALS

The enclosed Licensee Event Report is submitted pursuant to 10 CFR 50.73(a)(2)(iv) concerning several instances of Engineered Safety Features Actuations initiated by spurious signals from radiation monitors.

*G. L. Randolph*  
G. L. Randolph  
Manager, Callaway Plant

*B. J. S. Quirk*  
JDB/TPS/JWK/drs  
Enclosure

cc: Distribution attached

*IER2*  
*11*

cc distribution for ULNRC-1297

Mr. James G. Keppler  
Regional Administrator  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

American Nuclear Insurers  
c/o Dottie Sherman, Library  
The Exchange Suite 245  
270 Farmington Avenue  
Farmington, CT 06032

Mr. J. H. Smith  
Bechtel Power Corporation  
SNUPPS Project  
15740 Shady Grove Road  
Gaithersburg, MD 20877-1454

Mr. Nicholas A. Petrick  
Executive Director, SNUPPS  
5 Choke Cherry Road  
Rockville, MD 20850

NRC Resident Inspector  
D. F. Schnell (400)  
R. J. Schukai (470)  
S. E. Miltenberger  
J. F. McLaughlin  
J. E. Davis (Z40LER)  
(Z40LER) (w/c)  
D. W. Capone/R. P. Wendling (470)  
F. D. Field (470)  
A. P. Neuhalfen  
A. C. Passwater/D. E. Shafer/D. J. Walker (470)  
G. A. Hughes  
Z40.01 (QA Record)  
J. M. Price  
J. D. Blosser  
W. R. Robinson  
M. E. Taylor  
H. Wuertenbaecher, Jr. (100)  
S. L. Auston (470) (NSRB)  
J. D. Schnack  
GLR Chrono  
3456-0021.6  
3456-0260  
Z40ULNRC  
G56.37  
N. Date (Sandra Auston) (470)

Manager, Electric Department  
Missouri Public Service Commission  
P. O. Box 360  
Jefferson City, MO 65102

Mr. O. Maynard  
Kansas Gas and Electric Company  
P. O. Box 208  
Wichita, KS 62701

Records Center  
Institute of Nuclear Power Operations  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, GA 30339

Mr. Paul O'Connor  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Mail Stop P-316  
7920 Norfolk Avenue  
Bethesda, MD 20014

Mr. Merlin Williams  
Supt. of Regulatory Quality &  
Administrative Services  
Kansas Gas and Electric Company  
P. O. Box 309  
Burlington, KS 66839