

## LICENSEE EVENT REPORT (LER)

APPROVED OMB NO. 3180-0104  
EXPIRES: 6/3/85

FACILITY NAME (1)

INDIAN POINT UNIT 2

DOCKET NUMBER (2)

050000247

PAGE 3

1 OF 014

TITLE (4)

Inadequate Alarm Response Procedure for High Energy Line Break

EVENT DATE (8)			LER NUMBER (8)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME		DOCKET NUMBER (2)	
03	20	86	86	010	00	04	21	86			050000	
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. Check one or more of the following: (11)									
POWER LEVEL (10) 0100			20.402(a)			20.406(a)			60.73(a)(2)(iv)			73.71(a)
			20.406(a)(1)(i)			60.36(a)(1)			60.73(a)(2)(iv)			73.71(a)
			20.406(a)(1)(ii)			60.36(a)(2)			60.73(a)(2)(iv)			OTHER (Specify in Address below and in Text, NRC Form 308A)
			20.406(a)(1)(iii)			60.73(a)(2)(i)			60.73(a)(2)(iv)(A)			
			20.406(a)(1)(iv)			60.73(a)(2)(ii)			60.73(a)(2)(iv)(B)			
20.406(a)(1)(v)			60.73(a)(2)(iii)			60.73(a)(2)(v)						

LICENSEE CONTACT FOR THIS LER (12)

NAME

MICHAEL BLATT

TELEPHONE NUMBER

AREA CODE

914 512 6-1511217

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
D				N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)

X

NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 words, i.e., approximately fifteen single-space typewritten lines) (16)

A review of the High Energy Line Break Analysis for Indian Point Unit 2 revealed a procedural inadequacy regarding a line break in the piping penetration area. A procedure change was subsequently implemented which addresses appropriate operator response necessary to assure that the design basis of the analysis is met.

The public health and safety were not affected.

IE22  
Y18604250260 860421  
PDR ADOCK 05000247  
S PDR

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMS NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)  INDIAN POINT UNIT 2	DOCKET NUMBER (2)  0 5 0 0 0 3 4 7 8 6	LER NUMBER (5)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		— 0 1 1 0	— 0 0 0 2	OF 0 4			

TEXT (If more space is required, use additional NRC Form 266a) (17)

## Plant and System Identification:

Westinghouse 4-loop Pressurized Water Reactor: 900 MWe

## Identification of Occurrence:

A review of Significant Occurrence Report 86-118 determined that an alarm response procedure inadequacy existed.

Event Date: March 20, 1986

Reportability Determination Date: March 20, 1986

Report Due Date: April 21, 1986

Past Similar Occurrence: LER 82-010-00

## Description of Occurrence:

The reactor was in the hot shutdown condition. There were no inoperable structures, components or systems which contributed to this event.

In the course of inquiries regarding the design basis of the Primary Auxiliary Building (PAB) Piping Penetration Area a procedural inadequacy was discovered.

Our submittal of April 9, 1973 stated that temperature detectors will be installed in the Piping Penetration Area of the PAB. Three detectors are in place and provide a common alarm in the Central Control Room (CCR) when the temperature in the subject region of the PAB reaches 120°F. Even though we do not expect the temperature in the area to reach a point where equipment damage could occur, as a conservative measure the High Energy Line Break (HELB) analysis credits operator action as being the reason that no safeguards equipment would be affected by a HELB in the Piping Penetration Area. Thus, prompt operator action is required

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OIR NO. 3150-0104

EXPIRES 8/31/95

FACILITY NAME (1)

INDIAN POINT UNIT 2

DOCKET NUMBER (2)

LER NUMBER (3)

PAGE (3)

YEAR SEQUENTIAL REVISION  
NUMBER NUMBER NUMBER

0 5 0 0 0 2 4 7 8 6 - 0 1 0 - 0 0 0 3 OF 0 4

TEXT (If more space is required, use additional NRC Form 366a) (17)

to assure isolation of a ruptured line. The Alarm Response Procedure (ARP) for the subject alarm actuation was determined on March 20, 1986 not to be, in and of itself, adequate to assure prompt operator response to a HELB in the Piping Penetration Area, were one to occur.

#### Analysis of Occurrence:

This occurrence was determined to be a reportable event because the procedural inadequacy could have delayed the intended operator action in response to an alarm from the temperature detectors in the Piping Penetration Area.

Prompt operator action to isolate a postulated HELB in the PAB Piping Penetration Area would be assured in most cases via response to plant parameter changes and other alarm actuations which would occur in addition to the high temperature alarm. A postulated HELB in this area is expected to heat up the environment sufficiently to actuate the associated alarm. The ARP addressing the alarm did not provide the guidance necessary to properly identify and isolate the HELB. However, with the exception of a blowdown line rupture downstream of the flow control throttle valve, a rupture of high energy line in this area would disturb plant operating parameters so that the ruptured line could be promptly identified and isolated from the CCR.

A blowdown line rupture downstream of the flow control throttle valve is expected to heat up the Piping Penetration Area and actuate the associated alarm. However, such a rupture would not disturb plant operating parameters quickly enough to allow for isolation of the line in a timely manner as intended in our April 9, 1973 submittal. The ARP was therefore adjudged to permit the design basis of our HELB analysis to be exceeded. In our fire protection analysis for Appendix R to 10 CFR 50, the piping penetration area is circumvented by the Alternate Safe Shutdown System (ASSS). Thus, given potential loss of equipment in this area due to a HELB, the ASSS can be used in the same manner as for a design basis fire. In our April 9, 1973 submittal we assumed the use of Class I equipment to achieve safe shutdown. Even though portions of the ASSS are not required to be Class I, the ASSS was available to safely shutdown the plant.

Since the ARP was deemed inadequate, there was less than reasonable assurance that prompt operator action would have been taken as intended in the HELB analysis contained in our April 9, 1973 submittal.

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED LER NO. 3190-0104

EXPIRES: 8/31/95

FACILITY NAME (1)

INDIAN POINT UNIT 2

DOCKET NUMBER (2)

05000247

LER NUMBER (3)

YEAR SEQUENTIAL REVISION

86 010 00

PAGE (3)

04 OF 04

TEXT (If more space is required, use additional NRC Form 366a) (17)

## Cause of Occurrence:

The Subject Alarm Response Procedure, "Panel SMF CCR Safety Injection, Rev. 0" was issued on October 15, 1984. The scope of the project which prepared this procedure included a commitment search of documents dated January 1979 through October 1983. This procedure preparation effort thus did not consider commitments made in the April 9, 1973 submittal.

## Corrective Actions:

A procedure change was issued to the subject ARP. This change provides correct explicit information to the operator upon receipt of a high temperature alarm condition in the PAB Piping Penetration Area. The ARP, as amended, is adequate for the postulated conditions in our April 9, 1973 submittal.

John D. O'Toole  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003  
Telephone (212) 460-2533

April 21, 1986


Re: Indian Point Unit No. 2  
Docket No. 50-247  
LER-86-010-00

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Sirs:

The attached Licensee Event Report LER-86-010-00 is hereby submitted in accordance with the requirements of 10CFR Part 50.73.

Very truly yours,



attach.

cc: Dr. Thomas E. Murley,  
Regional Administrator - Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue

Senior Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, New York 10511

TE22  
11