LICENSEE EVENT REPORT (LER)								U.S. N	U.S. NUCLEAR REGULATORY COMMISSION APPROVED OME NO. 3150-0104 EXPIRES 8/31/86						
FACILITY	-	1)									DOCKET NUMBE	R (2)		FAC	181 30
Pilgrim Nuclear Power Station Unit No. 1								0 5 0 0	0 5 0 0 2 9 3 1 OF 0						
Mai	n Ste	am L	ine I	solation	While H	React	or Shi	itdow	1						
EVI	ENT DATE	(15)			(6)	R	PORT DAT	Æ (7)		OTHE	A FACILITIES INV	DLVED	(8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIA	L AEVEROP	MONTH	DAY	YEAR		PACILITY N	AMES	000	ET NUMBER	4(\$)	
												01	51010	101	11
0 3	2 2	8 6	8 6	- 0 0 7	- 010	0 14	2 2	8 6				0	51010	101	
OPE	RATING		THIS REP	ORT IS SUBMITT	ED PURBUANT	TO THE	REQUIREM	INTE OF 1	0 CFR \$ 10	Check one or more	at the fallowing) (11)			
MR	206 (8)	IN	20.4	02(6)	-	20.406	Hel		X	50.73(a)(2)(iv)		П	75.71(b)		
LEVE (10)	0	0,0	20.4	08(a)(1)(i)	-	50.360	a)(1)		-	80,73(a)(2)(v)		H	73.71(e)		
			20.4	06(a)(1)(iii)	F	80.736	s)(2)(i)		H	60.73(a)(2)(viii	(A) OTHER ISO			Text, NRC Form	
			20.4	05(a)(1)(lv)		80,736	a)(2)(8)			80.73(a)(2)(vill	(8)				
			20,4	08(a)(1)(v)		80.734	a)(2)()H)			50.73(e)(2)(x)					
NAME						LICENSEE	CONTACT	FOR THIS	LEM (12.			781.85	NONE NUM		
Daul	Uami	1+00	C.	Diant	Enginoo						AREA CODE	T			
raui	riam	i i con	- 51	. Flanc	cingineer						6117	71	4 16 1 -	1719	1010
				COMPLET	ONE LINE FO	R EACH C	OMPONENT	FAILURE	DESCRIBE	D IN THIS REPO	RT (13)				
CAUSE	SYSTEM	COMPO	ONENT	MANUFAC TURER	TO NPROS	E		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REI	O NPRDS		
	1	1	1	111	1	ļ				111	111				
	1	1		1.1.1						1.1.1					
				SUPPLEN	IENTAL REPOR	TEXPECT	'ED (14)	-	1				MONTH	DAY	YEAR
X YES (If you, complete EXPECTED SUBMISSION DATE)				E)	NO				DATE (15) 016		016	816			
	On 3/ line) event annur Notwi proba Corre engir conta Prote Imple expla time] ident	22/8) occ . R nciat hbly heeri heer	5 at urred oot ca ion o andin was th e act ng su for th n Sys ation on of ot ca d dur	1739 hou The r ause ana r comput g the co he resul ion is t port re he Prima tem (RPS of this the cau use anal ing this	rs a Gro eactor w lysis wa er print mplication t of a so o contin quests h ry Conta) be rev change se of so ysis. T event.	bup On was in as cont tout of tout of	ne pri n the mplica explar the ar ous re ith re been s nt Ise from xpecte r ever were	imary cold ated h nation nalys: eactor obt ca blatic latic norm ed to nts sh	conta shutd by the of w is to high uuse a ted r bn Sys ally provi nould quipme	inment i own cond fact th hat caus date ind water 1 nalysis. equestir tem (PCI closed" de a com they occ nt or co	solation lition at at there ed the is licates th evel sign In adding that th S) and th to "norma puter pri- cur thus a amponent f	(PC the was ola hal. tion e co in R illy into allo ail	IS main time no tion. the is n, two ompute eactor open" ut wing fures	n stea of th olation r	am e on

IE 22

8604290092 860422 PDR ADOCK 05000293 S PDR

NRC Form 366 (9-83)

. . .

1

NRC Ferm 306A (9-83)	LICENSEE EVENT REPOR	U.S. NUCLEAR REG	COMB NO 3150-0104		
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMB	ER (6)	PAGE (3)
			YEAR SEQUER	TIAL MEVISION	il

c | 5 | 0 | 0 | 0 ! 2 | 9 | 3 | 8 | 6 | - 0 | 0 | 7 |

00 012 010 13

Event

Pilgrim Nuclear Power Station Unit No.1

TEXT /# mane space is required, use additional MRC Form 3084's) (17)

On 3/22/86 at 1739 hours a Group One primary containment isolation occurred resulting in closure of the eight main steam line isolation valves (MSIV's) and the main steam inboard drain valve. The other three Group One isolation valves include the main steam outboard drain valve and the two reactor water sample valves. When the isolation occurred the outboard drain valve did not close and the two reactor water sample valves were already closed. The fact that the outboard drain valve did not close is by design depending on the signal which initiates the isolation.

Unexpectedly there was no annunciation or computer printout of what had initiated the isolation. At the time of the event the reactor was in the cold shutdown condition.

Cause

The cause of this event is believed to be a spurious signal. Root cause analysis was complicated by the fact that there was no annunciation or computer printout explanation of what had caused the isolation. Notwithstanding this complication, the analysis to date has provided a review of the seven inputs that initiate a Group One isolation. Six of the inputs were eliminated for various logical reasons. The remaining input, reactor high water level, was determined to be the most likely cause of the isolation signal.

The analysis indicates that the "C" and "D" channels of the reactor high water level isolation signal originate in indication switches located on instrument rack C2206. Activation of the "C" and "D" channels will, by design, close the eight MSIV's and the inboard drain valve as was experienced on 3/22/86. Since there were no reactor water level excursions when the event occurred it is believed that the isolation resulted from a spurious signal originating in the PCIS circuitry for reactor water level.

Historically the reactor water level switches have been sensitive to vibration (e.g. would sometimes trip when inadvertently bumped during work in or around instrument rack C2206). However, during this event there was apparently no work in progress around rack C2206 that could have resulted in the water level switches or sensing lines being bumped. A previous LER (86-002) discusses the sensitivity of other switches and sensing lines located on rack C2206.

The redundant instrument rack (C2205) was out of service when the event occurred in support of repair work on a reactor water level instrumentation line (ref. LER 86-006 for detail of that work). Therefore the redundant rack was ruled out as a source of the isolation signal.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSIO APPROVED OMB NO. 3150-0104

EXP	IRES	8/31	/85		

FACILITY NAME (1)	DOCKET NUMBER (2)		R NUMBER (6)	PAGE (3)							
Pilgrim Nuclear Power Station	10 2 3 6 8		YEAR		SEQUENTIAL NUMBER						
Unit No. 1	0 15 10 10 10 21	9 3	8 6	-	0 0 7	_ 0	010	013	OF	013	5

T (if more space is required, use additional NRC Form 386A's) (17)

Corrective Action

RC Form 366A

Root cause analysis of this event continues. The results of that analysis will be provided in an update to this LER. In addition, two Engineering Support Requests (ESR's 86-116 and 86-118) have been submitted requesting that the computer contacts for Primary Containment Isolation System (PCIS) and Reactor Protection System (RPS) alarms be changed from "normally closed" to "normally open". Implementation of this change is expected to provide a computer printout explanation of the cause of similar events should they occur thus allowing for more timely root cause analysis.

Safety Consequences

The MSIV's are designed to fulfill the following objectives:

- Prevent excessive damage to the fuel barrier by limiting the loss of reactor coolant from the reactor vessel resulting from either a major leak from the steam piping outside the primary containment, or a malfunction of the pressure control system resulting in excessive steam flow from the reactor vessel.
- Limit the release of radioactive materials by closing the nuclear system process barrier in case of a gross release of radioactive materials from the fuel to the reactor cooling water and steam.
- Limit the release of radioactive materials by closing the primary containment barrier in case of a major leak from the nuclear system inside the primary containment.

Since this event would not have prevented the fulfillment of the above stated objectives and since the reactor was in the cold shutdown condition when the event occurred, the consequences of this event were determined to be not significant. Implications of this event are pending completion of root cause analysis and will be discussed in the update to this report. There were no equipment failures identified during this event. Therefore discussion of available redundant equipment is not applicable to this LER. BOSTON EDISON COMPANY 800 BOYLSTON STREET BOSTON, MASSACHUSETTS 02199

WILLIAN D. HARRINGTON

April 22, 1986 BECo Ltr. #86-048

Document Control Desk U.S. Nuclear Regulatory Commission Washington, D.C. 20555

> Docket No. 50-293 License No. DPR-35

Dear Sir:

The attached Licensee Event Report 86-007-00, "Main Steam Line Isolation While Reactor Shutdown" is hereby submitted in accordance with the requirements of IOCFR50.73.

If there are any questions on this subject, please do not hesitate to contact me.

Respectfully submitted,

W. D. Harrington

PJH/vp

Enclosure: LER 86-007-00

xc: Dr. Thomas E. Murley Regional Administrator, Region I U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

Standard BECo LER Distribution

