N., C For (9-83)	m 366				LIC	ENSEE EVE	NT RE	PORT	(LER)		PROVED ONE XPIRES 8/31/85	
FACILIT	Y NAME (1)								DOCKET NUMBER	(2)	PAGE (3)
H. H	or other designs in the second s	oinson	n Uni	t 2						0 5 0 0	101216 B	1 OF 01
		Crip H	Resul	ting From	a Turbi	.ne Generat	or Lo	ckout				
	ENT DATE			LER NUMBER	(6)	REPORT DATE			OTHER	FACILITIES INVO	LVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL	REVISION NUMBER	MONTH DAY	YEAR		FACILITY NA	MES	DOCKET NUME	
											0 5 0	
0 3	2 4	8 6	8 6	0 1 0	00	0 4 2 2	8 6	1.10			0 15 10 1	0 1 0 1 1 1
	ERATING				D PURSUANT 1	20.405(c)	NTS OF 1	D CFR &: (0		of the following) (1	1) 73,71(b)	
POWE				405(a)(1)(i)		50.38(c)(1)		X	50.73(a)(2)(iv) 50.73(a)(2)(v)		73.71(c)	
LEVE (10)		110	20.	405(a)(1)(ii)		50.38(e)(2)			50.73(a)(2)(vii)			Specify in Abstract d in Taxt, NRC Form
				405(a)(1)(iii)	-	50.73(a)(2)(i) 50.73(a)(2)(ii)			50.73(a)(2)(viii) 50.73(a)(2)(viii)		366A)	
				606(a)(1)(v)		50.73(a)(2)(iii)			50.73(a)(2)(x)		1.1.1.1.1.1.1	
NAME			_		L	ICENSEE CONTACT	FOR THIS	LER (12)			TELEPHONE N	11860
NAME										AREA CODE	TELEPHONE N	Jaiden
1	Georg	ge Hor	nma							8 0 3	3 8 3 1	-1415 71
					1	EACH COMPONENT	FAILURE	DESCRIBE	D IN THIS REPO	T	1	1
CAUSE	SYSTEM	COMPO	NENT	MANUFAC- TURER	TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	TO NPADS	
								+		+++++	+	
		11	1		1			1	111	111	- Andrews	
				SUPPLEM	ENTAL REPORT	EXPECTED (14)				EXPECT SUBMISS		TH DAY YEA
YE	S (11 ym, c	ompiete E)	PECTED	SUBMISSION DATE	E)	X NO				DATE		
ABSTRA	CT (Limit	to 1400 spa	ices, i.e., e	oproximetaly fifteen	single-space type	ewritten lines) (16)				-		
Abs	tract											
						was in pro						
				subsequent		erator mot	oring	trip	(generat	tor lockou	it) resul	lting in a
cur	orne	erth	and	sanacdaeu	- LOGGEO							
						ne of the						
						grid. Onc bine gover						
						lear the m					HUL VAL	re not
						owever, th n limit sw						
						trip. The						
		100				ate, that						
par	t of	the g	enera	ator motor	ring tri	p circuit.						
sol	ely f	rom m	legawa	att output	t.							
The	turb	ine g	over	nor valve	shut po	sition lim	it sw	itche	s were re	set to cl	ear with	the
tur	bine	at ra	ted s	speed. Pr	rocedure	s will be	revis	ed to	incorpor	ate the n	lew setpo	oint and
pro	vide	more	spect	ific guida	ance to	the operat	or to	avoi	d a gener	ator moto	ring tri	p.
Add	ition	ally.	the	turbine !	trip log	ic diagram	will	be c	orrected	and licer	sed open	ators wil
						standing o						

8604290216 PDR ADOCK S	860422 05000261 PDR	_
------------------------------	---------------------------	---

IE22

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

US NUCLEAR REGULATORY COMMISSION APPROVED OMB NO 3150-0104

EXPIRES BIST RS

FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)					PAGE 13		
		YEAR	SEQUENTIAL		REVISION NUMBER	ON ER		Π		
H. B. Robinson Unit 2	0 5 0 0 2 6	1 816	-	01110	- 010		012	OF	0 12	

Event Description

RC Form 386A

On March 24, 1986, a unit startup was in progress with the reactor at 10% power. At 1454 hours, the Plant experienced a generator motoring trip (generator lockout) resulting in a turbine trip and subsequent reactor trip.

Unit 2 was being placed online. One of the Generator Output Oil Circuit Breakers (OCB) was closed, connecting Unit 2 with the system grid. Once the OCB is closed, at least one of the shut position limit switches on the turbine governor valves must clear (governor valve not fully shut) within one minute. This feature prevents the turbine generator from motorizing. These limit switches were set such that, with the generator producing as much as 30 megawatts, the motoring trip signal was still present. At least one closed limit switch on the governor should be open once the turbine reaches rated speed. Additional system load was being picked up in a controlled manner to avoid S/G level instabilities incurred at low power levels and to maintain RCS Tave. The turbine governor valves were not opened sufficiently to clear at least one shut position limit switch within one minute of closing the OCB; therefore, a generator motoring trip was received. Plant equipment performed as expected during the event.

Cause

The onshift operators were not aware that the governor valve shut limit switches were part of the generator motoring trip circuit. The turbine generator startup procedure did not address this feature nor was the motoring trip included on the turbine trip logic diagram. It was generally understood that any positive megawatt production would clear the motoring trip.

Corrective Actions

The turbine governor valve shut position limit switches were reset such that at least one limit switch will clear when the turbine reaches rated speed. Maintenance procedures will be revised to incorporate the new setpoint, and startup procedures will be revised to provide more specific guidance to the operator to avoid a spurious generator motoring trip.

Additionally, the turbine trip logic diagram will be corrected and licensed operators will review this report to ensure understanding of this feature.



Carolina Power & Light Company

ROBINSON NUCLEAR PROJECT DEPARTMENT POST OFFICE BOX 790 HARTSVILLE, SOUTH CAROLINA 29550

APR 2 2 1986

AND DESCRIPTION OF TAXABLE

Robinson File No: 13510C

Serial: RNPD/85-1608

United States Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

> H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-261 LICENSE NO. DPR-23 LICENSEE EVENT REPORT 86-010

Dear Sir:

. . . .

In accordance with 10CFR50.73, Licensee Event Report System, the enclosed Licensee Event Report is submitted. This report fulfills the requirements for a written report within (30) days of a reportable event and is in accordance with the format set forth in NUREG-1022, September, 1983.

Very truly yours,

I. L Low for

R. E. Morgan General Manager H. B. Robinson S. E. Plant

IE22 111

GH:esp

Enclosure

cc: INPO H. E. P. Krug J. N. Grace