Docket No. 50-423 B17049

Attachment 3

Integrated System Functional Review for Millstone Nuclear Power Station, Unit No. 3

Engineering Self Assessment Report (ESAR) 3 ESAR-97-043 (3DE-SA-97-10)

December 1997

-0

February 1998

9803030212 980226 PDR ADOCK 05000423 Q PDR

•

.

GP.

Integrated System Functional Review for Millstone Nuclear Power Station, Unit 3

Engineering Self Assessment Report (ESAR) 3 ESAR-97-043 (3DE-SA-97-10)

December, 1997

Prepared By: Nirmal Jam

Nirmal Jain Team Technical Lead Evaluator

Reviewed By

Evaluator's Supervisor

Approved By: Mario V. Bouaco

Mario Bonaca Director, Nuclear Engineering Dept.

Approved By:_

Ray Necci Director, CMP Date 12-31-97

Date 12-31-97

Das 12/31/97

Date 1-5-97

3-ESAR-97-043 Page 1

Executive Summary

Millstone Unit 3 evaluated an integrated functional plant response to design basis accidents (DBAs) as a part of the Station Self-Assessment Program. The DBAs examined were Loss of Coolant accidents with and without the off-site power supply. The assessment focused on the interactions which take place among the safety systems and the support systems during the changing conditions caused by the accident. The assessment also factored in the external operating experience in the system evaluation. This was a limited scope assessment which took a "horizontal slice" across the entire plant, rather than concentrating on how individual systems perform in response to plant conditions. This approach complemented other assessments (such as Configuration Management Program) and inspections performed by both internal and external organizations. To the best of our knowledge, this approach and the rigor of the review have not been used previously in the nuclear industry.

The Loss of Coolant accident was selected as the DBA of interest since its mitigation involves almost all the safety systems and thus maximized the number of system interactions in concert with each other to be studied. This was an extensive effort involving 6 full time and 7 part time team members over 8 weeks. The team evaluated over 25 systems. Engineering discussion sessions (brainstorming) were held to discuss the systems and question the design, the interfaces, the surveillances, the applicability of operating experiences at other plants, etc. Innumerable questions were asked, many of which had been previously addressed by the CMP process and could easily be discounted as not requiring further investigation. Although the purpose of this study was not to validate or assess the CMP effort, the overall effectiveness of the CMP was evident.

The team identified 44 items which were investigated further. Of these items 14 resulted in "Condition Reports" of varying significance. Some of the CRs have operability/ reportability considerations, a few require plant or procedure modification and others recommend enhancements to operating and surveillance procedures. Of these Condition Reports 12 need to be evaluated prior to plant start-up. Categorizing these CRs into functions; seven CRs can be attributed to incomplete or inadequate surveillance procedures, two CRs to Emergency or Abnormal Operating procedure deficiencies and/or training, and four CRs to inadequate design. Modification and/or a procedurai change may be required for eight of the CRs prior to MP3 going to mode 4.

The team recommends that the ongoing study of the Post Acc dent Sampling System (PASS) include the thought process of this study in evaluating the system adequacy.

Based on the extent of the Integrated System Functional reviews, the team concludes that additional review of different scenarios are likely to yield little new information for Millstone Unit 3 and therefore, is not warranted.

List of Condition Reports

CR Number	Issue
M3-97-4130	ECCS Venting Surveillance procedures do not require an operability assessment if any gas is found.
M3-97-4131	ECCS Venting Surveillance procedures do not include all sections of ECCS piping with a potential for gas accumulation.
M3-97-4156	Charging and SI suction side check valves are not being tested for an actual two train full flow. Currently only one train operation is being tested.
M3-97-4157	A potential of AFW pump cavitation exists during switch over from the CST to DWST.
M3-97-4158	QSS pumps do not have minimum flow lines. A single failure could result in a consequential breach of pressure boundary due to dead heading of the pump, creating a leak path for the RWST inventory.
M3-97-4342	The operator will not be able to close Charging suction valves to the RWST for the post LOCA sump ecirculation if VCT level is low.
M3-97-4343	A potential of H2 leakage from the VCT to Charging suction exist.
M3-97-4530	Let down isolation is recommended in the leak AOP to control pressurizer level.
M3-97-4531	The operators are not being made aware of the limitations of extended operation of AFW pumps at the minimum flow.
M3-97-4532	A portion of ECC3 piping inside he containment is being left in a potentially drained condition which would cause water hammer.
M3-97-4535	Portions of the ECCS piping inside the containment should be included in the surveillance for verifying full of water.
M3-97-4536	The operators are not being specifically trained on extigating failure of SI to reset, which may be a critical failure for the SGTR to prevent SG overfill.
M3-97-4640	Certain systems are not being declared "inoperable" when reconfigured for short duration. For example, the accumulators are not declared inoperable when the N2 vent valves are opened.
M3-97-4648	The heat tracing on the RWST level indication is non-safety grade.

Table of Contents

a

1

.

Backgrour.d	5
Purpose	5
Process	6
Results	8
Issues Recommended for Resolution Prior to Startup	9
Scope of Current Review	12
Recommendation for Further Review	13

Attachment 1 - List of Team Members Attachment 2 - SB LOCA Scenario Attachment 3 - List of Items Pursued in the Review Attachment 4 - Copies of CRs Generated by the Review

..

Background

All of the systems, including the support systems, need to work in concert through changing conditions to successfully mitigate an accident. Detailed reviews of the Millstone 3 design have been performed on a system by system basis by the CMP. However, the interactions that occur between the various systems during an accident have not been reviewed in as much detail.

The NSSS, which is designed by the PWR vendor, needs to interface with support systems designed by the Architect Engineering (AE) firm. The interfaces between the NSSS and support systems are fully understood under normal operating conditions. However, under accident conditions, the stand-by safety systems are required to operate and interface with both the NSSS and support systems. Because experience with the stand-by safety systems is limited to testing and surveillance, interface issues with these systems may remain undiscovered.

This integrated system functional review focuses on the dynamic interactions that occur between the normal operating systems, the stand-by which are sequenced to start and support systems. The need for this review was identified by the CMP Effectiveness Review Group and supported by the Nuclear Safety Advisory Board. The need for this review was highlighted after the discovery of potential water hammer in the RSS piping by the NRC ICAVP out-of-scope inspection (CR M3-97-0128, LER M3-97-03).

Purpose

The purpose of this integrated system functional review is to consider the dynamic interactions that take place between various systems during an accident scenario. This type of functional review examines a horizontal slice across the various systems, rather than a detailed vertical slice through each individual system. It also examines the interface between the operator recovery actions and the systems under changing conditions. Both industry and unit operating experiences are factored into the review.

This review relies on the results of the CMP design reviews, done to date, in ensuring that each individual system meets doe necessary design and licensing requirements. In other words, this review compliments the reviews done previously.

The goal of this review is to ensure that the various systems (including the support systems) can perform their safety functions to mitigate the postulated event while interfacing with each other under changing conditions during the event.

Process

The integrated functional system review was performed using a team approach. The team followed Design Control Manual, Chapter 9, Revision 5 as it relates to performing a preemptive self-assessment. The self assessment method of the DCM provided the flexibility and freedom to use the engineering judgment and experience of the team members to highlight the areas where an issue might be hidden and to determine the validity of identified issues. Plant operations experience, and especially the external operating experience, was found to be very useful in asking the probing question, "Does this system have the same or a similar condition?"

The review team members were experienced personnel selected to cover the following areas: knowledge of the system design basis, operations, safety analysis and startup testing. In addition, a team member with operations experience from a sister plant was included for comparison and contrast to Millstone Unit 3 operation. In-house experts and experts from external organizations were also consulted to factor in operating event experience. The average work experience level of the full time team members was greater than 20 years. A list of the team members is included in Attachment 1.

The first step of the integrated system functional review was to determine which systems should be included in the review. The review focused on the safety significant stand-by systems, the systems which are realigned during the accidents, and the systems which span both the NSSS and AE scope of design. A list of the systems reviewed follows:

- Electrical Distribution
- Off-site Power Supply
- · Diesel Generator and auxiliaries, including room cooling
- EGLS (i.e., sequencer under various LOP scenarios)
- Auxiliary Feedwater System
- · Accumulators, SIH, RHR, and auxiliaries
- Charging-SI mode, including auxiliaries such as lube oil cooling and room cooling
- QSS and RSS
- · Main Steam and ADVs
- Service Water System
- RPCCW and other safety grade cooling systems such as CCI and CCE

Next, an accident scenario was selected to examine the integrated response of the systems listed above. A LOCA scenario was selected because it uses all of the key safety significant systems and, along with operator recovery actions, uses most of the safety related interfaces between the AE and NSSS vendor systems. The postulated LOCA scenario is described in detail in Attachment 2.

The simulator, system P&IDs, and the Millstone Unit 3 EOPs were used during the integrated system functional review. The simulator was used to gain understanding and examine interactions between the normal operating systems and the safety systems during the pre-trip phase of the LOCA event. The simplified flow diagrams were created from the detailed P&IDs to provide the review team with a common frame of reference for discussion and an overview of the system. The EOPs were used to identify the post-trip operator recovery actions. For recovery from the LOCA event, the operator would go through emergency procedures E-0, "Reactor Trip or Safety Injection," E-1, "Loss of Reactor or Secondary Coolant", and ES-1.2 "Post-LOCA Cooldown and Depressurization." If the break size were large enough to cause the RWST to drain to the level required for transfer to cold leg re-circulation, the operator would enter ES-1.3, "Transfer to Cold Leg Re-circulation" and subsequently go to ES-1.4, "Transfer to Hot Leg Re-circulation."

The scope of the review was limited to design basis scenarios. Scenarios with nonlimiting single failures, or failures occurring at different progression points in the scenarios, were postulated to flush out associated items. The ultimate safety function of the system was kept in focus. A detailed review of a specific item was pursued only upon agreement within the review team that the CMP may not have addressed or overlooked the importance of the item. Questions relating to scenarios involving multiple failures were not pursued.

The review team used engineering discussion sessions (brainstorming) to review each safety system, versus a check list process. These brainstorming sessions provided the team with the most flexibility to identify potential items which required further review. The system engineer for the system, generally attended the brainstorming session. Many of the review team's questions were addressed by the system engineer when he provided an overview of his system. It is impractical to list all of the questions which were asked during a brainstorming session. The following is a partial list of topics that were discussed and covered by the team to give the flavor of the team's thinking and the review process:

- Potential for Pump Cavitation During Valve Lineup Changes
- Potential for Pump Deadheading During Valve Lineup Changes
- · Potential for Water Hammer
- Diesel Loading Sequence of Support Systems
- · Effects of Active and Passive Failures on the System Response
- · Effects of Operator Recovery Actions on the System Response
- · Timing of Automatic Actuation Signals
- Potentiai Release Paths for Off-site and Control Room Doses
- Adequacy of Surveillance
- Accumulation of non condensable gases in stagnant piping

Cavitation, deadheading, and water hammer problems are significant since they could lead to subsequent pump or valve failure that could place the plant outside its design basis. Considering the potential for pump cavitation and water hammer, the review team questions centered on ways non-condensable gas or water vapor could get into the lines (potential valve leakage for example) and not be detected or vented. Considering the potential for pump deadheading, the review team questions centered on the adequacy of the mini-flow lines and valves, particularly shared mini-flow lines.

Isometric drawings were reviewed to identify the potential of gas accuantation or void formation. The team also relied on previous walkdowns and the familiarity of the system engineers with the plant configuration to obtain geometry related details. In isolated instances, plant walkdowns were performed. The team did not perform a review of calculations. This was done in previous CMP reviews. For example, the team did not perform or review the available minimum NPSH calculations for the various pumps. Also, the team did not look into internal flooding since we assumed this was covered in the HELB program. Similarly, the scope of the review was kept limited to avoid rereview of the items reviewed in the CMP. For example, the valves that need to change position during the transient were reviewed to make sure they are in the GL89-10 program and to make sure that valves that are located in a harsh environment are in an EQ program. However, the details of the calculations associated with these programs were not reviewed.

A list of items were created to track the questions which could not be addressed during the brainstorming session. Review team members were assigned responsibility for addressing these open items. If required, additional engineering support personnel were contacted to help address the open items. Finally, the system engineers were brought back to address any remaining issues and if, in the opinion of the review team, these items could not be satisfactorily addressed, the team documented the item in a Condition Report (CR).

Results

The review identified a few design deficiencies, procedure inadequacies, and a few requiring operability/reportability considerations. The team identified 44 items which were investigated further in detail. Attachment 3 provides a discussion of all 44 items. Of these 44 items, 16 remain open and unresolved. All of the open items are being tracked in CRs. 14 items resulted in new CRs and the remaining two items had pre existing open CRs. A copy of all the CRs generated by this review is provided in Attachment 4.

Many of the 44 items were identified in previous reviews. This gave the review team confidence that the prior CMP reviews were effective in ferreting out the major issues. If a CR was already open on the item, the team did not generate a new CR, nor followed-up into the details of addressing the issue to close the CR.

The following major issues were found. The team recommends that these issues be resolved prior to start-up since they potentially challenge the operability of the safety systems. The remaining issues contain suggestions for improvement and need not be implemented prior to startup.

Issues Recommended for Resolution Prior to Startup

1. Potential for Non-condensible Gas in ECCS Piping

The Millstone Unit 3 Technical Specifications require that the ECCS piping be verified to be full of water. Non-condensable gas in the piping could result in a water hammer event or could gas bind a running pump. There have been many instances of non-condensible gas accumulation in the ECCS piping in the industry. Two principal sources for the gas have been leakage of hydrogen from the VCT, which can accumulate in the non-operating charging pump suction line, and nitrogen from the SI accumulators, which can accumulate in the RHR or SI piping. We have investigated these sources for Millstone Unit 3.

Millstone Unit 3 vents the accessible ECCS piping every 31 days to meet the Technical Specification requirement. In practice, Millstone Unit 3 only vents the ECCS high points which are located outside containment because the vents inside containment are considered in-accessible. This does not seem to be consistent with the industry practice. Discussions with Westinghouse revealed that other licensees do include portions of piping inside the containment for this surveillance. Also, the improved standard Westinghouse Technical Specifications do not differentiate between inside and outside containment, nor do they mention accessibility as a factor in scope of surveillance. Originally, Millstone Unit 3 was a sub-atmospheric containment with a fairly low operating pressure; this may have been a factor for considering the containment in-accessible. Now that the Millstone Unit 3 containment operating pressure is very near atmospheric pressure, we recommend that the decision of assuming all piping inside the containment as automatically in-accessible, be addressed.(CR M3-97-4532 & 4535)

For the piping outside containment, we reviewed the isometric drawings in detail to ensure that all locations where non-condensible gas could accumulate are being vented in accordance with the Technical Specification surveillance requirements. We found that about 50-feet of 6 to 8-inch ECCS piping is currently not being vented and therefore, not being verified to be full of water. This section of the ECCS piping is used during sump re-circulation. There are no vent valves for this portion of piping. Any non-condensible gas in this section of piping could cavitate both the charging and SI pumps after the transfer to sump re-circulation. (**Open CR M3-97-4130 & 4131**)

We have also reviewed the potential of H2 leakage from the VCT to the charging pump suction piping. On SI, the VCT is isolated from the charging suction. However, these isolation valves are not leak tested. Since the H2 overpressure in VCT is maintained on

SI, a potential of H2 leakage to charging pumps exists. Our review identified at least two paths for leakage of H2. (CR M3-97-4343)

2. Potential for Containment Sump Inventory Leakage Outside Containment

NRC Information Notice 91-56 requires consideration of all potential leakage paths in the off-site and control room dose analyses. We believe that this IN notice was inadequately addressed by Millstone Unit 3. For example, both the charging and SI suction lines from the RWST header have both isolation and check valves to prevent leakage back to the RWST during re-circulation. However, neither the isolation valves nor the check valves are leak tested. Any leakage past these valves would bypass the containment SLCRS boundary and accumulate in the RWST, which is vented to the atmosphere. Other paths, such as through the mini flow lines can also be postulated. Several CRs have been written to address this issue, and one of them is still open. This issue should be fully resolved prior to the unit start. (CR M3-97-3218)

3. Potential for Deadheading the QSS Pumps

The QSS pumps do not have mini-flow lines. If either discharge valve (MOV 34A or 34B) fails to open on a Containment Depressurization Actuation (CDA) signal, the associated QSS pump would start and deadhead. The deadheaded pump could develop a leak. The effect of such a leak on the RWST inventory or internal flooding has not been considered. The maximum leak rate for such a failure needs to be estimated to determine if this could pose a flooding or a significant loss of RWST inventory concern. (CR M3-97-4158)

4. Failure to Full Flow Test the SI and Charging Pump Suction Check Valves

The two SI pumps have check valve 3SIH-V11 in the common line from the RWST header. Similarly, the two charging pumps have check valve 3SIH-V268 in the common line from the RWST header. Per the IST procedure, the check valves are tested by operating only one pump at a time. Since both SI and both charging pumps will start following a safety injection signal and subject the valves to higher flow rates, this IST test does not represent the full flow test, i.e., the procedure does not demonstrate full lifting of the check valves. Apparently, these check valves were not full flow tested during initial startup either. There could be inadequate NPSH for the pumps if these check valves failed to fully open. (CR-M3-97-4156)

5. Inability to Isolate Charging Suction to RWST on Transfer to Sump Re-circulation

The charging pump suction isolation valves (3CHS-LCV112D & E) to the RWST are controlled to open on low VCT level (<4.4%). This protects the running charging pump by transferring suction from the nearly empty VCT to the RWST.

Following a LOCA event, these isolation valves need to be closed for sump re-circulation to limit back leakage to the RWST. The control system, however, will keep them open if the VCT level were less than 4.4%. The VCT low level signal to open valves 3CHS-LCV112D & E can not be overridden nor the valves have a locked close position.

The recovery procedure for transfer to sump re-circulation (EOP 35 ES-1.3) had been revised to remove power from these valves to keep them closed. The purpose of this revision was to address a scenario in which the VCT level were to fall below the low level transfer set-point after the system had been placed in re-circulation mode. That modification does not, however, properly address the scenario described above (i.e., closure of the valves when low VCT level is present). (CR M3-97-4342)

6. Differences Between Operations and the Design Basis

Several minor differences between operation and the design basis were discovered during the review. These are described briefly below. They are described in more detail in Attachment 3.

The normal charging system was designed so that, with letdown isolated, the flow from one charging pump could keep up with the leak rate from a 3/8-in line break in the RCS. This would allow the operator to perform an orderly shutdown. In practice, Millstone Unit 3 avoids letdown isolation and instructs the operators to trip the reactor and generate an SI if both charging pumps cannot keep up with the leak. This approach results in SI for the scenarios which could have been mitigated by a controlled shutdown. (CR M3-97-4530; evaluation of the CR is not necessary prior to the unit start)

A passive failure 24 hours into an event could disable both charging or both SI pumps during re-circulation. If neither charging pump is available, the emergency procedures instruct the operator to align the RSS system to inject through the RHR lines. Currently no analyses to support this lineup exists.(analysis is in progress)

The emergency operating procedures require SI to be reset before performing subsequent actions to trip ECCS pumps (to terminate or reduce the safety injection flow rate) or realign valves (prior to the transfer to re-circulation). The SI reset is vulnerable to single failure, yet there is no training or guidance in the procedure to address this failure.(CR M3-097-4536)

Non-safety grade piping is isolated from safety grade piping to ensure that the safety system will operate as intended when required. Non-safety grade piping is used to fill the SI accumulators, test valves, etc., and is not automatically isolated on a safety injection signal. The associated safety equipment is not declared inoperable during the period it is connected to the non-safety grade piping. (CR M3-97-4640)

7. Pumps Running on Mini-flow

NRC bulletin 88-04 requested licensees to evaluate the adequacy of the minimum flow bypass lines for safety related centrifugal pumps and to include verification from the pump manufacturer that current mini-low rates are sufficient to ensure no pump damage from low flow operation.

The AFW flow rate is controlled by the operator to maintain SG level following an accident. For certain size LOCAs, little AFW flow may be required for heat removal so these pumps could be running on mini-flow for an extended period. Design engineering received revised minimum flow rates from the pump manufacturer which were much higher than the original flow rates. The higher flow rates were not adopted since it was concluded that the original mini flows affect only the long term operation of the pumps (when operating on mini-flow). Operations was not aware of a time limit for running these pumps, so there is no guidance in the procedures and the operators are not trained to trip these pumps.(CR M3-97-4531)

8. Qualification of Heat Tracing

The heat tracing on the sensing lines for the RWST level indication, although redundant and reliable, is not safety grade. This indication is used by the operator to determine when to transfer to re-circulation. The sensing lines are located out side in the yard and are vulnerable to freezing during accident. (M3-97-4698)

Scope of Current Review

The focus of this review was to look at the types of issues that may not have been addressed in detail by the previous CMP review process. CMP reviewed in detail system design, it did not specifically focus on how systems interact with each other. This review took a broader perspective of considering interactions between operating systems with stand-by-systems or the interactions between stand-by-systems with each other and how this relates to each systems design. Operating event experience applied broadly, also led to the discovery of some issues. Most of the issues can be summarized in the following broad categories:

- · potential of a void or trapped gas in the ECCS piping
- inadequate testing of check valves
- design deficiencies such as inadequate or no min.-flow lines for pumps, uncertain pedigree of heat tracing

These findings were discovered by the review of safety systems credited in a LOCA scenario. This scenario captured the majority of the safety systems and the aspects of these systems which would also be credited for mitigation of other events (i.e., SGTR,

SLB, Loss of Feedwater flow, etc.). However, given the extent of this review, the question arises if the remaining few safety systems have similar concerns.

The systems which were not reviewed in this study include; VAC, Instrumentation & Logic, PASS, SLCRS, and containment isolation. Our basis for not expanding the review to include them can be summarized as follows:

- MP3 design maintains separation & redundancy in electrical/instrumentation design and CMP reviewed the design in detail. These are the main reasons for the absence of any findings in these areas. Therefore, the consensus of the team was that little added value would be gained by expanding the scope to include VAC, instrumentation or logic.
- Over the past few years SLCRS has been reviewed a number of times. Therefore, we
 did not anticipate finding anything new and the consensus of the team was that little
 added value would be gained in expanding the scope to include SLCRS.
- We looked at the functionality of various valves and raised issues relating to leak tightness. Our review found that the EQ and 89-10 programs for the valves have captured all the relevant valves. Therefore, the team assumed that the Containment Isolation Valve list is similarly complete and further review is not warranted.

Recommendation for Further Review

PASS was not reviewed by this effort. We understand that a study of PASS is currently in progress. We recommend, that this study include the type of review that was performed in this effort.

Attachment 1

List of Team Members

Full Time Review Team Members

Bill Stairs	NU - Project Lead
Nirmal Jain	ABB/CE - Technical Lead
John Rothert	NU - PRA
kick Ofstun	Westinghouse - Analysis
Allen Farlow	Westinghouse - Technical Support
Mike Galle	SCS - Operations

Part Time Review Team Members

Mike O'Conncr	NU - Operations
Bill Cote	NU - Training
John McInerney	Westinghouse - Licensing
Joe Moore	Westinghouse - Site Service
Richard Johnson	NU - Operating Event Experience
Bob Stanley	NU - Oversight
Mark Loeffler	Westinghouse - CMP
Mike Horton	SCS - Technical Services
Mark Bowmont	Westinghouse - Operating Event Experience

Contacts

Alberto Airas Dan Aube **Bob Bain** Lamar Brown **Bob Brouillier** Steve Chim Fred Cietek **Bob** Ciminel Joe Creamer **Rich** Debernardo Ray Deconto Dave Fink Jim Grover **Rick Halleck** Ted Hodge Cris Janus Steve Jonash Geoge Konopka Neil Lewis Bob McDonald Chris Morgan Dave Presutti

NU - RSS System Engineer NU - 1&C S&W Design Engineer Westinghouse - Licensing NU - HVAC System Engineer NU - 1&C NU - PRA (HVAC) INPO - Operating Event Experience S&W - Design Engineer NU - DC System Engineer NU - RSS System Engineer Westinghouse - LOCA Analysis Westinghouse - Dose Analysis NU - Electrical Design NU - FWA System Engineer NU - SI System Engineer NU - RHR System Engineer Westinghouse - Fluid System Design Westinghouse - SGTR Analysis NU - HVAC System Engineer Westinghouse - Licensing/Technical Specifications NU - AFW HVAC System Engineer

Integrated System Functional Review for Millstone Unit 3

Steve Pietryk John Plourde Pete Quinlin Brian Shanahan Brand Sisk Sheldon Stricker Bob Teixeira Pete Tirinzoni

NU - SW (Intake Structure) System Engineer NU - AC System Engineer NU - Engineering NU - EDG System Engineer NU - HVAC System Engineer NU - System Engineering NU - FWA System Engineer NU - CVCS System Engineer

> 3-ESAR-97-C-3 Page 1-3

> > -

Attachment 2

Scenario Description

The varying size LOCA event scenario described below will exercise the safety systems of interest. The discussion of the scenario is tailored to high-light the varying system interactions

The scenario involves an initial 100 gpm leak from the cold leg and is subsequently increased in size at varying times to allow for the observation of ineractions and control functions. Various control functions automatically sequence to control pressurizer pressure and level and core power. Eventually the leak developed to sufficient size to cause a reactor trip and safety injection (SI) initiation. Cases with and without the off-site power were considered. Charging, SI, and Residual Heat Removal (RHR) pumps start and begin to inject when the reactor pressure drops below their respective pump delivery capability. Both motor driven and turbine drive Auxiliary Feed Water (AFW) pumps supply the Steam Generator (SG) inventory. The SG pressure is controlled by the steam bypass valves (for the cases with off-site power) and by the atmospheric dump valves (for the cases without the off-site power). To show interactions with the containment spray system, conditions with and without the containment depressurization actuation (CDA) signal present are considered. On low refueling water storage tank (RWST) water level, the operator successfully initiates sump recirculation. At 11 hours, in accordance with the emergency operating procedures (EOPs), the operator would be required to initiate hot and cold side injection.

The operator is expected to take various recovery actions during the small LOCA event. In the scenario, some operator actions are delayed or omitted to allow the automatic functions to sequence.

Initial Conditions:

- Reactor Power 100%
- Normal contingent of equipment operating
- · Pressurizer pressure and level controls in auto
- · Rod Control system in auto

Scenario Steps:

- Loop 4 cold leg (RCP discharge) develops 100 gpm leak.
- 2. Charging flow increases. Second charging pump is started manually per AOP-3555. Make-up to the volume control tank (VCT) is normally controlled automatically; however, for this scenario it was manually stopped to observe the VCT low row level switch over to the RWST. Additionally, portions of VCT makeup are non-safety grade and can not be credited form design basis space.

Pressurizer back-up heaters energize automatically to control pressure.

3. No immediate change in containment pressure and temperature is expected; however, the radiation monitors might alarm. The operator would diagnose the leak from the start of the VCT make-up pump, miss-match between letdown and charging, decreasing VCT level and possibly by the changes in the pressurizer level.

The operator actions specified in AOP 3555 are omitted to allow the automatic functions to sequence. The most significant operator action would be to perform a controled shutdown if the pressurizer level had stabilized, otherwise the operator would manually scram and initiate SI.

 On low low VCT level, the charging suction switches from the VCT to the RWST.

The resulting boration will cause core power to decrease. Turbine control valves open to maintain turbine first stage pressure. Control rods will move out (if all are not out) to control Tavg.

- 5. At this time in the scenario the leak rate is assumed to increase (equal to about 3 inch line break).
- Loss of Power (LOP): The control rods fall in and trip the reactor. SI is generated on low pressurizer pressure.

The reactor trip causes turbine trip, turbine stop valves go close, and when the main generator experiences reverse power, its output breaker opens.

Case 1: Off-site power through NSST continues to provide power to plant equipment.

Case 2: Off-site power is lost at the time of LOCA (step 5).

- Case 3: Off-site power is lost at the time of main generator trip.
- Case 4: Grid experiences degraded voltage (between 90 and 70 %) at the time of main generator trip.
- Case 5: Off-site power is lost at some unspecified time after the main generator trip.
- Main feedwater isolates, motor driven AFW pumps start on SI, and turbine driven-AFW pump starts on low SG level.
 SG pressure is controlled by the Turbine bypass valves (if main condenser is available) or by the Atmospheric dump valves.
- 8. <u>DG Initiation</u>: DGs are started on SI or LOP, which ever occurs earlier. However, it (DG) remains unloaded until the off-site power is lost.
- Engineered Safety Features Actuation Signal Initiation: The SI and RHR pumps start and Charging injection transfers/switches from its normal alignment to all 4 cold legs.

For the cases where off-site power is available, all pumps start at the same time (i.e., no sequencing dclays). Otherwise, the loads are sequenced on the DG. Auxiliaries for these systems, such as lube oil cooling, room cooling are also automatically started.

- <u>Containment Isolation</u>: SI generates the containment isolation signal CI-A. Letdown and SG blowdown isolate. Instrument air to the containment is isolated. Cooling flow for the CAR fans is switched from the chilled water to the RPCCW. CAR fans A and B are started automatically, if not already running.
- 12. <u>Auxiliaries:</u> Until the off-sile power is available, all operating loads (essential and non-essential), including SW, TBCCW continue to run. Also, the pressurizer heaters remain energized unless the pressurizer level drops below the cut-off setpoint.

When (and if), off-site power is lost, 2 SW and 2 RPCCW pumps are restarted. All non-essential loads are secured.

13. <u>CDA and Start of Containment Sprays</u>: At a containment pressure of 23 psia a CDA signal is generated and the QSS pumps are started to provide containment spray (either on the off-site power or by the DG). The Recirculation Spray Sump (RSS) pumps are started 1 i min. after the QSS pumps start and recirculate the sump water to the containment spray headers. For small breaks, containment pressure may remain below the CDA setpoint. Therefore, the QSS and the RSS pumps will not start automatically.

CDA also generates containment signal CI-B. Reactor Protection Closed Cooling Water (RPCCW) to the containment is isolated.

- 14. Initiation of Sump Recirculation: The RHR pumps trip on low-low RWST level. The operator resets SI, CDA, LOP, and stops the RHR pumps by placing their switches in pull-to-lock and isolates a portion of the piping. If the RSS pumps are not already running (ie., the CDA had not been generated) the operator will start them and initiate the containment sprays to purge the lines of air. The Charging and the SI pumps will be aligned to the suction from the RSS pumps, then the suction valves form the RWST will be closed.
- 15. <u>Hot and Cold Side Injection</u>: The operator will turn off the SI pumps and the charging pump continues to provide the cold leg injection. The SI pump will be restarted after the cold leg injection valves are closed and hot leg injection valves are opened.

Attachment 3

List of Items Pursued in the Review





- a) The charging pump normally takes suction from the VCT. If the VCT level cannot be maintained for some reason, the charging pump suction is switched to the RWST. The valves from the RWST (112D&E) start to open once the VCT level reaches the low level set point (4.4%). After valves 112D&E are full open, the suction valves from the VCT (112B&C) start to close. Since the VCT is pressurized with hydrogen gas, it will continue to provide some flow until either valve 112B or 112C fully closes. Does the 4.4% switch over set point ensure that sufficient water is left in the VCT to provide a water seal between the hydrogen filled VCT and the charging pumps? Is there a vortex preventative device in the VCT?
- b) Valves 112B and 112C may not be leak tight. If the water seal is lost, hydrogen could leak by these two valves and find its way to the charging pump. Is the VCT vented after valves 112B&C are closed? What would the operator do if the VCT level dropped off-scale?
- c) Another potential hydrogen leak path from the VCT to the charging pump suction is through check valve V542 and the normally locked close valve V541. This is a 3-in line between the VCT gas space and the seal return line. Neither of these valves are in the leak check program. Leakage through this path could go undetected during normal operation because the seal return line is at a higher pressure than the VCT. Following safety injection, the seal return line is isolated and leakage through these valves could allow hydrogen to reach the charging pump suction. Why aren't these valves leak tested? A recent INPO SOER (97-1) deals with the industry experiences of leakage of H2 from the VCT to the charging suction.

NOTE: It is possible that by the time 112B&C are fully closed, the indicated VCT level would fall off-scale low. Based on our discussion with training (Bill Cote), the operator would not be mislead by the off-scale low indication if either valve 112B or C are verified to be closed.

Resolution

CR M3-97-4343 has been generated to address items b) & c), the potential of H2 leakage from the VCT. We recommend that this CR be resolved prior to MP3 start.

- a) Westinghouse performed a safety evaluation (NEU-97-308E) for increasing the stroke times for the 112 valves.. VCT design does not contain a vortex preventor device. Westinghouse has concluded that the current aetpoint (4.4%) is adequate to provide the vortex protection. However, this conclusion does not take into account any potential leakage past valves 112B&C.
- b & c) Our review indicates that there has been no systematic evaluation to ensure that all potential leakage paths from the VCT to charging pump suction are identified and addressed. For example our review identified the leakage path via valves V541 and V542. This is a 3" inch line between VCT gas space and RCP seal return line. These valves are also not leak tested to ensure leak tightness for H2. During normal operation, the seal return is at a higher pressure than the VCT and therefore, any leakage will be from the seal return to the VCT. Such a leak will go undetected. Post SI, since the seal return is isolated, it (seal return) will be at lower pressure than the VCT and therefore, the leakage will be from the VCT.

Item 2 - Basis for Boundary Between Class I and Class II Piping

According to Westinghouse, the normal charging system is designed for one pump to keep up with a 3/8 inch line break, assuming letdown has been isolated. Therefore, piping with an ID less than or equal to 3/8 inch is designed as Class II.

Assuming a 3/8 inch or smaller leak in the RCS, the operator will try to recover using procedure AOP-3555. If the pressurizer level is decreasing, AOP-3555 requires the operator to increase charging flow to maximum and start a second charging pump, but does not require letdown isolation prior to tripping the reactor and initiating SI. If the pressurizer level trend appears to be stable, AOP-3555 requires the operator to isolate both charging and letdown in an attempt to identify the source of leakage.

The instructions in AOP-3555 are not consistent with the design basis assumption which defines the upper limit for Class II piping. What do other companies do for this small leak size, do they isolate letdown?

Resolution

CR M3-97-4530 was generated suggesting that Millstone Unit 3 consider modifying AOP-3555 to include letdown isolation before tripping the reactor and generating a safety injection.

Our discussions with Operations (Mike O'Connor) and Safety Analysis (Don Parker) indicated that they believe the EOPs provide better guidance than the AOPs for RCS cooldown and depressurization following a leak. Therefore, if both charging pumps cannot provide enough makeup, the operator is instructed to trip the reactor and initiate safety injection (which also isolates letdown), then follow the EOPs to terminate SI and cooldown to cold shutdown.

The current guidance given in AOP-3555, which prevents letdown isolation on decreasing pressurizer level, is based on a concern for thermal shock to the charging nozzle following letdown isolation. Letdown flow is used in the regenerative heat exchanger to warm the charging flow before it enters the cold leg.

Marke Galle (Operations, Farley) indicated that at Farley, they would increase charging, then isolate letdown in order to avoid safety injection. They do not want to initiate SI for small leaks because they are concerned with the potential for overfilling the pressurizer before SI could be reduced and/or terminated through the EOPs. Also, since a small leak is less likely than other events that could cause letdown isolation, they feel that having instructions to isolate letdown for a small leak is not going to significantly increase the number of thermal cycles to the charging nozzle.

According to 10CFR50.55a.2, paragraphs i and ii, the NSSS system must be designed such that the reactor can be shutdown in an orderly manner following a break in the class

II piping. The charging system is sized to keep-up with a 3/8" line break, provided the letdown is isolated. Therefore, piping smaller than or equal to 3/8" are designed as class II piping. Also, a leak is less likely than other potential letdown isolation events which will results in thermal cycling of the charging nozzle. In this light, isolating letdown and performing a normal shutdown instead of a reactor trip with safety injection following a small leak (3/8" or smaller break) in the RCS would seem to merit further consideration.

Item 3 - Transfer Normal Charging to Safety Injection: Potential for Air in Piping

The line-up of charging for safety injection requires the use of piping downstream of valves 8801A&B. Gas in this piping could create a water hammer. How do we verify the piping between 8801A&B and the check valves is filled with water and remains that way?



Resolution

CR M3-97-4532 was written to address this issue.

There is a potential for a void between valves 8801A&B and check valve V005 remaining undetected. This portion of the piping is not checked to ensure it is full of water (TS surveillance 4.2.5). Infect leak testing of check valve V005, as discussed below, creates a potential of forming a void in the piping.

Check valve SIH*V005 is tested for leak tightness by applying safety injection pump discharge pressure to the downstream side of the check valve. The test frequency is a minimum of once per refueling interval or more frequently as conditions prevail. To perform this test, the upstream piping between valves 8801A&B and check valve V005 is isolated and depressurized to measure the check valve leak rate by opening manual drain valve V883. After the leakage measurement is completed, the drain valve and the downstream valves are closed and SI pump is stopped. This leaves the downstream lines pressurized, but the upstream line depressurized and potentially drained.

This portion of the piping (between valves 8801A&B and SIH*V005 will require refilling and repressurization to eliminate potential voids in the line.

Item 4 - Letdown Isolation May Lift Relief Valve

Either a control fai'ure, that results in closure of valve FV131, or an inadvertent SI, with a single failure of the upstream isolation valve 8160 to close, is postulated. This exposes the relief valve located between 8160 and 8152 to the RCS pressure. The relief valve is designed to open at 600 psi to protect the downstream piping and heat exchanger. Lifting of the relief valve provides a leakage path from the RCS to the pressurizer relief tank inside containment.

The relief valve is sized to relieve flow assuming all three orifices are open. Millstone Unit 3 normally operates at full power with only one orifice line open. The flow rate through the relief valve would be limited at the orifice, if not the relief valve itself.

It is likely that 2 charging/SI pumps would be able to match or exceed the relief valve flow rate at normal RCS operating pressure. This would prevent the pressurizer level from dropping below the low level letdown isolation set point, which would automatically close letdown isolation valves 459 and 460 and MOVs 8149A,B&C. Note, these are control grade valves but are designed to close on low pressurizer level to isolate letdown. The review team had the following question:

Is acceptable design to have failure of a control system resulting in a RCS leak?



Resolution

This item is considered closed.

Westinghouse (George Konopka) compared the Millstone design with the standard 4-loop plant design (SNUPPs). Although the Millstone design is not exactly the same as the

standard design, it meets the same requirements, i.e., the relief valve is located between the two containment isolation valves and is set to protect 600 psi rated piping. We believe this meets the applicable design criteria.

The operators are trained on the scenario described above. There is a temperature alarm on the relief line, so the operator should notice the leak. Also, the PRT level, temperature and pressure indications will be available to alert the operator of leakage. The operators would close valves upstream of the relief valve to terminate the leak.

Item 5 - Loss of RCP Seal Cooling

A CDA generated by high containment pressure following a LOCA or MSLB event would isolate CCP flow to the RCP thermal barrier. If flow control valve HCV-182 in the seal injection line were to fail in the closed direction, seal injection would also be lost. This could lead to leakage of RCS inventory through the RCP seals. A loss of RCS inventory caused by a MSLB with an assumed controller failure has not been analyzed.

Resolution

This item is considered closed.

HCV-182 fails open on a loss of power or instrument air. The instrument air compressors are tripped on a safety injection signal. It is not credible to assume a failure to close of a fail open type valve with a loss of air pressure (Ref.: e-mail from John McInerny, Westinghouse). Therefore, a loss of seal injection is not credible.

Ite ... - Transfer Charging from VCT to RWST: Hot Water to the VCT

CCP cooling to the non-regenerative heat exchanger in the letdown line is vulnerable to single failures. For example, only CCP train A provides cooling flow to the heat exchanger. A loss of cooling flow in the non-regenerative heat exchanger will introduce hot letdown flow to the VCT. Have the effects of hot water in the VCT been evaluated? For example, the operating charging pumps could cavitate due to inadequate available NPSH or the piping temperature may exceed the design temperature limit.

Resolution

This item is considered closed

Protopower calculated the maximum temperature in the VCT to be 286 F and the maximum temperature at charging pump outlet to be 152 F for this scenario (Protopower Calculation 97-128, file 10-283). This calculation credits the cooler seal return water mixing with the hotter water coming from the VCT for charging suction. The seal return heat exchanger is cooled by CCP train B. Therefore, a single failure cannot fail both the letdown and seal return heat exchangers. Protopower calculation concluded that the charging pump cannot cavitate since the VCT pressure will increase as the temperature of the water in the VCT increases. Higher back pressure in the VCT will provide the additional NPSHA needed for the hotter water. The charging system piping is designed to a temperature of 150 F. A charging water temperature of 152 F (2 F above the piping temperature limit) is justified.

Item 7 - Potential Leakage Path of Sump Water to the RWST

NRC Information Notice 91-56 requires consideration of all potential leakage aths in the cff-site and control room dose analyses.

Both the charging and SI is a ion lines from the RWST header have both isolation and check values to prevent leakage back to the RWST during recirculation, however, neither the isolation values nor the check values are leak tested. Any leakage past these values will bypass the containment SLCRS boundary and will accumulate in the RWST, which is vented to the atmosphere. The impact of any such leakage on the calculated dose, both for off-site and in the control room, has not been taken into account.

Resolution

CR M3-97-3218 was previously generated and its significance was under estimated. We recommend that it be fully resolved prior to unit re-start. This issue has been raised numerous plants by the NRC and therefore merits considerable attention to ensure proper closure.

IN 91-56 was inadequately addressed by Millstone Unit 3. Several condition reports have been written to address this issue (M3-97-1936, M3-97-2140 and M3-97-3218). CR M3-97-3218 is open and therefore, we did not generate a new CR.

Condition report M3-97-1936 was written to assess the leakage and the consequences of the leakage. A conservative leak rate was estimated in response to M3-97-1936. This information can be predesensess the impact of the valve leakage on the LOCA dose analysis as part of the corrective action plan for M3-97-3218. The dose analysis assessment has not yet been completed.

Condition report M3-97-3218 was written to address leak testing of the isolation and check valves. The corrective action plan for M3-97-3218 includes identification of the valves which are affected by Technical Specification 6.8.4, assessment of the impact of valve leakage on the LOCA dose analysis, and development of surveillance procedures for the affected valves.

Item 8 - Potential for Voids or Non-Condensable Gas in SCCS Piping

Technical Specification 4.5.2.b requires verification that the ECCS piping is full of water. How does Millstone Unit 3 meet this surveillance requirement?

Resolution

CR M3-97-4131 and CR M3-97-4130 (respectively) have been generated for the following two identified issues associated with item 8.



- a) The surveillance procedures and isometric drawings were reviewed to determine if all ECCS piping, including the portion used for sump recirculation are being verified to be full of water. After reviewing the piping isometrics, it was discovered that the SI pump suction piping downstream from MOV 8804A to check valve 982, between the vent valve 992 and MOV 8807, and between MOV 8804B to check valve 983 are not being verified to be full of water. These sections do not contain any vent or drain valves. The isometric of the piping suggest that gas could accumulate in these portions and therefore, would remain undetected. These segments of the piping are on the charging and SI pump suction side. Therefore, a void in these segments could gas bind both charging and SI pumps during sump recirculation.
- b) Detection of any gas in the ECCS piping raises the question of the system operability until the gas is purged. The current surveillance procedures do not provide any guidance on the need to do operability determination if any gas is detected.

-

Item 9 - Transfer to Sump Recirculation: ECCS Pump NPSH

In EOP 35 ES-1.3, step 2f, the operator is instructed to verify that recirculation spray pumps A and B are running. If not, he is instructed to start pumps A and B. The operator can proceed to step 2g if either pump A or B starts. In this condition, 1 RSS pump could be supplying 2 SI, 2 charging pumps and a spray header. A flow orifice was added to the discharge of each RSS pump to reduce the maximum flow rate from about 5000 gpm to about 3300 gpm to address the RSS pump runs at concern (see item 16). Have calculations been performed to determine the available NPSH for the ECCS pumps during recirculation under these conditions, considering the reduction in the RSS supplied flow rate after the flow orifices have been installed?

Resolution

This item is considered closed.

Westinghouse has done two calculations to evaluate the available NPSH for the ECCS pumps (SAE/FSE-C-NEU-079, SAE/FSE-C-NEU-0100). Two cases were run in the first calculation. In the first case, 1 RSS pump was assumed to provide suction to 1 charging and 2 SI pumps; this assumption minimizes the suction flow to the charging pump. In the second case, 1 RSS pump was assumed to provide suction to 1 SI and 2 charging pumps; this assumption minimizes the suction flow to the SI pump. A sump temperature of 150 F was assumed in both cases. In the second calculation, 2 RSS pumps were assumed to provide suction to 2 SI and 2 charging pumps. A sump temperature of 230 F was assumed in this second calculation. This assumption is consistent with a single failure loss of a service water train.

Consideration of a failure of the service water train and an additional (non-consequential) failure, that results in a single RSS pump having to supply both charging and both SI pumps, would be beyond the design basis. Therefore, no calculations have been performed to verify that adequate NPSH could be assured in this case.

2

Item 10 - Transfer to Sump Recirculation: Hot Water in RSS Piping

Originally, the RSS piping was qualified to 150 F. Assuming failure of one train of SW, the RSS piping down stream of the respective heat exchangers can be subjected to much higher temperatures (sump water temperature and from pump heat up). Has the RSS piping been qualified to these possible higher temperatures? Was the potential for water hammer considered in the RSS piping qualification calculations.

Resolution

This item is considered closed.

All RSS piping (and the relevant portions of the charging, RHR, and SI piping) has been qualified to 250 F (DCRs M3-96054, M3-96056, M3-96063, M3-96068 and M3-96069). Additionally, potential water hammer concerns were addressed.

Item 11 - Active vs. Passive Failures: Check Valves

FSAR section 3.1.1.2 states that check valves are classified as active components. A check valve is located between the RWST header and the charging pump suction isolation valves. A failure of this check valve could disable both the charging pumps. A similar situation exists in the SI pump suction.

Resolution

.0

 C_{x} . M3-97-2140 had previously been written on this issue. This item is considered closed.

In response to that CR, Westinghouse provided a letter (NEU-96-573) which states that the check valves in the ECCS system are considered to be passive components. They are designed to a more stringent criteria which assures no gross deformation and thus minimizes the likelihood of failure.

The FSAR, page 3-1.4, states that there are exceptions in the ECCS system. The need for any FSAR changes to clarify the exception will be determined in CR M3-97-2140 resolution.

Item 12 - RHR System: Leakage from Accumulators

The accumulators are pressurized to approximately 600 psi with a nitrogen cover gas. Leakage, during normal operation, of the nitrogen rich accumulator water through the check valves and into the low pressure RHR discharge piping could result in the gas coming out of solution. A nitrogen bubble at the RHR discharge could result in water hammer when the system is started

A recent INPO SOER 97-01 deals with the industry experiences of N2 accumulation in the low pressure side of the ECCS system

Resolution

CR M3-97-4580 and CR M3-97-4581 were generated by Safety Engineering in response to the SOER.

The accumulators are located at an elevation of -24 feet, while the connection to the SI system is at an elevation of about 13 feet. A significant volume of water must be displaced before water leaking from an accumulator can reach the check valve to the RHR piping. This would cause the accumulator level and pressure to decrease notably. The accumulator leakage would not go undetected for long because Millstone Unit 3 has a relatively narrow operating band on the accumulators.

The Millstone Unit 3 accumulator low level alarm response procedure does not provide any instructions or guidance to determine where the water went. Millstone Unit 3 Operations (Keith Covin) say they would write a CR to determine where the water was going if an accumulator had to be repeatedly filled. Considering that Millstone Unit 3 has such a narrow operating band on the accumulators, and that only one instance of accumulator in-leakage has been observed to-date, and that a large volume of water must be displaced before accumulator water could reach the low pressure piping, accumulation of N2 in the RHR piping is not likely.
Item 13 - Void in RHR Heat Exchanger at Low RWST Level

The RHR pumps can be turned off by the operator following ECCS actuation if the RCS pressure (including uncertainties) is above the RHR pump shutoff head or if a transfer to recirculation is required. Is it possible for the heat exchanger tubes to void after the pumps are tripped? If so, there could be a problem with water hammer if the RHR pumps are restarted.

Resolution

This item is considered closed.

The RHR heat exchangers may begin to drain when the RWST level decreases and falls below the elevation of the heat exchangers. Therefore, to determine if voiding could occur, the fluid elevation in the RWST was compared to the elevation for the top of the RHR heat exchanger. The data was taken from drawings No. EP-111M-8, "YARD PIPING SECTIONS SHEET 12" and D-74415, "REFUELING WATER STORAGE TANK". The data is given below.

Bottom of RWST is at 24-ft 6-in elevation. Isolation valve 3SIL*V1 is located at 29-ft elevation. RWST Tank Diameter is 59-ft.

Description	Volume	Fluid Elevation
RWST level Empty	~47,655 gal	~26-ft 9-in
RWST level LO-LO	~520,000 gal	~49-ft 11-in
RWST level LO	~1,171,000 gal	~81-ft 9-in
RWST level HI	~1,189,000 gal	~82-ft 8-in
RWST level HI-HI	~1,195,000 gal	~83-ft

The top of RHR heat exchanger is at an elevation of approximately 51-ft. Therefore, the RWST level is higher than the RHR heat exchanger until just before the transfer to recirculation. At this point, the RWST level is slightly lower than the top of the RHR heat exchanger. RHR, if needed, is expected to be initiated before the RWST water level drops to the setpoint where the sump recirculation is initiated. Therefore, the amount of void, if any, will be minimal when RHR is expected to be initiated.

The operator could start the RHR pumps after the transferring to sump recirculation, but only after consulting with the ADTS (see step 30d of ES-1.2). We are assuming that the TSC staff will provide the appropriate guidance at that time.

Item 14 - Heat-up of RHR Pumps on Mini-Flow

The CCP water supply to the RHR heat exchangers is isolated on a safety injection signal. The RHR pumps start following a safety injection signal, but may not provide flow to the RCS if the pressure is higher that the pump shutoff head. In this case, the pumps would run on mini-flow. The RHR pump mini-flow return is routed through the RHR heat exchanger back to the pump suction. Because the cooling flow to the RHR heat exchanger is isolated, there is a 30 minute limit for pump operation on mini-flow to prevent overheating. Should the 30 minute limit for RHR pump mini-flow operation be noted in the EOPs? Does the 30 minute limit take into account thermal expansion of the water trapped in the system?

Resolution

4

This item is considered closed.

The EOPs instruct the operators to trip the RHR pumps if the RCS pressure (including instrument errors) is greater than the shutoff head of the pumps. The EOPs do not have a note or caution regarding running the RHR pumps for more than 30 minutes on mini-flow. According to training (Bill Cote), this is not required because the operators are trained on the RHR mini-flow heat up problem.

Relief valves on RHR piping upstream of 8809A&B would open to limit the pressure increase due to thermal expansion.

0

Item 15 - EOP ES-1.3 Step 2.n RNO vs. Design Basis Assumption

Recovery procedure ES-1.3 (Step 2.n, response not obtained column) requires the operator to line up the RSS through the RHR line if both charging pumps are not available (due to a 50 gpm leak passive failure for example). Have analyses been done to show that the RSS pump in this line up would be able to support the NPSH requirements of the running SI pumps? Have analyses been performed to show that the P.HR piping (downstream of 8809A&B) is qualified for recirculation? Is this mode of operation consistent with what's described in the FSAR.

Resolution

CR M3-97-1545 had previously been written to address this item. This item is considered closed.

The RNO instructions were developed to address what was originally considered to be an event that went beyond the design basis. The potential 50 gpm passive failure that would make both charging pumps inoperable after 24 hours is, however, a design basis assumption. The necessary analyses to support this line-up will be done to address the CR.

Item 16 - RSS Pump Flow

Design changes have been made that require the RSS spray header valves (20A&B) to be open and the cross tie valves (8838A&B) to be locked closed (DCR M3-97045). Does the flow rate in this configuration exceed the 5000 gpm limit for the RSS heat exchanger, especially soon after the pump start when the header is empty? Are the runout and NPSH requirements for the RSS pump met under these conditions?

Resolution

This item is considered closed.

An orifice was recently installed in each of the RSS pump discharge lines to limit the flow rate to a maximum value of 3300 gpm when the header is empty. See Safety Evaluation E3-EV-97-0043 for DCR M3-97045.

Item 17 - Possible Sump Boron Dilution Due to RHR Piping Volume

When the RHR system is in service, it is filled with water having a boron concentration equal to the cold shutdown boron concentration of the RCS. During surveillance testing, prior to startup, the operator opens valve V43, which recirculates back to the RWST, to ensure the boron concentration in each train is the same as the RWST (See operating procedures OP-3310B and OP-3208B). This fills the RHR system behind valve 8809A&B with RWST (borated) water. The volume of water between valves 8809A&B and the RCS loops may be significant and may be at a lower boron concentration. Following a LOCA, this water could be available for sump dilution. Has this been considered in the RWST boron concentration limits calculation?

Resolution

This item is considered closed.

The RWST boron concentration calculation conservatively assumes all of the RHR piping is filled with water at the RCS pre-trip equilibrium xenon boron concentration.

Item 18 - QSS: Potential Deadheading of QSS Pump

The QSS pumps do not have mini-flow lines. If either discharge valve (MOV 34A or 34B) failed to open after a CDA signal was generated, the associated QSS pump would deadhead. Assuming the operator did not trip the affected pump, would the pump seal or something else develop a leak? If so, what is the maximum estimated leak rate for such a failure? Does this pose a flooding concern, or a possible significant loss of RWST inventory?

Resolution

CR M3-97-4158 was written to request information regarding the leak rate and to address the potential flooding concern.

There are low flow and high temperature alarms that would alert the operator to this condition. However, according to training (Bill Cote), the operators would not trip the deadheaded pump as long as a CDA is present.

Item 19 - OSS: Pump Starts with MOV 34A Full Open

If the QSS pump discharge valves (MOV 34A&B) fully open before the QSS pumps start, the pumps would be starting against an empty, low resistance system. This might require more than the normal starting current. Could the pump breaker trip?

What happens if a loss of off-site power is assumed and either a safety injection or CDA signal occurs after the diesel sequencer passes the SI or QSS pump start point; could these pumps start immediately (i.e., out of sequence) and potentially overload the diesel?

Resolution

This item is considered closed.

The flow rate is limited by an orifice at the QSS pump discharge. Even with an empty header, the pump horsepower would be less than the rated motor horsepower (500 hp). The breaker over-current setpoint is based on the rated motor horsepower.

The sequencer is reset following a safety injection or CDA signal. None of the current diesel loads (that had been loaded during the LOP sequence) are stripped during the process. The QSS pumps would be started at the specified time on the CDA sequence and the other loads would continue to run when specified to be loaded again on the CDA sequence. The diesel loading calculations are done in calculation NL-033.

Item 20 - RWST Cooling Isolation

The RWST temperature is maintained by pumping the borated RWST water through a separate heating/cooling system. The RWST heat/cooling system suction valves (AOV 27 and 28) get a signal to close on an SI. These fail close valves are located outside in the yard, next to the RWST. Are these valves on EQ (or some other program) to make sure the solenoid is capable of opening (and thus closing the valve) when required, i.e. no snow or ice, etc. is blocking the solenoid? This same question applies to the DWST also (there are similar valves in its heating/cooling lines).

Resolution

This item is considered closed.

The RWST heating/cooling system suction valves have been tested <u>quarterly</u> for 10 years (per SP 3609.9) and only failed once. Since the valves have been operated no numerous occasions during winter months with only one failure, we consider this design to be reliable. The DWST valves are in a doghouse.

Item 21 - ECCS Leakage Measurement

How is ECCS leakage controlled? Since the leakage is measured at cold conditions, does this leak rate apply at hot conditions (during recirculation)? This issue was raised during a design inspection at another plant.

Resolution

This item is considered closed.

Millstone Unit 3 has a design leak rate limit of 5000 cc/hr. The leak rates measured in the following surveillance procedures are summed to yield the total measured leak rate.

3604A.1-2 3604A.1-3 3604A.2-2 3604A.3-2 3606.1-2 3606.2-2 3606.3-2 3606.3-2 3606.4-2 3608.1-3 3608.2-3 3613A.2-1 3613A.2-2

Standard Review Plan section 15.6.5, Appendix B states that the leak rate used for the dose analysis should be twice the design leak rate ("sum of the simultaneous leakage from all components in the recirculation systems above which the technical specifications would require declaring such systems to be out of service."). Accordingly, the LOCA analysis assumes a leak rate of 10,000 cc/hr. The use of a leak rate that is twice the design leak rate for the dose analyses should account for any increase in the measured leakage at hot vs. cold conditions.

Item 22 - Thermal Shock to RSS Heat Exchanger

The RSS heat exchanger is a once through heat exchanger. The RSS heat exchanger may be filled with cold service water prior to the start of recirculation. Has it been designed to withstand the thermal shock when 260 F sump water begins to flow through the tubes?

Resolution

DCR M3-96054 is the issuing document to identify all changes relating the RSS heat exchanger. The heat exchanger manufacturer has analyzed the heat exchanger for mechanical and thermal performance based on the following revised design parameters: Shell side design temperature increased from 235 F to 260 F. Tube side design temperature increased from 200 F to 260F. The heat exchanger data sheet contained the minimum temperature of 35 F for the service water. The design change is documented by DCN DM3-S-0324-96 and DCN DM3-S-0626-96.

Item 23 - RSS Water Hammer

If containment pressure were to reach the CDA limit, then subsequently fall below 17.5 psia, EOP 35 E-1 (Step 8) would instruct the operator to turn off the QSS pumps, and also the RSS spray pumps (if RWST level were greater than 520,000 gal). After the RSS pumps are tripped, the hot water from the sump could drain back, leaving steam void behind. When the RWST level falls below 520,000 gallons, the operator transfers to the sump recirculation and restarts the RSS pumps per EOP 35 ES-1.3. Could the restart of RSS pumps cause water hammer in the RSS piping?

Resolution

This item is considered closed.

A recently installed orifice at the RSS pump discharge limits the flow rate to a maximum value of 3300 gpm. A baffle plate has also been added to the RSS heat exchanger inlet. Stone and Webster has done a calculation which shows that the water hammer loads are acceptable at the 3300 gpm flow rate. See Safety Evaluation E3-EV-97-0043 for DCR M3-97045.

Also, as part of the DCR, the EOPs will be reviewed to determine if the RSS pumps should be allowed to stay running, instead of being tripped by the operator. The Emergency Response Guidelines (ERGs) trip the spray pumps, but these pumps do not provide recirculation cooling like the RSS pumps do at Millstone Unit 3. Allowing the RSS pumps to continue to run in the Millstone Unit 3 EOPs would not seem to de any harm to the system and would eliminate this potential water hammer concern. As a result of the review, a procedure modification could be suggested.

Item 24 - Throttle Valve Settings

Are SI and charging pump throttling flow valves set for hot (recirculation) or cold (injection) water temperature?

Resolution

This item is considered closed.

The flow calculations were done assuming higher water temperature (Discussion with George Konopka, Westinghouse 12/10/97). At higher temperature, no adverse effect on the charging or SI pumps expected, but there would be some cavitation in the injection lines. The extent of cavitation would be small, since the injection conditions to the loops are very near to the suction conditions for the RSS pumps, and the fluid properties between these two locations is not expected to change.

Item 25 - SI Pumps: Common Mini-flow Line

Two SI pumps share a common 3 inch mini-flow line back to the RWST. Could the stronger pump could potentially deadhead the weaker pump? This was one of the NRC question also.

Resolution

This item is considered closed.

Each line from the pump discharge to the common mini-flow line has a flow orifice which takes most of the pressure drop, therefore, it is unlikely that one pump could be deadheaded. The NRC question was addressed.

Item 26 - HVAC: Intake Structure Cooling

The intake structure has 2 SW pumps in each of the 2 cubicles. A separate fan is used to cool each cabicle. The intake structure also has non-safety grade heating units for winter. The vertilation calculation assumes 1 SW pump running in each cubicle. By procedures, a second service water pump could be started after 4 hours to provide flow for fuel pool cooling. The ventilation calculation is inconsistent with operation.

Resolution

This issue is currently being addressed by a previous CR M3-97-3283. The ventilation calculation is being re-done.

Item 27 - AFW Suction Swap from CST to DWST

The AFW pump draws suction from the CST during startup and shutdown (below 10% power). If, during this period, an AFW initiation signal occurred, the suction valves to the CST would automatically close and at the same time the suction valves to the DWST would automatically open. These are fast acting (< 2 second) butterfly valves but are not interlocked to ensure that flow path from the CST is not closed off before path from the DWST is established. Could the running AFW pumps cavitate during the transfer?

Resolution

CR M3-97-4157 was written to address this issue.

a

Item 28 - Mini-Flow for AFW

Is there a time limit for running the AFW pumps on mini-flow? The EOPs do not specify any time limit and the AFW pumps are not tripped.

The minimum flow issue for the AFW pumps has been reviewed extensively in the past. Therefore, a background discussion in needed to show the remaining issue which has not been addressed completely.

Background

Commercial operation commenced April, 1986. A brief history of the AFW pump miniflow issue is provided below.

NRC Bulletin 88-04 issued.

June 1989. Letter to NRC The auxiliary feed pumps do show some indications that damage may be accumulating due to operation at relemmentation. However NUSCO does not believe there is a problem with the minimum server provided for these pumps. Engineering evaluations of these pumps are continuing.

April 22,1992. Sulzer-Bingham advised NUSCO to increase minimum flows

May 8,1992. Phone conversation between NUSCO and Sulzer-Bingham. Sultzer-Bingham was asked why the minimum flow rates were increased. The response was that the original analysis performed years ago did not identify pump damage at low flow. It was later identified that the flows should be increased to reduce the potential for impeller damage et low flows. Sultzer-Bingham indicated that the damage is gradual and not immediate.

May 11, 1992. Letter from Pete Clark to Gerry Drechsler (letter no. PSM3-92-310) indicates that there is a pump performance monitoring program, i.e. vibration monitoring, in place that is tracking pump degradation.

Oct. 16, 1993. Inter office memo from Pete Clark to Barret Nichols indicates that the rotating assembly for pump #FWA*P1A was replaced in August 1993. There was some minor internal damage to the pump casing and upon inspection by Gerry Dreschler it was determined not to be significant nor did it occur from cavitation. The damage was easily weld repaired. The memo continues on to specify that the minimum flow will not change, and pump performance will continue to be monitored along with additional inspections when the pumps are rebuilt in the future.

March 7, 1994. NRC inspector reviewed licensee's documentation of the minimum flow provisions for the AFW pumps and reported the following findings.

The adequacy was noted to be marginal, but the very limited frequency and duration of pump operation indicate that the pump minimum flow remains acceptable. There is some concern due to the previous indication of pump casing wear which required weld repair. Discussions with engineering personnel indicated that the casing wear was attributable to an original casting problem and possibly minimum flow operation. However the wear was very minor and pump disassembly revealed no other indications of pump degradation due to minimum flow operation. The IST program on the safety-related pumps is capable of detecting pump wear due to low flow operation via vibration monitoring. Operation of the pumps in minimum flow conditions is very limited.

Auxiliary feed water pumps are tested quarterly in modes 1, 2, or 3. Also the pumps are flow tested every refueling in modes 5, 6, or 0.

Operating procedure (OP 3322) or EOPs do not contain any precaution against extended operation at minimum flow.

Outstanding Issue

A CR (M3-97-4531) was written to address the issue of potential for operation for long term at the minimum flow. At issue is the following;

NRC Bulletin 88-04 requested licensees to evaluate the adequacy of the minimum flow bypass lines for safety related centrifugal pumps resulting from operation and testing in the minimum flow mode, and that the evaluation should also include verification from the pump manufacturer that current mini-flow rates are sufficient to ensure no pump damage from low flow operation.

The revised minimum flow rates recommended by the Auxiliary Feed Water (AFW) pump manufacturer, Sulzer-Bingham, for the motor driven pumps went from 45 gpm to 90 gpm during intermittent operation or less than approximately 2 hours, and to 126 gpm for continuous operation or greater than 2 hours. For the turbine driven pump, minimum flow went from 81 gpm to 150 gpm during intermittent operation and to 230 gpm for continuous operation. Reason for the increase of flow requirements is that the original analysis did not identify or consider pump damage at low flow.

Because the potential for pump damage at low flow occurs gradually and not immediately, Millstone Unit 3 did not increase the minimum rates as recommended by the manufacturer. Instead, a monitoring program (IST) was implemented to frequently monitor pump performance and vibration to maintain a historical record to predict future pump damage. The IST program is implemented and appears to be effective. However, the extended operation concern for minimum flow operation has not been conveyed to operations and training personnel. According to current operation procedures, the auxiliary feed water pumps can be operated indefinitely on minimum flow which may enhance potential for pump damage from low flow conditions.

Resolution

CR M3-97-4531 was written to ensure that the extended operation concern at the minimum flow be conveyed to the operators either through procedure changes or the training.

Item 29 - Long Term Usage of DWST

The design basis for small LOCA is to continue to use the steam generators (AFW and steam relief) and RSS for long term cooling. Therefore, a safety grade water source for AFW will be required for long term cooling. What instructions are provided to the operator for aligning alternate sources for AFW? Is another safety grade source for AFW available?

Resolution

This item is considered closed.

The loss of secondary heat sink function restoration procedure, EOP 35 FR-H.1, instructs the operator to transfer to the CST, if the DWST level is less than 80,000 gallons, and then refill the DWST with city water or the ecolochem system. Although the service water system is a long term safety grade source of water (MNPS-3 FSAR, July 1997, pg. 10.4-45), these non-safety grade systems are preferred over the safety grade service water system.

The loss of secondary heat sink procedure does not explicitly instruct the operator to align the AFW pumps to the safety grade service water system. However, if the heat sink could not be restored while using FR-H.1, the operators would contact the ADTS for additional instructions and the ADTS would recommend alignment to the service water supply at that time.

Item 30 - Full Flow Testing of Check Valves

The SI pumps have check valve V11 in their common line from the RWST header. Similarly, the charging pumps also have a check valve (V268) in their common line from the RWST header. Has full flow testing been done to assure these check valves will swing full open and assure adequate NPSH for the pumps? If the check valves fail to fully open, the pumps could cavitate, especially at low RWST level when the available NPSH will be low. Not testing at full flow may also be in violation of the intent of the IST program requirements.

Resolution

CR M3-97-4156 was written to address this item.

These check valves are not full flow tested. The valves are tested by operating a single pump at a time. This is not full flow testing since both SI and both charging pumps should and probably would start following a safety injection signal.

Item 31 - Charging Suction Valves from RWST

The charging pump suction valves (112D&E) to the RWST are controlled to open on low VCT level (<4.4%). These valves are supposed to be closed for sump recirculation. If the VCT level is less than 4.4% at the time of transfer to sump recirculation, the operator will try to close valves 1'2D&E, but the control system would try to keep them open. Prior to initiating sump recirculation, the operator resets SI, however, he does not bypass the low VCT level signal to these valves. The valves do not have a pull-to -lock position. Does the procedure for transfer to sump recirculation (EOP 35 ES-1.3) consider this scenario?



Resolution

CR M3-97-4342 was written to address this item.

The procedure does not consider this scenario. The procedure had been revised to remove power from the valves to address the scenario in which the VCT level falls below the VCT low level transfer setpoint after the system had been placed in recirculation mode. This modification does not, however, address the scenario described above.

Item 32 - Draining of Service Water Piping following a Loss of Offsite Power

Following a loss of off-site power, both operating service water pumps would stop until picked up by the diesel generator. In the meantime, the service water header could drain in the forward direction; reverse draining is prevented by check valves. The outlet for the service water system is below the water surface and therefore, draining of the piping will cause low pressure (vacuum) and water vapor could form. Water hammer in the service water piping could occur after the pump are restarted.

LOP/SI tests one train at a time. The operating train will keep the other train under test pressure until MOV 71 closes, which has a stroke time of 30 seconds or so. Hence, the test does not represent post- LOP condition where draining could occur.

Resolution

This item is considered closed.

A review of the isometrics (with Steve Pietrick) indicates there are no open vents or vacuum breakers for service water in the following locations:

- The CCP heat exchanger.
- The P3 pump
- The diesel generator heat exchanger outlet piping. (The diesel generator header is protected by the vent at the top of the HVK heat exchanger.)

Pre-operational tests of the service water system (U-12179-1398, "Service Water System Hydraulic Transient Test", January 1985) show that the CCP heat exchanger header does not drain and no gap forms in the time needed to restart the service water pumps following a loss of normal power, including the diesel generator start time (40 seconds). During this time period, only the HVK heat exchanger, which has a vacuum breaker, drained. Since the CCP heat exchanger and the rest of the system remains full, there are no water hammer concerns.

Item 33 - Service Water: Single Failure

If a safety bus (34C or 34D) is the single failure, one train of service water pumps will be inoperable. Assuming the A train has no power, MOV 71A will remain open. The running SW pump on the B train will provide flow to both the non-essential header (via valve 71B) and to the essential header until the non essential header is isolated by closing of valve 71B. If MOV 71B does not receive a signal to close, the running pump could potentially fail to provide adequate flow to the essential header. Will MOV 71B get a closure signal under this condition?



Resolution

6 mg

This item is considered closed.

In this scenario, only one SW pump on B side will be operating. Valve 71B will initially be open. Therefore, the running pump will provide flow to both essential and nonessential headers. A calculation documented in memo MP3-DE-97-1310 shows that with one pump operating, pressure in the vicinity of valve 71B will drop to 19.7 psia (about 5 psig). Valve 71B gets a closure signal when pressure drops to 25 psig. Therefore, valve 71B will close on low pressure. Also, the second SW pump on Side B may start due to low pressure at the pump header. Isolation of valve 71B or start of the second pump will ensure of adequate flow to the essential header.

Item 34 - CCI Heat Exchanger and Associated Piping

The CCI heat exchangers and piping are needed to remain operable for an extended period of time to provide lube oil cooling to the SI pumps. These heat exchangers are located near the SI pumps and may be inaccessible (due to radiation) during sump recirculation phase. There is a concern that the small bore piping in the heat exchangers could tail without prior warning.

Resolution

This item is considered closed.

A surveillance monitoring procedure is available for trending potential degradatio... of the heat exchanger tubing.

Inspection of the CCI and CCE heat exchangers is performed via procedure EN 31084. Trending of heat exchanger performance data is performed via procedure SP 3626.13 and forms 3626.13-1, -2, and -3. In addition to heat exchanger performance, the U-bends of the heat exchanger are installed with threaded coupling and the U-bends are removed, inspected, and the findings documented.

Item 35 - Single Reference Leg to VCT Level Transmitter

INPO recently issued SOER 97-1. This document describes a situation in which plants that have a common reference leg for the VCT level transmitters could have an erroneous level indication on both channels. Such an erroneous indication may go undetected due to common mode effect. Millstone Unit 3 has separate reference legs, however, they are connected to common upper and lower taps to the VCT.



Resolution

1.

This item is considered closed.

The isometric drawing for the VCT level transmitter instrumentation was reviewed and a walk down of the installation was performed to determine the configuration of the reference leg and taps into the VCT. The lower level tap which is common to both transmitters, is connected to an approximate 4 foot horizontal section of 1 inch diameter piping. The pipe slopes downward toward the transmitter diaphragm and capillary filled tubing. If a non-condensable gas were present in the horizontal pipe run, it would have a minimal impact on the indicated level. A void in the vertical capillary tubing connected to the transmitter would most definitely affect the transmitter level indication. MP3 design has separate vertical lines for each transmitter. Also, the vertical line is physically separated from the VCT by the diaphragm and is not subjected to the VCT internal atmosphere. Becaus: of the level transmitter installation and diaphragm separating the VCT from the transmitter, the accumulation of non-condensable gas in the sensing line affecting VCT level installation is not a concern.

Item 36 - EQ for AOV 31 and MOV 17

Why aren't the steam isolation valves 31 and 17 to the Terry turbine in the EQ program?



Resolution

þ

.

This item is considered closed.

According to NU calculation 97-ENG-1329-M3, Rev. 1 and NU memo RB-97-040, these valves are located in a break exclusion zone and non-harsh environment.

Item 37 - Technical Specification Bases Definition for "Accessible"

In order to meet the Technical Specification surveillance requirement to verify that the ECCS piping is full (4.2.5.b.1), Millstone Unit 3 vents the "accessible" ECCS piping every 31 days. The word "accessible" is used in the Millstone Unit 3 Technical Specification Bases to describe which ECCS high points must be vented. In practice, Millstone Unit 3 only vents the ECCS high points which are located outside containment. Is this definition for "accessible" still applicable (considering the Millstone Unit 3 normal operating containment pressure is closer to atmospheric now) and consistent with the rest of the industry?

Resolution

CR M3-97-4535 was written to address this item.

According to Westinghouse (Chris Morgan), other licensees do not necessarily assume that all piping in side the containment as "in-accessible" and therefore, need not be checked to ensure that it is full of water every 31 days. He also indicated that the venting is not the only means of verifying that the line is full of water. Some licensees address TS requirement 4.2.5.b.1 by verifying the piping is filled prior to mode 4 (checked by v(eting), then follow a checklist procedure every 31 days to verify that no valves were manipulated which could have introduced non-condensable gas in the piping. The checklist identifies all of the evaluations (such as filling the SI accumulators) which could potentially allow gas to enter the ECCS piping. These licensees assume that once the ECCS piping is filled, it should remain that way unless something is done to allow gas to enter the piping.

There may be other options to venting which could be used to meet the TS requirement to verify that the ECCS piping is filled. Millstone Unit 3 should examine other options and/or make sure the definition of "accessible" is still applicable.

Item 38 - CC and SI Pump Seal Qualification

The charging and SI pumps could be exposed to hot (230 F) water from the sump following the transfer to recirculation. Are these pumps and their seals qualified to this temperature limit?

Resolution

This item is considered closed.

Westinghouse calculation P-EC-326, rev. 0 states that the design temperature for both the pump suction and discharge is 300 F.

Item 39 - Throttle Valve Erosion

The charging, SI and RSS pumps all have throttling valves downstream of their discharge. Are these valves susceptible to erosion during extended use following an a selent.

Resolution

This item is considered closed.

Erosion of throttling valve internals due to cavitation was previously identified as impairing the present design. DCR-M3-96077 was written and provided the design basis for implementing a plant modification to resolve this issue. Permanent barrel type orifices were installed in the injection lines in series with the throttle valves. The orifices were sized to provide a large pressure drop and the throttle valve would only be used for fine tuning the pressure to the required value. The valve minimum opening requirement assures that the internal cross section corresponds to a velocity that will not promote any accelerated erosion. Similarly, erosion will be minimized in the barrel orifices because of the straight smooth path of the barrel insert and also due to the selection of special hardening materials.

Item 40 - Qualification of Heat Tracing

The RWST level indication is used by the operator to determine when to transfer to recirculation. This parameter is classified as an essential post accident monitoring instrumentation in the Technical Specifications and is classifies as Type A variable in RG 1.97. The sensing line to the transmitter is vulnerable to freezing during scident. Is the heat tracing on it safety related?

Resolution

CR M3-97-4698 was issued to resolve this item.

The original heat tracing specification 2286.000-274 specifies that separate, duplicate electrical heat tracing shall be installed where freeze protection is required in safety related lines, valves, and components. Backup tracing shall be provided if the primary section malfunctions, and the power supply for each section of the heat tracing will be connected to independent buses.

The actual plant installation has two heat usering panels, 3HTS-PNLF1 and 3HTS-PNLF2, that service the safety related requirements. These panels are powered from safety grade buses 32-1R (3EHS*MCC3A1) and 32-1W (3EHMS*MCC3B1), but the safety grade power is isolated from the panels by safety grade isolation transformers. It can therefore be concluded that the heat tracing system as well as the supplied power servicing the safety related system is not safety grade. Investigations to provide the justification for installing the safety grade isolation transformers between the safety grade bus and the heat tracing panel that establishes the current condition of a non safety related system supporting the operability of a safety related system was to no avail.

1

Item 41 - System Operability during Surveillance or Other non-Standard Line-up

The review of the surveillance procedures, normal operating procedures and discussions with the operation personnel, suggest that certain systems are not declared inoperable and appropriate Tech Spec action statements are not entered when the system line-up is modified during the surveillance. For example:

- SI pump mini flow valves (8920 and 8814) are stroked for surveillance purposes (SP 3608.6, a quarterly test). These valves do not receive an open signal on 3I. Therefore, during the time when the mini flow valve is closed, if a pump start signal is generated, the pump could dead-head until the valve is opened by the operator. In other words, an operator action is needed to restore the system, which is supposed to be fully automatic. Therefore, the corresponding SI pump may have to be declared inoperable while the valve is closed. One could argue that since the valve is closed only for a very short period of time, we need not declare the pump inoperable. We are not sure of any cut-off time period for such a decision. Our understanding is that other plants (e.g., MP1) declare the equipment inoperable under similar circumstances.
- Accumulator pressure is controlled by opening the N2 supply valves or by opening N2 vent valves. N2 vent valves (SV-8875 and HCV-943) do not receive any accident signal to close. Therefore, when the valves are open, the operability of the accumulator is a suspect since some N2 will leak out of the open line and thus would reduce injection to RCS.
- Various vent and drain valves in the ECCS system piping are opened to ensure that the piping is full of water (TS surveillance 4.5.2.b). However, we don't know of any special provision in the program which implements TS 6.8.4.a (minimizing leakage from those portions of the ECCS systems which would see radioactive fluids) to allow opening of these valves. Our concern is that when these valves are opened, we may be violating the intent of TS 6.8.4. As we understand, the vent and drain valves are not left open unattended. Maybe that is all we need to ensure that the intent of TS 6.8.4.a is not violated, however, a more definitive/ formal position may be needed.

Resolution

CR M3-97-4640 was generated to address this item.

Item 42 - SI Reset Single Failure

The operator is instructed to reset both trains of SI in the following scenarios: 1)in a LOCA prior to the transfer to sump recirculation, 2) in an inadvertent safety injection signal to prevent overfill of pressurizer and 3) in a SGTR to prevent overfill of the SG. A single failure of the SI reset switch could hamper operator's task to terminate SI injection in a timely manner since additional actions will be needed before injection from the ECCS train with the failed SI reset switch could be terminated. Hence the total time needed to terminate SI injection would be needed. The EOPs do not provide any guidance. (The response not obtained column contains no guidance.). Also, this scenario is not one of the standard training scenarios.

Resolution

CR M3-97-4536 recommends either a procedure modification or additional training be implemented to address this item.

Failure to reset is probably most critical for SGTR, where timely termination of injection in needed to prevent SG overfill. However, generic analyses performed by Westinghouse show that the failure to reset SI is not the limiting failure for the SG overfill analysis (WCAP-10698-PA). There is at least 30 minutes for operator action between the time SI was suppoded to have been reset and the time the charging/SI pumps are realigned for normal charging. This allows plet by of time for the operator to recognize the failure to reset SI and to address the problem.

Item 43 - Breaks in AFW Lines

A break upstream of the cavitating venturies in the AFW lines is not analyzed. Such a break could result in a spillage of a TDAFW and one MDAFW pump, leaving only one MDAFW pump for mitigation.

Resolution

This item is considered closed.

CR M3-97-2556 (generated by Jim Craffey) addresses this issue. A white paper "Technical Paper for Potential HELB Between the CAV and the First Check Valve in the AFW System" provides the Northeast Utilities position.

The review team agrees with the conclusions of this paper. A break in this area will result in a 300 gpm leak for the affected steam generator. This leak rate does not result in a reactor trip and therefore, is not required to be postulated in the FSAR Chapter 15 Feed Water Line break spectrum. The HELB aspect of the break can be mitigated by either the normal feed water train (since no loss of off-site power assumption is made) or the AFW train.

Item 44- Load Center Rack Out

A load center could be partially or completely removed for service. Is the cabinet declared inoperable without the breaker? Is the cabinet seismically qualified without the breaker?

Resolution

This item is considered closed.

These issues have been addressed for the 4160V and 480V breakers at Millstone Unit 3. The 4160V breaker cabinets were addressed in CR M3-96-1142. An evaluation of the 480V breaker cabinet seismic qualification was documented in ER-96-0362.

Attachment 4

Copies and Condition Reports Generated by the Review

-

Integrated System Functional Review for Millstone Unit 3

MP3 IFSR CR Listing

J

K

CR #	Subject	Recommendation	
M3-97-4130	ECCS Venting Surv. Procedure Enhancement	procedure change prior to mode 4	
M3-97-4131	ECCS Suction Piping - Gas Entrapment	modification required prior to mode 4	
M3-97-4156	Charging & SI Check Valve Full Flow Testing	requires surv. procedure mod. pror to mode 4	
M3-97-4157	CST and DWST to AFW Valve Interlock	evaluation may be needed prior to mode 4	
M3-97-4158	Potential QSS Pump Failure No Min- flow	formal calc. required and mod. if needed prior to mode 4	
M3-97-4342	CVCS 112D&E and VCT Lowlow Level Interlock	procedure change prior to mode 4 and eventua modification required	
M3-97-4343	VCT H2 Cover Gas Leakage Into CVCS Issues	surv. procedure mod. required and reportable if as found condition indicates leakage prior to mode 4	
M3-97-4530	CVCS Letdown Isolation Recommendation	need not be implemented prior to mode 4 considered an enhancement	
M3-97-4531	AFW Min-flow Requirements	enhance training program	
M3-97-4532	ECCS Potentially Drained in Containment from CV Testing	Surveillance procedure needs to be modified prior to mode 4.	
M3-97-4535	TS Clarification on ECCS "accessibility"	evaluation required to revisit our position prior plant startup	
M3-97-4536	EOP Enhancement for SI Reset Failure	evaluation required prior to mode 4	
M3-97-4640	System Operability Determinations During Surveillance Line-ups	procedure mod. prior to mode 4	
M3-97-4698	Non-Safety Grade Heat Tracing On RWST Level Indication	needs evaluation for exemption prior to mode 4	

CR Form Initiation initiator (please Discovery date: 8: Discovery time: 11/ condition was discovered re enhancement to prom	Effective Date type or pri Affected /5/97 1 2 organization cree pt action in the ev	CR (nt): Unit(s): 3 C ating condit	CR M3-97-4130 System #: ECCS ion, what activity was in progress
CR Forn Initiation initiator (please Discovery date: 8: Discovery time: 11/ condition was discovered re enhancement to prom	Affected organization cree organization in the event	CR (nt)_ Unit(s): 3 C ating condit	CR M3-97-4130 System #: ECCS ion, what activity was in progress
v initiator (pleas Discovery date: B: Discovery time: 11/ condition was discovered re enhancement to prom	Affected Affected (5/97 1 2 , organization cree	Unit(s): 3 C C ating condit	System #: ECCS ion, what activity was in progres
Discovery date: B: Discovery time: /// condition was discovered re enhancement to prom	Affected ///97 1 2 , organization cree	Unit(s): 3 C C ating condit	System #: ECCS ion, what activity was in progres
Discovery time: /// condition was discovered re enhancement to prom	$\frac{19}{97}$ 1 2 , organization cre pt action in the ev	ating condit	ion, what activity was in progres
re enhancement to prom	, organization cre pt action in the ev	ating condit	ion, what activity was in progres
ap suction piping. This	and currently do condition was dis	not require a covered duri	is detected during the monthly any action if gas is detected (an ing a Functional System Review. Continuation Sheet
ed upon trend or amount	Eng. Disp.# detected, require	root cause a	Continuation Sheet
			Continuation Sheet
	Time: 3	.00	Continuation Sheet Phone No.:
athit	Time: 3	1/19/97	Continuation Sheet Phone No.: Cost Control Center:
an Histair.	Time: 1	1 <u>/14/97</u> 2830	Continuation Sheet Phone No.: Cost Control Center:
AMA:STAIR. 9/ Slav	Time: 1 Date: 1 Time: 2 Date: 1	00 /14/97 930 1-19-9	Continuation Sheet Phone No.: Cost Control Center:
AM H. STAIR J. Stair J. Slas perability/Reportal	Time: 1 Date: 1 Time: 2 Date: 1 Date: 1	00 //4/97 930 1-19-9 g.Designe	Continuation Sheet Phone No.: Cost Control Center: Phone No: Phone No:
Perability/Reportal effect on plant or person 4400') or plant operation	Time: 1 Date: 1 Date: 1 Date: 1 Date: 1	00 //4/97 230 1-19-9 g.Designe	Continuation Sheet Phone No.: Cost Control Center: Phone No: Phone No: Cost Control Center:
Perability/Reportal effect on plant or person 4400) or plant operation required to be completed	Time: Date: _/ Date: Date: pillity;Screenin nel safety, operat	00 //4/97 530 1-19-9 g.Designe	Continuation Sheet Phone No.: Cost Control Center: Phone No: Phone No: Cost Control No: Cost Control Center:
AM H. STAIR. perability/Reportal effect on plant or person 4400) or plant operation required to be completed	Time: Date: _/ Time: Date: Date: Date: Dillity: Screenin nel safety, operat	9-97	Continuation Sheet Phone No.: Cost Control Center: Phone No: Phone No: Cost Control Center: Cost Center: Co
	ed upon trend or amount	Eng. Disp.# ed upon trend or amount detected, require	Eng. Disp.#

/s/ P. D. Hinnenkamp		ive Date		97-535 SORC MIR	No
Form Approved by	Enec	The Date			140.
	CR Form		CRNO	CR M3-9	7-4131
	Initiation				
ection 1: To be completed by	initiator (please type	or pr	int)	San the good	A gene in the
ganization identifying condition:	Discovery date: 8.00 Discovery time: 11/19/97	Affected	Unit(s):	System #: E	CCS
when event was discovered): r TS 4.5.2.b 1) the following ECCS piping * piping upstream of MV8807A & B and * piping between V982 & MV8804A (co * piping between V983 & MV8804B (co rese sections of piping are put into service vis- sociated piping has the potential for having ocedures and isometric drawings were revised 10A.3/3610A.3-1, and isometric drawings of 6. Attached is a rough sketch of the pipi- unctional System Review, sponsered by the	has not been verified full of will just downstream of V982 (co mmon suction to CHS and SI mmon suction to SI pumps - s when switching from the RWS air or H_2 entrapment due to its two to come to this conclusion; SIH-12 sh 1 of , SIH-13 sh 2 co ing layout based upon the previ- NSAB.	tter at leas mmon suc pumps - s ump recim f to sump physical SP 3606.5 f 6, SIL 1 ous iso's.	tt once per 31 trion to SI put ump recirc.) c.) recirculation arrangement. 5/3606.5-1, 3 sh 1 of 3, SI This condition	days; mps - sump reci following an ev The following 606.6/3606.6-1, L-8 sh 1 & 2 of on was discover	rc.) vent. The surveillance 3608.4/3608.4-1, 6, SIL-10 sh 1 & ed during a
Component Identification Number: Method of Discovery: Self		•		Conti	nuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken				Conti	nuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5				Conti	nuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken Ione required - mode 5 R#	<u>E</u>	ng. Disp.#	-	Conti Con	tinuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5 R#	E	ng. Disp.#	4:00	Conti Con Con Phone No.:	tinuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5 R#	E	ime: //	<u>8:00</u> ./9- 97	Conti Con Con Phone No.: Cost Control Ce	tinuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5 R#	E The stailer	ime: Time:	<u>8:00</u> ./9- 97	Conti Con Con Phone No.: Cost Control Ce	tinuation Sheet [ntinuation Sheet] 832-4740 enter:
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5 R#	E This Al Jons	ime: Time: Date:	-/9- 97 -/9- 97 -/9-97	Conti Con Con Phone No.: Cost Control Ce Phone No:	tinuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5 R# AWO# Recommended corrective action Initiator Name: J.K. Rothert Initiator's Signanure: J.K. Initiator's Signanure: J.K. Supervisor Name: J.K. Supervisor Name: J.K. Supervisor Signature: J.K. Supervisor Signature: J.K. Supervisor Signature: J.K. Supervisor Signature: J.K. Supervisor Signature: J.K. Supervisor Signature: J.K. Method S. Supervisor Signature: J.K. Supervisor Signature: J.K. Method S. Supervisor Signature: J.K. Supervisor Signature: J	E A J. STAIRC A J. J. STAIRC A J. J. STAIRC Erability/Répôrtability fiect on plant or personnel safe	ime: //	9:00 -/9- 97 9820 7-/9-92 g.Designed	Conti Con Con Phone No.: Cost Control Ce Phone No:	tinuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5 R# AWO# Recommended corrective action Initiator Name: J.K. Rothert Initiator's Signanure: J.K. Rothert Initiator's Signanure: J.K. Rothert Supervisor Name: J.K. Rothert Supervisor Name: J.K. Rothert Supervisor Signature: J.K. Supervisor Signature: J.K. Solution Supervisor Signature: J.K. Supervisor	E A H. STAIRC A District of plant operation? Erability/Reportability?	ime: // Date: // Creemin ty, operab	<u>-/9- 97</u> <u>820</u> <u>/-/9-97</u> <u>g.Designic</u> illity, N	Conti Con Con Phone No.: Cost Control Ce Phone No: Phone No:	tinuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5 R#	E A A STAIR A STAIR	ime: // Pate: // Date: // Creeinin ty, operat	9:00 -/9- 97 920 1-19-97 g.Designies	Conti Con Con Phone No.: Cost Control Ce Phone No: Phone No:	tinuation Sheet
Component Identification Number: Method of Discovery: Self Immediate corrective action taken one required - mode 5 R#	E A A. STAIR A STAI	ime: _/ Time: _/ Time: _/ Date: _/ Creemin ty, operab	9:00 -/9-97 9820 1-19-97 g.Designie Mility, N 1-97	Conti Con Con Phone No.: Cost Control Ce Phone No: Phone No:	tinuation Sheet

		9/30/97	97-535
Form Approved by	En	sotive Date	SORC Mtg. No.
	CR Form	CR	CR M3-97-4150
	Initiation	1	
Section 1= To be completed	by initiator (please ty	pe or print)	「日本のない」で、「「「「「「「「「」」
rganization identifying condition: AB	Discovery date: #/20/97 Discovery time: \$10	Affected Unit(s):	System #: CHS, SI
when event was discovered): ack of full flow testing of check valves it only one pump at a time. However, post flow rate. Since the valves are not tested Under current ISI test conditions the check cause cavitation of the operating pumps. NSAB.	in suction lines in CHS and SI sy SI, both CHS and both SI pumps to this higher flow condition, it of this condition was discovered of This condition was discovered of	stem. Check valves N will start and subject cannot be demonstrate open. A partially oper luring a Functional Sy	V261 and V11 are tested by runnin the check valves to a much higher to that these valves will fully lift. In valve may restrict the flow and estern Review, sponsored by the
Method of Discovery: Self			Continuation Sheet
2. Immediate corrective action taken			
none - mode 5			
TR#AWC		Eng. Disp.#	Continuation Shee
			Continuation Shee
4. Initiator Name: Nirmal Jain/J.	K. Rothert	Time: 11/20/97	Continuation Shee Phone No.: 832-4740
4. Initiator Name: Nirmal Jain/J. Initiator's Signature:N(`//	K. Rothert D. Jain D. D. Cotta	Time: <u>11/20/97</u> Date: <u>8:10</u>	Continuation Shee Phone No.: 832-4740 Cost Control Center:
 Initiator Name: Nirmal Jain/J. Initiator's Signature: <u>Ni'vn</u>- Initiator Requests Follow-up: YE Supervisor Name: <u>LallLL</u> 	K. Rothert D. Jain D. D. Deta s I Am H. STAIRS	Time: <u>11/20/97</u> Date: <u>\$:/0</u> Time: <u>0833</u>	Continuation Shee Phone No.: 832-4740 Cost Control Center:
4. Initiator Name: Nirmal Jain/J. Initiator's Signature: <u>Ni'vn</u> Initiator Requests Follow-up: YE Supervisor Name: <u>WILL</u> Supervisor Signature: <u>UILL</u>	K. Rothert D. Jain D. D. Detta s Am H. STAIRS a Albas	Time: <u>11/20/97</u> Date: <u>X:/0</u> Time: <u>0833</u> Date: <u>//-20-9</u>	Continuation Shee Phone No.: 832-4740 Cost Control Center: 2 Phone No: 59/2
4. Initiator Name: Nirmal Jain/J. Initiator's Signature: <u>Ni'vn</u> Initiator Requests Follow-up: YE Supervisor Name: <u>WILL</u> Supervisor Signature: <u>WILL</u> Section 2: For be completed by	K. Rothert D. Jain M. S. TAIRS S. M. S. TAIRS and Stans Operability/Reportability	Time: <u>11/20/97</u> Date: <u>X:/0</u> Time: <u>0835</u> Date: <u>//-20-9</u> Screening:Desig	Continuation Shee Phone No.: 832-4740 Cost Control Center: 2 Phone No: 59/2
 4. Initiator Name: Nirmal Jain/J. Initiator's Signature: Nivman Initiator Requests Follow-up: YE Supervisor Name: WILL Supervisor Signature: WILL Section 2: Fo be completed by 1. Does CR have an actual or potent reportability, (e.g., NGP 2.25, EP) 	K. Rothert D. Tain M. S. TAIRS S. M. S. TAIRS C. M. S. TAIR	Time: <u>11/20/97</u> Date: <u>8:10</u> Time: <u>0835</u> Date: <u>//-20-9</u> Screening:Desig	Continuation Shee Phone No.: 832-4740 Cost Control Center: 2 Phone No: 59/2 mee: Notes:
 4. Initiator Name: Nirmal Jain/J. Initiator's Signature: Nivman Initiator Requests Follow-up: YE Supervisor Name: Will Supervisor Signature: Will Supervisor Signature: Will Section 2.5 E0 be completed by. 1. Does CR have an actual or potent reportability, (e.g., NGP 2.25, EP No 	K. Rothert D. Tain D. D. H. S <i>Am H. STAIRS</i> Operability/Reportability tial effect on plant or personnel s IP 4400) or plant operation? a 3 required to be completed.)	Time: <u>11/20/97</u> Date: <u>8:10</u> Time: <u>0835</u> Date: <u>//-20-9</u> Screening:Desig	Continuation Shee Phone No.: 832-4740 Cost Control Center: 2 Phone No: 59/2 mees
 4. Initiator Name: Nirmal Jain/J. Initiator's Signature: Nirmal Jain/J. Initiator Requests Follow-up: YE Supervisor Name: NILL Supervisor Signature: NILL Section 2: For be completed by 1. Does CR have an actual or potent reportability, (e.g., NGP 2.25, EP Yes or Don't Know (Section No 	K. Rothert D. Jain M. S. TAIRS S Am H. S. TAIRS Operability/Reportability inal effect on plant or personnel s IP 4400) or plant operation? A required to be completed.)	Time: <u>11/20/97</u> Date: <u>\$:/0</u> Time: <u>0833</u> Date: <u>//-20-9</u> Screening:Desig afery, operability,	Continuation Shee Phone No.: 832-4740 Cost Control Center: Phone No: 59/2 Decision Notes: 77 0847
 4. Initiator Name: Nirmal Jain/J. Initiator's Signature: N('M- Initiator Requests Follow-up: YE Supervisor Name: UILL Supervisor Signature: UILL Supervisor Signature: UILL Section 22: Fo be completed by 1. Does CR have an actual or potent reportability, (e.g., NGP 2.25, EP Yes or Don't Know (Section No Keith Cov 	K. Rothert D. Tain D. D. A. A. S <i>Am H. STAIRS</i> Operability/Reportability rial effect on plant or personnel s IP 4400) or plant operation? A required to be completed.) <i>n</i>	Time: <u>11/20/97</u> Date: <u>8:10</u> Time: <u>0835</u> Date: <u>//-20-9</u> Screening:Desig afety, operability, [1-20-0 Date	Continuation Shee Phone No.: 832-4740 Cost Control Center: Phone No: 59/2 Definition Shee 2 Phone No: 59/2 Notes: 77 0847 Time
 4. Initiator Name: Nirmal Jain/J. Initiator's Signature: Nirmal Jain/J. Initiator Requests Follow-up: YE Supervisor Name: With Supervisor Signature: With Supervisor Signature: With Section 2.5 For be completed by 1. Does CR have an actual or potent reportability, (e.g., NGP 2.25, EP Xes or Don't Know (Section No Keith Cov Designee 	K. Rothert D. Tai. D.	Time: <u>11/20/97</u> Date: <u>X:/0</u> Time: <u>0835</u> Date: <u>//-20-9</u> Screening Desig afety, operability, [/-20-0 Date	Continuation Shee Phone No.: 832-4740 Cost Control Center: 2 Phone No: 59/2 meetings and the section number.
 4. Initiator Name: Nirmal Jain/J. Initiator's Signature: N('Main Initiator Requests Follow-up: YE Supervisor Name: Will Supervisor Signature: Will Supervisor Signature: Will Section 2.5 E0 be completed by. 1. Does CR have an actual or potent reportability, (e.g., NGP 2.25, EP A Yes or Don't Know (Section No Keith Cov Designee 	K. Rothert D. Tain D. D. H. S (Am H. STAIRS Coperability/Reportability dal effect on plant or personnel s Operability/Reportability dal effect on plant or personnel s IP 4400) or plant operation? A 3 required to be completed.) in 1.1. Page 7) are required, identify	Time: <u>11/20/97</u> Date: <u>8:10</u> Time: <u>0835</u> Date: <u>11-20-9</u> Screening Desig afery, operability, <u>11-20-0</u> Date	Continuation Shee Phone No.: 832-4740 Cost Control Center: 2 Phone No: 59/2 mee Notes: 77 0847 Time ntinued by section number. Form RP4-1
 4. Initiator Name: Nirmal Jain/J. Initiator's Signature: Ni/Maintain Requests Follow-up: YE Supervisor Name: Will Supervisor Signature: Will Supervisor Signature: Will Section 2: Folde completed by 1. Does CR have an actual or potent reportability, (e.g., NGP 2.25, EP A Yes or Don't Know (Section No Keith Cov Designee 	K. Rothert D. Tai. D. Taiks S D. Tai. D. Taiks S D. Derability/Reportability ial effect on plant or personnel s IP 4400) or plant operation? In 3 required to be completed.) In 1.1. Page 7) are required, identify	Time: <u>11/20/97</u> Date: <u>X:/0</u> Time: <u>08335</u> Date: <u>//-20-9</u> Screening:Desig afety, operability, <u>//-20-0</u> Date	Continuation Shee Phone No.: 832-4740 Cost Control Center: Phone No: 59/2 Decision number: Notes: ntinued by section number. Form RP4-1 Rev. 5 Page 1 of 7

1

•

.

-

/s/ P. D. Hinnenkamp		9/30/97	97-535
Form Approved by	Eff	ective Date	SORC MIG. NO.
	CR Form	CRI	CR M3-97-4157
action I To be completed b	winitiafor (nlease ty	peor print)	BERRY AND BERRY AND A PLAN AND AND AND AND AND AND AND AND AND A
ection 1:310 De completeu c	Discovery data: 11/20/9	7 Affected Unit(s):	System #: DELL
A B	Discovery time: \$:00	10 20 30 C	
Condition description (including how	condition was discovered, org	anization creating con	dition, what activity was in progress
when event was discovered): At low power or during shutdown, the mot ineup, if an AFW initiation signal is gener uction valves from DWST line while simu or interlock to ensure isolation of the CST bump(s) cavitating (any cavitation of these DWST AOVs are considered fast acting va- This condition was discovered during a Fu- Component Identification Number: Method of Discovery: Self	or driven AFW pumps suction ated the suction is automaticall altaneously closing the valves f line only when the DWST line pumps is an undesirable cond alves - stroke time <2 seconds, inctional System Review, spon	is switched from the D y switched to the DW rom CST line. The co is fully open and the p tion) under these circu therefore, a sustained sored by the NSAB.	OWST to the CST. During this ST. This is achieved by opening the oncern is that there is no time delay potential for the running AFW umstances. Note: these CST and cavitation is not considered likely.
Immediate corrective action taken	an a	4	
none - mode 5			
		Era Dim H	Continuation Sheet
TR# AWO	g an ann a' s ann an ann an an ann an an ann an ann an a	Eng. Disp.#	Containation Durer
 Recommended corrective action 			
			Continuation Sheet
A initiator Name: Nirmal Jain/J.k	Rothert	Time: 8:00	Phone No.: 832-4740
Initiator's Signature: Nicanal	Jain JAR Roll	- Date: 1420197	Cost Control Center:
Initiator Requests Follow-up: YES	61	(12/20/17	/
Supervisor Name: WILLIL	14 STAIRS	Time: 0.820	_
1/1/	0/11-	Date: 11.20.6	> Phone No: 591>
Supervisor Signature:	- Alter	Date: 1260-7	The second state of the state o
Section 2:3 To be completed by	Operability/Reportability	Screening Desig	Horas:
 Does CR have an actual or potentia reportability, (e.g., NGP 2.25, EPD 	ll effect on plant or personnel s P 4400) or plant operation?	afery, operatiuty,	NOISS.
Yes or Don't Know (Section)	3 required to be completed.)		
No			08118
Keith Cov	16	11-20-91	0840
Designee	anne a sector of the proceeding of a sector of the line	Date	lune
If continuation sheets (RP 4-	1, Page 7) are required, identif	y the section being con	utinued by section number.
			Rev. 5
			Page 1 of 7
			Sheet 1

*

.....

/s/ P. D. Hunnenkamp	9	30/97		97-535
Form Approved by	Effec	tive Date		SORC Mig. No.
	CR Form	[CF CR	M3-97-4158
	Initiation			
Section 1= To be completed by	initiator (please typ	e or print		時期的增加增加增加增加增加。 新聞的考虑
Organization identifying condition:	Discovery date: 11/20/97	Affected Un	it(s):	System #: QSS
SAB	Discovery time: 8:00	1 2 3		a har a mining a second a second
 Condition description (including how c when event was discovered): The QSS pumps do not have min-flow lines, open. Thus, a deadheaded pump could leak is no interlock between pump motor and val- deadheaded pump as long as CDA is present The potential amount of such leakage is unk discovered during a Functional System Revie 	thus, deadheading of the pump (seal, casing, etc.) resulting in ve open. Also discussions with the effects of such leakage i nown and therefore the severit ew, sponsored by the NSAB.	os could result a consequentia training sugg neluding intern y of its effects	if the downs al unisc atable ests that the o nal flooding i is unknown.	tream NOV34A or B fails to e RWST drainage path. There operators would not trip the may not have been evaluated. This condition was
Component Identification Number.	an manus moreorem manus reason inter- are	P ADDRESS OF BRIDE	a and the second second second	a annual and and annual train and annual
Method of Discovery: Self				Continuation Sheet
	a lar a disk anarow can be a base and a base of the second s			Continuation Sheet []
2. Immediate corrective action taken				
None - mode 2				
TR#AWO#		ing. Disp.#		Continuation Sheet
3. Recommended corrective action	anten, der anten er daten i der besterten er beide statetet er verstere in eine ander anten er beit einen er	and the second second second		and a subsequent the second states. Such assessment in a construction such as a such as the second state of the
at straine actions straining and strain straine strain strains strains		THE RECEIPTION PROPERTY AND		Continuation Sheet
4. Initiator Name: Nirmal Jain/J.K.	Rothert	Time: <u>8:0</u> ,	5	Phone No.: 832-4740
Initiator's Signature: Nirvel.	Sain DZERate	Date: 1/2	0/97 Co	st Control Center.
Initiator Requests Follow-up: YES	P			
Supervisor Name: WILLIAI	4. STAIRS	Time: 08	25	
Supervisor Signature: Costles	St. Slan	Date: 11-2	20.97	Phone No: (5317
Section 2 To be completed by O	perability/Reportability	ScreeningI	Designee	運営を発展していた。
1. Does CR have an actual or potential reportability, (a.g., NGP 2.25, EPIP	effect on plant or personnel sal (400) or plant operation?	ety, operabilit,	y, Notes	1999 (Particular Content of Conte
Yes or Don't Know (Section 3 r	equired to be completed.)	-		-
Kin Ar	states want water states to be being to be	11-20-	.97	0848
neith LOVIN	an and the state of the state o	11-20- Da	10	Time
Designee		00		nt internal de l'appendie de la companya de la comp
	.			
If continuation sheets (RP 4-1,	Page 7) are required, identify	he section bei	ng continued F	by section number. orm RP4-1
			R	ev. 5
			P	age 1 of /

Form Approved by Effective Date CR Form Initiation CR Form Initiation Condition 1: To be completed by initiator (please type or print) ganization identifying condition: Discovery d.ue: /2/2/97 Affected Unit(s): B Discovery time: /3:00 10 20 38 Condition description (including how condition was discovered, organization creating cowhen event was discovered): Unable to Isolate Charging Suction Valves 112D & E for Sump Recire if VCT P1.3, step 3.a requires the operator to isolate LCV-112D and E on sump recirculation. Sites valves be opened to ensure that the valves do not address the possibility that the VCT low-low or itch over. In that case, Valves 112D and E will not remain closed. It is possible to assume all breaks where the SI is generated after the VCT inventory is depited. Also, it is possible to assume all breaks where the SI is generated after the VCT inventory is depited. Also, it is possible to assume all breaks where the SI is generated after the VCT inventory is depited. Also, it is possible to assume all breaks where the SI is generated after the VCT inventory is depited. Also, it is possible to assume that the orthogeneral during a Functional System Review, sponsored by the NSAB. Component Identification Number: Method of Discov-ry: Self Immediate corrective action taken one - mode 5 Time: //3/2/////////////////////////////////	SORC Mtg. No. CR M3-97-4342
CR Form Initiation Initiation Initiation Condition 1: To be completed by initiator (please type or print) (anization identifying condition: B Discovery dit: (2/2/97) Affected Unit(s): B Condition description (including how condition was discovered, organization creating cowhen event was discovered): Unable to Isolate Charging Suction Valves 112D at E for Sump Recirc if VCT P 13, step 3.a requires the operator to isolate LCV-112D and E on sump recirculation. Ste se valves be opened to ensure that the valves do not go open if a low-low low level condition. Ste se valves be opened to ensure that the valves do not go open if a low-low low level condition. Ste se valves be opened to ensure that the valves do not go open if a low-low low level condition. Ste se valves be opened to ensure that the valves do not go open if a low-low low level condition. Ste se valves be opened to ensure that the valves do not go open if a low-low low level condition. Ste se valves be opened to ensure that the valves do not go open if a low-low low level condition state the ovel low low like low-low low low low low low low low low low	CR M3-97-4342
CR FORM Initiation Initiation Initiator (please type or print) Condition: Discovery d.te: /2/2/97 Affected Unit(s): Discovery d.te: /2/2/97 Condition description (including how condition was discovered, organization creating cowhen event was discovered): Unable to Isolate Charging Suction Valves 112D & E for Sump Recirc if VCT P1.3, step 3.a requires the operator to isolate LCV-112D and E on sump recirculation. Step servers this precaration does not address the possibility that the VCT low-low itch over. In that case, Valves 112D and E will not remain closed. It is possible to assume all breaks where the S1 is generated after the VCT inventory is depleted. Also, it is possible to reach the low-low initiated. Please note the VCT make-up is not safety grade and therefore, cannot be credited is condition was discovered during a Functional System Review, sponsored by the NSAB. Component Identification Number: Method of Discovery: Self Immediate corrective action taken ne - mode 5 Time: / 3.2.05 Initiator Name: Nirmal Jain/J.K. Rothert Time: / 3.3.05 Initiator's Signature: Mitching HA. Straffast Initiator's Signature: Mitching HA. Straffast Initiator Requests Follow-up: YES	CR M3-97-4342
Initiation Initiation Condition I: Discovery d. if: $ 2/2/ ^2 $ Affected Unit(s): Discovery time: $ 3.00 $ III 201300 or when event was discovered): Unable to Isolate Charging Suction Valves 112D & E for Sump Recirc if VCT P1.3, step 3 a requires the operator to isolate LCV-112D and E on sump recirculation. Step se valves be opened to ensure that the valves do not go open if a low-low level condition is irrulation. However, this precaution does not address the possibility that the VCT low-low level condition is incrudation. However, this precaution does not address the possibility that the VCT low-low level condition is is condition was discovered during a Functional System Review, sponsored by the NSAB. Component Identification Number: Method of Discovery: Self Immediate corrective action taken ne - mode 5 Recommended corrective action taken ne - mode 5 Initiator 's Signature: Miration 's Signature: Miration 's Signature: Miration 's Signature: Miration 's Completed by: Operability/Reopertability Screening Designature: Supervisor Name: Miration 's Completed by: Operability/Reopertability Screening Designature: Miration 's Signature:	
ction 1: To be completed by Initiator (please type of plut) anization identifying condition: Discovery d. te: /2/2/07 Affected Unit(s): B Discovery time: /3:00 10 20 350 10	
anization identifying condition: Discovery d. it: 72747 Affected Unity: B Discovery d. it: 72747 Affected Unity: Condition description (including how condition was discovered, organization creating cowhen event was discovered): Image: 2015 Image: 2015 Unable to Isolate Charging Suction Valves 112D & E for Sump Recirc if VCT P 1.3, step 3.a requires the operator to isolate LCV-112D and E on sump recirculation. Step set walves be opened to ensure that the valves do not go open if a low-low level condition is irculation. However, this precaution does not address the possibility that the VCT low-low level condition is irculation. However, this generated after the VCT inventory is depleted. Also, it is possible to assume all breaks where the SI is generated after the VCT inventory is depleted. Also, it is possible is condition was discovered during a Functional System Review, sponsored by the NSAB. Component Identification Number: Method of Discov-ry: Self Immediate corrective action taken me - mode 5 Recommended corrective action taken me - mode 5 Initiator Name: Mithod Mith. Stat. Mithod Mi	Sustem #: OSS
Condition description (including how condition was discovered, organization creating cowhen event was discovered): Unable to Isolate Charging Suction Valves 112D & E for Sump Recirc if VCT P 1.3, step 3.a requires the operator to isolate LCV-112D and E on sump recirculation. Step seaves be opened to ensure that the valves do not go open if a low-low level condition is irculation. However, this precaution does not address the possibility that the VCT low-low level condition is generated after the VCT inventory is depleted. Also, it is possible to assume all breaks where the S1 is generated after the VCT inventory is depleted. Also, it is possible to assume all breaks where the S1 is generated after the VCT inventory is depleted. Also, it is possible is condition was discovered during a Functional System Review, sponsored by the NSAB. Component Identification Number: Method of Discov-ry: Self Immediate corrective action taken me - mode 5 Recommended corrective action taken me - mode 5 Initiator Name: Nirmal Jain/J.K. Rothert Initiator Name: Nirmal Jain/J.K. Rothert Initiator requests Follow-up: YES Supervisor Signature: MIAAAMA H. STMAS Date: 122-2-2 ection 25: Supervisor Signature: MIAAAMA H. STMAS Date: 12-2-2 Supervisor Signature: MIAAAMA H. STMAS Date: 12-2-2 Supervisor Signature: MIAAAMA H. STMAS	
Initiator Name: Nirmal Jain/J.K. Rothert Time: 13:05 Initiator Name: Nirmal Jain/J.K. Rothert Time: 13:05 Initiator's Signature: Nicmal Jain/J.K. Rothert Date: 12/2/9 Initiator Requests Follow-up: YES Supervisor Name: WILLIAM H. STAIRJ Time: 13:33 Supervisor Signature: WILLIAM H. STAIRJ Time: 13:33 Supervisor Signature: WILLIAM H. STAIRJ Date: 12-2- Section 2: To be completed by Operability/Reportability Screening Design Does CR have an actual or potential effect on plant or personnel safety, operability, reportability, (e.g., NGP 2.25, EPIP 4400) or plant operation?	Iow-low level is present o 3.c requires that the breaker for achieved in the VCT during the sum level was present at the time of that the VCT is at low-low level for that the VCT level inventory will w setpoint before sump recirculation Continuation Sheet Continuation Sheet recirculation with a low low VCT
Initiator Name: Nirmal Jain/J.K. Rothert Time: 13:05 Initiator 's Signature: Nirmal Jain/J.K. Rothert Date: 12/2/9 Initiator Requests Follow-up: YES Supervisor Name: WILLIAM H. STAIRS Time: 13:33 Supervisor Signature: WILLIAM H. STAIRS Date: 12-2- Supervisor Signature: WILLIAM H. STAIRS Date: 12-2- Section 2: To be completed by Operability/Reportability Screening Design Does CR have an actual or potential effect on plant or personnel safety, operability, reportability, (e.g., NGP 2.25, EPIP 4400) or plant operation?	Continuation Sheet
Initiator's Signature: Microal Dain (19/2/9 Initiator Requests Follow-up: YES Supervisor Name: WILLIAM H. STAIRS Time: 1330 Supervisor Signature: WILLIAM H. STAIRS Date: 12-2- Section 2: To be completed by Operability/Reportability Screening Designation Does CR have an actual or potential effect on plant or personnel safety, operability, reportability, (e.g., NGP 2.25, EPIP 4400) or plant operation?	Phone No.: 832-4740
Initiator Requests Follow-up: YES Supervisor Name: WILLIAM H. STAIRS Time: 1330 Supervisor Signature: Willia R. Stars Date: 12-2- Section 2: To be completed by Operability/Reportability Screening Design Does CR have an actual or potential effect on plant or personnel safety, operability, reportability, (e.g., NGP 2.25, EPIP 4400) or plant operation? Yes or Don't Know (Section 3 required to be completed.)	Z Cost Control Center:
Supervisor Name: WILLIAM H. STAIRS Time: 1330 Supervisor Signature: Willia R. Stars Date: 12-2- Section 2: To be completed by Operability/Reportability Screening Designation Does CR have an actual or potential effect on plant or personnel safety, operability, reportability, (e.g., NGP 2.25, EPIP 4400) or plant operation? Yes or Don't Know (Section 3 required to be completed.)	
Supervisor Name: Supervisor Signature: Supervisor	
Supervisor Signature: Section 2: To be completed by Operability/Reportability Screening Designed Does CR have an actual or potential effect on plant or personnel safety, operability, reportability, (e.g., NGP 2.25, EPIP 4400) or plant operation? Yes or Don't Know (Section 3 required to be completed.)	· > Phone No: 59/2
 Does CR have an actual or potential effect on plant or personnel safety, operability, reportability, (e.g., NGP 2.25, EPIP 4400) or plant operation? Yes or Don't Know (Section 3 required to be completed.) 	Phone No. Q
	Notes:
	1/// 0
Keith Covin 12-2-9	1410
Designee Date	Time

1

1

. the

- Page 1 of 7 Sheet 1
| • | | | - 30 | 57 |
|--|--|--|--|---|
| /s/ P. D. Hinnenkamp | 9/
Effer | 30/97 | 97-53
SORC Mt | s. No |
| Form Approved by | CR Form | CR | CR M3-97 | -4343 |
| | Initiation | | | |
| ection 1: To be completed | by initiator (please typ | e or print) | 4 (A. 1977) | Postoje u t |
| rganization identifying condition: | Discovery date: 12/2/97
Discovery time: 12/2/97 | Affected Unit(s): | System #: | CVCS |
| here are two potential ways H2 can be in
For a very small break LOCA, SI may
VCT level (4.4%). Since this switch
is completed will be minimal (Please
scenario). However, the amount of w
and 112C. These valves are not leak
NEU-97-308E, dated Nov. 26, 97) ar
depiered, valves 112B and C will leal
Through valves V541 and V542. Th
leak tested to ensure leak tightness for
therefore, any leakage will be from th
isolated, it (seal return) will be at low
overpressure in the VCT may deplete
These issues were discovered during a Fu
Component Identification Number:
Method of Discovery: Self | troduced to Charging pump suction
y be delayed until after transfer of
over point is so low, the amount of
note, since the make-up to VCT is
vater available in the VCT may be
tested and therefore, may leak. We
did it makes no allowance for the low
k H2 also, jeopardizing charging p
is is a 3 inch line between VCT gap
or H2. During normal operation, the
seal return to the VCT. Such a
wer pressure than the VCT and the
e any water seal which may have of
inctional System Review, sponsor | on, causing pump ca
charging pumps fro
of water which will r
s not safety grade, it
critical since it prov
Ve have reviewed W
eakage. It is reasona
pump operation which
as space and seal return
he seal return line is
leak will go undetect
erefore, the leakage
existed at the time of
ed by the NSAB | witation, which ar
emain available al
cannot be credite
vides the water sea
estinghouse Safer
able to assume that
ch is needed for lo
urn line. These va
at higher pressure
cted. Post SI, since
will be from the V
f SI. | e:
VST on low-low
fter the switch over
d in the LOCA
of for valves 112B
y Evaluation (letter
t if the water scal is
ong term operation.
alves are also not
than the VCT and
the the seal return is
VCT. H2 |
| ione - mode 5 | | ng Disn# | | ontinuation Sheet |
| Recommended corrective action |)#
 | ang. Disp.# | | |
| A. Initiator Name: Nirmal Jain/J. | K. Rothert | Time: <u>1315</u> | Phone No
7 Cost Control | Center: |
| Initiator's Signature: ///ISTA
Initiator Requests Follow-up: YE
Supervisor Name: WILL | S H. STAIRI | Time: <u>1330</u> | | 0: .59/7 |
| Supervisor Signature: Mall | alph scally | Law. Iles | | har har |
| If continuation she zts (RP 4- | 1, Page 7) are required, identify ti | he section being con | tinued by section (
Form RP4-1
Rev. 5
Page 1 of 7
Sheet 1 | number. |

				X=:	1093
ALD D Hinnenkamp	9	30/97		97	-535
Form Approved by	Effe	tive Date		SORC	Mtg. No.
	CP Form		CR No:	A	entre binnen de antie aller a la para bann pe la ché bann chémic
	Initiation		m3-	97-	4530
The second secon	initiator (please typ	e or pri	nt) denie 28	a with my	altriation and a
ection 1: To be completed t	Discovery date: 12/10/97	Affected	Unit(s):	System	#: CVCS
ganization identifying condition:	Discovery time: 0930	1 2	3 × C		and proved the part of the second sector and prove the second second second second second second second second
DP E-0. The procedure instructions do n vel. his procedure is contrary to the design or piping. The charging system is designed nutdown could be initiated. The ability of DCFR 50.55a. It can be argued that the le nutdown and cooled down in an orderly of lso, manual initiation of SI increases the pop plant, the letdown is isolated. In the omplications associated with it will also otential of charging nozzle is considered This condition was discovered during a F Component Identification Number: Method of Discovery: Self	not allow the operator to isolate h iteria of Class I and II piping. P ed to keep up with a 3/8" line bre to perform the normal shutdown etdown will be isolated when SI manner (50.55a wording). I likelihood of a pressuizer over f ir approach, if isolation of letdow be avoided. This approach may l.	tdown in A ping equal t ak, provider for such bre is generated ill, especial on stabilizes be preferab	OP 3555 in a to or smaller to d the letdown taks is consist l. However, i ly for such sm the level, SI le even when NSAB.	han 3/8 " is isolated ent with t t would no hall leaks. initiation the infreq	are designed as Class i so that a normal he requirements of ot be a normal reactor At a Westinghouse 3- will be avoided and uent thermal cycling
None, since only a recommended improv	rement.				
	in mean more constant starts makes summaries and	Eng. Disp.#			Continuation Sheet
TR#AWC)#	Eng. Disp.#		-	Continuation Sheet
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the	e letdown isolation option for uto	Eng. Disp.# orporation i	nto AOP 355	5	Continuation Sheet
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the	e letdown isolation option for une	Eng. Disp.#	nto AOP 355	5	Continuation Sheet
TR#AWC 3. Recommended corrective action Evaluate the benefit of implementing the	b#	Eng. Disp.#	nto AOP 355	5 Phone	Continuation Sheet Continuation Sheet No.: 0661/832-470
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the 4. Initiator Name: Nirmal Jain / J	D# e letdown isolation option for und John Rothert	Eng. Disp.# orporation i Time: _/	nto AOP 355	5. Phone	Continuation Sheet Continuation Sheet No.: 0661/832-470
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the 4. Initiator Name: Nirmal Jain / J Initiator's Signature: Nirmal Jain / J	D# e letdown isolation option for und John Rothert	Eng. Disp.# orporation i Time: Date:	nto AOP 355	5 Phone Cost Cont	Continuation Sheet Continuation Sheet No.: 0(61/832-474 rol Center:
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the 4. Initiator Name: Nirmal Jain / J Initiator's Signature: Nirmal Jain / J Initiator Requests Follow-up: YE	D# e letdown isolation option for inc John Rothert C. Scinff Hotfut S	Eng. Disp.# orporation i Time: _/ Date: _]	nto AOP 355 /50 2-10-97	5. Phone Cost Cont	Continuation Sheet Continuation Sheet No.: 0441/832-474 rol Center:
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the 4. Initiator Name: Nirmal Jain / J Initiator's Signature: Nirmal Jain / J Initiator Requests Follow-up: YE Supervisor Name: WILLING	DH e letdown isolation option for und John Rothert Chainford Partiet S	Eng. Disp.# orporation i Time: _/ Date: _/ Time: _/	nto AOP 355	5. Phone Cost Cont	Continuation Sheet Continuation Sheet No.: 0461/832-476 rol Center:
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the 4. Initiator Name: Nirmal Jain / 3	DH e letdown isolation option for une John Rothert Chainford Contact S GAS H STAIRS QUILLES	Eng. Disp.# orporation i Time: _/ Date: _/ Time: <u>/</u> Date: //	nto AOP 355	5. Phone Cost Cont	Continuation Sheet Continuation Sheet No.: 0461/832-470 rol Center: e No: 59/2
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the 4. Initiator Name: Nirmal Jain / . Initiator's Signature: Nirmal Jain / . Initiator Signature: Nirmal Jain / . Initiator Signature: Supervisor Name: With the Supervisor Signature: Milling	John Rothert John Rothert Chaif 20/20/20/20/20 S Gras H STAIRS A Stars	Eng. Disp.# orporation i Time: _/ Date: _/ Date: _/ Screenin	nto AOP 355 <u>50</u> <u>2-10-9</u> 7 <u>300</u> <u>2-10-97</u> <u>150</u> <u>2-10-97</u> <u>150</u> <u>2-10-97</u>	5. Phone Cost Cont Phon	Continuation Sheet Continuation Sheet No.: 0461/832-476 rol Center:
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the 4. Initiator Name: Nirmal Jain / . Initiator's Signature: Nirmal Jain / . Initiator Requests Follow-up: Supervisor Name: Supervisor Signature:	DH e letdown isolation option for une John Rothert C. Sainf H. S. There S GM H. S. There M. Jacks Operability/Reportability	Eng. Disp.# orporation i Time: _/ Date: _/ Date: _/ Screenin	nto AOP 355 <u>2-10-9</u> 7 <u>300</u> <u>2-20-97</u> ng Designee	5. Phone Cost Cont Phon	Continuation Sheet Continuation Sheet No.: 0(661/832-470 rol Center: e No: 59/2
TR# AWC 3. Recommended corrective action Evaluate the benefit of implementing the 4. Initiator Name: Nirmal Jain / . 4. Initiator 's Signature: Nirmal Jain / . Initiator 's Signature: Nirmal Jain / . Supervisor Name: Nirmal Jain / . Supervisor Name: With Market Supervisor Signature: Mitting Section 2: To be completed by	De letdown isolation option for une John Rothert Chairford Charles S Gene H States Operability/Reportability	Eng. Disp.# orporation i Time: _/ Date: _/ Date: _/ Date: _/ Screenin	nto AOP 355 <u>/50</u> <u>2-10-9</u> 7 <u>300</u> <u>2-/0-97</u> ig Designée	5. Phone Cost Cont Phon	Continuation Sheet Continuation Sheet No.: 0461/832-476 rol Center: e No: 59/2

/s/ P. D. Hinnekamp	9/30/97	97-535 SOPC Min No
Form Approved by	CR Form	CR No:
	Initiation	M3-97-4530
ection 1: To be completed by it	nitiator (please type or print)	
(continued)	and a second and a second s	alle anna a' suis ann a' suis ann a' suis ann ann ann ann ann ann ann ann ann an
Initiator Requests Follow-up: YES		
Supervisor Name: WILLIAM +	1.57 A/KJ Time: 1305	-
Supervisor Signature: //illia	H Stars Date: 12-10-	27 Phone No: 5917
ection 2 To be completed by Opera	bility/Reportability Screening Design	nee
Does CR have an actual or potential effect reportability, (e.g., NGP 2.25, EPIP 4400)	t on plant or personnel safety, operability, or plant operation?	Notes:
Yes or Don't Know (Section 3 requir	red to be completed.)	
No		and a second of the last and a subscript the second second second second second second second second second se
		ana
Designee	Date	Time
If continuation sheets (RP 4-1, Pa	ge 7) are required, identify the section being co	ontinued by section number.
If continuation sheets (RP 4-1, Pa	ge 7) are required, identify the section being co	ontinued by section number. Form RP4-1
If continuation sheets (RP 4-1, Pa	ge 7) are required, identify the section being co	entinued by section number. Form RP4-1 Rev. 5
If continuation sheets (RP 4-1, Pa	ge 7) are required, identify the section being co	ontinued by section number. Form RP4-1 Rev. 5 Page 1 of 7

			2-3	09?
/s/ P. D. Hinnenkamp	9	/30/97		97-53s
Form Approved by	Elle	ctive Date	50	RC Mtg. No.
	CR Form		CR No:	And a second
	Initiation		M3-57	-4531
ection 1: To be completed l	by initiator (please typ	e or prin	t)	的18月2日的18月1日
Organization identifying condition: AP3 Technical Support/SAB	Discovery date: 12/10/97 Discovery time: 1000	Affected U	nit(s): Sys	tem #: AFW
Condition description (including how when event was discovered): UXILIARY FEED WATER PUMP MIN	v condition was discovared, organ	nization creat	ing condition, wha	t activity was in progress
TRC Bulletin 88-04 requested licensees to pumps resulting from operation and testing he pump manufacturer that current minim	evaluate the adequacy of the mi g in the minimum flow mode, and num flow rate, are sufficient to er	nimum flow b d that the eval isure no pump er (AFW) pun	bypass lines for sat uation should also damage from lov	ety related centrifugal include verification from flow operation. culzer-Bingham, for the
notor driven pumps went from 45 gpm to or continuous operation or greater than 2 ntermittent operation and to 230 gpm for analysis did not identify or consider pump	90 gpm during intermittent oper hours. For the turbine driven pu continuous operation. Reason for damage at low flow.	ration or le is i mp, minimum r the increase	than approximately flow went from 8 of flow requireme	2 hours, and to 126 gpm 1 gpm to 150 gpm during ents is that the original
Because the potential for pump damage at rates as recommended by the manufacture performance and vibration to maintain a h	low flow occurs gradually and n r. Instead, a monitoring program istorical record to predict future	ot immediate (IST) was in pump damage	ly, MP3 did not in aplemented to freq	crease the minimum flow uently monitor pump
The IST program is implemented and app operation has not been conveyed to operative water pumps can be operated indefinitely conditions.	ears to be effective. However, th tions and training personnel. Ac- on minimum flow which may en	e long term o cording to cur hance potenti	r extended operati rent operation pro al for pump dama	on concern for low flow cedures, the suxiliary feed te from low flow
This condition was discovered during a Fo Component Identification Number: Method of Discovery: Self	unctional Review System sponso	red by the NS	<u>AB.</u>	
	-		and the second second division of the second second	Continuation Sheet
 Immediate corrective action taken 				,
TR# AWO	#	ing. Disp.#		Continuation Sheet
 Recommended corrective action Incorporate into training and operation pr minimum flow conditions. i.e. Operating 	rocedures to minimize the time po g auxiliary feed water pumps on r	triod that aux	iliary feed water p should not excee	umps are operating at d one hour.
	an and and and and and and and and and a			Continuation Sheet
4. Initiator Name: Allen Farlow/J - Gebor France	ohn Rothert	Time: _/2/	Pho	10661/832- 4740
_ Initiator's Signature: Obla CFul	× A 22 Kathat	Date: 12/10/	97 Cost Co	ntrol Center:
If continuation sheets (RP 4-1,	Page 7) are required, identify th	e section bein	g continued by sec Form R	tion number. P4-1
			Rev. 5	
			Page 1 o Sheet 1	of 7

/S/F. D. Hinnekamp	9/30/97	97-535 SORC Mtr. No.
Form Approved by	CR Form	CR No:
	Initiation	MP3-97-4531
ection 1: To be completed by in	itiator (please type or print)	
(continued) Initiator Requests Follow-up: YES Supervisor Name: WILLIAM H Supervisor Signature: Without ection 2: To be completed by Operal Does CR have an actual or potential effect reportability, (e.g., NGP 2.25, EPIP 4400)	Date: 12-10-2 Dility/Reportability Screening Design on plant or personnel safety, operability, or plant operation?	27 Phone No: 59/7 nee Notes:
Yes or Dan't Know (Section 3 require	ed to be completed.)	
Crock-	12/10/97	1325
Designee	Date	Time

· Brief, Strategies and an and and	9/30/97	97-535
Form Approved by	CD Form	SORC Mtg. No.
	Initiation	MP3-97-4531
ection 1: To be completed by in	itiator (please type or print)	
Supervisor Name: WILLIAM H Supervisor Signature: Willia Of ection 2: To be completed by Operat	Java Date: 12-10-	27 Phone No: 59/7 nee
Does CR have an actual or potential effect reportability, (e.g., NGP 2.25, EPIP 4400) of Yes or Don't Know (Section 3 require	on plant or personnel safety, operability, or plant operation? d to be completed.)	Notes:
	12/10/97	(32.5
Designee	Date	Time

d ,

١

/s/ P. D. Hinnekamp	9/30/97	97-535
Form Approved by	CR Form	CR No.
	Initiation	MP3-97-4531
ection 1: To be completed by ini	tiator (please type or print)	
Initiator Requests Follow-up: YES Supervisor Name: WILLIAM H. Supervisor Signature: Without Office ection 2: To be completed by Operabi Does CR have an actual or potential effect of	STAILS Time: 1305 Date: 12-10-9 lity/Reportability Screening Designer n plant or personnel safety, operability,	7 Phone No: <u>59/7</u> De Notes:
reportability, (e.g., NGP 2.25, EPIP 4400) or Ves or Dan't Know (Section 3 required	to be completed.)	
C	12/10/97	1325
Designee	Date	Time

10 N

/s/ P. D. Hinnenkamp		0/30/07		07.53	nemer to object characteristic a prices and the work of
Form Approved by	- Eff	ective Date		SORC Mtg	. No.
			CD No.		a anna an tao anna an tao an tao an tao an tao an
	CR Form		CR NO:	07 115	
	Initiation		111.5-	71 - 450	52
ection 1: To be completed by	y initiator (please ty	pe or pr	int) a cost	William States	20 Samples and
rganization identifying condition:	Discovery date: 12/10/9	7 Affected	Unit(s):	System #:	ECCS
Condition description (including how i when event was discovered): CCS piping inside containment potentia it issue is the adequacy of procedure SP36 hich monitors the leakage rate on the upst CCS discharge piping that is not routinely takage testing on check valve V005, per SI an be left in a drained condition. The back lant startup or more frequently as other con onnected to drain valve V883 and there is esting. This condition was discovered during a Fur Component Identification Number: Method of Discovery: Self	condition was discovered, org Ily being left in a drained co 01F.4, 'RCS Pressure Isolation ream side of this valve. The p survailed being potentially le P3601F.1, the potential exists c leakage testing on V005 is p inditions prevail. When this te no guidance to refill this section inctional System Review, spor	anization cr ndition. n Valve Tes erformance ft in a draine that the ECC erformed on st is perform on of ECCS isored by the	eating condit d', Section 4.1 of this proce ed condition. CS piping bel ce per post of hed it has bee piping follo	ion, what activit 8, 'Leak Test of dure could resul In performing ween MV8801/ butage fill/vent a m discovered th wing completion	ty was in progress 3SIH-V005', It in a portion of check valve back A&B and V005 and just prior to at the hose is n of the back leak
one - mode 5					
TR# AWO#	neun annen desenders sonder dente manteren annen	Eng. Disp.	#	Co	ntinuation Sheet
Section 4.8; therefore, we recommend revi requirements and are not within a routine s	ewing other sections which le	ak test other	ECCS valve	s which have si	milar testing
4. Initiator Name: Allen Farlow/Joh Initiator's Signature: (Mb. 2) (Farlow Initiator Requests Follow-up: YES Supervisor Name: ()//////	in Rothert	Time: Date: Time:	1145 2/10/97 13:10	Phone No.: Cost Control C	0661/832- 4740
4. Initiator Name: Allen Farlow/Joh Initiator's Signature: Initiator Requests Follow-up: YES Supervisor Name: Supervisor Signature: Supervisor Signature:	in Rothert	Time: //	1145 2/10/97 13/0 2-10-97	Phone No.: Cost Control C	0661/832- 4740
 Initiator Name: Allen Farlow/Joh Initiator's Signature: Marc Farley Initiator Requests Follow-up: YES Supervisor Name: MARA Supervisor Signature: Marc Marc Section 2: To be completed by O 1. Does CR have an actual or potential reportability, (e.g., NGP 2.25, EPIP Yes or Don't Know (Section 3 No 	nn Rothert A 22 Rothert M H STAIRS perability/Reportability effect on plant operation? required to be completed.)	Time: _/ Date: _/ Time: Date: <u>y Screenin</u> afety, opera	1145 2/10/97 15/0 2-10-97 ig Designe bility,	Phone No.: Cost Control C Phone No Phone No e	0661/832- 4740
 Initiator Name: Allen Farlow/Joh Initiator's Signature: CBUC Failer Initiator Requests Follow-up: YES Supervisor Name: WIALIA Supervisor Signature: WIALIA Supervisor Signature: WIALIA Section 2: To be completed by O 1. Does CR have an actual or potential reportability, (e.g., NGP 2.25, EPIP Yes or Don't Know (Section 3 No 	nn Rothert A 22 Rothert M H STAIRS perability/Reportability effect on plant operation? required to be completed.)	Time: _/ Date: _/ Date: _/ <u>Screenin</u> afety, opera	1145 2/10/97 15/0 2-10-97 ng Designe bility, N	Phone No.: Cost Control C Phone No Phone No e	Street 0661/832- 4740 Center: 591> Market Construction Time

A second s		1.4	
/e/ P D Hinnenkamp	9/30/97		97-535
Form Approved by	Effective D	ate	SORC Mtg. No.
	CR Form	CR M	13-97-4535
	Initiation		
ection 1: To be completed by	y initiator (please type or	print)	Lawren & PCCS
rganization identifying condition:	Discovery date: .2/10/\$7 Affe	cted Unit(s):	System #: ECCS
Venting and filling of ECCS piping in he basis for considering containment "in-au aside of containment. TS 4.2.5.b 1) require accessible" ECCS piping be vented. Opera- herefore, this piping is not verified full per Driginally, MP3 was a much lower sub-atm accessible". The issue is, with MP3 now have espect to the ECCS piping that should be s containment would now be considered accession desirable (demonstrated by what could be considered accession containment may need to it be verified fille This observation is based in-part on discuss discharge piping should be surveillanced. The containment and has eliminated all reference based on significant ALARA consideration renses/utilities verify that their ECCS pip inply ensuring that none of the valves whether the surveing the surveing that none of the valves whether the surveing t	aside containment ccessible" needs to be addressed with es ECCS piping be verified filed every ation's currently considers all ECCS p the 31 day TS requirement. cospheric containment, this may have aving a near atmospheric containment urveillanced; especially when they con- essible during power operation, even t considered scheduled entries into cont d with water every 31 days per TS re- sions with Westinghouse (TS Support The improved standard Westinghouse ces to such terms as "accessible". The as for certain locations within contain- ing inside containment. Examples ci- icch could drain a portion of ECCS pi- mies to verify vented and filled.	respect to venting y 31 days. The bas iping inside contain been a factor in co , have we changed impare us to other hough extended an ainment). Thus, "a quirement when in Group) that revea to TS does not differ ey did provide that ment. Also Westim ted; 1) a utility ver ping were exercise	(verifying full) of ECCS piping is section discusses that nment to be "in-accessible"; nsidering containment "in- the NRC's expectation with licenses. Most of MP3 n entry into containment is not accessible" ECCS piping inside modes 1, 2, and 3. led that that all ECCS suction and rentiate between inside/outside of justifiable exemptions can be aghouse stated that several ifies full inside containment by d in the last month (a check list
Additionally, CR M3-97-4532 discusses a	situation that has potentially left a po	rtion of ECCS pip	ing inside containment in a
drained condition. This condition was discovered during a Fu Component Identification Number:	inctional System Review, sponsored	by the NSAB.	
drained condition. This condition was discovered during a Fu Component Identification Number: Method of Discovery: Self	inctional System Review, sponsored	by the NSAB.	Continuation Sheet
drained condition. This condition was discovered during a Fu Component Identification Number: Method of Discovery: Self 2. Immediate corrective action taken none - mode 5	inctional System Review, sponsored	by the NSAB.	Continuation Sheet
drained condition. This condition was discovered during a Fu Component Identification Number: Method of Discovery: Self 2. Immediate corrective action taken none - mode 5	Inctional System Review, sponsored	Disp.#	Continuation Sheet
drained condition. This condition was discovered during a Fu Component Identification Number: Method of Discovery: Self 2. Immediate corrective action taken none - mode 5 TR# AWO 3. Recommended corrective action Recommendation is for MP3 to reconside develop method for ensuring applicable I practices.	# Enc. # Enc. er it's position on what is considered " ECCS piping inside containment is fu	Disp.# accessible" or "in-till consistent with N	Continuation Sheet
drained condition. This condition was discovered during a Fu Component Identification Number: Method of Discovery: Self 2. Immediate corrective action taken none - mode 5 TR# AWO 3. Recommended corrective action Recommendation is for MP3 to reconside develop method for ensuring applicable I practices.	# Enc. Enc. Enc. Enc. Enc. Enc. Enc. Enc. Enc. Enc. Time	Disp.# accessible" or "in- Il consistent with N e: 1450	Continuation Sheet Continua Materia accessible" based on the above an IRC expectations and industry Continuation Sheet Phone No.: 832-4740
drained condition. This condition was discovered during a Fu Component Identification Number: Method of Discovery: Self 2. Immediate corrective action taken none - mode 5 TR# AWO 3. Recommended corrective action Recommendation is for MP3 to reconside develop method for ensuring applicable I practices. 4. Initiator Name: John K. Rother Initiator's Signature:		by the NSAB. Disp.# accessible" or "in- ll consistent with N e: 1450 :: $12/10/97$	Continuation Sheet Continuation Sheet Continuation Sheet Continuation Sheet Phone No.: 832-4740 Cost Control Center:

		2.12	1	
/s/ P. D. Hinnenkamp	9/3	0/97		97-535
Form Approved by	Effect	ive Date		SORC Mtg. No.
	CR Form		00	
	Initiation		CR	M3-97-4536
ction 1: To be completed	by initiator (please type	orprint) .	**************************************
anization identifying condition:	Discovery date: 12/10/97	Affected Un	it(\$):	System #:
B	Discovery time: 14130	1 2 3		
tost likely from outside the control room witch as a single failure in the SGTR And believe this is a legitimate single failur OPs do not have any contingency action iso, our discussion with a training instru- owever, it is reasonable to assume that to obably most critical in SGTR scenario (perator will have enough time to stop the	h), which will delay the desired act alysis Methodology to Determine f re. (Also, as we understand that suc if SI switch fails to reset. The Res actor (Bill Cote) has indicated that is the operator will be able to stop inju- (to prevent SG overfill). Our rough e injection in time to prevent overfil idance is warranted on this subject	tion. Westing Margin to Over the a failure we ponse Not Of the operators ection as need h review sugg fill, provided to to improve the	ghouse h erfill (W as actual btained c are not t ded. Tin gests that the failu he confic	tas postulated failure of the reset (CAP-10698-P-A) and therefore, Ily experienced at CY). column is blank for this step. rained on this specific failure. hely action of stopping injection t even for the SGTR scenario, th re to reset was noticed earlier wh dence that the operator would be
empted. However, some additional gui le to stop injection in a timely manner. structions in the EOPs. Since this is a fore plant start-up.	The additional guidance could be recommendation for improvement	in the form o t, we do not b	of trainin believe th	g on this failure or specific is issue needs to be addressed
tempted. However, some additional gui ole to stop injection in a timely manner. structions in the EOPs. Since this is a effore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self	The additional guidance could be recommendation for improvement functional System Review, sponso	in the form o t, we do not b ored by the N	SAB.	g on this failure or specific is issue needs to be addressed Continuation Sheet
tempted. However, some additional gui ole to stop injection in a timely manner. structions in the EOPs. Since this is a efore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self . Immediate corrective action taken one - mode 5. Also, suggestion for imp	The additional guidance could be recommendation for improvement functional System Review, sponso	in the form o t, we do not b ared by the N	SAB.	g on this failure or specific is issue needs to be addressed Continuation Sheet
tempted. However, some additional gui ble to stop injection in a timely manner. Istructions in the EOPs. Since this is a efore plant start-up. This condition was discovered during a F Component Identification Number: Method of Discovery: Self . Immediate corrective action taken ione - mode 5. Also, suggestion for imp	The additional guidance could be recommendation for improvement functional System Review, sponso provement only.	in the form of t, we do not b	SAB.	g on this failure or specific is issue needs to be addressed Continuation Sheet
tempted. However, some additional gui ole to stop injection in a timely manner. istructions in the EOPs. Since this is a efore plant start-up. This condition was discovered during a F Component Identification Number: Method of Discovery: Self Immediate corrective action taken ione - mode 5. Also, suggestion for imp R# AWC	The additional guidance could be recommendation for improvement functional System Review, sponso provement only.	in the form o t, we do not b ored by the Ni	SAB.	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet
tempted. However, some additional gui ole to stop injection in a timely manner. structions in the EOPs. Since this is a effore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self . Immediate corrective action taken one - mode 5. Also, suggestion for imp R# AWC . Recommended corrective action Consider providing guidance within app raining on this scenario.	The additional guidance could be recommendation for improvement functional System Review, sponso provement only.	in the form o t, we do not b ored by the Ni ang. Disp.#	SAB.	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide
empted. However, some additional gui le to stop injection in a timely manner. structions in the EOPs. Since this is a fore plant start-up. <u>his condition was discovered during a F</u> <u>Component Identification Number:</u> Method of Discovery: Self <u>Immediate corrective action taken</u> one - mode 5. Also, suggestion for imp <u>R#</u> <u>AWC</u> Recommended corrective action consider providing guidance within app raining on this scenario.	The additional guidance could be recommendation for improvement functional System Review, sponso provement only.	in the form of t, we do not b ored by the Ni ing. Disp.# for recovery f	SAB.	g on this failure or specific his issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide Continuation Sheet Phone No.: 832-4740
tempted. However, some additional gui le to stop injection in a timely manner. structions in the EOPs. Since this is a fore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self Immediate corrective action taken one - mode 5. Also, suggestion for imp R# AWC Recommended corrective action consider providing guidance within app raining on this scenario.	The additional guidance could be recommendation for improvement Functional System Review, sponso provement only.	in the form of t, we do not b ored by the Ni ing. Disp.# for recovery f	SAB.	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide Continuation Shee Phone No.: 832-4740
empted. However, some additional gui le to stop injection in a timely manner. structions in the EOPs. Since this is a fore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self Immediate corrective action taken one - mode 5. Also, suggestion for imp R# AWC Recommended corrective action Consider providing guidance within app raining on this scenario. Initiator Name: Nirmal Jain/J. Initiator's Signature: Nirmal Jain/J.	The additional guidance could be recommendation for improvement functional System Review, sponso provement only. D# E blicable EOPs in the RNO column f .K. Rothert	in the form of t, we do not b ored by the Ni or recovery f Fime: 140 Date: 12/	SAB. from failu	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide Continuation Shee Phone No.: 832-4740 Cost Control Center:
empted. However, some additional gui le to stop injection in a timely manner. structions in the EOPs. Since this is a fore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self Immediate corrective action taken one - mode 5. Also, suggestion for imp R# AWC Recommended corrective action Consider providing guidance within app raining on this scenario. Initiator Name: Nirmal Jain/J. Initiator Requests Follow-up: YE	The additional guidance could be recommendation for improvement functional System Review, sponso provement only. D# E blicable EOPs in the RNO column f K. Rothert Taut Markathat	in the form of t, we do not b ared by the Ni ang. Disp.# for recovery f fime: 140 Date: 12/	SAB. SAB.	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide Continuation Shee Phone No.: 832-4740 Cost Control Center:
tempted. However, some additional guide to stop injection in a timely manner. structions in the EOPs. Since this is a effore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self Immediate corrective action taken one - mode 5. Also, suggestion for imp R# AWC. Recommended corrective action Consider providing guidance within app raining on this scenario. Initiator Name: Nirmal Jain/J. Initiator Requests Follow-up: YE Supervisor Name: WILLIM	The additional guidance could be recommendation for improvement functional System Review, sponso provement only. D# E Dicable EOPs in the RNO column for K. Rothert Court Market S Area Area S Area Area Area S Area Area Area S Area Area Area S Area Area Area Area Area Area Area Area Area Area Area Area Area Area	in the form of t, we do not b ored by the Ni ing. Disp.# for recovery f fime: 12/ Date: 12/	SAB. From failure the form $failure for the failure form failure for the form faile for the form failure for the$	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide Continuation Shee Phone No.: 832-4740 Cost Control Center:
tempted. However, some additional guide to stop injection in a timely manner. structions in the EOPs. Since this is a effore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self Immediate corrective action taken one - mode 5. Also, suggestion for imponent of corrective action Consider providing guidance within appraining on this scenario. AWC Initiator Name: Nirmal Jain/J. Initiator 's Signature: Nirmal Jain/J. Supervisor Name: With Amountain Supervisor Signature: Nirmal Jain/J.	The additional guidance could be recommendation for improvement functional System Review, sponso provement only. D# E Dicable EOPs in the RNO column f K. Rothert S J. SzAiki S J. SzAiki	in the form of t, we do not b ored by the Ni or recovery f Fime: 140 Date: 12/ Date: 12/	from fails $\frac{10}{10/97}$	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide Continuation Shee Phone No.: 832-4740 Cost Control Center:
tempted. However, some additional guide to stop injection in a timely manner. structions in the EOPs. Since this is a effore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self . Immediate corrective action taken one - mode 5. Also, suggestion for imp . Recommended corrective action Consider providing guidance within app raining on this scenario. 4. Initiator Name: Nirmal Jain/J. Initiator 's Signature: <u>Nirmal Jain/J.</u> Initiator Requests Follow-up: YE Supervisor Name: <u>Dikking</u> Supervisor Signature: <u>Mirmal Jain/J.</u>	The additional guidance could be recommendation for improvement functional System Review, sponso provement only. D# E Dicable EOPs in the RNO column f K. Rothert Concertional System Review, sponso S Concertion State S Concertion State Concertion State Concertio	in the form of t, we do not b ared by the Ni ared b	From fails $\frac{10}{97}$ $\frac{10}{97}$ $\frac{10}{97}$ $\frac{10}{97}$ $\frac{10}{97}$	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide Continuation Shee Phone No.: 832-4740 Cost Control Center:
tempted. However, some additional guide to stop injection in a timely manner. structions in the EOPs. Since this is a effore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self Immediate corrective action taken one - mode 5. Also, suggestion for imp R# AWC Recommended corrective action Consider providing guidance within app raining on this scenario. Initiator Name: Nirmal Jain/J. Initiator 's Signature: Nirwal Initiator Requests Follow-up: YE Supervisor Name: Dikkim Supervisor Signature: Mike Supervisor Signature: Mike Supervisor Signature: Mike Mithing Mithing State Mithing State Mithing State Supervisor Signature: Mithing Mithing State Mithing State Mithing State Mithing State Mithing State Mithing State Mithing State Mithing State Mithing State Mithing State Nirmal Jain/J.	The additional guidance could be recommendation for improvement functional System Review, sponso provement only. D# E Dicable EOPs in the RNO column f R. Rothert Taul Talk S J. S = Aiki Operability/Reportability 1, Page 7) are required, identify th	in the form of t, we do not b ored by the Ni ing. Disp.# for recovery f Fime: 140 Date: 12/ Scheening te section bein	SAB. SAB. from failu from failu 10/97 10/97 20-9 Design	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet are of an SI reset and/or provide Continuation Sheet Phone No.: 832-4740 Cost Control Center: Phone No.: 59/2 Phone No: 59/2 Phone No: 59/2
tempted. However, some additional guide to stop injection in a timely manner. Instructions in the EOPs. Since this is a efore plant start-up. his condition was discovered during a F Component Identification Number: Method of Discovery: Self . Immediate corrective action taken ione - mode 5. Also, suggestion for imp IR# AWC . Recommended corrective action Consider providing guidance within app raining on this scenario. 4. Initiator Name: Nirmal Jain/J. Initiator's Signature: Nirmal Jain/J. Initiator Requests Follow-up: YE Supervisor Name: DIALM Supervisor Signature: DIALM Supervisor Signature: DIALM Section 2: EDE completed by If continuation sheets (RP 4-	The additional guidance could be recommendation for improvement functional System Review, sponso provement only. D# E Dicable EOPs in the RNO column f K. Rothert Care The Review of the Source of the	in the form of t, we do not b ared by the Ni ang. Disp.# for recovery f fime: 12/ Date: 12/ Date: 12/ Screening te section bein	From fails $\frac{10}{10/97}$ $\frac{10}{20-9}$ Design	g on this failure or specific is issue needs to be addressed Continuation Sheet Continuation Sheet ure of an SI reset and/or provide Continuation Sheet Phone No.: 832-4740 Cost Control Center: Phone No.: 59/2 Phone No: 59/2 Phone No: 59/2 Phone No: 59/2

		N.I	
/s/ P. D. Hinnenkamp	9/30/97	an and addressed in the sector and and a star plane	97-535
Form Approved by	Effective Dat	e	SORC Mtg. No.
	CR Form	-	ner gå, sen av en
	Initiation	CRM	13-97-4536
ction 1. To be completed by	initiator (please type or t	rint)	· · · · · · · · · · · · · · · · · · ·
ganization identifying condition:	Discovery date: 12/10/57 Affect	ed Unit(s):	System #:
.B	Discovery time: 1430 10 3		
EOPs, the operator is instructed to reset S set to stop charging or SI pump injection . sumed single failure) will prevent the oper nost likely from outside the control room), witch as a single failure in the SGTR Analy e believe this is a legitimate single failure. OPs do not have any contingency action if lsc, our discussion with a training instruct lowever, it is reasonable to assume that the robably most critical in SGTR scenario (to perator will have enough time to stop the is ttempted. However, some additional guide ble to stop injection in a timely manner. To instructions in the EOPs. Since this is a re- perfore plant start-up.	I signal to stop injection or reconfigure There are two reset switches, one for e ator from stopping injection from the o which will delay the desired action. We sis Methodology to Determine Margin (Also, as we understand that such a fail SI switch fails to reset. The Response or (Bill Cote) has indicated that the oper operator will be able to stop injection oprevent SG overfill). Our rough revie injection in time to prevent overfill, pro- ance is warranted on this subject to imp The additional guidance could be in the ecommendation for improvement, we d	valves; for exam each SI train. A corresponding tra Vestinghouse has to Overfill (WC. Jure was actually Not Obtained col- erators are not tra as needed. Time w suggests that e wided the failure form of training o not believe this	aple in E-0 ar.d E-3: the SI is fa'lure of one switch (the in without additional actions postulated failure of the reset AP-10698-P-A) and therefore, experienced at CY). fumn is blank for this step. ined on this specific failure. ly action of stopping injection is ven for the SGTR scenario, the to reset was noticed earlier when nice that the operator would be on this failure or specific issue needs to be addressed
Component Identification Number: Method of Discovery: Self	nenonal system review, sponsored by	and the second second	Continuation Sheet
2. Immediate corrective action taken		NATIONAL CONTRACTOR OF A DESCRIPTION OF A D	
none - mode 5. Also, suggestion for impre	ovement only.		
	Eas D		Continuation Sheet
TR# A WOR	Eug. Di	120.17	CALING REPORT OF STREET, PLANE, BUILDING, BUILDING, BUILDING, BUILDING, BUILDING, BUILDING, BUILDING, BUILDING,
Consider providing guidance within appli training on this scenario.	cable EOPs in the RNO column for rec	overy from failur	e of an SI reset and/or provide
	NUMBER OF STREET, STRE		Continuation Sheet
4. Initiator Name: Nirmal Jain/J.K	C. Rothert Time:	1440	Fnone No.: 632-4740
Initiator's Signature: Nirmel	Sand Methat Date:	12/10/97	Cost Control Center:
Initiator Requests Follow-up: YES	. V.		
***************************************	1 H. STAIRS Time:	1455	
Supervisor Name: WILLMA			
Supervisor Name: WILL-MA	Date:	12-10-9:	> Phone No: 59/7
Supervisor Name: Williams Supervisor Signature: Willio	Diservice Date:	12-10-9	7 Phone No: 59/7
Supervisor Name: Williams Supervisor Signature: Willio Section 2:35 Eo be completed by	Die: Date: Operability/Reportability/Scree	/2-/0-97 mingDesigne	7 Phone No: 59/7

/s/ P. D. Hinnenkamp	- 151151	9/30/97	97-53s
Form Approved by	1.11	Effective Date	SORC Mtg. No.
	CR For Initiatio	-m on	CR No: M3-97-4640
ection 1: To be completed	by initiator (plea	se type or prin	nt) · Latting and · Mathematical
rganization identifying condition:	Discovery date:	Affected U	Jnit(s): System #:
AB	Discovery time:		
he review of the surveillance proceduggest that certain systems are not determined by the system line-up is modified of SI pump mini flow valves (8924). These valves do not receive an op a pump start signal is generated, the words, an operator action is needed corresponding SI pump may have the valve is closed only for a very any cut-off time period for such a equipment inoperable under simile Accumulator pressure is controlled (SV-8875 and HCV-943) do not a operability of the accumulator is injection to RCS. Various vent and drain valves in surveillance 4.5.2.b). However, v 6.8.4.a (minimizing leakage from opening of these valves. Our con 6.8.4. As we understand, the vert ensure that the intent of TS 6.8.4.	dures, normal operating eclared inoperable and a during the surveillance. 0 and 8814) are stroked ben signal on SI. There the pump could dead-he ed to restore the system to be declared inopera- y short period of time, w a decision. Our unders lar circumstances. ed by opening the N2 su- receive any accident signal suspect since some N2 the ECCS system piping we don't know of any sp in those portions of the E incern is that when these int and drain valves are r a is not violated, however	procedures and dis appropriate Tech S For example: for surveillance p fore, during the time ad until the valve it , which is supposed ble while the valve ve need not declare standing is that other upply valves or by o gnal to close. Ther 2 will leak out of the g are opened to ensible becial provision in the CCS systems whice valves are opened, not left open unatter ver, a more definition	scussions with the operation personne pec action statements are not entered urposes (SP 3608.6, a quarterly test) he when the mini flow valve is closed is opened by the operator. In other d to be fully automatic. Theref e, to is closed. One could argue that since the pump inoperable. We are not su er plants (e.g., MP1) declare the opening N2 vent valves. N2 vent val- refore, when the valves are open, the he open line and thus would reduce sure that the piping is full of water (T the program which implements TS th would see radioactive fluids) to all , we may be violating the intent of TS inded. Maybe that is all we need to ve/ formal position may be needed.
his condition was discovered during a F Component Identification Number:	functional System Review	, sponsored by the N	<u>ISAB</u>
Method of Discovery: Self			Continuation Sheet
Immediate corrective action taken one - mode 5			
'R# AWO)#	Eng. Disp.#	Continuation She
Recommended corrective action			Continuation She
Initiator Name: Nirmal Jain/J.	K. Rothert	Time:	Phone No.: 832-4740
If continuation sheets (RP 4-1,	Page 7) are required, ide	ntify the section bein	g continued by section number. Form RP4-1 Rev. 5

/s/ P. D. Hinnekamp	9/30/97	97-535	
Form Approved by	CR Form	CR No:	
	Initiation		
ection 1: To be completed b	y initiator (please type or print)		
(continued)			
Initiator's Signature:	Date:	Cost Control Center:	
Initiator Requests Follow-up: YES Supervisor Name:			
Supervisor Signature:	Date:	Phone No:	
ction 2: To be completed by Op	erability/Reportability Screening De	signee a consideration of the second	
Does CR have an actual or potential e reportability, (e.g., NGP 2.25, EPIP 44 Yes or Don't Know (Section 3 re	ffect on plant or personnel safety, operability, 400) or plant operation? equired to be completed.)	Notes:	
Designee	Date	Тіпіе	

/s/ P. D. Hinnenkamp		/30/97	-	97-3	38
Form Approved by	Effe	ctive Date		SORC M	tg. No.
	CR Form Initiation		CR No	CR M3	-97-4698
ection 1: To be completed	by initiator (please typ	e or pri	nt)	William and	and the second of the
ganization identifying condition: P3 Technical Support/SAB	Discovery date: 12/17/97 Discovery time: 0800	Affected	Unit(s): 3 C	System #	QSS
N SAFETY GRADE HEAT TRACING RWST level transmitters provide oper type A instrumentation by Regulatory C transmitters must remain operable and ety related transmitters and the sensing oviding redundant heat tracing circuits p EHMS*MCC3B1), but the safety grade erefore the heat tracing and its power so cing is reliable, but discussions with sys- termine a basis for having a non safety p	G rator information to determine ac Guide 1.97. Since the operator no freezing of a sensing line could lines are heat traced. There are to powered from safety grade buses power is isolated from the heat to ource is considered to be non saf stem engineers, design engineers grade heat tracing system.	tions require reds to initia produce fals two heat trac 32-1R (3EF racing panel ety grade. R , CMP perso	ed for accid te sump re- e indication ting panels i IS*MCC3A s by safety tedundancy onnel, and S	ent mitigation circulation bas is. The level to 3HTS-PNLF1 1) and 32-1W grade isolation in the design tone & Webst	and are designated red on RWST level, ransmitters are and 3HTS-PNLF2 n transformers. implies that the hea er could not
Method of Discovery: Self				C -	tionation Charts
Immediate corrective action taken				Col	Intinuation Sheet
Immediate corrective action taken AWO Recommended corrective action ovide basis for non safety grade best tra	#	Eng. Disp.#	evel transm	Col	ontinuation Sheet
Immediate corrective action taken # AWO Recommended corrective action AWO ovide basis for non safety grade heat tra Initiator Name: Allen C.Farlow/	# I acing supporting operability of sa /John Rothert	ifety grade 1 Time: 16	evel transm	Co C itters. C Phone No	ontinuation Sheet ontinuation Sheet ontinuation Sheet 0661/832- 4740
Immediate corrective action taken # AWO Recommended corrective action ovide basis for non safety grade heat tro Initiator Name: Allen C.Farlow/ Initiator's Signature: Iller C.Farlow/	# H acing supporting operability of sa /John Rothert Farkee	ifety grade 1 Time: 160 Date: 12	evel transm	Control of Cost Control of Cos	ontinuation Sheet ontinuation Sheet ontinuation Sheet 0661/832- 4740 Center:
Immediate corrective action taken # AWO Recommended corrective action ovide basis for non safety grade heat tra Initiator Name: Allen C.Farlow/ Initiator's Signature: Deco C. Initiator Requests Follow-up: YES Supervisor Name: P	# H acing supporting operability of sa /John Rothert Faslow P. Nec. c.	ifety grade 1 Time: 160 Date: 12	evel transm	Co itters. C Phone No Cost Control	ontinuation Sheet (ontinuation Sheet (0661/832- 4740 Center:
Immediate corrective action taken # AWO Recommended corrective action ovide basis for non safety grade heat tro Initiator Name: Allen C.Farlow/ Initiator's Signature: DEGo C- Initiator Requests Follow-up: YES Supervisor Name: R Supervisor Signature: N	Acing supporting operability of sa John Rothert Farlow P. Necci ap c	ing. Disp.# afety grade 1 Time: 160 Date: 12 Time: 1 Date: 1	evel transm	Co itters. Co Phone No Cost Control o Phone No	ontinuation Sheet (ontinuation Sheet (ontinuation Sheet (0661/832- 4740 Center:
Immediate corrective action taken AWO Recommended corrective action ovide basis for non safety grade heat tro Initiator Name: Allen C.Farlow Initiator's Signature: DCG-2 C- Initiator Requests Follow-up: YES Supervisor Name: P Supervisor Signature: P Supervisor Signature	Acing supporting operability of sa /John Rothert Fasloe P. Necci Decability/Reportability I effect on plant or personnel saf P 4400) or plant operation?	ing. Disp.# afety grade 1 Time: 160 Date: 12 Time: 1 Date: 1 Screening ety, operabil	evel transm CO $\frac{1}{17/9.7}$ $\frac{600}{2-(7-9.7)}$ Des.gnee	Co itters. C Phone No Cost Control Phone No Phone No cost Control	ontinuation Sheet ontinuatio ontinuation Sheet ontinuation Sheet ontinuation Sheet o

-

Form KP4-1 Rev. 5 Pags 1 of 7 Sheet 1 .

/s/ P. D. Hinnekamp Form Approved by	9/30/97 Effective Date CR Form Initiation	97-535 SORC Mtg. No. CR No:
Section 2: To be completed by Opera	ability/Reportability Screening Designe	<u>e</u>
Designee	12/12/97 Date	
•		
If continuation sheets (RP 4-1, Page	e 7) are required, identify the section being contin	nued by section number. Form RP4-1 Rev. 5 Page 1 of 7 Sheet 2

Condition Report			
ection 3: To Be C	Completed By Shift Manage	r	1.5. 10.
Personnel Salety	onnel safety		
Condition does not	affect SSC operability C inoperable but operability restored	TS/TRM AC	rion Statement
SSC act currently : With the existing c RP5)	SC inoperable required to be operable but condition into condition reasonable expectation of Cont	st be corrected prior inued Operability ex	to operability Mode Restraint 97
Resolution assigned to	D:		Due date:
3. Reputable?			~
No			
4. Comments (Including	any immediate corrective actions taken)	1	
-	Ala		. /
Manager: WAA	//	Time: /(30 Date: 12/12/97
Section 4. Categoriz	ition-Corrective Action Department	IT Sig-Level	
1. CR Title:			
2. CR Owner:		Inv	Due Date:
2. CR Owner:		Inv Tra	Due Date:
2. CR Owner:		Inv Tra	Due Date:
2. CR Owner:	r Notifiei	Inv Tra	Due Date:
2. CR Owner:	r Notifiei AWO#	Inv Tra	no further documentation require
2. CR Owner: Comments: Comments: CR close to TR/ CR closed to CR	r Notifiel AWO#	Inv Tra , no furthe	Due Date:
2. CR Owner: Comments: Comments: CR close to TR/ CR closed to CR CA Department:	T Notifici AWO#	Inv Trac , no furthe (Signature)	Due Date:
2. CR Owner: 2. CR Owner: Comments: Comments: CR close to TR/ CR closed to CR CA Department:	r Notifici AWO# R#	Inv Trac , no furthe (Signature)	Due Date:
2. CR Owner: 2. CR Owner: Comments: Comments: CR close to TR/ CR close to TR/ CR closed to CR CA Department:	r Notifiel AWO#	Inv Trac , no furthe (Signature)	Due Date:
2. CR Owner: 2. CR Owner: Comments: Comments: CR close to TR/ CR closed to CH CA Department: If continue	ttion sheets (RP 4-1, Page 7) are require	Inv Trac , no furthe (Signature) d, identify the section	Due Date:
1. CR Title: 2. CR Owner: Comments: Comments: CR close to TR/ CR closed to CR CA Department: If continua	tion sheets (RP 4-1, Page 7) are require	Inv Trac , no furthe (Signature) d, identify the section	Due Date:

6

. D`.

4

Docket No. 50-423 B17049

Attachment 4

1

Millstone Nuclear Power Station, Unit No. 3

Response to Nuclear Regulatory Commission Request for Information - Nuclear Regulatory Commission Inspection Report 50-423/97-206, Attachment 1

February 1998

.

Response to Nuclear Regulatory Commission Request for Information Nuclear Regulatory Commission Inspection Report 50-423/97-206

Summary of Nuclear Regulatory Commission Reguest

Inspection Report 50-423/97-206 identified two apparent violations being considered for escalated enforcement and eight Severity Level IV Violations of Nuclear Regulatory Commission regulations. The letter transmitting this inspection notes, "Based on our findings, your staff initiated an evaluation of the effectiveness of the Configuration Management Program. In your response to the Notice of Violation please include a discussion of the scope and results of your evaluation of the Configuration Management Program."

NNECo's Response

Background

The original review of Millstone Unit 3 (MP3) configuration issues was performed in 1996 and took into consideration that Unit 3 was the newest of the Millstone units and recognized that:

- The unit's original design was reviewed against the Standard Review Plan.
- The unit met current industry standards for system design.
- The licensing and design bases documentation that was readily available when the unit was built was still available.

A multi-unit team, including Nuclear Oversight, developed the Configuration Management Program and a set of implementing instructions for conducting additional reviews. These reviews were designed to be a graded review, very detailed in areas that she ved weaknesses and less detailed where information supported that it was not necessary. The determination of key areas of weakness was performed through diagnostic assessments as described in NNECo letter dated July 2, 1996, "Initial Results of Millstone 3 Recovery Activities."

NNECo recognized that, due to the unprecedented type of reviews being done, feedback assessments would be required to check our results against the Configuration Management Program mission of restoring compliance with the licensing and design bases. Included in these internal assessments were the results from the Independent Corrective Action Verification Program contractors and Nuclear Regulatory Commission inspection teams. Lastly, the scope of the Configuration Management Program included a transition plan to move from the "restoration" phase to the "maintenance" phase.

The scope of the Configuration Management Program was comprehensive in its breadth and depth. More than 700,000 man-hours went into the direct effort of restoration for Millstone 3. This does not include many of the support activities performed by many organizations across the site. The scope included the 88 Maintenance Rule Group 1 and 2 systems and 19 topical areas. More than 60 programs also received graded reviews under the Configuration Management Program. Meetings were also held with Nuclear Regulatory Commission to clarify the specific requirements of the Independent Corrective Action Verification Program order and factor that into the scope of the Configuration Management Program.

The Final Safety Analysis Report was reviewed for key statements supporting the Unit 3 licensing and design bases. More than 30,000 annotations were made during this review providing the documentation of the bases for these statements of fact. The licensing basis reviews included a review of the licensing basis covered in the Final Safety Analysis Report, confirming key design parameters covered in the Technical Specifications and procedures, and a review of applicable correspondence. The reviews generally found compliance with Nuclear Regulatory Commission requirements and commitments.

NNECo's Configuration Management Program also included Nuclear Oversight reviews that resulted in expanding the reviews of design changes, expanding the type of walkdowns, and included 5 Independent Assessments that used a graded approach to confirm completion. Nuclear Oversight looked at both process and results. NNECo also used independent contractors to do system vertical slices to confirm readiness for the start of the Independent Corrective Action Verification Program and also tested the completion of discovery efforts. Enhancements were made to program reviews, electrical separation walkdowns, and maintenance requirements for the Design Basis Summary documents as a result of these reviews.

Configuration Management Program Effectiveness Assessment

An effectiveness assessment of the Millstone Unit 3 Configuration Management Program was undertaken in October of 1997 as discussed later in this section. The results of the assessment were summarized with the Nuclear Regulatory Commission at the Predecisional Enforcement Conference held on January 13, 1998. NNECo's assessment of the effectiveness of the Configuration Management Program concluded that the program was effective in identifying deviations and restoring compliance with the Nuclear Regulatory Commission approved licensing and design bases. NNECo's review of this assessment and input from the ongoing inspections led us to conclude that supplemental review and/or corrective action was still required in the following arcas:

- 1. Operating Experience (Nuclear Regulatory Commission Information Notices) reviews for issues involving system interactions and interfaces;
- 2. Controls to support identification and revision of key calculations;
- Technical Specification Section 6.0 required programs for compliance with licensing basis requirements;
- 4. Final Safety Analysis Report to assure proper alignment of Architect Engineer and Nuclear Steam Supply System vendor design requirements; and
- 5. Dose analysis calculations and assumptions.

Each of these areas, except dose analysis, is discussed below. Dose analysis calculations and assumptions are currently under review by the NRC as part of an ongoing inspection. In response to Nuclear Regulatory Commission questions received at the January 13, 1998 Predecisional Enforcement Conference, additional information on the use of Operating Experience in restoring configuration management is being provided.

NNECo believes that the Configuration Management Program review process as expanded, is sufficient to bring the Millstone Unit 3 physical plant configuration and supporting documentation into conformance with the Nuclear Regulatory Commission approved licensing and design bases. The reviews conducted to date under the Configuration Management Program have improved upon the accuracy of the original Final Safety Analysis Report, the quality of the supporting documentation and have provided the necessary programmatic improvements essential to maintaining the licensing and design bases over the remainder of the operational life of the unit.

Use of Operating Experience

The original scope of the Configuration Management Program included a review and validation of regulatory commitments communicated by NNECo to the Nuclear Regulatory Commission after the plant was originally licensed. This included a review of Millstone Unit 3 correspondence submitted by NNECo in response to Nuclear Regulatory Commission Generic Letters and Bulletins as well as Unit 3 Licensee Event Reports. In addition, Operating Experience was utilized extensively in the topical area reviews, and the Configuration Management Program team, assembled under the direction of Westinghouse and Southern Services Company, had extensive operational experience.

As part of the Configuration Management Program, 37 Design Basis Summary documents were developed for Maintenance Rule Group 1 and 2 systems. In preparing these Design Basis Summary documents, Operating Experience was factored into the performance aspects of the Millstone Unit 3 systems. For example, potential industry issues, such as net positive suction head requirements, valve flow requirements, post loss of coolant boron precipitation issues, service water heat removal requirements, reduced feedwater temperature transients, etc., were appropriately factored into the

Design Basis Summary documents by experienced system design and equipment engineers.

Also, an extensive review of key system calculations was performed. This review focused on key inputs and assumptions in order to ensure that known industry issues, such as sump vortexing and flow requirements, instrument uncertainties associated with setpoint calculations, performance characteristics of electrical equipment, structural methods, etc., were appropriately included in the calculations.

As NNECo discussed at the January 13, 1998 Predecisional Enforcement Conference, a review of historical Nuclear Regulatory Commission Information Notices was not included in the original scope of the Configuration Management Program. Information Notices were excluded on the basis of the Configuration Management Program scoping and diagnostic assessments which did not show a significant number of discrepancies relating to the use of Operating Experience information. NNECo acknowledges that a review of Information Notices could potentially have resulted in early identification and timely disposition of the Recurciating Spray System air entrainment and Refueling Water Storage Tank backleakage concerns.

As a result of the Configuration Management Program Effectiveness Assessment conducted following identification of the Recirculating Spray System air entrainment concern, NNECo initiated an Integrated System Functional Review as discussed below. This review included significant operating experience input. This input was derived both from the composition of the team and from the process followed. The team consisted of representatives from Westinghouse, ABB/CE and Southern Services Company. Personnel from the Nuclear Safety Engineering Group responsible for implementing the NNECo Operating Experience review program were also included on the team. The review considered input from many sources, including Operating Experience reports from other similar units. Drawing on the knowledge and experience of the team, Operating Experience reviews were factored into the review process. Chart 1 below provides a representative listing of the operating experience utilized in the review.

Genera! Issue Associated OE, IN, or IR Leakage of N2 from the Accumulators IN 97-40 Leakage of H2 into the ECCS piping from VCT, ECCS IN 88-23 & sup 3 gas entrapment, and other Net Positive Suction Head OE/LER 213-96006. CY concerns OE/LER 88-006-01, Oconee OE/LER 97-015-00, Millstone OE/LER 97-028-00, Millstone OE/LER 90-012-00.CY OE/LER 88-006-00. Oconee ER 38-008-00, Turkey Point J-261/97-201, Robinson IR 50-311/96-81, Salem IR 50-289/96-201, TMI Do we declare pumps inoperable when the min-flow OE/LER 92-007-00, Calvert Cliffs valve is closed? OE/LER 275-96001, Diablo Canyon Single failure of " reset switch OE/LER 89-018-00, Turkey Point OE/LER 289-97009, TMI Back leakage of Sump water to the RWST or VCT OE/LER 339-9600, 6/5/96 NSAL-92-008 OE/LER 93-006-00, North Anna OE/LER 91-010-00, Oconee OE/LER 91-023-00, Sequoyah IR 50-305/97002, Kewaunee IR 50-215/96013, Cook IK 50-346/97-201, Davis Besse Single reference leg feeding multiple level indicators SOER 01 (98), IN 97-31 Erosion of flow orifice/valves in the ECCS lines OE/LER 91-010-01, Trojan OE 7127, 03/02/95, Sequoyah Dead heading of ECCS flows during sump OE/LER 97-008-00, Crystal River recirculation when min-flow is isolated Internal flooding failing multiple trains OE/LER 97-046-00, N listone OE/LER 90-009-01, Millstone Mis-operation of non-safety electrical equipment OE/LER 93-002-00, Indian Point failing containment penetrations OE/LER 90-036-00, Millstone Order of SI & LNP signal generation may affect DG IN 93-17 performance OE/LER 255-92026, Palisades Single failure vulnerabilities of ventilation systems OE/LER 94-020-00, Millstone OE/LER 91-015-00, Trojan OE/LER 92-013-01, Hatch IR 50-311/96-81, Salem

Chart 1

Adequacy of pump min-flows. Time restriction on continued operation on less than recommended min-flow.	IN 88-04 OE/LER 86-001-00, Robinson IR 50-311/96-81, Salem
Surveillance of ECCS piping full of water	IN 97-60
Column separation of system causing water hammer on pump restart	IN 87-10, sup 1 OE/LER 97-003-00, Millstone
Common min-flow may result in dead heading of weaker pump	OE/LER 97-008-00, Crystal River OE/LER 90-029-00, McGuire OE/LER 87-030-00, Turkey Point OE/LER 87-018-00, Indian Point IR 50-311/96-81, Salem
Potential pump cavitation during pump line-up change	OE/LER 94-007-00, Millstone IN 97-60

The methodology utilized to perform the Integrated System Functional Review was developed to evaluate safety system interactions in relation to accident mitigation capability. The system interactions selected considered Operating Experience impact. The need to do these reviews resulted from a scope limitation in the Configuration Management Program. While detailed reviews of the Millstone Unit 3 design were performed on a system-by-system basis by the Configuration Management Program, the interactions and interfaces that occur between the various systems during an accident had not been reviewed in as much detail. The Nuclear Steam Supply System, which is designed by the PWR vendor, needs to interface with support systems designed by the Architect Engineering firm. The interfaces between the Nuclear Steam Supply System and support systems are fully understood under normal operating unditions. However, under accident conditions, the standby safety systems are support systems. Because experience with the standby safety systems is limited to testing and surveillance, interface issues with these systems may remain undiscovered.

To address this aspect of the design basis, NNECc assembled a team of experts to perform an Integrated System Functional Review. The purpose of this Integrated System Functional Review was to consider the dynamic interactions that take place between various systems during an accident scenario. The functional review process examines interfaces across the various systems, rather than a detailed vertical slice through each individual system. The functional review process also examines the interface between the operator recovery actions and the systems under changing conditions. Both industry and unit operating experiences were factored into the review. This review complimented the Configuration Management Program design reviews done previously. The goal of the review was to ensure that the various systems (including the support systems) can perform their safety functions to mitigate the

postulated event while interfacing with each other under changing conditions during the event.

The review team members were experienced personnel selected to cover the following areas: knowledge of the system design basis, operations, safety analysis and startup testing. In addition, a team member with operations experience from a "sister" plant was included for comparison and contrast to Millstone Unit 3 operation. In-house experts and experts from external organizations were also consulted to factor in operating event experience. The average work experience level of the full-time team members was greater than 20 years.

An accident mitigation scenario was selected to examine the integrated response of the systems included in the review. The Small Break Loss of Coolant Accident scenario was selected because its mitigation requires the use of approximately 25 key safety significant systems and operator recovery actions. Additionally, this accident scenario crosses most of the safety-related interfaces between the Engineer-Constructor and Nuclear Steam Supply System vendor systems.

The affected system drawings (P&IDs) and the Millstone Unit 3 Emergency Operating Procedures were used during the Integrated System Functional Review. The Millstone Unit 3 simulator was also used to gain understanding and examine interactions between the normal operating systems and the safety systems during the pre-trip phase of the Loss of Coolant Accident event. Simplified flow diagrams were created from the detailed P&IDs to provide the review team with a common frame of reference for discussion and an overview of the system. The Emergency Operating Procedures were used to identify the post-trip operator recovery actions.

The review team used engineering discussion sessions to review each safety system. These sessions provided the team with the most flexibility to identify potential items which required further review, and included the System Engineers who provided overviews of their systems. The following is a partial list of topics that were discussed and covered by the team:

- Potential for Pump Cavitation During Valve Lineup Changes
- Potential for Pump Deadheading During Valve Lineup Changes
- Potential for Water Hammer
- Diesel Loading Sequence of Support Systems
- Effects of Active and Passive Failures on the System Response
- Effects of Operator Recovery Actions on the System Response
- Timing of Automatic Actuation Signals
- Potential Release Paths for Offsite and Control Room Doses
- Adequacy of Surveillances
- Accumulation of Noncondensable Gases in Stagnant Piping

The Millstone Unit 3 Integrated System Functional Review team completed its review of systems interactions on January 5, 1998. Based on the results of the functional reviews, 14 level 2 Condition Reports were generated with 12 of those Condition Reports designated as startup related with one reportable condition. Given the extent of the Integrated System Functional Review process, the team concluded that additional review of different accident scenarios would yield little new information for Millstone Unit 3. The results of this review confirm NNECo's previous conclusion of the Configuration Management Program effectiveness in that the safety implications associated with the 14 identified Condition Report's are considered to be low.

Based on the above efforts, there is reasonable assurance that the reviews conducted and corrective actions being taken have adequately considered industry operating experience. This conclusion is based on Institute of Nuclear Power Operation evaluations (i.e., most recent was August 1996) which specifically assess the effectiveness of actions taken to address Institute of Nuclear Power Operation Significant Operating Experience Reports, an Institute of Nuclear Power Operation assist visit in the fall of 1997, and the Nuclear Oversight Audit of the Operating Experience Program which was conducted in November 1997. The 1997 Nuclear Oversight Audit concluded that industry operating experience information was being collected, evalur and distributed to appropriate personnel and appropriately screened for approximation. The Nuclear Oversight Audit did not identify any findings, and the deficiencies and observations noted were not related to programs or processes that could affect the licensing and design Bases.

On January 29, 1998, the Nuclear Safety Assessment Board confirmed the readiness of the Operating Experience Program to support Millstoné Unit 3 restart. NNECo has also reviewed the results and findings from the Independent Corrective Action Verification Program contractor and the Nuclear Regulatory Commission Tier I, II, and III inspections and has not identified any other significant weakness with respect to the use of Operating Experience. The expansion of the Configuration Management Program scope to address system interactions, integrated system functional responses, dose analysis and Technical Specification 6.0 operational programs targets the areas that were missed by the original Configuration Management Program and that need to be addressed prior to restart. Nevertheless, a further screening of Nuclear Regulatory Commission Information Notices will be conducted over the next several weeks to ensure that no Information Notices that are important to Millstone Unit 3 design, licensing and operating bases have been missed.

An "expert panel" consisting of Engineering, Operations, and Nuclear Safety Engineering (Operating Experience) representatives will perform the screening. The screening process will identify those Information Notices not addressed previously by the Integrated System Functional Review Team. After the screening is completed, Information Notices selected for further review will be forwarded to the Integrated Syste a Functional Review Team. The Integrated System Functional Review Team will

review the Information Notices and determine if they impact any previous conclusions. Condition Reports will be written for any adverse condition found during this phase of the review to document the condition, initiate appropriate operability and reportability determinations, and initiate the implementation of corrective actions.

Several key enhancements have also been made to the Operating Experience Program to assure long-term effectiveness and are discussed below:

- An executive sponsor was assigned to provide a high level of management support to the Operating Experience Program.
- Issue Managers have been assigned representing all three units and Nuclear Safety Engineering to foster increased use of Operating Experience information by applicable station organizations.
- Access to the Institute of Nuclear Power Operation Nuclear Network and Institute of Nuclear Power Operation event databases has been provided directly to more than 350 users to facilitate use of Operating Experience information in daily activities.
- One post restart enhancement to the program involves identification of Millstone events which are precursors to significant events which have occurred in the industry. The ability to correlate any Millstone precursor events to significant industry events will provide an additional performance measure if the effectiveness of the Millstone Operating Experience program. This part of the program will be in place by June 1998.

Calculation Control

Based on an assessment of the Independent Corrective Action Verification Program and Safety System Functional Inspection findings, NNECo concluded that existing Design Control Manual guidance did not support effective control and identification of key design basis calculations. This condition can result in confusion as to when a calculation was considered to be a "calculation of record" and the priorities assigned to making revisions.

Improvements to the Calculation Control Program have been made and include revisions to the Design Control Manual to differentiate between a "calculation of record" and those approved calculations which have not yet been incorporated into the licensing or design bases. This latter category of calculations is subject to final verification at the time of field installation or license amendment issuance. Applying this guidance, calculations that are performed to support plant modifications or Technical Specification changes are put on a hold status until the field installation is completed and released to operations and/or the revised license condition 1 in effect. These improvements are judged to be sufficient to ensure adequate design control in support of unit restart.

In addition to the restart required changes described above, NNECo is moving forward with further enhancements to the Calculation Control Program. Key calculations supporting the Millstone Unit 3 licensing and design bases are currently being uniquely identified and existing Design Control Manual direction for determining when a calculation revision is required is also being strengthened. The Design Control Manual will include direction to further clarify the requirements for calculation updates based on the number of changes and type of calculation. Requirements for periodic review field calculations with outstanding Calculation Change Notices will also be included in the Design Control Manual. These improvements to the Design Control Manual will be completed by March 31, 1998.

Review of the Millstone Unit 3 Technical Specifications and Surveillance Procedures

The preliminary results of the Nuclear Regulatory Commission's Tier II and III inspections, and the out of scope Tier I Safety System Functional Inspection identified examples of implementation deficiencies associated with procedures used to satisfy Technical Specification Surveillance requirements and the programmatic requirements contained in Technical Specification Chapter 6.0. On the basis of these preliminary findings, an a research of Technical Specification reviews performed under the Configuration Management Program and other initiatives was performed. As further discussed below, the assessment concluded that implementing procedure and technical requirements reviews were sufficient to support unit restart. However, while many of the site-wide programs covered under Section 6.0 of the Technical Specifications has previously been reviewed under the Configuration Management Program shad not. Consequently, supplemental reviews have been initiated to confirm the adequacy of Millstone Unit 3 compliance with the programmatic requirements of Technical Specification Section 6.0.

Millstone Unit 3 Technical Specifications and Technical Require is Manual, were reviewed under the Configuration Management Program for consistency with the design parameters delineated in the surveillance procedures, associated analyses and The review required that the setpoints, flowrates, volumes, and calculations. concentrations referenced in the Technical Specification and Technical Requirements Manual be verified to be consistent with the calculations, associated analyses and operating experience. Approximately 200 analytical values specified in the Technical Specifications were validated. For example, Reactor Protection System and Engineered Safety Features Actuation System setpoint basis documentation was reviewed for consistency with Technical Specification requirements. In performing this review, operating experience was also extensively factored into the process. Specifically, all Technical Bulletins and Nuclear Safety Advisory letters issued by Westinghouse since Millstone Unit 3 received its / perating license were factored into the calculation reviews. Industry issues impacting instrumentation (e.g., Rosemount transmitter issues) were also factored into the review. The results of this effort was the

submittal of a new Reactor Protection System/Engineered Safety Features Actuation System Technical Specifications to the Nuclear Regulatory Commission for approval. Additionally, Technical Specification issues associated with pressurizer level, the allowable value for Reactor Protection System/Engineered Safety Features Actuation System setpoints, and updates to 10CFR50 Appendix G curves were all identified under the Configuration Management Program. A review of Technical Specification implementing procedures associated with response time testing was also included. This review was conducted to evaluate conformance with the guidance contained in Nuclear Regulatory Commission Generic Letter 96-01.

In parallel with the Configuration Management Program project, NNECo has completed a review of those procedures implementing Technical Specification Surveillance Requirements. This review verified that the stated procedure objective was in alignment with the associated Surveillance Requirement, that appropriate triggers existed within the procedure for conditional Surveillance Requirements and that the tools used to support scheduling of Surveillances are accurate.

A supplemental compliance review of Technical Specification Section 6.0 programmatic requirements is in progress. This review will be completed and any deficiencies appropriately dispositioned prior to entry into Mode 4.

Final Safety Analysis Report Accuracy

An assessment of the quality of NNECo's Final Safety Analysis Report reconstitution project was performed based on reviews of Discrepancy Reports generated through the Independent Corrective Action Verification Program. Those assessments concluded that the overall project had been effective in that no safety significant findings had been identified for those Discrepancy Reports that had been responded to. However, based on the Nuclear Regulatory Commission's out of scope Safety System Functional Inspection, a validation of this conclusion was undertaken. This effort consisted of an in depth review of the Independent Corrective Action Verification Program findings and Nuclear Regulatory Commission out-of-scope Safety System Functional Inspection issues and confirmed no programmatic deficiency associated with the Configuration Management Program review of the Final Safety Analysis Report. While no programmatic deficiencies were noted, this latter assessment did conclude that additional benefits could be gained through a supplemental review of Final Safety Analysis Report sections (i.e., Chapters 3 and 6) containing design information for systems with significant Architect Engineer/Nuclear Steam Supply System vendor interface requirements and/or non-standard Westinghouse system designs unique to Millstone Unit 3. The intent of this review is to ensure effective coordination and integration of information between these Final Safety Analysis Report sections.

Supplemental reviews of Final Safety Analysis Report Chapters 3 and 6 are being performed. These reviews are being conducted by the Integrated System Functional

Review team with a focus on critical Architect Engineer/Nuclear Steam Supply System design interfaces and interactions and will examine the information contained in the Final Safety Analysis Report to ensure compatibility. This review will be completed with findings appropriately dispositioned prior to entry into Mode 2.

Conclusion

The Configuration Management Program methodology together with the supplemental reviews and actions previously discussed provides a high degree of assurance that Millstone Unit 3 will be operated in conformance with the Nuclear Regulatory Commission approved licensing and design bases.

The Integrated System Functional Review process brought industry expertise and knowledge of Operating Experience to focus on the complex system interactions and interrelationships and identifying associated design weaknesses. The limited number and relatively low safety significance of issues identified to date through this process has increased NNECo's level of confidence in the effectiveness of the Configuration Management Program. The Technical Specification reviews completed to date ensure that the operational and safety limitations imposed by Technical Specifications have been aligned with the licensing and design bases in support of plant operation. The additional reviews specified for Technical Specification Section 6.0 will provide an added level of assurance. With regards to Final Safety Analysis Report accuracy, an extensive review of the Nuclear Regulatory Commission's Safety System Functional Inspection findings and the findings provided through the Independent Corrective Action Verification Program confirmed no programmatic deficiency in the original Configuration Management Program review process. The supplemental review of Final Safety Analysis Report Chapters 3 and 6 under the Integrated System Functional Review process further enhance the review of complex system interfaces and interactions to its logical conclusior ..

For the reasons stated above, NNECo firmly believes that the Configuration Management Program has been effective in identifying safety significant equipment deficiencies and programmatic weaknesses. Appropriate actions have been or are being taken through the Corrective Action Program to address identified deficiencies.