

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Nine Mile Point Unit I	DOCKET NUMBER (2) 0 5 0 0 0 0 2 2 0	PAGE (3) 1 OF 0 2
---	--	----------------------

TITLE (4)  
Loss of Power to One Channel of Reactor Protection System Resulting in Full Scram.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																																									
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)																																							
0 4	0 2	8 6	8 6	0 0 5	0 0 0	0 4	2 3	8 6			0 5 0 0 0																																							
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:15%;">OPERATING MODE (9) N</td> <td colspan="10">THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)</td> </tr> <tr> <td rowspan="6">POWER LEVEL (10) 0 1 0 1 0</td> <td>20.402(b)</td> <td>20.405(c)</td> <td><input checked="" type="checkbox"/></td> <td>50.73(a)(2)(iv)</td> <td>73.71(b)</td> </tr> <tr> <td>20.405(a)(1)(i)</td> <td>50.38(e)(1)</td> <td></td> <td>50.73(a)(2)(v)</td> <td>73.71(c)</td> </tr> <tr> <td>20.405(a)(1)(ii)</td> <td>50.38(e)(2)</td> <td></td> <td>50.73(a)(2)(vii)</td> <td rowspan="4">OTHER (Specify in Abstract below and in Text, NRC Form 366A)</td> </tr> <tr> <td>20.405(a)(1)(iii)</td> <td>50.73(a)(2)(i)</td> <td></td> <td>50.73(a)(2)(viii)(A)</td> </tr> <tr> <td>20.405(a)(1)(iv)</td> <td>50.73(a)(2)(ii)</td> <td></td> <td>50.73(a)(2)(viii)(B)</td> </tr> <tr> <td>20.405(a)(1)(v)</td> <td>50.73(a)(2)(iii)</td> <td></td> <td>50.73(a)(2)(ix)</td> </tr> </table>												OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)										POWER LEVEL (10) 0 1 0 1 0	20.402(b)	20.405(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)	20.405(a)(1)(i)	50.38(e)(1)		50.73(a)(2)(v)	73.71(c)	20.405(a)(1)(ii)	50.38(e)(2)		50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)	20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)	20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)	20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)
OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																																																	
POWER LEVEL (10) 0 1 0 1 0	20.402(b)	20.405(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)																																													
	20.405(a)(1)(i)	50.38(e)(1)		50.73(a)(2)(v)	73.71(c)																																													
	20.405(a)(1)(ii)	50.38(e)(2)		50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)																																													
	20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)																																														
	20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)																																														
	20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)																																														

LICENSEE CONTACT FOR THIS LER (12)

NAME Robert G. Randall, Supervisor, Technical Support	TELEPHONE NUMBER 3 1 5 3 4 9 2 4 4 5
--	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS
X	JEREMY	B	455	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)

ABSTRACT

On April 2, 1986, Nine Mile Point Unit #1 was in the shutdown condition for refueling. The mode switch was in the "SHUTDOWN" position. At 0226 hours the unit experienced a full scram. Upon investigation it was determined that the cause was the loss of Reactor Protection System (RPS) Bus #11. It was further established that the loss of RPS Bus #11 was caused by the deenergization of a Brown Boveri ITE-27 undervoltage relay that monitors the output of the RPS Bus #11 supply (motor-generator set #162). Non-coincident logic during "SHUTDOWN" will cause a full scram upon loss of either RPS Bus (11 or 12). The undervoltage relay was reset when it was established that there was no undervoltage condition, and the supply to RPS Bus #11 was restored. The corrective action initiated involved an investigation into the cause of the relay trip. If required, the undervoltage relay will be repaired or replaced.

8605010126 860423  
PDR ADOCK 05000220  
S PDR

IE 22  
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Nine Mile Point Unit I	DOCKET NUMBER (2)  0 5 0 0 0 2 2 0	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 6	0 0 5	0 0 0	2	OF 0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

TEXT

On April 2, 1986, Nine Mile Point Unit I was in the shutdown condition for refueling. The mode switch was in "SHUTDOWN". At 0226 hours the unit experienced a full scram. It was determined that the cause of the scram was the loss of Reactor Protection System (RPS) Bus #11. It was determined that the loss of RPS Bus #11 was caused by the deenergization of an undervoltage relay, a Brown Boveri ITE-27 type #211B1165 relay. This resulted in the isolation of RPS Bus #11 from its normal supply, motor generator set #162. The low condenser vacuum bypass relay, main steam isolation valve closure bypass relay, and the reactor trip reset permissive after shutdown relay are all part of non-coincident logic available when the mode switch is in the "SHUTDOWN" position. Therefore, the loss of one RPS channel during shutdown will deenergize both subchannels of auto-reactor trip relays on each RPS channel, and both manual scram relays on both RPS channels. Subsequently, the loss of RPS Bus #11 during shutdown resulted in a full scram.

ASSESSMENT OF POTENTIAL SAFETY CONSEQUENCES

Since the Reactor Protection System functioned as designed for conditions corresponding to the shutdown mode, and in the conservative direction, there were no adverse safety consequences. There was no control rod movement. Due to the spiral off-load pattern used at Unit I, all rods were either fully inserted, or fully withdrawn and valved out if the corresponding fuel cell was unloaded. If the unit was to experience an event of this type during normal full power operation, the result would have been a half-scram. There would, again, have been no adverse safety consequences.

CORRECTIVE ACTION

An investigation into the cause of the relay trip was initiated. Based on the findings of this investigation, the relay will be repaired or replaced.

NIAGARA MOHAWK POWER CORPORATION

NIAGARA  MOHAWK

300 ERIE BOULEVARD WEST  
SYRACUSE, N. Y. 13202

THOMAS E. LEMPGES  
VICE PRESIDENT--NUCLEAR GENERATION

April 23, 1986

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

RE: Docket No. 50-220  
LER 86-05

Gentlemen:


In accordance with 10 CFR 50.73, we hereby submit the following  
Licensee Event Report:

LER 86-05      Which is being submitted in accordance with  
10 CFR 50.73 (a) (2) (iv), "Any event or condition  
that resulted in manual or automatic actuation  
of any Engineered Safety Feature (ESF), including  
the Reactor Protection System (RPS). However,  
actuation of an ESF, including the RPS, that  
resulted from and was part of the preplanned  
sequence during testing or reactor operation need  
not be reported."

A 10 CFR 50.72 report was made at 0315 on April 2, 1986.

This report was completed in the format designated in NUREG-1022,  
dated September 1983.

Very truly yours,



Thomas E. Lempges  
Vice President  
Nuclear Generation

TEL/tg  
Attachments  
cc: Dr. Thomas E. Murley  
Regional Administrator

LER 22  
/1