

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Limerick Generating Station - Unit 1						DOCKET NUMBER (2) 0 5 0 0 0 1 3 5 1 2		PAGE (3) 1 OF 0 1 4	
---	--	--	--	--	--	--	--	------------------------	--

TITLE (4)
Failure to Perform Hourly Fire Watch Due to Personnel Error

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																																																		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)																																																
0 4	0 5	8 6	8 6	0 1 9	0 0	0 5	0 5	8 6			0 5 0 0 0																																																
<table border="1"> <tr> <td colspan="2">OPERATING MODE (9)</td> <td colspan="10">THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10-CFR § (Check one or more of the following) (11)</td> </tr> <tr> <td>1</td> <td>1</td> <td>20.402(a)</td> <td>20.406(a)</td> <td>60.73(a)(2)(iv)</td> <td>73.71(b)</td> </tr> <tr> <td>POWER LEVEL (10)</td> <td>1 0 0</td> <td>20.406(a)(1)(i)</td> <td>20.36(a)(1)</td> <td>60.73(a)(2)(v)</td> <td>73.71(a)</td> </tr> <tr> <td></td> <td></td> <td>20.406(a)(1)(ii)</td> <td>60.36(a)(2)</td> <td>60.73(a)(2)(vi)</td> <td>OTHER (Specify in Abstract below and in Text, NRC Form 306A)</td> </tr> <tr> <td></td> <td></td> <td>20.406(a)(1)(iii)</td> <td>X 60.73(a)(2)(ii)</td> <td>60.73(a)(2)(vii)(A)</td> <td></td> </tr> <tr> <td></td> <td></td> <td>20.406(a)(1)(iv)</td> <td>60.73(a)(2)(iii)</td> <td>60.73(a)(2)(vii)(B)</td> <td></td> </tr> <tr> <td></td> <td></td> <td>20.406(a)(1)(v)</td> <td>60.73(a)(2)(iv)</td> <td>60.73(a)(2)(ix)</td> <td></td> </tr> </table>												OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10-CFR § (Check one or more of the following) (11)										1	1	20.402(a)	20.406(a)	60.73(a)(2)(iv)	73.71(b)	POWER LEVEL (10)	1 0 0	20.406(a)(1)(i)	20.36(a)(1)	60.73(a)(2)(v)	73.71(a)			20.406(a)(1)(ii)	60.36(a)(2)	60.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 306A)			20.406(a)(1)(iii)	X 60.73(a)(2)(ii)	60.73(a)(2)(vii)(A)				20.406(a)(1)(iv)	60.73(a)(2)(iii)	60.73(a)(2)(vii)(B)				20.406(a)(1)(v)	60.73(a)(2)(iv)	60.73(a)(2)(ix)	
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10-CFR § (Check one or more of the following) (11)																																																									
1	1	20.402(a)	20.406(a)	60.73(a)(2)(iv)	73.71(b)																																																						
POWER LEVEL (10)	1 0 0	20.406(a)(1)(i)	20.36(a)(1)	60.73(a)(2)(v)	73.71(a)																																																						
		20.406(a)(1)(ii)	60.36(a)(2)	60.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 306A)																																																						
		20.406(a)(1)(iii)	X 60.73(a)(2)(ii)	60.73(a)(2)(vii)(A)																																																							
		20.406(a)(1)(iv)	60.73(a)(2)(iii)	60.73(a)(2)(vii)(B)																																																							
		20.406(a)(1)(v)	60.73(a)(2)(iv)	60.73(a)(2)(ix)																																																							

LICENSEE CONTACT FOR THIS LER (12)

NAME		TELEPHONE NUMBER	
J. C. Nagle, Senior Engineer, Licensing Section		2 1 5 8 4 1 1 - 5 1 1 8 4	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	REPORTABLE TO NPDOS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If you complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

Abstract: 86-019

On April 5, 1986 at 0046 hours the fire watch inspection interval for an ineffective penetration seal (PSA-110-Z043) located between the RHR pump room and the service water pipe tunnel exceeded the one-hour limit of Technical Specification 3.7.7. The cause of this event was personnel error. The Fire Watch Coordinator failed to list the penetration seal on the fire watch patrol rounds sheet and the fire watch person failed to notice the discrepancy between the fire watch log and the rounds sheet. Consequently, the first fire watch patrol failed to inspect the affected fire area. The area was inspected during the second round of the fire watch patrol when the fire watch inspection sheet, which was posted in the area, was noticed by the fire watch person. The fire watch patrol rounds sheet was then compared to the fire watch log to ensure that all other fire areas listed in the log were listed on the rounds sheet. The Fire Protection Advisor, Fire Watch Coordinator, and fire watch person involved in this event were counseled on the importance of proper communication and performing each inspection.

8605080231 860505
PDR ADOCK 05000352
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Limerick Generating Station Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 5 2 8 6	LER NUMBER (3)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		1986	019	000	2	OF 04

TEXT (if more space is required, use additional NRC Form 206a) (17)

Unit Conditions Prior to the Event:

Operating Mode 1 (Power Operation)
Reactor Power 100%

Description of the Event:

On April 5, 1986 at 0046 hours, the hourly fire watch inspection for an ineffective penetration seal (PSA-110-2043) located between the RFR pump room and the service water pipe tunnel was not performed within one hour of the previous inspection. Technical Specification 3.7.7.a states, "With one or more of the above fire rated assemblies and/or sealing devices inoperable...establish an hourly fire watch patrol."

The actual inspection interval was one hour and thirty-four minutes which exceeds the one-hour limit of Technical Specification 3.7.7.

The EIIS code for the affected system, Fire Protection, is KP.

Consequences of the Event:

The possible consequences of this event were minimal. The pipe tunnel side of the penetration contains no combustible materials. The RFR side of the penetration has a low combustible loading (weight of combustible material/floor area) and operable fire detectors which would have provided early detection of a fire. If a fire was to occur in this area, the fire brigade would be dispatched to extinguish the fire using hose stations in the affected area and surrounding areas.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Limerick Generating Station Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 5 2	LER NUMBER (5)			PAGE (3)	
		YEAR 8 6	SEQUENTIAL NUMBER - 0 1 9	REVISION NUMBER - 0 0	0 3	OF 0 4

TEXT (if more space is required, see additional NRC Form 366a) (17)

Cause of the Event:

The cause of this event was a cognitive personnel error. The contract Fire Watch Coordinator failed to list penetration seal PSA-110-2043 on the fire watch patrol rounds sheet when the rounds sheet was prepared during shift change. Additionally, the oncoming contract fire watch person failed to notice the discrepancy between the fire watch log and fire watch patrol rounds sheet. Consequently, the first fire watch patrol on the shift failed to inspect the affected fire area.

Corrective Actions:

The affected fire area was inspected during the second round of the fire watch patrol when the posted fire watch inspection sheet was noticed by the fire watch person. The fire area was then added to the fire watch patrol rounds sheet. The Fire Watch Coordinator and responsible fire watch person compared the fire watch patrol rounds sheet to the fire watch log to ensure that all other fire areas listed in the log were listed on the rounds sheet.

Action Taken to Prevent Recurrence:

A mechanism exists to ensure that ineffective fire barriers or seals are properly inspected. The Fire Protection Advisor enters the ineffective barriers in the Fire Watch log which is utilized by the Fire Watch Coordinator to generate the fire watch rounds sheet. When the fire watch person picks up the rounds sheet, he signs off each barrier in the log recognizing the need for each inspection and checks the rounds sheet for agreement with the log.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Limerick Generating Station Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 5 2 8 6	LER NUMBER (3)			PAGE (3)	
		YEAR	IDENTICAL NUMBER	REVISION NUMBER		
		8 6	- 0 1 9	- 0	0 0 1 4	OF 0 1 4

TEXT (if more space is required, use additional NRC Form 366A (1))

The Fire Protection Advisor, Fire Watch Coordinator, and fire watch person involved in this event were counseled on the importance of proper communication and performing each required inspection within the designated time period.

Previous Similar Occurrences:

Limerick LERs 85-043 and 85-033 reported failures to meet hourly fire watch requirements of the Technical Specifications which resulted from personnel errors of different root causes.

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

May 5, 1986

Docket No. 50-352

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555


SUBJECT: Licensee Event Report
Limerick Generating Station - Unit 1

This LER concerns a failure to meet an hourly fire watch requirement of the Technical Specifications.

Reference: Docket No. 50-352
Report Number: 86-019
Revision Number: 00
Event Date: April 5, 1986
Report Date: May 5, 1986
Facility: Limerick Generating Station
P.O. Box A, Sanatoga, PA 19464

This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(i)(B).

Very truly yours,



G. M. Leitch
Superintendent
Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator, Region I, USNRC
E. M. Kelly, Senior Site Inspector
See Service List

TE22
/1