

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Browns Ferry Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 2 6 0 1 OF 0 3				PAGE (3) 1 OF 0 3			
TITLE (4) Engineering Safeguards Actuations During Surveillance Testing																	
EVENT DATE (5)				LER NUMBER (6)				REPORT DATE (7)				OTHER FACILITIES INVOLVED (8)					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)				
0 4	0 3	8 6	8 6	0 0 5	0 0 0	5 0	2 8	6	Browns Ferry Unit 1				0 5 0 0 0 2 5 9				
									Browns Ferry Unit 3				0 5 0 0 0 2 9 6				
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)															
N		20.402(b)				20.405(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)				73.71(b)			
POWER LEVEL (10)		20.405(a)(1)(i)				50.38(c)(1)				50.73(a)(2)(v)				73.71(c)			
0 1 0 1 0		20.405(a)(1)(ii)				50.38(c)(2)				50.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)			
		20.405(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(vii)(A)							
		20.405(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(vii)(B)							
		20.405(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(v)							
LICENSEE CONTACT FOR THIS LER (12)																	
NAME David L. Smith, Compliance Engineer										TELEPHONE NUMBER AREA CODE 2 0 5 7 2 9 - 3 8 6 5							
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																	
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs							
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR			
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										<input checked="" type="checkbox"/> NO							

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

An inadvertent containment isolation occurred during performance of a unit 2 surveillance instruction (SI). The SI verifies the reactor building ventilation exhaust radiation monitor isolation logic inputs with resulting isolations and system actuations. As part of the logic verification test, a jumper is installed to prevent initiation of engineered safety features when an actuation signal is generated. While the actuation signal was present, the jumper came loose which caused the isolation to occur. During the event, the actuated systems operated as designed.

The reactor operators returned the actuated systems to normal standby readiness within 24 minutes of initiation. To prevent similar occurrences in the future, the procedure was revised as an interim measure. The revised procedure no longer requires the jumpering of the isolation logic relay contacts. The long-term recurrence control will be to install test connections such that jumpers will be installed at a test panel.

8605090483 860502
PDR ADOCK 05000260
S PDR

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1) Browns Ferry Unit 2	DOCKET NUMBER (2) 0500026086	EVENT NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0	05	0	02	0	02

TEXT (If more space is required, use additional NRC Form 365A's) (17)

Units 1 and 2 were in refueling outages, and unit 3 was in an extended maintenance outage. Unit 2 and common ventilation systems were affected.

On April 3, 1986, at 1014, unit 2 instrument mechanics were performing Reactor Building Ventilation Radiation Monitor Calibration Surveillance Instruction (SI 4.2.A-10) on the channel 'B' detectors. The SI required a jumper to be placed across contacts of relay 16A-K61B to bypass an outboard isolation logic signal, which was to be generated in a subsequent step of the procedure. The instrument mechanics placed the jumper and deenergized relay 16A-K61B. The installed jumper came loose, lost continuity, and an inadvertent primary containment isolation occurred as follows:

- Standby gas treatment (BH) train "B" and "C" initiated
- Unit 1, 2, and 3 refuel zone (VA) isolated
- Unit 2 reactor zone (VB) isolated
- Control room emergency ventilation train "B" (VI) initiated
- Group 6 primary containment system (JM) isolation (purging and venting) occurred.

Because of the jumper disconnect, a secondary occurrence was that the jumper momentarily shorted to an adjacent terminal causing fuse 16A-F20, in panel 9-43, to blow. The isolation was initiated by the jumpers loss of continuity, not the blown fuse.

The instrument mechanics notified the reactor operator, who returned the activated safety systems, listed above, to normal standby readiness by 1038.

There are no safety concerns raised by the event since the affected unit was completely defueled. The safety system actuations were consistent with designed tripping functions of the relay involved.

Investigation of the occurrence revealed that the jumper was constructed utilizing alligator clips which could not be securely connected to the rounded screw head termination points. In addition, access to relay 16A-K61B is hampered by surrounding hardware. These conditions were the cause of the event.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1) Browns Ferry Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 2 6 0 8 6	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		— 0 0 5	— 0 0	0 3	OF	0	3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

As an interim measure to prevent further recurrences, the unit 2 SI was revised on April 9, 1986. The SI was changed so that the isolation function verification is verified before the logic verification. The reorganization of the procedure no longer requires jumper placement on the 16A-K61B relay contacts, and the expected isolation will not be reportable under 10 CFR 50.73 (a)(2)(iv).

The long-term recurrence control will be to install test connections such that required jumpers will be installed at a test panel.

Previous Similar Events - BFRO-50-296/86003, BFRO-50-259/86009

Responsible Section - N/A

TENNESSEE VALLEY AUTHORITY

Browns Ferry Nuclear Plant
P.O. Box 2000
Decatur, Alabama 35602

May 2, 1986

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Dear Sir:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 - DOCKET NO.
50-260 - FACILITY OPERATING LICENSE DPR-52 - REPORTABLE OCCURRENCE REPORT
BFRO-50-260/86005

The enclosed report provides details concerning engineering safeguards actuations during surveillance testing. This report is submitted in accordance to 10 CFR 50.73 (a)(2)(iv).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Robert L. Lewis
for Robert L. Lewis
Plant Manager
Browns Ferry Nuclear Plant

Enclosures

cc (Enclosures):

Regional Administration
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Resident Inspector, Browns Ferry Nuclear Plant

IE22
11