

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Sequoyah, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 2 7	PAGE (3) 1 0 4 4
--	---	----------------------------

TITLE (4)
Numerous Relays, Level Switches, Cycle Timers, Load Controllers, And Meters Have Not Been Routinely Calibrated Because They Were Not Identified In Procedures

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
01	29	87	87	010	01	03	19	87	Sequoyah Unit 2		0 5 0 0 0 3 2 8

OPERATING MODE (9) 5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)										
POWER LEVEL (10) 000	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)							
	<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)							
	<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)							
	<input type="checkbox"/> 20.405(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)								
	<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(vii)(B)								
	<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)								

LICENSEE CONTACT FOR THIS LER (12)

NAME J. L. Long, Plant Operations Review Staff	TELEPHONE NUMBER
	AREA CODE: 6 1 5 NUMBER: 8 7 0 - 7 2 5 4

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

This revision includes other components that have not been calibrated and were not covered by the previous revision of this LER.

On January 29, 1987, at 1300 EST, with unit 1 in mode 5 (0 percent power, 0 psig, and 109 degrees F), and unit 2 in mode 5 (0 percent power, 250 psig, and 110 degrees F), numerous time delay relays, cycle timers, level switches, and load controllers were identified as not being routinely calibrated. On February 20, 1987, with both units in mode 5, several undervoltage relays, overvoltage relays, and meters were identified as not being routinely calibrated. These discoveries were the result of a Division of Nuclear Quality Assurance audit.

The root cause of not calibrating the components was that before the Division of Nuclear Quality Assurance audit the components have not been identified on any procedure to require calibration due to lack of clearly defined departmental responsibilities.

Components necessary for unit 2 operation will be calibrated before startup of unit 2. Similarly, components necessary for unit 1 operation will be calibrated before unit 1 startup. Additionally, procedures will be prepared to routinely calibrate all of the components on a scheduled basis.

8703250389 870319
PDR ADOCK 05000327
S PDR

IE22
/11

FACILITY NAME (1) Sequoyah, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 2 7 8 7	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 7	— 0 1 0	— 0 1	0 2	OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

This revision includes other components that have not been calibrated and were not covered by the previous revision of this LER.

DESCRIPTION OF EVENT

On January 29, 1987, at 1300 EST, with unit 1 in mode 5 (0 percent power, 0 psig, and 109 degrees F) and unit 2 in mode 5 (0 percent power, 250 psig, and 110 degrees F), numerous time delay relays, cycle timers, level switches and load controllers were identified as being routinely calibrated. On February 20, 1987, with both units in mode 5, several undervoltage relays, overvoltage relays, and meters were identified as not being routinely calibrated. These discoveries were the result of a Division of Nuclear Quality Assurance audit. The audit was documented on Deviation Report No. QSQ-A-86-0007-001 dated July 11, 1986. The audit determined that certain Nuclear Quality Assurance Manual requirements and Sequoyah Nuclear Plant standard practices have not always been fully implemented and all electrical devices may not be adequately covered by the site's quality assurance program. Sequoyah Nuclear Plant's response was that the instruments would be identified and included in a comprehensive procedure to control calibration of instruments. The components that were identified as not being included on any procedure are associated with the following systems:

Time Delay Relays

EIIS Code

- | | |
|--|----|
| 1. Auxiliary feedwater pump turbine steam supply transfer | SJ |
| 2. Essential raw cooling water (ERCW) header isolation valves | KI |
| 3. Motor driven auxiliary feedwater pump steam generator level and bypass control valves | SJ |
| 4. Fire pump start logic | KP |
| 5. Diesel generator room exhaust fans | VJ |
| 6. Diesel generator battery hood exhaust fans | VJ |
| 7. Diesel generator 480 volt board room exhaust fans | VJ |
| 8. Containment air return fans | VC |
| 9. Auxiliary control air compressors | LD |
| 10. Centrifugal charging pump auxiliary oil pumps | CB |
| 11. Boric acid flow | CB |
| 12. Primary water flow | CB |
| 13. Diesel generator engine heat exchanger supply valves | LB |
| 14. ERCW supply header 1B to header 2A isolation valves | KI |
| 15. Component cooling system booster pumps | CC |
| 16. Component cooling water flow differential | CC |
| 17. Containment spray recirculation valves | BE |
| 18. Manipulator crane gripper engaged | DF |
| 19. Manipulator crane slow zone | DF |
| 20. Diesel generator solenoid valves for air start motors | LC |
| 21. Diesel generator normal stop logic | EK |
| 22. Diesel generator hydraulic governor control | EK |
| 23. Diesel generator speed switch relay | EK |
| 24. Upper head injection positive displacement pump recirculation valve | BQ |
| 25. 480 Volt shutdown board control voltage transfer switches | ED |
| 26. 6.9kv shutdown board control voltage transfer switches | EB |
| 27. 6.9kv shutdown board degraded voltage | EB |
| 28. Centrifugal charging pump load sequencing logic | EB |

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Sequoyah, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 2 7	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 7	- 0 1 0	- 0 1	0 3	OF	0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

- | | |
|---|----|
| 29. 6.9kv shutdown board load sequencing logic | EB |
| 30. Containment spray pump load sequencing logic | EB |
| 31. Auxiliary feedwater pump load sequencing logic | EB |
| 32. ERCW pumps load sequencing logic | EB |
| 33. Component cooling system pump load sequencing logic | EB |
| 34. 120 VAC vital inverters | EF |
| 35. Control Building pressurizer fans | VI |
| 36. Battery room exhaust fans | VF |
| 37. Control room air handling units | VI |
| 38. 480 Volt board room pressurizer fans | VF |
| 39. Main control room air handling units | VF |
| 40. Electric board room air handling units | VF |
| 41. Electric board room chillers | VF |
| 42. Main control room chillers | VI |
| 43. 480 Volt board room air handling units | VF |
| 44. Emergency gas treatment system fans | BH |
| 45. Shutdown board room chillers | VF |

Level Switches

EIIS Code

- | | |
|--|----|
| 1. Diesel generator day tanks | DC |
| 2. Spent fuel pit water level | DA |
| 3. Auxiliary air compressor oil level | LD |
| 4. Shutdown board room compressor tank level | VF |

Cycle Timers

EIIS Code

- | | |
|---|----|
| 1. Auxiliary control air compressor dryer | LD |
|---|----|

Load Controllers

EIIS Code

- | | |
|--------------------------------------|----|
| 1. Electric board room chiller motor | VF |
| 2. Main control room chiller motor | VI |
| 3. Shutdown board room temperature | VF |

Undervoltage Relays

EIIS Code

- | | |
|----------------------------------|----|
| 1. Vital battery boards | EJ |
| 2. Vital battery chargers | EJ |
| 3. Vital inverters | EF |
| 4. Vital instrument power boards | EF |

Overvoltage Relays

EIIS Code

- | | |
|-------------------------|----|
| 1. Vital battery boards | EJ |
|-------------------------|----|

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Sequoyah, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 2 7	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		87	010	01	4	OF 04

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Meters

EIIS Code

1. Vital battery chargers
2. Vital battery boards
3. ERCW motor control centers

EJ
EJ
ED

Many of these instruments are used for compliance to Technical Specification parameters. However, the safety related systems that contain any of the above components are periodically functional tested. Any inoperable components most probably would have been discovered during this testing. Therefore, no limiting conditions for operation were entered.

Some components and systems are common to units 1 and 2.

CAUSE OF EVENT

The root cause of not periodically calibrating the aforementioned components was that, until the Division of Nuclear Quality Assurance audit, the components were not identified by any procedure to require routine calibration due to lack of clearly defined departmental responsibilities.

ANALYSIS OF EVENT

This event is reportable under 10 CFR 50.73 paragraph a.2.i.B as an operation or condition prohibited by plant technical specifications.

Even though the above listed timers, level switches, load controllers, undervoltage relays, and overvoltage relays have not been calibrated, the systems are routinely functional tested. The functional tests provide a high level of confidence that the systems do operate properly. Therefore, there has been no threat to the safety of plant personnel or the general public.

CORRECTIVE ACTION

Work requests and instructions are being prepared to calibrate all of the aforementioned components. Those necessary for unit 2 operation will be completed before startup of unit 2. Similarly, unit 1 components will be calibrated before unit 1 startup. Procedures will be prepared to routinely calibrate all of the components on a scheduled basis.

Additional research is being performed as a result of the Division of Nuclear Quality Assurance audit in other areas. If other deficiencies are identified, the LER will be revised.

ADDITIONAL INFORMATION

There have been no previous occurrences.

0381Q

TENNESSEE VALLEY AUTHORITY
Sequoyah Nuclear Plant
Post Office Box 2000
Soddy-Daisy, Tennessee 37379

March 20, 1987

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO.
50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT
SQRO-50-327/87010 REVISION 1

The enclosed revised licensee event report identifies additional components that have not been routinely calibrated because they were not identified on any procedure. This event was originally reported in accordance with 10 CFR 50.73, paragraph a.2.i.B, on January 29, 1987.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Nobles
Acting Plant Manager

Enclosure
cc (Enclosure):

J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street, NW
Atlanta, Georgia 30323

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

NRC Inspector, Sequoyah Nuclear Plant

111
IE 22