NRC Fore (9-83)	LICENSEE EVENT REPORT (LER)										(LER)	U.S. NUCLEAR REGULATORY COMMISS APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85										
FACILITY	Y NAME (1)										DOCKET NUMBER	(2)	PAGE (3)								
Wolf Creek Generating Station					on						0 5 0 0	1014181	2 1 OF UI									
		al Sr	ocif	ication	Vio	lation	. M	iccoo	Haus	1 Fi	re Watch											
	ENT DATE		T	LER NUMBE		racion		PORT DA		ly FI		FACILITIES INVO	LUED (B)									
		YEAR	YEAR	SEQUENT	SEQUENTIAL		MONTH	DAY	YEAR		FACILITY NA		DOCKET NUMBER(S)									
	JA.	- TEAN	1.5	NUMBE	-	NUMBER	MONTH	UAT	TEAN				0 5 0									
0 3	1 9	8 5	8 5	000	4 -	00	0 4	1 7	8 5				0 5 0 0	010111								
	RATING		THIS RI	PORT IS SUBMI	TTED P	PURSUANT 1	TO THE R	EQUIREM	ENTS OF 1	O CFR 8: /	Check one or more	of the following) (1										
POWER LEVEL (10) 0 0 0 0			20 20 20 20 20 20	20.402(b) 20.405(a)(1)(i) 20.405(c)(1)(ii) 20.405(a)(1)(iii) 20.405(a)(1)(iv) 20.405(a)(1)(v)				(c) (1) (1) (2) (2)(i) (2)(ii) (2)(iii)			50.73(a) (2) (iv) 50.73(a) (2) (v) 50.73(a) (2) (vii) 50.73(a) (2) (viii) (50.73(a) (2) (viii) (50.73(a) (2) (x)		73.71(b) 73.71(c) OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
						L	ICENSEE	CONTACT	FOR THIS	LER (12)												
Mer	lin (G. Wi	Ilia	ms - Sup and	eri Adı	ntende minist	nt of	f Reg	ulato rvice:	ry, Qu	uality,	3 1 6	3 6 4 -	HBER - 18181311								
				COMPLE	TE ON	E LINE FOR	EACH CO	OMPONEN	T FAILURE	DESCRIBE	D IN THIS REPOR	RT (13)										
CAUSE	SYSTEM COMP		DNENT MANUFAC-			PORTABLE TO NPRDS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPROS									
А											111	111										
	,	1	1 1		T						111											
				SUPPLE	MENT	AL REPORT	EXPECTE	D (14)				+	MONT	H DAY YEAR								

From 2300 CST on March 19, 1985 to 0100 on March 20, 1985, following initial fuel loading, hourly fire watch patrols for one room in the Auxiliary building and one room in the Control building were missed. This is a violation of Technical Specification Action Statement 3.7.11.a. This resulted in fire barriers with inoperable penetration seals not being patrolled during the 2300 hour patrol (two rooms) and during the 2400 hour patrol (one room). Patrol of one room was reestablished during the 2400 hour patrol, and patrol of the second room was reestablished during the 0100 (3-20-85) patrol.

X NO

The required room fire detection and suppression systems were operable during this time.

This event posed no threat to the public health and safety.

IE22

EXPECTED SUBMISSION DATE (15)

8504250488 850417 PDR ADDCK 05000482 PDR PDR

YES (If yes, complete EXPECTED SUBMISSION DATE)

NFIC Form 366A 19-831	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION										N	U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85												
FACILITY NAME (1) -			DOCKET NUMBER (2)							LE	R NL	MBE	R (6)				PAGE (3)							
											YEA	R			UENT				SION					
Wolf Creek G	Generating Statio	n	0	5	0	10	0	4	8	12	81	5	_	0	0	4	_	0	10	01	2	OF	0	12
	use additional NRC Form 366A's) (17)			-		-			-	_	-	_				-	_	_				_		-


On March 19, 1985, following initial fuel loading, the 2300 CST hourly fire watch patrol missed entering room 1322 in the Auxiliary building and room 3101 in the Control building. The 2400 hourly fire watch patrol reestablished entry to room 1322 in the Auxiliary building but again missed entering room 3101 in the Control building. Entry to room 3101 in the Control building was reestablished during the 0100 hourly fire watch patrol on March 20, 1985.

This resulted in fire barriers (room 1322 floor pipe sleeve and room 3101 wall conduit penetration) with inoperable penetration seals not being hourly patrolled in violation of Technical Specification Action Statement 3.7.11.a. Room 1322 fire detectors and room 3101 fire detectors and suppression equipment were operable during this time.

The cause of this event was ACAD card readers which control access to these rooms being temporarily off-line due to computer software modifications and failure of the contractor personnel conducting the fire watch patrol to notify the Control Room or Security to gain the required access.

This procedural error was discovered on March 28, 1985 by the Fire Protection Coordinator during a review of completed Fire Watch Impairment Logs. Corrective Actions taken include a review of all Fire Watch Impairment Logs completed since issuance of the facility license - no other instances were found. The Fire Protection Coordinator has met personally with the involved fire watch personnel and has placed a notice in the Fire Watch Impairment Log Book (used during each fire watch patrol) reiterating the procedural requirement to check each impairment once each hour.

Additional actions to prevent recurrence of similar events in the future include a change from contractor personnel to permanent personnel conducting fire watch patrols, more frequent reviews of Fire Watch Impairment Loss and the addition of specific emphasis in this area to the Fire Watch training courses.





GLENN L KOESTER VICE PRESIDENT - NUCLEAR

April 17, 1985

U.S. Nuclear Regulatory Commission COPY FOR Mashington Document Control Desk

Mr. R.P. Denise, Director Wolf Creek Task Force U.S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

> KMLNRC 85-090 Re: Docket No. STN 50-482 Subj: Licensee Event Report 85-004-00

Gentlemen:

The enclosed Licensee Event Report is submitted pursuant to 10 CFR 50.73 (a)(2)(i) concerning a Technical Specification Violation.

> Yours very truly, Glenn L Kaister

GLK:bb Enc.

xc:PO'Connor (2)

JCummins