


TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER - 400 NORTH OLIVE STREET, L.B. 81 - DALLAS, TEXAS 75201

January 8, 1987

WILLIAM G. COUNSIL
EXECUTIVE VICE PRESIDENT

Mr. Eric H. Johnson, Director
Division of Reactor Safety and Projects
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012



SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKETS NOS. 50-445 AND 50-446
LARGE BORE PIPING AND SUPPORTS
SDAR: CP-86-36 (INTERIM REPORT)

Dear Mr. Johnson:

On June 9, 1986, we verbally notified you of a reportable item involving the scope of plant modifications resulting from the project's pipe support reverification program (see TXX-4844). This is a follow-up interim report on a reportable item under provisions of 10CFR50.55(e). Our latest interim report logged TXX-6117 was submitted on November 25, 1986.

The continuing engineering evaluation has not identified any additional instances which are considered reportable pursuant to 10CFR50.55(e). The attached list shows the support modifications issued to date. The evaluation is continuing and we anticipate submitting our next report by February 20, 1987.

Very truly yours,

A handwritten signature in cursive script that reads "W. G. Council".

W. G. Council

8701200295 870108
PDR ADOCK 05000445
S PDR

BY:

A handwritten signature in cursive script that reads "G. S. Keeley".
G. S. Keeley
Manager, Nuclear Licensing

BSD/amb
Attachment

c - NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

ATTACHMENT
LARGE BORE PIPE SUPPORT MODIFICATIONS

<u>Unit</u>	<u>Category</u>	<u>Number of Modifications</u> *
1	Prudent	862
	Recent Industry Practice	1303
	Adjustment	655
	Cumulative Effects	853
2	Prudent	1265
	Recent Industry Practice	286
	Adjustment	184
	Cumulative Effects	474

* Changes in these figures from the last report represent not only identification of further modifications but a reclassification and/or recategorization of certain supports. Reductions in these figures from the previous report are due in part to the removal of some small bore pipe support modifications which were inadvertently included in the previous report.