



UNITED STATES
NUCLEAR REGULATORY COMMISSION
ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
WASHINGTON, D. C. 20555

54-0007

1304 JAN 27 11:17 AM
REGISTRATION

January 23, 1984

MEMORANDUM FOR: Ben B. Hayes, Director
Office of Investigations
FROM: *Jesse C. Ebersole*
Jesse C. Ebersole, Chairman, ACRS

SUBJECT: ALLEGATIONS REGARDING CONSTRUCTION PRACTICES AT THE
DIABLO CANYON NUCLEAR POWER STATION

This memorandum is to confirm conversations between you and Mr. Raymond F. Fraley, Executive Director, ACRS, regarding allegations received by me concerning the Diablo Canyon Nuclear Power Station.

On January 16, 1984, Dr. Henry Myers, Science Advisor to Congressman Morris K. Udall set up a conference call between himself, me, and an unnamed person who appeared to be a person knowledgeable with respect to electrical work at the Diablo Canyon Nuclear Station. He desired to bring to my attention various allegations which had been identified by this unnamed allegor. I am bringing them to your attention so that they may be considered and resolved with the numerous other allegations identified with respect to this project. It may be that you already have some of these allegations under consideration. The items discussed are as follows:

- . Inadequate planning and routing of cables within the plant giving rise to a potential for inadequate separation of redundant safety-related cables and loss of traceability.
- . Transfer of cable to alternate reels - short sections of cable were frequently transferred from their original reel to other reels of cable as a convenience resulting in confusion regarding specific documentation of cable characteristics.
- . Improper clearing of cable ways before pulling cables. Failure to adequately clear the cable ways could have resulted in damage to cables when they were pulled through the cable ways.
- . Inadequate control of tension levels when pulling cables -- inadequate control was exercised in pulling electrical cable through cable ways and could have resulted in damage to cables during installation.
- . Changes from interim "as built" drawings to final drawings -- inadequate control has been exercised over the transition from interim drawings to final drawings of the station as actually constructed.

- . Anchor bolts (torquing of "red-head" bolts).
- . RHR pump suction line valve control. Potential damage to RHR pumps due to loss of suction as a result of a single failure.

cc:

R. C. DeYoung, IE
H. Schierling, NRR
J. B. Martin, Region V
H. H. E. Plaine, OGC
W. J. Dircks, EDO



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
 WASHINGTON, D. C. 20555

January 23, 1984

RECEIVED
 1984 JAN 27 11:12:34
 INVESTIGATION

MEMORANDUM FOR: Ben B. Hayes, Director
 Office of Investigations
 FROM: *Jesse C. Ebersole*
 Jesse C. Ebersole, Chairman, ACRS

SUBJECT: ALLEGATIONS REGARDING CONSTRUCTION PRACTICES AT THE
 DIABLO CANYON NUCLEAR POWER STATION

This memorandum is to confirm conversations between you and Mr. Raymond F. Fraley, Executive Director, ACRS, regarding allegations received by me concerning the Diablo Canyon Nuclear Power Station.

On January 16, 1984, Dr. Henry Myers, Science Advisor to Congressman Morris K. Udall set up a conference call between himself, me, and an unnamed person who appeared to be a person knowledgeable with respect to electrical work at the Diablo Canyon Nuclear Station. He desired to bring to my attention various allegations which had been identified by this unnamed allegor. I am bringing them to your attention so that they may be considered and resolved with the numerous other allegations identified with respect to this project. It may be that you already have some of these allegations under consideration. The items discussed are as follows:

SAME AS
 171
 172
 177
 174

54.
 59.
 62.
 133.
 146

- Inadequate planning and routing of cables within the plant giving rise to a potential for inadequate separation of redundant safety-related cables and loss of traceability.
- Transfer of cable to alternate reels - short sections of cable were frequently transferred from their original reel to other reels of cable as a convenience resulting in confusion regarding specific documentation of cable characteristics.
- Improper clearing of cable ways before pulling cables. Failure to adequately clear the cable ways could have resulted in damage to cables when they were pulled through the cable ways.
- Inadequate control of tension levels when pulling cables -- inadequate control was exercised in pulling electrical cable through cable ways and could have resulted in damage to cables during installation.

175 SAME AS (61)

Changes from interim "as built" drawings to final drawings -- inadequate control has been exercised over the transition from interim drawings to final drawings of the station as actually constructed.

301

176-5000 (10.14.154)

- Anchor bolts (torquing of "red-head" bolts).
- RHR pump suction line valve control. Potential damage to RHR pumps due to loss of suction as a result of a single failure.

CC:
R. C. DeYoung, IE
H. Schierling, NRR
J. B. Martin, Region V
H. H. E. Plaine, OGC
W. J. Dircks, EDO

FILE COPY
3-8-84
Final

Task: Allegation or Concern No. 171

AITs No. RV-84-A0007

BN No. N/A

Characterization:

Inadequate planning and routing of cables within the plant giving rise to a potential for inadequate separation of redundant safety-related cables and loss of traceability.

Implied Significance to Plant Design, Construction or Operation

See statement below.

Assessment of Safety Significance

This concern is addressed in Allegation or Concern Nos. 54, 59 and 63 of SSER-21, including supplements thereto.

Staff Position

See Allegation or Concerns referenced above.

Task: Allegation or Concern No. 172

FILECOPY

JC
FINAL
3-8-84

ATS No.: RV-84-A0007

BN No.: N/A

Characterization:

The transfer of cable to alternate reels - short sections of cable were frequently transferred from their original reel to other reels of cable as a convenience resulting in confusion regarding specific documentation of cable characteristics.

Implied Significance to Plant Design, Construction or Operation

See statement below.

Assessment of Safety Significance

This concern was addressed in Allegation or Concerns 54 and 59 of SSER-21.

Staff Position

See Allegation or Concerns referenced above.

Task: Allegation or Concern No. 173

FINAL COPY
JC
3/2/84
JL

ATS No: RV-84-A-0007

BN No: N/A

Characterization:

Improper clearing of cable ways before pulling of cables. Failure to adequately clear the cable ways have resulted in damage to cables when they were pulled through the cable ways.

Implied Significance to Plant Design, Construction or Operation

Pulling of cables into cable ways which have defective conditions, such as sharp edges on conduit or junction boxes, could result in unacceptable damage to the cable being pulled.

Assessment of Safety Significance

During an inspection at the site on January 31 through February 8, 1984, this concern was pursued by the staff. The staff's examination of QC records of the H. P. Foley Company, the electrical installation contractor, revealed that there were instances when cables were pulled into raceways prior to QC inspection and clearance of the raceways. These instances were documented in nonconformance reports (NCR's) by the contractor's QC department.

Dispositioning of the NCR's required thorough inspection of the raceways to determine their acceptability and that conditions did not exist which would

have resulted in damage to the cables which were installed. An example was NCR No. 8802-975, dated December 12, 1983. In this instance cable had been repulled into a conduit following modifications to the conduit. The modified conduit was inspected on January 20, 1984 and found to be acceptable in terms of size, type, identification, support placement, installation detail and workmanship. Based upon the results of the raceway inspection the cable installation was accepted as installed. The quality records also include the results of satisfactory post-installation continuity and megger testing of the cables installed.

Staff Position

The licensee contractor disposition of the nonconforming conditions identified appears acceptable.

Action Required

None.

ENCLOSURE

~~██████████~~ Petition at 5.

It is alleged that:

In November 1981 PG&E also accepted out-of-code practices when PG&E official Robert Torstrom overruled an inspector who found that engineering drawings specified a weld not recognized by AWS. The drawing called for a fillet weld. Due to the fitup angle for the weld, however, AWS does not credit it as a fillet weld. Instead, contrary to the design, the weld can only be considered as a partial penetration groove weld. In this instance, Karner backed the inspector, but Mr. Torstrom blocked corrective action with the unexplained conclusion that there was "no need" for it. (citing 2/25/84 Anon. Aff. at 5 and related Exhibit 4.)

The significant difference between the Petition and Attachment 2 is found on the sketch located on page 2 of Exhibit 9 to Attachment 2. The sketch indicates that the allegation is referring to an open, accessible weld root connection rather than an acute intersection. Therefore, the discussion of root fusion and effective throat in the original response to this allegation contained in the second half of paragraph 107 is no longer relevant and should be deleted.

A review of the sketch provided substantiates the original symbolization as fillet welds and supports Mr. Torstrom's disposition of the Discrepant Condition Notice (DCN) initiated by Mr. McDermott. The sketch shows that a right angle intersection for a fillet weld exists at the root and for a portion of the fillet weld leg permitting full penetration and fusion at the root. For the condition as sketched, there would be no deduction from

symbolize this particular weld joint in more than one way. The meaning of the effective throat. As discussed in the original response, it is acceptable to weld symbol used in this instance is clear and there was no out of code practice.

GAP #183 and 184, Petition at 7.

It is alleged that:

In 1981 PG&E neutralized a corrective action program by accepting welds that failed an MT (magnetic particle) test, based on results from previously-discredited tests that had accepted the same welds. The current selector switch on a testing machine had erroneously been installed backwards, to run at alternating current (AC) rather than on direct current (DC). AC, unlike DC, cannot detect subsurface cracks. Pullman and PG&E both require the use of DC for this reason. After 80 welds had been approved with the machine in an AC mode, the problem was discovered. When a sample of eight erroneously approved welds were retested, three failed because of subsurface flaws. Nonetheless, PG&E directed Pullman to accept these three welds, based on the earlier inadequate approvals with AC. (citing 2/25/84 Anon. Aff. at 9-10 and related Exhibits 15-19.) One such weld had "linear indications", suggesting possible cracks, as long as 3 inches." (citing 2/25/84 Anon. Aff. at 9-10 and related Exhibits 17 and 19.)

In the same case, PG&E directed Pullman to accept welds that had never been properly tested. Rather than retesting the remainder of the 80 welds that had been erroneously accepted using an improper testing method, PG&E directed Pullman to accept all of them without retesting, based on the AC tests. The reason PG&E gave for this was the cryptic statement that "the ability of DC to detect subsurface defects is limited in our configurations." (citing 2/25/84 Anon. Aff. at 9-10 and related Exhibit 18.) As described above, PG&E offered this excuse in spite of the fact that a retest with DC had failed more than a third of the sample, a result that PG&E's Torstrom called "inconclusive" (citing 2/25/84 Anon. Aff. at 10 and related Exhibit 18.)

The difference between the Petition and Attachment 2 is the reference to the memo from Mr. McDermott to Mr. Spanner, dated August 26, 1981, requesting an explanation of the Disposition of Pullman D.R.'s 4350 and 4352 and the

FINAL
JC
3-6-84

Task: Allegation or Concern No. 174

FILE COPY

ATS No: RV-84-A-0007

BN No: N/A

Characterization:

Inadequate control of tension levels when pulling cables - inadequate control was exercised in pulling electrical cable through cable ways and could have resulted in damage to cables during installation.

Implied Significance to Plant Design, Construction or Operation

Inadequate control of pulling tension during the installation of electrical cables could result in unacceptable damage to the cables.

Assessment of Safety Significance

The allegation in this instance was not accompanied by detailed supporting information. However, during the staff's examination into other allegations at the Diablo Canyon site information of a related nature was obtained as follows.

The staff's review of H. P. Foley quality records revealed a condition identified by the QA department's review of quality records wherein it had not been documented that pulling tension had been measured directly by QC inspection as required. These instances, which involved the pulling of five circuits, were the subject of a nonconforming report (NCR No. 8802-1027) dated

January 19, 1984. All cable pulls in this case involved high temperature resistance (HTR) cables with "soft" jacket material - thus the requirement for direct measurement of pulling tension. The disposition of the NCR in this instance was "accept-as-is," based upon successful post installation electrical continuity and resistance tests and the fact that all pulls were made by hand.

Staff Position

The staff concludes that there were instances when QC inspections were not conducted in accordance with QA/QC program requirements regarding QC monitoring and witnessing of special cable pulls. These conditions were documented by the H. P. Foley QC department and acceptable dispositions were made regarding the nonconforming conditions identified.

Action Required

None.

PG&E

FOR INTRA-COMPANY USES

From Division or Department: STATION CONSTRUCTION
Diablo Canyon Project

FILE NO.

RE LETTER OF SUBJECT: Audit of the H. P. Foley Company
Tool Calibration

To Division or Department: Audit Report DCO-82-027

0 0 2 1 5 - 3 2 2 1

August 13, 1982

R. D. ETZLER

Attention: D. A. Rockwell

From May 14 through June 10, 1982, Quality Control conducted an audit of tool calibration performed by the H. P. Foley Company.

The scope and results of this audit are outlined in the attached report. Discrepancies were identified which required the issuance of Minor Variation Report E-2375.

JAMES R. BRATTON
Lead Quality Control Engineer

Attachment: Audit DCO-82-027

Jlystrom:1gh

PACIFIC GAS AND ELECTRIC COMPANY
STATION CONSTRUCTION DEPARTMENT
DIABLO CANYON PROJECT

Audit of H. P. Foley Company
Tool Calibration
Audit Report DCO-82-027

June 10, 1982

D. A. ROCKWELL

From May 14 through June 10, 1982, an audit was conducted by the Quality Control Department of H. P. Foley Company tool calibration.

SCOPE

This audit was conducted to investigate tool calibration performed by the H. P. Foley Company to verify compliance with H. P. Foley Company Quality Assurance Manual Section XII and Quality Control Procedure QCP-8.

AUDIT POINT ONE

Verify that procedure QCP-8, as a minimum, contains the following QA Manual requirements:

- a) Item identity name and/or number.
- b) Frequency of calibration and the applicable procedure used for calibration.
- c) The date calibrated and the due date for the next calibration.
- d) The name of the person, or subcontractor, performing the calibration.
- e) Responsible authority review of calibration results.

Results

A review of QCP-8 verified that these requirements have been addressed.

Corrective Action

No corrective action is required.

AUDIT POINT TWO

Verify that tools are being recalled in accordance with the requirements of procedure QCP-8.

Results

A review of approximately 20% of the Calibration Log (form HPF/CR Log) and the active recall memo file verified that tools are being recalled in accordance with the procedure.

Corrective Action

No corrective action is required.

AUDIT POINT THREE

Verify that calibrated tools that have been returned to production have current calibration stickers affixed to them.


Results

All but two of the 47 tools inspected in the tool crib had current calibration stickers. Two torque wrenches (HPF #1014 and HPF A1) had exceeded their calibration periods. Further investigation showed that the calibration stickers affixed to the wrenches incorrectly specified a one month calibration period instead of the required three month period.

Corrective Action

Minor Variation Report E-2375 was initiated to document this discrepancy.

An exit interview was conducted with D. A. Rockwell, the Electrical Resident Engineer, to discuss the scope and results of this audit.



JOHN NYSTROM
Electrical Quality Control
Engineer

PG and E

FOR INTRA-COMPANY USES



From Division or Department

STATION CONSTRUCTION
Diablo Canyon Project

FILE NO.

RE LETTER OF SUBJECT

Audit of the H. P. Foley Company
Soldering Activities
Audit Report DCO-82-029

To Division or Department

0 1 2 1 5 3 2 2 5

August 13, 1982

R. D. ETZLER

Attention: D. A. Rockwell

From June 10 through June 16, 1982, Quality Control conducted an audit of Class One soldering performed by the H. P. Foley Company.

The scope and results of this audit are outlined on the attached report. Minor Variation Report E-2376 has been issued for the outstanding deficiency identified.

Deck Bell for

JAMES R. BRATTON
Lead Quality Control Engineer

Attachment: Audit DCO-82-029

JHystrom:lgH



PACIFIC GAS AND ELECTRIC COMPANY
STATION CONSTRUCTION DEPARTMENT
DIABLO CANYON PROJECT

June 16, 1982

Audit of H. P. Foley Company
Soldering Activities
Audit Report DCO-82-029

D. A. ROCKWELL

From June 10 through June 16, 1982, Quality Control conducted an audit of Class One soldering performed by the H. P. Foley Company.

SCOPE

This audit was conducted to verify that Class One soldering performed by the H. P. Foley Company complies with their Quality Control Procedure QCP-18, "Soldering".

AUDIT POINT

Verify that soldering is being performed and documented in accordance with procedure QCP-18.

Results


No soldering has been performed per procedure QCP-18, and there are no HPF/Solder Reports in the H. P. Foley QC files.

However, Class I soldering has been performed by the contractor on LOCA splices. This soldering was documented on an Electrical Process Traveler for each splice in accordance with procedure QCP-17, paragraph 4.3.2. A review of all travelers for the LOCA splices verified that H. P. Foley QC had inspected the soldering in accordance with the included procedure, with the exception of one splice. Traveler #34 for Flow Transmitter 1-FT-532 does not have a QC sign-off for the soldering.

Corrective Action

Minor Variation Report E-2376 has been initiated to document this deficiency.


An exit interview was conducted with D. A. Rockwell, the Electrical Resident Engineer, to discuss the scope and results of this audit. This included a discussion that FT-532 and its LOCA splice have been removed from the plant as part of Design Change Notices DCO-E-M-556, 764, and 1108.



JOHN J. NYSTROM
Quality Control Engineer

INTEROFFICE MEMORANDUM

Diablo Canyon Project



PACIFIC GAS AND ELECTRIC COMPANY
BECHTEL POWER CORPORATION

To -R. D. ETZLER / D. A. ROCKWELL
From -James R. Bratton
Of Quality Control
At DCPD Extension 69-1466

Date December 31, 1982
File No. Audit Report DCO-82-049
Subject Audit of H. P. Foley Company
Welder Qualification

ATTENTION: W. E. COLEY

On December 6-10, 1982, Quality Control audited the H. P. Foley Company for conformance to the welder qualification requirements of their Quality Control Procedure QCP-5, "Welder Qualification and the Qualification of Welding Procedures". The scope and results of the audit are outlined in the attached report.

The qualification records for one welder indicated that insufficient tests were performed to qualify him for indirect butt splices in reinforcing steel. This has been documented on Minor Variation Report E-2437. No other discrepancies were identified.

JAMES R. BRATTON
Lead Quality Control Engineer

PACIFIC GAS AND ELECTRIC COMPANY
STATION CONSTRUCTION DEPARTMENT
DIABLO CANYON PROJECT

Audit of H. P. Foley Company
Welder Qualification
Audit Report DCO-82-049

December 31, 1982

W. E. COLEY

On December 6-10, 1982, Quality Control conducted an audit of the H. P. Foley Company to verify conformance to the welder qualification requirements of the contractor's Quality Control Procedure QCP-5, "Welder Qualifications and the Qualification of Welding Procedures".

SCOPE

This audit reviewed welder qualification procedures, test records, and documentation providing objective evidence of welder qualification continuity.

AUDIT POINT ONE

Review H. P. Foley Quality Control Procedure QCP-5 for conformance to the welder qualification requirements of the American Society of Mechanical Engineers (ASME) and American Welding Society (AWS) welding codes.

Results

The technical and administrative requirements of Procedure QCP-5 comply with code requirements.

Corrective Action

No corrective action required.

AUDIT POINT TWO

Examine welder qualification test records to verify that qualification tests were performed and documented in accordance with Procedure QCP-5. Determine the limits of each welder's qualifications.

Results

The qualification test records of all seventy-three H. P. Foley welders were examined. The welders have performed qualification tests to qualify for various welding processes (i.e. shielded metal-arc, gas tungsten arc) to be used for welding requiring compliance with the ASME Boiler and Pressure Vessel Code, the AWS Structural Steel Welding Code, the AWS Sheet Steel Welding Code, and the AWS Reinforcing Steel Welding Code.

The following discrepancies were identified:

<u>Welder</u>	<u>Discrepancy</u>
(1) H. Dutton	I.D. symbol is not referenced consistently. Records indicate "S" or "D2".
(2) D. Estrada	AWS certification dated 11/4/82 was not signed by Quality Control.
(3) W. Haines	AWS certification dated 11/4/82 was not signed by Quality Control.
(4) J. Lavoie	AWS certification dated 11/19/82 was not signed by Quality Control.
(5) L. McFadden	AWS D1.4 certification dated 1/13/81 indicates insufficient macroetch tests were performed.
(6) C. Smith	AWS D1.4 certification dated 10/8/82 does not indicate bar size used in test.
(7) D. Waller	AWS certification dated 11/19/82 was not signed by Quality Control.

The limitations of each welder's qualifications, with respect to code, process, thickness, diameter, position, backing, filler metal, and date of original qualification, were compiled for later comparison with the H. P. Foley Company Active Welder List, in-process inspection reports, and production inspection reports.

Corrective Action

Six of the discrepancies identified above were corrected during the course of the audit. Minor Variation Report #E-2437 has been initiated to document the remaining unresolved discrepancy.

<u>Discrepancy</u>	<u>Corrective Action</u>
(1)	Dutton's symbol was confirmed to be "S". Records indicating "D2" were corrected.
(2)	Certification was signed by Quality Control.
(3)	Certification was signed by Quality Control.
(4)	Certification was signed by Quality Control.
(5)	Reference MVR #E-2437.

<u>Discrepancy</u>	<u>Corrective Action</u>
(6)	Test bar size was entered on certification.
(7)	Certification was signed by Quality Control.

AUDIT POINT THREE

Review the H. P. Foley Active Welder List to verify that the welders listed are qualified and that the limitations listed are correct. Review past lists to assure that the list is revised when there is a change in welder qualification status.

Results

The Active Welder List effective at the beginning of the audit contained the following discrepancies:

- 1) Welder V. Matties had successfully completed an AWS qualification test on 12/3/82, but was not identified on the Active Welder List.
- 2) Welders H. Dutton and A. Schofield are qualified for unlimited thickness groove welds. The list limits these welders to materials 3/4" thick or less.

A review of superseded lists indicates that the Active Welder List is revised to reflect changes in the status of welder qualification.

Corrective Action

The discrepancies identified above were corrected/explained as follows:

- 1) The list was in the process of being revised to reflect the addition of V. Matties as a qualified welder. Prior to the conclusion of the audit, the revised list was issued.
- 2) The Quality Control inspector supervising the qualification of welders preferred to list welders H. Dutton and A. Schofield as limited thickness welders. This does not represent a violation of codes or procedures.

AUDIT POINT FOUR

Review the contractor's program for monitoring welders to assure that each welder's qualification in a given code and process is maintained.

Results

The contractor performs an inspection of a welder's production work prior to expiration of the welder's qualification, documents this

inspection on an "In-Process Inspection Report", and files the inspection report with the qualification records as documentary evidence of welder qualification continuity. The records on file were not sufficient to maintain qualification of welders D. Backes and K. Parke to the present date.

Corrective Action

During the course of the audit, Quality Control located documentation providing evidence that welding was performed by these welders on dates sufficient to extend their qualifications to the present. Copies of this documentation were then filed with each welder's qualification records.

AUDIT POINT FIVE

Review a random selection of production weld inspection reports for all types of welding to assure that welders have not exceeded the limits of their qualifications.


Results

Approximately 50 weld inspection reports from work packages involving the welding of structural steel, sheet steel, and pipe were examined. No discrepancies were identified.


Corrective Action

No corrective action required.

An exit interview was conducted with the Electrical Resident Engineer to discuss the scope and results of this audit.



DEREK BELL
Quality Control Engineer
Audit Team Leader



TERRY E. PIERCE
Quality Control Engineer

INTEROFFICE MEMORANDUM

Diablo Canyon Project



PACIFIC GAS AND ELECTRIC COMPANY
BECHTEL POWER CORPORATION

To - R. D. Etzler
From - James R. Bratton
Of - Quality Control
At - DCPP Extension 69-1466

Date - January 24, 1983
File No. - Audit Report DCO-83-001
Subject - Audit of H.P. Foley Company
Welding Electrode Control

ATTENTION: W. E. COLEY

On January 20, 1983, Quality Control audited the H. P. Foley Company for conformance to Quality Control Procedure QCP-4A, "Welding Electrode Control". The scope and results of the audit are outlined in the attached report.

Several discrepancies in the control of welding electrodes were identified. Minor Variation Report #C-1238 has been initiated to document these discrepancies and assure that corrective action will be provided.

JAMES R. BRATTON
Lead Quality Control Engineer

EEB: [unclear]
Attachment - Audit DCO-83-001

265

PACIFIC GAS AND ELECTRIC COMPANY
STATION CONSTRUCTION DEPARTMENT
DIABLO CANYON PROJECT

Audit of H.P. Foley Company
Welding Electrode Control
Audit Report DCO-83-001

January 24, 1983

W. E. COLEY

On January 20, 1983, Quality Control conducted an audit of the contractor's practice for control of welding electrodes to verify conformance to Quality Control Procedure QCP-4A, "Welding Electrode Control".

SCOPE

This audit was conducted to assure satisfactory control of welding electrodes at issuance stations and in welding areas. The audit was limited to the issuance station in the Unit One Turbine Building and the welding areas in the Unit One Fuel Handling Building.

AUDIT POINT ONE

Observe the issuance of welding electrodes to assure that accountability of electrodes is established prior to use.

Results

Issuance of electrodes to several swing shift welders was observed. The attendant counted the electrodes and made the correct entries on the Weld Electrode Requisition Form, recording the oven temperature, the welder, the work location, the amount issued, and the time of issue. No discrepancies were noted.

Corrective Action

No corrective action required.

AUDIT POINT TWO

Inspect welding areas to assure that welding electrodes are not left uncontrolled at the work location.

Results

Inspection of the welding area revealed five uncontrolled electrodes; three used and two unused.

Corrective Action

Refer to Minor Variation Report #C-1238 for the details of the discrepancy and corrective action.

AUDIT POINT THREE

Observe the return of welding electrodes to assure that accountability of electrodes is maintained.

Results

Return of electrodes by several day shift welders was observed. The attendant did not count unused electrodes or stubs; the welders discarded their stubs in an open bucket, placed their unused electrodes in the oven, and apparently informed the attendant of the amount of each. At no time did the attendant handle or count returned electrodes. Although no procedural requirement exists, this does not constitute adequate control of welding electrodes.

At the end of the shift, the attendant locked the ovens and left the station. The swing shift attendant did not show up until twenty minutes later. During this period, two welders returned their electrodes, waited for an attendant, placed their electrode containers on the table, and left. The electrode containers were not traceable to the welders. This is in violation of Procedure QCP-4A, paragraph 4.4.1.3.

The Weld Rod Requisition Forms were reviewed at this point and showed that all outstanding electrodes had been returned; this indicates that electrodes are being documented as returned to the station prior to their physical return. Discussion with the night shift attendant confirmed that this practice occurs frequently. This does not conform to the requirements of Procedure QCP-4A, paragraph 4.4.1.2.

Corrective Action

Refer to Minor Variation Report #C-1238 for the details of the discrepancy and corrective action.

An exit interview was conducted with the Civil Resident Engineer and the Structural Steel Group supervisor to discuss the scope and results of this audit.



DEREK BELL
Quality Control Engineer

INTER DEPARTMENTAL INTERFERENCE

REQUEST BY: JOHN HEARD EXT: 3858

DEPT: CIVIL

TYPE OF INTERFERENCE:

HNGRS
 PINK

PIPING

HVAC

ELECT

CIVIL

INST

MECH

TAGGING:

RED

WHITE

BLUE

YELLOW

ORANGE

GREEN

DESCRIPTION OF INTERFERENCE: PIPE HANGER INTERFERENCE WITH STRUCTURAL BRACE

Ch. 12, 6.22.83 mech

NEED IDI REMOVED BY: 6-27-93
(DATE)

ESTIMATED TIME TO COMPLETE INSTALLATION AFTER REMOVAL OF INTERFERENCE 2 WEEKS
DAYS / WEEKS

AREA: 1 F


ELEVATION: 117

LINE NO: NA

HANGER NO: 2153-39

INST. OR DEVICE NO: NA

CONDUIT OR SUPPORT NO: NA



SUGGESTED SOLUTION: REMOVE HANGER, REDESIGN TO ATTACH TO NEW STRUCTURAL BRACE.

D.C.P.P.

JUN 22 1983

RECEIVED UNIT 2
I.D.I. DEPT.

D.C.P.P.

JUN 23 1983

RECEIVED UNIT 1
I.D.I. DEPT.

266

INTEROFFICE CORRESPONDENCE

REC 11/3/83
JJO

11/77
R.R.

DATE November 2, 1983
TO All QA/QC/ Redliners
FROM Bob Hosman/QA Supervisor
SUBJECT AS-BUILT DISCREPANT CONDITIONS:

SMALL BORE - DISCREPANT CONDITIONS

1. Changes to A/B - within ESD tolerance

- corrective action -

Redliner to correct A/B - initial and date change.
QC to verify correction - initial and date verification.
Also, QC shall note correction/changes on the back of the F.P.S.
and the method of justification.

(Ref. ESD 254)

2. Changes to A/B (Hanger) - outside ESD tolerance without PG&E authorization.

- corrective action -

QC shall verify actual field condition.
QA shall initiate DCN (per ESD 253) requesting PSDTC for authorization.
The QA reviewer has authorization to sign "Contractor Receipt" on the PSDTC.

3. Documentation problems, i.e. missing or discrepant information on the F.P.S., snubber checklists or other record documents.

- corrective action -

Problems can be resolved by locating objective evidence which provides sufficient proof to rectify the discrepancy. This may entail checking QC dailies, logs, or physical verification. Corrections/changes can be made when justified and shall be noted on the F.P.S. (Ref. ESD 254).

LARGE BORE - DISCREPANT CONDITIONS

1. Copy of A/B reflects field condition but there is no PG&E authorization (PSDTC).

- corrective action -

QC shall verify field condition.
QA reviewer shall initiate a DCN to obtain PG&E authorization (PSDTC)

267
JJO


2. Copy of A/B does not reflect Field condition and the discrepancy is outside ESD tolerance (includes missing information)

- corrective action -

QC shall verify Field condition.


QA Reviewer shall initiate a DR.

3. Documentation problems: Same as Small Bore.




Bob Hosman
QA Supervisor

BH:jg




VIEW G-G
LKG DWN




VIEW I-I
LKG DWN

SAPym
25 5/19/83
5-19-83



VIEW J-J



SECT. Y-Y

CONTROLLED COPY

P.P.P. AS BUILT DRAWING

DATE	P.P.P. VERIFIED
7/24/83	5/11/83

UNLESS OTHERWISE SPECIFIED

REF. DWG. 500090 SYS E/a
CLASS 1 UNIT AREA K
ELEV 100 DESIGN PJL/21-
ISO MULTI DATE 2-16-83


PIPE SUPPORT

268

DWG No. 90-11 REV. No. 1
BUILT SHT 10 OF 25

Use to check that a considerable
preference are 0" bottom
end of two sides and top


105	1	1/2" R. 4 1/2 x 7" ✓ CUT AS SHOWN
106	1	1" R. 1 1/2" x 10" 7/15/53 7 1/2" LG. CUT AS SHOWN
84	2	R 3/4 x 5 8 1/2 5" LG
85	1	T.S. 4 x 4 x 3/8" 20" LG LENGTH
1.2	1	R 3/4 x 5 x 4" LG.



P.P.P. AS BUILT DRAWING	
DATE	P.P.P. VERIFIED
7/24/53	J.M.M.

LOCATION PLAN


UNLESS OTHERWISE SPECIFIED U-bolts: field-fit, nut each side. Horiz. pipe clearances are: 0" bottom and 1/16" two sides and top.	REF. DWG. 500099 SYS 8/9	PIPE SUPPORT DWG. No. 99-11 REV. No. 7 SHT 31 OF 35
	GLASS 1 UNIT 1 AREA K	
	ELEV 100' DESIGN J.M.M.	
	ISO MULTI DATE 7/24/53	



SAP/ym
AS 5/19/83
5-19-83

SEC. K-K

CONTROLLED COPY




DETAIL VI

P.P.P. AS BUILT DRAWING

DATE	PPP VERIFIED
7/2A/83	<i>JMM</i>

LKG UP



ELEV. SECT P.P

UNLESS OTHERWISE SPECIFIED

REF. DWG. 500099 SYS F/G
 CLASS 1 UNIT 1 AREA E
 ELEV 100' DESIGN P-21/23
 ISO MULTI DATE 2-16-83

PIPE SUPPORT

DWG No. 99-11 REV. No. 7
 (17)
 BUILT SHT 12 OF 35

Sections for shift-autoschedule Horiz-
 Pipe clearances are 0'-bottom
 and 1'-5" two sides and top.

1. LOCATION OF SUPPORT COMPARES WITH DRAWING.		2245	✓	7/11/03
2. DRAWING NUMBER NOTED AND COMPONENTS CORRELY WITH MATERIAL LIST		2245	✓	7/11/03
3. ANCHORS INSTALLED AND WEDGED BY O.C.		2245	✓	7/30/03
B. Shield/Plug Driven to Tolerance TYPE: Hilti/Phillips		2245	✓	7/11/03
(C) Type Stud Installed	SIZE: 1x9"	MIN. DEPTH: 4 1/2"	TYPE: Hilti/Phillips	3080 7/30/03
D. Anchors Torqued		2245	✓	7/11/03
E. Unused holes dry packed		2245	✓	7/11/03
4. BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATES		N/A	✓	N/A old work
5. FIT-UPS: A. Pipe attachments installation:		(1) Seat No: N/A	✓	N/A
		(2) P.O. No: N/A	✓	N/A
B. Support Members:		ITEMS	SPECIAL INSTRUCTIONS	
(1) Groove & Full Pen Welds			Filter Signed in Error 7/11/03	
C. Purge Established where required		N/A	✓	N/A
6. WELD PREP ZONES CLEAN OF PAINT, OIL		2245	✓	7/11/03
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) P.U.#			✓	N/A
8. WELDING OF HANGER SUPPORT MEMBERS ONLY:		IDENTIFICATION	WELD CODE	
SPECIAL WELDING INSTRUCTIONS:		3080	551	7/11/03
9. OTHER INSTRUCTIONS:		3080	✓	7/11/03
All welds at @ plate #96 on per O.P. Jemic 96-97-98-10				
10. FINAL WELD CONDITION-SUPPORT MEMBERS:		A. Weld Surface Clean	2245	✓
		B. Arc Strikes Removed/Minimized	2245	✓
		C. Weld Size Complies with drawing	3080	✓
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION:		FOREMAN INITIAL DATE	O.C. DATE & INITIAL	
A. Components and Dimensions Conform w/ Dwg. & Mat'l. List		DB. 7/11/03	7/11/03	8.2-83
B. Pipe Clearance in Accordance with Drawing		DB. 7/11/03	7/11/03	
C. Riser Clamp Bears upon Lug		N/A	N/A	
D. Hanger is Level and Plumb		DB. 7/11/03	7/11/03	
E. All Bolts/Nuts Installed and Tight		DB. 7/11/03	7/11/03	
F. Wall & Ceiling Plates Shinned where Necessary		N/A	N/A	
G. Grout Request Submitted		N/A	N/A	
H. Lug Clearance within Tolerance		N/A	N/A	
12. SUBBERS:		A. Installed per Separate Process Sheet	N/A	✓
NONE		B. Grinnell Flt. # & Size		
		C. PEA Size		
		D. TUB: WT, NON-IT		
13. SUPPORT ACCEPTED BY O.C. (Complete Installation Review)		O.C. SIGNATURE	DATE	
			7.2.03	

4
 nal
 g
 7" Hilti
 sik Bolts
 1/2" 2
 6.83
 - 7.16.83
 0 ft/103
 7/1/03

PREINSPECTION REMARKS:

NO.	DEFICIENCY	DATE
1.	ALL WELDS INSPECTED	✓ RC 5-25-83
2.	WELDS: Inaccessible Areas/Identified	✓ RC 5-25-83
3.	GAPS: T-Bolts, Tee Spots and Joints	✓ RC 5-25-83
4.	CRACKED PLATES: Gross Damaged or Holes in Plate	✓ RC 5-25-83
5.	WELDS: Back Welds	N/A
6.	WELDS NOT FULLY FUSED	N/A
7.	ARC STRIKES	N/A
8.	MATERIAL SIZE	✓ RC 5-25-83
9.	OVERSIZED HOLES IN PLATE; Washers	N/A
10.	WASHER BASE PLATES/MEMBERS	N/A

Pre-inspection was done by R. Noji (see rev G) 5/25/83

PREINSPECTION REMARKS:

REMOVE EXISTING 1/2" RATE AND INSTALL 3/4" RATES ITEMS (9) & (20)
 INSTALL ITEMS (44) THRU (56)

NOTE INSULATION REMOVAL REQUIRED TO INSTALL ITEM (48)
 ALSO REQUIRED FOR 44, 45, 46 & 47

AN INTERFERENCE MAY EXIST WITH INSTALLATION OF ITEM (51)
 RESOLVE IN PROCESS FOR CONFORMANCE

RELOCATE ITEM ITEM (53) 3" TO UTILIZE EMBED flush corner
 SEE RED-LINED DIMENSION X1355

PGRE PI. FINAL PKG. REVIEW - COMPLETE. MML 6/4/83
 WORK W/ TC - 7142

FINAL INSPECTION COMMENTS: INSPECTOR: DATE:

#54 to #1 fillit gap 3/32 gap exists, also #1 has been grinding down
 to clear some gap on South side 276/27/83
 found volume w/ Chuck for TC-8222 276/28/83
 OPI welds on TC-8222 OK plus upper #53 OK insert OK 276/29/83

FINAL INSPECTION COMPLETE - (AW) 7-10-83

AS BUILT CHANGES AFTER QC FINAL ACCEPTANCE PER QA REQUEST
 WITH THE KNOWLEDGE & APPROVAL OF THE FIELD QA/QC MANAGER (D) 11/3/83
 DCN 16CA-025 WRITTEN FOR DEFICIENCIES (D) 11/3/83

P.G. and
 54
 7-12-83

X 1355

ENGINEER

UN AUTHORIZED BY UNAUTHORIZED PERSONS
 UNAUTHORIZED AND PARTS ADDED TO PIPE AT
 RESTRAINED LINE 1-K-108-1E DUE TO CHECK
 VALVE NEAR HGR 547-17

UN TENSIONED SPRING CAN, HGR 547-17
 SUPPORT 384/322R - UNAUTHORIZED
 WORK, NO CHANGES TO SPECS AFTER
 AFC STAMP SIGNED SWAY STRUT INSPECTE
 BY FIELD ENGINEERS
 GRINDING GOUGE ON 1-K-103-20
 LOG WELDING ON SCW L.O. LINES

GAPS ON HGR 547-17
 TO REN FOR QA VERIFICATION - HGR 384/20
 " HGR 10-1365L

A/P WRONG - SUPPORT 99/11
 WILL REQ. A DR
 ISO 1-A-363 WACKDOWN
 SFWX2165 IRREGULARITY

ARC STRIKES, GOUGES ON VCT
 HOLD POINT ON SUPPORT 229/618
 BOLTS BACKED OFF FIELDS UP, NOT VERIFIABLE
 DESK ON 140 TURBINE, DOC. CONTROL

1604-016	9/20/83	1604-016	9/20/83
1604-017	9/22/83	1604-017	9/22/83
1604-018	9/22/83	1604-018	9/22/83
1604-019	10/10/83	1604-019	10/10/83
020	10/12/83		
021	10/12/83		
022	10/20/83		
023	10/26/83	} NO HOLD TAG	
024	10/26/83		
025	11/3/83	NO HOLD TAG	
026	11/10/83		
027	11/15/83	NO	
028	11/29/83	NO	
029	12/15/83	NO	

PULLMAN POWER PRODUCTS
DCN/HOLD TAG/D.R. LOG

D.C.N.		HOLD TAG		D.R.		DWG #	DISCREPANCY	DATE CLOSE
#	DATE	#	DATE	#	DATE			
1604/001	7/25/83	1604/001	7/25/83	NA	NA	D016-13 REV. A	ARC STRIKES & SCOURCS ON LINES 1-51-3269-4" 1-52-3270-4" [E], 1-52-3271-4" [E] AND 1-52-3272-4" [E]	
1604/002	7/26/83	1604/002	7/26/83	VOID	VOID	344741 REV 2	SCOURCS ON PIPE 1-56-225-10 [A]	
1604/003	7/27/83	1604-003	7/27/83	NA	NA	049265 REV 4	ARC STRIKE ON PIPE 56-508-8 REF. BY PTEC INSULATION INSPECTOR	10/15/83
1604/004	8/5/83	1604-004	8/4/83	↓	↓	1501-21-14	ARC STRIKE ON AIR INTAKE HDR DG 1-2	11/10/83
1604/005	8/6/83	1604-005	8/6/83	↓	↓	060384	SWAY STRUT ON HDR 384-370R REMOVED AFTER FINAL WORKMANSHIP ACCEPTANCE	11/3/83
1604/006	8/8/83	1604-005	8/8/83	↓	↓	SK-18-5R	GOUGES ON PIPE, ARC STRIKE, WEAR PT INDICATION	
1604/007	8/11/83	1604/007	8/11/83	↓	↓	SK-18-5R	ALTERATION OF DCN 1604-006 + FURTHER EXPLA NATION OF DETAILS REF DCN 1604-006	
1604/008	8/11/83	1604/008	8/11/83	VOID	VOID		PASSING QC HOLD POINT	
1604/008	8/15/83	1604/008	8/15/83	52A2	8/21/83 9/9/83	049318	UNDERSIZE WELD ON HDR. PIPE ATTACHMENT HANGER 2A/B5R, WEST LUG LOCATION	
1604/009	8/24/83	NA	NA	↓	↓	049235	REF. DCN - WORK DONE AFTER FINAL WORKMANSHIP HDR 235/11R; 235/165R; 235/36R	11/16/83
1604-010	8/25/83	1604/010	8/25/83	↓	↓		ARC STRIKES ON LINE - HANGER 234/21R VOID - CLASS E DCN NOT WRITTEN LINE REPAIRED	
1604/011	8/30/83	1604/011	8/30/83	↓	↓		SWO H83, HANGER 384/306R - NEW REV PER PG+E MEMO 8/23/83	
1604/012	8/30/83	1604/012	8/30/83	↓	↓		SWO H84, HANGER 384/342 - NEW REV PER PG+E MEMO 8/23/83	9/9/83
1604/013	8/30/83	1604/013	8/30/83	↓	↓		SWO H85, HANGER 384/354R - NEW REV PER PG+E MEMO 8/23/83	
1604/014	9/6/83	1604/014	9/6/83	↓	↓	049294	HANGER 2A/17R - REJECTED BY BILL YOUNG FOR INSUFFICIENT SWAY STRUT CLEARANCE ON PIPE CLAMP	
							HANGER 5A7-14 - ON WHEELS FOR PIPE GAPS OUT OF TOLERANCE	

PULLMAN POWER PRODUCTS
D.C.N./HOLD TAG/D.R. LOG

D.C.N.		HOLD TAG		D.R.		DWG #	DISCREPANCY	DATE CLOSED
#	DATE	#	DATE	#	DATE			
016	9/20/83	016	9/20/83	NA	NA	051396	UNAUTHORIZED R+WELD FOUND BY PPP FE BILL AVELLAN AT PREINSPECT - VOIDED BY HAROLD KARNER	N/A
017	9/22/83	017	9/22/83			049242	UNINTENTIONAL RESTRAINT, HGR 547-17 VOIDED BY IDI TO REMOVE "T" COUPLING	N/A
018	9/22/83	018	9/22/83			500547	UNTENSIONED SPRING CAN, LOOSE PIPE CLAMP	11/12/83
019	10/10/83	019	10/10/83			060384	UNCONTROLLED DOCUMENTATION, X HTS VOIDED BY RICK MARKS	N/A
020	10/12/83	020	10/12/83			5K-18-17R	GOUGE ON PIPE	11/2/83
021	10/12/83	021	10/12/83				ACCEPT AS IS BY PG+E	
022	10/20/83	022	10/20/83			500547	GAPS ON HGR 547-17 ACCEPTED BY ME OUT OF TOLERANCE	11/10/83
023	10/15/83	NA	NA			384-207R	FOR R.E. NIEMYER OF QA	12/13/83
024	10/23/83	NA	NA			049308	FOR R.E. NIEMYER OF QA	
025	11/3/83	NO	NA				VOIDED BY R MARKS - WILL BE RE-SUBMITTED AT A LATER DATE	
026	11/10/83	NA	NA			1501-4-363	SHARP IRREGULARITY, SFWX-2165	
027	11/15/83	NA	NA	5578	11/19/83	049315	ARC STRIKES + GOUGES, UNIT 1 VOLUME CONTROL TANK.	
028	11/29/83	NA	NA			049229	PASSED HOLD POINT - CANNOT VERIFY BOLTS BACKED OFF PRIOR TO WELDING	
029	12/15/83	NA	NA				UNCONTROLLED DOCUMENTS, STAMPS, ETC IN UFE DESK, U-1 MO' TURBINE	
030	12/15/83	NA	NA				VOIDED BY JEFF CHARBONEAU FOUND BARE WIRE UNCONTROLLED. SUPT CHARBONEAU INSTRUCTED THIS SHOULD BE REPORTED ON MONTHLY MAINTENANCE REPORT	

DEFICIENT CONDITION NOTICE

UNIT # 1	AREA G	ELEV. 100'	COL/LINE 182' 00' R=48' 4"	DATE: 7/26/83	NOTICE NO. 1604-002
-------------	-----------	---------------	----------------------------------	------------------	------------------------

DEFICIENT CONDITION: DURING FINAL WORKMANSHIP INSPECTION OF SUPPORT 54N/11R, INSPECTOR NOTICED MANY HAMMER GAUGES (DINGS) IN LINE 1-56-255-10 (A). THE GAUGES ARE APPROXIMATELY 1/8 IN. DIA AND 1/64 DEEP, LOCATED AS SHOWN ON PAGE 2. GAUGES ARE LOCATED NEAR FWX354E AND FWX354F AS SHOWN. CRAFT WORKERS CLAIM GAUGES WERE ALREADY PRESENT BEFORE WORK ON HANGER BEGAN, AND PIPE WAS COVERED WITH CLOTH WHEN INSPECTING. INFORMATION COPY OF FIELD PACKAGE INCLUDED FOR REFERENCE. HANGER 56N-133R IS STILL IN PROCESS, AND CRAFT INSTRUCTED NOT TO ATTACH TO WALL UNTIL HOLD IS CLEARED.

ORIGINATOR'S SIGNATURE:
T.D. O'Neil

HOLD TAG APPLIED: YES	TAG # 1604-002	INITIALS <i>TO</i>	DATE 7/26/83
-----------------------	----------------	--------------------	--------------

RECOMMENDED DISPOSITION:

1000

FIELD ENGINEER
FIELD QC INSPECTOR
CHIEF ENGINEER
LEVEL III
FIELD QA/QC MANAGER

FIELD QA/QC MANAGERS EVALUATION: APPROVED AS RECOMMENDED OTHER

- NON-CONFORMANCE - D.R.# _____
- REPAIR ORDER
- REWORK/REINSPECT
- INTERNAL AUDIT
- OTHER

COMMENTS: *7/26/83*

CAUSE CODE


DATE	FIELD QA/QC MANAGER
------	---------------------

CORRECTIVE ACTION REQUIRED BY: _____ NOT LATER THAN: _____

STEPS TO PREVENT RECURRENCE: NOT APPLICABLE

RESPONSIBLE SUPERVISOR	DATE	FIELD QA/QC MANAGER
DEFICIENT CONDITION CLOSED:	DATE	SIGNATURE:

76-1483(4-82)

AREA <u>1-G</u>	LINE <u>1-56-255-10-A</u>	HANGER SYMBOL 
EL <u>100'-0"</u>	<u>SYS 03 SIS</u> <u>ACCUM INJ LOOP 3</u>	Y RESTRAINT <u>---</u>
		LOC ON DWG <u>500056</u>

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
2	10-4-82	<p>AS BUILT PER M.E. LEPPKE MEMO DATED 6-1-82.</p> <p>THIS PIPE HAD HAMMER DINGS AND COUSES WHICH WOULD HAVE GONE ON DCN 1604-00Z WHICH WAS VOIDED DUE TO RICK MARKS INSTRUCTION THAT DEFECTS WERE ACCEPTABLE AS-IS. 8/6/83</p> <p>FOR INFORMATION ONLY</p>	JS	JS	JEB	176X	TJM	JKL
		<p>A.S.W.R.</p> <p>REASON: _____</p> <p>_____</p> <p>Work to attached sheet 56N-1338</p> <p>ENGR: <u>RNO</u></p> <p>JE 3/17/83</p>						

NOTES:

WORK W/ 56N-133R

APPROVED FOR CONSTRUCTION

DATE 3-17-83 ENGR RNO

JE 3/17/83

NOTE: INSTALL COMPLETE ~~AS BUILT~~ PRIOR TO WORK SIS 56N-133R

W.A. 6/3/83

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 3 SHEETS)

176	176A	176X																	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20



DSGN JS
DWN JS
CHKD JEB

DRAWING NO 049261

PROJECT: <u>DIABLO CANYON</u>	UNIT: <u>ONE</u>	176X OF <u>SHS</u>	P G & E CO	ISSUE
-------------------------------	------------------	--------------------	------------	-------

MICROFILM

AREA <u>1 G</u>	LINE <u>1-56-255-10 A</u>	HANGER SYMBOL <u>56N</u> Y-RESTRAINT <u>11R</u>
EL. <u>100'-0"</u>	ACCUMULATOR INTEL NOS. TION LOOP 3	LOC. ON DWG. <u>500056</u>



NO. OF ASSEMBLIES REQUIRED 1

NO.	REQD	MATERIALS
1	2	L3 x 3 x 1/2, 2'-4" LG. EA. W/(2) - 15/16" HOLES.
2	4	7/8" Ø STUD. TYPE CONCRETE ANCHOR. - UU
3	2	4 E 7-25, 6" LG. EA. (SEE DETAIL ABOVE) - SLD
4	2	STIFF PL 1 3/8 x 1/4, 3 3/8" LG. EA. CUT TO FIT.

FOR INFORMATION ONLY

REV. 1: REDESIGNED. THIS SH. SUPERSEDED SH. 102.
APPROVED FOR CONSTRUCTION.

INCORPORATED FIELD VERIFICATION SHEET AS OF 6-24-82	PG & E CO. SHEET 176 OF 176 SHEETS	DRAWING NO. 049261	2
--	---------------------------------------	-----------------------	---

DSGN: AC. 5/6/80
CHK: CHG 1: P.K. 5/6/80

AREA 1G

EL 100'-0"

LINE 1-56-255-10 A

ACCUMULATOR INJECTION LOOP 3


HANGER SYMBOL

RESTRAINT Y



LOC ON DWG 500056

76-111



APPROVED FOR CONSTRUCTION

DATE ENGR

6-24-82

09 SIS

ELEV: 116 FT SOUTH

FOR INFORMATION ONLY

INCORPORATED FIELD VERIFICATION SHEET AS OF 6-24-82

DSGN DWN TS 7-2-82 CHKD

DRAWING NO 049261

PROJECT: DIABLO CANYON UNIT: ONE

SMT176A OF SHTS

P G & E CO


ISSUE 2 REV

MICROFILM

PIPE SUPPORT DESIGN TOLERANCE CLARIFICATION FORM

SUBJECT 56N-11R REV 2 SEQUENCE NUMBER TC-1-9826 CLASS I/A
LOCATION AREA: 1-6 ELEV: 91 pre-inspect
in-work
past work
DR #

DESCRIPTION:



CHANGE WELD ITEM 1-2 AS SHOWN. WELD SYMBOLS ON DWA. UNCLAR.

FOR INFORMATION ONLY

REFERENCE DRAWING 049261 SH 176 P.P.P. F.E. SKP
ATTACHMENTS YES (NO) PAGES (INC. THIS SHEET) 1 G.C. F.E.
AREA ENGINEER: Stephen Beckey DATE 7-22-83
CONSTRUCTION MAY PROCEED
CONSTRUCTION D.P. REQ'D
CONTRACTOR RECEIPT Dur Peck DATE 7/22/83

QUICK FIX DESIGN CHANGE

QFDC NUMBER QF1-1963

SUBJECT 56N-11R REV 2 54914 CLASS 1A

LOCATION 1-G EL=100

DESCRIPTION:

COPE ITEM #1 (L 3x3x1/2) AS NEEDED TO CLEAR ITEM #11 (W 4x13) OF HGR. # 56N-133R.

APPROVED FOR CONSTRUCTION
3-7-83 - JAP
DATE BY

3-7-83

FOR INFORMATION ONLY

P.G. 9 E.F.E. 1A

REFERENCE DRAWING 049261

ATTACHMENTS YES NO

PAGES (INCLUDE THIS SHEET) 1

AREA ENGINEER:

CONSTRUCTION MAY PROCEED Howard Grottk

DATE 15-MAR-83

CONSTRUCTION D.P. REQ'D

CONTRACTOR RECEIPT

David Park

DATE 3-5-83

PULLMAN POWER PRODUCTS

REQUEST FOR AUTHORIZATION
TO ADD HANGERS TO EXCEPTION LIST

AREA G

DATE 3-5-83

REQUEST # 1388

YS#	HGR SYM.	DWG #	REV.	LINE #	S/B ISO #	CLASS	COMMENTS
7	56N-11R	049261	2	255	—	I/A	

ASON FOR REQUEST:

HGR # 56N-133R REV. 3 CALLS FOR 2'30N 56N-11R TO BE TRIMMED. 56N-133R NOW BEING WORKED. NEED ASWR OF 56N-11R ASAP.
REVISION 2 IS EIA'D REQUEST TO 11W EIA 56N-11R

FOR INFORMATION ONLY

REQUESTED BY: Doug Beck P.P.P. DATE: 3-5-83

E. DISPOSITION:

SKETCH SHOWS AN INTERFERENCE OF 1/4" BETWEEN ITEM NO 1 OF HGR 57N-11R AND HGR 57N-133R. IF THIS IS THE TRUE FIELD CONDITION, REQUEST TO ASWR HGR 56N-11R IS APPROVED PROVIDED ITEM NO 1 IS NOT TRIMMED MORE THAN 1/2" DEEP. RESUBMIT THE MODIFIED AS BUILT OF 56N-11R TO QFDC FOR REVIEW AND APPROVAL PENDING RESPONSE PER WFF QFDC # 1963

DISPOSITIONED BY: I. ANUMA APV P.B.E. DATE: 3-8-83

X USER
 EST TO ROVE
 50 STUDS
 TO 110FT LB
 DN 7-23-83
 PPP 39

ACCEPT WELDS
 3
 4
 DN 7-26-83

1. LOCATION OF SUPPORT COMPLIES WITH DRAWING		3353	7/26/83
2. DRAWING CHANGES NOTED AND COMPONENTS COMPLY WITH MATERIAL LIST		3353	
3. ANCHORS INSTALLED AND WITNESSED BY Q.C.		040606	OLD WORK NA
A. Holes drilled to tolerance and Check adjacent anchors B. Shield/Flug Drives to Tolerance TYPE: Hill/Phillips C. Type Stud Installed SIZE: 7/8" MIN. DGS TYPE: Hill/Phillips D. Anchors Torqued SIZE: 7/8" VALUE: 110 FT-LBS WRENCH SERIAL NUMBER: PPP # 39 E. Unused holes dry packed		3344	7-25-83
4. BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATE		N/A	NA
5. FIT-UPS: A. Pipe attachments installation:		(1) Heat No: N/A	NA
		(2) P.O. No: 1	NA
B. Support Members:			
(1) Groove & Full Pen Welds		3/4" G C E T N A P E R T C + 41026 NA	7-16-83
C. Purge Established where required			NA
6. WELD PREP ZONES CLEAN OF PAINT, OIL		3344	
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) P.S. 1			NA
8. WELDING OF HANGER SUPPORT MEMBERS ONLY:			
SPECIAL WELDING INSTRUCTIONS:		CS/CS 7/81 8997 NA	
		SS/SS 129	NA
		CS/CS 15/16	NA
		SS/SS	NA
9. OTHER INSTRUCTIONS:			
RETORQUE NUTS 1' BOLTS DUE TO INSUFFICIENT GAP IN PIPE		7/16/83	7/26/83
WRENCH PPP # 75, 33 CAL 7/15/83 DOE 8/15/83 110' LB			
10. FINAL WELD CONDITION—SUPPORT MEMBERS:			
A. Weld Surface Clean		3344	7-26-83
B. Arc Strikes Removed/Minimized		3344	7-26-83
C. Weld Size Complies with drawing		3344	7-26-83
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION:			
A. Components and Dimensions Comply W/Dwg. & Mat'l. List			
B. Pipe Clearance in Accordance with Drawing			
C. Riser Clamp Bears upon Lug		NA	NA
D. Hanger is Level and Plumb			
E. All Bolts/Nuts Installed and Tight			
F. Wall & Ceiling Plates Shimmed where Necessary		NA	NA
G. Grout Request Submitted			
H. Lug Clearance within Tolerance			
12. SURFACES:			
A. Installed per Separate Process Sheet			
B. Grinnell Fig. / & Size			
C. PSA Size			
D. TYPE: WY			
E. MIN-WY			
13. SUPPORT ACCEPTED BY Q.C. (Complete Installation Review) Q.C. SIGNATURE			
DATE			

FOR INFORMATION ONLY

FOREMAN INITIAL/DATE: [Signature] 7/26/83
 Q.C. DATE & INITIAL: [Signature] 7/26/83
 [Signature] 7/26/83
 [Signature] 7/26/83

PRE-INSPECTION COMMENTS

Q.C.	REMARKS
✓	5-17-83
✓	5-17-83
✓	5-17-83
NA	
NA	
✓	5-17-83
	Painted
✓	5-17-83
✓	5-17-83
✓	5-17-83

N/A
JAF
3/17/83

PRE-INSPECTION REMARKS:

OK TO WORK WITH 56N-133R

JAF 3/17/83

READ!

PRE-INSPECTION COMPLETE. O.K. TO INSTALL PER QF-1963
MUST INSTALL THIS SUPPORT FIRST DUE TO ACCESSIBILITY
PROBLEMS (BEFORE 56N-133R Y-STENCIL HANGER AFTER COMPLETION)

W.A.G.
1/10

PGCE FINAL PACKAGE REVIEW COMPLETE W/M 6-4-83

PRE-INSPECT COMPLETE - JAF 6/19/83

VG & F. PREINSPECTION COMPLETE, 11 RELEASE. JAF 6/17/83

O.K. TO INSTALL ITEM 1 PER REV-2

FINAL INSPECTION COMMENTS:

INSPECTION

DATE

HANGER COMPLETE PER REV 2 & TC-10 99269 QF-1963 NOV 7-25-83
ANCHOR BOLTS STILL NEED DRIVING - COMPLETE 1412 7-26-83
DCN 1604-002 WRITTEN FOR GAUGES ON TOP
OF PROCESS PIPE, HXD TAG APPLIED 7/26/83

FOR INFORMATION ONLY

NO. SGN 11R REV. 2

AREA/ELEV. 1G
SYSTEM 9

HANGER FINAL INSPECTION CHECK SHEET

ITEMS TO BE CHECKED	REFERENCES OTHER THAN ESD 223	ENGINEERING INSPECTION	
		INITIAL	FINAL
Common To All Hangers/Supports:			
1. Hanger Location within ESD 223 Tolerance			<i>WJ 7-25</i>
2. Bolting Support to Structure / Adjacent Anchor Spacing			NA
3. Preheat of Structural Steel if Required			NA
4. All Items in B.O.M. Installed & Are Correct Type		N/A	<i>WJ</i>
5. All Items in B.O.M. Exhibit the Correct Dimension		N/A	<i>WJ</i>
6. Configuration as Per Design Dwg.			<i>WJ</i>
7. Hanger Carrying Load (Examine Total Support)		N/A	<i>WJ</i>
8. All Welds Complete and Acceptable			<i>X QC</i>
9. Integ. Attach. Mt. No. & F.W. No. noted on Process Sheet			NA
10. Threaded Connections Secure		N/A	NA
11. Thread Engagement Adequate		N/A	<i>WJ</i>
12. Guide Clearances Acceptable		N/A	<i>WJ</i>
13. Expansion Offset Correct as Designed (Thermal)			NA
14. Clamping Config. Correct		N/A	NA
Review Package for Design Change Approvals			<i>WJ</i>
16. Hanger Properly Identified, No. Written on Hanger			<i>WJ</i>
17. Hanger & Pipe Clearances are Adequate for Thermal Movement			NA
18. Configuration is Free from Arc Strikes		N/A	QC
19. Configuration is Free from Weld Spatter		N/A	QC
20. Weep Holes Installed		N/A	NA
21. Attachment to Other Supports As-Built			NA
Spring Cans:			
22. Spring Can LD. Plate Complete		N/A	NA
23. Load Column Not Bound on "F" Cans		N/A	
24. Spring Can Set Per Dwg.			
25. Thread Engagement Adequate on Spring Components		N/A	
26. Hot & Cold Load Indicators Attached			
Shock Supports/Sway Struts/Specials:			
27. High Strength Nut & Bolt Mat'l. Properly LD.		N/A	
28. Staking of Ball Bushings Complete		N/A	
29. Mech. Shock LD. Plate Complete		N/A	
30. Load Stud Centered on Clamp		N/A	
31. Shocks Protected		N/A	
32. Verify Thread Engagement on Rod Ends		N/A	
33. Welds in Accord. with ESD 223		N/A	
34. Hot & Cold Setting Per Dwg.		N/A	

FOR INFORMATION ONLY

COMMENTS: _____

Record Fitter & Welder Badge No.: _____

Attnd 02

7 00 02

JANUARY 14, 1983,

INTEROFFICE CORRESPONDENCE

MARCH 9, 1983,
APRIL 25, 1983, AND
JULY 21, 1983

DATE

TO ALL FIELD SUPERINTENDENTS

FROM P. STIEGER/R. FAULL

SUBJECT ARC STRIKES, GRINDER GOUGES AND PUNCH MARKS.

PLEASE CONDUCT A TRAINING SESSION WITH ALL CRAFT PERSONNEL CONCERNING THE FOLLOWING:

In the recent past we have had too many arc strikes and grinder gouges on pipes, hangers, rod assemblies, etc. In order to eliminate these conditions, each person must take the following precautions:

- 1) Do not ground to pipes, hangers, etc.
- 2) Protect surrounding pipe hangers and other equipment in work area from weld splatter, grinding and thermal debris.
- 3) Be careful not to let stingers arc pipe, hangers, etc., when hanging stingers, setting them down or during other movements of stinger.
- 4) Do not drag leads over pipes, etc: if they have bare spots or open connectors they may arc.
- 5) Disconnect all leads from grids before pulling or rolling them up.
- 6) Use extreme caution when grinding in close proximity of piping. Protect the pipe prior to grinding. It is your responsibility to follow these steps and to eliminate arc strikes and grinder gouges on piping and other members.
- 7) Be sure cables are connected with matching connectors. Do not use a Cam-lock connector with a Jackson as they do not fit properly.
- 8) Check cables for broken insulation on bare spots.
- 9) All welding arc starts shall be confined to weld preparation area.
- 10) Center punches shall not be used on piping where the punch mark will not be removed by subsequent cutting or grinding. A low stress stamp or vibrorod is an acceptable method of marking.

P. Steiger
P. Steiger
Resident Construction Manager

R. Faull
R. Faull
Assistant Resident Construction Manager

PS:sam

269

AREA 1G

LINE 1-56-508-B III B

HANGER SYMBOL





EL. 117'-0"


NOS.

LOC. ON DWG. 500058

DESIGN CLASS II
NODE CLASS B
X



EXIST. INSTL. ACCEPT
SEE *Prior Rev. 3*
6-16-83 LOCATION PLAN



NO. OF ASSEMBLIES REQUIRED 1

FOR DATA SEE FILE 33

NO.	REQD	MATERIALS
1	2	MAX13, 2'-1 3/8" LG. EA.
2	2	MAX13, 1'-0 1/2" LG. EA.
3	1	MAX13, 2'-9 1/4" LG. TRIM TO SUIT
4	2	8"Ø PIPE, 1/2" INSULATION, FIG. 212, MODIFIED SPIDER CLAMP SEE DETAIL "A" ABOVE
5	12	STIFF R 1/4 X 1/8 X 0'-3 1/2" LG EACH (CUT TO FIT)
6	2	M. 4 X 13 6" LG (TRIM TO FIT)

270
3

DESIGN UNIT #1

PG & E CO.

DRAWING NO.

SHEETS 7 OF

SHEETS

049265

4

LDWE 1-K-241

HANGER SYMBOOL


1-25/83

LOC ON DWG 5000

FIELD SUPPORT RELOCATION
TOLERANCE 0" DOWN 9/16" UP

DESIGN CLASS
CODE CLASS 3

CALLED NORTH



APPROVED FOR
CONSTRUCTION
6/25/83 WNW
DATE ENGR

CR ESD 223
6.8.2.3 E
CE7
6.8.2.3

MATERIALS PER ASSEMBLY SEE T.C. # 1-10212
CE7 7-21/83

NO	REOD	DESCRIPTION
1	1	SRS-20-PC SWAY STRUT ASSY. C-C = B = 4 3/4" W/F
2	1	SPC-20-D60 PIPE CLAMP
3	4	1/4" x 3 13/16" C.S. PLATE 7/8" LG (CUT TO FIT)
4	1	1" x 2'-0" C.S. PLATE 2'-0" LG 2'-1" x 2 1/2" CONTROLLED COPY
5	14	1" HILTI KWIK BOLTS MIN. EMB. 6"
6A	2	1" x 10" C.S. PLATE 2'-0" LG 2'-1"
7	2	1" x 5" C.S. PLATE 2'-0" LG 2'-1"

ISO 1-14-5

PIPE SUPPORT DESIGN TOLERANCE CLARIFICATION FORM

SUBJECT 1B-5R REV DC SEQUENCE NUMBER TC-1-257B CLASS 1


LOCATION AREA: 1-D ELEV: 98'-0" pre-inspect
SYS 14 in-work
past work
DR #

DESCRIPTION:

ITEM 17 WARPAGE PRODUCES ~~VARIGD~~ VARIGD GAP

SOLUTION.

REVISE WELD OF ITEM 17 TO THE PIPE AS SHOWN BELOW --



NEW FIELD WELD #5
(E) X1414 A-H

FWX1414 A-D NS
TYP
FWX1414 E-H FS

P.P.P. F.E. [Signature] 7/2/83
G.C. F.E. [Signature]

REFERENCE DRAWING DC-1-EP-9041 REV 0
049242 SH 14, 15, 16, 16X

ATTACHMENTS YES (NO) PAGES (INC. THIS SHEET) 1

AREA ENGINEER:

CONSTRUCTION MAY PROCEED [Signature]

DATE 7-2-83

CONSTRUCTION D.P. REQ'D

CONTRACTOR RECEIPT [Signature] DATE 7/2/83

AREA 1-D

LINE 1-K-104-20

HANGER SYMBOL

$\frac{1}{2}$ " RESTRAINT



EL 98'-0"

C.C.W. SUPPLY HDR.

LOC ON DWG 500028



DESIGN CLASS-I
CODE CLASS-C

TYP. BETWEEN
ITEM #7 &
PIPE WALL

DETAIL '1'

TYP. THREE
SIDES
ONLY

REFER TO SHTS 15 & 16



NO. OF ASSEMBLIES REQUIRED 1

NO.	REQ'D	MATERIALS PER ASSEMBLY			
1	1	W8x28, 11'-7" LG.	18	2	PL $\frac{3}{8}$ x $\frac{7}{8}$ x 2'-0" LG
2	2	W8x28, 5'-0" LG.	19	4	STIFF. PL $\frac{1}{2}$ x $\frac{3}{8}$ x 0'-7 $\frac{1}{8}$ "
3	1	W8x28, 3'-6" LG.			
4	1	W8x28, 2'-0 $\frac{1}{8}$ " LG.			
5	6	PL $\frac{1}{2}$ x 2 $\frac{3}{4}$ x 0'-7" LG.			
6	2	PL $\frac{3}{8}$ (25 PER DETAIL #2)			DELETED
7	2	PL $\frac{3}{8}$ x 4" BEND TO FIT 20" O.D. PIPE. (PER DET. #2) 12 $\frac{1}{2}$" LB			
8	2	LG x 4 x $\frac{3}{8}$ x 4'-5 $\frac{1}{2}$" LG. (CUT TO FIT)			DELETED
9	1	W8x28, 1'-4" LG. (CUT AS SHOWN)			
10	1	W8x28, 2'-9" LG. (CUT AS SHOWN)			
11	1	W8x17, 5'-9 $\frac{7}{8}$ " LG. (CUT AS SHOWN)			
12	2	BAR 7x4, (A) $\frac{1}{2}$ " THK., (B) $\frac{7}{8}$ " THK.			
13	1	PL 6 $\frac{1}{2}$ " x 8" x $\frac{1}{8}$ " SHIM PLATE			
14	2	W4x13x 5'-0" (FIELD CUT TO SUIT)			
15	2	PL $\frac{3}{4}$ " x 6" x 7" - STIFF. PLATE			
16	2	PL 1 $\frac{1}{4}$ " x 3" x 8" C.S. PLATE (FIELD GRIND THK. TO SUIT)			
17	4	PL $\frac{3}{8}$ x 4" x 12" LG. BEND TO FIT 20" O.D. PIPE			

DSGN LCC's
DWN RKB-10-22-80
CHKD TUD-11-17-80

DRAWING NO
SK-18-5R

D R E C O

AREA 1-D

LINE 1-K-104-20 [C]

HANGER SYMBOL




Y/E RESTRAINT

EL 98'-0"

C.C.W. SUPPLY HDR.

LOC ON DWG 50002X



ELEVATION LKNG. EAST
VIEW A-A


SECTION D-D



SEE DETAIL #2

DSGN LGE 2	DRAWING NO -
DWN OG 9.10.81	SK-18-5R
CHKD [Signature]	


AREA 1-D
 EL 98'-0"

LINE 1-K-104-20 C
C.C.W. SUPPLY HDR.

HANGER SYMBOL 
Y&Z RESTRAINT
 LOC ON DWG 500028



SECTION B-B



SECTION C-C

* GRIND ITEM # 17 IF REQ'D SUCH
 THAT UNIFORM CLEARANCE
 MAINTAIN WITH ITEM # 16

REFER TO SHTS. 14 & 15

DSGN L.C. 1	DRAWING NO	
DWN RKS 10-25-50	SK-18-5R	
CHKD L.C. 11/1/50		

AREA 1-D

LINE 1-K-104-20-C

HANGER SYMBOL

18
5R

EL 98'-0"

CCW SUPPLY HDR.
SYS. 14

Y. Z RESTRAINT

LOC ON DWG 500028

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
		EXIST FW# x1377 A-D ITEM #17 EXIST FW# x.860 & x.861 ITEM #7 EXIST FW# x.860 & x.861 160 140 2243 EXIST FW# x1414A-H ITEMS #7:17 SEE QF-1-8578						
1	06 20 83	ADDED ITEMS 15 & 19 PER NEW ANAL. 4-102 REV. 2. UNDER DC-1-E- P-9041 REV. 1	DAR	DAR	W. J. W. ED	HGT		
					14 CCS			

NOTES:

FOR INFORMATION ONLY

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 4 SHEETS)

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
			15	16	16 X														

DCN # DC-1-E-P-9041 REV. 0

PROJECT: DIABLO UNIT: ONE

DSGN NI
DWN YBS
CHKD NI

SHT. 12 OF SHS

DRAWING NO
SK-18-SR


P G & E CO

ISSUE REF


EL 98'-0"

C.C.W. SUPPLY HDR.


LOC ON DWG 500028



SECTION B-B



DETAIL # 3



SECTION C-C

DUPLICATE COPY CCS
CONSTRUCTION
INFORMATION ONLY

DETAIL # 2

* GRIND ITEM # 17 IF REQD. SUCH
THAT UNIFORM CLEARANCE
MAINTAIN. WITH ITEM # 16

REFER TO SHTS. 14 & 15

273

DIN NO. DC-E-P-904

DSGN LCTY	DRAWING NO
DWN <i>[Signature]</i>	SK-18-5R
CHKD <i>[Signature]</i>	

EA VAULT 0-2

LINE 1-2-J-3092-2 1/2
1-2-J-2599-2
1-2-J-2746-2
FO TRANS PPO-2 RV DISCH

HANGER SYMBOL

20
85R


77'-0"

LOC ON DWG 508845


DIESEL FO TRANS. PPO-2 DISCH.
DIESEL FO FILTER 0-2 BYPASS

DESIGN CLASS I
CODE CLASS C

CALLED NORTH



LOCATION PLAN



A-A

21
DFOS

NO. OF ASSEMBLIES REQUIRED

NO	REQ'D	MATERIALS PER ASSEMBLY
1	1	1/2" X 2 1/2" FIG 137
2	3	L3 X 3 X 3/8" 2' LG ±
3	2	L4" X 3" X 3/8" 2' LG ± (NOT TO BE USED)
4	2	3/8" X 2 1/2" FIG 137
5	4	1/2" X 3/4" X 1 1/2" C.S. LUGS
6	2	WF 6 X 15.5 4'-11 1/2" LG.
7	2	M4 X 13 2'-10" LG.
8	2	STIFFNER PL 3/8" CUT TO FIT
9	4	PL 12" X 12" X 1/2" THK SEE A-A INCREASE BOLT HOLE SIZE TO 1 1/16" Δ
10	2	L3" X 3" X 3/8" 2 1/2" LG
11	16	S-58 PHILLIPS CONG. FASTENERS W/ STUD & NUT REMOVE Δ
12	2	WF 6 X 15.5 8'-11" LG.
13	1	L3 X 3 X 3/8 LENGTH BY FIELD
14	1	L2 X 2 X 3/8 1'-6 3/4" LG. (N) REMOVE Δ
15	1	1/2" X 1" X 1" C.S. LUG
16	16	1" Φ HILTI KWIK BOLTS Δ (NEW)
17	1	L3 X 3 X 1/2 X 1'-6 3/4" LG. Δ (NEW)

FOR INFORMATION ONLY

274

DSGN Dwn
DWN R. CHINN
CHKD J. K. [unclear]

DRAWING NO
049318

VAULT 0-2

LINE 1-2-3092-2 1/2
1-2-2746-2
1-2-2599-2

HANGER SYMBOL



77'

NCS.


LOC. ON DWG. 508845

PIPE FREE TO SLIDE AXIALLY

EL. 82'-2"

ALSO SEE SHTS 107, 107

21
DFOS



FOR INFORMATION

SECTION LKS. NORTH

1" = GROUT (TYP.) 1" = GROUT (TYP.)
T.O.C. EL. 77'-0"

DSGN P. ISAAC
DWN R. BAUTISTA
CHKD H. S. SANTIAGO

DRAWING NO
049318

PROJECT: DIABLO CANYON

UNIT: I

SHT 108 OF SHTS

P G & E CO

2
ISSUE REV

PIPE SUPPORT INSTALLATION WORKLIST

DANGER NO.: 235-36R Sys: 18
 LINE#: 1-K-5038-4
 LEV: 85 AREA: B DWG. NO. 049235 SHT. 44X
 DCN NO. _____ REV. 5
 PPP ENGINEER: PAT BRIGNOLLE DATE: 7-30-83
 PGE ENGINEER: H.B. ST DATE: 7-30-83

THE FOLLOWING WORK IS REQUIRED TO COMPLETE THIS PIPE SUPPORT:

OIC TO INSTALL PER REV 5
 PG&E PREINSPECTION FINAL PER REV. Comp. 8/8. 7-30-83

REMOVE EXISTING SUPPORT ON
 PEDESTAL

FOREMAN: TAKE ROPEWAYS DIMENSION FROM 90°
 WORK H&R # 235-165R, 235-36R & 235-11R
 TOGETHER. SUPPORTS 235-165R & 235-36R NEED
 TO BE RELOCATED ALONG PIPE

FOR INFORMATION ONLY

REQ'D	TYPE	DATE INIT.	DATE RET.	REMARKS
YES	<input checked="" type="checkbox"/> C-51			HEAT TRACE: W/A VIB ATTENPTS: N/A
	<input checked="" type="checkbox"/> INS. RMV.			
	<input checked="" type="checkbox"/> IDI			
	<input checked="" type="checkbox"/> G 108			
	<input checked="" type="checkbox"/> PSDTC			
<input checked="" type="checkbox"/>	IMATLAVAL			LINE CLEARANCE REQ'D <u>NO</u>

AREA 1-B

LINE 1-K-5033-4

HANGER SYMBOL

XZ RESTRAINT
TOGETHER WITH 235/36R

235/36R

EL 53'-0"

LOC ON DWG 300120

76-149115

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
2	9-27-82	AS BUILT PER M.E. LEPPKE MEMO DATED 6-1-82.	FSD	FSD	JEK	MUS	JAY	JAY
3	12-10-82	REVISED DWS BY ADDING LINE NO AND ADD DESIGN CLASS I WHICH WAS MISSING (NO FEE WORK)	CEK	JK	RE	JL		TT
4	7-8-83	REDESIGNED SUPPORT TO REMOVE FROM TURBINE PEDESTAL. REPLACED EDS DESCRIPTION FOR REV A & B PER EDS REV C 7-1-83	JK	K	DGH	JAY	JAY	JAY
		ADDED HANGER ENGINEERING FOR CONSTRUCTION DON 031-E-1-8366 SUPPORT REDESIGN						
		CORRECTED RELOCATION TOLERANCE	LFL	LFL	PI	VE	DRC	ASM
5	7/21/83	REVISED TO ROTATE SWAY STRUT REAR BRACKET & CHANGE SIZE OF ITEM 1 (LIMPELL REV A, 7-21-83)	EFT	EFT	DS	N/A	JAY	WJ
		ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION					ASM	DRC

FOR INFORMATION ONLY

NOTES: 1) WORK THIS SUPPORT W/ SUPPORT 25/15R

APPROVED FOR CONSTRUCTION
 7/30/83 DATE
 [Signature] ENGR

NO PIPING PROCESS SHEETS REQUIRED

CONTROLLED COPY

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 2 SHEETS)

44	44X																			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	
											DSGN	DRAWING NO								
											DWN	049235								
											CHKD									
PROJECT: DIABLO CANYON										UNIT: ONE			44X OF SHS		P G & E CO			ISSUE	REV	

MICROFILM

AREA 1-E
EL 25'-0"



LINE 1-K-503R-4
ISO NE 18-220

HANGER SYMBOL
X,Z RESTRAINT
TOGETHER WITH 225/165R
LOC ON DWG 500/20

DESIGN CLASS =
CODE CLASS =
CALLED NORTH

APPROVED FOR
CONSTRUCTION
7/30/83
DATE
ENGR

FIELD SUPPORT RELOCATION
TOLERANCE 10" UP 0" DOWN



LOCATION PLAN
115'-1" PCE
1" SPECIFIED
" PCE
" TOLERANCE
CEM
STRUT ASSY
5/4 C PIPE
8-1-83
19'-2 1/2"
19'-4"
19'-0"
8/19/83

FOR INFORMATION ONLY

NO	RECD	MATERIALS	ASSEMBLY
1	1	SPE TYPE PC, SWAY STRUT	SIZE: 5/4 C.C. = 0'-10 5/8"
		SPE-DB-040	

CONTROLLED COPY

DSGN <u>J. 2/2</u>	DRAWING NO	
DWN <u>GCM</u>	<u>049235</u>	
CHKD <u>CBH</u>		
3HT 44 OF 8HTS	PG & E CO	ISSUE <u>5</u> REV

UNIT: ONE

REV. 4

76-1483

AREA 1-B

LINE 1-K-5033-4

HANGER SYMBOL
XZ RESTRAINT
TOGETHER WITH 235/165
LOC ON DWG 500120

EL 85'-0"

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
2	9-27-82	AS BUILT PER M.E. LEPPKE MEMO DATED 6-1-82.	TRD	RED	JEB	DUS	LM	MS
3	2-10-83	REVISED DWG BY ADDING LINE NO. AND ADD DESIGN CLASS I WHICH WAS MISSING CVD FIELD WORK	CBK	CBK	RE	UJ		JFS
4	7-8-83	REDESIGNED SUPPORT TO REMOVE FROM TURBINE PEDESTAL. REPLACED EDS DESCRIPTION FOR REV. A & B PER EDS REV. C 7-1-83	K	K	DGM	JAY	JAY	JAY
		ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION DEN DCI-E-P-5060 SUPPORT REDESIGN						
		CORRECTED RELOCATION TOLERANCE	CBK	CBK	PI	N/A	DRC	ASM

ASVR N/A 2/18/83
 REASON: WORK TO REV 4
 ENGR: TRD

APPROVED FOR CONSTRUCTION
 DATE: 2/17/83 ENGR: TRD
 DATE: 7-18-83

FOR CONSTRUCTION INFORMATION ONLY
 SUPERCEDED BY REV. 5

NOTES: WORK TO BE DONE FOR THE SUPPORT OF THE 235/165 R
JOB 167
FOR INFORMATION ONLY
CONTROLLED COPY

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 2 SHEETS)

44	44X																			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	
DSGN <u>TRD</u>											DRAWING NO									
DWN <u>TRD</u>											049235									
CHKD <u>JEB</u>											PG & E CO									
PROJECT: <u>DIABLO CANYON</u>											UNIT: <u>ONE</u>				44X OF <u>8</u> SHS		ISSUE <u>4</u>		REV <u>2</u>	
MICROFILM <u>2</u>																				

AREA 1-B

LINE 1-K-5038-4

HANGER SYMBOL

X,Z RESTRAINT
TOGETHER WITH 235/115R

235
36R

EL 85'-0"


150 NR 1B-220

LOC ON DWG 500120

DESIGN CLASS I
CODE CLASS G


↑ CALLED NORTH

APPROVED FOR
CONSTRUCTION
2/12/83 TRAO
DATE ENGR
SHM 7-18-83



FIELD SUPPORT RELOCATION
- TOLERANCE 10" UP 0" DOWN

EXIST. TS. @ MK #1
235/11R



LOCATION PLAN

SECTION A-A
(TS. PIPE ROTATED FOR CLARITY)

FOR INFORMATION ONLY

NO ASSEMBLIES REQUIRED

MATERIALS PER ASSEMBLY

NO	REQD	
1	1	SRF TYPE PC, SWAY ELEV. SIZE NR 6; C.C. = 10' 7 1/16"
		SPC-06-090
		FOR CONSTRUCTION INFORMATION ONLY
		SUPERCEDED BY REV. <u>2</u>
		CONTROLLED COPY

DSGN J. K. K.
OWN GCM
CHKD C. B. H.

DRAWING NO
049235

PROJECT: DIABLO CANYON UNIT: ONE

SHT 44 OF 58

PG & E CO

ISSUE 4
REV

(MICROFILM)

NPS STRUT INSPECTION CHECK LIST

INSPECTOR K. H. Hall

DATE 8-5-83

RANGE 235-36R

- 1. A) Strut size: (08, 14, 20, etc.) 08
- B) Clamp size: (enter pipe dia.) 4"
- C) Coupling type: solid/socket weld solid

CHECK MARK INDICATES ACCEPTANCE

- 2. Clamp bolts installed and tight ✓
- 3. Clamp spacer installed and tight ✓
- 4. Load pin holes aligned in both clamp halves ✓
- 5. End eye threads visible through sight holes N/A
- 6. Jam nut tight N/A
- 7. Strut ends within $\pm 60^\circ$ of optimum or within special requirements noted on drawing/memos ✓
- 8. 1/16" pull back in socket weld verified on process sheet * N/A
- 9. Solid coupling installed concentrically within 1/8" * ✓
- 10. Spherical bearings free of paint and not pushed out ✓
- 11. Cotter pins fully spread ✓
- 12. Spherical bearing washes/spacers installed where required, reducing total side clearance to less than one washer thickness and greater than 0". ✓
- 13. Clamp ears parallel $\pm 1/8"$ at load pin side of clamp ✓
- 14. Comments and/or explanations NPS Strut SRF Type PC K48-5-83

FOR INFORMATION ONLY

* Items 8 and 9 apply to field-fabricated struts, per NPS 11-9 procedure

HANGER PRE-INSPECTION CHECK LIST

ITEMS TO BE CHECKED	REFERENCES ESD 223 AND OTHERS	PREINSPECT CHECKLIST
1. Can Hanger Be Installed At The Proper Location	6.2	P/S
2. Is The Adjacent Anchor Spacing Acceptable	6.4.1	N/A
3. Can All Items Be Installed And All Welds Made		P/S
4. Are All Welding Symbols Accurate And Complete	6.8	P/S
5. Is Old Work As-Built, Acceptable, Or To Be Reworked	PG&E Memo 4-11-93	N/A
6. Disposition DR No. 4678/4730 (As Appropriate)		N/A
7. Is Pre-Heat Or Structural Steel Rod. & Noted On Process Sht	6.8.2.2	N/A
8. Are All Q.C. Hold Points Noted On The Process Sheet	ESD 264	P/S
9. Have All The Necessary Forms Been Originated (Pipe Atch. IDI, Inst. C-51)		P/S
10. Have All The Interferences Been Resolved		P/S
11. Pre-Inspect Package Complete (Reqd. Checklists Attached)		P/S

RE INSPECTED BY: Pat Brigue DATE: 7-30-93

HANGER FINAL INSPECTION CHECKLIST

ITEMS TO BE CHECKED	REFERENCES ESD 223 AND OTHERS	FINAL INSPECT CHECKLIST
1. Hanger Location Within ESD 223 Tolerances	6.2	CCM JL
2. Adjacent Anchor Spacing Acceptable	6.4.1	N/A
3. Threaded Connections Secure/Engagement Adequate		CCM JL
4. All Items In B.O.M. Installed And Are Correct Type	6.6	CCM
5. Configuration As Per Design Dwg.		CCM
6. All Welds Complete And Acceptable (Size, Configuration)	6.8	CCM JL
7. Config. minimized From ARC Strikes, Weld Splatter, Etc.	6.8.2.4	CCM JL
8. Pipe In/Or Guide Clearances Acceptable	6.7	CCM
9. Base Plates, Fish Plates, & Stiffeners Installed Per ESD 223	6.3.7 & 6.3	N/A
10. Hanger Properly Identified. No. Written On Support		CCM
11. Attachments To Other Supports Identified		CCM
12. Specials Rod Supports (I.D. Bolt) Properly Installed	6.5, 6.4.2	N/A
13. Spring Can Installed Cold	6.4.2	N/A
14. Sway Struts Correct Size & Spacing (Reqd. Checklists Attached)	6.7	CCM
15. P To P Within Tolerance	ESD 223	CCM
16. Snock Supports Mechanical Shock. I.D. Plate Complete		N/A
17. Hot & Cold Setting Within Tolerance	6.10.2	
18. P To P Within Tolerance	6.6.2.2	
19. Alignment Acceptable (Clamp & Lead Wks)	Atch. A & B	
20. All Hardware Compatible		
21. Package Reviewed For Completeness (Design Change Appr. Etc)		CCM

FOR INFORMATION ONLY

COMMENTS: Final completed CCM 8.5.83
Reinspected strut installation 8/24/83 JL

RECORD FITTER & WELDER BADGE NO. 5/158 - 5/186

INSPECTED BY: C. E. Tye DATE 8-5-83

INSPECTION CHECKLIST

NO.	DEFECTS	REMARKS
1.	ALL MEMBERS ENGAGED	
2.	WELDS: Inaccessible and/or Under-sized	
3.	GAS: U-Bolts, Tee Shoes and Lugs	
4.	CRACKED PLATES: Cracks damaged or Holes in Plate	
5.	SEAMS: Tack Welds	
6.	WELDS NOT FULLY ENGAGED	
7.	ARC SURFACES	
8.	MAJOR TYPICAL DEFECTS	
9.	OVERHEATED WELDS BY PLATE: WARRIORS	
10.	WELDED BASE PLATE CORROSION	

NEW SUPPORT
 PRE INSPECT
 NO A.C.
 REVID
 PUB 85
 7-30-83

INSPECTION RESULTS:

OK TO INSTALL PW2 REN 5. PUB-7-30-83
 PG&E PREINSPECTION FINAL PACKAGE REVIEW COMPLETE. 7-30-83

FINAL INSPECTION DATE:

DATE OF 8-5-83

FINAL CONCRETE. COM 8-5-83
 Rainwater start installation 8/24/83 JL

DCN 1604-009 WRITTEN FOR WORKING HANGER AFTER
 QC FINAL WORKMANSHIP INSPECTION TO 8/24/83



FOR INFORMATION ONLY

PIPE SUPPORT INSTALLATION WORKSHEET

HANGER NO.: 235-11R

Sys: 18
LINE#: 1-K-5038-4

ELEV: 85 AREA: B DWG. NO. 049235 SHT. 15X

DCN NO. _____ REV. 5

PPP ENGINEER: PAT BEIGNONE DATE: 7-30-83

PG#E ENGINEER: M.B. [Signature] DATE: 7-30-83

THE FOLLOWING WORK IS REQUIRED TO COMPLETE THIS PIPE SUPPORT:

OK TO INSTALL SUPPORT PER REV 5.
C.S. SUBMITTED

PG&E PREINSPECTION FINAL PKG REV. COMP. 7-30-83

FOREMAN: WORK THIS HGR WITH HGRS # 235-165R & 235-36R. THESE HANGERS ARE ATTACHED TO 235-11R & NEED TO BE RELOCATED ALONG THE PIPE RELATIVE TO THE 90° BEND.

FOR INFORMATION ONLY

REQ'D	TYPE	DATE INIT.	DATE RET.	REMARKS
<input checked="" type="checkbox"/>	C-51	7-30-83		HEAT TRACE: N/A WELD ATTEMPTS: N/A
<input checked="" type="checkbox"/>	INS. RMV.			
<input checked="" type="checkbox"/>	IDI			
<input checked="" type="checkbox"/>	G 108			
<input checked="" type="checkbox"/>	PSDTC			
<input checked="" type="checkbox"/>	MATL. AVAIL			LINE CLEARANCE REQ'D

AREA 1-B

LINE 1-K.5076-4 G

HANGER SYMBOL

X-Z RESTRAINT TOGETHER WITH 235/104R

235
11R

EL 85'-0"

LOC ON DWG 500120

76-14

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL			
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR	
2	9-27-82	AS BUILT PER M.E. LEPPKE MEMO DATED 6-1-82.	JS	JS	JEB	MSL	JH	ACT	
3	7/14/82	ADDED PG&E DESIGN CLASS I & CODE CLASS G. DCN DCI-E-P-5060.	PI	PI	RE	dlk	JAE CYER (DR)	TS	
4	7-11-83	REDESIGNED SUPPORT TO REMOVE FROM TURBINE PEDESTAL, (REPLACED DESCRIPTION FOR REV. A) PER EDS REV. B, 7-5-83	fc	JOL	DG4	JRJ	JRH	JRY	
		ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION. DCN. DCI-E-P-5060. FRAME MODIFICATION						DRC	ALM
		ADDED SHTS 15A & 15B BY EDS REVISED ELEV. OF HANGER ASSY. & RELOCATION TOLERANCE	PI	PI	CR	N/A		DRC	ALM
5	7-23-83	REVISED ITEM No. 8 (IMPELL REV. A, 7-21-83)	EFT	EFT	JDS	N/A	JRH	JRY	
		ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION. DCN. DCI-E-P-5060. FRAME MODIFICATION						ASME	DRC

FOR INFORMATION ONLY

NOTES: EC

NO PIPING PROCESS SHEETS REQUIRED

ASWRD TO REV A

APPROVED FOR CONSTRUCTION

7/30/83 RAD

DATE ENGR

CONTROLLED COPY

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 4 SHEETS)

15	15X	15A	15B														
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
											DSGN	JS	DRAWING NO				
											DWN	JS	049235				
											CHKD	JEB					
PROJECT: <u>DIABLO CANYON</u>											UNIT: <u>ONE</u>		15X OF <u>8</u> SHE		PG & EC I		

E
RE

1-B

LINE 1-K-5033-4


X-T RESTRAINT TOGETHER WITH 235/164R 11R

85'-0"

ISO 118 18-220

LOC ON DW 502125

DESIGN CLASS I
CODE CLASS G



FOR INFORMATION ONLY

18
FP

ELEVATION LOOKING EAST

NO OF ASSEMBLIES REQUIRED

APPROVED FOR CONSTRUCTION

NO	REQD	MATERIALS PER ASSEMBLY
1	1	T.S. 6"x6"x 1/2", 9'-10 1/2" LG.
2	1	T.S. 6"x6"x 1/2", 9'-1" LG.
3	1	T.S. 6 x 6 x 1/2, 5'-10" LG. (CUT TO SUIT)
4	1	T.S. 6 x 6 x 1/2, 3'-7" LG. (CUT TO SUIT)
5	1	T.S. 6 x 6 x 1/2, 2'-10" LG. (CUT TO SUIT)
6	1	SRF TYPE PC, SWAY STRUT SIZE NO. 06, C-C = 0'-10 7/16" S.P. - 06-040.

DATE 7/30/63
SIGNATURE [Signature]

CONTROLLED COPY

DSG: [Signature]
DWN G.C. MOORE
CHKD A.P. [Signature]

DRAWING NO
049235

PROJECT: DIABLO CANYON UNIT: ONE

SHT 15 OF 3MTE

PG & E CO

ISSUE RE

MICROFILM


IM INDEXED COPY

76-1117 RC

AREA L-B
25'-0"


LINE 1-K-503B-4
150' NB 1R-220

HANGER SYMBOL
X-Z RESTRAINT
TOGETHER WITH 235/164R
LOC ON DWG 50-120



FOR INFORMATION ONLY

SECTION A-A
(TOP VIEW)



(4) 1/16" DIA. BOLTHOLES

DETAIL 1
(TOP & PLS) (TS ROTATED FOR CLARITY)

APPROVED FOR CONSTRUCTION
7/30/83
DATE RAH
ENGR

S.P.
3/14/83
torqued
Actual EMS

- 1. 6 3/4
 - 2. 6 3/4
 - 3. 6 3/4
 - 4. 6 1/2
- ← E
- 1. 6 3/4
 - 2. 6 3/4
 - 3. 6 3/4
 - 4. 6 3/4
- ↓ N

RM INDEXED REV. 4

CONTROLLED COPY

DRIVING NO. 049235	DATE 7/30/83	ENGR RAH
GCM	J. B. SKINNEY	
SMT 15A 11	BHTS	FC & E CC

SEA 1-B


LINE SEE SHT. 15

HANGER SYMBOL
X-2 RESTRAINT
TOGETHER WITH 235/104R



FL 85'-0"

LOC ON DWG 500120



SECTION B-B
(LKG. NORTH)

Handwritten initials and date: T 10/25

APPROVED FOR CONSTRUCTION
130/25 [Signature]
DATE BSR

FOR INFORMATION ONLY

NO	REQD	MATERIALS PER ASSEMBLY
7	2	^{HW 8/6/83} ^{para 6.3} 1/2" x 7" x 12" GS-PLATE, 12" LG
8	8	5/8" DIA HILTI STUD ANCHOR BOLT MIN. EMB. = 6 1/2"
9	2	1/2" x 7" x 8" Lg HW 8/8/83
10	2	1/2" x 7" x 9 1/4" Lg TC-1-10630

CONTROLLED COPY

RM 1 XLD REV.

DSGN /	DRAWING NO
DWN / JDL	049235
CHKD / [Signature]	


PIPE SUPPORT DESIGN TOLERANCE CLARIFICATION FORM

SUBJECT 235-11R REV 5 SEQUENCE NUMBER TC-1-10630 CLASS IG

LOCATION AREA: 1B ELEV: 104'-0" pre-inspect
in-work
past work
DR

DESCRIPTION:

Due to angle cuts on items ③, ④ & ⑤, need to provide end plates to cover overhang when attached to members ① & ②, as shown.



Item	Qty	Material
9	2	PL 1/2" x 7"
10	2	PL 1/2" x 7"

FOR INFORMATION ONLY

THIS IS ACCEPTABLE.

REFERENCE DRAWING 049235

ATTACHMENTS: YES TAGS (INC THIS SHEET) 1

AREA ENGINEER:

CONSTRUCTION MAY PROCEED Kiran Patel

DATE 8-3-83

CONSTRUCTION D.P. REC'D

CONTRACTOR REC'D [Signature] DATE 8/3/83

A 1-B
EL 85'-0"

LINE 1-K-5078-4 (5)

X RESTRAINT 11R
LOC ON DWG 500120

ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
		DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
2-9-82	AS BUILT PER M.E. LEPPKE MEMO DATED 6-1-82.	JS	JS	JEB	M.S.L.	JAT	AS
3-17-82	ADDED PG&E DESIGN CLASS I & CODE CLASS G. DCN DCI-E-P-5060.	PI	PI	RE	WLL	JAE CATER (DRC)	TPS
4-7-11-83	REDESIGNED SUPPORT TO REMOVE FROM TURBINE PEDESTAL, (REPLACED DESCRIPTION FOR REV.A) PER EDS REV.B, 7-5-83	fc	JDL	DG4	JAY	JRY	JRY
	ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION. DCN. DCI-E-P-5060. FRAME MODIFICATION						DRC ASM
	ADDED SHTS 15A & 15B BY EDS REVISED ELEV. OF HANGER ASSY. & RELOCATION TOLERANCE.	PI	PI	CEK	N/A		DRC ASM

FOR INFORMATION ONLY

FOR CONSTRUCTION
REVISIONS ONLY
EXCEEDING REV. 5

NOTES: PRI 2012 R 7-19-83

NO PIPING PROCESS SHEETS REQUIRED

APPROVED FOR CONSTRUCTION
DATE 7/19/83 ENGR RAO

CONTROLLED COPY

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 2 SHEETS)

15	15X	15A	15B																	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	


PROJECT: <u>DIABLO CANYON</u> UNIT: <u>ONE</u>	DSGN <u>JS</u>	DRAWING NO. <u>049235</u>	PG & E CO	ISSUE	REV
	DWN <u>JS</u>				
	CHKD <u>JEB</u>				
	15X OF 812				
				MICROFILM	<u>2</u>

25'-0"

ISO NR 18-270

LOC ON DW. 500129

DESIGN CLASS I
CODE CLASS G



LOCATION PLAN
FIELD SUPPORT RELOCATION
TOLERANCE 10" UP 0" DOWN

APPROVED FOR CONSTRUCTION
10/63 DAO
RR 2-99-83

NOTE: DIMENSIONS SHOWN ARE FIELD MEASUREMENTS
18 FP

NO OF ASSEMBLIES REQUIRED


NO	REQD	MATERIALS PER ASSEMBLY
1	1	T.S. 6" x 6" x 1/2", 9'-10 1/2" LG.
2	1	T.S. 6" x 6" x 1/2", 9'-10 1/2" LG.
3	1	T.S. 6" x 6" x 1/2", 3'-1" LG.
4	1	T.S. 6" x 6" x 1/2", 2'-10" LG. (CUT TO SUIT)
5	1	T.S. 6" x 6" x 1/2", 2'-10" LG. (C-C = 0'-10 1/16"; SPC = ...)
6	1	SPE. TYPE PC, SWAY ...

FOR INFORMATION ONLY

DSGN. J.P.H.	DRAWING NO. 049235
OWN G.C. MOORE	
CHKD A.B. ...	
BHT 15 OF 18 PAGES	PG & E CO
	ISSUE REV 4
	MICROFILM

PROJECT: DIABLO CANYON UNIT: ONE

AREA L-B LINE 1-K-503B-4 HANGER SYMBOL 255
11R
85'-0" ISO NR 18-220 X RESTRAINT
 LOG ON DWG 500120



SECTION A-A
 (PLAN VIEW)

18
 FD

APPROVED FOR
 CONSTRUCTION
 7/17/83
 ENGR. 108-83

FOR INFORMATION

FOR CONSTRUCTION
 INFORMATION ONLY
 SUPERCEDED BY REV. 5

ONLY

CONTROLLED COPY

DETAIL
 (TYP 2 PLCS) (T.S. ROTATED
 FOR CLARITY)

PROJECT: <u>DIABLO CANYON</u>	VIEW: <u>ONE</u>	SHT <u>15A</u>	SHTS <u>15</u>	DRAWING NO <u>049235</u>	4
P & E CC					

LOCATIONS

HANGER SYMBOL

235
11R


LINE SEE SHT. 15

X-RESTR.

LOC ON DWG 500120

.15

95'-0"



APPROVED FOR
CONSTRUCTION
7/17/83 *[Signature]*
RP 7-1983

SECTION B-B
(LKG. NORTH)

FOR INFORMATION ONLY

MATERIALS PER ASSEMBLY

NO	REQD	DESCRIPTION
7	2	3/4" x 12" C.S. PLATE
8	8	5/8" DIA. HILTI SHELL

FOR CONSTRUCTION
INFORMATION ONLY
SUPERCEDED BY REV. 5

CONTROLLED COPY

DSGN / <i>[Signature]</i>	DRAWING NO	
DWN / JDL	049235	
CHKD <i>[Signature]</i>	PG & E CO	ISSUE 4
- 15 OF SHTS		RE

18
EP

HANGER PRE-INSPECTION CHECK LIST

ITEMS TO BE CHECKED	REFERENCES ESD 223 AND OTHERS	PREINSPECT CHECKLIST
1. Can Hanger Be Installed At The Proper Location	6.2	P/B
2. Is The Adjacent Anchor Spacing Acceptable	6.4.1	P/B
3. Can All Items Be Installed And All Welds Made		P/B
4. Are All Welding Symbols Accurate And Complete	6.8	P/B
5. Is Old Work As-Built, Acceptable, Or To Be Reworked	PG&F Memo 4-11-83	W/A
6. Disposition DR No. 4678/4730 (As Appropriate)		W/A
7. Is Pre-Heat Or Structural Steel Rod. & Noted On Process Shd	6.8.2.2	W/A
8. Are All Q.C. Hold Points Noted On The Process Sheet	ESD 264	P/B
9. Have All The Necessary Forms Been Originated (Pipe Atch. IDI, Insl. C-51)		P/B
10. Have All The Interferences Been Resolved		P/B
11. Pre-Inspect Package Complete (Read. Checklists Attached)		W/B

RE INSPECTED BY: Pat R... DATE: 7-30-83

HANGER FINAL INSPECTION CHECKLIST

ITEMS TO BE CHECKED	REFERENCES ESD 223 AND OTHERS	FINAL INSPECT CHECKLIST
1. Hanger Location Within ESD 223 Tolerances	6.2	JJC B/14/83
2. Adjacent Anchor Spacing Acceptable	6.4.1	JJC B/14/83
3. Threaded Connections Secure/Engagement Adequate		JJC B/14/83
4. All Items In B.O.M. Installed And Are Correct Type	6.6	JJC 8/14/83
5. Configuration As Per Design Dwd.		JJC B/14/83
6. All welds Complete And Acceptable (S... Configuration)	6.8	JJC B/14/83
7. Config. minimized From ARC Strikes, Weld Spatter, Etc.	6.8.2.4	WCB/14/83
8. Pipe And/Or G... Acceptable	6.7	N/A
9. Base Plates, ...	6.3.7 & 6.3	JJC B/14/83
10. Hanger Properly ...		JJC B/14/83
11. Attachments To Other Supports ...		N/A
12. Specials Rod Supports, T-Snoes, U-Bolts, Properly ...	6.4.3	N/A
13. Spring Can Installed And ...		JJC B/14/83
14. Sway Struts Correct Size Installed ...	6.6.2.2	WCB/14/83
15. ...		N/A
16. Shock Supports Mechanical Shock I.D. Plate Complete	6.10.2	N/A
17. ...	6.6.2.2	N/A
18. ...	Atch. A & B	N/A
19. ...		N/A
20. All Hardware Compatible		JJC B/14/83
21. Package Reviewed For Completeness (Design Change Appr. Etc)		

FOR INFORMATION ONLY

COMMENTS: _____

RECORD FITTER & WELDER BADGE NO. _____

INSPECTED BY: [Signature] DATE: 8/14/83

1. LOCATION OF SUPPORT SYSTEMS AND BEARING. 5/15/83 7/46 W.

2. BEARING BEARS LOAD AND BEARING CAPACITY. 5/15/83 7/46 W. 2/17/83

3. BEARING BEARING AND BEARING BY O.C. TYPE: HILTI/PHILLIPS 5/15/83 7/46 W. 2/17/83

4. TYPE SIZE INSTALLED TYPE: HILTI/PHILLIPS 5/15/83 7/46 W. 2/17/83

5. ANCHOR BOLTS TYPE: HILTI/PHILLIPS 5/15/83 7/46 W. 2/17/83

6. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

7. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

8. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

9. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

10. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

11. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

12. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

13. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

14. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

15. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

16. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

17. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

18. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

19. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

20. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

21. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

22. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

23. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

24. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

25. BEARING BEARING BY O.C. 5/15/83 7/46 W. 2/17/83

See Remarks on setting Abstract 8/1/83

* Accepted Final Weld at Item 1 to Civil Steel. At 8-5-83
 * Accepted Final Weld at Item 2 to Civil Steel. At 8-5-83

FOR INFORMATION ONLY

1. WALL BRACING CLAS	5/15/83	5/30	8/8-14
2. ANCHORS REMOVED/REPLACED	5/15/83	5/36	8/8-14
3. BEARING BEARING BY O.C.	5/15/83	5/36	8/8-14
4. BEARING BEARING BY O.C.	NA	NA	NA
5. BEARING BEARING BY O.C.	NA	NA	NA
6. BEARING BEARING BY O.C.	D.C. 8-13	NA	8/8-14
7. BEARING BEARING BY O.C.	D.C. 8-13	NA	8/8-14
8. BEARING BEARING BY O.C.	NA	NA	NA
9. BEARING BEARING BY O.C.	NA	NA	NA
10. BEARING BEARING BY O.C.	NA	NA	NA
11. BEARING BEARING BY O.C.	NA	NA	NA
12. BEARING BEARING BY O.C.	NA	NA	NA
13. BEARING BEARING BY O.C.	NA	NA	NA
14. BEARING BEARING BY O.C.	NA	NA	NA
15. BEARING BEARING BY O.C.	NA	NA	NA
16. BEARING BEARING BY O.C.	NA	NA	NA
17. BEARING BEARING BY O.C.	NA	NA	NA
18. BEARING BEARING BY O.C.	NA	NA	NA
19. BEARING BEARING BY O.C.	NA	NA	NA
20. BEARING BEARING BY O.C.	NA	NA	NA
21. BEARING BEARING BY O.C.	NA	NA	NA
22. BEARING BEARING BY O.C.	NA	NA	NA
23. BEARING BEARING BY O.C.	NA	NA	NA
24. BEARING BEARING BY O.C.	NA	NA	NA
25. BEARING BEARING BY O.C.	NA	NA	NA

AWAY FROM DC 8-13 8/8-14

PRELIMINARY CHECKLIST:

- 1. ALL STUDS INSTALLED
- 2. WELDS; Inaccessible and/or Underlaid
- 3. GAPS; U-Bolts, Tee Shoes and Lugs
- 4. CRACKED PLATES; Cracks repaired or Holes in Plate
- 5. SEAMS; Tack Welds
- 6. WELDS NOT FULLY INSTALLED
- 7. ADD STUDS
- 8. MATERIAL SIZE
- 9. OVERLAPPED EDGES OF PLATE; WELDING
- 10. WELDED BASE PLATE CORNER

HIGH
 SUPPORT
 TO
 RE
 REPAIR
 10-13
 PRE
 INSPECT
 ONLY
 PUP
 7-30-83

PRELIMINARY REPORT:

OK TO WESTERN PIER KEY S. C-51 SUBMITTED PUP 7-30-83
 PGE PREINSPECTION FINAL PUG REVIEW COMPLETE 28-7-30-83
 Field to relocate east Base # 1/2" upward & 1/4" westward and relocate
 West Base # 1/2" upward, due to rebar interference & to keep min.
 distance from holes drilled from Rev. 4 - HW 8/6/83
 Increase Base # thickness to 1" - HW 8/6/83
 Relocate West Base #, 1/4" westward, also - HW 8/7/83
 While setting (4) bolts with bolts 7/8" x 7/8" on west pt with 3 to
 5 turn of the nut the threads were damaged on 3 of the 4 bolts.
 bolts also (3) of which would spin in the holes. Rejected
 (3) of the 4 bolts with bolts on west pt. 1/2" ESD-223 a distance of 1/8"
 due to thread damage.

FINAL REPORT:

Due to Bad anchor on West Plate. Cut anchors flush to concrete &
 relocate plate & anchors 1/4" eastward. - HW 8/8/83

NOTE: Elevate

FOR INFORMATION ONLY

DCL 1604-009 WRITTEN FOR WORKING DANGER AFTER
 QC FINAL WORKMANSHIP INSPECTION 8/24/83

168-1483


PIPE SUPPORT INSTALLATION WORKLIST

ORDER NO.: 235-165R SYS: 18
 ELEV: 85' AREA: B DWG. NO. 049235 SHT. 170 Line #: 1-K-5038-4
 DCN NO. _____ REV. 1
 PPP ENGINEER: A. Wendt DATE: 7/17/82
 PG&E ENGINEER: John Bennett DATE: 7-18-83

THE FOLLOWING WORK IS REQUIRED TO COMPLETE THIS PIPE SUPPORT:
Install as per design Rev. 1

WORK WITH SUPPORT # 235-11R.
PG&E PREINSPECT FINAL PKG REV. COMP. 8/3. 7-18-83

FOREMAN: TAKE REFERENCE DIMENSION FROM 90° ELBOW
SUPPORTS 235-165R & 235-36R NEEDED TO BE
RELOCATED ALONG PIPE. WORK HSR # 235-165R,
235-36R & 235-11R TOGETHER.

FOR INFORMATION ONLY

REQ'D	TYPE	DATE INIT.	DATE RET.	REMARKS
YES <input type="radio"/> NO <input checked="" type="radio"/>	C-51			HEAT TRACE: N/A WELD ATTCHMTS: N/A
<input checked="" type="checkbox"/>	INS.RMV.			
<input checked="" type="checkbox"/>	IDI			
<input checked="" type="checkbox"/>	G 108			
<input checked="" type="checkbox"/>	PSDTC	#	#	
<input checked="" type="checkbox"/>	MATL.AVAL			LINE CLEARANCE REQ'D <u>NO</u>

AREA <u>1-B</u>	LINE <u>1-K-5038-4</u>	HANGER SYMBOL X,Z RESTRAINT TOGETHER WITH 235/36R	
EL <u>85°0'</u>	<u>ISO No 18-220</u>	LOC ON DWG <u>500/20</u>	

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
1	7/1/83	REDESIGNED SUPPORT TO REMOVE FROM TURBINE PEDESTAL, PER EDS REV A, 6-13-83	LC	GCM	COP	JEB	JEB	JEB
		ADD RELOCATION TOL. PER (EDS REV. B, 7-1-83)	LC	NPM	JGM	JBT	JBT	JBT
		ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION, DEN: DL-1-E-P-5060 "SUPPORT ADDITION"					ASM	DRC
		CORRECTED LOCATION & RELOC. TOL. TO LOCATE HGR. WITHIN ALLOW. TOLER. FROM ANA-12-102, REV. 1 LOCATION.	LC	LC	PI	N/A	ASM	DRC

~~AS.WR.~~

~~REASON WORK REV.~~

~~ENGR. RAO~~

N/A 7/1/83

FOR INFORMATION ONLY

NOTES: WORK THIS SUPPORT WITH HANGER NO. 235/36R REV. 5

NO PIPING PROCESS SHEETS REQUIRED

APPROVED FOR CONSTRUCTION

7/1/83 RAO

DATE ENGR

CONTROLLED COPY

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 2 SHEETS)

170	170X																			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	
PROJECT: <u>DIABLO CANYON</u> UNIT: <u>ONE</u>											DSGN <u>LC</u>		DRAWING NO							
											DWN <u>GCM</u>		<u>049235</u>							
											CHKD <u>JEB</u>									
											SHT <u>170X</u> OF		P G & E CO.		ISSUE		REV			

LINE 1-B
EL 85'-0"

LINE 1-K-5038-4
ISO. N# 18-220

HANGER SYMBOL
X,Z RESTRAINT
TOGETHER WITH 235/36R
LOC ON DWG 500122

235
165R



DESIGN CLASS J
CODE CLASS G

CALL NORTH

APPROVED FOR
CONSTRUCTION
7/10/83 RAO
BATE BNG2
1-1-83

FIELD SUPPORT RELOCATION
TOLERANCE 12" UP, 0" DOWN

EXIST. T.S. @ CEM 8-5-83
MR# 235/11 R
PER ESD 223 SEC. 6.6.2.2A



FOR INFORMATION ONLY
SECTION LOOKING NORTH
18
FP

NO OF ASSEMBLIES REQUIRED

NO	REQD	MATERIALS PER ASSEMBLY
1	1	SRF TYPE PC SWAY STRUT SIZE N#6 C-C = 15 3 7/8"
		SPC-06-040

CONTROLLED COPY

DESIGN <u>1-1-83</u>	DRAWING NO	
	049235	
DWN <u>BCM</u>		
CHKD <u>CBP</u>		
PROJECT: <u>DIBBIO CANYON</u> UNIT: <u>ONE</u>	BMT <u>1700P</u> BMT8	PG & E CO
	ISSUE	REV

HANGER PRE-INSPECTION CHECK LIST

ITEMS TO BE CHECKED	REFERENCES ESD 223 AND OTHERS	PREINSPECT CHECKLIST
1. Can Hanger Be Installed At The Proper Location	6.2	HW
2. Is The Adjacent Anchor Spacing Acceptable	6.4.1	N/A
3. Can All Items Be Installed And All Welds Made		HW
4. Are All Welding Symbols Accurate And Complete	6.8	HW
5. Is Old Work As-Built, Acceptable, Or To Be Reworked	PG&E Memo 4-11-83	N/A
6. Initiate DR No. 4678/4730 & Dispositioned (As Appropriate)		N/A
7. Is Pre-Heat Or Structural Steel Rod. & Noted On Process Shd	6.8.2.2	N/A
8. Are All O.C. Hold Points Noted On The Process Sheet	ESD 264	HW
9. Have All The Necessary Forms Been Originated (Pipe Atch. IDI, Insl. C-51)		N/A
10. Have All The Interferences Been Resolved		N/A
11. Pre-Inspect Package Complete (Reqd. Checklists Attached)		HW

PRE INSPECTED BY: H. Wendt DATE: 7/17/83

HANGER FINAL INSPECTION CHECKLIST

ITEMS TO BE CHECKED	REFERENCES ESD 223 AND OTHERS	PREINSPECT CHECKLIST
1. Hanger Location Within ESD 223 Tolerances	6.2	CEM ✓
2. Adjacent Anchor Spacing Acceptable	6.4.1	JA
3. Threaded Connections Secure/Engagement Adequate		CEM JL
4. All Items In B.O.M. Installed And Are Correct Type	6.6	CEM
5. Configuration As Per Design Dwg.		CEM
6. All Welds Complete And Acceptable (Size, Configuration)	6.8	CEM JL
7. Configuration Free From ARC Strikes, Weld Splatter, Etc.	6.8.2.4	CEM JL
8. Pipe And/OR Guide Clearances Acceptable	6.7	CEM
9. Base Plates, Fish Plates, & Stiffeners Installed Per ESD 223	6.3.7 & 6.3	N/A
10. Hanger Properly Identified. No. Written On Support		CEM
11. Attachments Under Supports Identified		CEM
12. Specials Rods, Shoes, etc. Identified	6.5.2.4	N/A
13. Springs Correctly Installed and Oil Loss Per Dwg	6.4.5	JA
14. Sway Struts Correct Size Installed (Ref. Attached Checklist)		CEM
15. P To P Within Tolerance	6.6.2.2	CEM
16. Shock Supports Mechanical Shock I.D. Plates, etc.		N/A
17. Hot & Cold Setting Within Tolerance	6.10.2	
18. P To P Within Tolerance	6.6.2.2	
19. Alignment Acceptable (Clamp & Rear Brkt.)	Atch. A & B	✓
20. All Hardware Compatible		
21. Package Reviewed For Completeness (Design Change Appr. Etc)		CEM

FOR INFORMATION ONLY

COMMENTS: Final Complete.
Reinforced strut installation 8/24/83 JL

RECORD FITTER & WELDER BADGE NO. 5/158 5/146
INSPECTED BY: [Signature] DATE 8-5-83

1. LOCATION OF SUPPORT MEMBERS WITH DRAWING.				5/146	5/158	N/A	8-5-83
2. DRAWING DRAWING NOTED AND COMPONENTS COMPLY WITH MATERIAL LIST				5/146	5/158	N/A	
3. ANCHORS INSTALLED AND WITNESSED BY O.C.						N/A	X N/A
a. Holes drilled to tolerance and Check adjacent anchors						N/A	X N/A
b. Shield/Plug Driven to Tolerance						N/A	X N/A
c. Type Stud Installed	SIZE	QTY	RS			N/A	X N/A
d. Anchors Torqued	SIZE	VALUE				N/A	X N/A
e. Drilled holes dry packed						N/A	X N/A
4. BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATES						N/A	X N/A
5. TIE-UPS: A. Pipe attachments installation:							
(1) Beat No:				5/146	5/158	N/A	N/A
(2) P.O. No:				5/146	5/158	N/A	N/A
B. Support Members:							
(1) Groove & Full Pen Welds						N/A	X N/A
c. Purge Established where required						N/A	X N/A
6. WELD PREP DONE CLEAN OF PAINT, OIL				5/146			
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) T.V.1							X N/A
8. WELDING OF HANGER SUPPORT MEMBERS ONLY:							
SPECIAL WELDING INSTRUCTIONS:				CS/CS	(1/8)	5/158	
						88/89	
						25/25	
						25/25	
9. VERIFY "STOUT @ 1/8" CONCENTRIC				5/146	5/158		X 8-5-83

FOR INFORMATION ONLY

10. FINAL WELD				5/146			X 8-5-83
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFORMANCE:							
A. Components and Dimensions Comply w/Spec							X 8-5-83
B. Pipe Clearance in Accordance with Drawings							X 8-5-83
C. Hanger Clamp Bears upon Longitudinal Centerline of Hanger							X 8-5-83
D. Hanger is Level and Plumb							X 8-5-83
E. All Bolts/Nuts Installed and Tight							X 8-5-83
F. Wall & Ceiling Plates Shimmed where Necessary							X 8-5-83
G. Gross Request Submitted							X 8-5-83
H. Log Clearance within Tolerance							X 8-5-83
A. Installed per Separate Process Sheet							X 8-5-83
B. Trunnell Fig. 1 & Size							X 8-5-83
C. PSA Size							X 8-5-83
D. TYPE: [Signature]							X 8-5-83
12. SUPPORT ACCEPTED BY O.C. (Complete Installation Review) O.C. SIGNATURE							

NPS Stout
 168-5-83

PREINSPECTION CHECKLIST

NO. 100

	D.O.	REMARKS
1. ALL MEMBERS INSTALLED		
2. WELDS; Inaccessible and/or Undersized		
3. GAPS; U-Bolts, Tee Shoes and Lugs		
4. GROUDED PLATES; Grout damaged or Holes in Plate		
5. SETMS; Tack Welds		
6. NUTS NOT FULLY ENGAGED		
7. ARC STRIKES		
8. MATERIAL SIZE		
9. OVERSIZED HOLES IN PLATE; Washers		
10. WARPED BASE PLATES/MEMBERS		

N/A
 Done 7/18/83
 New Hanger
 11/17/82

PREINSPECTION REMARKS:

OK to install as per Rev. 1 after Har. 235-11R Rev. 9 is installed. -HW 7/17/83
 FILE PREINSPECT FINAL PRG REVIEW COMPLETE 7-18-83

FINAL INFORMATION

FINAL INSPECTION COMPLETE:

INSPECTOR CGY DATE 8-5-83

FINAL COMPLETE: CGY 8-5-83

Reinspected strut installation 8/24/83 JL

DCN 1604-009 WRITTEN FOR WORKING HANGER AFTER
 QC FINAL WORKMANSHIP INSPECTION TJD 8/24/83

P.G.
 R.C.
 8-24-83

NPS STRUT INSPECTION CHECK LIST

INSPECTOR Kurt G. ... DATE 8-5-83 RANGE 235-165 R

- 1. A) Strut size: (08, 14, 20, etc.) 06
- B) Clamp size: (enter pipe dia.) 4"
- C) Coupling type: solid/socket weld solid

CHECK MARK INDICATES ACCEPTANCE

- 2. Clamp bolts installed and tight ✓
- 3. Clamp spacer installed and tight ✓
- 4. Load pin holes aligned in both clamp halves ✓
- 5. End eye threads visible through sight holes N/A
- 6. Jam nut tight N/A
- 7. Strut axis within ± 60 of optimum or within special requirements noted on drawing/nanos ✓
- 8. $1/16"$ pull back in socket weld verified on process sheet * N/A
- 9. Solid coupling installed concentrically within $1/8"$ * ✓
- 10. Spherical bearings free of paint and not pushed out ✓
- 11. Cotter pins fully spread ✓
- 12. Spherical bearing washes/spacers installed where required, reducing total side clearance to less than one washer thickness and greater than 0". ✓
- 13. Clamp ears parallel $\pm 1/8"$ at load pin side of clamp ✓


14. Comments and/or explanations NPS Strut SRF Type PC 11-5-83

FOR INFORMATION ONLY

* Items 8 and 9 apply to field-fabricated struts, per NPS 11-9 procedure

1-A
 1-A
 7/11/83
 119.0"

LINE 1-K-4405-24IP
 DIESEL ENG. 1-3 EXCH RISER

HANGER SYMBOL
 Z-RESTRAINT 
 LOC ON DWG _____

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
1	1-5-82	NEW PIPE SUPPORT AS PER ANALYSIS NO. 14-103, ISSUED UNDER DCN # DCI-E-P-5060. ADDITION OF SUPPORT	HS	ST	ANP	4	4	JWC
2	3-8-83	DELETED CLAMP FROM ITEM 1 & ADDED ITEM 4.	JWC	ST	ANP	4	4	JWC
3	6-28-83	DELETED ITEMS 2, 3; ADDED ITEMS 5 THRU 9 & DWG. SHT'S 60A, 60B, 60C; REVISED SUPPORT ELEVATION.	DL	VHT	ZW	4	4	NIT

APPROVED FOR CONSTRUCTION
 7/10/83 RAO
 ENGR

21
 DFOS

A.S.W.R.
 REASON: WORK TO REV 1, 2 & 3
 ENGR: RAO

7-11-83
 JDF4001 J08#467027

NOTES: DRI 20

INFO ONLY

7-11-83

CONTROLLED COPY

276

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL, 5 SHEETS)

60	60A	60B	60C	60X															
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20

RM INDEXED REV. 2

DSGN HS DWN ST CHKD ANP


DRAWING NO. 049294

PROJECT: DIABLO CANYON UNIT: ONE SHEETS: 60X OF 68 P G & E CO



ISSUE 3 REV. _____

AREA 1-A
 1.57 EL 85'-0"
 2/10/83 719'-0"

LINE 1-K-0405-247P
 DIESEL ENG. 1-3 EXCH. RISER

HANGER SYMBOL 
 Z-RESTRAINT
 LOC ON DWG

APPROVED FOR CONSTRUCTION
 2/10/83
 DATE
 ENGR



NO. OF ASSEMBLIES REQUIRED - (1)

NO	REQ'D	MATERIALS PER ASSEMBLY	PLATE ON BACK OF SLAB TC-1-9592 DWN 8-10-83 12 1 R 1' x 2'-0" x 2'-0"
1	1	SRS TYPE PC NPS SWAY STRUT SIZE 20 C-C = 2'-10 1/2" WITH SRS 20 240 PIPE CLAMP 10/16/ASST.B. TC-9121	
2	1	W 10 x 49 x 7'-1" LG. DELETED	JL 8/10/83
3	2	C.S. BAR 1/2" x 3 1/4" x 8 7/8" DELETED	
4	1	NPS SPECIAL ALLOY PIPE CLAMP, SPA-20-240 FOR USE WITH SRS SIZE 20 SWAY STRUT, CLAMP MAT'L. ASME SA-387 GR. B7, NUT MAT'L. ASME 194 GR. 24 T.O. 22", PIPE SIZE = 24". NOTE: DESIGN LOADS TO BE IDENTICAL TO OR GREATER THAN CDRS NO. SPC REV. 1, DESIGN TEMP. -910°F	
5	1	W 10 x 49 x 7'-1" LG. 6'-6" JET 8/5/83	
6	2	PLATE 3/4" x 1'-2" x 1'-9" LG. 2' x 2' CONTROLLED COPY JET 8/8/83	
7	2	PLATE 1/4" x 2'-0" x 2'-0" LG. (CUT TO FIT) (8A) 1 1/4 x 28 1/4 x 24 1/4	
8	3	PLATE 1/4" x 2'-0" x 2'-0" LG. (8B, 8C) 2x TC-9121	
9	1	1/4" x 1/4" x 1/4" MULT. KWIK BOLTS WITH 9" MIN. PLATE PER B-2-83	

SEE TC-1-9430 & TC-1-9592
 & TC-1-9121

DRGN	BL	DRAWING NO	
DWN	VHT	049294	
CHKD	JW		
SHT	OF	SHTS	PG & E CO

PROJECT: DIABLO UNIT: ONE

SEA 1-A

LINE 1-K-4405-24TP EA

HANGER SYMBOL


2
47R

STARTING BELOW
EL 119'-0"
7/11/83

DIGSEL ENG 1-3 EXCH. RISER

Z-RESTRAINT

LOC ON DWG



APPROVED FOR
CONSTRUCTION
7/10/83
DATE
RAG
DATE
RAG

7-11-83

1/8" VENT HOLE


FL. EL. 119'-0"

5'-7 1/2" TEL-9/12/81
JET 8/8/83

SECTION B-B

DFOS

1/8" VENT HOLE



TC-1-11557
FOR LATEST
INFORMATION
SEE
TEL-1-8944
SEE

FL. EL. 119'-0"

SECTION C-C

CONTROLLED COPY

7'-3" TEL-9/12/81
JET 8/8/83

F.E. DOCUMENTS
1/16" GAP BETWEEN
MIN #7 + MIN #8'S.
8/20/83
WFID JOBS 3/8 PIUET

PROJECT: DIABLO UNIT: ONE

DSGN	EL	DRAWING NO	
DWN	VHT	049294	
CHKD	TW		
SHT	OF	SHTS	PG & E CO
			ISSUE

EA 1-A

LINE 1-K-4405-247P [E]

HANGER SYMBOL




Z-RESTRAINT

LOC ON DWG

DESIGNED BY CARON
CHECKED BY [Signature]
DATE 7/10/83

DIESEL ENG. 1-3 EXCH. RISER


SEE
T.C. #1-8949
CEM
7/11/83




(8) 1 5/16" HOLES (TYP.)

10 1/4" 10 1/4" 13 1/4" (TYP.)

SEE TCI-9121 N.D.D. 21
JET 8/8/83 DFOS



SECTION E-E



SECTION F-F

APPROVED FOR
CONSTRUCTION
2/10/83 [Signature]
DATE [Signature] BGR

CONTROLLED COPY

DESIGN	ISL	DRAWING NO	
DWN	VHT	049294	
CHEK	EW		
SHEET	60 E	PG & E CO	ISSUE

OBJECT: DIABLO CANYON UNIT: ONE

GROUTING INSTRUCTIONS
FOR FLOOR MOUNTED BASEPLATES

1. BASEPLATES (ITEMS # 8B.8C) TO BE GROUTED USING CEILCOTE 658N HIGH TEMPERATURE EPOXY GROUT.
2. EXCEPT FOR THE ADDITIONAL NOTES BELOW, GROUT SHALL BE APPLIED ACCORDING TO PROCEDURES SPECIFIED BY THE MANUFACTURER.
- ~~3. BEFORE GROUTING, CONCRETE FASTENER NUTS OR BOLTS SHALL BE REMOVED. GROUT SHALL THEN BE POURED INTO THE HOLE UNTIL FULL AND FREE OF VOIDS OR LARGE BUBBLES. NUTS OR BOLTS SHALL THEN BE REPLACED AND RETORQUED ACCORDING TO EXISTING STANDARD PROCEDURES.~~
4. NO SPECIAL PREPARATION NEED BE DONE ON THE SURFACE OF THE BASEPLATE OR CONCRETE.

21
DFOS

#1-8949
T.C. CEM
7/11/87

7/10/83
DATE
DWS

7-11-83
CONTROLLED COPY

DESIGN	BL	DRAWING NO	
DWN	VHT	049294	
CHECK	FUJ		
PROJECT	DIABLO CANYON	UNIT	ONE
DWG. OF	6DC	SHTS	P G & E CO
		ISSUE	3
		REV	

ENCLOSURE


85-D-1

MATERIALS

EM	QTY.	DESCRIPTION
1	1	L 2" x 2" x 1/4" x 0'-5" LG (CUT TO FIT)
2	1	PUS SIZE 010 U-BOLT

PACIFIC GAS & ELECTRIC CO.
APPROVED FOR CONSTRUCTION
 ENGINEERING DEPARTMENT
 DATE 8/8/83 8-12-83
 BY GRJ AS

FOR INFORMATION ONLY



NEW HGR. PER SPP-1729 (8-3-83),
 S/A 14-303H, D.P. 85. MOD FOR SMALL
 BORE REVERIFICATION PROGRAM,
 L. MANGOBA.

KEB 8-4-83

LOCATION PLAN

UNLESS OTHERWISE SPECIFIED


~~U-bolts field fit, set each side Horiz.~~
~~pipe clearances are 0" bottom~~
~~and 1/16" two sides and top~~

REF. DWG. 500547 SYS 14
 CLASS C/E UNIT 1 AREA D
 ELEV 85' DESIGN G, SHAH
 ISO 14-250 DATE 9-21-83


PIPE SUPPORT

ID 9001 RM 85-D-1
 DWG. No. 547-17 REV. No. 0
 Z-RSTR. SHT 1 OF 2

PIPE CLR. $\frac{1}{8}$ " MIN. TOP & BOTTOM,
 $\frac{1}{16}$ " WEST SIDE, $\frac{1}{16}$ " EAST SIDE.



ELEV. VIEW (LKG. EAST)



ELEV. VIEW (LKG. NORTH)

EXIST W8x28
 REF. HGR. 16
11K

FOR INFORMATION ONLY

PACIFIC GAS & ELECTRIC CO.
 APPROVED FOR
 CONSTRUCTION
 ENGINEERING DEPARTMENT
 DATE 8/8/83 8-12-83
 BY GRS JS

UNLESS OTHERWISE SPECIFIED

~~U-bolts field fit, not each side Horiz.~~
~~pipe clearances are 0" bottom~~
~~and 1/4" sides and top~~

REF. DWG. 500547 SYS 14
 CLASS C/E UNIT 1 AREA D
 ELEV 85' DESIGN G.R. SHAH
 ISO 14-250 DATE 7-21-83

PIPE SUPPORT

DWG. No. 547-17 REV. No. 0
 Z-RSTR. SHT 2 OF 2

4-62
REV. 1/82

WEEKLY WELDERS QUALIFICATION STATUS

WEEK OF: 8-29-83 PAIR: 26 OF 31

9-4-83

WELDER	WAT#	STEMO	STATUS
J. COLLINGSWORTH	3153	TVI	B
A. HAMP	3018	TVI	B
D. SALAYER	3156	TVI	B
U. BOWEN	3160	TVI	B
B. DODD	3104	TVI	B
G. MURPHY	2958	TVI	B
M. COVIELLO	3155	TVI	B
N. BALTON	3030	PS2	B
S. STEVENSON	3342	FOR	B
T. WALL	3118	DX2	B
E. RYAN	3169	DX2	B
J. PETERS	3170	DX2	B
A. CZARNICKI	3162	YAI	B
M. BOOKIN	3181	VBI	B
L. IZATT	3101	VPI	B
R. ANDERSON	1897	XB	B
D. DOUGHTY	3098	FD3	B
D. AGEE	3245	VFI	B
D. MARYADORE	3322	VBI	B

STATUS:
 A - Recommended for 3-ray welds
 B - Recommended for 2-ray welds
 C - Recommended for 1-ray welds only

WELD PROCESSES:
 1/5 - CR Insert/710 Boot (E208-2), Weld Out Stitch (7018).
 1/4 - CR Sealing Ring, Weld Out Stitch (7018).
 201 - CR Insert/710 Boot and Weld Out (E208-2).
 202 - CR Open Butt/710 Boot and Weld Out (E208-2).
 203 - CR Open Butt/710 Boot and Weld Out (E208-2), no purge.
 88/89 - CR Open Butt/710 Boot (E208-2), Weld Out Stitch (7018).
 15/16 - CR Fillets, Sockets, and Butts, Insert/710 Boot (E208-2), Weld Out Stitch (E-308).
 79/80 - CR Fillets, Sockets, and Butts, Insert/710 Boot (E208-2), Weld Out Stitch (E-308).
 129 - CR Open Butt all 710 (E208-2).
 134 - CR Open Butt, 710 Boot, Weld Out (E-309) Stitch Boot, Weld Out (E-309) & Weld Out (E-309).
 145 - CR/CR Fillets, Sockets, Coupling and Bolt, Insert/710 Boot (E208-2), Weld Out Stitch (E-309).
 150 - CR/CR Fillets, Sockets, Coupling and Bolt, Insert/710 Boot and Weld Out (E-309).
 160 - CR/CR/CR Butts, Fillets, Sockets (E-309) & Weld Out (E-309).
 168 - CR/CR Butts, Fillets, Sockets (E-309) & Weld Out (E-309).

1. Number referenced is the Max. qualified wall thickness on groove welds.
 2. Dia. qualification is Large Dia. (LD) unless otherwise noted. See Legend.

CARBON STEEL				STAINLESS				O.S. to B.S.			EXP.									
7/8	7/8 BE PLATE	88/89 AD	200	201	202	203	203 PLATE ONLY WITH BACKING	13A O/D/O	7/8 PLATE ONLY	15/16	79/80	129	129 ⊕	134 (TIG)	134 (TIG & SMAW)	134 (SMAW) WITH BACKGRIND	149	150	B1, B3, B4	
4/5																				409 (CNT)

AREA 2G
EL 107'-6"

LINE 2-56-1977-4 B
SAFETY INJ PP I-2 DISCHARGE SYSTEM 09


HANGER SYMBOL
AXIAL RESTRAINT 72
34SL
LOC ON DWG 500907

DESIGN CLASS I
CODE CLASS B

CALLED NORTH

Item ⑦ see
RF# ~~242-2476~~
OR 6/10/83
EL. 107'-2 1/4"

⊗ = INACCESSIBLE WELDS



ELEVATION A-A

DC-2-E-F-6810
SK-72/34SL REV. C

03
SIS

NO OF ASSEMBLIES REQUIRED 1

NO	REQD	MATERIALS PER ASSEMBLY
1	1	PSA-1, NF, STROKE C.S. = 2 H.S. = 1 15/16" STROKE = 4"
2	1	REAR BRACKET
3	1	SS. PL 1/2" x 3 1/2" x 4 1/2"
4	1	W 4 x 13, 1'-9 1/8" LG.
5	1	STIFFENER R 3/8" THK, (FIELD TO FIT)
6	2	STIFFENER R 3/8" x 4" x 4" CUT AS SHOWN
7	1	R 1" x 4" x 6" LG x 0-4" LG

APPROVED FOR CONSTRUCTION
DATE 6-9-83 ENGR
OF 2-2976 M7/6-9-83

M.W.K. AS BUILT 3-31-78
BECHTEL WALKDOWN 7.10.82

DSGN DWN'D <u>6/9/83</u>	DRAWING NO <u>051396</u>
CHKD <u>JEB</u>	P G & E CO
SHT <u>53</u> OF <u>53</u> SHTS	ISSUE <u>2</u> REV



PROJECT: DIABLO CANYON UNIT: TWO

AREA 2G
EL. 107'-6"

LINE 2-56-1977-4 B
NOS.

HANGER SYMBOL 72
345L
LOC. ON DWG. 500907

LINE NO.	2-56-1977-4
RESTR. X, Y, Z	AXIAL 1
ANAL. NO. & DATE	6-6 6-19-75
DATA POINT	115
FORCE FAY:AL	164 #
ANAL. NO. & DATE	92G 8-8-75
DATA POINT	545-550
NORM. MVMT. ΔX, ΔY, ΔZ	-0.49", 0.01", 0.13"
INCID. MVMT. ΔX, ΔY, ΔZ	-0.63", 0.0", 0.10"



NO. OF ASSEMBLIES REQUIRED 1

AS-BUILT DRAWING ACCEPTED
COPY TO S.F. YES NO
BY JT | APR 15 1978

NO.	REQD	SER NO. 944	MATERIALS
1	1		PSA-1/4, 1/4" EXT. STROKE, (C.S. = 2") (H.S. = 2 1/4")
2	1		REAR BRACKET FOR PSA-1/4
3	1		S.S. R: 3 1/2" x 1/2" x 3 1/2"
4	1		(WF 4x13, 1'-9 1/8" LG.)
5	1		STIFFENER R 3/8" FIELD FIT
6	2		STIFFENERS R 3/8" 4"x4" : 09
7	1		EXTENSION TUBE 3/4" Ø SCH 40 LENGTH BY FIELD

1=APPD. FOR CONST.

AREA <u>2G</u>	LINE <u>2-S6-1977-4 [B]</u>	HANGER SYMBOL	<u>72</u>
EL <u>107'-6"</u>	SAFETY INJ PP 1-2 DISCHARGE SYSTEM 09	AXIAL RESTRAINT	<u>34SL</u>
		LOC ON DWG <u>500907</u>	


DESIGN CLASS I
CODE CLASS E

CALLED NORTH par QP # 2-2186

⊗ = INACCESSIBLE WELDS

Item 7 see
QP # ~~2-2476~~
OR 6/10/83

EL. 107'-2 1/4"



ELEVATION A-A

DC-2-E-P-6810

SK-72/34SL REV. C

09
SIS

NO OF ASSEMBLIES REQUIRED 1

NO	REQD	DESCRIPTION
		<i>W/NPS FWD. BKT 6/8/86 A OR 21 QP # 2-2186 4 NPS R. BKT MATERIALS PER ASSEMBLY</i>
1	1	PSA-1, NF, STROKE CS=2 H.S.=1 5/16" STROKE=4"
2	1	REAR BRACKET
4	1	W 4x13, 1'-9 1/8" LG.
5	1	STIFFENER R 3/8 THK. (FIELD TO FIT)
6	2	STIFFENER R 3/8 x 4" x 4" CUT AS SHOWN
7	1	R 1" x 4" x 6" LG x 0-4" LG

APPROVED FOR CONSTRUCTION

DATE 6-1-83 ENGR B.L.

DATE 6-9-83 ENGR M.H. 6-9-83

M.W.K. AS BUILT 3-31-78 (1)
BECHTEL WALKDOWN 7-10-82

DSGN
DWNS *6/17/82*
CHKD JEB

DRAWING NO
051396

PROJECT: DIABLO CANYON

UNIT: TWO

SHT 53 OF SHTS

PG & E CO

ISSUE REV

REA 2G

LINE 2-56-1977-4 B

HANGER SYMBOL

72
34SL

EL: 107'-6"

NOS.



LOC. ON DWG. 500907

SEISMIC	LINE NO.	2-56-1977-4
	RESTR. X, Y, Z	AXIAL
	ANAL. NO. & DATE	6-6 6-19-75
THERMAL	DATA POINT	15
	FORCE F _{AXIAL}	164 #
	ANAL. NO. & DATE	92G B-8-75
	DATA POINT	545-550
NORM. MVMT. ΔX, ΔY, ΔZ		-0.49", 0.01", 0.13"
INCID. MVMT. ΔX, ΔY, ΔZ		-0.63", 0.0", 0.14"



DESIGN CLASS I
CODE CLASS B

CALLLED NORTH.



ELEV. LKG. NORTH

AS-BUILT DRAWING
ACCEPTED
COPY TO SF. YES NO
BY JT | APR 15 1978

NO. OF ASSEMBLIES REQUIRED 1

NO.	REQD	SER NO. 944	MATERIALS
1	1	PSA-1/4, 1/4" EXT. STROKE, (C.S. = 2")	(H.S. = 2 1/4")
2	1	REAR BRACKET FOR PSA-1/4	
4	1	WF 4x13, 1'-2 1/8" LG.	
5	1	STIFFNER R 3/8" FIELD FIT	
(6)	2	STIFFNERS R 3/8" 4"x4"	09
(7)	1	EXTENSION TUBE 3/4" Ø SCH. 40	LENGTH BY FIELD

DIPLO CANYON UNIT #2

P O & E CO. DRAWING NO. [REDACTED]
SHEETS 3 OF SHEETS 051396

5-11-82
FORM F-65

FULLMAN POWER PRODUCTS

NO. 384-322R-00384
PREPARED BY DATE 7/5/83
BADGE NUMBER 157
O.C. DATE & INITIAL

✓ DC VERIFICATION POINTS		GENERAL FIELD SUPPORT PROCESS SHEET		7/5/83	157	NA	NA	8-15-83
1. LOCATION OF SUPPORT COMPLES WITH DRAWING.								
2. DRAWING GRANDES NOTED AND COMPONENTS COMPLY WITH MATERIAL LIST								
3. ANCHORS INSTALLED AND WITNESSED BY O.C.				n. holes drilled to tolerance and Check adjacent anchors		NA	*	N/A
B. Shield/Plug Driven to Tolerance				TYPE: Hilti/Phillips		WA	*	N/A
C. Type Stud Installed		SIZE	MIN. EMB.	TYPE: Hilti/Phillips		NA	*	N/A
						NA		
D. Anchors Torqued				SIZE	VALUE	WRENCH SERIAL NUMBER		NA * N/A
						NA		
E. Unused holes dry packed						NA	*	N/A
4. BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATES								
5. FIT-UPS: A. Pipe attachments installation:				(1) Seat No: F	NA		*	N/A
				(2) P.D. No: A	NA		*	N/A
B. Support Members:				ITEMS	SPECIAL INSTRUCTIONS			
(1) Groove & Full Pen Welds				1, 7, 11, 2, 2			WA	* N/A
C. Purge Established where required						NA	*	N/A
6. WELD BEP BEING COVER OF PAINT, OIL								
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET)-P.V.1								
8. WELDING OF HANGER SUPPORT MEMBERS ONLY:								
SPECIAL WELDING INSTRUCTIONS:				IDENTIFICATION		WELD CODE		
<p>PROTECT CIVILIAN STEEL TO SOFF Thickness < 3/4" No Preheat req. H&J 7/27/83</p>				CS/CS		7/8	157	* N/A
				↓		86/89	58	
				SS/SS		129	NA	
				↓		15/16		
				CS/SS				
<p>VERIFY SOLID COUPLING INSTALLED CONCENTRIC W/IN ± 1/8"</p>								
10. FINAL WELD CONDITION-SUPPORT MEMBERS								
A. Weld Surface Clean				2/3 3 157		NA		8-15-83
B. Arc Strikes Removed/Minimized				2/3 3 157		NA		8-15-83
C. Weld Size Complies with drawing				2/3 3 157		NA		8-15-83
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION:								
A. Components and Dimensions Comply w/Dwg. & Mat'l. List				27 8-4-83		NA		8-15-83
B. Pipe Clearance in Accordance with Drawing				27 8-4-83		NA		8-15-83
C. Riser Clamp Bears upon Lug				NA		NA		8-15-83
D. Hanger is Level and Plumb				27 8-4-83		NA		8-15-83
E. All Bolts/Nuts Installed and Tight				NA		NA		8-15-83
F. Wall & Ceiling Plates Shipped where Necessary				NA		NA		8-15-83
G. Groot Request Submitted				NA		NA		8-15-83
H. Lug Clearance within Tolerance				NA		NA		8-15-83
12. NPS Stru				A. Installed per Separate Process Sheet GRF-24		27 8-4-83		8-15-83
				B. Grinnell Fig. # & Size		C. PSA Size		D. TYPE: #

PROTECT CIVILIAN STEEL TO SOFF
Thickness < 3/4" No Preheat req.
H&J 7/27/83

VERIFY SOLID COUPLING INSTALLED CONCENTRIC W/IN ± 1/8"

280

SIDE

PREINSPECTION CHECKLIST

1267

NO. OF MEMBERS

NO. OF DEFECTS

DATE

1. ALL MEMBERS INSTALLED

2. WELDS; Inaccessible and/or Undersized

3. GAPS; U-Bolts, Tee Shoes and Lugs

4. GROUTED PLATES; Grout damaged or Holes in Plate

5. SHIMS; Tack Welds

6. NUTS NOT FULLY ENGAGED

7. ARC STRIKES

8. MATERIAL SIZE

9. OVERSIZED HOLES IN PLATE; Washers

10. WARPED BASE PLATES/MEMBERS

PREINSPECTION REMARKS:

Refer to TC-1-8648 to work with Rev 1 - OK to work HW 7/6/83
PG 9E PREINSPECT FINAL PKG REVIEW COMPLETE 28-7-83
Work to TC-1-951C-5 TC-1-9143 HW 7/17/83

FINAL INSPECTION COMMENTS: INSPECTOR DATE

ACCEPT UP FROM #1 TO #2 ON BOTH SIDES & BOTTOM - TOP WELD CALLED AS
FULL PEN - NEED CLARIFICATION OF WHAT CONSTITUTES FULL PEN ON PLATE
BEVER WELDS - SHOULD THIS NOT BE CALLED A SKEWED T JOINT?
ACCEPT UP ON TOP #1 TO #2 - 7-22-83 - CLOSED PER TC-9672 7-25-83
PIPE CLAMP - IS A 1/4" STRIKE - ATTACHED - THAT IS ATTACHED
TO BEAM UNDER CLAMP - 8-16-83 R.M.

Rejected! - Zero Clearance all around - Not obtained between
SBH 160 Pipe sleeve end Firewater line 2467
CONDITION HAS BEEN CORRECTED 8-20-83 BY 8-18-83

85'-0"

FIRE PROTECTION SYSTEM
18 TURB. BLDG 1 LOOP HDR. CON

HGR No. 384/141R

LOC ON DWG 500120

ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
		DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
6-27-83	ORIGINAL ISSUE NEW DESIGN REQUIRED PER REANALYSIS (BY EDS)	L.D.	COL	RTC	N/A	1557	1557
	ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION.					11/2	DRC
	ADDED DESIGN & CODE CLASS TO DWG.	S.T.	S.T.	LE	11/2	DRC	GPS
	REVISED TO INCORPORATE EDS CHANGES: "REVISED TO REPLACE ITEM #1 AND ADD ITEMS #6, #7, & #8 BY EDS REV. A 5-28-83" DRAFTING CHANGES, CLARIFIED WELDING BETWEEN ITEMS 1 & 2, AND ITEMS 3 & 6 TO EXISTING STEEL. REMOVED LOADING. ADDED PIPING LOCATION DRAWING. CLARIFIED EDS' CHANGES: CHANGED ITEM 5, INCREASED NO OF ITEM 4 TO 2, ADDED ITEM 9. REFER TO CALC. SEQ. # 5-4843 REV. 1 FOR EDS SIGNATURES. FIELD MODIF. REQ'D DCN. DC-1-E-P-5060						
		Djm	Djm	J.L	N/A	DRC	CPS
2 8-15-83	REVISED TO SHOW X, Z, RESTRAINT W/ HGR No. 384/141R IN THE HGR. SYMBOL BLOCK. NO FIELD WORK IS REQ'D (IMPELL REV. A 8/3/83)	Am	Am	PR	N/A	1-501	1-501
	ACCEPTED BY PROJECT ENGINEERING NO FIELD WORK REQUIRED					11/2	73

FOR CONSTRUCTION
INFORMATION ONLY

NOTES:

**NO PIPING PROCESS
SHEETS REQUIRED**

APPROVED FOR
CONSTRUCTION
2/21/83 KAW
DATE ENGR

^{1/30/83} SUPERCEDED BY REV.

CONTROLLED COPY

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 3 SHEETS)

372A	372B	372X																	
2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	
DSGN L. D.										DRAWING NO									
DWN C. DE LUCA										060384									
CHKD RTC										PG & E CO									
PROJECT: DIABLO CANYON					UNIT: ONE					372X OF 5MS					P G & E CO				
										ISSUE 2 REV									

EL 85'-0"

FIRE PROTECTION SYSTEM
1B TURB. BLDG 1 LOOP HDR. CON.

X-RESTRAINT
LOC ON DWG 50012D

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
1	6-27-83	ORIGINAL ISSUE NEW DESIGN REQUIRED PER REANALYSIS (BY EDS)	L.D.	CDL	RL	U/A	MSY	MSY
		ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION.					MSY	DRC
		ADDED DESIGN & CODE CLASS TO DWG.	S.T.	S.T.	KE	MSY	DRC	GPS
		REVISED TO INCORPORATE EDS CHANGES: "REVISED TO REPLACE ITEM #1 AND ADD ITEMS #6, #7, & #8 BY EDS REV A 5-28-83" DRAFTING CHANGES, CLARIFIED WELDING BETWEEN ITEMS 1 & 2, AND ITEMS 3 & 6 TO EXISTING STEEL. REMOVED LOADING. ADDED PIPING LOCATION DRAWING. CLARIFIED EDS CHANGES. CHANGED ITEM 5, INCREASED NO. OF ITEM 4 TO 2, ADDED ITEM 9. REFER TO CALC SEQ# S-4843 BR. 1 FOR EDS SIGNATURES. FIELD MODIF. REQ'D DCN: DC-1-E-P-5060				18 FP		
2	8/23/83	ADDED ITEMS 10, 11, 12, & 13; & SHT. # 372 C PER CIVIL REQUEST. REVISED ITEM 8 & ITS WELD & SIZE. REF. HGR. LOCATION; APPROVED FOR CONSTRUCTION PER DCN-DC- 1-E-P-5060.	VKL	VNT	Helu	ST	HST	Jr
3	09/30/83	REVISED TO UPGRADE DWG. ISSUE REVISION NO. OF VALID MODIFIED SUPPORT DATED 8-23-83 SINCE REV. WAS ISSUED TWICE W/ TWO DIFF. DESCRIPTION OF CHANGES NO FLD WORK REQ'D. PAPER FIX ONLY. DCN NO 8-26-1-E-1-5060	JR	JR	WTS.		Jr	Jr

APPROVED FOR
CONSTRUCTION
DATE 10/4/83
ENGR WNW

CONTROLLED COPY

RM INDEXED REV.

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 5 SHEETS) 783 special ID 400.

372	372A	372B	372C	372X															
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20

DSGN L.D.
DWN C. DE LUCA
CHKD RL
DRAWING NO. 060384

PROJECT: DIABLO CANYON UNIT: ONE 372X OF SHS PG & E CO

ISSUE R
MICROFILM

LOCATION OF SUPPORT COMPLIES WITH DRAWING.

DRAWING CHANGES NOTED AND COMPONENTS COMPLY WITH MATERIAL LIST

3. ANCHORS INSTALLED AND WITNESSED BY Q.C. A. Holes drilled to tolerance and Check adjacent anchors

B. Shield/Plug Driven to Tolerance TYPE: Hilti/Phillips

C. Type Stud Installed SIZE MIN. EMB. TYPE: Hilti/Phillips

D. Anchors Torqued SIZE VALUE WRENCH SERIAL NUMBER

E. Unused holes dry packed

4. BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATES

5. FIT-UPS: A. Pipe attachments installation: (1) Beat No: (2) P.O. No:

B. Support Members: ITEMS SPECIAL INSTRUCTIONS

(1) Groove & Full Pen Welds

C. Purge Established where required

6. WELD PREP ZONES CLEAN OF PAINT, OIL

7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) F.W.#

8. WELDING OF HANGER SUPPORT MEMBERS ONLY:	IDENTIFICATION	WELD CODE
SPECIAL WELDING INSTRUCTIONS:		CS/CS 7/8
		↓ 88/89
		SS/SS 129
		↓ 15/16
		CS/SS

9. OTHER INSTRUCTIONS:

10. FINAL WELD CONDITION-SUPPORT MEMBERS: A. Weld Surface Clean B. Arc Strikes Removed/Minimized C. Weld Size Complies with drawing

11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION: FOREMAN INITIAL/DATE Q.C. DATE & INITIAL

A. Components and Dimensions Comply w/Dwg. & Mat'l. List

B. Pipe Clearance in Accordance with Drawing

C. Riser Clamp Bears upon Lag

D. Hanger is Level and Plumb

E. All Bolts/Nuts Installed and Tight

F. Wall & Ceiling Plates Shimmed where Necessary

G. Grout Request Submitted

H. Lag Clearance within Tolerance

12. SNUBBERS: A. Installed per Separate Process Sheet B. Grinnell Fig. # & Size C. PSA Size D. TYPE: NF NON-NF

13. SUPPORT ACCEPTED BY Q.C. (Complete Installation Review) Q.C. SIGNATURE DATE

ONLY
 NO WORK PERFORMED
 1. NO WORK PERFORMED
 PROCESS SHEET: 4-8-83
 ACCEPTED ON REV. 1. NO WORK PERFORMED
 ACCEPT PER ATTACHED
 WORKMANSHIP ACCEPT PER ATTACHED
 ON REV. 2.

28

DATE 8-20-85

384-3224

- 1. A) Strut size: (08, 14, 20, etc.) _____
- B) Clamp size: (enter pipe dia.) _____
- C) Coupling type: solid/socket weld _____

N/A

CHECK MARKS INDICATES ACCEPTANCE

- 2. Clamp bolts installed and tight _____
- 3. Clamp spacer installed and tight _____
- 4. Load pin holes aligned in both clamp halves _____
- 5. End eye threads visible through sight holes _____
- 6. Jam nut tight _____
- 7. Strut axis within ± 50 of optimum or within special requirements noted on drawing/notes _____
- 8. 1/16" pull back in socket weld verified on process sheet * _____
- 9. Solid coupling installed concentrically within 1/8" * _____
- 10. Spherical bearings free of paint and not pushed out _____
- 11. Cotter pins fully spread _____
- 12. Spherical bearing washes/spacers installed where required, reducing total side clearance to less than one washer thickness and greater than 0". _____
- 13. Clamp ears parallel $\pm 1/8$ " at load pin side of clamp _____
- 14. Comments and/or explanations _____

WORK SIGNED OFF UNDER REV #1. NO ADDITIONAL

FIELD WORK WAS REQUIRED BY REV #2. 8-24-85

* Items 8 and 9 apply to field-fabricated struts, per NPS 11-9 procedure

EL 85'-0"

LINE 1-K-2667-6" 3754 '83/09/30
FIRE PROTECTION SYSTEM X-RESTRAIN
18 TURB. BLDG 1 LOOP HDR. CON. LOC ON DWG

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION		
			DSGN	DWN	CHKD
1	6-27-83	ORIGINAL ISSUE NEW DESIGN REQUIRED PER REANALYSIS (BY EDS)	L.D.	COL	ETC
		ACCEPTED BY PROJECT ENGINEERING FOR CONSTRUCTION.			
		ADDED DESIGN & CODE CLASS TO DWG.	S.T.	S.T.	EE
		REVISED TO INCORPORATE EDS CHANGES: "REVISED TO REPLACE ITEM #1 AND ADD ITEMS #6, #7, & #8 BY EDS REV. A 5-28-83" DRAFTING CHANGES, CLARIFIED WELDING BETWEEN ITEMS 1 & 2, AND ITEMS 3 & 6 TO EXISTING STEEL. REMOVED LOADING. ADDED PIPING LOCATION DRAWING. CLARIFIED EDS CHANGES: CHANGED ITEM 5, INCREASED NO. OF ITEM 4 TO 2, ADDED ITEM 9, REFER TO CALL. SEQ. # S-4843 REV. 1 FOR EDS SIGNATURES. FIELD MODIF. REQ'D DCN. DC-1-E-P-5060		18 FP	J.L.
2	8/23/83	ADDED ITEMS 10, 11, 12, & 13; SHT. # 372 C PER CIVIL REQUEST. REVISED ITEM 8 & ITS WELD SIZE, REF. HGR. LOCATION; APPROVED FOR CONSTRUCTION PER DCN. DC- 1-E-P-5060.	VKL	VHT	4th
3	09-30-83	REVISED TO UPGRADE DWG 1 & 2 ISSUE REVISION NO. OF VALID MODIFIED SUPPORT DATED 8-23-83 SINCE REV. A WAS ISSUED TWICE W/ TWO DIFF. DESCRIPTION OF CHANGES. NO FIELD WORK REQ'D. PAPER FIX ONLY. DCN NO. DC-1-E-P-5060	JR	JR	WTS

FL
BK
TBL
MECH
(4)

RM INDEXED REV.

SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 5 SHEETS) *7-83 Special*

372	372A	372B	372C	372X											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16

PROJECT: DIABLO CANYON	UNIT: ONE	372X OF 5	PG 8
		DSGN L.D.	DRAWING
		DWN C. DE LUCA	060
		CHKD RTL	

PIPE SUPPORT INSTALLATION

1-K-2667-6

System # 18

TAGGER NO.: 384-322R

NO. 85 AREA: C DWG. NO. 060384 SHT. 372 X

CON NO. _____ REV. 3

PEP ENGINEER: _____ DATE: _____

PG/E ENGINEER: Dan Hwang DATE: 10-5-83

THE FOLLOWING WORK IS REQUIRED TO COMPLETE THIS PIPE SUPPORT:

PG/E FIELD TO REWORK PER TC-1-13380
clean up all weld, add filter where it's
REQ'D FOR FINAL Date 10-5-83

REQ'D	TYPE	DATE INIT.	DATE RET.	REMARKS
<input checked="" type="checkbox"/>	C-51			No weld ATT'S REQ'D
<input checked="" type="checkbox"/>	INS.RMV.			
<input checked="" type="checkbox"/>	IDF			
<input checked="" type="checkbox"/>	G-108			
<input checked="" type="checkbox"/>	PSDTC-13380			
<input checked="" type="checkbox"/>	MATL.AVAL			LINE CLEARANCE REQ'D

SCHEDULE UPDATE FORM

HANGER SYMBOL 38A-322P REV. 3 D.C.B. Q.S.B.
 UNIT 1 AREA C SYSTEM 18

SENT BY _____ RECEIVED BY _____
 NAME [Signature] NAME _____
 EXT. _____ DATE _____ EXT. _____ DATE _____

FROM	DRAWING LOCATIONS	TO
1 <input type="checkbox"/>	P.G. & E.	<input type="checkbox"/>
2 <input type="checkbox"/>	P.P.P. OFFICE	<input type="checkbox"/>
3 <input type="checkbox"/>	F.L.D. ENGR.	<input type="checkbox"/>
4 <input checked="" type="checkbox"/>	FOREMAN	<input type="checkbox"/>
5 <input type="checkbox"/>	Q.C. / INSPECTION	<input type="checkbox"/>
6 <input type="checkbox"/>	F.L.D. ENGR. / AS-BUILDING	<input type="checkbox"/>
7 <input type="checkbox"/>	Q.C. / FINAL INSPECTION	<input type="checkbox"/>
8 <input type="checkbox"/>	Q.A. / FINAL CHECKING	<input type="checkbox"/>
9 <input type="checkbox"/>	AS-BUILT TO P.G. & E.	<input type="checkbox"/>

PLACE DWG. ON HOLD _____ CODE _____
 REMOVE HOLD _____
 OTHER _____

REMARKS _____

 OVER

WORKLIST

1-K-2667-6'

System # 18

372 X

10-5-83

SEE THIS PIPE SUPPORT:

PG & E FIELD TO REWORK PER TC-1-13380
& clean up all weld, add filler where it
REQ'D FOR FINAL DATE 10-5-83

REQ'D	TYPE	DATE INIT.	DATE RET.	REMARKS
<input checked="" type="checkbox"/>	C-51			No weld ATT'S REQ'D
<input checked="" type="checkbox"/>	INS.RMV.			
<input checked="" type="checkbox"/>	IDI			
<input checked="" type="checkbox"/>	G 108			
<input checked="" type="checkbox"/>	PSDTC	<u>13380</u>		
<input checked="" type="checkbox"/>	MATL.AVAL			LINE CLEARANCE REQ'D

AREA 1-D

LINE 1-K-2277-20 [C]

HANGER SYMBOL

18
17R

EL 85'-0"



CCW SUPPLY HDR C

AXIAL - RESTRAINT

LOC ON DWG 5000:5

DESIGN CLASS 1
CODE CLASS C

CALLED NORTH



FOR INFORMATION ONLY

NOTE: COVER IS COVER IS NOT SHOWN FOR CLARITY

EXIST FW# X 1353A-D
17EM #6

ELEVATION LOOKING NORTH


NO OF ASSEMBLIES REQUIRED - 1

14
CC

NO	REQD	MATERIALS PER ASSEMBLY
1	2	REAR BRKT, SRS, SIZE 36 - DELETED
2	2	SRS TYPE PC, SWAY STRUT SIZE 36 9/16 = 12'-5" WITH SFC-36-140 PIPE CLAMP FOR 1.7" Ø PIPE.
3	2	18" Ø STANCHION PIPE SCH. / STD. 2'-4" LG. (CUT TO FIT) DL 7.2
4	2	1/2" x 15" x 1.7" COVER PL. DELETED
5	12	R. 1" x 7/16" x 1'-1" LG. STIFFENER PL. (CUT TO FIT)
6	2	R. 9/16" x 21" x 2'-8 3/4" LG. (BEND TO FIT PIPE O.D.)
7	2	14" Ø STANCHION PIPE SCH. / STD. 2'-2" LG. (CUT TO FIT)
8	2	R. 1/2" x 15" x 1.7" LG. COVER PL.
9	1	W 14 x 91 x 5'-6" LG. (FLD. CUT TO FIT)
10	6	STIFF. PL. 1/2" x (BY FIELD)

PROJECT: <u>DIABLO CANYON</u>	UNIT: <u>ONE</u>	BHT <u>36</u> OF <u>38</u> SHTS	DESIGNER: <u>G. L.</u>	DRAWING NO: <u>SK-18-17R</u>	281
			DWN: <u>S. G.</u>		
			CHKD: <u>6/2/11</u>		
				PG & E CO	2
				ISSUE	RE

R. 1/8" MIN. TOP & BOTTOM,
WEST SIDE, 1/16" EAST SIDE.



ELEV. VIEW (LKG NORTH)

NOTE: HOLES IN LITER #1 FOR
U-BOLTS TO BE 1/4"

SM 8/23/83

EXIST W8x25
REF. HGR



ELEV. VIEW (LKG EAST)

PACIFIC GAS & ELECTRIC CO.
APPROVED FOR
CONSTRUCTION
ENGINEERING DEPARTMENT
DATE 8/18/83 842-83
BY G26 AS

1480
OK

APPROVED FOR
CONSTRUCTION
8/17/83 LWXW
DATE ENGR
72128-18-83

CONTROLLED COPY

UNLESS OTHERWISE SPECIFIED U-bolts field fit, not each side Horiz. pipe clearances are 6" bottom and 4 1/2" two sides and top	REF. DWG. <u>500547</u> SYS <u>14</u>	PIPE SUPPORT <u>282</u> DWG. No. <u>547-17</u> REV. No. <u>10</u> 2-RSTR SHT <u>2</u> OF <u>2</u>
	CLASS <u>C/E</u> UNIT <u>1</u> AREA <u>D</u>	
	ELEV <u>85'</u> DESIGN <u>G.R. SHAH</u>	
	ISO <u>14-250</u> DATE <u>7-21-83</u>	

A. 10/17/83
 B. 10/17/83
 C. 10/17/83
 D. 10/17/83

FULLMAN POWER PRODUCTS

SUPPORT NO. 547-17
 DRAWING NO. 0
 PREPARED BY
 DATE 10/17/83
 FITTER/WELDER
 BADGE NUMBER 2271
 Q.C. DATE & INITIAL 10/17/83

GENERAL FIELD SUPPORT PROCESS SHEET

SUPPORT COMPLES WITH DRAWING.		2271	10/17/83
ALL NOTES AND COMMENTS COMPLY WITH MATERIAL LIST			
INSTALLED AND WITNESSED BY Q.C.		A. Holes drilled to tolerance and Check adjacent anchors	NA
Shield/Plug Driven to Tolerance		TYPE: Milti/Phillips	NA
Type Stud Instal.	SIZE	VALVE	TYPE: Milti/Phillips
Anchor Part No.	SIZE	VALVE	FRANCH SERIAL NUMBER
BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATES			
7. F.W. - A. Pipe attachment installation:		(1) Heat No:	NA
		(2) P.O. No:	NA
B. Support Members:		ITEMS	SPECIAL INSTRUCTIONS
(1) Groove & Full Pen Welds			NA
C. Purge Established where required			NA
9. WELD PREP ZONES CLEAN OF PAINT, OIL			
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) P.W./			NA
8. WELDING OF HANGER SUPPORT MEMBERS ONLY:		IDENTIFICATION	WELD CODE
SPECIAL WELDING INSTRUCTIONS:		CS/CS 7/8	
		88/89	
		SS/SS 129	
		15/18	
		CS/SS	
9. OTHER INSTRUCTIONS:			
10. FINAL WELD CONDITION-SUPPORT MEMBERS:		A. Weld Surface Clean	2271 10/17/83
		B. Arc Strikes Removed/Minimized	2271 10/17/83
		C. Weld Size Complies with drawing	2271 10/17/83
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION:		POPEMAN INITIAL/DATE	Q.C. DATE & INITIAL
A. Components and Dimensions Comply W/Dwg. & Mat'l. List		AS 10-17-83	
B. Pipe Clearance in Accordance with Drawing		AS 10-17-83	10/17/83
C. Riser Clamp Bears upon Lug		N/A	NA
D. Hanger is Level and Plumb		AS 10-17-83	10/17/83
E. All Bolts/Nuts Installed and Tight		AS 10-17-83	10/17/83
F. Wall & Ceiling Plates Shimmed where Necessary		N/A	NA
G. Grout Request Submitted		N/A	NA
H. Lug Clearance within Tolerance		N/A	NA
12. SHROBBERS:		A. Installed per Separate Process Sheet	N/A NA
		B. Grinnell Fig. / & Size	
		C. PSA Size	
		D. TYPE: NF	NOB-NF
13. SUPPORT ACCEPTED BY Q.C. (Complete Installation Review) Q.C. SIGNATURE			
DATE			

4 SE

PREINSPECTION CHECKLIST

	CHECKED	
	Q.C.	ENGINEER
1. ALL MEMBERS INSTALLED		
2. WELDS: Inaccessible and/or Undersized		
3. GAPS: U-Bolts, Tee Shoes and Lugs		
4. GROUTED PLATES: Grout damaged or Holes in Plate		
5. SEWDS: Tack Welds		
6. NUTS NOT FULLY ENGAGED		
7. ARC STRIKES		
8. MATERIAL SIZE		
9. OVERSIZED HOLES IN PLATE: Washers		
10. WARPED BASE PLATES/MEMBERS		

PREINSPECTION REMARKS:

Handwritten remarks area with multiple blank lines for notes.

FINAL INSPECTION COMMENTS:

INSPECTOR

DATE


DCN 1604-015 VOIDED AS PIPE GAPS ARE NOW WITHIN DESIGN TOLERANCES - FINAL WORKMANSHIP ACCEPTED 10/17/83



GAPS WERE INCORRECTLY TRANSFERRED EAST AND WEST WEST GAP IS 0". DCN 1604-022 WRITTEN TO REWORK 10/22/83

Additional blank lines for final inspection comments.

NO. 1 PIPE CR. $\frac{1}{8}$ " MIN. TOP & BOTTOM,
 $\frac{1}{16}$ " WEST SIDE, $\frac{1}{16}$ " EAST SIDE.



ELEV. VIEW (LKG. NORTH)

NOTE: HOLES IN ITEM #1 FOR
 U-BOLTS TO BE $\frac{1}{4}$ "
JM 8/23/83

ELEV. VIEW (LKG. EAST)

PACIFIC GAS & ELECTRIC CO.
**APPROVED FOR
 CONSTRUCTION**
 ENGINEERING DEPARTMENT
 DATE 8/18/83 842-13
 BY GDS JB

**FOR INFORMATION
 ONLY**

**APPROVED FOR
 CONSTRUCTION**
 8/17/83 WAXW
 DATE ENGR
 92126-18-83

CONTROLLED COPY

UNLESS OTHERWISE SPECIFIED	REF. DWG. 500542 SYS 14	PIPE SUPPORT
	CLASS C/E UNIT 1 AREA 2	
NO. CLEARANCES ARE 0" BOTTOM	ELEV 85' DESIGN GR SHAH	DWG. No. 512-12 REV. No. 0
	ISS. DATE 7-21-83	E-PATR. SHT 2 OF 2



EL 115'-0"

RELOCATION

LOC ON DWG


DESIGN CLASS I
CODE CLASS C

CALLED NORTH



LOCATION PLAN

FIELD RELOCATION
TOLERANCE 12" NW 0" SE



PLAN VIEW

FOR INFORMATION ONLY

P.P.P. AS BUILT DRAWING

DATE	P.P.P. VERIFIED
9-10-83	JMA

NO OTHER OFFSETS

NO	REQD	MATERIALS PER ASSEMBLY 1
1	2	SMA. SIZE 1, TYPE BA, SHOCK ARRESTOR. 4" STROKE. S.C. = 5-5 5/8", C.S. = 2 1/4", H.S. = 1 1/16". LOAD = 1100# (DELET
2	1	T.S. 8 x 4 x 3/8, 2'-0" LG. 11 1/2" LG. ✓
3	4	3/4" φ HILTI SHELL TYPE CONC. ANCHOR ✓
4	2	T.S. 4 x 4 x 1/4, 45" LG. 15 1/8" ✓
5	1	FIG. 1375, U-BOLT, A = 1/2", B = 4 1/2", C = .5", D = 8 3/4", E = 7 1/4" w/ (6) HEX NUTS ✓

CONTROLLED COPY

PROJECT: DIABLO CANYON	UNIT: ONE	DSGN <i>L. J. ...</i>	DRAWING NO 283
		DWM C. DELUCA	049308
		CHKD <i>...</i>	PG & E CO
		SHT 177 OF SHTS	ISSUE

Pullman Power Products

FIELD PROCESS SHEET

N/A - NOT APPLICABLE

PG&E		NO & SYSTEM	ISOMETRIC DRAWING NO.	DETAIL DRAWING NO.	SHEET NO.			
		N/A	N/A		1 OF 2			
PREPARED BY	JOB NO.	DATE	CODE	CLASS	MARK NO.			
RDG	7177	4-7-83	N/A	I	10-13652			
OPER. NO.	OPERATION	HOLD FOR AUTH. INSP.	HOLD FOR PTT INSP.	PROC. NO.	OPER.	DATE CDOP.	PTT INSP. & DATE	AUTH. INSP. & DATE
FABRICATION OF NPS TRANSITION KIT								
1	Cut "T" to dimension required: 4-1/4"				2677	4/1/83	rem 4/2/83	
2	Center punch & drill 1/4" Ø sight hole @ dimension "T" from end		*		2677	4/1/83	rem 4/13/83	
3	Clean barrel and coupling nut for welding							
4	Thread coupling nut into jig and tack weld pipe to coupling.			7/8				
5	Remove assembly from jig and complete weld to fillet size "T" 3/16"		*		51	4/13/83	rem 4/13/83	
6	Metal stamp coupling nut.				2673	4/13/83	rem 4/13/83	
I.D. No. 041								

FOR INFORMATION ONLY

FOR INFORMATION ONLY

1. LOCATION OF SUPPORT COMPLIES WITH DRAWING.	2171	✓	12-22-83
2. DRAWING GRANTED NOTED AND COMPONENTS CHECKED WITH MATERIAL LIST	2171	✓	MC 9/12/83
3. ANCHORS INSTALLED AND WITNESSED BY O.C. <small>a. notes drilled to tolerance and Check adjacent anchors</small>	2171	✓	7-20-83
B. Shield/Plug Driven to Tolerance		TYPE: <i>Hilti/Phillips</i>	<i>N/A</i> * <i>N/A</i>
C. Type Stud Installed	SIZE	MIN. DR.	TYPE: <i>Hilti/Phillips</i>
<i>(10) 1/4" x 15 KWIKS HILTI TRUCK & SET.</i>	<i>1/4"</i>	<i>10 1/2"</i>	<i>SEE O.C. NOTE ON DRAW.</i>
D. Anchors Torqued	SIZE	VALUE	WRENCH SERIAL NUMBER
<i>(10) 1/4" x 15 KWIKS TO 22.5 FT/16</i>	<i>1/4"</i>	<i>225#</i>	<i>PPP #102 UOE 844-83</i>
E. Unused holes dry packed <small>(4) HOLES NEED DRY PACKING (2) 1/4" x 2(2) 1/2"</small>			
4. BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATES <small>ALL NUTS BACKED OFF PRIOR TO WELDING</small>	2171	✓	15-7-1983
5. FIT-UPS: A. Pipe attachments installation:	(1) Seat No: <i>L41491</i>	2171/2419	✓ <i>8P3</i> 7-2-83
<i>Item 7 to pipe</i>	(2) P.O. No: <i>12237</i>	2171/2419	✓ <i>8P3</i> 7-2-83
B. Support Members:	ITEMS	SPECIAL INSTRUCTIONS	
(1) Groove & Full Pen Welds			<i>N/A</i> * <i>N/A</i>
			<i>N/A</i> * <i>N/A</i>
C. Purge Established where required			<i>N/A</i> * <i>N/A</i>
6. WELD PREP FINISH CLEAN OF PAINT, OIL			
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) <i>1300</i>			✓ <i>8P3</i> 7-2-83
8. WELDING OF HANGER SUPPORT MEMBERS ONLY:	WELD TYPE	WELD CODE	
SPECIAL WELDING INSTRUCTIONS:		<i>CS/CS - 2419</i>	<i>15-7-83</i>
		<i>↓ 88/89</i>	
		<i>SS/SS 129</i>	
		<i>↓ 15/15</i>	
		<i>CS/SS</i>	
9. OTHER INSTRUCTIONS:			
<i>QC VERIFY ACTUAL ALIGNMENT OF ITEM 8</i>	2171	✓	7-22-83
<i>QC VERIFY EPOXY GROUT SET TIME DATE 6-10-83</i>	2171	✓	6-17-83
10. FINAL WELD COMMISSION-SUPPORT POINTS:	A. Weld Surface Clean	2171	✓ <i>15-7-83</i>
	B. Arc Strikes Removed/Minimized	2171	✓ <i>15-7-83</i>
	C. Weld Size Complies with drawing	2419	✓ <i>15-7-83</i>
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION:	FOREMAN	O.C. DATE	
A. Components and Dimensions Condy W/dwg. & Mat'l. List	<i>APP 7-25-83</i>	<i>9/12/83</i>	
B. Pipe Clearance in Accordance with Drawing	<i>NA</i>	<i>NA</i>	
C. Elser Clamp Bears upon Lug	<i>NA</i>	<i>NA</i>	
D. Hanger is Level and Plumb	<i>APP 7-25-83</i>	<i>15-7-83</i>	
E. All Bolts/Nuts Installed and Tight	<i>APP 7-25-83</i>	<i>15-7-83</i>	
F. Wall & Ceiling Plates Shipped where Necessary	<i>APP 7-25-83</i>	<i>15-7-83</i>	
G. Grout Request Submitted	<i>NA</i>	<i>NA</i>	
H. Lug Clearance within Tolerance	<i>NA</i>	<i>NA</i>	
12. SURVEYS:	A. Installed per Separate Process Sheet	<i>APP 7-25-83</i>	✓ <i>15-7-25-83</i>
	B. Grinnell Fig. & Size	<i>APP 7-25-83</i>	
	C. Size <i>PP100</i>	TYPE: <i>N/A</i>	
13. SUPPORT ACCEPTED BY O.C. (Complete Installation Review) O.C. SIGNATURE <i>Chuck Keskey</i>			DATE <i>9/12/83</i>

see back
 OFTC-8940
 for EMB class
 4-7-22-83

NO NOTIFICATION FOR

PREINSPECTION CHECKLIST

CHECKED	
O.C.	ENGINEERING

1. ALL MEMBERS INSTALLED
2. WELDS; Inaccessible and/or Undersized
3. GAPS; U-Bolts, Tee Shoes and Lugs
4. GROUTED PLATES; Grout damaged or Holes in Plate
5. SHIMS; Tack Welds
6. NUTS NOT FULLY ENGAGED
7. ARC STRIKES
8. MATERIAL SIZE
9. OVERSIZED HOLES IN PLATE; Washers
10. WARPED BASE PLATES/MEMBERS

N/A
NEW
2/3/83

PREVIEW COMPLETE - 5/13/83 AC / MATERIALS REVIEW COMPLETE 5/14/83

PREINSPECTION REMARKS:

QC * VERIFIED HOLES IN WALL FOR 1 1/2 x 1 1/2 KWIKS AS GOOD ALL (10) HOLES. ALSO 4 HOLES NEED DR PACKING (2) 1 1/2 x 2 (2) 1" HOLES. 7-13-83
QC * ITEM Y NEEDS SHIMMING AROUND P TO OVER 25% R 4-7-22-83

PKY ENG. & P.G. & E TO TRANSFER ORIGINAL COMMENTS TO THIS PROCESS SHEET OR EXPLAIN WHY NOT p.c. 7-13-83

FOR INFORMATION

FINAL INSPECTION COMMENTS

INSPECTOR

DATE

OVERALL LENGTH OF TUBE AT PIPE IS 50 1/2" J.S. 7-22-83
 VERIFIED TO "PULL AC" AT BOTH ENDS STA (3). J.S. 7-23-83
 Verified that assembly was disassembled prior to welding socket end to adapter end of extension tube J.S. 7/23/83. Line I.K. 95.30 is resting directly on line #X.B2.20
 NO CLEARANCE J.S. 7/23/83

FROM BUREAU DRAWING SET JMS 7/22/83



8-25-83

INSPECTOR: Jere Ayers

NO. 373

SYS: 3

DRWG. NO: 049308

SHT: 177


135	✓
Top	Both
✓	✓
INDICATES	ACCEPTABILITY

SHOULDER AXIS WITHIN 10° OF OPTIMUM (NO INTERFERENCE AT REAR BRACKET OR FORWARD ADAPTER)	✓	✓
COLD SETTING WITHIN FIELD TOLERANCE ($\pm 1/4 W$) <u>1 5/16" ± 0.0003 *</u>	<u>1 5/16</u> <u>0.99183</u>	<u>1 5/16</u> <u>0.991</u>
Transition Tube bolts/cap screws tightened, Torque sealed, and Safety Wired (if applicable) at final inspection	✓	✓
Bolt/cap screw lock washers installed (if applicable)	NA	NA
REAR BALL JOINT NOT LOOSE OR PUSHED OUT	✓	✓
REAR BRACKET COTTER PINS SPREAD	✓	✓
REAR BRACKET WASHERS INSTALLED CORRECTLY	✓	✓
PSA SHOCKER CLAMP INSTALLED	NA	NK
CLAMP LINED IF REQUIRED	NA	NA
CLAMP SHORTENED IF REQUIRED	NA	NK
GRADE 5 BOLT INSTALLED IN PROPER HOLE	NA	NK
LOCK NUT INSTALLED ON GRADE 5 BOLT	NA	NA
1-3 BOLT THREADS EXPOSED BEYOND NUT ON ALL CLAMP BOLTS	NA	NA
ALL CLAMP NUTS TIGHTENED	✓	✓
NEW-STYLE LOCK NUT NOT BACKED OFF OR REMOVED ONCE TIGHTENED	NA	NA
SPACER INSTALLED IN PROPER LOCATION	NA	NK
FORWARD ADAPTER BALL JOINT NOT LOOSE OR PUSHED OUT	✓	✓
WASHERS INSTALLED EACH SIDE OF FORWARD ADAPTER	✓	✓
EXTRA REAR BRACKET WASHERS INSTALLED CORRECTLY	NA	NK
EXTRA REAR BRACKET COTTER PINS SPREAD	NA	NK
SHOCKER NOT DAMAGED INTERNALLY	✓	✓
SHOCKER BOOT INSTALLED	NA	NI


FOR INFORMATION ONLY

NOTE: IF THERE IS MORE THAN A SMALL AMOUNT OF PLAY WHEN ONE END OF THE SHOCKER IS TWISTED WITH RESPECT TO THE OTHER, THE SHOCKER IS BROKEN INTERNALLY AND MUST BE REPLACED.

DO HOLD POINT DURING BOOT INSTALLATION ONLY.




VIEW G-G
LKG DWN




VIEW I-I
LKG DWN

SAP/ym
5/19/83
5-19-83



VIEW J-J



SECT. Y-Y

CONTROLLED COPY

P.P.P. AS BUILT DRAWING

DATE	PPP VERIFIED
7/24/53	8/11/11

UNLESS OTHERWISE SPECIFIED


Welds: field fit; not exact side-horiz.
Clearances are: 0" bottom
and 1/8" two sides and top.

REF. DWG: 500090 SYS E/A
CLASS 1 UNIT 1 AREA K
ELEV 100' DESIGN PUJ-21-
ISO MULTI DATE 2-16-83

PIPE SUPPORT

284
DWG No. 00-11 REV No. 7
BUILT SHT 10 OF 20

105	1	1/2" R, 4 1/2 x 7" ✓ CUT AS SHOWN
106	1	1" R, 1 1/2" x 10" DATE 7/15/53 7 1/2" LG. CUT AS SHOWN
84	2	R 3/4 x 5 8 1/2" LG 5 1/2" LG 5" LG
5	1	T.S. 4" x 4" x 3/8", 20" LG. LENGTH
2	1	R 3/4 x 5 x 4" LG.




UNLESS OTHERWISE SPECIFIED

U: field-fit, nut each side. Horiz. pipe clearances are: 0" bottom and 1/16" two sides and top.

REF. DWG. 500099 SYS 8/9
 GLASS 1 UNIT 1 AREA V
 ELEV 100' DESIGN J.M.M.
 ISO (ULT) DATE 7/24/53

PIPE SUPPORT


DWG. No. 92-11 REV. No. 7
 SHT 3 OF 3



SEC. K-K

SAP/ym ds 5/19/83
5-19-83

CONTROLLED COPY




DETAIL VI

P.P.P. AS BUILT DRAWING

DATE	PPP VERIFIED
7/2A/83	<i>J.M.M.</i>

LKG UP



ABANDONED HOLES, TYP (A) PLS. 3/4" Ø

ELEV. SECT P.P

LESS OTHERWISE SPECIFIED

REF. DWG. <u>500099</u>	SYS <u>F/G</u>
CLASS <u>I</u>	UNIT <u>I</u>
ELEV <u>100'</u>	DESIGN <u>2/21/83</u>
ISO MULTI	DATE <u>2-16-83</u>

PIPE SUPPORT

DWG. No. <u>99-11</u>	REV. No. <u>7</u>
(17)	<u>36</u>
BUILT SHT <u>12</u>	OF <u>20</u>

- pipe clearances are 0" bottom and 1/16" two sides and top.

REV. 5-11-82		GENERAL FIELD SUPPORT PROCESS SHEET		SUPPORT NO. 49-11		PROJECT NO. 200099		PAGE 7	
1. LOCATION OF SUPPORT COMPLIES WITH DRAWING.				2245		✓		7/11/83	
2. DRAWING EXAMPLE NOTES AND COMPONENTS COMPLY WITH MATERIAL LIST				2245		✓		7/11/83	
3. WORKERS DETAILLED AND WITNESSED BY Q.C.		n. notes drilled to tolerance and Check adjacent anchors		2245		✓		7/6/83	
B. Shield/Plug Driven to Tolerance		TYPE: Hitco/Phillips		2245		✓		7/11/83	
C. Type Stud Installed		SIZE	LEN. DRS.	TYPE: Hitco/Phillips	3080	✓		7/7/83	
1" X 9" Hilti		1 X 9"	4 1/2"		3080	✓		7/7/83	
D. Anchors Torqued		SIZE	VALUE	WRENCH	2245	✓		7/10/83	
7/8"		3/4"	100 ft/lb	4 1/2" Hex	2245	✓		7-27-83	
E. Thrused holes dry packed		1"		220 ft. lb	2245	✓		7/11/83	
4. BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATES				N/A		✓		N/A old work	
5. FIT-UPS: A. Pipe attachments installation:		(1) Heat No:		N/A		✓		N/A	
		(2) P.O. No:		N/A		✓		N/A	
B. Support Members:		ITEMS		SPECIAL INSTRUCTIONS					
(1) Groove & Full Pen Welds		Fitter Signed in Error		N/A		✓		7/11/83	
C. Purge Established where required				N/A		✓		N/A	
6. WELD PREP ZONES CLEAN OF PAINT, OIL				2245		✓		7/11/83	
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) P.V.#				N/A		✓		N/A	
8. WELDING OF HANGER SUPPORT MEMBERS ONLY:		IDENTIFICATION		WELD CODE		551		7/11/83	
SPECIAL WELDING INSTRUCTIONS:		SO2A (80)		CS/CS 7/8		3080		7/11/83	
				↓ 8/83					
				SS/SS 129					
				↓ 15/16					
				CS/SS					
9. OTHER INSTRUCTIONS:		all welds ok @ plate #96 on pu of		3080		✓		7/11/83	
Items 96-97-98-10									
10. FINAL WELD CONDITION-SUPPORT MEMBERS:		A. Weld Surface Clean		2245		✓		7/11/83	
		B. Arc Strikes Removed/Minimized		2245		✓		7/11/83	
		C. Weld Size Complies with drawing		3080		✓		7/11/83	
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION:		FOREMAN		Q.C. DATE					
A. Components and Dimensions Comply w/Dwg. & Mat'l. List		DB		7/11/83		✓		7/11/83	
B. Pipe Clearance in Accordance with Drawing		DB		7/11/83		✓		7/11/83	
C. Sizer Clamp Bears upon Lug		N/A		N/A		✓		N/A	
D. Hanger is Level and Plumb		DB		7/11/83		✓		7/11/83	
E. All Bolts/Nuts Installed and Tight		DB		7/11/83		✓		7/11/83	
F. Wall & Ceiling Plates Shinned where Necessary		N/A		N/A		✓		N/A	
G. Grout Request Submitted		N/A		N/A		✓		N/A	
H. Lug Clearance within Tolerance		N/A		N/A		✓		N/A	
12. STUDS:		A. Installed per Separate Process Sheet		NONE		✓		N/A	
		B. Grinnell Flt. # & Size		E. PSA Size		F. TYPE: WT, NON-WT			
13. SUPPORT ACCEPTED BY Q.C. (Complete Installation Review) Q.C. SIGNATURE								DATE 8-2-83	

et 4
Final
7/11/83
19" Hilti
Nik Bolts
2AE*2
16.83
7-16-83
20 ft/lb
7/11/83

2245 ✓ 7/11/83
2245 ✓ 7/11/83
2245 ✓ 7/6/83

2245 ✓ 7/11/83
3080 ✓ 7/7/83
3080 ✓ 7/7/83

2245 ✓ 7/10/83
2245 ✓ 7-27-83
2245 ✓ 7/11/83

N/A ✓ N/A old work
N/A ✓ N/A
N/A ✓ N/A

N/A ✓ N/A
N/A ✓ N/A
N/A ✓ N/A

2245 ✓ 7/11/83
N/A ✓ N/A

551 ✓ 7/11/83
3080 ✓ 7/11/83
129 ✓ 7/11/83

3080 ✓ 7/11/83

2245 ✓ 7/11/83
2245 ✓ 7/11/83
3080 ✓ 7/11/83

DB 7/11/83 ✓ 7/11/83
DB 7/11/83 ✓ 7/11/83
N/A ✓ N/A

DB 7/11/83 ✓ 7/11/83
DB 7/11/83 ✓ 7/11/83
N/A ✓ N/A

N/A ✓ N/A
N/A ✓ N/A
N/A ✓ N/A

DATE 8-2-83

INSPECTION REMARKS

NO.	DEFICIENCY	STATUS	DATE
1.	ALL MEMBERS IDENTIFIED		NR RC 5-25-83
2.	WELDS: Inaccessible Ends Identified		NR RC 5-25-83
3.	GAP: T-Bolts, Tee Shoes and Lugs		✓ RC 5-25-83
4.	CRACKED PLATES: Cracks identified at Holes in Plate		✓ RC 5-25-83
5.	WELDS: Tack Welds		N/A
6.	WELDS NOT FULLY ENGAGED		N/A
7.	ARC STRIKES		N/A
8.	MATERIAL SIZE		✓ RC 5-25-83
9.	OVERSIZED HOLES IN PLATE; Washers		N/A
10.	WAPPED BASE PLATES/MEMBERS		N/A

Pre-inspection was done by R. Noji (see rev 6) with 5/25/83

REINSPECTION REMARKS:

REMOVE EXISTING 1/2" RATE AND INSTALL 3/4" RATES ITEMS (49) & (50)
 INSTALL ITEMS (44) THRU (54)

NOTE INSULATION REMOVAL REQUIRED TO INSTALL ITEM (48)
 ALSO REQUIRED FOR 44, 45, 46 & 47

AN INTERFERENCE MAY EXIST WITH INSTALLATION OF ITEM (51)
 RESOLVE IN PROCESS FOR CONVICTION

RELOCATE ITEM (53) 3" TO UTILIZE EMBED *flush cover*
 SEE REO-LINED DIMENSION X1355

PG 26 PI FINAL PKG. REVIEW - COMPLETE. MMC 6/6/83
 WORK W/ TC - 7/4/83

FINAL INSPECTION COMMENTS: INSPECTOR: DATE:

#54 to #1 fillit gap 3/2 gap insert also #1 has been ground down
 to close some gap on South side 2/6/27/83
 found where w/ Quick Fix TCI-822 2/6/28/83
 OK W/ TC 822 OK phi upper #53 at insert OK 2/4/83

FINAL INSPECTION COMPLETE - (AW) 7-10-83

AS BUILT CHANGES AFTER QC FINAL ACCEPTANCE PER QA REQUEST
 WITH THE KNOWLEDGE & APPROVAL OF THE FIELD QA/QC MANAGER (JO) 11/3/83
 DCN 1604-025 WRITTEN FOR DEFICIENCIES (JO) 11/3/83

Handwritten signature: G. and B. 7-12-83

PRE-INSPECTION ENGINEER - R. Noji X1355

JANUARY 14, 1983.

NTT OFFICE CORRESPONDENCE

MARCH 9, 1983,
APRIL 25, 1983, AND
DATE JULY 21, 1983

TO ALL FIELD SUPERINTENDENTS

FROM P. STIEGER/R. FAULL

SUBJECT ARC STRIKES, GRINDER GOUGES AND PUNCH MARKS.

PLEASE CONDUCT A TRAINING SESSION WITH ALL CRAFT PERSONNEL CONCERNING THE FOLLOWING:

In the recent past we have had too many arc strikes and grinder gouges on pipes, hangers, rod assemblies, etc. In order to eliminate these conditions, each person must take the following precautions:

- 1) Do not ground to pipes, hangers, etc.
- 2) Protect surrounding pipe hangers and other equipment in work area from weld splatter, grinding and thermal debris.
- 3) Be careful not to let stingers arc pipe, hangers, etc., when hanging stingers, setting them down or during other movements of stinger.
- 4) Do not drag leads over pipes, etc: if they have bare spots or open connectors they may arc.
- 5) Disconnect all leads from grids before pulling or rolling them up.
- 6) Use extreme caution when grinding in close proximity of piping. Protect the pipe prior to grinding. It is your responsibility to follow these steps and to eliminate arc strikes and grinder gouges on piping and other members.
- 7) Be sure cables are connected with matching connectors. Do not use a Cam-lock connector with a Jackson as they do not fit properly.
- 8) Check cables for broken insulation on bare spots.
- 9) All welding arc starts shall be confined to weld preparation area.
- 10) Center punches shall not be used on piping where the punch mark will not be removed by subsequent cutting or grinding. A low stress stamp or vibrotool is an acceptable method of marking.

P. Steiger
P. Steiger
Resident Construction Manager

R. Faull
R. Faull
Assistant Resident Construction Manager

UNIT 1





FIELD INSTALLATION INSTRUCTIONS

Item No.	Part No.	QTY	REMARKS
2723	E 7/8	1	
849 - 846	E 7/8	1	

POST CLOSE-OUT ISO DRAWING

THIS DRAWING IS TO BE USED FOR FIELD INSTALLATION INSTRUCTIONS ONLY. IT IS NOT TO BE USED FOR CONSTRUCTION OR FOR ANY OTHER PURPOSE. ANY CHANGES TO THIS DRAWING MUST BE APPROVED BY THE DESIGN OFFICE.



AS BUILT
 THE H. W. KELLOGG CO.
 Cable Tray

FIELD INSTALLATION INSTRUCTIONS

Item No.	Part No.	QTY	REMARKS

FOR INFORMATION ONLY

REVISIONS

NO.	DESCRIPTION	DATE

UNIT





FIELD INSTALLATION INSTRUCTIONS

Part No.	Qty	Unit	Notes
2723	1	EA	
808 - 5/16"	1	EA	

ST CLOSE-OUT
 SN 071111

NO FIELD INSTALLATION INSTRUCTIONS
 TO BE USED FOR THIS UNIT
 SEE THE DRAWING FOR THE
 LOCATION OF THE UNIT
 AND THE LOCATION OF THE
 FIELD INSTALLATION INSTRUCTIONS



AS BUILT
 THE M. W. KELLOGG CO.
 Diablo Canyon

Date: 1-23-67 By: G. J. ...

FIELD INSTALLATION INSTRUCTIONS

Part No.	Qty	Unit	Notes
2723	1	EA	
808 - 5/16"	1	EA	

FOR INFORMATION ONLY

NOTE

COPY ...

COPE CLAY ...

REV.	BY	DATE	DESCRIPTION
1			
2			
3			
4			

APPROVED FOR FABRICATION AND INSTALLATION ONLY


76-1116 Proj

AREA

K

LINE SI-1 (LT-114 LC)

HANGER SYMBOL



EL 100'-0"



ISO. H9-748
VOLUME CONTROL TANK

LOC ON DWG ECC099

DESIGN CLASS /
CODE CLASS 3
CALLED NORTH

NOTE:

WORK THIS DRAWING
FOR THE
P.P.P. AS SHOWN
DATE 6-15-63



PLAN
NORTH
(EL 100'-0")

(4) 5/8" HOLES

ATT. &
R (TYR)

CONTROLLED COPY
BASE DETAIL

NOTE: NO OFFSETS
IN EITHER DIRECTION

NO OF ASSEMBLIES REQUIRED 1

NO	REQD	MATERIALS PER ASSEMBLY
1	1	TS 3" x 3" x 0.25" x 1'-0" LG. 7 3/4" LG.
2	2	PL 3/8" x 4" x 4"
3	1	PL 1/2" x 9" x 9" (PER BASE PL DETAIL) R 3/4" x 11" x 9" LG.
4	4	1/2" φ HDI CONC. ANCHORS (STUD TYPE)
5	1	PSA-1/4 (PRE-NF), RET. STROKE = 1/8", CS = 2 1/2"
6	1	3/4" φ C.S. SCH. 40 PIPE x 2'-0" LG (FIELD)
7	1	PSA-1/2 SNUBBER PIPE CLAMP, FOR 2" φ PIPE (PER DRAWING)
8	2	3/8" FILLER PLATE (PER DETAIL '1')

OR
EYES

DESIGN	DRAWING NO
BY C. [unclear]	023315
CHECKED	

PROJECT: <u>DIABLO</u>	UNIT: <u>1</u>	SHT: <u>33</u>	SHTS:	PG & E CO	ISSUE: REV
------------------------	----------------	----------------	-------	-----------	------------

76-11 (4-82)

LA

OUTSIDE AREA <u>1-P</u>	LINE <u>1-K-5148-36</u> E	HANGER SYMBOL X, Z RESTRAINT	
EL <u>851-04</u>	AUX. BOILER FLUE GAS STACK	LOC ON DWG _____	

REV	ISSUE DATE	DESCRIPTION OF CHANGES	PREPARATION			APPROVAL		
			DSGN	DWN	CHKD	DUS	ENGR	SUPV ENGR
01	6-25-83	ISSUED FOR FABRICATION & INSTALLATION	D.S.	RC	PS	J140 FIR A. SATO	DRC	ASM

SEE #1-14001
T.C. & #1-13822
CEM/03
11/5/03

FOR INFORMATION ONLY

APPROVED FOR CONSTRUCTION
3/3/83
DATE: 3/3/83 ENGR: NNW

NPO CLEARANCE REQUIRED PRIOR TO WORK

NOTES:

NO PIPING PROCESS SHEETS REQUIRED

CONTROLLED COPY

CLASS E

06
AXS


SHEETS ASSIGNED TO THIS HANGER SYMBOL (TOTAL 4 SHEETS)

287


64	64A	64B	64X																
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
										DSGN D. SHVEYD		DRAWING NO							
										DWN RC		049229							
										CHKD P. SATO									
PROJECT: DIABLO CANYON					UNIT:					64X OF SHS		P G & E CO				ISSUE R/			

7E 1-6 Rev. 3-76

AREA <u>1-P.</u>	LINE <u>1-K-5148-36 E</u>	HANGER SYMBOL <u>229</u>
EL <u>85'-0"</u>	<u>AUX. BOILER FLUE GAS STACK</u>	<u>X, Z RESTRAINT 61R</u>
		LOC ON DWG _____



DESIGN CLASS II
 CODE CLASS E
 CALLED NORTH



SECT. A-A FOR INFORMATION ONLY

*SEC #1-1400
 T.C. #1-13822
 CEM/1/83
 11/1/83*

APPROVED FOR CONSTRUCTION
 DATE

NO. OF ASSEMBLIES REQUIRED I

NO	REQ'D	MATERIALS - PER ASSEMBLY
1	2	C.S. PL 3/4 X 14" X 1'-2" LG.; W/(4) 1/16" φ HOLES (SEE ITEM 1 DET. SH. 64A)
2	8	1" φ HILTI KWIK BOLTS
3	2	W6 X 20; 4'-10" LG. EA.
4	4	T-SHOE (SEE DET. ON SH. 64A) C.S. PL
5	2	W6 X 20; LG BY FIELD (CUT TO FIT)
6	2	W6 X 20; 3'-8 1/8" LG. EA.
7	4	C.S. PL 3/4 X 12" X 1'-3" LG. W/(4) 3/16" φ HOLES (SEE DET. ITEM 7 SH. 64A)
8	16	3/4" φ HILTI KWIK BOLTS
9	2	W6 X 20; LG. BY FIELD (CUT TO FIT)
10	2	C.S. PL 1/2" X 7" X 0'-10" LG. EA.
11	24	C.S. PL 5/8" X 2 3/4" X 0'-5 1/2" (CUT TO FIT)
12	1	T.S. 6" X 6" X 1/2" X 8'-0" LG. - A500 GRB (CUT TO SUIT)
13	2	T.S. 4" X 4" X 1/2" X 1'-3" LG. - A500 GRB (CUT TO SUIT)

CONTROLLED COPY

*22K
 2/24/83
 15/83*

PROJECT: <u>DIABLO CANYON</u>	UNIT: <u>1</u>	DSGN <u>DS</u>	DRAWING NO
		DWN <u>RC</u>	<u>049229</u>
		CHKD <u>P SATO</u>	
SHT <u>64</u> OF <u>68</u> SHTS		PG & E CO	
		ISSUE	

ITEM	QUANTITY	MATERIAL
14	8	FISH PLATE 1" X 4" X 4" w/ 1/16" ϕ HOLE ON CENTER C.S. A-36
15	16	FISH PLATE 1/2" X 3" X 3" w/ A 25/32" ϕ HOLE ON CENTER C.S. A-36

FOR T.C. # 1-14001 CEM 11/5/83

7A	1	PLATE 1" X 13 1/2" X 16 3/4" C.S. A-36 FOR STD 223 SEC. 6.3.1 T.C. # 1-14001 CEM 11/5/83
----	---	--

7B	1	PLATE 1/4" X 12 1/2" X 15 1/4" C.S. A-36 FOR STD 223 SEC. 6.3.3 CEM 11/4/83
----	---	---

7C	1	PLATE 1/4" X 13 1/4" X 15 3/8" C.S. A-36 FOR STD 223 SEC. 6.3.3 CEM 11/4/83
----	---	---

7D	1	PLATE 1/4" X 13 1/4" X 15 1/4" C.S. A-36 FOR STD 223 SEC. 6.3.3 CEM 11/5/83
----	---	---

16	2	PLATE 1/4" X 7" X 7" C.S. A-36 FOR STD 223 SEC. 6.6.2.14 CEM 11/29/83
----	---	---

FOR INFORMATION ONLY

76-17 Rev 3-76

AREA 1-P.

LINE 1-K-5148-36 E

HANGER SYMBOL

229


EL 85'-0"

AUX. BOILER, BLUE GAS STACK


X. 2 RESTRA

(LOC ON DWG)


FISH PLATES ADDED FOR ITEMS #1 PER ESD 223 SEC. 6.3.6



DET. ITEM 1



DET. ITEM 7



DET. ITEM 4

FOR INFORMATION ONLY

OF AXES

CONTROLLED COPY

FOR FISH PLATES SEE T.C. 11/1/83 21-1X001

DATE 11/1/83 ENGR WNW

PROJECT: DIABLO CANYON

UNIT:

DSGN DS
DWN RC
CHKD P SATO

DRAWING NO
049229

SHT 64 OF SHTS

P G & E CO

01

Flux bolt hole with rebar Encon
acceptable only as per Telecom A location
inspected by civil direction K.A. BELL
A. S. Smart 11/4/83

(1) 1" X 9" HKB
drawing of 1" X 9" HKB
attached 11/7/83

Unable to
set (P) 1" X 9" HKBs
with min 3 to 5
of the nut so as to
we to you to deal all
(P) 1" X 9" HKBs to 220 FTKZ
with 1000
A. S. Smart 10/31/83

OKED (A) 3/4" holes in
concrete
Witnessed drawing
of (A) 3/4" X 7" HKBs
during drawing of
the bolt circles as
this detail plate third
was damaged but should
not be rejectable due to
it will be spliced after
final torque.
A. S. Smart
10/31/83

FOR INFORMATION
ONE

OK to drive (7) 1" X 9" HKBs
DAIING (I) OF THE (8) identified with
Rebar was encountered and Eng' evaluation
for acceptability prior to driving the
bolt.

also checked (2) 3/4" holes in concrete
OK to drive (2) 3/4" X 7" HKBs
DAIING OF (2) 3/4" X 7" HKBs
A. S. Smart 10/31/83

Witnessed drawing of (A) 3/4" X 7" HKBs
during drawing of the bolt circles as this detail plate third was damaged but should not be rejectable due to it will be spliced after final torque.
A. S. Smart 10/31/83

Witnessed drawing of (A) 3/4" X 7" HKBs during drawing of the bolt circles as this detail plate third was damaged but should not be rejectable due to it will be spliced after final torque.
A. S. Smart 10/31/83

Witnessed drawing of (A) 3/4" X 7" HKBs during drawing of the bolt circles as this detail plate third was damaged but should not be rejectable due to it will be spliced after final torque.
A. S. Smart 10/31/83

76-1117 Rev. 3-

AREA L-P

LINE 1-K-5148-30 E

HANGER SYMBOL



229
61R

EL 85'-0"

AUX. BOILER FLUE
GAS STACK

X.2 RESTRAINT

LOC ON DWG



FOR INFORMATION ONLY



SECT. B-B (ROTATED 90°)
(ITEM 4 NOT SHOWN FOR CLARITY)

APPROVED FOR CONSTRUCTION
9/3/83 WNW
DATE ENGR


CONTROLLED COPY
REC'D 223
SEL. 6.3.3
CEM
11/4/83
T.C. #1-1400
CEM
11/4/83
FOR FINISH

PROJECT: BLASB CAYTON	UNIT: L	DSGN D.S	DRAWING NO		
		DWN RC	049229		
		CHKD P. SATO			
		SHT 64 OF 64 SHTS	P G & E, CO		01
				ISSUE	RE

EMBEDMENT DIAGRAM



TB → S
REQUIRES SHIMMING
(RESTORING) NO
EMBS @ THIS TIME
10/4/29/03



CONTROLLED COPY 11/29/03

FOR INFORMATION ONLY

PIPE SUPPORT DESIGN TOLERANCE CLARIFICATION FORM

SUBJECT 229/61R REV 1 SEQUENCE NUMBER TC-1-14189
CLASS ZE
LOCATION AREA 1-P ELEV: 85'-0" pre-inspect
in-work
past work
DR

DESCRIPTION: DRAIN HOLES ARE REQUIRED IN
ITEMS # 3, # 6, AND # 5.

SOLUTION: PROVIDE 1/4" Ø DRAIN HOLES
IN ALL POCKET AREAS OF ITEMS # 3, # 6,
AND # 5 ALONG THE CENTERLINE BETWEEN
THE FLANGES.

FOR INFORMATION
ONLY

P.P.P. F.E. CEM 11/29/83
G.C. F.E. _____

REFERENCE DRAWING 049229 SH 64
ATTACHMENTS YES NO PAGES (INC. THIS SHEET) 1

AREA ENGINEER:
CONSTRUCTION MAY PROCEED Stephen Bakey
DATE 11-29-83

CONSTRUCTION D.P. REQ'D _____
CONTRACTOR RECEIPT C. E. Mayo DATE 11-29-83

PIPE SUPPORT DESIGN TOLERANCE CLARIFICATION FORM.

SUBJECT 229/61R REV 1 SEQUENCE NUMBER TC-1-14001
CLASS II E
LOCATION AREA: 1-P ELEV: 162-3 pre-inspect
in-work
past work
OR

DESCRIPTION:

THE ANCHOR LOCATIONS FOR THE UPPER EASTERN-MOST ITEM # 7 (#7A) COULD NOT BE MAINTAINED WITHIN ESD 223 TOLERANCES. ALSO, DUE TO CONSTRUCTION TOLERANCES, FISHPLATES WILL BE REQUIRED FOR ITEMS # 7 (4 EACH). HOWEVER, DUE TO THE PROJECTIONS OF THE 3/4" ANCHORS, ONLY 1/2" THICK FISH PLATE CAN BE USED.

SOLUTION: ACCEPT THE ANCHOR SPACINGS AS SHOWN FOR ITEM # 7A. ADD ITEM # 15 TO THE B.O.M AS FOLLOWS.

ITEM # 15-16 REQUIRED - PLATE 1/2" X 3" X 3" W/A 25/32" HOLE ON CENTER. C.S. A-36. WELD AS

SHOWN ON SHEET 2 OF 2

FOR INFORMATION ONLY

P.P.P. F.E. CEM 11/5/83
G.C. F.E. _____

REFERENCE DRAWING 049229 SH 64

ATTACHMENTS YES NO PAGES (INC. THIS SHEET) 2

AREA ENGINEER:

CONSTRUCTION MAY PROCEED Stephen Bailey

DATE 11-5-83


CONSTRUCTION D.P. REQ'D _____

CONTRACTOR RECEIPT [Signature] DATE 11-5-83

SHEET 2 of 2

TC=1-14001
SAT 2 of 2

FISHPATE DETAIL TYPICAL
FOR ITEMS 7B, 7C, 7D



FOR INFORMATION ONLY

PIPE SUPPORT DESIGN TOLERANCE CLARIFICATION FORM

SUBJECT 229/612 REV 1 SEQUENCE NUMBER TC-F-13822
CLASS II E

LOCATION AREA: 1-7 ELEV: 85'-0" pre-inspect
in-work
past work
DR

DESCRIPTION: THE DESIGN DRAWING FOR SUPPORT 229/612
REQUIRES HORIZONTAL BRACES (ITEMS # 5) AT
ELEVATION 162'-3". HOWEVER, THE WALL ENDS AT
APPROXIMATELY 15'-4" WEST OF COLUMN "U" AND
DOES NOT ALLOW FOR PROPER INSTALLATION OF
THE WESTERN MOST ITEM 75 AND 8.

SOLUTION: 1. DELETE ITEM 5
2. PERMIT THE INSTALLATION AS SHOWN
ON ATTACHED SHEET 2022 AND REFACE THE R.O.M. AS
FOLLOWS: REINFORCE QUANTITY OF ITEMS AS FOLLOWS:
Add Item 12 - 1200 LBS 6x6x1/2 x 8'-0" LG - A500 GRB (CUT)
Add Item 13 - 2200 LBS 4x4x1/2 x 1'-3" LG - A500 GRB (CUT)

FOR INFORMATION ONLY
(WEST SIDE ONLY)

P.P.P. F.E. CEN 10/28/83
G.C. F.E. _____

REFERENCE DRAWING 049229 SH 64

ATTACHMENTS YES NO PAGES (INC. THIS SHEET) 2

AREA ENGINEER: _____
CONSTRUCTION MAY PROCEED: [Signature]

DATE 10/28/83

CONSTRUCTION D.P. REQ'D _____

CONTRACTOR RECEIPT C. E. Mc DATE 10/28/83

TC-1-13822



12'-0"

FOR INFORMATION ONLY

PARTIAL VIEW ELEV. 162'-3"

1 2

3

5

10

6

8

7

11

1

2

13

12

16

12

12

7

SECTION X-X




NOTES

1. INTENTED FOR AND...
2. OMITTED FOR CLARITY...
3. WEST HORIZONTAL...
ONLY. ALL OTHER...
WILL BE AS PER DESIGN.
3. LINE 1-K-5148-39
OMITTED FOR CLARITY.

VENT HOLE
PER CSD 223
SEC. 6.6 2/14B
CET

1/16"

DM 10/10/83
= 11.0/83



PULLMAN POWER PRODUCTS

ACCOUNTING REQUIREMENTS (A, R)

ATTN: Craft Foreman

Write the following code on the time sheet in the "Hanger No. or IEC No." of Hanger Time Sheets or in the "Piece No./Weld No." section of Piping Time Sheets when working on the attached work authorization:

<u>229-61R-NONE</u>
<u>1-62/338-06</u>
<u>P105913-0505</u>

Supplemental or additional work authorizations pertaining to this work authorization that were received in the field require recoding. No other detail, information or accounting is required in this section of the time sheets.

* * * * *

The following pertains to the Pullman Accounting Office only:

DCI NO. _____

WORK REQUEST NO. _____

DRAWING NO. 049229

DATE ISSUED 8-30-83

06
AXS

CONTROLLED COPY

FOR INFORMATION ONLY

PG & E
MEMORANDUM

TO: F. RUSSELL / D. ROSENEAU
FROM: R. TINKLE / J. ARNOLD
SUBJECT: REBAR EXPOSURE

Location: DCPP
Location: DCPP
229/61R

Date: 11/1/83
Ext. 3478
Ext. 3109
File No.

DRILLING FOR 1" ϕ HICBS, EXPOSED RE-BAR
@ THE WESTERN-MOST LOCATION OF ITEM # 1
IN THE LOWER EAST BOLT LOCATION.
PER YOUR REQUEST THE ATTACHED SUPPORT
DRAWING LOCATES THE EXACT POSITION OF THE
ENCOUNTER. IS THIS AN EXCEPTABLE
CONDITION?

K. Bell
11/4/83

CC: BOB OLDENKAMP / K. BELL / SUPPORT PACKAGE
CHUCK MORRIS W/REPLY
Date

Yes, this is a surface issue and will not
be a structural problem.

Rossman

FOR INFORMATION
ONLY

1. LOCATION OF SUPPORT COMPLIES WITH DRAWING.						
2. DRAWING CHANGES NOTED AND COMPONENTS COMPLY WITH MATERIAL LIST.						
3. ANCHORS INSTALLED AND WITNESSED BY Q.C.				Holes drilled to tolerance and Check adjacent anchors	7/90	* 11/7/83
B. Shield/Plug Driven to Tolerance				TYPE: Miller/Phillips	n/a	* 11/7/83
C. Type Stud Installed		SIZE	MIN. EMB.	TYPE		
(16) 3/4" x 7" HKRS		3/4"	1"	Miller/Phillips	7/90	* 11/7/83
D. Anchors Torqued				SIZE	VALUE	WRENCH SERIAL NUMBER
3/4"		100ft-lb	1"	220ft-lb	11/12/83	DOE 12/1/83
E. Unused holes dry packed						
4. BACK OFF BOLTS PRIOR TO WELDING ON BASE PLATES						
5. FIT-UPS: A. Pipe attachments installation:				(1) Heat No:		
				(2) P.O. No:		
B. Support Members:		ITEMS	SPECIAL INSTRUCTIONS			
(1) Groove & Full Pen Welds		9, 9	(2) Item (1), (11) Item (5) both ends of all pieces			
C. Purge Established where required						
6. WELD PREP ZONES CLEAN OF PAINT, OIL						
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) P.W.1						
8. WELDING OF HANGER, SUPPORT MEMBERS ONLY:				IDENTIFICATION	WELD CODE	
SPECIAL WELDING INSTRUCTIONS				CS/CS	7/8	
					88/89	
					SS/SS	129
						15/16
						CS/SS
9. OTHER INSTRUCTIONS:				VERIFY 1/16" Ø HOLES IN ITEMS # 14 PER ES0223 SEC. 6.3.6		* R. Noj 11/20/83
				VERIFY 25/32" Ø HOLES IN ITEMS # 15		* 11-19-83
10. FINAL WELD CONDITION-SUPPORT MEMBERS:				A. Weld Surface Clean		
				B. Arc Strikes Removed/Minimized		
				C. Weld Size Complies with drawing		
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION:				FOREMAN INITIAL/DATE	Q.C. DATE & INITIAL	
A. Components and Dimensions Comply w/Dwg. & Mat'l. List						
B. Pipe Clearance in Accordance with Drawing						
C. Riser Clamp Bears upon Lug						
D. Hanger is Level and Plumb						
E. All Bolts/Nuts Installed and Tight						
F. Wall & Ceiling Plates Shimmed Where Necessary						
G. Grout Request Submitted						
H. Lug Clearance within Tolerance						
12. SNUBBERS:				A. Installed per Separate Process Sheet		
				B. Grinnell Fig. / & Size	C. PSA Size	D. TYPE: NF NON-NF
13. SUPPORT ACCEPTED BY Q.C. --(Complete Installation Review) Q.C. SIGNATURE						
				DATE		

8) 1" x 9" HKRS

CEM
 11/7/83
 T.C. #1-
 14001
 CEM
 11/5/83

add
 11/7/83
 in case
 11/7/83
 10/31/83

SEEK
 BACK

11/2/83

FOR INFORMATION ONLY

PREINSPECTION CHECKLIST	CHECKED	
	Q.C.	ENGINEERING
1. ALL MEMBERS INSTALLED		
2. WELDS; Inaccessible and/or Undersized		
3. GAPS; U-Bolts, Tee Shoes and Jugs		
4. GROUTED PLATES; Grout damaged or Holes in Plate		
5. SEAMS; Tack Welds		N/A
6. NUTS NOT FULLY ENGAGED		PRE
7. ARC STRIKES		N/A
8. MATERIAL SIZE		20
9. OVERSIZED HOLES IN PLATE; Washers		1/2
10. WARPED BASE PLATES/MEMBERS		1

PREINSPECTION REMARKS:

Refer to notes on (2) Bolt HOK SEE BACK OF CONSTRUCTION
DWG for remarks re 1st visit 10/27/83

PER TELEPHON & LOCATION INSPECTION WITH CIWR. THE REBAR
EXPOSURE IS ACCEPTABLE PER BOLL'S PS 15. (11-3-83)

FINAL INSPECTION COMMENTS:



Engineering should have a review package &
sign that is required for construction application to
planner. Material list of items to be signed by KRB 11/19/83
is inaccurate to what is on 11/19/83. (11/19/83)

TORQUED (8) 1x9 HKB, 220 FT-LB; WRENCH PPP 103; CAL 11/19/83
DUE 12/19/83; SEE BACK OF DWG PG 64B FOR ENP. DIA T 11/21/83
NO VERIFICATION OF BACKING DEF OF BOLTS PRIOR TO
WELDING ON ALL ITEMS - DCK REF. ITEM 7B BOTTOM,
GAP > 1/8 IN. ENTIRE LENGTH REQUIRES SHIMMING 11/29/83
ALSO TORQUED (6) 1x9 HKB, 105 FT-LB; PPP 103 AS ABOVE 11/29/83

FOR INFORMATION
ONLY

DESIGN CLASS I
CODE CLASS C

CALLED NORTH



LOCATION PLAN

FIELD RELOCATION
TOLERANCE 12" NW 0" SE

FOR INFORMATION ONLY

P.P.P. AS BUILT DRAWING

DATE	P.P.P. VERIFIED
9-10-83	JMA

NO OTHER OFFSETS

NO	REQD	MATERIALS PER ASSEMBLY
1	2	SMA, SIZE 1, TYPE BA, SHOCK ARRESTOR, 4" STROKE, C.C. = 5' 5 5/8", C.S. = 2 1/4", H.S. = 1 1/16", LOAD = 1100# (DELETE)
2	1	T.S. 8 x 4 x 3/8, 2'-0" LG. 11 1/2" LG. ✓
3	4	3/4" φ HILTI SHELL TYPE CONC. ANCHOR ✓
4	2	T.S. 4 x 4 x 1/4, 45" LG. 15 1/8" ✓
5	1	FIG. 1375, U-BOLT, A = 1/2", B = 4 1/2", C = 5", D = 8 3/4", E = 7 1/4" w/(6) HEX NUTS ✓

CONTROLLED COPY

DSGN <i>JMA</i>	DRAWING NO
DWM <i>C. DELUCA</i>	049308
CHKD <i>JRC</i>	
SHT 177 OF SHTS	P G & E CO
	ISSUE

PROJECT: DIABLO CANYON UNIT: ONE

Pullman Power Products

FIELD PROCESS SHEET

N/A = NOT APPLICABLE

PG&E		NO & SYSTEM	ISOMETRIC DRAWING NO.	DETAIL DRAWING NO.	SHEET NO.			
		N/A	N/A		1 OF 2			
PREPARED BY	JOB NO.	DATE	CODE	CLASS	MARK NO.			
RDG	7177	4-7-83	N/A	I	10-13656			
OPER. NO.	OPERATION	HOLD FOR AUTH. INSP.	HOLD FOR TYP. INSP.	PROC. NO.	OPER.	DATE COMP.	TYP. INSP. & DATE	AUTH. INSP. & DATE
FABRICATION OF NPS TRANSITION KIT								
1	Cut "T" to dimension required. 9-1/4"					2673	4/13/83	RCM 4/13/83
2	Center punch & drill 1/4" Ø sight hole @ dimension "T" from end		*			2673	4/13/83	RCM 4/13/83
3	Clean barrel and coupling nut for welding							
4	Thread coupling nut into jig and tack weld pipe to coupling.				7/8			
5	Remove assembly from jig and complete weld to fillet size "T" 3/16"		*			2673	4/13/83	RCM 4/13/83
6	Metal stamp coupling nut.					2673	4/13/83	RCM 4/13/83
	I.D. No. 041							

FOR INFORMATION ONLY

FOR INFORMATION ONLY

1. LOCATION OF SUPPORT COMPLIES WITH DRAWING.		3414	9-1-83
2. DRAWING DETAILS NOTED AND COMPONENTS COMPLY WITH MATERIAL LIST		3414	9-1-83
3. ANCHORS INSTALLED AND WITNESSED BY Q.C.		NA	* old work
A. holes drilled to tolerance and Check adjacent anchors		NA	* old work
B. Shield/Plug Driven to Tolerance		NA	* old work
C. Type Stud Installed		SIZE	MIN. DMB.
D. Anchors Torqued		SIZE	VALUE
E. Drused holes dry packed		NA	* NA
4. BACK OFF BOLTS PRIOR TO WELDING ON BACK PLATES		NA	* NA
5. FIT-UPS: A. Pipe attachments installation:		(1) Beat No:	NA
		(2) P.D. No:	NA
B. Support Members:		ITEMS	SPECIAL INSTRUCTIONS
(1) Groove & Full Pen Welds			NA
C. Purge Established where required			NA
6. WELD PREP ZONES CLEAN OF PAINT, OIL		3414	
7. WELDING OF PIPE ATTACHMENTS (PER SEPARATE PROCESS SHEET) F.W.1			* NA
8. WELDING OF HANGER SUPPORT MEMBERS ONLY:		IDENTIFICATION	WELD CODE
SPECIAL WELDING INSTRUCTIONS:		CS/CS (7/8)	2280
		↓	85/69
		SS/SS	129
		↓	15/26
		CS/SS	
9. CHECK INSTRUCTIONS:			
10. FINAL WELD CONDITION-SUPPORT MEMBERS:		A. Weld Surface Clean	2280/3414 9-1-83
		B. Arc Strikes Removed/Minimized	2280/3414 9-1-83
		C. Weld Size Complies with drawing	2280/3414 9-1-83
11. REVIEW FOR GENERAL WORKMANSHIP AND CONFIGURATION:		FOREMAN	Q.C. DATE
A. Components and Dimensions Comply w/Dwg. & Mat'l. List		MWD 9/1	9-1-83
B. Pipe Clearance in Accordance with Drawing		NA	NA
C. Riser Clamp Bears upon Lug		NA	NA
D. Hanger is Level and Plumb		MWD 9/1	9-1-83
E. All Bolts/Nuts Installed and Tight		MWD 9/1	9-1-83
F. Wall & Ceiling Plates Shinned where Necessary		NA	NA
G. Grout Request Submitted		NA	NA
H. Lug Clearance within Tolerance		NA	NA
12. SWEBBERS:		A. Installed per Separate Process Sheet	X MWD 9/1 9-1-83
		B. Grinnell Fig. / & Size	C. PSA Size 1/2
		D. TYPE: RT	NOY AT
13. SUPPORT ACCEPTED BY Q.C. (Complete Installation Review)		Q.C. SIGNATURE	DATE: 9-19-83

FOR INFORMATION ONLY

FURNISH WORK PROGRAM

SUPPLY NO. 70-1365L DRAWING NO. 049308

PREPARED BY DATE 7.2.1983

1. LOCATION OF SUPPORT SYSTEMS THE MATING.

2. MATING GRADES WITH AND CONDITIONS OF THE MATERIALS

3. MATING SYSTEMS AS APPROVED BY G.C. (4) A. NOTES SHOWN TO COMPLIANCE AND CHECK ADJACENT ANCHORS

B. GRADE/TYPE SYSTEM IS TOLERANCE (4) 3/4" TYPE: M100/PH11102

C. TYPE SIZE TOLERANCE TYPE: M100/PH11102

4. ANCHOR SYSTEM

WELL 3/4" Ø 55-55 1/2 PDP38 DUE 5/25/83

5. TYPICAL PLAN OF PANEL ADJACENT HOLES (CHECK FOR GROOVES)

6. PLAN OF PANEL WITH TO TOLERANCE OF EACH PANEL

7. TOLERANCE: A. TYPICAL INSTALLATION: (1) EDGE SET: NA

(2) P.D. SET: NA

8. SUPPORT CONDITIONS: (1) GROOVE & FULL PEN WELDS: NA

(2) FULL PEN WELDS: NA

9. TYPE INSTALLATION WHERE APPLICABLE: NA

10. THE TOP SURFACE GRADE OF PANEL: NA

11. TOLERANCE OF PIPE ALIGNMENT (PER SPECIFICATION)

12. TOLERANCE OF EACH SUPPORT MEMBER: NA

FOR INFORMATION ONLY

13. TOLERANCE OF RUBBER CAPSCREWS TO 22 IN/A ± 2 IN/A DUE SPACE

OR TO VERIFY 1/16" PULL BRCK 7/8" INSERT (ITEM A)

14. FIELD AND SUPPORT SYSTEMS: A. Field Surface Case: 2836

B. Air Surface Smooth/Finished: 2836

C. Field Side Condition with surface: 2836

15. SYSTEM FOR GENERAL REQUIREMENT AND CONFIRMATION:

A. Dimensions and Dimensions Comply w/Draw. & det'L List: N/A

B. Pipe Clearances in Accordance with Drawing: N/A

C. Floor Clamp Seats upon Log: N/A

D. Hanger is Level and Plane: N/A

E. All Bolts/Nuts Installed and Tight: N/A

F. Wall & Ceiling Plates Checked where Necessary: N/A

G. Gross Ingress Solved: N/A

H. Log Clearances within Tolerances: N/A

16. SURVEYS: A. Installed per Separate Process Sheet: N/A

B. Overall Plg. & Size: N/A

C. Plg. Size: N/A

17. SUPPORT ACCEPTED BY G.C. (Complete Installation Review) G.C. SIGNATURE: [Signature]

W/N/A
M/G

8-25-83

INSPECTOR:

Jare Ayers

Top

Bot

E NO.

373

SYS:

3

DRWG. NO: 049308

SHT: 177

ACCEPTABILITY

SHOCKER AXIS WITHIN 10° OF OPTIMUM (NO INTERFERENCE AT REAR BRACKET OR FORWARD ADAPTER)

✓

✓

COLD SETTING WITHIN FIELD TOLERANCE ($\pm 1/4$ in) 1 5/16" resp 8/24/83 *

1 5/16

8/24/83

1 5/16

8/24/83

Transition Tube bolts/cap screws tightened, Torque sealed, and Safety Wired (if applicable) at final inspection

✓

✓

Bolt/cap screw lock washers installed (if applicable)

NA

NA

REAR BALL JOINT NOT LOOSE OR PUSHED OUT

✓

✓

REAR BRACKET COTTER PINS SPREAD

✓

✓

REAR BRACKET WASHERS INSTALLED CORRECTLY

✓

✓

PSA SHOCKER CLAMP INSTALLED

NA

NA

CLAMP LINED IF REQUIRED

NA

NA

CLAMP SHORTENED IF REQUIRED

NA

NA

GRADE 5 BOLT INSTALLED IN PROPER HOLE

NA

NA

LOCK NUT INSTALLED ON GRADE 5 BOLT

NA

NA

1-2 BOLT THREADS EXPOSED BEYOND NUT ON ALL CLAMP BOLTS

NA

NA

ALL CLAMP NUTS TIGHTENED

✓

✓

NEW-STYLE LOCK NUT NOT BACKED OFF OR REMOVED ONCE TIGHTENED

NA

NA

SPACER INSTALLED IN PROPER LOCATION

NA

NA

FORWARD ADAPTER BALL JOINT NOT LOOSE OR PUSHED OUT

✓

✓

WASHERS INSTALLED EACH SIDE OF FORWARD ADAPTER

✓

✓

EXTRA REAR BRACKET WASHERS INSTALLED CORRECTLY

NA

NA

EXTRA REAR BRACKET COTTER PINS SPREAD

NA

NA

SHOCKER NOT DAMAGED INTERNALLY

✓

✓

REAR SHOCKER BOOT INSTALLED

NA

NA

NOTE: IF THERE IS MORE THAN A SMALL AMOUNT OF PLAY WHEN ONE END OF THE SHOCKER IS TWISTED WITH RESPECT TO THE OTHER, THE SHOCKER IS BROKEN INTERNALLY AND MUST BE REPLACED.

*DA HOLD POINT DURING BOOT INSTALLATION ONLY.

TOP INFORMATION ONLY

EL: 115'-0"


AUX. FEEDWATER

L.H. RESTR.


1365L

LOG ON DWG 500021

DESIGN CLASS I
CODE CLASS C
CALLED NORTH



PLAN VIEW



LOCATION PLAN

FIELD RELOCATION TOLERANCE 12" NW 0" SE

NOTE: NOTCH EXISTING STEEL (1/31R) AS REQ'D.

P.P.P. AS BUILT DRAWING

DATE	APP. VERIFIED
9-10-83	JMA

NO OTHER OFFSETS

NO	REQD	MATERIALS PER ASSEMBLY 1
1	2	SMA, SIZE 1, TYPE BA, SHOCK ARRESTOR, 4" STROKE. S-C = 5'-5 5/8", C.S. = 2 1/4", H.S. = 1 1/16", LOAD = 1168# (DELETE)
2	1	T.S. 8 x 4 x 3/8, 2'-0" LG. 11 1/2" LG. ✓
3	4	3/4" φ HILTI SHELL TYPE CONC. ANCHOR ✓
4	2	T.S. 4 x 4 x 1/4, 45" LG. 15 1/8" ✓
5	1	FIG. 1375, U-BOLT, A = 1/2", B = 4 1/2", C = 5", D = 8 3/4", E = 7 1/4" w/(6) HEX NUTS ✓

CONTROLLED COPY

DSGN LMA
DWN C. DELUCA
CHKD JBE

DRAWING NO
049308

PROJECT: DIABLO CANYON

UNIT: ONE

SHT 177 OF SHTS

P G & E CO

ISSUE REV
3

DATE: 8-25-83 INSPECTOR: Jare Ayers

136

LINE NO. 373 SYS: 3 DRWG. NO: 049308 SHT: 177

Top Bottom
 VOP VOP
 ACCEPTABILITY

SWIBBER AXIS WITHIN 10° OF OPTIMUM (NO INTERFERENCE AT REAR BRACKET OR FORWARD ADAPTER)	✓	✓
COLD SETTING WITHIN FIELD TOLERANCE ($\pm 1/4$ ") <u>1 5/16" resp 8/16/83 *</u>	<u>1 5/16</u> <u>8/16/83</u>	<u>1 5/16</u> <u>8/16/83</u>
Transition Tube bolts/cap screws tightened, Torque sealed, and Safety Wired (if applicable) at final inspection	✓	✓
Bolt/cap screw lock washers installed (if applicable)	NA	NA
REAR BALL JOINT NOT LOOSE OR PUSHED OUT	✓	✓
REAR BRACKET COTTER PINS SPREAD	✓	✓
REAR BRACKET WASHERS INSTALLED CORRECTLY	✓	✓
PSA SHUBBER CLAMP INSTALLED	NA	NA
CLAMP LINED IF REQUIRED	NA	NA
CLAMP SHORTENED IF REQUIRED	NA	NA
GRADE 5 BOLT INSTALLED IN PROPER HOLE	NA	NA
LOCK NUT INSTALLED ON GRADE 5 BOLT	NA	NA
1-2 BOLT THREADS EXPOSED BEYOND NUT ON ALL CLAMP BOLTS	NA	NA
ALL CLAMP NUTS TIGHTENED	✓	✓
NEW-STYLE LOCK NUT NOT BACKED OFF OR REMOVED ONCE TIGHTENED	NA	NA
SPACER INSTALLED IN PROPER LOCATION	NA	NA
FORWARD ADAPTER BALL JOINT NOT LOOSE OR PUSHED OUT	✓	✓
WASHERS INSTALLED EACH SIDE OF FORWARD ADAPTER	✓	✓
EXTRA REAR BRACKET WASHERS INSTALLED CORRECTLY	<u>NA</u>	<u>NA</u>
EXTRA REAR BRACKET COTTER PINS SPREAD	<u>NA</u>	<u>NA</u>
SHUBBER NOT DAMAGED INTERNALLY	✓	✓
PROTECTIVE BOOT INSTALLED	NA	NA

NOTE: IF THERE IS MORE THAN A SMALL AMOUNT OF PLAY WHEN ONE END OF THE SHUBBER IS TWISTED WITH RESPECT TO THE OTHER, THE SHUBBER IS BROKEN INTERNALLY AND MUST BE REPLACED.

*DA HOLD POINT DURING BOOT INSTALLATION ONLY.



AREA: G.W
EL: 100'-0"

LINE: 1-K14-207-20 II
M.S. LEAD = 2

X-RESTRAINT
LOC ON DWG: 50016

9/8/83 501700 1st COAT 9483
Primed

DESIGN CLASS I
CODE CLASS E
CALLED NORTH



EXIST. W 14x426
SEE DWG 1000110SH.7

LOCATION PLAN
ON OTHER SIDE OF WALL

P.P.P. AS BUILT DRAWING

DATE	VERIFIED
6-24-83	SA

ELEV. VIEW X-X

NO. OF ASSEMBLIES REQUIRED: 1

NO	REQD	MATERIALS PER ASSEMBLY
1	2	NF FIG C-201 S & S SUPPRESSOR 4" CYL X 10" S LESS PIPE CLAMP W/ ADDITIONAL REAR BRACKET W/ RESERVOIR, W = 3'-2 1/2" TOP CPS = 5' 1/16" HPS = 6' 2 3/4" BOTTOM CPS = 5' 2 3/32"
2	2	R 1" X 5 1/2" X 7"

289

DSGN	DWG	DRAWING NO
CHKD	SA	049182
DATE	BY	PG & F CD

DIAELO

AREA: GW


LINE 1-K16-2479-24
SYS 03 FS
STM GEN 1+2 FEED LEAD

Y RESTRAIN
LOC ON DWG 500164 100-


EL 112'-6"

DESIGN CLASS I
CODE CLASS E

CALLED NORTH



LOCATION PLAN



DETAIL B

~~FIELD SUPPOR RELOCATION TOLERANCES 0'-0" NORTH 0'-0" SOUTH~~

NO OF ASSEMBLIES REQUIRED

MATERIALS PER ASSEMBLY

NO	REQ'D	MATERIALS PER ASSEMBLY
1	1	PSA 25 (NF) MECHANICAL SNUBBER STROKE-6"
2	1	3/2" W/ 24" PIPE CLAMP
3	1	EXTENSION PIPE 4" φ SCH. XX5 (LENGTH BY FIELD)
4	1	T.S. 8" x 8" x 1/2", 3'-0" LG. W/ 1/4" φ VENT HOLE (CUT TO SUIT)
5	1	T.S. 8" x 4" x 3/8", 4'-0" LG. W/ 1/4" φ VENT HOLE (CUT TO SUIT)
6	2	1" x 23 1/2" x 1" 11 1/2" LG. (SEE DETAIL B)
7	1	1" φ HILTI-KWIK BOLT 9" LG. (STUD TYPE) W/ NUT
8	1	R 1/4" x 9" x 0'-9" LG.
9	1	FISH R 1" x 2 1/2" x 0'-2 1/2" LG.
10	1	AD-5501 MECH. SNUBBER (SER # 6B), W/ AD-5505 R
11	1	AD-5506 TRANS. TUBE KIT & NPS 3PC-24-240 PIPE
12	1	CLAMP C.S. 2 1/2" H.S. 3"
13	1	T.S. 8" x 8" x 1/2", 3'-0" LG. W/ 1/4" φ VENT HOLE
14	1	T.S. 8" x 4" x 3/8", 4'-0" LG. W/ 1/4" φ VENT HOLE (CUT AS SHD)
15	2	(5A) (1) R 1" x 23 1/2" x 25 1/2" LG.
		(5B) (1) R 1" x 25" x 33 1/2" LG.

CONTROLLED COP

P.P.P. AS BUILT DRAWING

DATE	VERIFIED
7-20-83	<i>[Signature]</i>

WESTINGHOUSE NUCLEAR ENERGY SYSTEMS
PITTSBURGH PA.

DSSN
DWN T.C.M
CHKD J.P.T.

DRAWING NO
049198

PROJECT: DIABLO CANYON

UNIT: ONE

SHT 45 OF 81TS

PG & E CO

MICRO

AREA

GE

JO-GA-1

LINE

J-SS-3848-7111

LOC ON DWG

50056


EL 100'-0"

NOS WASTE FILTER O-2 DRAIN


DESIGN CLASS I
CODE CLASS B

CALLED NORTH


INACCESSIBLE WELD.



VIEW "B-B"



VIEW "C-C"



LOCATION PLAN

NO OF ASSEMBLIES REQUIRED I

MATERIALS PER ASSEMBLY

NO	RECD	MATERIALS PER ASSEMBLY
1	1	FE 1/2" x 9" x 11"
2	1	4WF 13, 43 3/4" LG. CUT AS SHOWN
3	1	6WF 20, 69 1/4" LG.
4	1	PSA-1/2 PRE-NF TYPE, 3/16" RET STROKE CS=1 1/8" H.S
5	1	W / PRE-NF REAR BRACKET. SER #176
6	1	4" O WESTERN NON-SHORTENED PIPE CLAMP.
		3/4" SCH. 40 PIPE 3 1/4" MITG. LENGTH BY F:4D

DSGN
DWN MAX-T
CHKD

DRAWING NO
SK-15-16SL

SHT 25 OF

SHTS

PG & E CO

UNIT: ONE

EST. DIABLO CANYON

P.P.P. AS BUILT DRAWING

PPP

7-25-83

RECEIVING OFFICE

1. Facility(ies) Involved:
(If more than 3, or if generic, write GENERIC)

(Name) Diablo Canyon 1/2

Docket Number (if applicable)					
0	5	0	0	0	2
0	5	0	0	0	2

2. Functional Area(s) Involved:
(Check appropriate box(es))

<input type="checkbox"/>	operations	<input type="checkbox"/>	onsite health and safety
<input checked="" type="checkbox"/>	construction	<input type="checkbox"/>	offsite health and safety
<input type="checkbox"/>	safeguards	<input type="checkbox"/>	emergency preparedness
<input type="checkbox"/>	other (Specify) _____		

3. Description:
(Limit to 100 characters)

F	e	l	e	y	a	n	d	P	u	l	l	i	m	a	n	l	o	s	t	
t	r	a	c	e	a	b	i	l	i	t	y	a	n	p	i	p	e	d	i	t
t	f	o	l	l	o	w	p	r	o	c	e	d	u	r	e	s				
N	u	m	b	e	r	s	1	6	8	1	6	9	a	n	d	1	7	9		

4. Source of Allegation:
(Check appropriate box)

<input type="checkbox"/>	contractor employee	<input type="checkbox"/>	security guard
<input type="checkbox"/>	licensee employee	<input type="checkbox"/>	news media
<input type="checkbox"/>	NRC employee	<input type="checkbox"/>	private citizen
<input type="checkbox"/>	organization (Specify) _____		
<input checked="" type="checkbox"/>	other (Specify) <u>Confidential</u>		

5. Date Allegation Received:

MM	DD	YY
01	-	-
8	4	

6. Name of Individual Receiving Allegation:

(First two initials and last name) _____

7. Office:

		R	V
--	--	---	---

ACTION OFFICE

8. Action Office Contact:

(First two initials and last name) H.L. Canter

9. FTS Telephone Number:

4	6	3	-	3	7	1	9
---	---	---	---	---	---	---	---

10. Status:
(Check one)

<input type="checkbox"/>	Open, if followup actions are pending or in progress
<input type="checkbox"/>	Closed, if followup actions are completed

11. Date Closed:

MM	DD	YY

11.1 Document Nos. _____

12. Remarks:
(Limit to 50 characters)

12.1 Man-hours/Date
13. Allegation Number:

Office	Year	Number
R	V	-
8	4	-
A	-	0
0	0	2
2		

Task: Allegation or Concern No. 168

FILE COPY

ATS No.: RV-84-A-0022

BN No.:

See allegation #123

Characterization

Foley did not properly grout base plate anchor bolts.

Implied Significance to Plant Design, Construction, or Operation

The staff's face value assessment is that this concern is of minimal safety significance and even if true would not seriously degrade the operability of the diesel fuel oil transfer system.

Assessment of Safety Significance

The allegor specifically referred to support No. 20/85R in the diesel generator fuel oil vault of Unit 1. Specifically, the allegor referred to an instance where a U-Bolt hole had been drilled through a weld attaching a shim plate to the support. Also, he stated that one of four anchor bolts in a baseplate had allegedly been improperly grouted, as evidenced by an excessively large amount of grout which had leaked out of the grout cap onto the surrounding floor area. Thus, the allegor concluded that the anchor bolt hole was not properly filled with grout. The allegor states that the first condition was wrongly accepted by field engineering and that Foley improperly accepted the anchor bolt grouting.

The staff considers that extensive evaluation of this concern is not likely to result in any significant new management or quality performance issues.

Action Required

This item will be turned over to PG&E for evaluation and ~~resolution~~. The licensee will be required to provide the results of their evaluations, and any necessary corrective actions, to the staff in writing.

response

FAX to H. Schierling
Phillips Bldg. @1344
3-15-84

Task: Allegation or Concern No. 169

FILE COPY

ATS No.: RV-84-A-0022

BN No.:

Characterization

Pullman failed to conduct support welds as required by procedures.

Assessment of Safety Significance

The allegor stated that two W14X90 wide flange beams were welded together on support Nos. 2/45R and 2/49R (on the diesel generator exhaust system) by use of an unqualified welding technique. Specifically, the allegor stated that Pullman welding procedure specification (WPS) 7/8 was used to join the steel shapes without the use of the procedure required backing bar; in place of which a back-gouging was performed, contrary to the qualified technique. The allegor further stated that the Pullman QA/QC Manager wrongly approved the technique utilized.

Staff Position

Because welding related allegations had been extensively examined by the staff, an exhaustive examination of these two specifics would in the staffs opinion, add little to the management or quality performance issue.

Action Required

This item will be turned over to PG&E for evaluation and ^{response} ~~resolution~~. The licensee will be required to provide the results of their evaluation, and any necessary corrective actions, to the staff in writing. ||

FAX TO H. Schierling.
Phillips Bldg.
1344
3-15-84 ✓

292
~~292~~

sent to PGFE

Allegation or Concern No. 170

Characterization

Pullman may have lost pipe traceability due to inadequate training of Fab Shop Inspectors.

It was alleged that a Pullman shop inspector was given an assignment and didn't know that copies of the Field Warehouse Requisition (FWR) form were to be routed to QA, and it was his perception that FWR's were being reconstructed by field inspection to verify material traceability.

Task: Allegation or Concern No.170

FILE COPY

ATS No: RV84A022

BN No:

Characterization

Pullman lost pipe traceability due to inadequate training of fab shop inspectors.

Implied Significance to Plant Design, Construction, or Operation

Assessment of Safety Significance

Staff Position

Sensitive

Action Required

Problem Statement

Allegation #(s): 171-177

ATS No.(s): RV-84-0007

BY(s):

This document lists (or directly references) each allegation or concern brought to the attention of NRC personnel. The purpose of this statement sheet is to assure that all points raised by the allegor are covered.

If the problem statement is not clear as to who, what, where, when, or why regarding the issue, the commentary section will amplify the statement. The commentary section will also be used if there is apparent conflicting information or if there is no or very little original information available which describes the concern(s). (This can occur if, for example, a line concern was received in an interview).

Problem Statements (use extra sheets as necessary)

Allegation#

Verbatim Statement or Reference

#171 through #177

SEE ATTACHED SHEET

Commentary

Date This Statement was Completed

2-16-84

W. Carter

Technical Reviewer Signature

RECEIVING OFFICE

1. Facility(ies) involved:
(If more than 3, or if generic, write GENERIC)

(Name) Diable Canyon units 1&2

Docket Number (if applicable)

0	5	0	0	0	2	7	5
0	5	0	0	0	3	2	3

2. Functional Area(s) Involved:
(Check appropriate boxes)

<input type="checkbox"/>	operations	<input type="checkbox"/>	onsite health and safety
<input checked="" type="checkbox"/>	construction	<input type="checkbox"/>	offsite health and safety
<input type="checkbox"/>	safeguards	<input type="checkbox"/>	emergency preparedness
<input type="checkbox"/>	other (Specify) _____		

3. Description:
(Limit to 100 characters)

INadequate AND Improper @
onstruction practices inv
olving electric cables, AN
char bolts, RHR pumps

4. Source of Allegation:
(Check appropriate box)

<input type="checkbox"/>	contractor employee	<input type="checkbox"/>	security guard
<input type="checkbox"/>	licensee employee	<input type="checkbox"/>	news media
<input type="checkbox"/>	NRC employee	<input type="checkbox"/>	private citizen
<input type="checkbox"/>	organization (Specify) _____		
<input checked="" type="checkbox"/>	other (Specify) <u>unnamed person</u>		

5. Date Allegation Received:

MM	DD	YY
0	1	2784

Copy of
Ltr to Ben Hayes from J.C. Ebersole
Chairman ACRS to D.B. Martin

6. Name of Individual Receiving Allegation:

(First two initials and last name)

7. Office:

		R	V
--	--	---	---

ACTION OFFICE

8. Action Office Contact:

(First two initials and last name) D. Kirsch

9. FTS Telephone Number:

4	6	3	-	3	7	2	3
---	---	---	---	---	---	---	---

10. Status:
(Check one)

<input checked="" type="checkbox"/>	Open, if followup actions are pending or in progress
<input type="checkbox"/>	Closed, if followup actions are completed

11. Date Closed:

MM	DD	YY

11.1 Document Nos. _____

12. Remarks:
(Limit to 50 characters)

12.1 Man-hours/Date
13. Allegation Number:

Office	Year	Number
R	V	-84-A-
		0007

Task: Allegation or Concern No. 176

ATS No: RV-84-A-007

BN No:

Characterization

Anchor Bolts (torquing of "Red-Head Bolts).

Implied Significance to Plant Design, Construction, or Operation

See Task Allegation or Concern No. 25

Assessment of Safety Significance

See Task Allegation or Concern No. 25

Staff Position

See Task Allegation or Concern No. 25

Action Required

See Task Allegation or Concern No. 25

304
~~304~~

PROBLEM STATEMENT

Allegation No(s): 176

ATS No(s):

BN(s):

This document lists (or directly references) each allegation or concern brought to the attention of NRC personnel. The purpose of this statement sheet is to assure that ALL points raised by the allegor are covered.

If the problem statement is not clear as to who, what, where, when, of why regarding the issue, the commentary section will amplify the statement. The commentary section will also be used if there is apparent conflicting information or if there is NO or very little original information available which describes the concern(s). (This can occur if, for example, a one line concern was received in an interview).

PROBLEM STATEMENTS (use extra sheets as necessary)

ALLEGATION #	VERBATIM STATEMENT OR REFERENCE
176	Staff characterization statement: Deficiencies in concrete anchor bolt installations. This allegation is a direct reference to allegation No. 58, transmitted to the NRC by Dr. Henry Myers and documented in a 1/23/84 memorandum from J.C. Ebersole to B.B. Hayes.

COMMENTARY
See allegation No. 58 files.

Date This Statement was Completed 3/09/84

D. Haist

Technical Reviewer
Signature

305
~~22~~