

TENNESSEE VALLEY AUTHORITY
DIVISION OF NUCLEAR POWER
SEQUOYAH NUCLEAR PLANT

MONTHLY OPERATING REPORT
TO THE
NUCLEAR REGULATORY COMMISSION
December 1, 1985 - December 31, 1985

UNIT 1

DOCKET NUMBER 50-327
LICENSE NUMBER DPR-77

UNIT 2

DOCKET NUMBER 50-328
LICENSE NUMBER DPR-79

Submitted by:

P. R. Wallace

P. R. Wallace, Plant Manager

8604020144 851231
PDR ADOCK 05000327
R PDR

DE 24
111

TABLE OF CONTENTS

I. Operational Summary	<u>Page</u>
Performance Summary	1
Significant Operational Events	1
Fuel Performance and Spent Fuel Storage Capabilities	2
PORVs and Safety Valves Summary	2
Licensee Events and Special Reports	2-3
Offsite Dose Calculation Manual Changes	3
II. Operating Statistics	
A. NRC Reports	
Operating Data Reports	4-5
Unit Shutdowns and Power Reductions	6-7
Average Daily Unit Power Level	8-9
B. TVA Reports	
Nuclear Plant Operating Statistics (December 1985)	10
Unit Outage and Availability	11-12
Reactor Histograms	13
III. Maintenance Summary	
Electrical Maintenance	14-15
Instrument Maintenance	16-23
Mechanical Maintenance	24-26
Modifications	27-35
IV. Quarterly Schedule Summary	36-38

Operations Summary

December 1985

The following summary describes the significant operational activities for the month of December. In support of this summary, a chronological log of significant events is included in this report.

Unit 1

Unit one, cycle three refueling/modification outage ended at 2400c, December 19, 1985. The unit remained in an administrative shutdown due to documentation concerns relating to the environmental qualifications of various electrical equipment (NUREG 0588). Maintenance and other modifications remain in progress. The present schedule for synchronization of unit one is February 10, 1986. Actual start-up is dependent upon NRC review of the Sequoyah Start-up Readiness Plan and the resolution of significant employee concerns. The unit has been off-line 131 days.

Unit 2

The unit remained in the administrative shutdown the entire month due to documentation concerns relating to the environmental qualification of various electrical equipment (NUREG 0588). Outage related maintenance and modifications are being performed. The present schedule has the unit prepared to return to service on February 2, 1986. Actual start-up is dependent upon NRC review of the Sequoyah Startup Readiness Plan and the resolution of significant employee concerns. The unit has been off-line 132 days.

Significant Operational Events

Unit 1

<u>Date</u>	<u>Time</u>	<u>Event</u>
12/1/85	0001C	Cycle 3 refueling/modification outage continued. The reactor was in mode #5.
12/19/85	2400C	All refueling outage activities were completed. The unit entered a forced administrative outage due to documentation concerns relating to NUREG 0588 equipment.
12/31/85	2400C	The reactor was in mode #5. The administrative shutdown due to NUREG 0588 concerns continues.

Unit 2

<u>Date</u>	<u>Time</u>	<u>Event</u>
12/1/85	0001C	The reactor was in mode #5. The administrative shutdown due to NUREG 0588 concerns continues.
12/31/85	2400C	The reactor was in mode #5. The administrative shutdown due to NUREG 0588 concerns continues.

Fuel Performance

Unit 1

The core average fuel exposure accumulated during December was 0.00 MWD/MTU.

Unit 2

The core average fuel exposure accumulated with the total accumulated during December was 0.00 MWD/MTU with the total accumulated core average exposure of 8097.51 MWD/MTU.

Spent Fuel Pit Storage Capabilities

The total storage capability in the spent fuel pit (SFP) is 1,386. However, there are five cell locations which are incapable of storing spent fuel. Four locations (A10, A11, A24, A25,) are unavailable due to a suction strainer conflict and one location (A16) is unavailable due to an instrumentation conflict. Presently, there are a total of 348 spent fuel bundles stored in the SFP. Thus, the remaining storage capacity is 1,033.

PORVs and Safety Valves Summary

No PORVs or safety valves were challenged in December 1985.

Licensee Events and Special Reports

The following licensee event report (LER) was reported to the Nuclear Regulatory Commission in December 1985.

LER

DESCRIPTION OF EVENT

1-85046

On November 14, 1985, at 1305 CST, with unit 1 in mode 6, a deluge valve, 1-FCV-26-231, on high pressure fire protection (HPFP) inadvertently opened and charged the fire hose stations in unit containment annulus and the area around the reactor coolant pumps (RCPs). After investigation, the valve was manually isolated and the Unit Operator (UO), after reviewing the HPFP drawings, determined that only the hose stations around the RCPs were being isolated. In actuality, the annulus hose stations are supplied by this header also and therefore, they were isolated. Since the annulus contains equipment that was required operable, a failure to comply with action (a) of Technical Specification LCO 3.7.11.4 occurred in that backup hoses were not run (required within 24 hours). This condition remained until its discovery on November 18, 1985, at approximately 1345 CST, during the performance of a HPFP surveillance on valve positions. At that time, the header and associated hose stations were returned to service.

1-85047

Technical Specification 6.12.2 requires access to high radiation areas be controlled by locks with keys administratively controlled by the shift engineer and/or health physics. On December 15, 1985, it was discovered that several employees may have had keys to locks for six high or potentially high radiation areas.

LER

DESCRIPTION OF EVENT (cont.)

1-85048

An NRC inspection team on December 6, 1985, identified that the maintenance program guidelines (SQM-2 and SQM-57) were required to be PORC reviewed and failure to do so was a violation of the technical specification 6.8.2.

Special Reports

There were no special reports for the month of December 1985.

Offsite Dose Calculation Manual Changes

No changes were made to the Sequoyah Offsite Dose Calculation Manual during the month.

OPERATING DATA REPORT

DOCKET NO. 50-327
DATE JANUARY 6, 1986
COMPLETED BY D.C. DUPREE
TELEPHONE (615) 870-6544

OPERATING STATUS

1. UNIT NAME: SEQUOYAH NUCLEAR PLANT, UNIT 1
2. REPORT PERIOD: DECEMBER 1985
3. LICENSED THERMAL POWER(MWT): 3411.0
4. NAMEPLATE RATING (GROSS MWE): 1220.6
5. DESIGN ELECTRICAL RATING (NET MWE): 1148.0
6. MAXIMUM DEPENDABLE CAPACITY (GROSS MWE): 1183.0
7. MAXIMUM DEPENDABLE CAPACITY (NET MWE): 1148.0
8. IF CHANGES OCCUR IN CAPACITY RATINGS (ITEMS NUMBERS 3 THROUGH 7) SINCE LAST REPORT, GIVE REASONS: _____

NOTE:

9. POWER LEVEL TO WHICH RESTRICTED, IF ANY (NET MWE): _____
10. REASONS FOR RESTRICTIONS, IF ANY: _____

THIS MONTH YR.-TO-DATE CUMULATIVE

11. HOURS IN REPORTING PERIOD	744.00	8760.00	39481.00
12. NUMBER OF HOURS REACTOR WAS CRITICAL	0.00	3797.25	24444.91
13. REACTOR RESERVE SHUTDOWN HOURS	0.00	0.00	0.00
14. HOURS GENERATOR ON-LINE	0.00	3762.18	23871.13
15. UNIT RESERVE SHUTDOWN HOURS	0.00	0.00	0.00
16. GROSS THERMAL ENERGY GENERATED (MWH)	0.00	1238385.96	77060971.91
17. GROSS ELECTRICAL ENERGY GEN. (MWH)	0.00	4239570.00	25976336.00
18. NET ELECTRICAL ENERGY GENERATED (MWH)	196.00	4061107.00	24942737.00
19. UNIT SERVICE FACTOR	0.00	42.95	60.46
20. UNIT AVAILABILITY FACTOR	0.00	42.95	60.46
21. UNIT CAPACITY FACTOR (USING MDC NET)	0.00	40.38	55.03
22. UNIT CAPACITY FACTOR (USING DER NET)	0.00	40.38	55.03
23. UNIT FORCED OUTAGE RATE	38.71	17.89	16.27
24. SHUTDOWNS SCHEDULED OVER NEXT 6 MONTHS (TYPE, DATE, AND DURATION OF EACH):			

25. IF SHUTDOWN AT END OF REPORT PERIOD, ESTIMATED DATE OF STARTUP: FEBRUARY 10, 1986, PENDING N.R.C. REVIEW OF SEQUOYAH NUCLEAR PLANT STARTUP READINESS PLAN.

NOTE THAT THE THE YR.-TO-DATE AND CUMULATIVE VALUES HAVE BEEN UPDATED.

OPERATING DATA REPORT

DOCKET NO. 50-328
DATE JANUARY 6, 1986
COMPLETED BY D.C. DUPREE
TELEPHONE (615) 870-6544

OPERATING STATUS

1. UNIT NAME: SEQUOYAH NUCLEAR PLANT, UNIT 2
2. REPORT PERIOD: DECEMBER 1985
3. LICENSED THERMAL POWER(MWT): 3411.0
4. NAMEPLATE RATING (GROSS MWE): 1220.6
5. DESIGN ELECTRICAL RATING (NET MWE): 1148.0
6. MAXIMUM DEPENDABLE CAPACITY (GROSS MWE): 1183.0
7. MAXIMUM DEPENDABLE CAPACITY (NET MWE): 1148.0
8. IF CHANGES OCCUR IN CAPACITY RATINGS (ITEMS NUMBERS 3 THROUGH 7) SINCE LAST REPORT, GIVE REASONS: _____

9. POWER LEVEL TO WHICH RESTRICTED, IF ANY (NET MWE): _____

10. REASONS FOR RESTRICTIONS, IF ANY: _____

NOTES:

	THIS MONTH	YR.-TO-DATE	CUMULATIVE
--	------------	-------------	------------

11. HOURS IN REPORTING PERIOD	744.00	8760.00	31441.00
12. NUMBER OF HOURS REACTOR WAS CRITICAL	0.00	5289.42	21984.54
13. REACTOR RESERVE SHUTDOWN HOURS	0.00	0.00	0.00
14. HOURS GENERATOR ON-LINE	0.00	5224.24	21494.42
15. UNIT RESERVE SHUTDOWN HOURS	0.00	0.00	0.00
16. GROSS THERMAL ENERGY GENERATED (MWH)	0.00	17128966.35	69127977.22
17. GROSS ELECTRICAL ENERGY GEN. (MWH)	0.00	5845100.00	23536780.00
18. NET ELECTRICAL ENERGY GENERATED (MWH)	-4096.00	5610949.00	22631957.60
19. UNIT SERVICE FACTOR	0.00	59.64	68.36
20. UNIT AVAILABILITY FACTOR	0.00	59.64	68.36
21. UNIT CAPACITY FACTOR (USING MDC NET)	0.00	55.79	62.70
22. UNIT CAPACITY FACTOR (USING DER NET)	0.00	55.79	62.70
23. UNIT FORCED OUTAGE RATE	100.00	40.32	19.05
24. SHUTDOWNS SCHEDULED OVER NEXT 6 MONTHS (TYPE, DATE, AND DURATION OF EACH):			

25. IF SHUTDOWN AT END OF REPORT PERIOD, ESTIMATED DATE OF STARTUP:
FEBRUARY 02, 1986, PENDING N.R.C. REVIEW OF SEQUOYAH NUCLEAR PLANT STARTUP
READINESS PLAN.

NOTE THAT THE THE YR.-TO-DATE AND
CUMULATIVE VALUES HAVE BEEN UPDATED.

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-327

UNIT NAME SEQUOYAH ONE

DATE JANUARY 2, 1986

COMPLETED BY D. C. DUPREE

TELEPHONE (615)870-6544

REPORT MONTH DECEMBER 1985

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
6	850822	S	456	C	4				Refueling/Modification Outage
7	851220	F	288	F	9				NUREG 0588 Documentation Concerns

¹F: Forced
S: Scheduled

²Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F-Administrative
G-Operational Error (Explain)
H-Other (Explain)

³Method:
1-Manual
2-Manual Scram.
3-Automatic Scram.
4-Cont. of Existing
Outage
5-Reduction
9-Other

⁴Exhibit G-Instructions
for Preparation of Data
Entry Sheets for Licensee
Event Report (LER) File
(NUREG-0161)

⁵Exhibit I-Same Source

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH DECEMBER 1985

DOCKET NO. 50-328
 UNIT NAME SEQUOIA TWO
 DATE JANUARY 2, 1986
 COMPLETED BY D. C. DUPREE
 TELEPHONE (615)870-6544

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
9	850821	F	744	F	4				NUREG 0588 Documentation Concerns

¹F: Forced
 S: Scheduled

²Reason:
 A-Equipment Failure (Explain)
 B-Maintenance or Test
 C-Refueling
 D-Regulatory Restriction
 E-Operator Training & License Examination
 F-Administrative
 G-Operational Error (Explain)
 H-Other (Explain)

³Method:
 1-Manual
 2-Manual Scram.
 3-Automatic Scram.
 4-Cont. of Existing
 Outage
 5-Reduction
 9-Other

⁴Exhibit G-Instructions
 for Preparation of Data
 Entry Sheets for Licensee
 Event Report (LER) File
 (NUREG-0161)

⁵Exhibit I-Same Source

SEQUOYAH NUCLEAR PLANT
AVERAGE DAILY POWER LEVEL

DOCKET NO. : 50-327

UNIT : ONE

DATE : JANUARY 6, 1986

COMPLETED BY : D. C. DUPREE

TELEPHONE : (615) 870-6944

10TH DECEMBER 1985

DAY	AVERAGE DAILY POWER LEVEL (MWe Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe Net)
01	0	17	0
02	0	18	0
03	0	19	0
04	0	20	0
05	0	21	0
06	0	22	0
07	0	23	0
08	0	24	0
09	0	25	0
10	0	26	0
11	0	27	0
12	0	28	0
13	0	29	0
14	0	30	0
15	0	31	0
16	0		

SEQUOYAH NUCLEAR PLANT
AVERAGE DAILY POWER LEVEL

DOCKET NO. : 50-328

UNIT : TWO

DATE : JANUARY 6, 1986

COMPLETED BY : D. C. DUPREE

TELEPHONE : (615) 870-6544

MONTH DECEMBER 1985

DAY	AVERAGE DAILY POWER LEVEL (MWe Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe Net)
01	0	17	0
02	0	18	0
03	0	19	0
04	0	20	0
05	0	21	0
06	0	22	0
07	0	23	0
08	0	24	0
09	0	25	0
10	0	26	0
11	0	27	0
12	0	28	0
13	0	29	0
14	0	30	0
15	0	31	0
16	0		

NUCLEAR PLANT OPERATING STATISTICS

SEQUOYAH NUCLEAR

Plant

Period Hours 744

Month DECEMBER 19 85

Item No.	Unit No.	UNIT ONE	UNIT TWO	PLANT
1	Average Hourly Gross Load, kW	0	0	0
2	Maximum Hour Net Generation, MWh	0	0	0
3	Core Thermal Energy Gen, GWD (t) ²	0	0	0
4	Steam Gen. Thermal Energy Gen., GWD (t) ²	0	0	0
5	Gross Electrical Gen., MWh	0	0	0
6	Station Use, MWh	196	4069	4265
7	Net Electrical Gen., MWh	-196	-4069	-4265
8	Station Use, Percent	N/A	N/A	N/A
9	Accum. Core Avg. Exposure, MWD/Ton ¹	0	8098	8098
10	CTEG This Month, 10 ⁶ BTU	0	0	0
11	SGTEG This Month, 10 ⁶ BTU	0	0	0
12				
13	Hours Reactor Was Critical	0.0	0.0	0.0
14	Unit Use, Hours-Min.	0:00	0:00	0:00
15	Capacity Factor, Percent	0.0	0.0	0.0
16	Turbine Avail. Factor, Percent	0.0	0.0	0.0
17	Generator Avail. Factor, Percent	0.0	0.0	0.0
18	Turbogen. Avail. Factor, Percent	0.0	0.0	0.0
19	Reactor Avail. Factor, Percent	0.0	0.0	0.0
20	Unit Avail. Factor, Percent	0.0	0.0	0.0
21	Turbine Startups	0	0	0
22	Reactor Cold Startups	0	0	0
23				
24	Gross Heat Rate, Btu/kWh	N/A	N/A	N/A
25	Net Heat Rate, Btu/kWh	N/A	N/A	N/A
26				
27				
28	Throttle Pressure, psig	N/A	N/A	N/A
29	Throttle Temperature, °F	N/A	N/A	N/A
30	Exhaust Pressure, InHg Abs.	N/A	N/A	N/A
31	Intake Water Temp., °F	N/A	N/A	N/A
32				
33	Main Feedwater, M lb/hr	N/A	N/A	N/A
34				
35				
36				
37	Full Power Capacity, EFPD	404.86*	363.65	768.51
38	Accum. Cycle Full Power Day, EFPD	0.0	210.8416	210.8416
39	Oil Fired for Generation, Gallons			2,244
40	Oil Heating Value, Btu/Gal.			138,000
41	Diesel Generation, MWh			34
42				
43	Max. Hour Net Gen.	Max. Day Net Gen.	Load Factor, %	
	MWh Time Date	MWh Date		
	N/A N/A N/A	N/A N/A	N/A	

Remarks: ¹For BFNP this value is MWD/STU and for SQNP and WBNP this value is MWD/MTU.
²(t) indicates Thermal Energy.
 *Approximately

Date Submitted

Date Revised

P.R. Wallace
 Plant Superintendent

UNIT OUTAGE AND AVAILABILITY

SEQUOYAH

Nuclear Plant

Licensed Reactor Power 3411 MW(th)

Unit No. ONE

Generator Rating 1220.5 MW(e)

Month/Year DECEMBER 1985

Design Gross Electrical Rating 1183 MW

Period Hours 744

		Time Unit Available						Time Not Available								Unit				OUTAGE CAUSE	METHOD OF SHUTTING DOWN REACTOR	UNIT STATUS DURING OUTAGE	CORRECTIVE ACTION TAKEN TO PREVENT REPETITION
Day	Total		Gen.		Not Used		Turbine		Gen.		Reactor		Unit		Time Out		Time In						
	Hrs	Min	Hrs	Min	Hrs	Min	Hrs	Min	Hrs	Min	Hrs	Min	Hrs	Min	Hrs	Min	Hrs	Min					
1	00	00	00	00			24	00	24	00	24	00	24	00					Refueling Outage Continues	N/A	Mode #5		
2	00	00	00	00			24	00	24	00	24	00	24	00									
3	00	00	00	00			24	00	24	00	24	00	24	00									
4	00	00	00	00			24	00	24	00	24	00	24	00									
5	00	00	00	00			24	00	24	00	24	00	24	00									
6	00	00	00	00			24	00	24	00	24	00	24	00									
7	00	00	00	00			24	00	24	00	24	00	24	00									
8	00	00	00	00			24	00	24	00	24	00	24	00									
9	00	00	00	00			24	00	24	00	24	00	24	00									
10	00	00	00	00			24	00	24	00	24	00	24	00									
11	00	00	00	00			24	00	24	00	24	00	24	00									
12	00	00	00	00			24	00	24	00	24	00	24	00									
13	00	00	00	00			24	00	24	00	24	00	24	00									
14	00	00	00	00			24	00	24	00	24	00	24	00									
15	00	00	00	00			24	00	24	00	24	00	24	00									
16	00	00	00	00			24	00	24	00	24	00	24	00									
17	00	00	00	00			24	00	24	00	24	00	24	00									
18	00	00	00	00			24	00	24	00	24	00	24	00									
19	00	00	00	00			24	00	24	00	24	00	24	00									
20	00	00	00	00			24	00	24	00	24	00	24	00				Refueling Outage ends @2400C	N/A	Mode #5			
21	00	00	00	00			24	00	24	00	24	00	24	00				NUREG 0588 Outage begins @ 0001C	N/A	Mode #5			
22	00	00	00	00			24	00	24	00	24	00	24	00									
23	00	00	00	00			24	00	24	00	24	00	24	00									
24	00	00	00	00			24	00	24	00	24	00	24	00									
25	00	00	00	00			24	00	24	00	24	00	24	00									
26	00	00	00	00			24	00	24	00	24	00	24	00									
27	00	00	00	00			24	00	24	00	24	00	24	00									
28	00	00	00	00			24	00	24	00	24	00	24	00									
29	00	00	00	00			24	00	24	00	24	00	24	00									
30	00	00	00	00			24	00	24	00	24	00	24	00									
31	00	00	00	00			24	00	24	00	24	00	24	00									
Total	00	00	00	00			744	00	744	00	744	00	744	00									

UNIT OUTAGE AND AVAILABILITY

SEQUOYAH Nuclear Plant

Licensed Reactor Power 3411 MW(th)

Generator Rating 1220.5 MW(e)

Design Gross Electrical Rating 1183 MW


Month/Year DECEMBER 1985

Period Hours 744


Unit No. TWO

Day	Time Unit Available						Time Not Available						Unit						OUTAGE CAUSE	METHOD OF SHUTTING DOWN REACTOR	UNIT STATUS DURING OUTAGE	CORRECTIVE ACTION TAKEN TO PREVENT REPETITION			
	Total			Gen.			Not Used			Turbine			Gen.			Reactor							Unit		
	Hrs	Min	Sec	Hrs	Min	Sec	Hrs	Min	Sec	Hrs	Min	Sec	Hrs	Min	Sec	Hrs	Min	Sec					Hrs	Min	Sec
1	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	NUREG 0588 Outage Continues	N/A	Mode #5	
2	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
3	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
4	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
5	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
6	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
7	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
8	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
9	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
10	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
11	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
12	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
13	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
14	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
15	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
16	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
17	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
18	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
19	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
20	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
21	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
22	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
23	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
24	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
25	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
26	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
27	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
28	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
29	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
30	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
31	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				
Total	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00	00				

SEQUOYAH ONE REACTOR HISTOGRAM



SEQUOYAH TWO REACTOR HISTOGRAM



DATE....	COMPONENT.....	FAILURE DESCRIPTION.....	CAUSE OF FAILURE.....	CORRECTIVE ACTION.....	MP.NO..
11-05-85	1-CRN-079-JN /VE1	MANIPULATOR CRANE WOULD NOT MOVE	LR1 RESISTOR AND A500FP PRINTED CIRCUIT BOARD WAS DEFECTIVE	REPLACED LR1 RESISTOR AND A500FP PRINTED CIRCUIT BOARD	A546239
11-12-85	2-GENB-082-000 2A-A	2A-A DIESEL GENERATOR TRIPPED ON DIFFERENTIAL RELAY #87	CABLES WINDINGS AND BOLTS WERE DEFECTIVE	MEGGERED, BRIDGED AND HIPOTED 6.9KV CABLES AND RETORQUED BOLTS	A528112
11-15-85	2-MVOP-001-001 7	RESET LIMIT SWITCH TO PREVENT BACKSEATING AND PREMATURE BYPASS SWITCH TRIP OUT	GREASE IN SWITCH COMPARTMENT, CONTACTS ON LIMITS WERE CORRODED AND TORQUE SWITCH WAS COVERED WITH OIL	REPLACED BAD TORQUE SWITCH AND ADJUSTED. REF: MR A547B01	A299905
11-20-85	2-FSV-067-0338 -8	CONTROL CIRCUIT WAS CONTINUALLY BLOWING FUSES	SOLENOID WAS BURNED UP	REPLACED SOLENOID AND CHECKED FOR PROPER OPERATION	A545023
11-21-85	1-FCV-090-0116 -8	VALVE WOULD NOT STAY IN OPEN POSITION	LIMIT SWITCH ACTUATOR ARM OUT OF ADJUSTMENT	ADJUSTED LIMITS AND CHECKED FOR PROPER OPERATIONS	A536247
11-22-85	0-CHR-311-0156 0171	CHILLER WAS NOT WORKING CAUSING TEMPERATURE TO RISE TO OVER 85 DEGREES RESULTING IN COMPUTER FAILURE	UNIT WAS OUT OF ALIGNMENT	RESTARTED UNIT WITH PROPER ALIGNMENT AND CHECKED FOR PROPER OPERATION	A594569
11-25-85	2-ZS-067-0354	LIMIT SWITCH DID NOT ACTUATE PROPERLY WHEN VALVE CHANGED POSITIONS	LIMIT SWITCH WAS OUT OF ADJUSTMENT	ADJUSTED LIMIT SWITCH AND CHECKED FOR PROPER ACTUATION	A546246
11-26-85	1-FSV-043-0251 -A	CONDUIT COUPLING LEADING TO 1-FSV-63-71 WAS BROKEN	POSSIBLY HAD BEEN STEPPED ON BY PERSONNEL	REPLACED CONAX CONNECTION, CONDUIT AND WTRING	A541841
11-27-85	1-HS-031-04758	JUMPER FROM 1-HS-31-4758	CUT WAS DUE TO CLOSING OF	REPLACED WIRE #1117V7	A522257

11:58:39 01-02-86 ELECTRICAL MAINTENANCE MONTHLY REPORT FOR DECEMBER PAGE 2
 DATE.... COMPONENT..... FAILURE DESCRIPTION..... CAUSE OF FAILURE..... CORRECTIVE ACTION..... MR.NO..
 -A TO TERMINAL BLOCK 1117V7 DOOR ON 1-L-572C FROM JB 572-C
 HAD BEEN CUT

9 records listed.

INSTRUMENT MAINTENANCE

Unit 1

An inadvertant containment vent isolation occurred on 12-/85 as a result of power loss to radiation monitor 1-RM-90-112A (PRO-1-85-362). The power supply plug was verified to be connected to the correct plug mold. Recorder 1-RR-90-112 indicated that the monitor lost power for approximately ten minutes. It was believed that the monitor's power supply failed in service. However, the power supply was removed from service, placed under a load test, and was determined to be functioning properly. Further investigation revealed that the radiation analyzer (RP-30) connector pins could have momentarily opened the power circuit. The connector pins were cleaned and 1-RM-90-112A was returned to service.

The reactor coolant system narrow range RTD manifolds on loops 2,3, and 4 were found damaged during performance of SMI-0-68-28 to install new RTD's for qualified life replacement. MR's were initiated to allow repair by Mechanical Maintenance. Six of eight RTD's have already been replaced. The remaining two will be completed after the manifolds are repaired.

Unit 2

During performance of a required soldering modification to 2-PT-68-66, RHR suction valve 2-FCV-74-2 was inadvertantly closed, isolating the suction to the RHR pumps (PRO-2-85-134). Investigation revealed a deficiency with SI-484 that caused the isolation. The instruction was revised under a temporary change to include additional steps for prevention of RHR isolation when working on the loop.

2-PT-68-323 was found out of tolerance during performance of refueling calibration, SI-94.1. PRO-2-85-133 was initiated, the transmitter was recalibrated, and the loop was returned to service.

Common

Contracted with Westinghouse to perform a re-analysis of Sequoyah's setpoint methodology report. This was necessary to consider maintenance and test equipment inaccuracies and new equipment installations to ensure safety margins are not compromised. Preliminary calculations from Westinghouse are expected to be submitted and reviewed before startup.

During performance of SI-620, auxiliary air compressor pressure switch 0-PS-32-62 was found out of tolerance. PRO-1-85-359 was initiated and the switch was recalibrated.

Continued support for the environmental qualification program. Received QMDS binders and began verification of essential maintenance requirements. Coordinated with OE to resolve binder discrepancies and equipment installation problems.

MR. COMP	U	FUNC	SYS	ADDRESS	DATE	DESCRIPTION	CORRECTIVE ACTION
A085196	2	PT	068	322	12/13/85	2-PT-068-322-, *NPRD* RECALIB XMTR BECAUSE OF TEST EQ OUT OF TOLERANCE	TEST EQUIPMENT USED TO CALIBRATE FOUND OUT OF TOLERANCE, CHECK CALIBRATION RECAL IF NECESSARY
A085197	2	PM	001	13	12/13/85	2-PM-001-13-, AIR LEAK	DEFECTIVE REGULATOR REPLACE REGULATOR
A085200	2	LR	003	98P001	12/11/85	2-LR-003-98P001-, PEN IS BROKEN REPAIR	BROKEN PEN REPLACE PEN
A122992	0		090		12/17/85	0-090--, COORD W/ELECT MOD & HAVE THE COMPONENTS ON THE ATTACHED LIST ENERGIZED AS REQ'D TO A MAX LOAD COND SO SMI 0 317 23 CAN BE PERFORMED	NONE ASSIST ELECTRICAL MODIFICATIONS IN TESTING
A230512	0	RM	090	122	12/12/85	0-RM-090-122-, MON BACKGROUND TOO HIGH CLEAR MON	PARTICULATE CONTAMINATION CLEAN OUT MONITOR
A298561	2	RM	090	271	12/20/85	2-RM-090-271-, FOUND OUT TOLERANCE ON SMI 0 90 1 WHEN DETECTOR PLACED IN 100 R FIELD. REPAIR PER VALIDATED GA MANUALS R244	DEFECTIVE DETECTOR INSTALL NEW DETECTOR
A299299	1	XIS	068	388	12/03/85	1-XIS-068-388-, CUT OUT EXISTING ISOL AND WELD NEW ISOL IN PLACE	DEFECTIVE ISOLATOR INSTALL NEW HYDRALIC ISOLATOR
A300827	2	PX	003	170	12/23/85	2-PX-003-170-, PWR SUP IS READING APPROX 55 VDC SHOULD BE READING APPROX 35 VDC	DEFECTIVE DIODE IN POWER SUPPLY REPLACE DIODE VERIFY PROPER VOLTAGE OUTPUT & RETURN TO SERVICE MR A300827 SI-97
A300828	2	PX	003	163	12/23/85	2-PX-003-163-, PWR SUP IS LOADING APPROX 55VDC SHOULD BE READING APPROX 35 VDC	DEFECTIVE DIODE IN POWER SUPPLY REPLACE DIODE VERIFY PROPER VOLTAGE OUTPUT AND RETURN TO SERVICE MR A300828 SI-97
A300829	2	PX	003	147	12/23/85	2-PX-003-147-, PWR SUP IS READING APPROX 55 VDC SHOULD BE READING APPROX 35 VDC	DEFECTIVE DIODE IN POWER SUPPLY REPLACE DIODE VERIFY PROPER VOLTAGE OUTPUT AND RETURN TO SERVICE MR A300829 SI-97
A300835	1	LI	003	175	12/23/85	1-LI-003-175-, *NPRD* IND POINTER BROKEN NEEDED TO COMPLETE SI 207	ABNORMAL SHOCK ON THE METER REPAIR METER POINTER CHECK CALIBRATION & RETURN TO SERVICE
A300836	0	RE	090	122	12/23/85	0-RE-090-122-, THE MONITOR BACKGROUND IS APPROX 100,000 CPM & WILL NOT RENSE DOWN EVEN WITH THE ACID FLUSH DECON AS NECESSARY FOR LIQUID RELEASE NO TAG HUNG	PARTICULATE CONTAMINATION CLEAN SAMPLE CHAMBER
A300839	2	XI	092	5001A	12/27/85	2-XI-092-5001A-, *NPRD* SR DISPL RAPID INCR FROM APPROX 12 APPROX 40 CPS WHILE DIGITAL INSTR INDICATED APPROX ORIGINAL READING OF 11 CPS	NONE COULD BE FOUND PERFORM SI-278 NO PROBLEM FOUND RETURNED TO SERVICE
A301070	2	FI	001	3A	12/17/85	2-FI-001-3A-, NEEDS TO BE CALIB. READING .5X106 PPH WHILE OTHER CHANNEL(S) OPPH	FLEX HOSE FEEDING TRANSMITTER LEAKING, TRANSMITTER OUT OF CALIBRATION. REPAIR FLEX HOSE LEAK AND RECALIBRATE TRANSMITTER MR A301070, A548861

COMP

MR.	COMP	U	FUNC	SYS	ADDRESS	DATE	DESCRIPTION	CORRECTIVE ACTION
A301665	1	TE	068	2A	12/26/85	1-TE-068-2A-	REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE OF DEVICE. REPLACE RTD WITH EQUIVALENT TYPE.
A301666	1	TE	068	2B	12/26/85	1-TE-068-2B-	REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE. REPLACE RTD WITH EQUIVALENT TYPE
A301667	1	TE	068	14A	12/26/85	1-TE-068-14A-	REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE OF DEVICE. REPLACE RTD WITH EQUIVALENT TYPE.
A301668	1	TE	068	14B	12/26/85	1-TE-068-14B-	REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE OF DEVICE. REPLACE RTD WITH EQUIVALENT TYPE.
A523201	0	RR	090	205	12/17/85	0-RR-090-205-	REPORTER PEN SLIPS SLIGHTLY FROM DRIVE CORD HOLDING SCREW MAY BE WORKING ITSELF OUT	HOLDING SCREW WORKING ITSELF LOOSE TIGHTENED SCREW
A523203	0	RM	090	133A	12/11/85	0-RM-090-133A-	INPRDS* THE RM SHOWS A HIGH RAD COND THAT NEEDS TO BE FERVIED CHECK RAD MONITOR FOR PROPER OPERATION	BACK GROUND TOO HIGH CHANGED SETPOINT PER SI-204
A523204	0	RM	090	212	12/18/85	0-RM-090-212-	INST MALFUNCTION WILL NOT CLEAR	CLOGGED SENSING LINE TO ROTOMETER CLEAN OUT SENSING LINE
A523205	0	RM	090	140A	12/11/85	0-RM-090-140A-	RAD MONITOR SPIKES HIGH AND LOW NO ACTIVITY FOUND IN WATER ALARM CONTINUOUSLY COMES IN ON 0-M-12	BACKGROUND TOO HIGH FOR SETPOINT CHANGE SETPOINT PER SI 204
A523207	2	PCV	001	12	12/13/85	2-PCV-001-12-	INPRDS* AIR LEAK ON CONTROLLER	NO FAILURE NORMAL POSITIONER AIR BLEED NONE
A523578	2	PM	001	31	12/17/85	2-PM-001-31-	AIR FLTR REGULATOR FOR 2 PM 1 31 AND 2 HCV 1 31 HAS AIR BLOWING FROM SMALL HOLES	DEFECTIVE REGULATOR INSTALL NEW REGULATOR
A523579	2	LCV	003	171	12/13/85	2-LCV-003-171-	INPRDS* LCV OPERATES PROPERLY IN AUTO BUT WON'T RESPOND IN MANUAL	THE POSITIVE LEAD FEEDING THE POSITIONER WAS G ROUNDED IN THE CONOULET. REPAIR GROUNDED WIRE AND FUCTIONALLY TEST MR523579
A523715	0	TS	032	64	12/13/85	0-TS-032-64-	IN* CHECK CALIB OF TEMP SW AUX AIR COMPRA AA	SWITCH OUT OF CALIBTATION RECALIBRATE SWITCH
A529379	2	RM	090	292	12/18/85	2-RM-090-292-	BROKEN CABLE TO DETECTOR FOUND ON SI 685.2	BROKEN CABLE TO DETECTOR REPAIR CABLE
A529607	2	RI	090	278	12/13/85	2-RI-090-278-	INDICATOR IS DEAD. REPAIR FOUND DURING PERFORMANCE OF SI 685.2	LOOSE WIRE & STICKING INDICATOR TIG. ITEN WIRE & REPAIR INDICATOR
A529608	2	RI	090	275	12/18/85	2-RI-090-275-	INDICATOR WILL NOT CALIB FOUND DURING PERFORMANCE OF SI 685.2	DEFECTIVE INDICATOR INSTALL NEW INDICATOR
A529609	2	RI	090	276	12/18/85	2-RI-090-276-	INDICATOR WILL NOT CALIB	DEFECTIVE INDICATOR INSTALL NEW

COMP

MR. COMP	U	FUNC	SYS	ADDRESS	DATE	DESCRIPTION	CORRECTIVE ACTION
A534188	2	LEV	003	156A	12/13/85	FOUND DURING PERFORMANCE OF SI 685.2 2-LEV-003-156A-, ANPRD* LEV 156A HAS AIR LEAK	INDICATOR DEFECTIVE REGULATOR AND LOOSE BONNET TO YOKE CONNECTING BOLTS REPLACE REGULATOR AND TIGHTEN CONNECTING BOLTS MAKE STROKE AND LIFT-OFF ADJUSTMENTS MR A534188
A536089	1	PCV	032		12/13/85	1-PCV-032--, STOP SUP AIR REG AIR 'LEAK	BLOWN GASKET BETWEEN THE GAUGE MANIFOLD AND POSITIONERREPLACE DEFECTIOVE GASKET
A539502	2	RE	090	273	12/20/85	2-RE-090-273-, REMOVE THE RAD ELEMENT FROM 2 RM 90 273	NONE REINSTALL DETECTOR
A539504	2	RE	090	274	12/20/85	2-RE-090-274-, REMOVE THE RAD ELEMENT FROM 2 RM 90 274	NONE REINSTALL WHEN TEST IS COMPLETE
A539521	2	LT	003	38	12/04/85	2-LT-003-38-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	HARDWIRE PIN CONNECTORS TO MAINTAIN QUALIFICATIONS HARDWIRE CONNECTORS
A539525	2	LT	003	51	12/04/85	2-LT-003-51-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HARDWIRING TO MAINTAIN QUALIFICATIONS HARDWIRE CONNECTOR
A539527	2	LT	003	39	12/04/85	2-LT-003-39-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTORS NEED HARDWIRING TO MAINTAIN QUALIFICATIONS
A539529	2	LT	003	106	12/04/85	2-LT-003-106-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HARDWIRING TO MAINTAIN QUALIFICATIONS HARDWIRE CONNECTOR
A539530	2	LT	003	98	12/04/85	2-LT-003-98-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HARDWIRING HARDWIRE CONNECTOR
A539531	2	LT	003	97	12/04/85	2-LT-003-97-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HARDWIRING TO MAINTAIN QUALIFICATIONS HARDWIRE CONNECTOR
A539532	2	LT	003	52	12/04/85	2-LT-003-52-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HARDWIRING HARDWIRE CONNECTOR
A539533	2	LT	063	179	12/05/85	2-LT-063-179-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR	PIN CONNECTER NEEDS HARDWIRING TO MAINTAIN QUALIFICATION HARDWIRE CONNECTOR SMI 2-317-23
A539534	2	LT	063	177	12/06/85	2-LT-063-177-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR	PIN CONNECTOR NEEDS HARDWIRING TO MAINTAIN QUALIFICATIONS HARD WIRE CONNECTOR
A539535	2	LT	003	111	12/04/85	2-LT-003-111-, HARD WIRE IN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PINCONNECTOR HANDWIRING FOR QUALIFICATIONS HARDWIRE CONNECTOR

COMP

MR.	COMP	U	FUNC	SYS	ADDRESS	DATE	DESCRIPTION	CORRECTIVE ACTION
A539536	2	LT	003		107	12/04/85	2-LT-003-107-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HARDWIRING HARDWIRE PIN CONNECTOR
A539537	2	PT	068		323	12/05/85	2-PT-068-323-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HARDWIRE TO MAINTAIN QUALIFICATIONS. HARDWIRE CONNECTOR
A539538	2	PT	068		322	12/06/85	2-PT-068-322-, HARD WIRE PIN CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HARDWIRING TO MAINTAIN QUALIFICATIONS HARDWIRE CONNECTOR.
A539539	2	PT	068		69	12/10/85	2-PT-068-69-, HARDWIRE CONNECTOR FOR BARTON LOT 2 XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	CONNECTOR NEEDS HANDRINGS TO MAINTAIN QUALIFICATIONS HARDWIRE PIN CONNECTOR
A539544	2	PT	068		340	12/06/85	2-PT-068-340-, HARD WIRE PIN CONNECTOR FOR LOT 2 BARTON XMTR TO MAINTAIN QUALIFICATIONS PER SMI 2 317 23	PIN CONNECTOR NEEDS HANDWIRING TO MAINTAIN QUALIFICATIONS HARDWIRE CONNECTOR.
A545926	1	RM	090		112B	12/13/85	1-RM-090-112B-TSC, TSC READINGS WERE FND OUT OF CAL PER SI 83	TSC OUT OF CALIBRATION RECALIBRATE TSC
A545927	1	RM	090		112A	12/13/85	1-RM-090-112A-TSC, TSC READINGS ARE OUT OF TOLERANCE PER SI 83	TSC OUT OF CALIBRATION RECALIBRATE TSC
A546509	1	LI	003		172	12/16/85	1-LI-003-172-, #NPRD# LVL IND POINTER IS OFF BROKEN NEEDED TO COMPLETE SI 207	POINTER BROKEN OFF, REPAIR INDICATOR
A546561	2	PS	068		668/E	12/09/85	2-PS-068-668/E-, INVESTIGATE PROB W/2 PS 68 668/E AND 2 FCV 74 2 RHR VLV WHICH WENT CLOSED	COULD NOT BE DETERMINED. RECALIBRATE PRESSURE SWITCH MR A546561
A547678	0	RM	090		212	12/19/85	0-RM-090-212-, PUMP OR MOTOR BEARING IS LOUD MAY BE GOING BAD	BAD BEARINGS REPLACE BEARINGS
A547695	2	HTCK	234		123	12/19/85	2-HTCK-234-123-, THERMOSTAT CONTACTS ARE VIBRATING WHEN MADE	DEFECTIVE TEMPERATURE CONTROLLER REPLACE TEMPERATURE CONTROLLER
A547696	2	HTCK	234		69	12/19/85	2-HTCK-234-69-, NO GRN OR RED IND ON THERMOSTAT	BAD THERMOSTAT REPLACE THERMOSTAT
A548051	2	LI	070		63A	12/19/85	2-LI-070-63A-, CHECK CAL ON LT SUSPECT FAULTY LVL IND	WATER IN DRY LEG OF TRANSMITTER DRAIN WATER FROM DRY LEG MR A548051
A548052	2	LI	070		99A	12/19/85	2-LI-070-99A-, CHECK CUT ON LT SUSPECT FAULTY LVL IND	WATER IN DRY LEG OF TRANSMITTER DRAIN WATER FROM DRY LEG MR A548052
A548798	2	RE	090		271	12/20/85	2-RE-090-271-, REMOVE THE RADIATION ELEMENT FROM 2-RM-90-271	NONE REINSTALL DETECTOR
A548800	2	RE	090		272	12/20/85	2-RE-090-272-, REMOVE THE RAD ELEMENT FROM 2 RM 90 277	NONE REINSTALL DETECTOR
A548858	2	RM	090		112C	12/13/85	2-RM-090-112C-TSC, TSC COMPUTER FND OUT OF CAL ON SI 205.2	TSC OUT OF CALIBRATION RECALIBRATE TSC
A548859	2	RM	090		100	12/11/85	2-RM-090-100-, REPAIR FAILTER FAIL ALARM	DEFECTIVE SLOW MOTOR REPLACE SLOW MOTOR

MR.	COMP	U	FUNC	SYS	ADDRESS	DATE	DESCRIPTION	CORRECTIVE ACTION
A548860	1	RE	090		119	12/06/85	1-RE-090-119-, RM FLOW SIGHT GLASS NEEDS TO BE CLEANED OR REPLACED	DIRTY GLASS CLEAN SIGHT GLASS
A548861	2	FS	001		3	12/17/85	2-FS-001-3-A-, *NPRD* HI STM FLOW ALARM IN AND BYSTABLE LIGHT IS LIT	FLOW TRANSMITTER OUT OF CALIBRATION RECALIBRATE FLOW TRANSMITTER MR A548861
A548872	2	RM	090		121	12/04/85	2-RM-090-121-, LOW TRIP DOES NOT WORK FND DURING PERFORM OF SI 204.2 TAG ON RP 30	DEFECTIVE PUSHBUTTON SWITCH REPLACE PUSHBUTTON SWITCH
A548877	1	PDT	065		80	12/09/85	1-PDT-065-80-, *I* INSTALL ET'S INCLINE MANOMETER 0-10" ACROSS SAID PT FOR SI-264	NONE INSTALL TEST EQUIPMENT AND REMOVE WHEN NO LONGER NEEDED
A548880	1	RM	090		106	12/09/85	1-RM-090-106-, MCR INSTR MALFUNC ALARM WON'T CLEAR DUE TO LOW IODINE FLOW	DIRTY ROTOMETER CAUSING LOW FLOW CLEAN OUT ROTOMETER
A548882	0	PDIS	026		7A	12/11/85	0-PDIS-026-7A-, DELTA DID NOT DROP DOWN AFTER APPROX 15 MIN OF BACKWASHING CALIB DELTA P GAUGE	NO PROBLEM FOUND, NONE
A548883	0	TR	082		5036/3	12/13/85	0-TR-082-5036/3-, RECORDER STAMPING ON ONE POINT BUT STAYING RIGHT	CONTACTS ON RECORDER DIRTY, CLEAN CONTACTS
A548887	1	RM	090		112A	12/26/85	1-RM-090-112A-, 1 RM 90 112A FAILED MOMENTARILY ON 12/7/85 CAUSING A CVI PRO 1 85 362	LOOSE SCREWS & DIRTY PINS ON RP-30 TIGHTEN SCREWS & CLEAN PINS PRO 1-85-362
A548891	1	PT	001		20A	12/16/85	1-PT-001-20A-, *NPRD* INSTR WAS CALIB W/M&TE E00244 WHICH WAS FND OUT OF TOLERANCE AT THE LAB. VERIFY OR RECALIB INSTR. GIVE RESULTS TO ORIG	TRANSMITTER WAS CALIBRATED WITH TEST EQUIPMENT THAT WAS OUT OF CALIBRATION. RECALIBRATE PRESSURE TRANSMITTER MR A 548891
A548893	1	RM	090		112	12/26/85	1-RM-090-112-, AUDIBLE ALARM DOES NOT WORK	BROKEN WIRE ON ALARM RESOLVER BROKEN WIRE
A548910	0	PS	032		62	12/07/85	0-PS-032-62-, RECALIB OPS 32 62	OUT OF CALIBRATION RECALIBRATE SWITCH
A550516	1	LIC	003		174	12/10/85	1-LIC-003-174-, *SERVO MOTOR APPEARS TO BE BAD UNABLE TO DRIVE PROCESS INDILATOR NO W&TE	DEFECTIVE POTENTIOMETER AND SERVO MOTOR REPLACE POTENTIOMETER AND SERVO MOTOR. MR A 550516
A550517	1	LIC	003		156	12/18/85	1-LIC-003-156-, *SERVO MOTOR APPEARS TO BE BAD PROCESS INDICATOR HANGS OCCASIONALLY	DEFECTIVE RIBBON CABLE CONNECTOR INSTALL NEW RIBBON CABLE CONNECTOR CALIBRATE CONTROLLER & RETURN TO SERVICE MR A550517 PM 1334-003
A550518	2	LS	070		210A&B	12/19/85	2-LS-070-210A&B-, CHECK LS FOR PROPER OPER	WATER IN DRY REFERENCE LEG OF SWITCH DRAIN WATER FROM SWITCH
A550519	1	LS	070		209A/B	12/19/85	1-LS-070-209A/B-, CHECK LS FOR PROPER OPER	WATER IN DRY REFERENCE LEG DRAIN WATER FROM DRY REFERENCE LEG
A550664	2		099			12/16/85	2--099--. COMPUTER NOT RECEIVING SIGNAL CHANGE ON: V03200; V03210; V03220; Y03200; Y03210; Y0	DEFECTIVE INPUT CONTACT BUFFER CARD IN UNIT 2 P250 COMPUTER REPLACE DEFECTIVE CARD

COMP

MR. COMP U FUNC SYS ADDRESS. DATE.... DESCRIPTION..... CORRECTIVE ACTION.....

MR. COMP	U	FUNC	SYS	ADDRESS	DATE	DESCRIPTION	CORRECTIVE ACTION
A560058	2	RM	090	272	12/20/85	3220 2-RM-090-272-, TROUBLE SHOOT AND ADJUST/REPAIR AS NEEDED TO CLEAR RAD MON OF NI RAD ALARM	DEFECTIVE DETECTOR REPLACE DETECTOR
A562131	2	FIT	062	10	12/26/85	2-FIT-062-10-, REMOVE TRANSMITTERS FROM PIPE FOR REPAIRING OF FLANGES ON MR A564777	NONE REINSTALL TRANSMITTER

LUMP

MR2....	U	FUNC	SYS	ADDRESS.	DATE....	DESCRIPTION.....	CORRECTIVE ACTION.....
A300820	2	PNL	500	381	12/06/85	2-PNL-500-381-, CHANGE COVERS & ID TAGS ON 2 FM 3 142 A & 2 FM 46 57	PERSONNEL ERROR. INSTALL COVERS & TAGS ON PROPER DEVICES
A301674	1	TE	068	44A	12/31/85	1-TE-068-44A-, REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE OF DEVICE. REPLACE RTD WITH EQUIVALENT TYPE.
A301676	1	TE	068	44B	12/31/85	1-TE-068-44B-, REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE OF DEVICE. REPLACE WITH EQUIVALENT TYPE.
A301677	1	TE	068	56A	12/31/85	1-TE-068-56A-, REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE OF DEVICE. REPLACE WITH EQUIVALENT TYPE RTD.
A301678	1	TE	068	56B	12/31/85	1-TE-068-56B-, REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE OF DEVICE. REPLACE WITH EQUIVALENT TYPE RTD.
A301681	1	TE	068	79A	12/31/85	1-TE-068-79A-, REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE OF DEVICE REPLACE WITH EQUIVALENT RTD.
A301682	1	TE	068	79B	12/31/85	1-TE-068-79B-, REPLACE EXISTING NARROW RANGE RTD DUE TO THE EXPIRATION OF THE QUALIFIED LIFE	END OF QUALIFIED LIFE. REPLACE WITH EQUIVALENT TYPE RTD
A523577	1	PT	068	337C	12/30/85	1-PT-068-337C-, #NPRD# ZERO SHIFTS ON XMTR WHEN TEST PRESS IS DROPPED BELOW 1700 PSI	TRANSMITTER OUT OF CALIBRATION PERFORM STATIC ALIGNMENT & FLEXURE ADJUST CALIBRATE PER SI-92
A548895	2	LT	003	97	12/31/85	2-LT-003-97-, #NPRD# INST FAILED HIGH	TRANSMITTER OUT OF CALIBRATION RECALIBRATE LEVEL TRANSMITTER MR A548895
A559963	1	XS	068	66	12/02/85	1-XS-068-66-, RETURN INJ SW XS 68 66 PS/403 IN 1 R 5 TO NORMAL WHILE RX VESSEL IS BEING FILLED & VENTED. LOOP IS NOT BEING REPAIRED OPERABLE. THIS IS ONLY TO ALLOW UP	NONE. RETURN SW TO NORMAL WHILE VESSEL IS BEING FILLED AND VENTED

90 records listed.

MONTHLY REPORT

DEC 1985

MECH. MAINT.

UNIT 0

1. WORK ON AUX. BOILER COMPLETED AND BACK IN SERVICE
2. REPLACED SEAL AND COMPLETED ALIGNMENT ON CDWE VAPOR BODY RECIRCULATION PUMP.
3. UNSTOPPED LINES ON CDWE
4. COMPLETED MONTHLY AND QUARTERLY SI ON 2AA D/G.
5. D STATION AIR COMPRESSOR COMPLETE
6. INSTALLED UNLOADER VALVE ON C AIR COMPRESSOR
7. PERFORMED P. M. ON AUX. BLDG. CRANE.
8. HFFP STRAINERS THAT FEED RX BLDG. COMPLETE
9. COMPLETED MONTHLY AND QUARTERLY SI ON 2BB D/G
10. REKEYING HIGH RAD. SECURITY DOORS
11. COMPLETED MONTHLY INSPECTION ON 1AA D/G
12. CLOSED UP A CCS HTX.

MONTHLY REPORT
DEC. 1985
MECH. MAINT.
UNIT 1.

1. INSTALLED NEW SOLENOID ON 1-FSV-063-166
2. COMPLETED SI-239 ON DIVIDER BARRIER SEAL
3. COMPLETED THRUST ASSEMBLY ON 1A RPT
4. PRESSURIZED CONTAINMENT
5. UNIT 1. BLDG HEATING COILS BACK IN SERVICE
6. REPAIRED OIL LEAK ON A RPT
7. COMPLETED INSPECTION ON 2B RPT
8. REPACKED 1-FCV-001-4
9. COMPLETED INSPECTION OF 1-FCV-030-134, REASSEMBLED
10. COMPLETED NDE ON BONNET, STEM AND BODY OF 1-FCV-003-100
11. INSPECTION COMPLETE ON 1-LCV-106A&106B, REASSEMBLED
12. COMPLETED STEAM GENERATOR CLEANUP

MONTHLY REPORT
DEC 1985
MECH. MAINT.
UNIT 2

1. 2B RFP X-RAY GOOD ON DISCHARGE PIPE
2. 6 OF 7 BUILDING HEATING COILS BACK IN SERVICE
3. LUBE OIL PUMP COUPLING INSPECTION ON 2B CCP COMPLETE
4. WATERBOX WORK COMPLETE AND CLOSED UP
5. COMPLETED STRESS RELIEF ON 2B RFP
6. INSPECTION COMPLETE ON 2A RFP
7. COMPLETED INSPECTION OF 2-FCV-043-22, REASSEMBLED
8. COMPLETED GENERATOR CRAWL THRU
9. COMPLETED UNIT 2 NOZZLE COVER WORK
10. COMPLETED INSPECTION ON 2-LCV-106A&106B, REASSEMBLED
11. ALIGNMENT COMPLETE ON 2A&2B RFP,S
12. RETIRED AND INSTALLED 20 TON AIR FAN MOTOR BASE
13. COMPLETED NDE ON 2-FCV-003-33

SUMMARY OF WORK COMPLETED

MODIFICATIONS

DECEMBER 1985

NUREG 0588

ECN 6231 - Remove Interferences

A-train ERCW piping has been rerouted. Work has begun on B-train. Supports will be installed later.

APPENDIX R

ECNs 5265, 5435, and 6343 - Fire Doors

Door C-50 tested satisfactorily; however, it still lacks final electrical hookup and testing. When door C-50 is complete and operable, work will begin on door C-49. Additional work plans for ECN 6343 were prepared and placed in the approval cycle.

ECN 6235 - Reroute Various Cables

Work is on hold for the nine workplans previously in work. Workplan writing is on hold.

ECN 6305 - Elevation 714 Fire Barrier

Framing is complete, and the installation of the fireboard and door is in progress.

ECN 6311 - Operator Extension on PORV

Work is complete except for postmodification testing scheduled during startup.

ECN 6315 - Replace Fuses

Fuse installation was begun.

ECN 6319 - Fire Protection Piping

Installation of piping and hangers continues.

OTHER ITEMS

ECN 5009 - ERCW Piping Changeout From Carbon Steel to Stainless Steel

The installation of A-train piping to the unit 1 upper compartment cooler is complete. The installation of B-train is complete with the exception of the two additional check valves which is in progress. The additional hanger for the auxiliary air compressor was installed.

OTHER ITEMS (Continued)

ECNs 5034, 5713, 5743, and 6064 - Various Platforms in Lower Containment

The application of protective coating continues. The installation of platforms between Nos. 2 and 3 steam generators continues. The safety gates for the upper platforms have been installed.

ECN 5200 - Postaccident Sampling Facility

No work was performed this period.

ECN 5202 - Fifth Diesel Generator

The backfilling was completed and tested. Missile barrier concrete will be poured at the first opportunity. The workplans will be prepared for electrical interface work.

ECN 5237 - Laundry Facility

No work was performed this period.

ECN 5252 - Label Node Voltages in Manholes

No progress on this job this period; four manholes remain.

ECN 5347 - Replace Doors C-49 and C-50 (Electrical Portion)

This work is on hold until door C-50 passes the leak test.

ECN 5373 - Condensate Demineralizer Air Compressor

The new design was received, and installation was begun.

ECN 5620 - Add Instrumentation for Auxiliary Feedwater Pump

Work is on hold.

ECN 5645 - Replacement of Flow-Control Valve 2-329

The installation of the unit 2 valve is almost complete. The vendor representative will not be here until January to modify both valves.

ECN 5657 - Installation of MSR Drain Valves

The installation of the unit 2 valve assemblies is well underway.

OTHER ITEMS (Continued)

ECN 5795 - Field Services Building

Fire detection system work is on hold for materials.

ECN 5914 - Improve Reliability of Steam Dump

Conduit is complete; valve remains to be wired in.

ECNs 5938 and 6506 - Feedwater Heater Replacement

All mechanical work was completed. Installation work continues.

ECN 6057 - Cable Tray Covers

Approximately 240 out of 290 cable tray covers have been remanufactured or replaced.

ECN 6147 - Airlock Packing Nut

The unit 1 airlocks were tested with satisfactory result. The antirotation devices were installed on unit 2, thus completing this modification.

ECN 6152 - SPDS

All consoles have been installed.

ECN 6196 - Pressurizer Hangers and Valves

Unit 1 support work was completed. Final installation of the mirror insulation remains. Installation of the last support on unit 2 was started.

ECN 6204 - Electrical Penetration Overcurrent Protection

Fuse replacement and fuse block installation are complete. We are awaiting a technical specification change to place the circuits in operation.

ECNs 6251 and 6532 - Waste Disposal Hangers

This work was completed.

ECN 6259 - Moisture Separator Reheater Tube Bundle Replacement

Reinstallation of the doghouses continues. The repair of inadequate SECO welds continues. Reinsulating work is in progress.

ECN 6263 - Feedwater Hangers Lower Containment

This work is complete.

OTHER ITEMS (Continued)

ECN 6352 - Fire Protection Isolation Valves

This work is complete.

ECNs 6402 and 6439 - Pressurizer Instrumentation Relocation

The unit 1 work was completed. The unit 2 workplan was written and approved, and work was started. The core drills have been completed, and piping work is in progress.

ECN 6417 - Install Alternate Seal Water for Pumps, CDWE

Electrical drawings remain to be issued.

ECN 6491 - ERCW Supports

Eighteen of the first twenty supports are complete. The final two are awaiting approval of the FCR. The workplan for the final 21 supports was written and approved, and the work was started.

ECN 6494 - ERCW Pipe Replacement at CCW Heat Exchangers

The degraded valve body was replaced with a new body. The old body will be refurbished. This completes this work.

ECN 6495 - Modification of Pressurizer Pots

This work was completed.

Dry Active Waste Building (DCR 1898)

Work began on dismantling the old carpenter shop and cleaning up the site to begin construction. The workplan is in the approval cycle. Concrete foundation work will be done as weather permits. The transfer of structural steel for the building from Yellow Creek Nuclear Plant has been completed.

Preliminary indications are that several additional work items may be forthcoming that will be required to be completed before startup. Preliminary work has begun on these items as follows:

ECN 5667 - Double Isolation Valves for Flow Orifices (Unit 2)
- Removal of EGTS Backdraft Dampers

ECN 6548 - Additional Support for Incore Drive Cart

ECN 6552 - 0588 Solenoids
- Replacement of Degraded Secondary Side Piping

Date: 1/2/66

SCR No.	Description	Memo	ECN	Issued	Drawings	Engineer	Workplan No.	Estimated Date of Completion		Comments
								U-1	U-2	
EQP 8501	Disconnect 1- & 2-HS-62-61	9/18	6524	Yes	11/29-30	Peters	11901			Workplan in approval cycle.
EQP 8502	Replace penetrations 23, 48	9/13	6490	Yes	Yes	Peters	11801, 11802, 11810, 11811	1/3	C	Final laydown and merger in progress. Assembling QIR for closure.
EQP 8503	Relocate RE-90-273, -274	9/25	6500	Yes	Yes	Peters	11810, 11811	C	N/A	Preparing QIR for closure.
EQP 8504	Splice methods not correct	10/2	N/A	N/A	N/A	Stockton	80 MRs	C	C	Preparing QIR for closure.
EQP 8505	Drawing	10/11	N/A	N/A	N/A	N/A	N/A	N/A	N/A	
EQP 8506	Seal cntmt isolation valve	10/17	6514	Yes	Yes	Kimsey	11880	1/5	1/5	Workplan in field. Hanger Design is impeding installation.
EQP 8507	Rewire MOV	10/29	N/A	N/A	N/A	Rutledge	11866, 11853	1/5	12/31	On U-2, 127 rewired; 126 functioned; 90 MOVATS. On U-1, 72 rewired; 10 functioned; ___ MOVATS.
EQP 8508	JB weepholes (press)	10/17	6523		12/12	Alas	11898	C	C	Preparing QIR for closure.
EQP 8509R1	Conduit seals	11/6	6529	11/29	12/16	Kimsey	11903, 11904			Writing workplans.
EQP 8510	Disconnect local hand-switches	11/12	6527		12/8	Peters	11901	1/20	1/13	Workplan in work.
EQP 8511	Submerged JB inside cntmt	11/13	6549	12/5	12/18	Peters	11901		1/5	Workplan in work.
EQP 8512R2	Rewire JB	N/A	N/A	N/A	N/A	Amburn	11855, 11856	1/20	1/13	On U-2, 71 of 83 rewired. On U-1, 56 of 70 rewired.
EQP 8513	Weep holes (moisture)	11/14	6547	11/29	12/5	Alas	11898	C	C	Preparing QIR for closure.
EQP 8513R2	Weep holes (moisture)		6565	12/18	1/2	Alas		1/10	1/10	
EQP 8514	Motor insulation 74-1, -2	11/14	6540		12/3	Branham	11906	N/A	1/8	Workplan in field. Need PMT requirements clarified. Paperwork holdup on release of motors from warehouse.

SCR No.	Description	Memo	ECN	Issued	Drawings	Engineer	Workplan No.	Estimated Date of Completion		Comments
								U-1	U-2	
EQP 8515	Replace 2-PDT-30-43	11/15	6554	12/6	12/11	Legg	11912	1/12	1/12	Workplan in field.
EQP 8516	Replace 2-LT-3-174	11/15	12/29			Inst. Maint.				
EQP 8517	ABGTS humidity control				1/7			1/20	1/20	
EQP 8518	Submerged cables	11/15	6533	11/27	12/8	Various/6	Various	2/8	1/23	On schedule.
EQP 8519	Tee drains	11/22	N/A	N/A	N/A	Elect. Maint.		C	C	El. Maint turned in OIR.
EQP 8520	Expired cables	11/22	6553	12/5	12/12	Gonzalez	11902	1/20	1/13	Workplan in field 12/30/85.
EQP 8521	Delete TR and rework splices	11/22	6550	12/5	12/14	Stockton	11914, 11915	1/20	1/13	Workplan in approval cycle.
EQP 8522	Rewire local panels	11/26				Stockton	11914, 11915	1/20	1/13	Workplan in approval cycle.
EQP 8523	Missing bolts and washers and misplaced brackets	N/A	N/A (MR)	N/A	N/A	Stockton	11914, 11915	1/20	1/6	Workplan in approval cycle.
EQP 8524	Change setpoints	11/26	6551	12/6	12/17	Inst. Maint.	11916	Unkn.	Unkn.	Workplan in approval cycle.
EQP 8525	Retermine hydrogen recombiner	N/A	N/A (MR)	N/A	N/A	Elect. Maint.		1/6	1/6	
EQP 8526	Replace FSVs, U-1 1, U-2 11	11/26	6552	12/5	12/14	Mech. Mods.				Mech. Mods. has workplan to resolve comments.

SCR No.	Description	Memo	ECN	Issued	Drawings	Engineer	Workplan No.	Estimated Date of Completion		Comments
								U-1	U-2	
EQP 8527	Coat TB, U-1 3, U-2 8	N/A	N/A (MR)	N/A	N/A	Stockton	11914, 11915	1/5	1/5	Workplan in approval cycle.
EQP 8528	Solder strain gauge Barton transmitters	11/26	IMI			Inst. Maint.		Unkn.	Unkn.	
EQP 8529	PDT-30-42, -43 capacitor	11/26	6554	12/6	12/11	Legg	11912	1/12	1/12	Workplan in field.
EQP 8530	Gasket, Namco L/S	N/A	N/A (MR)	N/A	N/A	Fleet. Maint.		Unkn.	Unkn.	152 of 185 complete.
EQP 8531	Delete MOV heaters	Yes	6544	11/27	12/2	Rutledge	11866, 11853	1/5	C	Work with MOV rewire.
EQP 8532	Delete L/S 1-, 2-43-201, -202, -207, and -208	Yes	6563	12/18	12/24	Alas		1/23	1/16	Writing W/P.
EQP 8533	Delete dual voltage splice	Yes	N/A	N/A	N/A	Rutledge	11866, 11853	1/12	C	Work with MOV rewire.
EQP 8534	Resplice valve positioner 3-174 and -175					Maxwell	MR	1/13	1/13	MR's in field.
EQP 8535	Replace limit switches, U-1 10, U-2 12	Yes	6556	12/7	12/18	Stockton		1/30	1/23	
EQP 8536	Valve room submergence		6561			Mech. Mods.			1/23	Elect. Mods.???
EQP 8537	Rebuild or replace JB 3078		6579	12/27	1/2	Amburn		1/16	N/A	Hold for design resolution.
EQP 8538	Replace capacitors FCO-31-475, -476					Maxwell		1/18	1/18	

Date: 1/2/86

SCR No.	Description	Memo	ECN	Issued	Drawings	Engineer	Workplan No.	Estimated Date of Completion		Comments
								U-1	U-2	
EQP 8539	Replace capacitors					Inst. Maint.	-	Unkn.	Unkn.	Capacitors onsite.
EQP 8540	Replace pigtaills to Target Rock solenoid valves					Maxwell		1/31	1/20	Writing workplan. Need drawings.
EQP 8541	Delete brakes					Branham		1/31	N/A	1-FCV-63-93, -94.
EQP 8542	Replace unqualified cables					Hall		Unkn.	N/A	work for resolution of issue.
EQP 8543	Replace JB wire					Amburn		1/31	1/20	Writing functionals.

Date: 1/2/86

SCR No.	Description	Memo	ECN	Issued	Drawings	Engineer	Workplan No.	Estimated Date of Completion		Comments
								U-1	U-2	
N/A	Move surge suppression network for PORV	N/A	5773	Yes	Yes	Kimsey	11883	1/6	1/4	On U-2, complete. On U-1, 1-PCV-68-340 in hold.
EEB 8523	Penetration overcurrent		6204 6219 6452	Yes	Yes	Legg	11891	C	C	All fuse blocks installed. Need to run functional when submerged conduit is complete. Preparing QIR for closure.
N/A	Work FCR to delete 1-, 2-PS-3-160A, -160B, -165A, and -165B	N/A	5883	Yes	Yes	Hall				Need SI-166.
N/A	Replace 1-FI-1-3A, -3B, -10A, -10B, -21A, -21B, -28A, -28B	N/A	6347	Yes	Yes	Inst. Maint.		Unkn.	N/A	
NEB 8510	Relocate LT-68-320, PT-68-323, -320	N/A	6439	U-1 U-2	U-1	Carrasquillo Peters	Various	1/18	1/23	On schedule.
	Remount 63-71, 68-308	N/A	6496	Yes	Yes	Legg	11865	C	C	
	Replace LS-65-4, -5	N/A	6504	Yes	Yes	Legg	11865	N/A	Unkn.	65-5 complete. 65-4 in hold for maintenance.
MEB 8410R3	Replace LS-77-127	11/22	6525	Yes	Yes	Legg	11865	N/A	C	
	Delete brakes FCV-62-61		6521	Yes	12/3	Branham	11905			Workplan in approval cycle.
EEB 8517	Replace pressure switch 65-80 and 65-82.		6488		12/24	Stanton				Writing W/P

SEQUOYAH NUCLEAR PLANT
DATE SUMMARY OF UPCOMING OUTAGES

<u>Unit 1</u>	<u>Start Date</u>	<u>Duration (Days)</u>	<u>Finish Date</u>
Initial Criticality	07/05/80		
U1, C3	08/22/85	173*	02/11/86*
Surveillance/Ice	04/03/87	17	04/19/87
U1, C4	06/26/87*	50	08/14/87*
Surveillance/Ice	10/07/88	17	10/23/88
U1, C5	12/30/88*	51	02/18/89*
Surveillance/Ice	04/06/90	17	04/22/90
U1, C6	07/06/90*	75	09/18/90*
Surveillance/Ice	10/04/91	17	10/20/91
U1, C7	01/31/92*	45	03/15/92*

<u>Unit 2</u>	<u>Start Date</u>	<u>Duration (Days)</u>	<u>Finish Date</u>
Initial Criticality	11/05/81		
U2, C3	09/05/86*	50	10/24/86*
Surveillance/Ice	10/30/87*	17	11/15/87*
U2, C4	03/18/88*	51	05/07/88*
Surveillance/Ice	05/12/89*	17	05/28/89*
U2, C5	09/22/89*	45	11/05/89*
Surveillance/Ice	11/09/90*	17	11/25/90*
U2, C6	03/22/91*	75	06/04/91*
Surveillance/Ice	06/05/92*	17	06/21/92*
U2, C7	10/23/92*	45	12/06/92*

NOTE: The unit 2 schedule assumes a 02/02/86 return-to-service from the forced outage that began on 08/21/85 and a 75% operating capacity factor (OCF) for the 153 effective full power days that remain in the unit 2 core.

*Denotes changes since last update.

ATP:CCM 01/08/86

SEQUOYAH NUCLEAR PLANT
FUEL CYCLE DESIGN BASIS INFORMATION SHEET

Unit 1

	<u>Cycle 3</u>	<u>Cycle 4</u>	<u>Cycle 5</u>	<u>Cycle 6</u>	<u>Cycle 7</u>
Operating Cycle Length (Days)	492	499	503	502	499
*Operating Capacity Factors	76	85	85	85	85
Scheduled Mid-cycle Outage Days	37	17	17	17	17
Estimated Coastdown Days	1	5	3	2	0
Core Full Power Days	345	405	410	410	410

Unit 2

	<u>Cycle 3</u>	<u>Cycle 4</u>	<u>Cycle 5</u>	<u>Cycle 6</u>	<u>Cycle 7</u>
Operating Cycle Length (Days)	618	510	502	501	506
*Operating Capacity Factors	61	85	85	85	85
Scheduled Mid-cycle Outage Days	0	17	17	17	17
Estimated Coastdown Days	12	9	2	1	6
Core Full Power Days	364	410	410	410	410

ATP:OCM 01/03/86

Sequoyah Nuclear Plant Quarterly Schedule Summary

This schedule summary includes outage information from the first quarter of FY 86. Plans for the remainder of FY 86 and subsequent fiscal years will be included after the impact of employee concerns and Environmental Qualification (EQ) work is accurately defined.

The unit 1 refueling and unit 2 forced outage schedules have been revised on a biweekly basis since November 1985 as a result of required Environmental Qualification work. The total scope of work to be performed has not been completely defined; however, at least 28 Engineering Change Notices (ECNs) have been issued this FY and 21 scheduled ECNs are in work or have been completed. At least 6 ECNs have not been issued and 4 of these have not been scheduled. At least 31 scheduled ECNs are in work or have been completed since the outages began.

TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant

P. O. Box 2000

Soddy-Daisy, Tennessee 37379

January 10, 1986

Nuclear Regulatory Commission
Office of Management Information
and Program Control
Washington, DC 20555

Gentlemen:

SEQUOYAH NUCLEAR PLANT - MONTHLY OPERATING REPORT - DECEMBER 1985

Enclosed is the December 1985 Monthly Operating Report to the NRC for Sequoyah Nuclear Plant.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

P.R. Wallace

P. R. Wallace
Plant Manager

Enclosure

cc (Enclosure):

Director, Region II
Nuclear Regulatory Commission
Office of Inspection and Enforcement
101 Marietta Street
Suite 3100
Atlanta, GA 30323 (1 copy)

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339 (1 copy)

Director, Office of Inspection
and Enforcement
Nuclear Regulatory Commission
Washington, DC (12 copies)

Mr. A. Rubio, Director
Electric Power Research Institute
P. O. Box 10412
Palo Alto, CA 94304 (1 copy)

Mr. R. C. Goodspeed
MNC 461
Westinghouse Electric Corporation
Pittsburgh, PA 15230 (1 copy)

Mr. K. M. Jenison, Resident NRC Inspector
Sequoyah Nuclear Plant

IE24
1/1

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer