

see ltr. to Flouy
from J. Pepin
2/28/85
WM-48

DEPARTMENT OF ENERGY
ALBUQUERQUE OPERATIONS OFFICE
CONTRACT NO. DE-AC04-83AL18796

Draft Radiological and Engineering Assessment

Vicinity Property No. NIIR 032

Remedial Actions
Contractor
for the
Uranium Mill Tailings
Remedial Actions
Project



MORRISON
KNUDSEN

WMFO-7

NR FILE CENTER COPY

9707090130 850227
PDR WASTE
WM-48 PDR

Vicinity Property No. 032

WM-48

DRAFT
THE RADIOLOGICAL AND ENGINEERING ASSESSMENT
AND FINAL DESIGN
FOR
PROPERTY
DU-032
February 27, 1985

PREPARED FOR
URANIUM MILL TAILINGS REMEDIAL ACTION PROJECT OFFICE
UNITED STATES DEPARTMENT OF ENERGY

PREPARED BY
MORRISON-KNUDSEN COMPANY, INC.

NOTE:
SUPPLEMENTAL STANDARDS

URFO-7

NRC FILE CENTER COPY

TABLE OF CONTENTS

1.0 Executive Summary

- 1.1 Introduction
- 1.2 Evaluation and Recommendation

2.0 Engineering Field Survey

- 2.1 Property Description
- 2.2 Existing Facilities and Structures

3.0 Radiological Survey and Assessment

- 3.1 Gamma Exposure Rate Survey
- 3.2 Borehole Survey
- 3.3 Radon/Radon Daughter Survey
- 3.4 Estimated Extent of Contamination
- 3.5 Supplemental Standards

4.0 Engineering Assessment

- 4.1 Evaluation of Options
- 4.2 Recommendation

5.0 Technical Specifications

6.0 Construction Drawing

DU-032-020 Excavation & Restoration Plan DU-032

FIGURES

- 2.1 Vicinity Map DU-032
- 2.2 Site Plan DU-032
- 2.3 Property Photos
- 2.4 Property Photos
- 3.1 Radiological Survey Data DU-032
- 4.1 Excavation & Restoration Plan DU-032

TABLES

- 2.1 Property Survey Data
- 3.1 Outdoor Gamma Survey
- 3.2 Borehole Survey
- 3.3 Angle Hole Survey
- 4.1 Costs
- 5.1 Index of Technical Specifications

APPENDIX

- A. Survey Data Logs

1.0 EXECUTIVE SUMMARY

1.1 Introduction

Property DU-032 is a private residence located at 460 San Juan Drive, Durango, CO.

1.2 Evaluation and Recommendation

1.2.1 Residual Radioactive Material Involvement

There are two areas of contamination located in the yard area of this property.

1.2.2 Recommended Remedial Action Option

The recommended option is to remove the contaminated material.

Due to severe time constraints, the field survey crew was unable to get a core drilled in the sidewalk or street. Unidentified contamination may, therefore, extend under the front sidewalk and San Juan Drive. It is recommended that if contamination is found during remedial action to extend under this area, the contamination be left in place in accordance with the criteria of 40 CFR 192.21(c), "Criteria for Applying Supplemental Standards."

1.2.3 Estimated Costs

The estimated cost for removal of the contaminated material and restoration of the property is \$15,700.00.

1.2.4 Schedule

The estimated duration of the remedial action effort is 5 to 10 days.

2.0 ENGINEERING FIELD SURVEY

2.1 Property Description

2.1.1 Property Use and Occupancy

Property DU-032 is a private residence located at 460 San Juan Drive, Durango, Colorado and owned by Floyd T. Denton. The map in Figure 2.1 illustrates the property's vicinity location.

2.1.2 Legal Description

The legal description as recorded with the La Plata County Recorder's Office in Deed Book No. 320, Page 298 follows:

Lot Six (6) in Block One (1), Thompson's Addition to the City of Durango, together with all improvements thereon situate.

2.1.3 Bordering Properties

The lot is zoned R-1, Residential District. It is located in a residential area less than 2-1/4 miles northeast of the old Vanadium Corporation of America mill tailings site. The property is bounded on the north by a residence; on the east by a residence; on the south by San Juan Drive; and on the west by a residence.

2.2 Existing Facilities and Structures

2.2.1 Structures

The residence is a single story wood frame structure with asbestos lap siding on a concrete foundation. A two car asphalt paved driveway extends from the street to the southwest corner of the house and narrows to one car width along the west side of the house. Concrete sidewalks are located along the street just outside the south property line, from the driveway to the covered concrete front porch, and from the end of the driveway out into the rear yard.

A prefabricated metal shed on a concrete slab is located in the northwest corner of the rear yard. A narrow concrete curb borders the entire west lot line and most of the east property line. Two large sheet metal concentric circular planters are located in the rear yard, as well as a clothes line.

Front and rear yards are grassed. The rear yard is fenced on the east and west sides with a white picket fence atop the concrete curb and on the north side with a large wood plank fence. Two small shrubs have been planted near a large garden plot in the northeast corner of the rear yard.

The residence is less than 50 years old and therefore meets the requirements of Stipulation I.a. of the Programmatic Memorandum of Agreement between the DOE, the Colorado Historic Preservation Officer, and the Advisory Council on Historic Preservation.

2.2.2 Utilities

Utilities are serviced to the property as follows:

Electric power - Overhead to north side of house

Telephone - Overhead to east side of house

Water - Underground from San Juan Drive main to south side of house

Gas - Underground from utility right-of-way on north to east side of house

Sewer - Underground from San Juan Drive main to south side of house

2.2.3 Site Plan and Survey Data

See Figure 2.2 for a site plan of the property. Property survey data and photos are presented in Table 2.1 and Figure 2.3 and Figure 2.4.

Table 2.1

PROPERTY SURVEY DATA

GENERAL:

Site Location: Durango

Property Address: 460 San Juan Drive

Owner's Name: Floyd T. Denton Address: Same

Lot No.: 6 Property Type: Residence

Occupancy Group: Adults: N/A Children: N/A

Survey Completed By: R. Livengood/C. Sanders-Meena Date: 5-17-84

Property Description - Exterior:

Dwelling: Sq. Ft.: N/A

Levels: Single Story with Crawl Space

Construction Type: Wood Frame with Asbestos Lap Siding

Foundation: 32" High Concrete Perimeter Wall

Garage: None

Storage Bldg: Prefab: 6-1/2'x8' Metal on Concrete Slab in NW Corner of Backyd

Other: _____

Improvement Additions: None Porches: Covered Conc South Side

to Dwellings: Deck: None Patio: None

Other: _____

Driveway: Concrete: _____ Paved: Two Car from Street

Gravel: _____ Other: _____

Sidewalks: Concrete/Paved: As Noted on Drawing

Other: _____

Fences/Gates: Wood: 4' White Picket on East/West Sides Back Yard; 6' Wood
Along Back (North) of Lot

Radiological and Engineering Assessment: Property DU-032

Table 2.1 (cont'd)

PROPERTY SURVEY DATA

Site Location: Durango
Property Address: 460 San Juan Drive
Electric Line Location: Overhead to North Side of House
Gas Line Location: Underground from Utility ROW on North to East Side House
Water Line Location: Underground from San Juan Drive main (See Drawing)
Sewage Line Location: Underground from San Juan Drive main (See Drawing)
Telephone Line Location: Overhead to East Side of House

Building Codes and Zoning:

<u>Codes</u>	<u>Local</u>	<u>State</u>	<u>Federal</u>
<u>Building Work</u>	<u>UBC</u>		
<u>Plumbing</u>			
<u>HVAC</u>			
<u>Electrical</u>			
<u>Other</u>			


Zoning District: City of Durango

Present Dwelling Zoning: R-1 Residence District

Setbacks: Front: _____
Rear: _____
Side: _____
Other: _____


Photographs:

<u>Roll Frame</u>	<u>Description</u>	<u>Direction</u>
<u>3-4</u>	<u>Front of House</u>	<u>Looking North</u>
<u>3-3</u>	<u>Rear of House</u>	<u>Looking South</u>
<u>3-2</u>	<u>Rear of Yard</u>	<u>Looking Northwest</u>
<u>3-1</u>	<u>Rear of Yard</u>	<u>Looking Northeast</u>



OLD VANADIUM CORP
MILL TAILINGS SITE


CITY OF



LEGEND

W	WATER LINE
G	GAS LINE
GM	GAS MAIN
S	SEWER LINE
SM	SEWER MAIN
STM	STORM SEWER
E	ELECTRICAL LINE
T	TELEPHONE LINE
TV	CABLE TV
---	PROPERTY LINE
- - -	FENCE LINE
⊙	METER
⊗	VALVE
●	PROPERTY PIN
●	POWER POLE

NOTE: OVERHEAD SERVICE DENOTED BY SOLID LINE.
UNDERGROUND SERVICE DENOTED BY DASHED LINE.



**ANSTEC
APERTURE
CARD**

Also Available on
Aperture Card

9707090130-02

U. S. DEPARTMENT OF ENERGY
ALBUQUERQUE, NEW MEXICO

FIGURE 2.2
SITE PLAN DU-032

DURANGO, COLORADO
URANUM MILL TAILINGS REMEDIAL ACTION PROJECT

DESIGNED BY
DRAWN BY
CHECKED BY
APPROVED BY

DATE

NR

DATE

DOE PROJECT MANAGER

NR

DATE

DOE PROJECT ENGINEER

NR

DATE

PROJECT NO.

DE-AC04-83AL18796

DRAWING NO.

DU-032-010

REV

A




MORRISON
KNUDSEN

NO.	DATE	REVISIONS	BY	CHECKED BY	APPROVED BY	DATE	BY	CHECKED BY	APPROVED BY	DATE
A	02/83	FINAL REA SUBMITTAL	DDY	WLP	WLP					




Front of House Looking North




Rear of House Looking South

Figure 2.3 Property Photos



Rear of Yard Looking Northwest



Rear of Yard Looking Northeast

Figure 2.4 Property Photos

3.0 RADIOLOGICAL SURVEY AND ASSESSMENT

3.1 Gamma Exposure Rate Survey

3.1.1 Survey Method

The outdoor contaminated areas identified in the inclusion survey (Results of the Radiological Survey at Property DU-032, ORNL, May 1983) were surveyed in accordance with the RAC UMTRA Procedure 019. The survey was made on a 10' x 10' grid. A surface scan was made of the entire gridded yard with a gamma scintillometer to identify the boundary of the contamination. Gamma readings were made within one foot of the house on all sides of the structure.

An indoor gamma survey was not conducted inside the building since the inclusion survey reported that no contamination is present in or under the structure.

3.1.2 Survey Results

Surface gamma readings on the property range from 15 to 66 micro R/hr (Table 3.1). This may be compared with the background for the Durango site of 14 micro R/hr. Table 3.1 lists surface gamma readings greater than 16 micro R/hr.

3.2 Borehole Survey

3.2.1 Survey Method

A gasoline-powered hand auger was used to drill 4-inch diameter holes in and around the regions identified as contaminated during the gamma survey. The holes were surveyed in compliance with the RAC UMTRA Procedure 018. Holes were also angled under the footings of the structure inside the crawl space.

3.2.2 Survey Results

Contamination was found in 11 of the 16 outdoor holes augered. The location and depth of the contamination is described in Table 3.2 and is shown in Figure 3.1.

3.3 Radon/Radon Daughter Survey

No radon/radon daughter surveys were performed inside the buildings at the property, since the inclusion survey reported that no contamination is present in or under the structures. The inclusion survey reported a single radon daughter concentration measurement of 0.01 WL inside the house.

3.4 Estimated Extent of Contamination

Two areas of contamination were identified in the survey.

Area A has an estimated depth of contamination of 18 inches, but could be 24 inches in some locations. Contamination above guidelines could exist underneath the paved driveway, but this has not been determined. When Area A has been excavated, the walls of the driveway should be checked; if contamination is present, the driveway also should be added to Area A.

Area B is in the rear of the property and has an estimated depth of contamination of 18 inches.

3.5 Supplemental Standards

Due to severe time constraints, the field survey crew was unable to get a core drilled in the sidewalk or street. Unidentified contamination may, therefore, extend under the front sidewalk and San Juan Drive. It is recommended that if contamination is found during remedial action to extend under this area, the contamination be left in place in accordance with the criteria of 40 CFR 192.21(c), "Criteria for Applying Supplemental Standards."

Table 3.1
OUTDOOR GAMMA SURVEY
Property DU-032

POINT	uR/hr
0+00,20R	22
0+00,30R	24
0+00,40R	33
0+00,50R	19
0+10,20R	33
0+10,30R	26
0+10,40R	25
0+10,50R	20
0+20,00R	18
0+20,20R	30
0+20,30R	28
0+20,40R	28
0+20,50R	21
0+40,08R	24
0+70,00R	21
0+70,10R	17
0+70,50R	17
0+80,00R	23

Radiological and Engineering Assessment: Property DU-032

Table 3.1 - Cont'd.
OUTDOOR GAMMA SURVEY
Property DU-032

POINT	uR/hr
0+80,50R	18
0+90,00R	28
1+00,00R	29
1+00,50R	18
1+10,00R	28
1+10,10R	16
1+10,20R	16
1+10,30R	24
1+10,50R	17
1+20,00R	27
1+20,10R	19
1+20,20R	19
1+20,30R	20
1+20,40R	20
1+20,50R	18
1+30,00R	66
1+30,10R	22
1+30,20R	19
1+30,30R	20

Table 3.1 - Cont'd.
OUTDOOR GAMMA SURVEY
Property DU-032

POINT	uR/hr
1+30,40R	19
1+30,50R	17
0+33,20R	26
0+33,30R	20


Table 3.2
BOREHOLE SURVEY
Property DU-032


HOLE	LOCATION	CONTAMINATION DEPTH
1	0+67,02R	None
2	0+87,09R	None
3	1+00,02R	0-12"
4	1+29,02R	0-18"
5	1+28,22R	0-6"*
6	1+10,15R	None
7	1+10,45R	None
8	0+00,20R	0-18"
9	0+00,40R	0-24"
10	0+20,20R	0-18"
11	0+20,40R	0-18"
12	0+26,40R	0-18"
13	0+26,20R	0-18"
14	0+36,6R	0-18"
15	0+44,6R	0-18"
16	0+31,9R	0-18"

*Low-level contamination present.

Table 3.3
ANGLE HOLE SURVEY
Property DU-032

HOLE	LOCATION (All at Crawl Space)	CONTAMINATION DEPTH
H-1	North Wall	None
H-2	Southeast Corner by Water and Sewer Line	None
H-3	Under Sewer Line	None
H-4	South Wall	None
H-5	West Wall	None
Note: Could not dig deeper - rocky soil.		





CL SAN JUAN DR

LEGEND

⊙ B AUGER HOLE DESIGNATION

▲ H-5 ANGLE HOLE DESIGNATION

ESTIMATED DEPTH OF CONTAMINATION



**ANSTEC
APERTURE
CARD**

Also Available on
Aperture Card

9707090130-03

U. S. DEPARTMENT OF ENERGY
ALBUQUERQUE, NEW MEXICO

DESIGNED BY
d/w

CHECKED

REVIEWED

RECOMMENDED

APPROVED

NR

DATE

DOE PROJECT MANAGER

NR

DATE

DOE PROJECT ENGINEER

NR

DATE

FIGURE 3.1

RADIOLOGICAL SURVEY DATA DU-032

DURANGO, COLORADO

URANUM MILL TAILINGS REMEDIAL ACTION PROJECT

PROJECT NO.

DE-AC04-83AL18796

DRAWING NO.

DU-032-015



MORRISON
KNUDSEN

FINAL REA SUBMITTAL

REVISIONS

DATE

BY

CHECKED

BY

APPROVAL

LOC

APPROVAL

DATE

FILE

APPROVAL

DATE

ENGINEERING ASSESSMENT

Engineering options were formulated and evaluated based on the radiological and engineering assessment for this property. Factors forming the basis of the evaluation were: the extent and location of the contamination, construction costs, and required demolition and constructibility for the various options. Results of the evaluation are detailed below.

4.1 Evaluation of Options

4.1.1 Options

Two options were evaluated for property DU-032:

1. No action should be taken.
2. Complete decontamination of the property including retrieval of the contaminated material and restoration of the property. See Figure 4.1 Excavation and Restoration. Plan for scope of work.

Option 2 includes the following:

- o Remove, salvage, and replace porch railing and shore roof.
- o Demolish, remove, and replace concrete porch, sidewalk, shed slab and concrete area of driveway.
- o Demolish and remove asphalt driveway and replace with concrete.
- o Remove and replace shrubs and planter.
- o Remove and replace fence.
- o Excavate contaminated materials in areas as shown in Figure 4.1.
- o Backfill excavated areas with common fill. In lawn area, top with topsoil and sod. In concrete area, top with structural fill.

4.1.2 Costs

Estimated costs for the activities associated with Option 2 are detailed in Table 4.1. Costs include labor, insurance, material, equipment, supplies, overhead, profit, and contingency. All costs are listed in 1985 dollars. It is anticipated that the time required for the subcontractor to complete the work will be 5 to 10 days.

4.2 Recommendation

The limited cost and amount of remedial action work precluded evaluating any more than these two options. The results of the radiological assessment concluded that contamination levels on the property exceeded EPA guidelines. Therefore, based on these guidelines, it is recommended that Option 2, decontamination of the property, be pursued. The total estimated cost for Option 2 is \$15,700.00.

Table 4.1
OPTION 2 COSTS

Activity	Unit Price	Quantity	Estimated Cost
Remove Porch Railing and Shore Roof	LS		170.00
Remove Concrete Porch, Sidewalk, Driveway Slab and Shed Slab	3.00	330 sf	990.00
Remove Asphalt Driveway	.20	598 sf	119.60
Relocate and Replace Metal Shed	LS		300.00
Remove and Salvage Fence	2.75	45 lf	123.75
Excavation (Machine)	8.30	208 cy	1,726.40
Common Backfill	7.20	150 cy	1,080.00
Structural Fill	26.40	17 cy	448.80
Topsoil	26.40	41 cy	1,082.40
Sod	3.00	186 sy	558.00
Construct Concrete Porch, Sidewalk, Shed Slab, and Driveway	3.50	928 sf	3,248.00
Replace Planter	LS		105.00
Replace Fence	8.20	45 lf	369.00
Replace Shrubs	50.00	12 ea	600.00
Subtotal			\$10,920.95
5% Subcontractor's Contingency			564.05
20% Overhead and Profit			2,184.19
Subtotal			\$13,651.19
15% Contingency			2,047.68
Total (Rounded)			\$15,700.00

5.0 TECHNICAL SPECIFICATIONS

Technical specifications applicable to this property are indexed in Table 5.1 . Specifications previously approved by the Department of Energy (DOE) are noted in the table. Also listed are specifications not previously submitted to the DOE which require approval. The text for these additional specifications follow the table.



Table 5.1
INDEX OF TECHNICAL SPECIFICATIONS

Description	Specifications	
	Previously Approved	Specifications Requiring DOE Approval
Division 2 - Site Work		
SECTION 02050	DEMOLITION	X
SECTION 02110	CLEARING AND GRUBBING	X
SECTION 02130	CONTAMINATED MATERIAL REMOVAL	X
SECTION 02200	EXCAVATION AND BACKFILL	X
SECTION 02480	LANDSCAPING	X
SECTION 03300	CAST-IN-PLACE CONCRETE	X

6.0 CONSTRUCTION DRAWINGS

Listed below is an index of the construction drawings required for remedial action on this property. Copies of the drawings follow this section.

<u>Drawing Number</u>	<u>Drawing Title</u>
DU-032-020	Excavation & Restoration Plan DU-032



APPENDIX A
SURVEY DATA LOGS

OUTDOOR GAMMA SCREENING SURVEY DATA SHEET

LOGGING CREW:

E. COUCH
L. BENALLY, JR
E. SCHULTZ

 SHEET 1 OF 5 PAGE 1

 DATE: JUNE 25, 1984

 PROPERTY ID: DU-032

INSTRUMENT ID NO.: _____

BACKGROUND CALCULATION:

 #1 _____ + #2 _____ + #3 _____ = _____ - 3 = 11,500 COUNTS/1MIN

AREA: _____		AREA: _____		AREA: _____		AREA: _____	
POINT ID	READING COUNTS/1MIN	POINT ID	READING COUNTS/1MIN	POINT ID	READING COUNTS/1MIN	POINT ID	READING COUNTS/1MIN
0100+00R	14450	0140+00R	14710	0190+00R	56080	0110+00R	154910
0100+10R	14180	0140+08R	43080	0190+10R	15670	0110+10R	37770
0100+20R	37660	0140+46R	14300	0190+20R	14010	0110+20R	27450
0100+30R	43090	0140+50R	15670	0190+30R	14420	0110+30R	31920
0100+40R	70830	0150+00R	13700	0190+46R	14570	0110+40R	26910
0100+50R	27560	0150+08R	14320	0190+50R	15540	0110+50R	22230
0110+00R	15890	0150+46R	15850	01100+00R	57440	0133+20R	49020
0110+10R	11720	0150+50R	14600	01100+10R	17210	0133+30R	30160
0110+20R	70580	0160+00R	14150	01100+20R	14870		
0110+30R	48230	0160+08R	14140	01100+30R	14010		
0110+46R	47660	0160+46R	15580	01100+40R	14040		
0110+50R	29790	0160+50R	13690	01100+50R	25510		
0120+00R	23800	0170+00R	34460	01100+100R	55950		
0120+10R	12020	0170+10R	19130	01100+20R	15250		
0120+20R	63890	0170+20R	14270	01100+30R	43240		
0120+30R	58420	0170+30R	13930	01100+40R	15140		
0120+46R	56160	0170+40R	14260	01100+50R	19880		
0120+50R	32750	0170+50R	19030	01120+00R	54320		
0130+00R	18220	0180+00R	41500	01120+10R	27700		
0130+10R	17370	0180+10R	15470	01120+20R	26580		
0130+20R	15870	0180+20R	14580	01120+30R	28970		
0130+30R	17070	0180+30R	13870	01120+40R	29730		
0130+40R	16510	0180+40R	13960	01120+50R	25670		
0130+50R	18980	0180+50R	24220				

 REMARKS: ALL READINGS ARE IN COUNTS PER MINUTE (CPM)
TOP- ARE CONTACT MEASUREMENTS
BOTTOM- READINGS TAKEN 1 METER ABOVE GROUND LEVEL
* Rose and Flower garden - No Bore Holes Drilled

BOREHOLE LOG

LOGGING CREW:

E. COUCH
L. BENNETT, JR
E. SCHULTZ

SHEET 2 OF 5 PAGE 2

DATE: JUNE 25, 1992

PROPERTY ID: DH-032

INSTRUMENT ID NO. _____

AREA: Durango, Colorado

NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED, CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC., IN THE REMARKS SECTION.

①		②		③		④	
HOLE ID: <u>0+67+02R</u>		HOLE ID: <u>0+82+09R</u>		HOLE ID: <u>0+100+02R</u>		HOLE ID: <u>0+129+02R</u>	
TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____	
TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____	
SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____	
DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN
SURFACE		SURFACE		SURFACE		SURFACE	
0"	<u>29560</u>	0"	<u>16620</u>	0"	<u>53510</u>	0"	<u>66860</u>
6"	<u>32010</u>	6"	<u>21100</u>	6"	<u>65920</u>	6"	<u>100990</u>
12"	<u>26850</u>	12"	<u>21640</u>	12"	<u>50010</u>	12"	<u>86200</u>
18"	<u>24440</u>	18"	<u>21370</u>	18"	<u>32310</u>	18"	<u>42150</u>
24"	<u>21840</u>	24"	<u>21000</u>	24"	<u>28640</u>	24"	<u>30070</u>
30"	<u>20570</u>	30"	<u>21880</u>	30"	<u>26460</u>	30"	<u>27250</u>
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS:

BACK Ground Measurement 23,000 CPM
ALL measurements are in Counts Per Minute (CPM)

0+130+23R ————— 0+130+50R
GARDEN AREA
0+115+23R ————— 0+115+50R

} NO Bore Holes Drilled
 } in garden even though
 } most readings indicate area
 } is contaminated. See

BOREHOLE LOG

LOGGING CREW: E. Couch
L. BENNETT, JR.
E. SCHULTZ
 INSTRUMENT ID NO. _____

SHEET 3 OF 5 PAGE 3
 DATE: JUNE 25, 1984
 PROPERTY ID: DH-032
 AREA: Durango, Colorado

NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
 2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED. CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC. IN THE REMARKS SECTION.

⑤		⑥		⑦		⑧	
HOLE ID: <u>0+128+22R</u>		HOLE ID: <u>0+110+15R</u>		HOLE ID: <u>0+110+45R</u>		HOLE ID: <u>0+00+20R</u>	
TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____	
TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____	
SOIL TYPE: <u>⊗</u>		SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____	
DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN
SURFACE		SURFACE		SURFACE		SURFACE	
0"	30260	0"	14430	0"	16160	0"	45480
6"	37490	6"	16450	6"	19830	6"	63470
12"	32980	12"	20050	12"	22230	12"	74900
18" 15"	24460	18"	22450	18"	21150	18"	41890
24"		24"	22520	24" 25"	20690	24"	30950
30"		30" 28"	21090	30"		30"	
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS: Back Ground Measurement 23,000 CPM.
All measurements are in Counts Per Minute (CPM)
⊗ We drilled until large rock and gravel bed prevented further drilling

BOREHOLE LOG

LOGGING CREW: E. Gorch
L. Benally, Jr.
E. Schultz
 INSTRUMENT ID NO. _____

SHEET 4 OF 5 PAGE 4
 DATE: June 25, 1984
 PROPERTY ID: Du-032
 AREA: Durango, Colorado

NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
 2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED, CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC., IN THE REMARKS SECTION.

⑨		⑩		⑪		⑫	
HOLE ID: <u>0100+40R</u>		HOLE ID: <u>0120+20R</u>		HOLE ID: <u>0120+40R</u>		HOLE ID: <u>0126+40R</u>	
TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____		TIME DRILLED: _____	
TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____		TIME LOGGED: _____	
SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____		SOIL TYPE: _____	
DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN
SURFACE		SURFACE		SURFACE		SURFACE	
0"	82350	0"	56240	0"	63170	0"	55010
6"	120550	6"	91260	6"	93740	6"	84960
12"	104900	12"	72460	12"	81480	12"	70850
18"	48890	18"	37420	18"	37590	18"	36150
24"	37450	21"	31430	24"	32430	24"	27750
30"		30"		30"		30"	
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS: Back Ground Measurement 23,000 CPM
All measurements are in Counts Per Minute (CPM)

BOREHOLE LOG

LOGGING CREW: E. Couch
L. BENNY, JR.
E. Schwitzky
 INSTRUMENT ID NO. _____

SHEET 5 OF 5 PAGE 5
 DATE: June 25, 1984
 PROPERTY ID: DH-037
 AREA: Durango, Colorado

NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
 2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED. CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC., IN THE REMARKS SECTION.

(13) HOLE ID: <u>0726120R</u> TIME DRILLED: _____ TIME LOGGED: _____ SOIL TYPE: _____		(14) HOLE ID: <u>073616R</u> TIME DRILLED: _____ TIME LOGGED: _____ SOIL TYPE: _____		(15) HOLE ID: <u>074416R</u> TIME DRILLED: _____ TIME LOGGED: _____ SOIL TYPE: _____		(16) HOLE ID: <u>073118R</u> TIME DRILLED: _____ TIME LOGGED: _____ SOIL TYPE: _____	
DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN
SURFACE		SURFACE		SURFACE		SURFACE	
0"	49550	0"	37870	0"	55300	0"	55430
6"	82730	6"	86870	6"	124720	6"	143100
12"	71790	12"	61470	12"	106330	12"	68940
18"	35840	18"	29160	18"	38580	18"	32590
24"	26650	24"	24220	24"	29440	24"	25200
30"	23240	30" 26"	23880	30"	26980	30"	23270
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS: Back Ground Measurements 23,000 CPM
All measurements are in Counts Per Minute (CPM)
 (X) CORE -- CONCRETE

BOREHOLE LOG

Supplemental Data

LOGGING CREW: Ernest Couch
Edward Schultzy
Julius Buttrick
 INSTRUMENT ID NO. LVD2220 #131982 #1410 #16538

SHEET 1 OF 2 PAGE 1
 DATE: October 16, 1984
 PROPERTY ID: DU-032
 AREA: Durango, Colorado

NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
 2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED, CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC., IN THE REMARKS SECTION.

HOLE ID: <u>N WALL</u>		HOLE ID: <u>H2O+SEWER</u>		HOLE ID: <u>SEWER</u>		HOLE ID: <u>S. WALL</u>	
TIME DRILLED: _____		TIME DRILLED: <u>LINE</u>		TIME DRILLED: _____		TIME DRILLED: _____	
TIME LOGGED: _____		TIME LOGGED: <u>SE</u>		TIME LOGGED: _____		TIME LOGGED: _____	
SOIL TYPE: _____		SOIL TYPE: <u>CORNER</u>		SOIL TYPE: _____		SOIL TYPE: _____	
DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN
SURFACE	<u>16270</u>	SURFACE	<u>17720</u>	SURFACE	<u>16520</u>	SURFACE	<u>17270</u>
0"	<u>17340</u>	0"	<u>16570</u>	0"	<u>17630</u>	0"	<u>19080</u>
6"	<u>19210</u>	6"	<u>19610</u>	6"	<u>19060</u>	<u>8.5"</u>	<u>21320</u>
<u>H 12" 4"</u>	<u>19570</u>	12"	<u>21200</u>	<u>H 12" 4</u>	<u>21670</u>	<u>11" 3"</u>	<u>19840</u>
18"		18"	<u>20010</u>	<u>H 18" 10</u>	<u>22320</u>	18"	
24"		<u>21</u>	<u>20790</u>	<u>H 24" 12</u>	<u>22520</u>	24"	
30"		30"		30"		30"	
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS: H = horizontal, H # number equals the
holes was angled and # of inches under
spread footing, background is 23000 cpm, all
counts in cpm (In crawl space)

BOREHOLE LOG

Supplemental Data

LOGGING CREW: Ernest Concl
Edward Schultky
Julius Petrilly

SHEET 2 OF 2 PAGE 2

DATE: October 16, 1984

PROPERTY ID: DV-032

INSTRUMENT ID NO. U0220 #34982 / 100 #1652X

AREA: Orange, Colorado

- NOTES: 1. ALL HOLES ARE 4" DIA. UNLESS OTHERWISE NOTED.
2. RECORD UNUSUAL CONDITIONS, SUCH AS THE PRESENCE OF WATER IN BOREHOLES AND DEPTH, CASING TYPE AND THICKNESS IF USED, CONCRETE CORES AND THICKNESS, OBSTRUCTIONS, UTILITIES, ETC., IN THE REMARKS SECTION.

HOLE ID: <u>W. WALL</u>	HOLE ID: _____	HOLE ID: _____	HOLE ID: _____
TIME DRILLED: _____	TIME DRILLED: _____	TIME DRILLED: _____	TIME DRILLED: _____
TIME LOGGED: _____	TIME LOGGED: _____	TIME LOGGED: _____	TIME LOGGED: _____
SOIL TYPE: _____	SOIL TYPE: _____	SOIL TYPE: _____	SOIL TYPE: _____

DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN	DEPTH	COUNTS/.1MIN
SURFACE	<u>17100</u>	SURFACE		SURFACE		SURFACE	
0"	<u>18170</u>	0"		0"		0"	
<u>82"</u>	<u>19170</u>	6"		6"		6"	
12"		12"		12"		12"	
18"		18"		18"		18"	
24"		24"		24"		24"	
30"		30"		30"		30"	
36"		36"		36"		36"	
42"		42"		42"		42"	
48"		48"		48"		48"	
54"		54"		54"		54"	
60"		60"		60"		60"	
66"		66"		66"		66"	
72"		72"		72"		72"	
78"		78"		78"		78"	
84"		84"		84"		84"	
90"		90"		90"		90"	
96"		96"		96"		96"	

REMARKS: Shallow shovel holes are due to
rocky ground in crawl space, background
is 23000 cpm, all counts in CPM.



MORRISON-KNUDSEN COMPANY, INC.

UMTRA PROJECT OFFICE
P.O. BOX 9136
ALBUQUERQUE, NEW MEXICO 87119