NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block) EXCILIPY 8XMP (1)								APPROVED BY OMB NO. 3150-0104 EXPIRES 04/30/98 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY INFORMATI COLLECTION REDUEST 50:0 HRS REPORTED LESSONS LEARNED ARE INCORPORATED IN THE LICENSING PROCESS AND FED BACK TO INDUSTRY. TORWARD COMMENTS REGARIU BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T.6.F3 U.S. NUCLEAR REGULATORY CUMMISSION WASHINGTON, DC 20055-0001, AND TO T PAPERWORK REDUCTION PROJECT (2150-0104), OFFICE OF MANAGEMENT AND BUDDI WASHINGTON, DC 20503.								
								DOCK	TINUMBER	1000.221	FACE (3)					
Duane	Arnok	i Ener	gy Cente	er							03	5000-331			OF 3	
nnras Inadeqi Lack of	uate Si f Atter	arveilla ition to	ance Tes Detail	sting of l when Pr	Reac	tor Wa ising a '	ter Clea Fechnic	anup A tal Spe	rea D cifica	iffer tion	ential T Amendi	emperature I nent.	solatic	on Logic	Caused by	
EVEN MONTH 1	ST DAT:	(5) VEAR	VEAD	TRNUM	ER (6) T HEUTENNA	REPO	DRT DAT	E (7)	FATT	TTY NAME	OTHER FACILT	TIES IN	VOL VED (() RAHITE	
angra i n	LINT	TEAN	TEAM.	NUMBER		NUMBER	Month	EVA I	106.1	FACILITY NAME				05000-331		
07	24	97	97 .	009		00	08	21	97	FACIL	FACILITY NAME			05000-331		
OPERA	TING		THIS RE	FORT IS S	TRAI	TTEDPU	RSUANT	torm	REQUI	REM	NTS OF 1	OCFR §: (Check	one of m	iore) (11)	PERSONAL PROPERTY AND INCOME.	
FOW	TR	1 Determinants	20.2201(b) 20.2203(a)(1)			20.2203(a)(2)(v) 20.2203(a)(2)(v)			X 50.73(a)(2)(i) 50.73(a)(2)(ii)				50.73(a)(2)(* (ii)			
LEVEL (10) 100		20.2203(a)(2)(1)				20.2203(a)(3)(11)			_	50.73(a)(2)(111)	2)(11)				
			20.2203(a)(2)(ii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iii) 20.2203(a)(2)(iv)				20.2203(a)(4) 50.36(c)(1) 50.36(c)(2)				50.73(a)(2)(iv) a)(2)(v)	(iv)		R distract below or	
										50.73(a)(2)(VII)				NRC Form MitA		
CAUSE	51	STEM	COMPONE	NT MAN	E ONE LINE FO		H COMP PORTABLE 0 NPRDS		CAU	EE DES	SYSTEM	COMPONENT	T (13) MANO	FACTURER	REPORTABLE TO NPRDS	
		a the second sector of														
		s	TPPLEME	NTAL REP	ORT	EXPECT	D (14)				E	PECTED BMISSION	MONT	H 54	YEAR	
YES (If yes	s, comple	SI te EXPEC	TED SUBN	NTAL REP MISSION D	ORT ATE).	EXPECT	eb (145		<u> </u>		su	PECTEB BMISSION	MONT	H DAY	YEAR	

Following discovery, the existing annual channel calibration tests were successfully performed, which fully satisfied the requirements of the CFT. Other corrective actions include revising the procedure to incorporate the CFT definition, Licensing department briefings, and continued reviews of surveillance test procedures as part of the conversion to ITS. The actual and potential safety consequences associated with this event were minimal as all equipment performed properly when tested.

97082	270064	970821
PDR	ADOCK	05000331
S		PDR

NRC FORM 366A 14-95	of the second		U.S. NUCLEAR REGULAT	ORY (OMMIS	SION	
LICENSE	E EVENT REPORT (I						
FACILITY NAME (1)	DOCKET	DOCKET LER NUMBER (6) PAGE					
		YEAR	SEQUENTIAL REVISION NUMBER NUMBER	2	OF	3	
Duane Arnold Energy Center	05000-331	97	009 00				

TEXT (If more space is required, use additional copies of NRC Form 366.4) (17)

1. DESCRIPTION OF EVENT:

On July 24, 1997, during a review of surveillance test procedures (STPs) for conversion to the Improved Standard Technical Specifications (ITS), a deficiency in STP 42A016-Q,A, "Reactor Water Cleanup System Leak Detection Instrument Functional Test and Calibration," was discovered. This STP had been credited for implementing the Channel Functional Test (CFT) required by TS Table 4.2-A for the Reactor Water Cleanup (RWCU) Area Ventilation Differential Temperature-High Isolation.

The procedure, which also includes the CFT for RWCU Area Temperature -High, had incorporated an exception to the CFT definition which was approved in the first revision to DAEC TS. From 1974 to 1993, TS Table 4.2-A had listed one line item with a note (8) for both the High Area Temperature and High Ventilation Area Differential Temperature surveillances. Note (8) was the exception which stated "The functional test will consist of comparing the analog signal of the active thermocouple element feeding the isolation logic to a redundant thermocouple element." TS Amendment 193, implemented on July 21, 1993, split the two separate surveillances into two line items in Table 4.2-A and changed note (8) to note (a), but only included the footnote on the line item for the RWCU Area Temperature High surveillance. This essentially deleted the exception for the Differential Temperature surveillance and resulted in a non-compliance that was not detected during the implementation of the amendment.

Upon discovery of this issue, actions in accordance with TS 3.2.A.1.B and Action 23 of Table 3.2-A were taken and a 1 hour Limiting Condition for Operation (LCO) was entered. The annual channel calibrations were performed satisfactorily and the LCO was exited on July 24, 1997.

II. CAUSE OF EVENT:

The cause of the event was lack of attention to detail when processing and implementing TS Amendment 193. When the new line item was added for the RWCU Ventilation Area Differential Temperature-High surveillance without the footnote, the change in surveillance requirements was not recognized. TS Amendment 193 included an extensive revision of TS instrumentation tables and surveillance frequencies.

III. ANALYSIS OF EVENT:

Upon discovery, the annual channel calibrations for the RWCU leak detection instrumentation, which incorporate full CFTs were performed satisfactorily for both RWCU leak detection channels. The last channel calibration was performed on December 2, 1996, which also demonstrated satisfactory performance of the CFTs.

High differential temperature in the RWCU system equipment room is sensed by six differentialtemperature switches. High ambient temperature in the RWCU system equipment room is sensed by six temperature switches. The tripping of either channel initiates the isolation of the cleanup system. The basis for this setting was so that a leak of 8 to 10 gpm would be detected. Additionally, high ambient

NRC FORM 366A 34.950	de ender anderer in de Alexandri Lare die de Laren in de Laren de Sander		U.S. NUCLEAR REGU	ATC	DRY C	OMMIS	SION
LICENSE	E EVENT REPORT (I EXT CONTINUATION	ER)					
* FACILITY NAME (I)	DOCKET	T	LER NUMBER (6)	1	ana ana a	PAGE (3)
		YEAR	SECUENTIAL REVIS NUMBER NUME	ICIN IER	3	OF	3
Duane Arnold Energy Center	05000-331	97	009 00				

TEXT (If more space is required, use additional copies of NRC Form 3664) (17)

III. ANALYSIS OF EVENT: (continued)

temperature in the southeast reactor building first floor is sensed by four temperature switches. Two thermocouples are located above the Transverse In-Core Probe (TIP) room mezzanine and two are located above the Control Rod Drive (CRD) master control area for detection of a leak in the RWCU return piping above the TIP room. Sufficient redundant operable leak detection instrumentation existed to ensure the leak detection function was maintained.

The actual and potential safety consequences of this event were minimal. There were no other structures, systems, or components inoperable at the time of discovery that contributed to the event.

IV. CORRECTIVE ACTIONS:

- STP 42A016-Q,A will be revised to incorporate the full CFT for the RWCU Area Ventilation Differential Temperature-High Isolation instrumentation. This action will be completed by September 3, 1997, which is prior to the next scheduled quarterly CFT.
- 2. Appropriate Licensing personnel have received a briefing regarding best practices and industry techniques regarding attention to detail within the TS Amendment process.
- 3. As a long term corrective action for this event and as part of an ongoing effort at the DAEC for converting to the ITS, all the ITS required surveillance procedures will receive an equivalent level of review to ensure they meet all requirements. This corrective action will be completed in accordance with the schedule for implementation of the ITS. It should be noted that this event was discovered during the review process for ITS required test procedures.

V. ADDITIONAL INFORMATION:

A. EIIS System Codes: Reactor Water Cleanup: CE Containment Isolation Control System: JM

B. Previous Similar Events:

LER 331/97-007-00 submitted to the NRC on July 24, 1997, by letter number NG-97-1303, documented a review of previous similar events. That review is applicable to this LER. This event was discovered by the ongoing reviews associated with conversion to ITS which is also a previous LER corrective action. Therefore, previous corrective actions, though they have not prevented events of this nature, have been successful in their discovery.

This event is being reported pursuant to 10CFR50.73(a)(2)(i)(B).