NRC Perr (9-83)	. 164				LICI	ENSEE EV	ENT RE	PORT	LER)	U.S. NUC AP EX	PROVED ONE NO	RY COMMISSION 3150-0104
ACILITY	-								DX	CKET NUMBER	(2)	PAGE (S)
F	point	Bea	ach	Nuclear	Plant				0	15 0 0	0 3 0 1	1 OF0 5
TITLE (4	Conta	inme	ent	Isolatio	n Valv	e Leaka	age in	Exce	ess of Te	ech Spe	c Limits	
EVI	INT DATE	(6)		LER NUMBER IS	u 1	REPORT D	ATE (7)		OTHER F	ACILITIES INVOL	VED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH DAY	YEAR		FACILITY NAM	ES	DOCKET NUMBER	(\$)
											0   5   0   0	
1 10	014	8 6	816	- 01015	- ol 1	0 20 19	8 17		None		0 151010	
00	D I I I		THIS RE	PORT IS SUBMITTE	D PURSUANT T	O THE REQUIR	EMENTS OF 10	CFR §: 10	Check one or more of	t the following) (11	)	
M	008 (0)		20	.402(b)		20.406(e)			50.73(a)(2)(iv)		73.71(b)	
LEVE			20	.436(a)(1)(i)		60.36(e)(1)			80.73(a)(2)(v)		73.71(e)	with in Abstract
(10)		10	20	.408(a)(1)(H)	X	60.73(a)(2)(1)		H	60.73(6)(2)(viii)(A		below and in 366A/	Text, NRC Form
			20	.408(a)(1)(lv)		60.73(a)(2)(ii)			60.73(a)(2)(viii)(B	)		
			20	).406(a)(1)(v)		90.73(a)(2)(iii)			50.73(a)(2)(x)			
NAME					L	CENSEE CONTA	ACT FOR THIS	LER (12)		1	TELEPHONE NUM	BER
										AREA CODE		
с.	W. F	ay,	Vic	e Presid	ent-Nuc	clear F	Power			41114	212111-	12181110
				COMPLETE	ONE LINE FOR	EACH COMPON	IENT PAILURE	DESCRIBE	D IN THIS REPOR	T (13)	1 1	
CAUSE	SYSTEM	COMP	ONENT	MANUFAC- TURER	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC	REPORTABLE TO NPRDS	
X	BD	II	ISIV	R131410	Yes							
				BUPPLEME	INTAL REPORT	EXPECTED (14	u	11			MONTH	DAY YEAR
	18 (If you, c	ompiete l	XPECTER	D SUBMISSION DATE	1)		0			SUBMISS DATE (1	ED ION (5)	
ABSTRA	CT /Limit	0 1400 H		approximately fifteen	single-space type	ewritten lines/ [1]	6)					<u> </u>
	On Oc react valve by Te leaka a new On Oc letdo excee valve repla	ctob cor echn age v va ctob own eded e wa aced	er 3 cool 55A) ical prob lve er 8 heat the s di	3, 1986, lant pump ) leak ra l Specifi plems wit prior to 3, 1986, t exchange t exchange t echnic isassembl Post-repa	during compo te exc cation th this o unit during ger sup cal Spe led and air lea	a type eeded s 15.4 valve startu g a type ply ch ecifica i the d hkage w	e "C" ooling the co .4.II. , it w p. e "C" eck va tion l isk O- as mea	leak wate ntain B and as re leak lve imit sure	rate te er suppl nment le d III.B. emoved a rate te (767), 1 s cited and spr d at 2 s	st, the y line ak rate Becau and repl est of t eakage above. ing wer sccm.	check allowed se of pa aced with the excest also This re	d ast th ss
		0.000	3702 2DR 3	180500 8. 900CK 0	70209 500030 PDR	1				IE	52	

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPHUVEL	UMBN	0. 3150-0	104
EXPIRES 8	3/31/85		

FACILITY NAME (1)			DOCKET NUMBER (2)					LER NUMBER (6)							T	PAGE (3)					
										YEAR		SEO	UENT	AL		NUMB	R		T	Γ	
Point Beach Nuclear Plant	0	15	10	1	0 10	1	З	q	1	8	6-	0	101	5	_	01		12	OF	0	15
TEXT IN more space is required, use additional NRC Form 3064's (117)		-	-	-		-		-	-		_	-	-			-	-	_	-	-	-

### EVENT DESCRIPTION

NRC Form 366A

On September 27, 1986, Unit 2 was shut down for its annual refueling. The total "as-found" leakage for type "B" and "C" local leak rate testing exceeded 0.6 La when excessive leakage through the "A" reactor coolant pump component cooling water (CCW) supply containment isolation valve (755A) and the excess letdown heat exchanger supply check valve (767) was found on October 3, 1986, and October 8, 1986, respectively. The leak rate limit of 0.6 La is required by Technical Specifications 15.4.4.II.B and III.B.

Valve 755A was tested according to procedure; however, the required test pressure of 65 psig could not be achieved in the test volume. An indicated test pressure of 18.3 psig was achieved while an indicated leak rate of greater than 162,000 sccm existed. Note that this leak rate is not the actual leak rate which would exist if the test volume could have been pressurized to 65 psig. Therefore, in view of the test findings, it is assumed that the leak rate of 755A by itself violates the total leakage limits set forth in the Technical Specifications.

755A is a four-inch, 150-pound, carbon steel, check valve model 73908 manufactured by Velan Corporation. This valve is located inside containment in an incoming component cooling water line to the "A" reactor coolant pump. Additional isolation capability is provided by valve 754A located outside containment which can be operated remotely from the control room. Operator action would be required to shut this valve in the event it is needed to establish containment isolation. This valve (754A) was subjected to a type "C" test with satisfactory results. When valve 755A was last tested after its repair prior to the startup of Unit 2 in the fall of 1985, it had a leak rate of 1680 sccm. (See LER 85-002-01). As noted in the supplemental LER submitted May 19, 1986, it was anticipated that the repair was successful, since a similar Unit 1 valve was repaired in 1985 in the same manner and had passed its leak test after a full year of operation.

An inspection of the old 755A check valve was performed after its removal. The disc would hang up slightly when it was manually supported and slowly lowered toward the closed position. It would hit the top of the seat first, and friction from this point of contact would hold the disc slightly away from the bottom portion of the seat. It is possible that after the system was secured as flow was coasting down, the closing motion of the disc was gentle enough that the disc would hang up in a manner similar to that manually simulated.

LICENSEE EVENT	REPORT (LER)	TEXT CONTINUATION
----------------	--------------	-------------------

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED	OMB NO.	3150-0104	
EXPIRES 8	131/85		

FACILITY NAME (1)	DOCKET NUMBER (2)		LE	R NUMBER (6)	PAGE (3)				
		YEAR		SEQUENTIAL NUMBER		REVISION		TT	
Point Beach Nuclear Plant	0 5 0 0 0 0 3 0 3	8 6	-	0 0 5	-	011	0 3	OFO	15
TEXT (If more space is required, use additional NRC Form 306A's) (17)									

Another possible circumstance that could have caused the disc to hang up occurred when the system water was drained through the valve in preparation for the leak test. To simulate this, the valve and a short section of upstream and downstream piping was filled with water and then drained. Minimal movement of the disc occurred during this test and a very small amount of hangup appeared to occur. Because of the differences of the actual installed configuration and the simulated situation, it is possible that the valve response was different in the simulation than in the actual piping. In the simulation, the valve bonnet was removed and the piping system was open. During the draining of the valve for the refueling rest, which is when it failed, water slugs may have traveled through the valve when air was introduced in preparation for the leak test. An attempt was made to simulate this condition by intermittently pouring water into the upstream line as the line was draining. The disc hangup during the former simulation was much greater than the latter.

The reason for the valve disc hangup appears to be the result of too much clearance in the disc-to-hanger arm joint. This excessive clearance was due to wear. A complete disassembly of the valve revealed no other visible problems.

Two possible mechanisms which could have caused the valve hangup were investigated. Either gentle closure or the fluid dynamics of the test environment could have been the reason. In either case, we believe that during a design basis accident, the valve would have seated and limited penetration leakage.

Valve 767 was also tested and the required test pressure of 65 psig could not be achieved in the test volume. An indicated leak rate of greater than 200,000 sccm existed. However, the test volume could only be pressurized to 23 psig. The actual leakage through the valve would have been greater if the test volume could have been pressurized to 65 psig.

Valve 767 is a two-inch, 600- pound, carbon steel Rockwell Edward lift check valve, Figure 838YJ. The check valve is in the supply line to the excess letdown heat exchanger and is located inside of containment. A manual valve in the line outside of containment provides additional isolation capability, although the manual valve does not have to be leak tested in accordance with Appendix "J."

The previous leak rate test on 767 done in 1985 had an as-found leakage of 73 sccm. No repairs were done. The total Unit 2 as-left type "B" and "C" leakage in 1985 was 14,840 sccm, or 6.4% of allowable.

NRC Form 386A

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUMBER (6)	PAGE (3)			
		YEAR	SEQUENTIAL NUMBER	REVISION		IT	
Point Beach Nuclear Plant	0 15 10 10 10 3 0 1	8 6	-01015 -	-011	0 14	OFO	15
TEXT (If more space is required, use additional NRC Form 386A's) (17)					~ <u>1</u> *	1 10	1-

## REPORTABILITY

AC Form 366A

This report is filed pursuant to 10 CFR 50.73(a)(2)(i), "Any operation or condition prohibited by the plant's Technical Specification."

# SAFETY ASSESSMENT

Operation of Unit 2 during the last fuel cycle posed no safety hazard to the employees of Point Beach Nuclear Plant or the general public for several reasons.

First, during the test procedure of 755A, no actual backflow condition was created through the check valve as would be expected under hypothetical accident conditions. Therefore, there was no shutting force created by reverse flow against the disc during the test. It is very likely that during a design basis accident, should the containment atmosphere be exposed to a broken CCW line creating reverse flow in the line, liquid remaining in the line would cause the valve disc to seat resulting in a less significant leak rate than found during the test. Second, the CCW system is a closed system outside containment with a design pressure greater than containment accident pressure. Third, the existence of remote operating valve 754A, which passed its most recent leak rate test, allows the operator to isolate this CCW line should it become necessary to establish containment integrity.

As in the case of 755A, check valve 767 would probably limit the leak rate to a much less significant level than indicated by the test. In addition, the CCW system is a closed system outside containment with a design pressure greater than that expected during an accident inside containment. As discussed above, a manual isolation valve exists just outside containment which could be shut to provide containment integrity.

## SIMILAR OCCURRENCES

Valve 2-755A has failed its leak test several times in the past. Each time, the valve was disassembled and repaired such that the after-repair leak rate was acceptable. Leak testing of this valve prior to 1983 revealed no problems. See LERs 83-004/T-01, 84-008-00, 85-002-00, and 85-002-01.

Valve 767 has had a good history of successful type "C" tests in the past.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

5

		EXPIRES 8/3	1/85		
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)		
		YEAR SEQUENTIAL REVISION NUMBER NUMBER			
Point Beach Nuclear Plant	0 15 10 10 10 1 31 01 1	86-095-01	0 15 OF 0		
TEXT (If more space is required, use additional NRC Form 386A's) (17)					

#### CORRECTIVE ACTIONS

NRC Form 366A (9-83)

755A has been replaced with a new Velan swing check valve with a slightly different disc/seat orientation. This seat is angled approximately 15 degrees from the vertical to allow gravity to assist the disc to seat properly in the valve.

Valve 767 has been repaired by disassembly and replacement of a disc O-ring and spring. The valve was returned to service with an as-left leak rate of 2 sccm.

#### ENERGY INDUSTRY IDENTIFICATION

The Energy Industry Identification for each of these valve is as follows:

	755A	767
System	BD	BD
Component	ISV	ISV



(414) 221-2345

VPNPD-87-062 NRC-87-016

February 10, 1987

Document Control Desk U. S. NUCLEAR REGULATORY COMMISSION Washington, D. C. 20555

Gentlemen:

DOCKET 50-301 LICENSEE EVENT REPORT 86-005-01 CONTAINMENT ISOLATION VALVE LEAK RATE IN EXCESS OF TECHNICAL SPECIFICATIONS POINT BEACH NUCLEAR PLANT, UNIT 2

Enclosed is Supplemental Licensee Event Report 86-005-01 for Point Beach Nuclear Plant, Unit 2. This report details the failure of two containment isolation valves to pass their Type "B" leak rate tests and the findings of our further investigation of the valve condition.

LER-86-005-01 is filed pursuant to 10 CFR 50.73(A)(2)(i), "Any operation or condition prohibited by the plant's Technical Specifications."

If any further information is required, please contact us.

Very truly yours,

Cu ta C. W. Fay

Vice President Nuclear Power

Enclosure

Copies to NRC Resident Inspector NRC Regional Administrator, Region III