NriC Form 366 (9-83)			U.S. NUCLEAR	REGULATORY COMMISSION
	LICENSEE EVEN	T REPORT (LER)	EXPIRE	8: 8/31/85
FACILITY NAME (1)			DOCKET NUMBER (2)	PAGE
JAMES A, FITZPATRICK NUC	LEAR POWER PLANT		0 5 0 0 0	3 3 3 1 OF 0 4
HICH PRESSURE COOLANT IN IEC	TION SYSTEM VALVE	FAILURE DUE TO PR	OCEDURAL INADE	OUACY
EVENT DATE (6) LER NUMBER	(6) REPORT DATE	(7) OTHE	R FACILITIES INVOLVED	(8)
MONTH DAY YEAR YEAR SEQUENTIAL NUMBER	NUMBER MONTH DAY	YEAR FACILITY N	AMES DOCK	ET NUMBER(S)
			0 1	8101010111
0 9 0 3 8 6 8 6 0 1 4		3 6	0 1	51010101 1 1
OPERATING N THIS REPORT IS SUBMITT	ED PURSUANT TO THE REQUIREMEN	ITS OF 10 CFR §: /Check one or ma	re of the following) (11)	
MODE (9) (7 20.402(b)	20.406(e)	50.73(a)(2)(iv		73.71(b)
POWER LEVEL 11010 20.405(a)(1)(0)	50.38(e)(1)	X 50.73(a)(2)(v)		73.71(e)
20.408(a)(1)(HI)	50.73(a)(2)(i)	50.73(a)(2)(vi	(A)	below and in Text, NRC Form 366A)
20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii	i)(B)	
20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)		
NAME	LICENSEE CONTACT P	OR THIS LER (12)	TELEP	HONE NUMBER
ROBERT BAKER, MAINTENANCE S	UPERINTENDENT		AREA CODE	
			3 1 5 3 4	4 2 - 3 8 4 0
	ONE LINE FOR EACH COMPONENT	FAILURE DESCRIBED IN THIS REP	DRT (13)	
CAUSE SYSTEM COMPONENT TURER	TO NPROS	CAUSE SYSTEM COMPONENT	TURER TO	NPRDS
D B. I.I.S. V. I. 2.0.0	v			
SUPPLEM	INTAL REPORT EXPECTED (14)		EXPECTED	MONTH DAY YEAR
YES IIT yes, complete EXPECTED SUBMISSION DATE			DATE (15)	
ABSTRACT /Limit to 1400 speces, i.e., epproximately fifteen	single-space typewritten lines) (16)			
On September breaker for the H Suction Valve Ope the control room, investigation rev to overheating at surveillance test Functional Test, plant's modificat Corrective a tests to identify subjected to over size, configurati examination of a frequency during	3, 1986 while igh Pressure Co rator, 23 MOV-5 thus, renderin ealed that the tributed to exc entitled, HPCI "F-ST-4E". The ion program and ctions include: other DC motor stroking, b) an on, and switch similar valve w the identified	at 100% power, olant Injection 8, tripped on a g HPCI inoperal actuator's moto essive stroking Subsystem Log motor was rep HPCI restored a) a review of operated valve analysis to co settings is add hich underwent surveillance to	the circuit (HPCI) Tor an open sign ole. An or had faile g during a p ic System laced under to service. f surveillan es that coul onfirm opera equate, and the same cy est.	the the ce d be tor c) the rcling
PDR ADOCK 050	003333			
Б	PDR			N
				19.11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

																		-	
							YEA		5	NUMB	TAL		NUM	BER					
1 15	10	10	10	12	1 2 1	2				011	14		0 1	0		2	OF	0	14
)	5	5 0	5 0 0	5 0 0 0	5 0 0 0 3	5 0 0 0 3 3	5 0 0 0 3 3 3	15 10 10 10 13 13 13 816	15 10 10 10 13 13 13 8 16 -	15 10 10 10 13 13 13 816 -	15 10 10 10 13 13 13 816 - 011	15 10 10 10 13 13 13 8 16 - 011 1 4	15 10 10 10 13 13 13 816 - 011 14 -	15 10 10 10 13 13 13 8 16 - 011 1 4 - 01	15 10 10 10 13 13 13 816 - 011 4 - 010	15 10 10 10 13 13 13 8 16 - 011 1 4 - 0 10 0	15 10 10 10 13 13 13 816 - 011 14 - 0 10 0 2	15 10 10 10 13 13 13 8 16 - 011 1 4 - 0 10 0 2 OF	15 10 10 10 13 13 13 8 16 - 0 11 1 4 - 0 10 0 1 2 OF 0

On September 3, 1986 the James A. FitzPatrick Nuclear Power Plant was operating at full power.

At approximately 2200, the Reactor Core Isolation Cooling (RCIC) System was declared inoperable due to oscillating readings from a RCIC high steam flow sensor (see LER 86-015). As a result, the surveillance test entitled, High Pressure Coolant Injection (HPCI) Flow Rate/HPCI Pump Operability/HPCI Valve Operability Test "F-ST-4B", was init; ed to verify HPCI operability. At 2205, the circuit breaker for the valve HPCI Torus Suction to HPCI, 23MOV-58, tripped when given an open signal from the control room. A second attempt to open the valve, after resetting the breaker, was unsuccessful. The HPCI system was declared inoperable and the plant entered a 24 hour limiting condition of operation (LCO) due to the inoperability of the HPCI and RCIC systems.

An investigation into the valve inoperability was commenced by the Maintenance Department. Concurrently, the RCIC system high steam flow sensor was replaced. RCIC operability tests were completed at 0916 on September 4, 1986 and RCIC was declared operable. The plant was now in a seven day LCO due to the HPCI inoperability.

Disassembly of the valve actuator and motor revealed a motor insulation failure due to overheating. There was no evidence of other mechanical or electrical problems in either the motor or actuator.

The motor was replaced under James A. FitzPatrick's Modification M1-86-100 and tested satisfactorily. HPCI operability testing was completed at 0415 on September 5, 1986 and HPCI declared operable. The modification format was utilized because the replacement motor had a slightly higher output torque, and an engineering review was judged necessary. An investigation into the root cause of the motor failure was initiated.

Earlier on September 3, 1986, at 1355, a semi-annual surveillance test entitled, "HPCI Subsystem Logic System Functional Test" was completed. Valve 23MOV-58 had been cycled as part of this test. Examination of the procedure details revealed that due to a combination of direct stroking and

NAC Form 366A

ARC Form 308A (9-83) LICENSEE EVE	NT REPORT (LER) TEXT CONTINU	OITAU	N	U.S. /	APPROVE EXPIRES	REG 0 0 8/3	MB NO.	Y CO	MMISSION 0104
FACILITY NAME (1)	DOCKET NUMBER (2)	T	LE	R NUMBER (6)			1	AGE	(3)
JAMES A. FITZPATRICK		YEAR		SEQUENTIAL	REVIS	ION		T	
NUCLEAR POWER PLANT	0 15 10 0 0 3 3 3 3	8 6	-	0114	-01	0	0 3	OF	0 4

TEXT (If more space is required, use additional NRC Form 305A's) (17)

stroking due to the operation of associated relaying, the valve stroked eight times within a 20 to 30 minute period. (Stroking refers to an open or a close operation. Cycling refers to an open and a close operation.) The surveillance test requires 3 close operations and 3 open operations during its performance, for a total of six strokes. During the last valve stroking of the surveillance test, the breaker tripped. The valve was then cycled, after resetting the breaker, to verify operability. This breaker trip is now judged to have been an indication of motor degradation.

The failed motor was a 125 volt, 7.5 foot-lb torque, 0.5 horsepower DC motor with a 5 minute (intermittent) duty rating. The stroke time for this valve is approximately 60 seconds. Discussions with the actuator's manufacturer, Limitorque, revealed that this type of motor can be continuously stroked three to four times without danger of overheating. Stroking beyond this would lead to insulation degradation, and eventual failure of the motor. It was judged, based on these discussions, that a direct correlation between the number of excess strokes that the valve was subjected to, and the actual time of motor failure, could not be made. However, insulation degradation, once begun, would lead to premature motor failure.

A review of this valve's maintenance history revealed three previous motor failures of a cyclic nature (approximately 18 months apart) that can be attributed to overheating. These previous failures and the current one are believed to have the same root cause, that is, the number of cycling operations conducted in a short time.

It is noted that these motors have not failed every time the surveillance test, "F-ST-4E", has been performed. This is evidence that the number of strokes performed do not lead to a catastrophic motor failure but rather a long term insulation degradation leading to motor failure. It is also noted that the valve duty while performing this surveillance test is more severe than the duty required while performing its safety function. The normal source of water to the HPCI pump is from the condensate storage tanks. Upon low level in these tanks, the source of water to the HPCI pump is taken from the suppression pool. Valve 23MOV-58, closed when the condensate storage tanks are being utilized, would open when using the suppression pool as a supply. This service is considerably less severe than during the surveillance test, and it is judged that a motor design problem does not exist.

				1		1	EXPIRES	8/31/85					
JAMES A. FITZPATRICK		DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)				
			YEAR	SE	NUMBE	R	REVISI	DN LA					
NUCLEAR PO	WER PLANT	0 15 10 10 10 13 13 13	816	_ 01114		4 -	0 0	0 14	OF	0 14			
TEXT (If more space is requ	ired, use additional NRC Form 386A's/ (17)		010					1.1	-				
	The felledes comment												
	The following correct:	ive actions are b	peing	g pe	rio	rme	ed:						
1)	An engineering analys operator's size, confi adequate.	is is being made iguration and swi	to d tch	conf set	irm	tł gs	are	the					
2)	Operations is reviewind DC motor operated values stroking. Potential properties be resolved by proceeding appropriate.	ng surveillance t ves subject to si problems identifi ural change or en	tests mila led h ngine	s to ar e by t eeri	id xce his ng	ent ssi re rev	tify ive eview view,	othe w wil , as	er .1				
3)	Valve 23MOV-57, anothe was also subject to the The valve was stroked however, the actuator during the next schede	er similar HPCI S he same surveilla several times to shall be disasse uled outage.	Syste ance ver emble	em v tes rify ed a	alv t " op ind	e/a F-S era exa	actua ST-4H abili amine	tor, ". Lty;					
	There have not been an dequacy has resulted in	ny similar LERs i the overheating	n wh and	fai	pr lur	oce e c	edura of mo	al otor					

James A. FitzPatrick Nuclear Power Piant P.O. Box 41 Lycoming, New York 13093 315 342.3840

> Radford J. Converse Resident Manager



October 3, 1986 JAFP 86-0836

United States Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

REFERENCE: DOCKET NO. 50-333 LICENSEE EVENT REPORT: 86-014-00

Dear Sir:

Enclosed please find referenced Licensee Event Report in accordance with 10CFR50.73.

If there are any questions concerning this report, please contact Mr. Robert Baker at 315-342-3840, extension 220.

Very truly yours,

Laur RADFORD J. CONVERSE

RJC:RB:PJS:nan

CC: USNRC, Region I (1) INPO Records Center, Atlanta, Ga. (1) American Nuclear Insurers (1) Internal Power Authority Distribution NRC Resident Inspector Document Control Center LER/OR File