NRC Form (9-83)	366				LIC	ENSI	EE EVE	NT RE	PORT	(LER)	U.S. NU A E	CLEAR RE	GULAT OMB NO 31/85	ORY COM	MISSION 04
FACILITY	NAME (1)									DOCKET NUMBER	(2)		PAG	GE (3)
	Cat	awba	Nucle	ear Stati	on, Unit	1					0 15 0 0	0 4	1 3	1 08	0 14
TITLE (4)	For	ced !	Shutdo	wn Cause	d by Exc	essi	ve lea	kage	Due to	Weld Fa	ilure				
EVE	NT DATE	E (5)	T	LER NUMBER	(6)	R	EPORT DAT	E (7)	but to	OTHER	FACILITIES INVO	LVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIA	L REVISION NUMBER	MONTH	DAY	YEAR		FACILITY NA	MES	DOCKET	NUMBE	R(S)	
								-		N/A		0 151	0 0	101	
06	13	8 6	8 6	- 0 3 1	-02	10	01	86	CER 8. /		of the following) (1	0 151	0 1 0	101	1.1
OPEI	RATING DE (9)	1	20.4	402(b)	TED PURSUANT	20.40	B(c)	ENTE OF IC	CFR g: I	50.73(a)(2)(iv)		73.	71(b)		
POWER	1	11	20.4	405(a)(1)(i)		50.36	(c)(1)			50.73(a)(2)(v)		73.	71(c)		
(10)	0	1418	20.4	405(a)(1)(iii)	_	50.58	(c)(2)		_	50.73(a)(2)(vii)		OT Dela	HER (Sp	ecity in Ab n Text, NR	C Form
			20.4	408(a)(1)(III)	X	50.73	(a)(2)(i)		-	50.73(a)(2)(viii)(A) -	366	EA)		
			20.4	406(a)(1)(iv)		50.73	(a)(2)(iii)			50.73(a)(2)(x)					
						ICENSE	E CONTACT	FOR THIS	LER (12)						
NAME											AREA CODE	TELEPHO	NE NUM	BER	
			0 1								71.01/	2 1 71	21	171 5	1 310
	Rog	er W.	. Ouer	COMPLET	E ONE LINE FOR	E EACH	COMPONENT	FAILURE	DESCRIBI	D IN THIS REPOR	AT (13)	12 1 / 1	21-	1/1-	1 310
CAUSE	SYSTEM	COMP	ONENT	MANUFAC-	REPORTABLE TO NPROS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORT	ABLE		
	1										1.1.1				
			1 1 1	SUPPLER	AENTAL REPORT	EXPECT	TED (14)				EXPECT	-	MONTH	DAY	YEAR
							_				SUBMISSI DATE (1	QN 5)			
YES	(If yes, c	complete E	XPECTED	SUBMISSION DA	TE)		X NO				1				
	On Juresul loss Varia resul unit This Const Letdo This	inci inci	3, 198 in exc ower t Letdow trans at 482 dent f ion/In rifice dent f	86, at ap cessive F to a Moto wn Orific sient, a ' power a is assign hstallati e failed is report	proximat eactor Cor contro e. The l inch p at the ti ned Cause due to f cable pur	ely cola i Ce orif ipe me o cod ienc atig	1600 h nt Sys nter c ice fa weld o f this e B, D y. A ue res t to 1	ours, tem 1 aused iled in the inci esign weld sultin 0 CFR	a we eakag a lou in the disc dent. , Man on the g from 50.7	ld break e causing ss of con e opened harge of ufacturin e outlet m cavitat 3, Sectio	on Letdow a forced trol powe position. the orifi g, flange on ion induc n (a)(2)(n pip: shuto r to t Dur: ce bro the v ed vil	ing lown the ing oke. vari	. A The able ion.	
		BPG	61010 DR A	0691 88	5000413 PDR							J	É21	2	

1

NRC Form 366A (9-83)	LICENS	EE EVENT	REPOR	TF	(L.EI	R) T	EXT	C	ON	TIN	NU.	ATI	ION	V		U.S.	AP	ROVED	GULA OMB N 31/85	ORY C	OMM -010	4
FACILITY NAME (1)				DO	CKET	NUM	BER (2)			1			LER	NUM	BER (6	,		Τ	PAG	E (3)	
											I	YEA	R	1	NU	NTIAL		NUMBER			T	
Catawb	a Nuclear	Station,	Unit	10	5	0	010	0	41	1	3	81	6	_	0	3 1	-	0 2	0	20	F	0 4

BACKGROUND

TEXT (If more space is required, use additional NRC Form 366A's) (17)

One of the functions of the Chemical and Volume Control (NV) System (EIIS:CB) is to maintain a programmed water level in the pressurizer and a required water inventory in the Reactor Coolant (NC) System (EIIS:AB). This is achieved by means of charging and letdown, which is a continuous feed and bleed process. The charging rate is automatically controlled by Pressurizer level. The letdown rate can be chosen to suit various plant operational requirements by selecting the proper combination of letdown orifices. Three parallel lines are provided to reduce the pressure and control the flow of reactor coolant leaving the NC System. Two of the lines incorporate fixed letdown orifices. The third line utilizes a valve as a variable orifice. An alternate (excess) letdown path is provided in the event that the normal letdown path is inoperable. The excess letdown can also be used to maintain normal heatup rate of the unit, by providing additional letdown capability during heatup.

Technical Specification (Tech Spec) 3.4.5.2 states that NC leakage shall be limited to 1 gpm of unidentified leakage. With unidentified leakage greater than 1 gpm, the leakage rate must be reduced to within limits within 4 hours or be in at least Hot Standby within the next 6 hours and in Cold Shutdown within the following 30 hours.

DESCRIPTION OF INCIDENT

On June 13, 1986, the Unit was at 48% power. The Variable Letdown Orifice, 1NV849, was in service and throttled to approximately 30 gpm to reduce pressure due to a NV to Component Cooling System (EIIS:CC) leak at the Letdown Heat Exchanger. The fixed orifices flowpaths were isolated.

At 1100 hours, the Unit entered the action statement of Tech Spec 3.4.5.2 due to unidentified NC leakage of 1.486 gpm. At 1500 hours, an Unusual Event was declared due to unidentified NC leakage of greater than 1.0 gpm. At approximately 1542 hours, alarms were received indicating the loss of Motor Control Center (MCC) 1MXD. This resulted in the loss of control power to 1NV849 and 1RL138, Hydrogen Cooler Temperature control valve, causing the valves to fail open and closed, respectively. Charging flow suddenly increased to approximately 130 gpm and Pressurizer level began decreasing. This gave the indication of a probable NC leak. At 1550:11 hours, an alarm was received indicating an increasing Hydrogen temperature on the Generator. At 1551:02 hours, 1NV849 was isolated, but the Pressurizer level continued to decrease. The hydrogen temperature on the Generator also continued to increase. The Containment Floor and Equipment Sump B High Level alarm was received at 1601:13 hours, confirming NC leakage.

At approximately 1610 hours, Reactor power and Turbine load were decreased due to high Generator hydrogen temperature and NC leakage. Pressurizer level was being maintained by maximum charging. At 1638:34 hours, the Main Turbine was manually tripped and the Unit entered Mode 2, Startup. At 1638:46 hours, valves 1NV1A and 1NV2B, NC Letdown to Regeneration Heat Exchanger Isolation valves, were manually closed in an attempt to isolate the NC leak. Excess Letdown was established at 1641:28 hours. Pressurizer level returned to normal. At approximately 1700 hours,

NRC Form 366A (9-83)	N		U.	S. NUC	NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85								
FACILITY NAME (1)		DOCKET NUMBER (2)		RNU	MBER	6)		PAGE (3)					
			YEAR		SEQ	UENTIA	-	REVISION					
Catawba Nuclear St	ation, Unit 1	0 5 0 0 0 4 1 3	8 6	_	0	3 1	_	012	0 3	OF	0	14	

the Unit entered Mode 3, Hot Standby. A Work Request was initiated to investigate and repair MCC 1MXD. At 2105 hours, the Unit entered Mode 4, Hot Shutdown. On June 15, 1986, at 0257 hours, the Unit entered Mode 5, Cold Shutdown. The Work Request was completed on June 18, 1986.

CONCLUSION

This incident is assigned Cause Code B, Design, Manufacturing, Construction/ Installation deficiency. Upon shutdown of the unit, an investigation revealed a 360 degree circumferential weld failure on the outlet flange of 1NV849. The preliminary conclusion is that the weld failed due to fatigue resulting from cavitation induced vibration of 1NV849. This can be attributed to long term utilization of the valve throttled at low flow. 1NV849 had been used for approximately one month to reduce pressure due to the Letdown Heat Exchanger leak. A formal failure analysis is being performed by Westinghouse. The interim resolutions are to replace the failed weld and limit operation of 1NV849 to a short period of time, 5 to 10 minutes, at low flow when re-establishing letdown to minimize shock on the piping. Vibration in the vicinity of the letdown orifices will be monitored to verify acceptable operations. The weld has been repaired. Upon receipt of the Westinghouse report of the failure analysis, Duke will review the data and make recommendations for a permanent resolution.

A contributing cause to this incident is loss of power on MCC 1MXD. Investigation revealed that the nameplate on a control transformer in compartment R04A of MCC 1MXD became unglued. The nameplate fell against a terminal strip and caused an overload. The overload tripped the normal feeder breaker to the MCC and prevented the alternate feeder breaker from closing in. The failure of MCC 1MXD caused a loss of control power to 1NV849 and 1RL138. The breaker in 1MXD R04A was replaced and the work completed on June 18, 1986. On May 15, 1986, a Work Request was initiated to remove the nameplates from all control transformers in all Unit 1 and shared Nelson 600V MCCs. The work request was completed on June 16, 1986. The removal of all control transformer nameplates from Unit 2 Nelson 600V MCC was done in 1985 per Significant Deficiency No. 414/85-09. At that time, an inspection of Unit 1 revealed a low percentage of fallen nameplates. A decision was made to remove the Unit 1 nameplates during the first refueling outage.

An exact value of the leakrate was found to be difficult to determine. Personnel employed various calculation methods in an attempt to quantify the NC leakage. The method which was chosen as the most accurate was the Radwaste inventory method. This data covered the entire span of the incident, and the Radwaste input before and after the incident was constant. Therefore, using the Radwaste generation base as the most reliable indication, the average leakrate was determined to be 87 gpm.

A post shutdown inspection for NC leakage revealed a leak on the manway of the Pressurizer. The leak has been repaired.

Post incident vibration monitoring of the associated Unit 2 piping revealed no unusually high vibrations on the variable letdown orifice flowpath.

NRC Form 366A (9-83)	ENSEE EVENT REPORT (LER) TEXT CON	TINUATION	U.S. NUCLEAR REGULATORY COMMISSIO APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85					
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NO	JMBER (6)	PAGE (3)				
		YEAR SEO	UENTIAL REVISION UMBER NUMBER					

Catawba Nuclear Station, Unit 1 0 5 0 0 0 4 1 3 8 6 - 0 3 1 - 0 2 0 4 0F 0 4

a second to the second second failures of this

A review of NPRDS indicated there are no reported failures of this type involving Nelson MCC.

There were two previous incidents of a Unit Shutdown due to unidentified leakage at Catawba (see LER's 413/85-59 and 413/85-61).

CORRECTIVE ACTION

TEXT (If more space is required, use additional NRC Form 366A's) (17)

- (1) Reactor power and Turbine load were decreased.
- (2) Valves 1NV1A and 1NV2B were closed.
- (3) A Work Request to repair MCC 1MXD RO4A, was initiated and completed.
- (4) A Work Request to remove all remaining control transformer nameplates from Unit 1 MCCs, was completed.
- (5) Procedure changes to OP/1/A/6100/01, Controlling Procedure for Unit Startup and OP/1/A/6200/01, Chemical and Volume Control System, were implemented to add operational limitations for 1NV849.
- (6) The weld failure was repaired.
- (7) A followup surveillance will be performed based on the proposed action as stated in the final resolution of the weld failure cause.
- (8) An accurate determination of the NC leakrate during this incident has been completed.

SAFETY ANALYSIS

All NC System leakage from the failed weld went to the Containment Floor and Equipment Sump. The water was pumped to the Waste Evaporator Feed Tank, Floor Drain Tank, and the Steam Generator Drain Tank. All water was eventually processed, sampled, and discharged through the Liquid Radwaste System. NC System inventory was maintained by the Centrifugal Charging Pumps and the Fueling Water Storage Tank. There were no unexpected exposure problems during the cleanup of the Containment Building.

During the Unit Shutdown, NC System cooldown rates did not exceed 100 degrees F in any 1 hour period. Pressurizer pressure did not decrease below 2050 psi and the Pressurizer level did not decrease below 19%. Average temperature decreased to 530 degrees F post shutdown, but stabilized at 551 degrees F after 30 minutes. The Steam Generator levels decreased to a minimum of 35% narrow range but quickly stabilized at approximately 50% post shutdown.

The health and safety of the public were not affected by this incident.

DUKE POWER COMPANY P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER VICE PRESIDENT NUCLEAR PRODUCTION

TELEPHONE (704) 373-4531

October 1, 1986

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Subject: Catawba Nuclear Station, Unit 1 Docket No. 50-413

Gentlemen:

Pursuant to 10 CFR 50.73 Section (a) (1) and (d), attached is Revision 2 to Licensee Event Report 413/86-31 concerning a forced shutdown cuased by excessive Reactor Coolant leakage due to a weld failure. This event was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

A.B. Tuchn / flad

Hal B. Tucker

RWO/49/s1b

Attachment

xc: Dr. J. Nelson Grace, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

> American Nuclear Insurers c/o Dottie Sherman, ANI Library The Exchange, Suite 245 270 Farmington Avenue Farmington, CT 06032

M&M Nuclear Consultants 1221 Avenue of the Americas New York, New York 10020

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Resident Inspector Catawba Nuclear Station