NRC Form 366		U.S.	NUCLEAR REGULATORY COMMISSION
			APPROVED OMB NO. 3150-0104
	LICENSEE EVENT REPORT	(LER)	EAPINES: 8/31/88
FACILITY NAME (1)		DOCKET NUMB	ER (2) PAGE (3)
Sequevab. Unit 1		0 15 10 1	0 1 0 1 3 2 7 1 OF 0 3
TITLE (4)			
Inadequate Verification Of ECO	CS Flow Due To Procedura	1 Inadequacy	
EVENT DATE (5) LER NUMBER (6)	REPORT DATE (7)	OTHER FACILITIES IN	DOCKET NUMBERIS
NUMBER N	UMBER MONTH DAT TEAM	quovab. Unit 2	0 15 10 10 10 1 3 2 8
		quojan, onte r	
0 9 2 5 8 6 8 6 0 4 4	a o 1 0 2 4 8 6		0 5 0 0 0 1
OPERATING THIS REPORT IS SUBMITTED PURS	SUANT TO THE REQUIREMENTS OF 10 CFR & (C	heck one or more of the following)	(11)
20.402(b) 20.402(b) 20.405(a)(1)(i)	20.405(c)	50.73(a)(2)(iv)	73.71(b)
LEVEL 20.405(a)(1)(ii)	50.36(c)(2)	50.73(a)(2)(vii)	OTHER (Specify in Abstract
20.405(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(vili)(A)	below and in Text, NRC Form 366A)
20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(e)(2)(viii)(B)	
20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)	
NAME	LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER
		AREA COD	
James D. Smith, Plant Operation	ng Review Staff	61	5 8 7 0 - 6 6 7 2
COMPLETE ONE LI	NE FOR EACH COMPONENT FAILURE DESCRIBED	IN THIS REPORT (13)	
CAUSE SYSTEM COMPONENT MANUFAC REPORTON	PRDS CAUSE SYSTEM	COMPONENT MANUFAC	REPORTABLE TO NPRDS
		111111	
SUPPLEMENTAL F	REPORT EXPECTED (14)	EXPEC	TED MONTH DAY YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)	XXNO	DATE	(15)
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-sp	ace typewritten lines) (16)		
While both units were in m procedures used to meet te (SRs). On September 25, 1 (SI)-137.3 for SR 4.4.6.2. (EIIS System CB) flow rate accident analysis. More s gpm at reactor coolant sys during normal operating co a 100 psi pressure differe normal RCS operating condi resistance to limit emerge Based upon Westinghouse id with centrifugal charging greater than the RCS press consequences as adequate C condition constitutes oper with 10 CFR 50.73, paragra inadequate SI has been det SI. Even though the SI co been verified that the SI	ode 5 at zero percent po chnical specifications (986, it was determined to 1.C did not adequately e was less than or equal pecifically, SI-137.3 ve tem (RCS) (EIIS System A nfigurations. However, ntial in addition to the tions is required to ens ncy core cooling system entified acceptable crit pumps (CCPs) discharge p ure would have precluded CP flow would have been ation prohibited by TS a ph a.2.i.B, for both uni ermined to be inadequate mplied with the explicit ensured that the base of	wer, a review w TSs) surveilland hat Surveilland to that Surveilland to that which w rified seal inju- C) pressure of Westinghouse has requirement for sure an acceptab flow through th teria, nominal p pressure of at 1 any significan available. The and is reportabl its 1 and 2. Th e preparation an twording of the the TS was met	as conducted of ce requirements e Instruction seal injection as assumed in the ection flow of 40 2235 <u>+</u> 20 psig s indicated that r 40 gpm at le system is pathway. lant conditions east 100 psi t safety above described e in accordance e cause for the d review of the SR, it had not
SI-137.3 is being changed injection flow path resist established to ensure this	to ensure that an adequa ance is achieved and adm resistance is maintaine	ate reactor cool ministrative con ed.	ant pump seal trols will be
IRC Form 366 8610310119 PDR ADOCK S	861024 05000327 PDR		Jest h

NRC Form 366A (9-83) LICENSEE EV	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION				U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88			
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)			
		YEAR	SEQU	UNBER	REVISION			
Sequoyah, Unit l	0 5 0 0 3 2 7	8 6	- 0	4 4	- 010	0 2	OF	0 3

DESCRIPTION OF EVENT

With both units 1 and 2 in mode 5 at zero percent power (unit 1 was at 270 psig, 127 degrees F and unit 2 was at 5 psig, 140 degrees F), an ongoing review was conducted of plant surveillance instructions (SIs) used to complete technical specifications (TSs) surveillance requirements (SRs). On September 25, 1986, it was determined that SI-137.3, "Measurement of the Controlled Leakage to the Reactor Coolant Pump Seals," for SR 4.4.6.2.1.C did not ensure that the reactor coolant pump (RCP) seal injection (EIIS System CB) flow rate during a loss of coolant accident is less than or equal to that assumed for the accident analysis. SI-137.3 meets the explicit requirements of SR 4.4.6.2.1.C, i.e., measurement of the controlled leakage to the RCP seals when the reactor coolant system (RCS) (EIIS System AC) is 2235 + 20 psig at least once every 31 days with the modulating valve (FCV-62-93) fully open to be less than or equal to 40 gpm. However, the intent of the SR is to ensure that the seal injection flow during the full spectrum of primary side line breaks is less than or equal to that which has been assumed by Westinghouse in the accident analysis. Westinghouse has indicated that the acceptable range for seal injection flow is 40 gpm at operating RCS pressures to 74 gpm at RCS pressures near atmospheric. SI-137.3 and/or applicable plant controls failed to ensure that:

- 1. The seal injection line provided a minimum acceptable resistance during the performance of SI-137.3.
- Adequate administrative controls had been placed to ensure that this minimum acceptable resistance is maintained between performances of SI-137.3.

SI-137.3 is applicable to both units. No immediate operator action is required while both units are in mode 5.

CAUSE OF EVENT

SI-137.3 was inadequate in that preparation and previous reviews performed in conjunction with the SI did not adequately ensure that the intent of the SR, as described in the bases, was met. While the SI did meet the verbatim requirements of the TS and associated SR, lack of administrative controls and/or procedural requirements could have contributed to a condition which resulted in an operation prohibited by the intent of the TSs.

ANALYSIS OF EVENT

This condition is applicable to both units 1 and 2 and constitutes operation prohibited by TSs which is reportable in accordance with 10 CFR 50.73, paragraph a.2.i.B.

NRC Form 366A (9-83)	LICENSEE EVENT REPORT (LER) TEXT CO	NTINUATION	U.S. NUCLEAR REGU APPROVED ON EXPIRES: 8/31/6	ULATORY COMMISSION IB NO. 3150-0104 88	
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUN	ABER (6)	PAGE (3)	
		YEAR	ENTIAL REVISION		

		LEH NOMBER (6)	PAGE (3)		
		YEAR SEQUENTIAL REVISION NUMBER NUMBER			
Sequoyah, Unit 1	0 5 0 0 3 27	8 6 - 0 4 4 - 0 0	0 3 OF 0 3		
TEXT (If more space is required, use additional NRC Form 366A's) (17)					

SI-137.3 measured the seal injection flow of 40 gpm at 2235 \pm 20 psig. Westinghouse has indicated that a 100 psi pressure differential in addition to the requirement for 40 gpm at normal RCS operating conditions will ensure an acceptable resistance to limit emergency core cooling system flow through this

This event is not considered to have had any significant safety consequences on the plant for the following reasons:

- Normal plant conditions while performing SI-137.3 would have likely given a pressure differential of greater than 100 psi as the centrifugal charging pump (CCP) discharge pressure is greater than 2400 psig.
- SI-260.2, "BIT Cold Leg Injection Flow Balance, Pump Performance and Check Valve Test," verifies the pump capacity is within accident constraints for the large break LOCA. The CCPs' flow rate has previously been shown as more than adequate to meet ECCS assumptions (i.e., margin exists to minimum requirements).

CORRECTIVE ACTION

pathway.

Westinghouse has confirmed that an acceptable seal injection configuration exists provided that a flow of less than or equal to 40 gpm is measured while the RCS is at 2235 ± 20 psig and a pressure drop of greater than or equal to 100 psi exists across the seal injection lines. SI-137.3 is being revised to reflect this pressure differential requirement. This will be completed before restart of either unit.

In addition, administrative controls will be placed on the seal injection line needle valves (VLV-62-556, -557, -558, and -559) to ensure that the seal injection line system overall resistance is not adversely affected following successful performance of SI-137.3. This will be completed before restart of either unit.

The SI review program currently in progress which identified this event will ensure the technical adequacy of this SI.

ADDITIONAL INFORMATION

Previous reports on items not performed as required by TSs - Thirteen -SQRO-50-327/86042, 86039, 86035, 86030, 86027, 86023, 86020, 86018, 86017, 86013, 86011, 86008, and 86007.

0221Q

TENNESSEE VALLEY AUTHORITY Sequoyah Nuclear Plant Post Office Box 2000 Soddy-Daisy, Tennessee 37379

October 24, 1986

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - DOCKET NOS. 50-327 AND 50-328 - FACILITY OPERATING LICENSE DPR-77 AND -79 -REPORTABLE OCCURRENCE REPORT SQR0-50-327/86044

The enclosed licensee event report provides details concerning inadequate verification of emergency core cooling system flow due to procedural inadequacy. This event is reported in accordance with 10 CFR 50.73, paragraph a.2.i.B.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

C.R. Wallow

P. R. Wallace Plant Manager

Enclosure cc (Enclosure):

> J. Nelson Grace, Regional Administrator U.S. Nuclear Regulatory Commission Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30323

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, Sequoyah Nuclear Plant