

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Hope Creek Generating Station DOCKET NUMBER (2) 0 5 0 0 0 3 5 4 1 OF 0 4 PAGE (3)

TITLE (4) PRIMARY CONTAINMENT ISOLATION SYSTEM ACTUATION DUE TO MOMENTARY LOSS OF POWER TO RADIATION MONITORING EQUIPMENT.

EVENT DATE (5)			LER NUMBER (8)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)	
0	1	3	8	7	8	7	0	2	19	8	7	0 5 0 0 0

OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §. (Check one or more of the following) (11)									
1		<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
POWER LEVEL (10) 1 0 0		<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)						
		<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
		<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
		<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							
		<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)							

LICENSEE CONTACT FOR THIS LER (12)
NAME: R.B. COWLES, LEAD ENGINEER, TECHNICAL STAFF
TELEPHONE NUMBER: 610 931 3191-15264
AREA CODE: 610 931 3191-15264

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)
YES (If yes, complete EXPECTED SUBMISSION DATE) NO
EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)
A Primary Containment Isolation System (PCIS) actuation occurred when Reactor Building Exhaust (RBE) radiation monitoring channel "A" momentarily tripped at the same time that channel "C" was in a tripped condition. With channel "C" previously tripped, a "2 of 3 channels tripped" logic was satisfied when channel "A" tripped, actuating PCIS. After determining that the channel "A" trip was momentary and spurious, all associated systems and equipment were returned to normal service. Subsequent simulation by I&C Department determined that a momentary power loss to channel "A" caused the channel "A" trip. The root cause of the momentary power loss could not be determined, as such, a definite corrective action can not be identified. I&C Department is tracking this event for any repeat occurrences.

8702260594 870219
PDR ADOCK 05000354
S PDR

IEZZ

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Hope Creek Generating Station	DOCKET NUMBER (2) 0 5 0 0 0 3 5 4 8 7	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		87	- 0 0 5	- 0 0	0 2	OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor (BWR/4)
 Primary Containment Isolation System (EIIS Designator: JM)
 Process Radiation Monitoring (EIIS Designator: IL)
 Radiation Monitoring System Channel "A" (EIIS Designator: CHA)

IDENTIFICATION OF OCCURRENCE

Primary Containment Isolation System (PCIS) Actuation Due to Momentary Loss of Power to Radiation Monitoring Equipment
 Event Date: 01/23/87
 Event Time: 1054
 This LER was initiated by Incident Report No. 87-015.

CONDITIONS PRIOR TO OCCURRENCE

OPERATIONAL CONDITION 1 (Power Operation), Reactor Power 100%, unit load 1124 MWe.

DESCRIPTION OF OCCURRENCE

On January 23, 1987 at 1054, A Primary Containment Isolation (PCIS) Actuation occurred when Reactor Building Exhaust (RBE) Radiation Monitoring Channel "A" Momentarily tripped at the same time that channel "C" was in a tripped condition. After determining that the channel "A" trip was momentary and spurious, all associated systems and equipment were returned to normal service.

The following alarms and indication were observed during the course of this incident.

- RBE Radiation Alarm/Trouble Alarm
- FRVS Recirc Fan Trouble Alarm; FRVS Recirc Fan and "B" FRVS Vent Fan Start
- Reactor Building Ventilation Panel Alarm; Reactor Building Ventilation Isolation
- Service Water Supply Loop A&B Trouble; "B" Service Water Pump Start
- "A" SACS Loop Trouble; "B" SACS Pumps Start
- Instrument Gas System A&B Trouble; Instrument Gas System Isolation
- Unit Substation Feeder Breaker Trouble; Trip of Reactor Building Vent Fans

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Hope Creek Generating Station	DOCKET NUMBER (2) 0 5 0 0 0 3 5 4	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 7	- 0 0 5	- 0 0	0 3	OF	0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF OCCURRENCE CONT'D

The following system/equipment actuations were observed during this incident:

- FRVS System Start
- Reactor Building Ventilation Isolation
- Service Water and SACS Auto-Start
- Instrument Gas System Isolation
- Torus Water Cleanup Isolation
- Drywell Floor and Equipment Drain System Isolation

APPARENT CAUSE OF OCCURRENCE

Equipment Malfunction - Momentary loss of power to radiation monitor channel "A". The root cause of the momentary power loss could not be determined.

ANALYSIS OF OCCURRENCE

On 1/19/87, the reactor building exhaust channel "C" radiation monitor failed a source check, causing it to be declared inoperable per technical specification 3.3.2, and was subsequently tripped. During channel "C" sensor calibration on 01/23/87 (channel "C" still tripped), a channel "A" trip was momentarily received, and the "2 of 3 channels tripped" logic was satisfied, actuating PCIS.

I&C department subsequently ran a simulation in an effort to determine exactly what caused the momentary channel "A" trip signal. The only simulation that repeated all previously listed system responses was a momentary loss of power to the Radiation Monitoring System RBE channel "A". No reason for the momentary loss of power could be determined, and such is being considered as an isolated occurrence.

No similar incidents of this nature have been reported. I&C department is monitoring the RMS panel to determine if a trend toward momentary power interruptions is occurring. An analysis of the safety impact of this event will be done should a trend be identified by I&C.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Hope Creek Generating Station	DOCKET NUMBER (2) 0 5 0 0 0 3 5 4	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 7	- 0 0 5	- 0 0	0 4	OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CORRECTIVE ACTIONS

Because the cause of the momentary loss of power to the Radiation Monitoring System Channel "A" can not be determined, I&C is monitoring the Radiation Monitoring System to determine if a trend toward momentary power interruptions is occurring.

Sincerely,

R. S. Salvesen
General Manager -
Hope Creek Operations

RBC:tlb
SORC Mtg. 87-023



Public Service Electric and Gas Company P.O. Box L Hancocks Bridge, New Jersey 08038

Hope Creek Operations

February 18, 1987

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Dear Sir:

HOPE CREEK GENERATING STATION
DOCKET NO. 50-354
UNIT NO. 1
LICENSEE EVENT REPORT 87-005-00

This Licensee Event Report is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(iv).

Sincerely,

A handwritten signature in cursive script, appearing to read "R. S. Salvesen".

R. S. Salvesen
General Manager -
Hope Creek Operations

RBC:tlb

Attachment
SORC Mtg. 87-023

C Distribution

IE22
1/1