

UNITED STATES NUC TAR REGULATORY COMMISSION REGION II 101 MARIETTA ST. N.W. SUITE 3100 ATLANTA GEORGIA 30303

September 10, 1982

MEMORANDUM FOR: Chief, Vendor Inspection Branch, Region IV FROM: R. C. Lewis, Director, Division of Resident and Reactor Project Inspection

SUBJECT: CONSTRUCTION DEFICIENCY REPORT - CONFIRMATION OF TELECON (AITS NO. F02700286)

Enclosed is a 10/CFR 50.55(e)/10 CFR 21 report received from <u>Duke</u> <u>Power Company</u>. This appears to be a generic problem. Would you please followup on the generic aspects of the problem with the AE/Vendor? Should you have additional questions, we will be glad to discuss them with you.

R.C. Jewis

Enclosure: as stated

cc: J. Clshinski, RII Director, RRPI, RI Director, RRPI, RIII Director, RRP&E, RV B. Heishman

CONTACT: A. Ignatonis (242-5588)

8612120259 861203 PDR FOIA ELLIS86-656 PDR

050

1-41

REGIONAL ACTION

PLANCE A ALL PROPERTY OF THE DATE PERMIT CONDUCTION

UATE 9/10/82

THM OR EVENI

CDR - Unsuitable Rubber Application to Diesel Followup per MC 2512. Generator Coupling - Per the 6/23 letter from Region IV Notified. DeLaval Co. to NRC reporting a Part 21 item, Catawba was listed as one of the plants that Cat I received an unacceptable governor drive coupling manufactured by Koppers Co., Inc., Baltimore, MD. The concern is that Isoprene rubber material was used in the coupling. This rubber tends to deteriorated under oil and high temperature conditions which creates the potential of metal to metal contact between flanges in the coupler while the diesel generator is running. Metal to metal contact can give false indication of generator frequency and trip out the running DG. For corrective action the licensee will remove couplers having Isoprene material and replace them which would have Meoprene material. Written report due 10, 8.

(ALL)

Licensee 9/9

1011 101-104

Catawba 1 & 2 DNS:50-413 - 50-414

. .

0/51

	VIB SPECTION REPO	ORT ROUTE SHEET	, ,	. B-6 Rev. 11/81
VENDOR/EONTRACTOR RANS ANTUNIC Delavel, Incompanded, Engine and compressor Div - DOCKET NO. 99900334 REPORT NO. 82-02 DATE OF INSPECTION: August 23-26, 1982				
REPORT DUE DATE: 9-17-82				
SUBMITTED TO PROCESSING:				VIB rf
PRIORITY STATUS:* DRAFTUR		FINAL	URGENT	EIB
	JTINE		ROUTINE	RPBdm
the second s	n progress; <u>ASAP:</u> Sup Routine must be initi Inspection Data Sheet	aled by Branch	Chief	
			Date Comp	leted
DRAFT: Review/Concurrent/Signa REPORT SUBMITTED TO PRO	10/	- 9/20kitt	S) 4/2 NSP/0-5-82/5	G 10/4 Sc. ∓S S.c.
TO: INSPECTOR/SECTION		182.0		10/2/22/2)
TO: BRANCH CHIEF TO: ENFORCEMENT COORDIN		Lond	$3) \pm S_{\ell}$	5 OF 10/6/02
COMMENT:	T COPY TO BRANCH SECR	ETARY AFTER EN	FORCEMENT CO	ORDINATOR
 (S) Completed by Secretary (3) Completed by Branch Chief (4) Completed by Enforcement Coordinator (2) Completed by extra Section Chief, if more than one section is involved *If Enforcement Coordinator is not present, submit to Administrator for review/concurrence *Branch Chief makes determination about status of report, i.e. redrafted, etc. 				
FINAL: Review/Concurrence/Sign		tted	Date Comp	leted
rut for Corr 10/9 -		182 1	S) /18/8 NSP. Gr. Nye /	5.C. #3 / S.C. W4
TO: BRANCH CHIEF:	(S)	-	3) IBS	11/24
Net for ear 1/17->	ATOR: (S)		4)	
DATE DUE AFTER 10 DAYS	A 1/2	CLOSEO	UT DATE 4	20/83
DATE DUE AFTER 30 DAYS (RESPONSE DUE) 1810				