NRC Form (9-83)	366				LIC	ENSEE EVE	NT REP	PORT	(LER)	U.S. NUC AJ ED	PROVED (GULATOF DM6 NO. 31/85	1Y COMMI 3150-0104	SSION
														731
ACILITY	NAME (1)	1							D	OCKET NUMBER	(2)		1 05	010
Cata	awba	Nucle	ear S	tation, Un	it 2				10	19 0 0	0141	11.41	1 1011	016
TTLE (4)														
Deg	raded	Aux	iliar	y Feedwate	r Flow	Due to De	sign D	etici	OTHER F	ACILITIES INVOI	LVED (8)			
EVE	NT DATE	(5)	VEAD	SEQUENTIAL	REVISION	MONTH DAY	YEAR		FACILITY NAM	ES	DOCKET	NUMBER	S)	
MONTH	DAY	YEAH	TEAR	NUMBER	NUMBER				N/A		0 151	0 0	011	1
							1.1							
0 5	2 1 1	8 6	8 6	01 7	0 0	0620	86				0 151	0 0	0	_
OPE	RATING		THIS RE	PORT IS SUSMITTE	D PURSUANT T	TO THE REQUIREN	AENTS OF 10	CFR \$: 10	Check one or more of	t the following) (1)	1)			
MO	DE (9)	2	20.	402(b)	_	20.405(c)			50.73(s)(2)(iv)		73.	71(6)		
POWER		~ ~	20.	405(a)(1)(i)	-	50.36(c)(1)			50.73(a)(2)(v)		- OT	HER /Som	city in Abs	tract
(10)	0	013	20.	465(a)(1)(ii)	v	50.38(c)(2)		-	50.73(a)(2)(viii)(A	0	De/0 366	ow and in [A]	Text, NAC	Form
			20.	408(a)(1)(iii)	A	50.73(a)(2)(H)			50.73(s)(2)(vill)(8	0				
			- 20	405(a)(1)(v)		50.73(a)(2)(iii)			50.73(e)(2)(x)					
			1 1			ICENSEE CONTAC	T FOR THIS	LER (12)						
NAME										AREA CODE	TELEPHO	NE NUMB	IEM	
										7101/	12171	1.21	17 1 5	1.1
Rog	er W.	Oue.	llett	e, Associa	te Engi	neer - Li	censin	OFECRIPI	O IN THIS REPOR	T (13)	1317	11-	1/12	171
				COMPLETE	ONE LINE FOR	EACH COMPONEN		I		MANUFAC	REPOR	TABLE		
CAUSE	SYSTEM	COMP	ONENT	TURER	TO NPROS		CAUSE	SYSTEM	COMPONENT	TURER	TON	PRDS		
в	BIA	IF	I CI Y	FI 11 31 0	NO					111	-	_		
-														
			11									LHONTH	LOAY	VEAR
-				SUPPLEM	ENTAL REPORT	T EXPECTED (14)				EXPECT SUBMISS	ED	MONTH	- CAT	
	e //		XPECTED	SURMISSION DAT	F)	NO				DATE	15)	1		1
	On Ap (CA) found found could assoc with While revie that has m This Insta	Pump Pump a v ed wi ay 21 1 not iate debr inved test inved inci illat	29, 1 Turb alve th de , 198 prod d wit is. estig and i in 0 thro dent ion D	986, at 1 ine could associated bris, pre- 6, at 1850 uce the re- h the pump ating the t was dete ctober, 19 ugh all mo is assigne	340 hour not pro d with t venting 0 hours, equired p had th flow pr ermined 985, and odes of ed Cause The C	ts, person oduce the the turbin passage of it was d discharge heir press coblems, t that the i has like operation e Code B, CA control	nnel de requir he had of requir letermi flow. flow. flow f ly bee durin Design valve	termi ed di the p ired ned t The ducti tem p rom t n deg g the , Man s' pr	ned that is scharge firessure reflow. hat the Me investigation cage as re-operation for the se pumps raded since period of ufacturing essure reconstructions.	the Auxil low. The eduction otor Driv ation fou ssemblies ional tes s was deg ce that t f degrade g, Constr duction c	iary invector cage ren CA and tw also t res traded ime. d CA ructio age a	Feedu stiga asser Pump o val foul ults duri flow. n/	water ation mbly 2B lves led were ing 2 2	
	are s corro activ This	ized sion itie inci 860 PDF	such prod s whi dent 07020 AI	that the ucts or sm ch are lan is reporta	cages c mall mat rger tha able pur 520 00414	could foul cerials re in the cag suant to	due t mainin e open 10 CFR	o the g in ing. 50.7	inability the system 3, Section	y to pass n after f	i)(B)	ng	Th	2
NRC Fo (9-83)	arm 30-	5			FUR							+ U.S.GP	O:1984-0-4	64-481

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)		
		YEAR SEQUENTIAL REVISION NUMBER NUMBER			
Catawba Nuclear Station, Unit	0 5 0 0 4 1	486 - 0117 - 010	012 OF 016		

BACKGROUND

RC Form 366A

There are two separate systems which can supply feedwater to the Steam Generators. The Main Feedwater (CF) System (EIIS:SJ) is the normal supply and is in service for most modes of plant operation. The Main Feedwater System consists of two feedwater pumps which take suction from the discharge of three Condensate Booster Pumps and two C Feedwater Heater Drain Tank Pumps. The Auxiliary Feedwater (CA) System (EIIS:BA) acts as a backup supply of feedwater to the steam generators if the Main Feedwater Pumps become unavailable. There are two Motor Driven Auxiliary Feedwater Pumps and one turbine driven pump. These take their suction from either the Auxiliary Feedwater Condensate Storage Tank, the Upper Surge Tank for the Main Condensate System, or the Condenser Hotwell, with the Nuclear Service Water (RN) System (EIIS:BI) as the assured source of suction. The two Motor Driven Auxiliary Feedwater Pumps will start automatically upon the loss of both Main Feedwater Pumps.

The following valves are Fisher, Cavitrol-type, control valves which utilize a pressure reduction cage assembly to provide pressure drop across the valve:

2CA-36, CAPT Flow to S/G 2D 2CA-40, CA Pump 2B Flow to S/G 2D 2CA-44, CA Pump 2B Flow to S/G 2C 2CA-48, CAPT Flow to S/G 2C 2CA-52, CAPT Flow to S/G 2B 2CA-56, CA Pump 2A Flow to S/G 2B 2CA-60, CA Pump 2A Flow to S/G 2A 2CA-64, CAPT Flow to S/G 2A 2CA-180, CA Pump 2B Flow to Upper Surge Tank Dome Throttle 2CA-181, CAPT Discharge to Upper Surge Tank Dome Throttle 2CA-179, CA Pump 2A Discharge to UST Dome Throttle

The openings in these valves pressure reduction cage assemblies are 0.049 inches. RN is strained at the RN Pump Structure to 0.031 inches.

The Condenser Circulating Water (RC) System (EIIS:SG) may contain materials up to 0.125 inches in diameter since the Low Pressure Service Water (RL) System (EIIS:KG) is strained to that size. The RC supply to the CA System was added with the Standby Shutdown Facility Design in approximately 1979.

The RN System provides the assured suction source for the CA System, by automatic swapover logic. Should RN head pressure not be detected on the CA suction header, CA suction will automatically realign to the RC System. However, this swapover will not occur as long as RN head pressure is detected.

Procedure PT/2/A/4250/06B, CA Flow Verification, is required to be performed prior to entry into Mode 2 if the unit has been in Cold Shutdown for greater than 30 days.

LICENSEE	EVENT	REPORT	(LER)	TEXT	CONTINUATION
	And 0 Am 1 0 1				

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OM8 NO. 3150-0104 EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)	
		YEAR SEQUENTIAL REVISION NUMBER NUMBER		
Catawba Nuclear Station, Unit 2	0 5 0 0 4 1	486 - 011 7 - 010	0 3 OF 0 1	

DESCRIPTION OF INCIDENT

Form 366A

At 0305 hours, on April 23, 1986, the unit initially entered Mode 3. On April 29, 1986, an unacceptable flow rate to the Upper Surge Tank (UST) was obtained from the Auxiliary Feedwater Pump Turbine (CAPT) during a Performance Surveillance Test. Personnel issued a work request to investigate/repair valve 2CA-20. This valve was found to be fouled with pieces of Iron Magnetite and sand. Also, the valve's cascade piston would not respond due to rust.

Prior to completion of the repair to the valve, personnel attempted to verify proper CAPT flow to steam generator (S/G) 2B. Flow was unacceptable (less than 260 gpm) at normal S/G pressure. A work request was then initiated to investigate/repair valve 2CA-181. The cage assembly of 2CA-181 was found to be fouled with Iron Magnetite and sand. Repairs of 2CA-20 and 2CA-181 were completed on May 2, 1986, and CAPT flow to the UST was verified to be acceptable.

On May 15, 1985, Motor Driven CA Pump 2B failed to provide acceptable flow to the UST during an Operations Surveillance Test. A work request was issued to investigate/repair valve 2CA-180. Personnel then attempted to verify proper Motor Driven CA Pump 2B flow to S/Gs 2C and 2D. The flow rate obtained was unacceptable at normal S/G pressure. The cage assembly of 2CA-180 was found to be fouled with Iron Magnetite and sand. Repair to 2CA-180 was completed May 16, 1986, and Motor Driven CA Pump 2B flow to the UST was verified to be acceptable.

On May 21, 1986, at 1415 hours, Feedwater Isolation occurred due to a high-high S/G level. During the transient, personnel had difficulty maintaining CA flows. Following the transient, 3 post-trip CA flow graphs from Reactor Trips on May 17, 18, and 19, 1986, and the Auxiliary Feedwater Pre-operational Test results were reviewed. CA flow was found to be degraded to S/Gs 2C and 2D during the post-trip transients and the pre-operational test. Personnel then attempted to verify CA Train B flow to the S/Gs with flow control valves full open. The flow to S/G 2C was found to be 185 gpm, and flow to S/G 2D was found to be 210 gpm. Acceptable flow to each S/G was greater than/equal to 240 gpm. Personnel then issued work requests to investigate/repair 2CA-40 and 2CA-44. Repairs to both of these valves were completed on May 23, 1986, and Motor Driven CA Pump 2B flow to the S/Gs was verified to be acceptable (greater than 300 gpm to each S/G).

CONCLUSION

This incident is assigned Cause Code B, <u>Design</u>, Manufacturing, Construction/ Installation Deficiency. The CA control valves' cage assemblies were not sized to assure that fouling of the cages would not occur. Although these materials have not been chemically analyzed, the material found appears to be Iron Magnetite, sand, and small diameter dirt or rock. The RN System is strained to 0.031 inches and the RL System is strained to 0.125 inches at the intakes.

The sand should pass through the cage assembly. However, larger diameter Iron Magnetite has been found to be the major contributor to the fouling. The differential pressure across the strainer cage is expected to force the Iron Magnetite through the cage so that fouling does not occur. This breakdown of the Iron Magnetite apparently has not consistently occurred. LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

AF	PPF	NON	ED	OM	B NO.	31	50-0104
E)	P	RES	8/	31	85		

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)		
		YEAR SEQUENTIAL REVISION NUMBER NUMBER			
Catawba Nuclear Station, Unit 2	0 5 0 0 4 1	486-0117-00	0 4 0 0 0 0		

The CA Flush Procedure was reviewed. The methods used were consistent with accepted practice. All of the Fisher Control Valves utilizing cage assemblies were removed from the system for flush and later reinstalled. Approximately 25 feet of 4 or 6 inch piping was not flushed, due to the inability to push flow through the CAPT. This section was also not flushed on Catawba Unit 1, or McGuire Units 1 and 2. McGuire CA Control Valves utilize cage assemblies which vary from 0.05 inches at the lowest flow position to 0.125 inches at the full flow position. McGuire has experienced no fouling problems with this size cage assembly.

The pre-operational test of Unit 1 CA System did not verify flow into the S/Gs. The Unit 2 CA System pre-operational test verified that CA flow was being supplied to the S/Gs. However, the specific values of CA flow were not included in the acceptance criteria for the test. The CA System Flow Verification Surveillance Test has previously been performed in Mode 4 (Hot Shutdown), with S/G pressure not at normal pressure (greater than 1000 psig). Performing these surveillances at normal S/G pressure would have indicated valve fouling problems earlier in the process. 3 Reactor trips occurred prior to discovery of the CA valve fouling problems. The degraded CA flow to S/Gs 2C and 2D was not recognized during the post-trip reviews of Reactor Trips on May 17, 18, and 19, 1986. Currently, specific CA flow is not required to be reviewed during the post-trip review. Also, a standard group of transient monitor plots was specified to be generated for the post-trip review. CA flow to S/Gs C and D was not included in this group. Personnel plan to review the post-trip format to include expected CA flow values, as well as other improvements.

On May 22, 1986, the CAPT failed to provide adequate flow to S/G 2B. Personnel adjusted the position of the CAPT throttle control valves to provide additional flow to the S/Gs. It is believed that this is indicative of further valve fouling.

During the Unit Blackout Test on May 27, 1986, CA flows to S/G's 2C and 2D were observed to be degraded (less than 300 gpm). On May 28, 1986, at 2232 hours, the unit entered Mode 4. On June 9, 1986, S/G 2D was drained to approximately 65% wide range. Motor Driven CA Pump 2B was placed in service and control valve fouling was verified. 2CA-40 was cleaned and reassembled on June 10, 1986. Also on that day, S/G 2C was drained to approximately 20% wide range. Motor Driven CA Pump 2B was placed in service and control valve fouling was verified. On June 11, 1986, 2CA-44 was cleaned and reassembled.

On June 11, 1986, at 2015 hours, a Unit 1 Reactor Trip occurred. During the transient, CA flow was observed to be slightly decreased from previous values, although still remaining acceptable. Personnel plan to monitor transient responses on both units for indications of CA flow degradation.

Personnel may utilize Motor Driven CA Pumps to provide normal feedwater during unit startup. This could potentially contribute to CA control valve fouling after the system is flow tested prior to entry into Mode 2.

Flow degradation due to control valve fouling has not occurred previously on Units 1 or 2.

RC Form 366A

LICENSEE	EVENT	REPORT	(LER)	TEXT	CONTINUATION
LIGEIGOLL		1161 0111	1 100 100 1 1 1 1		

U.S. NUCLEAR REGULATORY COMMISSION

CILITY NAME (1)		DOCKET NUMBER (2)	LER N	UMBER (6)			PAGE	3)
			YEAR SEC	UMBER	NUMBER			
Catavha	Nuclear Station Unit 2	0 15 10 10 10 14 1 1	4816 -0	11 7 -	0 10	01	5 OF	0
If more space is	required, use additional NRC Form 366.4's/ (17)		4010110					
CORF	RECTIVE ACTION							
(1)	Cage assemblies were cleaned or replaced for valves 2CA-181, 2CA-180, 2CA-40, and 2CA-44.							
(2)	S/G's 2C and 2D were drain 2CA-44 were cleaned again.	ed and CA Pump 2B flo	w was obser	ved.	2CA-40	and	I	
(3)	CAPT flow control valves h acceptable.	ave been throttled op	en so that	flow re	emains			
(4)	Procedures PT/1 & 2/A/4250 at S/G pressure greater th Unit Coordinator.	/06B were revised so an 1000 psig, and res	that CA flo ults will b	w will e provi	be ve ded to	rifi o th	ed	
(5)	The latest Unit 1 Reactor Trip Transient was reviewed and possible CA flow control valve fouling was identified.							
(6)	2CA-20 was cleaned and ret	urned to service.						
(7)	The frequency of PT/2/A/42 will be verified prior to are corrected, the surveil Specification 4.7.1.2.2.	50/06B has been incre each entry into Mode lance interval will b	ased so tha 2. After t e as requir	t prope he foul ed by T	r CA 1 ing pr echnic	flow robl al	ems	
(8)	The need to utilize main for Auxiliary Feedwater System	eedwater in non-emerg has been emphasized	ency situat to the oper	ions ra ators.	ther t	han	the	
(9)	CA Control Valve cage asser 0.05 inches at minimum flow	mblies will be change w to 0.125 inches at	d to variab full flow.	le size	opent	Ings	of	
SAFE	TY ANALYSIS							
The 2, S 1986 the that	Auxiliary Feedwater System : tartup, and 1, Power Operation, during power escalation to unit was in Modes 3, 2, or 1 time, CA Pump 2A was inoper	is required to be oper ion. Unit 2 initially esting. Motor Driven 1, except for 8.5 hour rable due to a failure	rable in Mo y entered M CA Pump 2A rs on May 9 e of Diesel	des 3, ode 3 o was op and 10 Genera	Hot St n Apri erable , 1986 tor (I	and 1 2 wh	by, 3, ile At 2A.	

The worst single failure that would affect CA System coincident with control valve fouling would be a failure of D/G 2A. In that event, Motor Driven CA Pump 2A would not respond if required. Auxiliary Feedwater flow would be provided by Motor Driven CA Pump 2B and the CAPT and flow from both would be degraded.

and S/G 2B during all surveillance testing and unit transients to the present date.

During the post-trip responses of May 17, 18, and 19, 1986, the minimum flow provided by Motor Driven CA Pump 2B was approximately 170 gpm to S/G 2C and 150 gpm to S/G 2D. The CAPT did not start during these Reactor trips. The minimum flow provided by the CAPT during the Unit Blackout Test on May 27, 1986, was 317 gpm to S/G 2B, and S/G 2C.

NRC Form 366A

NRC Form 366A (9-83)	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85								
FACILITY NAME (1)		DOCKET NUMBER (2)	1	LER NUMBER (6)		PAGE			
			YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Catawba Nuclea	ar Station, Unit 2	0 5 0 0 4 1 4	8 6 -	-0117	-010	06 06	0 6		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On an autostart of the CA System with D/G 2A inoperable and CA control valves fouled to the extent previously observed, CA flow of 954 gpm would be provided to S/Gs 2B, 2C, and 2D. The CAPT could be manually realigned to equalize flows to feed S/Gs 2C and 2D. Based on previously obtained flowrates, S/Gs 2C and 2D would receive 954 gpm from Motor Driven CA Pump 2B and the CAPT. Therefore, sufficient auxiliary feedwater flow would have been available for cooldown from extended full power operation.

The health and safety of the public were not affected by this incident.

DUKE POWER COMPANY P.O. BOX 33189 CHARLOTTE, N.C. 28242

HAL B. TUCKER VICE PRESIDENT NUCLEAR PRODUCTION

TELEPHONE (704) 373-4531

June 20, 1986

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Subject: Catawba Nuclear Station, Unit 2 Docket No. 50-414

Gentlemen:

Pursuant to 10 CFR 50.73 Section (a) (1) and (d), attached is Licensee Event Report 414/86-17 concerning degraded Auxiliary Feedwater flow caused by blockage in the flow control valves due to a design deficiency. This event was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

Hal B. Jucker June

RWO:s1b

Attachment

xc: Dr. J. Nelson Grace, Regional Administrator U. S. Nuclear Regulatory Commission Region II 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

> American Nuclear Insurers c/o Dottie Sherman, ANI Library The Exchange, Suite 245 270 Farmington Avenue Farmington, CT 06032

M&M Nuclear Consultants 1221 Avenue of the Americas New York, New York 10020

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Resident Inspector Catawba Nuclear Station

IE22