

SEPTEMBER 28, 1999

Florida Power and Light Company  
ATTN: Mr. T. F. Plunkett  
President - Nuclear Division  
P. O. Box 14000  
Juno Beach, FL 33408-0420

SUBJECT: MEETING SUMMARY - ST. LUCIE AND TURKEY POINT NUCLEAR PLANTS

Dear Mr. Plunkett:

This refers to the engineering meeting that was conducted at the NRC Region II Office at 1:00 p.m. on September 8, 1999, to discuss engineering issues at your St. Lucie and Turkey Point facilities. A list of attendees and a copy of your presentation handout are enclosed.

It is our opinion that this meeting was beneficial. We appreciate your update on the plant status and engineering issues at your facilities.

In accordance with Section 2.790(a) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this meeting, please contact us.

Sincerely,

ORIGINAL SIGNED BY  
ROBERT SCHIN FOR:

Kerry D. Landis, Chief  
Engineering Branch  
Division of Reactor Safety

Docket Nos. 50-335, 50-389, 50-250,  
50-251

License Nos. DPR-67, NPF-16, DPR-31,  
DPR-41

Enclosures: 1. List of Attendees  
2. Licensee Presentation Handouts

cc w/encs: See Page 2

080011

9910080188 990928  
PDR ADOCK 05000250  
P PDR

11/1  
IE45

cc w/encs:

J. A. Stall  
Vice President  
St. Lucie Nuclear Plant  
6351 South Ocean Drive  
Jensen Beach, FL 34957

R. G. West  
Plant General Manager  
St. Lucie Nuclear Plant  
Electronic Mail Distribution

E. J. Weinkam  
Licensing Manager  
St. Lucie Nuclear Plant  
Electronic Mail Distribution

John Gianfrancesco, Manager  
Administrative Support & Special Projects  
Florida Power & Light Company  
Electronic Mail Distribution

Mark Dryden  
Administrative Support & Special Projects  
Florida Power & Light Company  
Electronic Mail Distribution

Rajiv S. Kundalkar  
Vice President - Nuclear Engineering  
Florida Power & Light Company  
Electronic Mail Distribution

M. S. Ross, Attorney  
Florida Power & Light Company  
Electronic Mail Distribution

William A. Passetti  
Bureau of Radiation Control  
Department of Health  
Electronic Mail Distribution

Joe Myers, Director  
Division of Emergency Preparedness  
Department of Community Affairs  
Electronic Mail Distribution

(cc w/encs cont'd - See page 3)



(cc w/encls cont'd)

J. Kammel  
Radiological Emergency  
Planning Administrator  
Department of Public Safety  
Electronic Mail Distribution

Douglas Anderson  
County Administrator  
St. Lucie County  
2300 Virginia Avenue  
Ft. Pierce, FL 34982

Plant General Manager  
Turkey Point Nuclear Plant  
Florida Power and Light Company  
9760 SW 344th Street  
Florida City, FL 33035

R. J. Hovey  
Site Vice President  
Turkey Point Nuclear Plant  
Florida Power and Light Company  
9760 SW 344th Street  
Florida City, FL 33035

Steve Franzone  
Licensing Manager  
Turkey Point Nuclear Plant  
Florida Power and Light Company  
Electronic Mail Distribution

Attorney General  
Department of Legal Affairs  
The Capitol  
Tallahassee, FL 32304

County Manager  
Metropolitan Dade County  
Electronic Mail Distribution

Distribution w/encls:

W. Gleaves, NRR  
K. Jabbour, NRR  
PUBLIC

Distribution w/encls cont'd - See page 4:

Distribution w/encl w/encls cont'd:  
 U.S. Nuclear Regulatory Commission  
 ATTN: T. Ross  
 P. O. Box 6090  
 Jensen Beach, FL 34957-2010

U.S. Nuclear Regulatory Commission  
 ATTN: C. Patterson  
 9762 Southwest 344<sup>th</sup> Street  
 Florida City, FL 33035

OFFICE	RII:DRS	RII:DRP	RII:DRS				
SIGNATURE	<i>PLS for</i>	<i>to with</i>					
NAME	LANDIS	WERT					
DATE	9/24/99	9/27/99	9/ /99	9/ /99	9/ /99	9/ /99	9/ /99
COPY?	YES <input checked="" type="checkbox"/> NO	YES <input checked="" type="checkbox"/> NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY

DOCUMENT NAME: S:\DRS\STLTURS\SUMMARY.WPD



**FPL**

---

**Florida Power and Light  
Nuclear Engineering /  
NRC Interface Meeting**

**September 8, 1999**

**Region II**

**Atlanta, Georgia**





**FPL**

# Agenda

---

- **Opening**  
R. S. Kundalkar
- **Engineering Performance**  
C. R. Bible  
D. J. Tomaszewski
  - St. Lucie
  - Turkey Point
- **Problem Solving / Root Cause Analysis**  
B. K. Dunn  
C. R. Bible  
A. T. Zielonka  
B. K. Dunn  
R. Noble
  - St. Lucie Unit 1 Manual Reactor Trip on Low Condenser Vacuum
  - St. Lucie Unit 2 Rod Control Event
  - Turkey Point HHSI System Gas Venting
  - St. Lucie ECCS Piping
  - St. Lucie AFW Equipment Qualification
- **Self Assessment**  
A. T. Zielonka  
C. R. Bible  
D. J. Tomaszewski
  - Fire Protection Assessment / Inspection
  - St. Lucie System/Component Engineering
  - Turkey Point Outage
- **Initiatives**  
R. D. Gil  
E. A. Thompson
  - Steam Generator Program
  - Turkey Point License Renewal



**FPL**

---

- **Organization**
- **Corrective Action Program**
- **Cornerstones**
- **Self Assessments**
- **Y2K**


**R. S. Kundaikar**  
**Vice President, Nuclear Engineering**





**FPL**

# Nuclear Engineering







**FPPL**

# **Engineering Performance**

---

**St. Lucie**

**Engineering**


**C. R. Bible**

**Engineering Manager**



**FPPL**

# WANO Weighted Overall Performance





# Engineering

## FPL Department Indicators and Goals

### Safety Focus

Indicators	Goals		St. Lucie Actuals
	Green	Red	
A. Cited Violations	0	>2	0
B. Non-Cited Violations	4	>12	0
C. Quality Assurance Findings	0	2	0
D. Reactivity Events	No Reactivity Events Due To Engineering	ECC >200 pcm or Engineering Error Reactivity Event	0
E. Fire Impairments	On Schedule	Behind Schedule	Ahead of Schedule
F. WANO Fuel Performance	$\leq 5.0 E - 4$	$>5.0 E - 4$	Unit 1 - 1.1 E -04 Unit 2 - 4.0 E -05
G. OSHA Recordables	0	1	0
H. Minor Injuries	$\leq 2$	>2	0
I. Lost Time Accidents	0	>0	0





# Engineering

## FPL Department Indicators and Goals

Problem Identification and Correction				
Indicators		Goals		St. Lucie Actuals
		Green	Red	
A.	Self Assessment	1 Per Quarter	< 1 Per 6 Months	2 Self Assessments
B.	Unplanned Plant Change Revisions	0 Revisions	≥ 2 Revisions	0 Revisions
C.	Drawing / Vendor Technical Manual / Total Equipment DataBase Changes	0 Late	≥ 6 Late	0 late
D.	Outage Plant Changes Issued on Time	Major Modifications Issued 6 Months Prior To Outage	Otherwise	0 late
E.	System Walkdown Program	> 90% Walkdowns Complete	< 70%	~80%
F.	Condition Reports	0 Late	> 5 Late	0
G.	Condition Report Corrective Actions	< 450 By Year End	> 500 By Year End	Trending to < 450
		0 Late	> 10 Late	



# Engineering

## FPL Department Indicators and Goals

### Workforce Quality

Indicators	Goals		St. Lucie Actuals
	Green	Red	
A. Engineering Training Program	100%	<90%	100%
B. Training Effectiveness	100% Attendance >95 % Pass Rate	<100% ≤95% Pass Rate	100% >95% Pass Rate
C. Significant Human Performance Issues	0	>2	0
D. Maintenance Rule Administration	Zero Untimely (a)(1) Classifications	>1	0
E. System Engineer Qualification	100% Qualified	<80% Qualified	100%
	Quality 5 System Experts	Off Plan	Behind But Recoverable
F. ALARA	>5% Under Budget	>5% Over Budget	167 Mr
G. Quality of Real Time Support	0 Perceived Deficiencies	>2 Deficiencies	1 Deficiency



# Engineering

## FPL Department Indicators and Goals

Cost Performance			
Indicators	Goals		St. Lucie
	Green	Red	Actuals
A. Unit Availability	Unit 1 >85.81% Unit 2 >94.97%	>1.0% Off Target	Both Units On Target To Meet Goal
B. Budget Performance	-2% Deviation	≥0% Deviation	-3.0%
C. Thermal Performance Indicator	>99.7%	<99.5%	99.8%
D. Fuel Cost	≤0.45¢/kw	>0.47¢/kw	0.43¢/kw
E. Refueling Outage	< 30 Days	> 30 Days	U1 Outage September '99
F. Procurement Engineering Cost Avoidance	>\$5M	<\$4M	
G. Preventive Maintenance Change Requests	Acceptable Trend	Unacceptable Trend	Backlog Decreasing





**EPPL**

---

---

# Engineering Performance


## Turkey Point Engineering

**D. J. Tomaszewski**  
**Engineering Manager**



**FPL**

# WANO Weighted Overall Performance





# Engineering

## FPL Department Indicators and Goals

Safety Focus			
Indicators	Goals		Turkey Point Actuals
	Green	Red	
A. Cited Violations	0	>2	0
B. Non-Cited Violations	4	>12	1
C. Quality Assurance Findings	0	2	0
D. Reactivity Events	No Reactivity Events Due To Engineering	ECC >200 pcm or Engineering Error Reactivity Event	0
E. WANO Fuel Performance	$\leq 5.0 E-4$	$>5.0 E-4$	Unit 3 - 4.91 E-04 Unit 4 - 5.97 E-05
F. OSHA Recordables	0	1	0
G. Minor Injuries	$\leq 2$	>2	1
H. Lost Time Accidents	0	>0	0
I. ALARA	<3.75 Rem	>4.5 Rem	





# Engineering

## FPL Department Indicators and Goals

Problem Identification and Correction				
Indicators		Goals		Turkey Point Actuals
		Green	Red	
A.	Self Assessment	1 Per Quarter	<1 Per 6 Months	2 Self Assessments
B.	Unplanned Plant Change Revisions	0 Revisions	≥2 Revisions	0 Revisions
C.	Drawing/Vendor Technical Manual / Total Equipment DataBase Changes	0 Late	≥6 Late	0 Late
D.	Outage Plant Change Issued on Time	Major Modifications Issued 6 Months Prior To Outage	Otherwise	0 Late
E.	System Walkdown Program	>90% Walkdowns Complete	<70%	75%
F.	Condition Reports	0 Late	>5 Late	0
G.	Condition Report Corrective Actions	<200 Total	>300 Total	279 Total
		0 Late	>10 Late	



# Engineering

## FPL Department Indicators and Goals

Workforce Quality				
Indicators		Goals		Turkey Point Actuals
		Green	Red	
A.	Turnovers/Vacancies	≤3	>11	4 Turnovers
B.	Engineering Training Program People Not Started Initial Training Within 12 Months Of Hire Date	≤1	>5	3
C.	SRO Training For Supervisor	≥80% Certified	<50% Certified	66%
D.	System Engineer Qualification	100% Qualified	<80% Qualified	95%
		50% Qualified On Backup System	<25%	58%
E.	Backup STA Availability	≥3 Qualified	0 Qualified	2 At Year's End



# Engineering

## FPL Department Indicators and Goals

Cost Performance				
Indicators		Goals		Turkey Point Actuals
		Green		
A.	Unit Availability	Unit 3 $\leq 95\%$ Unit 4 $\leq 85\%$	Unit 3 $< 95\%$ Unit 4 $< 85\%$	Unit 3 – 98.6 Unit 4 – 88.2
B.	Thermal Performance Indicator	$> 99.70\%$	$< 99.4\%$	Unit 3 – 99.9% Unit 4 – 99.9%
C.	Fuel Cost	$\leq 0.45¢/kw$	$> 0.47¢/kw$	.43¢/kw
D.	Refueling Outage	On time/under budget	Over budget or over schedule	23 days/ 20:57 Hrs:Min Under Budget
E.	Procurement Engineering Cost Avoidance	$> \$5M$	$< \$4M$	\$2.9M to date





**FPL**

# **Problem Solving Root Cause Analysis**

---

## **St. Lucie Unit 1 Manual Reactor Trip on Low Condenser Vacuum**

**B. K. Dunn**

**Special Projects Manager**

**St. Lucie**



**FPL**

# St. Lucie Unit 1

## Manual Reactor Trip

---

- Unit 1 on line for 545 Days
- On 8/23/99, Unit 1 was manually tripped
  - 1234: D-24 Alarm received "Gland Steam Hi/Lo Pressure"
  - 1236: D-13 Alarm received "Turbine Vacuum Low"  
Vacuum was 5.0" Hg and rapidly increasing
  - 1236: Manual Reactor Trip at 5.5" Hg condenser vacuum
- All safety systems performed as expected
- Two (2) non safety related anomalies

Condensate recirculation valve did not open as expected

6.9kV bus did not transfer from auxiliary to start up transformer









**FPL**

# St. Lucie Unit 1 Manual Reactor Trip

## Gland Steam Regulator



Actuator. Dirt and corrosion byproducts present



Pilot Regulator Nozzle : Powdery dirt found in supply port. Vent nozzle found binding due to dirt.





**FPL**

# St. Lucie Unit 1

## Manual Reactor Trip

---

### Low Condenser Vacuum

- Gland steam regulator failed, causing loss of low pressure turbine gland steam
- Pilot regulator malfunctioned due to plugged port
- Root cause is inadequate preventive maintenance (PM) on pilot regulators.
- Corrective Actions:
  - Replaced the failed pilot assembly (complete)
  - Inspected/tested all other Unit 1 gland steam regulators (complete)
  - Inspect/test Unit 2 gland steam regulators
  - Develop PM program for gland steam regulators for both units



# St. Lucie Unit 1

## FPL Manual Reactor Trip

---

### Condensate Recirculation Valve

- Valve failed to open causing a minor secondary side transient
- Results of troubleshooting:
  - Regulator providing 27 psig (50 psig required for proper operation)
  - Regulator was found to be in good condition - 1995 manufacture date
  - Cause of the inadequate pressure setting is not known, however vibration affecting the setting is a potential cause
- Corrective Actions
  - Replaced air regulator (complete)
  - Adjusted valve per plant procedure; no problems noted (complete)
  - Performed static and dynamic diagnostic checks (complete)
  - System Engineer will monitor air regulator setting for drift



## Loss of Non Safety 6.9KV BUS

- Sequence of Events

- [illegible]

- 22





**EPRI**

# **Problem Solving Root Cause Analysis**

---

## **Rod Control Events at St. Lucie**

**Manual Reactor Trip due to CEDMCS**

**C. R. Bible**

**Engineering Manager**



**FPL**

# St. Lucie Unit 2 - Manual Reactor Trip due to CEDMCS

## Time Line

### May 25:

- 5 Control Element Drive Mechanisms (CEDMs) transferred to lower grippers, trouble alarms received in the control room
- Root Cause Team formed. Troubleshooting plan developed

### June 1:

- CEA 40 spuriously dropped into core, power reduced as required by license, CEA retrieved following troubleshooting
- Event Response Team (ERT) formed, involves all Plant Departments
- Coil traces indicated anomalies at several coils

### June 3:

- ERT specified replacement of Subgroup 21 power switch



### June 4:

- Power Switch 21 (PS) replacement and troubleshooting - two successful transfers from control rod hold bus - rods dropped on third transfer.
- Operations performed a *manual trip* of the reactor.

### June 11:

- Unit returned to service following repairs to CEDMCS.

Control  
Element Drive  
Mechanism  
(Training  
mock-up)



Unit 2 CEDMCS Room



# St. Lucie Unit 2 - Manual Reactor FPL Trip due to CEDMCS

---

## Root Causes

### **Reactor Trip:**

- Replacement PS not seated into back plate
- Inadequate PS installation procedure.
- Blind transfer from hold bus was contributing factor.



### **CEDMCS Alarms and Rod Drops:**

- Phase-to-ground shorts found in PS 9, 21.
- Failed Mylar washer (PS-21).
- Anomalies (PS-9).

### **Corrective Actions prior to Unit Restart**

- Replaced PS-9, 21.
- Successful Megger test of CEDMCS.
- All coil traces verified to be acceptable.

Power  
Switch 21  
Panel



Power Switch back plate - view looking into  
cabinet with power switch removed





# St. Lucie Unit 2 - Manual Reactor

## **FPL** Trip due to CEDMCS

---

### **Key Corrective Actions:**


1. Enhanced procedure for installing power switches
2. Megger test CEDMCS to detect grounds during Refueling Outages
3. Perform Coil checks of 25% of CEA's during quarterly FLC EA tests



**EPFL**

## St. Lucie Unit 2 - CEDMCS - Comparison of Coil Traces

---



CEA #38 As-found condition shows an erratic upper gripper coil waveform caused by a missing phase in the power switch.

CEA #38 After repairs. Upper gripper coil trace shows a waveform balanced between the three phases. There are no indications of noise superimposed on the signal.

*Handwritten:* CEA #38



**EPRI**

# **Problem Solving Root Cause Analysis**

---

**Turkey Point**

**HHSI System Gas Venting**

**A. T. Zielonka**

**Systems Engineering Manager**

**Turkey Point**





**EPPL**

# Turkey Point HHSI System Gas Venting

---

- HHSI Pump Gas Intrusion
  - On 1/5/99, the 4B HHSI Pump failed to develop normal discharge pressure.
  - Root cause analysis performed. Potential causes evaluated:
    - Suction obstruction
    - Mechanical/Motor/Valve failures
    - Gas Intrusion Paths



**FPPL**

## Turkey Point HHSI System Gas Venting

---

- Root Cause: Minor leakage through multiple valves over a long period of time
- Corrective Actions
  - Vented pumps weekly
  - Cut/cap test line during spring refueling outage





**FPL**

## Turkey Point HHSI System Gas Venting

---

- After spring refueling outage
  - Operator detects warm pipe on one cold leg injection line
  - Checked for gas - Increased sensitivity due to previous experience
  - Venting header daily - Minor gas being detected
  - Overhaul suspect valves during outage of sufficient duration







**FPPL**

# Problem Solving Root Cause Analysis

---

**St. Lucie - ECCS Piping**

**B. K. Dunn**



**Special Projects Manager**

**St. Lucie**




**FPPL**


# St. Lucie ECCS Piping




24" ECCS PIPE FROM RWT TO PIPE TUNNEL



24" ECCS PIPE ENTERING PIPE TUNNEL



24" ECCS PIPE IN PIPE TUNNEL



24" ECCS PIPE EXITING PIPE TUNNEL AT RAB EAST WALL





**FPPL**

## St. Lucie ECCS Piping

- **Unit 1 (1996)**
  - Indication of "through wall leak" on 24" line at circumferential weld
  - Minor leakage, NO SAFETY SIGNIFICANCE
  - Defect removed and branch connection installed to arrest leak
  - Failure mechanism - stress corrosion cracking
  - Expanded inspection to include applicable circumferential welds
  - Applied protective coating to circumferential welds
- **Unit 2 - Refueling Outage (1998)**
  - Inspected numerous welds on 24" line
  - One minor indications removed (buffed out) and two branch connections installed
  - ASME Flaw evaluation completed for continued operation
- **Unit 2 Cycle 11 Operation (1999)**
  - Leak identified in March, branch connection installed
  - In April leaks discovered on both 24" lines
  - Relief request submitted to NRC for continued operation to prepare for repairs
  - Branch connections installed on both ECCS lines
  - Applied protective coating to all circumferential welds



**FPL**

## St. Lucie ECCS Piping

---

- **Unit 2 Replacement Plan**

- Replace piping during Spring 2000 refueling outage
- Install more corrosion resistant material
- Installation duration of 26 days at a cost of approximately \$1.7 million

- **Unit 1 Inspection Plan / Contingencies**

- No new leaks identified since 1996
- Continue enhanced inspection frequency
- Fall 1999 Refueling Action Plan
  - Inspect 2 circumferential welds and compare results to initial inspection
  - Remove 2 supports and inspect piping surface
  - Materials for pipe repairs are available, if required



**FPPL**

---

---

# **Self Assessment**

## **Fire Protection Assessment/Inspection**

**A. T. Zielonka**

**Systems Engineering Manager  
Turkey Point**





**FPL**

# Fire Protection Status

## St. Lucie Plant

---

- 1999 Targeted to Complete
  - Unit 1 & 2 Emergency Lighting Upgrades
  - Unit 1 & 2 Hose Station Additions
  - Unit 1 SSA Circuit Modifications (Outside Containment)
  - Fire Impairment Reductions
  - Detection/Suppression System Engineering Reviews



**EPPL**

# Fire Protection Status St. Lucie Plant

---

- 2000/2001 Scope of Work
  - Unit 1 Containment SSA Circuit Modification
  - Unit 2 SSA Circuit Modifications
  - Detection/Suppression System Reviews and Modifications
  - Fire Impairment Reductions



# Fire Protection Status

## EPPL Turkey Point Plant

---

- Thermo-Lag Upgrades Proceeding as scheduled. Completion in 2001.
- Fire Protection Self Assessment
  - Following NRC TI Format
  - 85% complete
  - 85 Potential Discrepancies Identified
    - 48 Minor Procedure and/or Drawing Errors
    - 18 Program Discrepancies
    - 19 Enhancements/Not Discrepant Conditions





# Fire Protection Status

## EPPL Turkey Point Plant

---

- Fire Protection Self Assessment (Cont'd)
  - No Safe Shutdown/Operability Issues
  - Condition Reports to Address Discrepancies
  - Final Report due September 30, 1999



**FPL**

## **Self Assessment**

---

**St. Lucie System / Component  
Engineering  
(SCE)**

**C. R. Bible  
Engineering Manager**



**FPL**

# St. Lucie

## SCE Performance

---

- Prior to 1996, System Engineering Group was small
- Since then have implemented a number of enhancements:
  - Upgraded System Engineering Procedures, incorporating INPO recommended practices
  - Preventative maintenance review process enhanced
  - SCE Hot Items database in Lotus Notes
  - Upgraded training program for System and Component Engineers. Progressive process from plant introduction to system expert
  - Developed System Health Window report which has played a key role in improved system reliability



[illegible][illegible][illegible]

G: Green Rating  
 W: White Rating  
 Y: Yellow Rating  
 R: Red Rating

▲ Up Trend  
 ▼ Neutral Trend  
 ▴ Down Trend

\*Classification under review

RS: Risk Significant  
NRS: Non Risk Significant  
a(2): MR Rating Acceptable  
a(1): MR Rating Unacceptable

MR Rating/Color  
SYS NAME  
ZW 1Y

Risk Significant Systems Status										Non-Risk Significant Systems Status									
RCS					CVCS					HPSI					SITs				
Main Steam					Main F/W					AFAS					CCW				
HVAC (RS)					170/208 VAC					120 V/1AC					4.16 KV				
SWGR&BRK					SWGR&BRK					Gen & Distr					EDG				
Penetration					ESFAS														
RPS																			

**Risk Significant Systems Status**

Classification under review by Expert Panel

RS: Risk Significant

NRS: Non Risk Significant

a(2): MFR Rating Acceptable

a(1): MFR Rating Unacceptable

**ABBREVIATIONS**

G: Green Rating

W: White Rating

Y: Yellow Rating

R: Red Rating

▲ Up Trend

◀ Neutral Trend

▼ Down Trend

**MAINTENANCE RULE**

SYS NAME

MR Rating/Color

ZW 1Y

[illegible][illegible]

**ABBREVIATIONS**

G: Green Rating  
W: White Rating  
Y: Yellow Rating  
R: Red Rating

Classification under review by Expert Panel

▲ Up Trend  
→ Neutral Trend  
▼ Down Trend

RS: Risk Significant  
NRS: Non Risk Significant  
a(2): MFR Rating Acceptable  
a(1): MFR Rating Unacceptable

**MAINTENANCE RULE**

MFR Rating/Color

Color	Rating
Red	1Y
Yellow	2Y

MR Rating/Color	
SYS NAME	
2M	1Y

▲ Up Trend  
 ▼ Neutral Trend  
 ▲ Down Trend

\*Classification under review by Expert Panel

▲ Up Trend  
▼ Neutral Trend  
▲ Down Trend





St. Lucie

**FPPL**

## SCE Performance

---

- Self Assessments related to SCE activities include:
  - INPO Assist visits
  - Preventative Maintenance program
  - Event Response Team (ERT) effectiveness
  - SCE effectiveness in meeting expectations
- SCE has matured as evidenced by improved equipment reliability
- Additional process enhancements needed to ensure focus on the highest priority activities
- Communications is an area for further improvement





**FPL**

---

# Self Assessment

---

## **Turkey Point Outage Performance**

**D. J. Tomaszewski**  
**Engineering Manager**  
**Turkey Point**



# Turkey Point Unit 4 Outage

**FPPL**

## Self Assessment

---

---

- Engineering Performance
  - Safety
  - Work Quality
- Future Improvements



**EPPL**

## Outage Safety

---

- Pre-Outage Risk Review
  - Two Trains of Shutdown Cooling
  - Delayed start of Emergency Diesel Inspections
  - No reduced inventory
  - Active PSA Review
- Increased Awareness Tools
  - Second Item in Plan of the Day after Industrial Safety





**EPRI**

## Outage Safety

---

- Full Core Off-Load
  - Insert Shuffle in Spent Fuel Pit
  - Shutdown Cooling Work performed when no fuel was in the Reactor



# Work Quality

**FPL**

---

---

- **Modifications - 18 Modifications**
  - 12 Regulatory/Corrective Action items
  - 6 Economic/Reliability Upgrades
  - No Unplanned Revisions
  - Minimum number of minor changes
- **Improved Processes**
  - ALARA Focus
    - Lift Rig
    - Risk Informed ISI



**EPRI**

## Work Quality

---

- Improved Processes (Cont'd)
  - Cross Under Repairs
  - Computerized Radiography
  - Low Power Physics Testing
  - Core Mapping
  - Power Ascension







**FPPL**

---

---



# Fuel Identification System





**FPPL**

**What does it look like?**








**FPPL**

## In Use at Turkey Point








**EPRI**

# Power Ascension Improvements

**TURKEY POINT STATION - Power Ascension Comparison**





**FPL**

---

## Future Improvements

- ALARA
  - Risk Based ISI - Class I only
  - Reactor Coolant System Cleanup/Shutdown Chemistry Improvements
- On-Line Inspection/Maintenance
- Risk Awareness Improvements



**FPPL**

---

## **Initiatives**

### **Steam Generator (SG) Program**

**R. D. Gil**

**Component Support & Inspections  
Manager**





**FPPL**

## **SG Program**

---


- Turkey Point SGs replaced in 1983 and 1984 (Unit 4 & Unit 3 respectively) - in good health
- St. Lucie Unit 1 SGs replaced in 1997
- St. Lucie Unit 2 SGs are in good health - closely monitored



**EPFL**

# SG Program St. Lucie Unit Comparison

PSL 1 & 2 SG Tube Plugging





**FPL**

## **SG Program**

---

---

- Health of SGs is a high management priority
  - SG Management Team is in place
- Implementation of NEI 97-06 industry initiative being finalized this year





**FPPL**

## **SG Program**

---

---


- **Robust Inspection Program**
  - Exceeds regulatory minimums
  - Use best available technology
- **Aggressive Maintenance Program**
  - Sludge lancing performed each outage
  - Developed high volume bundle flush
  - Optimized chemistry program



FPPL

# SG Program

## Turkey Point Unit 3 Steam Generator Sludge Removal History





**FPL**

## **SG Program**

---

- Recent NRC Notices and Generic Letters
  - No Impact on FPL Program
    - IN 97-88: Experiences During Recent SG Inspections
    - GL 97-05: Steam Generator Tube Inspection Techniques
    - GL 97-06: Degradation of Steam Generator Internals





**FPPL**

---

---

## **Initiatives**

### **Turkey Point**

#### **License Renewal**

**E. A. Thompson**


**Project Manager**



# FPL License Renewal Project


---

- Preparing an application for renewed license for Turkey Point
- Planning to submit application by end of 2000
- Benefits of license renewal include:
  - Low cost electricity producer
  - Excellent station performance
  - Key location--south of Miami
  - Environmental benefits - low greenhouse emissions
  - Precludes need for construction of alternate generating capacity
- Renewed license keeps option available to continue operating Turkey Point





# Renewed License Application Preparation Timeline








**FPL**

# License Renewal Timeline





**FPL**

## Project Progress

---

---

- Project is on target
  - Interfacing with other federal, state, and local agencies
    - . Facilitate license application review period
    - . Feedback is positive
- Following NRC inspections of other applicants



## St Lucie

# **FPL Unit 1 Steam Trestle HELBA**

---

---

### ISSUE

Review of the high energy line break analysis (HELBA) and qualification of equipment located in the steam trestle area

- Licensing basis for the steam trestle determined the area was not harsh due to a short event duration and "thermal lag" effects
- NRC Letter dated June 14, 1999 stated the steam trestle should be considered a "harsh environment" per 10 CFR 50.49





# St Lucie

## FPL Unit 1 Steam Trestle HELBA

---

---

### LICENSING BASIS (UFSAR Section 3.11)

- Dept. of Operating Reactors (DOR) guidelines used for qualification of electrical components.
- Steam trestle components determined to be outside scope of DOR
  - Weatheright boxes
  - Short duration of HELB environment
- Licensed to main steam line break HELBA criteria (UFSAR Section 3.11):
  - Postulates full guillotine rupture of main steam header
  - Steam generator blows dry in 60-90 seconds (event terminated)
  - Conservatively assumes break at any location (not limited to high stress)
  - Results documented in FSAR
- Predates 10 CFR 50.49
  - The steam trestle areas are open to atmosphere

CENTER LINE  
REACTOR

GRATING NOT SHOWN  
AT FLOOR ELEV. 41'  
FOR CLARITY

REACTOR CONTAINMENT


PENETRATION LOCK  
AT ELEV. 36'

MV-09-8


CHECK VALVE

B1507  
PUSH BUTTON  
STATION FOR  
(MV-09-12)

TURBINE GENERATOR  
BUILDING




Steam Trestle Area (View A)






Typical Grating & Electrical Box (View B)



# Steam Trestle Overhead Grating







**FPL**

## St Lucie Unit 1 Steam Trestle HELBA

### TIMELINE

- 1976 - Operating License granted based on MSLB HELBA in UFSAR (Appendices 3C & 3D)
- January, 1980 - IEB 79-01 issued, accepts use of existing HELBA
- August, 1980 - PSL response to IEB documents use of existing HELBA
- September, 1980 - Suppl. 2 to IEB issued, requested consideration of a spectrum of breaks
- May, 1981 - NRC SER accepts use of FSAR HELBA
- February, 1983 - NRC TER accepts use of FSAR HELBA (Franklin Institute Report)
- April, 1983 - NRC SER accepts use of FSAR HELBA (agrees with TER)
- 1987 - GL 87-11 issued
  - PSL commits to comply for future modifications (added UFSAR Appendix 3J)
- NRC letter of June 14, 1999 states that steam trestle area needs to be considered harsh





# St Lucie

## FPPL Unit 1 Steam Trestle HELBA

---

### IMMEDIATE ACTIONS

- Condition Report 99-0780 issued
- Plant operability verified to UFSAR criteria (licensing basis)
  - Identified Safety Related equipment installed in steam trestle
  - Safety Related equipment found to be in weatherproof boxes or qualified for harsh environment
  - Walkdowns performed to confirm configuration
  - Material condition of electrical boxes verified by walkdown



# St Lucie

## FPL Unit 1 Steam Trestle HELBA

---

### ADDITIONAL ACTIONS

The licensing basis HELB does not include analysis of a spectrum of break sizes. Engineering is reviewing these "beyond licensing basis" breaks. Actions include:

- Identification of high energy lines in steam trestle area (MFW, AFW, MS)
- Identification of break locations per UFSAR Appendix 3J (BTP MEB 3-1)
  - 33 potential break locations identified based on stress analysis criteria
  - Conservatively identified 12 potential leakage crack locations in addition to break locations
  - Independent verification completed
- Walkdowns for each break location to identify affected components
  - Developed matrix relating each potential break location with potentially affected equipment
  - 33 x 97 matrix also identifies distance to affected components (line-of-sight)
- Identification of bounding break scenarios
  - Grouped similar break locations and identified 6 bounding break locations
  - Only 2 of the bounding scenarios potentially impacted required redundant equipment
- Detailed review of affected equipment for bounding scenarios



**FPL**

# St Lucie Unit 1 Steam Trestle HELBA

---

## ANALYSIS OF AFFECTED EQUIPMENT

- Limiting break locations potentially affect only two components:
  - MV-09-11 (AFW Pump 1C to S/G 1A)
  - Push button station for MV-09-12 (B1507)
- MV-09-11 is qualified to inside containment EQ criteria.
- B1507 will not be directly impacted
  - Distance from break to box is ~ 21 feet
  - Push button construction - an electrical box installed within a weathertight box
  - Line-of-sight to break location is severely limited due to several obstructions
  - Altran analysis shows that break influence is less than 11 feet
- Leakage Crack were also conservatively investigated.
  - 12 potential locations identified
  - Only 1 leak location potentially impacted redundant safety related equipment
  - closest equipment is ~ 13 feet
  - Altran analysis shows leakage crack influence is less than 3 feet





**FPL**

## St Lucie


### Unit 1 Steam Trestle HELBA

---

#### CONCLUSIONS


- Plant meets licensing basis requirements
- Walkdowns and reviews conducted demonstrate equipment operability
- Results from review of a spectrum of break locations indicate that Safety Related equipment would not be adversely impacted by postulated breaks

B1507 (NEMA-4) (View C)





Box 1507 Looking Toward Break (View D)





Break Looking Toward B1507 (View E)

