



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

JUL 15 1986

MEMORANDUM FOR: Richard W. Starostecki, Director, DRP, RI
Roger D. Walker, Director, DRP, RII
Charles E. Norelius, Director, DRP, RIII
Eric H. Johnson, Director, DRP, RIV
Dennis F. Kirsch, Director, DRP, RV

FROM: Edward L. Jordan, Director
Division of Emergency Preparedness
and Engineering Response
Office of Inspection and Enforcement


SUBJECT: IE BULLETIN 80-20 CLOSEOUT

Enclosed is a copy of NUREG/CR-3962 pertaining to the closeout of IE Bulletin 80-20 "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches". This report was prepared by Parameter Inc. under contract to IE. Parameter's review effort included evaluation of utility responses, deficiency reports, and NRC regional inspection reports for 124 nuclear power plants in operation or under construction.

Parameter's review of utility responses and NRC/IE inspection reports determined that the bulletin has been closed for 122 out of the 124 current facilities. The closed out facilities reported that they either do not use the affected equipment in safety related systems or they comply with the requirements of the bulletin. Proposed followup items for the remaining 2 current facilities (Sequoyah 1&2) are presented in Appendix C.

IE has reviewed NUREG/CR-3962 and concur in the contractor's conclusions that IEB 80-20 is considered closed. However, Appendix C proposes followup items for 2 facilities and IE agrees. Since no additional failures were noted in the responses to this bulletin, IE is not suggesting any additional action.

If you have any questions pertaining to the closeout, please contact James C. Stewart of my staff at 492-9061.


Edward L. Jordan, Director
Division of Emergency Preparedness
and Engineering Response
Office of Inspection and Enforcement

Enclosure: NUREG/CR-3962

8607180129

XA

IE11
11

Closeout of IE Bulletin 80-20: Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches

Prepared by R. S. Dean, W. J. Foley, A. Hennick

PARAMETER, Inc.

Prepared for
U.S. Nuclear Regulatory
Commission

~~860701448~~

NOTICE

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, or any of their employees, makes any warranty, expressed or implied, or assumes any legal liability of responsibility for any third party's use, or the results of such use, of any information, apparatus, product or process disclosed in this report, or represents that its use by such third party would not infringe privately owned rights.

NOTICE

Availability of Reference Materials Cited in NRC Publications

Most documents cited in NRC publications will be available from one of the following sources:

1. The NRC Public Document Room, 1717 H Street, N.W.
Washington, DC 20555
2. The Superintendent of Documents, U.S. Government Printing Office, Post Office Box 37082,
Washington, DC 20013-7082
3. The National Technical Information Service, Springfield, VA 22161

Although the listing that follows represents the majority of documents cited in NRC publications, it is not intended to be exhaustive.

Referenced documents available for inspection and copying for a fee from the NRC Public Document Room include NRC correspondence and internal NRC memoranda; NRC Office of Inspection and Enforcement bulletins, circulars, information notices, inspection and investigation notices; Licensee Event Reports; vendor reports and correspondence; Commission papers; and applicant and licensee documents and correspondence.

The following documents in the NUREG series are available for purchase from the GPO Sales Program: formal NRC staff and contractor reports, NRC-sponsored conference proceedings, and NRC booklets and brochures. Also available are Regulatory Guides, NRC regulations in the *Code of Federal Regulations*, and *Nuclear Regulatory Commission Issuances*.

Documents available from the National Technical Information Service include NUREG series reports and technical reports prepared by other federal agencies and reports prepared by the Atomic Energy Commission, forerunner agency to the Nuclear Regulatory Commission.

Documents available from public and special technical libraries include all open literature items, such as books, journal and periodical articles, and transactions. *Federal Register* notices, federal and state legislation, and congressional reports can usually be obtained from these libraries.

Documents such as theses, dissertations, foreign reports and translations, and non-NRC conference proceedings are available for purchase from the organization sponsoring the publication cited.

Single copies of NRC draft reports are available free, to the extent of supply, upon written request to the Division of Technical Information and Document Control, U.S. Nuclear Regulatory Commission, Washington, DC 20555.

Copies of industry codes and standards used in a substantive manner in the NRC regulatory process are maintained at the NRC Library, 7920 Norfolk Avenue, Bethesda, Maryland, and are available there for reference use by the public. Codes and standards are usually copyrighted and may be purchased from the originating organization or, if they are American National Standards, from the American National Standards Institute, 1430 Broadway, New York, NY 10018.

Closeout of IE Bulletin 80-20: Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches

Prepared by R. S. Dean, W. J. Foley, A. Hennick

PARAMETER, Inc.

Prepared for
U.S. Nuclear Regulatory
Commission

~~860701448~~

NOTICE

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, or any of their employees, makes any warranty, expressed or implied, or assumes any legal liability of responsibility for any third party's use, or the results of such use, of any information, apparatus, product or process disclosed in this report, or represents that its use by such third party would not infringe privately owned rights.

NOTICE

Availability of Reference Materials Cited in NRC Publications

Most documents cited in NRC publications will be available from one of the following sources:

1. The NRC Public Document Room, 1717 H Street, N.W.
Washington, DC 20555
2. The Superintendent of Documents, U.S. Government Printing Office, Post Office Box 37082,
Washington, DC 20013-7082
3. The National Technical Information Service, Springfield, VA 22161

Although the listing that follows represents the majority of documents cited in NRC publications, it is not intended to be exhaustive.

Referenced documents available for inspection and copying for a fee from the NRC Public Document Room include NRC correspondence and internal NRC memoranda; NRC Office of Inspection and Enforcement bulletins, circulars, information notices, inspection and investigation notices; Licensee Event Reports; vendor reports and correspondence; Commission papers; and applicant and licensee documents and correspondence.

The following documents in the NUREG series are available for purchase from the GPO Sales Program: formal NRC staff and contractor reports, NRC-sponsored conference proceedings, and NRC booklets and brochures. Also available are Regulatory Guides, NRC regulations in the *Code of Federal Regulations*, and *Nuclear Regulatory Commission Issuances*.

Documents available from the National Technical Information Service include NUREG series reports and technical reports prepared by other federal agencies and reports prepared by the Atomic Energy Commission, forerunner agency to the Nuclear Regulatory Commission.

Documents available from public and special technical libraries include all open literature items, such as books, journal and periodical articles, and transactions. *Federal Register* notices, federal and state legislation, and congressional reports can usually be obtained from these libraries.

Documents such as theses, dissertations, foreign reports and translations, and non-NRC conference proceedings are available for purchase from the organization sponsoring the publication cited.

Single copies of NRC draft reports are available, free, to the extent of supply, upon written request to the Division of Technical Information and Document Control, U.S. Nuclear Regulatory Commission, Washington, DC 20555.

Copies of industry codes and standards used in a substantive manner in the NRC regulatory process are maintained at the NRC Library, 7920 Norfolk Avenue, Bethesda, Maryland, and are available there for reference use by the public. Codes and standards are usually copyrighted and may be purchased from the originating organization or, if they are American National Standards, from the American National Standards Institute, 1430 Broadway, New York, NY 10018.

Closeout of IE Bulletin 80-20: Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches

Manuscript Completed: April 1986
Date Published: June 1986

Prepared by
R. S. Dean, W. J. Foley, A. Hennick

PARAMETER, Inc.
13380 Watertown Plank Road
Elm Grove, WI 53122

Prepared for
Division of Emergency Preparedness and Engineering Response
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555
NRC FIN B8729

ABSTRACT

On June 18, 1980, Commonwealth Edison Company submitted Licensee Event Report (LER) 50-295/80-24 to the NRC, describing a malfunction of a Westinghouse Type W-2 control switch important to safety at Zion Unit 1. On the same date, Westinghouse submitted a preliminary issue of Technical Bulletin NSD-TB-80-9 to the NRC on the subject switches. On July 31, 1980, IE Bulletin 80-20 was issued to all power plant licensees and permit holders, requiring them to take specific actions and report results. Evaluation of utility responses and NRC/IE inspection reports shows that the bulletin can be closed out per specific criteria for 122 (98%) of the 124 current facilities to which it was issued. A followup item for the remaining two facilities is proposed for use by NRC/IE, to ensure satisfactory completion of corrective action.

TABLE OF CONTENTS

| | <u>Page</u> |
|---|-------------|
| Abstract | iii |
| Introduction | 1 |
| Summary | 1 |
| Conclusions | 3 |
| Remaining Areas of Concern | 3 |
| Criteria for Closeout of Bulletin | 4 |
| Appendix A Background Information | |
| IE Bulletin 80-20 | A-1 |
| CECO LER 50-295/80-24 for Zion 1 | A-4 |
| Westinghouse Technical Bulletin | |
| NSD-TB-80-9, Rev. 1 | A-7 |
| Letter of November 19, 1985, to | |
| James Stewart (IE/HQ) from | |
| J. W. Hufham (TVA) | A-9 |
| Letter of August 5, 1981 to J. A. | |
| Raulston (TVA) from J. L. Tain (<u>W</u>) | A-10 |
| Appendix B Documentation of Bulletin Closeout | |
| Table B.1 Bulletin Closeout Status | B-1 |
| References | B-10 |
| Appendix C Proposed Followup Item | C-1 |
| Appendix D Table D.1 Identification of Affected | |
| Systems, Numbers of Type | |
| W-2 Switches and Numbers | |
| of Failures | D-1 |
| Appendix E Abbreviations | E-1 |

CLOSEOUT OF IE BULLETIN 80-20:
FAILURES OF WESTINGHOUSE TYPE W-2
SPRING RETURN TO NEUTRAL CONTROL SWITCHES

INTRODUCTION

In accordance with the Statement of Work in Task Order 003 under Contract NRC 05-85-157-02, this report provides documentation for the closeout status of IE Bulletin 80-20. Documentation is based on the records obtained from the IE File, the NRC Document Control System, and the cognizant engineer's file.

IE Bulletin 80-20 was issued July 31, 1980 because of concern about failures of Westinghouse Type W-2 spring return to neutral control switches. Commonwealth Edison Company (CECO) had submitted a Licensee Event Report (LER) to the NRC to describe the failure of a Type W-2 switch to actuate automatic start of a service water pump at Zion Unit 1. A review of this matter by Westinghouse led to the issuance of a technical bulletin. In order to ensure operability of safety-related systems containing these switches, all holders of operating licenses and construction permits were required to take specific actions and report results.

For background information, IE Bulletin 80-20, CECO LER 50-295/80-24, Westinghouse Technical Bulletin NSD-TB-80-9, letter of November 19, 1985 from TVA to IE/HQ and letter of August 5, 1981 from Westinghouse to TVA are included in Appendix A. Evaluation of licensees' responses and NRC/IE inspection reports is documented in Appendix B as the basis for bulletin closeout. A followup item is proposed in Appendix C for use by NRC/IE in assuring satisfactory completion of corrective action. Tabulation of supplementary information required by the bulletin is included in Appendix D. Abbreviations used in this report and associated documents are presented in Appendix E.

SUMMARY

1. The bulletin has been closed out for 40 non-current facilities, per Criterion 1 (see Page 4).

2. The bulletin has been closed out for the following 84 current facilities which have no subject Type W-2 switches in safety-related systems, per Criterion 2.

| | | |
|--------------------|---------------------|------------------|
| Arkansas 1,2 | Fort Calhoun 1 | Perry 1,2 |
| Beaver Valley 1,2 | Fort St. Vrain | Pilgrim 1 |
| Big Rock Point 1 | Grand Gulf 1 | Quad Cities 1,2 |
| Browns Ferry 1,2,3 | Harris 1 | River Bend 1 |
| Brunswick 1,2 | Hatch 1,2 | Robinson 2 |
| Callaway 1 | Hope Creek 1 | San Onofre 2,3 |
| Calvert Cliffs 1,2 | La Crosse | Seabrook 1,2 |
| Catawba 1,2 | LaSalle 1,2 | Shoreham |
| Clinton 1 | Limerick 1,2 | South Texas 1,2 |
| Cook 1,2 | Maine Yankee | Summer 1 |
| Cooper Station | McGuire 1,2 | Surry 1,2 |
| Crystal River 3 | Millstone 1,2,3 | TMI 1 |
| Davis-Besse 1 | Monticello | Trojan |
| Diablo Canyon 1,2 | Nine Mile Point 1,2 | Vermont Yankee 1 |
| Dresden 2,3 | Oconee 1,2,3 | Vogtle 1,2 |
| Duane Arnold | Oyster Creek 1 | WNP 1,2 |
| Fermi 2 | Palisades | Waterford 3 |
| FitzPatrick | Palo Verde 1,2,3 | Wolf Creek 1 |
| | | Yankee-Rowe 1 |

3. The bulletin has been closed out for the following 14 current facilities which have no subject Type W-2 switches with the neutral position contacts in control circuits for safety-related systems, per Criterion 3.

| <u>Facility</u> | <u>*Number of Type W-2 Switches</u> |
|------------------|-------------------------------------|
| Bellefonte 1,2 | 22 |
| North Anna 1,2 | 16 |
| Peach Bottom 2,3 | 26 |
| Rancho Seco 1 | 4 |
| Salem 1,2 | 6 |
| St. Lucie 1,2 | (Not given) |
| Susquehanna 1,2 | 88 |
| WNP 3 | (Not given) |

*Used in safety-related systems, with neutral position contacts not used in circuits for automatic control of safety-related systems.

4. The bulletin has been closed out for the following 24 current facilities for which NRC/IE inspectors indicate satisfactory completion of corrective action, per Criterion 4.

| | | |
|-------------------|--------------------|------------------|
| Braidwood 1,2 | Haddam Neck | San Onofre 1 |
| Byron 1,2 | Indian Point 2,3 | Turkey Point 3,4 |
| Comanche Peak 1,2 | Kewaunee | Watts Bar 1,2 |
| Farley 1,2 | Point Beach 1,2 | Zion 1,2 |
| Ginna | Prairie Island 1,2 | |

5. The bulletin is called open for Sequoyah 1 and 2. Followup is proposed in Appendix C.
6. Table D.1 lists 1068 subject Type W-2 switches. No failures during the first series of tests have been reported.
7. For Zion 1,2, closure of the bulletin was by Inspection Report 295/80-20, 304/80-21 (11-28-80). After that time, problems developed concerning the switch circuits for starting auxiliary feedwater pumps. The switch modifications made to comply with the bulletin produced these circuitry problems only at Zion. This situation is addressed in detail in Inspection Report 295/81-22, 304/81-18, where inspection followup items were initiated to track the problem. The inspection items were closed out by Inspection Report 295/82-20 for Unit 1, and by Inspection Report 302/84-07 for Unit 2.

CONCLUSIONS

1. There were no failures of the neutral contact closure during the first series of tests. This would verify the Westinghouse conclusion that the problem at Zion 1 was not generic, but rather that the intermittent failure of the contacts to close was a random occurrence.
 2. The occurrence of failure of the neutral contacts of the switch to close has been shown to be random, quite infrequent, and unpredictable. The safety-related consequences, as described by the bulletin (Appendix A), are serious. Therefore, action to avoid the occurrence completely is justified. Suitable action approved by the NRC can be any one of the following:
 - (1) The periodic and after use testing for contact closure
 - (2) Rewiring the switches to put the indicator lamp in series with the neutral contacts
 - (3) Replacement of switches with ones made using Westinghouse revised manufacturing procedures.*
- *Refer to Westinghouse letter to TVA of August 5, 1981 (see Appendix A, Page A-10).
3. The problems with modified W-2 switch circuits were unique to Zion and have been corrected.

REMAINING AREAS OF CONCERN

Verification by IE inspection that bulletin actions have been completed satisfactorily is needed to close out the bulletin for Sequoyah 1 and 2 (See Appendix C).

CRITERIA FOR CLOSEOUT OF BULLETIN

The bulletin is closed out for facilities to which one of the following criteria applies:

1. The facility has been cancelled, deferred indefinitely or shut down indefinitely.
2. A response for the facility complies with actions required by the bulletin and indicates that it does not have Westinghouse Type W-2 spring return to neutral control switches in safety-related systems.
3. A response for the facility complies with actions required by the bulletin and indicates that it has Westinghouse Type W-2 spring return to neutral control switches in safety-related systems, but that the neutral position contacts are not used, or are not used in circuits for automatic control of safety-related systems.
4. A response for the facility complies with required bulletin actions and an NRC/IE inspection report indicates that corrective action has been completed satisfactorily.

APPENDIX A

Background Information

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

SSINS No.: 6820
Accession No.:
8006190023

July 31, 1980

IE Bulletin No. 80-20

FAILURES OF WESTINGHOUSE TYPE W-2 SPRING RETURN TO NEUTRAL CONTROL SWITCHES

By letter dated June 18, 1980, Commonwealth Edison Company submitted Licensee Event Report No. LER 50-295/80-24 to the NRC describing a malfunction of a Westinghouse Type W-2 control switch at the Zion Generating Station, Unit 1. The malfunctioning switch is a three position spring return to neutral switch. Although the switch was in its proper neutral position when it malfunctioned, its neutral contacts failed to close properly thereby preventing the automatic start of 1A Service Water Pump.

Subsequent tests conducted on the malfunctioning switch revealed that contact closure was intermittent with the switch in the neutral (or "Auto Start") position. Other tests conducted on identical switches from spares and from Unit 2 equipment disclosed two additional switches with a tendency for intermittent contact closure.

A review of this matter by Westinghouse led to the issuance of NSD Technical Bulletin No. NSD-TB-80-9 to the utility owners of all Westinghouse operating plants. The recommendations contained in the Westinghouse technical bulletin include: (i) testing the neutral position contacts of the subject W-2 switches for continuity, and (ii) rewiring of the indicating light circuit to permit the early detection of a neutral contact failure as shown in Figure 1.

Depending on how the indicating light circuit is wired, loss of continuity thru the neutral position contact of a W-2 switch could remain undetected until the equipment associated with the switch were called upon to operate. Since such a failure would be equivalent to by-passing the system associated with the switch, consideration should be given to rewiring the switches used in safety-related applications as shown in Figure 1. Such rewiring would provide an acceptable means for detecting contact failure, provided the indicating light is in the control room and readily visible by the operator. If the indicating light is not so located, consideration should be given to annunciating the neutral position contact failures at the control room to alert the operator of the inoperable status of a safety-related system. In addition, consideration should be given to adding redundant contacts to the W-2 switches or to replacing the W-2 switches with others having a more positive contact wiping action.

ACTIONS TO BE TAKEN BY LICENSEES AND HOLDERS OF CONSTRUCTION PERMITS:

1. Determine whether Westinghouse Type W-2 control switches with spring return to neutral position are used in safety-related applications at your facility. If so, identify the safety-related systems using these

switches and the total number of switches so used. If no such switches are used in your facility, you should indicate that this is the case and ignore the remaining questions.


2. Licensees of operating plants using Type W-2 spring return to neutral control switches in safety-related applications shall perform continuity tests on all such switches. These tests shall be performed with the switch operator in the neutral position and completed within ten (10) days of the date of this bulletin. In addition, this continuity test shall be repeated at least every thirty-one (31) days after the initial test and after each manipulation of the switch from its neutral position. These continuity tests may be discontinued subsequent to implementing the longer term corrective measures described below.
3. Licensees of operating plants and holders of construction permits shall describe the longer term corrective measures planned and the date by which such measures will be implemented by actual installation or by design change, as appropriate. As a minimum, the longer term corrective measures should include rewiring the indicating light as shown in Figure 1 provided the light is readily visible to the control room operator. If not, failures of the neutral position contacts should be annunciated in the control room.

A report addressing the above matters, including the number of failures detected during the first series of tests and the safety-related systems involved, shall be submitted to the director of the appropriate NRC regional office within forty-five (45) days of the date of this bulletin. A copy of the report shall be forwarded to the Director, Division of Reactor Operations Inspection, Office of Inspection and Enforcement, Nuclear Regulatory Commission, Washington, D. C. 20555.

Approved by GAO, B180225 (R0072); clearance expires 7/31/80. Approval was given under a blanket clearance specifically for identified generic problems.

Enclosure:
Figure 1

EXISTING INDICATING LIGHT CIRCUIT (TYPICAL)



PROPOSED REWIRING OF INDICATING LIGHT CIRCUIT (TYPICAL)




FIGURE 1

REWIRING OF INDICATING LIGHT CIRCUIT OF W-2 SWITCHES
AS RECOMMENDED BY WESTINGHOUSE TECHNICAL BULLETIN NSD-TB-80-9

Updated Report - Previous Report Date: 6-13-80 U.S. NUCLEAR REGULATORY COMMISSION
LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 I L Z I S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

ON'T
1 REPORT SOURCE L 6 0 5 0 0 0 2 9 5 7 0 5 1 5 8 0 8 0 6 1 8 8 0 9
60 61 DOCKET NUMBER 65 66 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

12 During power operation while performing PT-10, Safeguards Actuation Tests
13 1A service water pump failed to start from train A of Safeguards. The
14 pump was started from the control board satisfactorily. Re-test was
15 immediately attempted and completed satisfactorily from train A and B of
16 Safeguards. On 6/14/80 this was reported to the NRC under 10CFR21.
17
18
19

9 SYSTEM CODE WA 11 CAUSE CODE B 12 CAUSE SUBCODE B 13 COMPONENT CODE C K T B R K 14 COMP SUBCODE E 15 VALVE SUBCODE Z 16
17 LER NO REPORT NUMBER 8 0 21 22 0 2 4 24 25 9 9 28 29 X 30 1 32
ACTION TAKEN X 18 FUTURE ACTION F 19 EFFECT OF PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPD-4 FORM 400 Y 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURED W 1 1 2 1 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 After circuit was proved operable a follow up investigation revealed
11 Westinghouse Type W-2 switch contacts used in ESF component actuation
12 circuits were making intermittent contact. The root cause could not be
13 determined due to the random nature of the failure. All switch contacts
14 have been verified closed. Permanent modifications are being evaluated.
15
16
17

15 FACILITY STATUS E 16 POWER 1 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION Engineer Observation 32
16 ACTIVITY CONTENT 2 33 2 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
17 PERSONNEL EXPOSURES NUMBER 1 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
20 PUBLICITY N 44 DESCRIPTION NA 45

80063004/2

W. R. Kurth

PHONE 312-746-2084 X349

ATTACHMENT TO LER

NO. 80-24/99 X-1

COMMONWEALTH EDISON CO.

ZION GENERATING STATION

50-295

The failure of the 1A Service Water Pump during testing precipitated an investigation of the actuating circuit for this particular pump. The testing revealed a random failure mode for the Westinghouse Type W-2 Control Switch which caused the closed auto start contact to be open intermittently. These switches are used in many of the ESF Components' Circuitry and the failure of the auto start contact could prohibit component auto start on a safeguards actuation signal. Therefore the NRC was notified of a safety significant defect in the Westinghouse Type W-2 Control Switch under the requirements of 10CFR21.21. Voltage measurements were made to verify the contacts were in fact closed on the operating unit. All W-2 switch contacts on the unit in refueling will be verified prior to startup. Permanent modifications are being evaluated to correct the problem.

The following information is provided as required by 10CFR21.21.b.3:

- i. Name and address of the individual or individuals informing the Commission.

Larry Soth, Assistant Superintendent, Zion Generating Station.
101 Shiloh Blvd
Zion, Illinois 60099

- ii. Identification of the facility, the activity, or the basic component supplied for such facility or such activity within the United States which fails to comply or contains a defect.

Westinghouse Type W-2 Control Switch with spring return to neutral position.

- iii. Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.

Westinghouse Electric Company (Electrical Division)

- iv. Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply.

The auto start closed contact has been observed to fail open when the switch is in the neutral or auto start position. This failure could cause the respective piece of ESF equipment controlled by the switch to fail to auto start on a safety injection signal.

- v. The date on which the information of such defect or failure to comply was obtained.

6/13/80

- vi. In the case of a basic component which contains a defect or fails to comply, the number and location of all such components in use at, supplied for, or being supplied for one or more facilities or activities subject to the regulations in this part.

There are presently 29 switches per unit in ESF circuits at Zion Station and 7 in the station storeroom. No new switches are presently on order.

- vii. The corrective action which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action.

All switches on the operating unit in ESF circuits have been tested to show the contact to be presently closed. 13 of the 29 switches on the unit in refueling have been tested and the remaining 16 switches will be tested prior to startup. Modifications are being evaluated for permanent solution to the problem by Commonwealth Edison Company and Westinghouse Electric Corporation. Modifications will be implemented expeditiously.

- viii. Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees.

Commonwealth Edison Company is presently awaiting written results of the Westinghouse management evaluation and recommended solution.



Westinghouse
Nuclear
Service
Division

Technical Bulletin



An advisory notice of a recent technical development pertaining to the installation or operation of Westinghouse-supplied Nuclear Plant equipment. Recipients should evaluate the information and recommendation, and initiate action where appropriate.

P.O. Box 2728, Pittsburgh, PA 15230

| | | | |
|-----------------|---|---------|----------------------|
| Subject | W-2 Switches (with spring return to neutral) | Number | NSD-TB-80-9 (Rev. 1) |
| System(s) | Electrical Control | Date | 2/16/81 |
| Affected Plants | All Sites | S.O.(s) | 385 |
| References | NSD TB-73-26, & initial issue of this bulletin, dated 7/18/80 | Sheet | 1 Of 2 |

BACKGROUND INFORMATION

During monthly operational testing of the safeguards system at an operating nuclear plant, intermittent W-2 switch operation was discovered in the neutral (auto) position. Investigations revealed that the intermittent operation resulted when the switch is returned from the eleven or one o'clock position to the neutral (auto) position. The matter was reported to the Nuclear Regulatory Commission on June 18, 1980. At the same time, the initial issue of this Bulletin presented preliminary Westinghouse recommendation,

W Switchgear Division, the manufacturer, has completed a thorough evaluation of the W-2 switch with spring return to neutral (auto), and concluded that no generic failure mechanism exists. This conclusion has been confirmed by independent tests at the W Research Laboratories. The intermittent contact closure reported above was a random occurrence. The RECOMMENDED ACTION previously provided by Westinghouse in the initial issue of this Bulletin is modified as indicated below. These actions meet the minimum requirements recommended by NRC Bulletin 80-20 of July 31, 1980.

RECOMMENDED ACTION

1. All plants should test all safety-related contacts of the W-2 switches (with spring return to neutral position) in the neutral position.
2. These tests should be repeated following each subsequent use (removal from the neutral position) of the switch, and should be done either at normal operating voltage at the contacts, or at least 24 VDC.

Additional Information, if Required, may be Obtained from the Originator. Telephone 412 - 256-5493 or (WIN) 236-5493.

Originator
W H Furfari
W. H. Furfari
Electric Service

Approval
J R Terry
J. R. Terry, Manager
Electric Service

Neither Westinghouse Electric Corporation nor its employees make any warranty or representation with respect to the accuracy, completeness or usefulness of the information contained in this report or assume any responsibility for liability or damage which may result from the use of such information.

WESTINGHOUSE FORM 55378



Westinghouse
Nuclear
Service
Division

Technical Bulletin



An advisory notice of a recent technical development pertaining to the installation or operation of Westinghouse-supplied Nuclear Plant equipment. Recipients should evaluate the information and recommendation, and initiate action where appropriate.


P.O. Box 2728, Pittsburgh, PA 15230

NSD-TB-80-9 (Rev. 1)

-2-

2/16/81

As an alternative to these periodic tests, a permanent resolution of any tendencies to intermittent contact continuity is to wire the existing breaker green light indicator in series with the neutral position safety-related switch contacts (See Sketch). In those instances where no indicating lights exist, a lamp drawing a minimum of 30 milliamperes D.C. should be added. This current provides for breakdown of contact film contaminants (fritting) so that no safety circuit relaying on contact continuity can fall into a degraded condition. Green light indication will now confirm closure of the safety-related switch contacts, and this indication should be checked after each switch operation.



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
5N 157B Lookout Place

November 19, 1985

Mr. James Stewart
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mail Stop 359 EW/W

Dear Mr. Stewart

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - OFFICE OF INSPECTION AND ENFORCEMENT
- BULLETIN 80-20 - FAILURES OF WESTINGHOUSE TYPE W-2 SPRING RETURN-TO-NEUTRAL
CONTROL SWITCHES - SUPPLEMENTAL INFORMATION

As discussed in your recent telephone conversation with Ralph Shell, we are providing a copy of the August 5, 1981 Westinghouse letter describing to us the two options available for correction of the problems with the type W-2 switches.

If there are any question, please get in touch with R. H. Shell at
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. W. Hufham
J. W. Hufham, Manager

Licensing and Risk Protection

Enclosure

395-05
395-05
95-29

NAR



82082703131

2

Westinghouse
Electric Corporation

Water Reactor
Divisions

AUG 13 81

Nuclear Commercial
Operations Division

Box 355
Pittsburgh Pennsylvania 15230

| JAR COM | DRAFT COM | INFO | DUE |
|------------------|------------|------|------|
| CL | REPLY COPY | COPY | DATE |
| E. W. C126C-K | | 1 | 9/4 |
| C. S. W. C126C-K | | | |
| A19 W1002C-K | | | |
| HVC 249A HB-K | | | |
| C.M. | | JFC | 9/11 |
| WL | X | | 9/4 |
| RWC | 1 | | |

August 5, 1981

TVA Contract Nos.
and 71C62-54114-1

919:

TVA-8319
WAT-D-4525

File: 16.0

Mr. J. A. Raulston
Chief Nuclear Engineer
TENNESSEE VALLEY AUTHORITY
400 Commerce Avenue, W10 C126
Knoxville, Tennessee 37902

DL Hill X-4184

N.A.R.
LA 8/27/82

Dear Mr. Raulston:

TENNESSEE VALLEY AUTHORITY
SEQUOYAH AND WATTS BAR NUCLEAR PLANTS
UNIT NUMBERS 1 AND 2

W-2 Switch - Punch List Item 12-395-05

08 12 623

The purpose of this letter is to review and document the Westinghouse position on the W-2 switch used in safety related applications at Sequoyah and Watts Bar and many other Westinghouse designed nuclear facilities.

Following the reported intermittent behavior at the Zion station, W conducted a thorough investigation of similar W-2 switches in service at the time of failure at Zion, switches mounted at the Byron Units and switches in inventory at both stations.

The results of the testing proved that there was no common mode failure mechanism at work in the W-2 switches. The failures induced in the test samples were random in nature and were attributable to dirt, sulfide on contact surfaces and plastic debris from manufacture.

Westinghouse then recommended to our customers and the NRC that the lamp, previously recommended, be maintained in service with the subject contact to assure the operator that the contact is capable of carrying current.

In summary, Westinghouse has confirmed through the testing that the switch is adequate for the service intended, internal contaminants could produce switch malfunctions and there are no common mode failure mechanisms. Westinghouse has revised the switch manufacturing process to include additional cleaning steps to reduce internal contamination during assembly.

NEB '820803 992

ADVANCE COPY OF THIS
LETTER SENT TO SWP.

A-10

N2M/N3M-2-X

TVA has two options:

1) To wire in the monitoring lamp for assurance of contact continuity


-or-

2) To purchase switches manufactured to the new manufacturing process for additional margin.

If Westinghouse can be of any further assistance, please call.

Very truly yours,

WESTINGHOUSE ELECTRIC CORPORA



J. L. Tain, Manager
Tennessee Valley Author
Projects

/rcc

J. A. Raulston, 3L

cc: R. E. Lyman, 1L
S. A. Moser, 1L
B. Wade, 1L
L. M. Mills, 1L

APPENDIX B

Documentation of Bulletin Closeout

TABLE B.1 BULLETIN CLOSEOUT STATUS

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|------------------|---------|--------|-----------------|------------|-----------------------|----------------------------|-------------------------------|
| Arkansas 1 | AP&L | 50-313 | OL | IV | 09-09-80 | | Closed 2 |
| Arkansas 2 | AP&L | 50-368 | OL | IV | 09-09-80 | | Closed 2 |
| Bailly 1 | NIPSCO | 50-367 | CD | III | 08-11-80 | | Closed 1 |
| Beaver Valley 1 | DLC | 50-334 | OL | I | 08-18-80 | 80-25(12-05-80) | Closed 2 |
| Beaver Valley 2 | DLC | 50-412 | CP | I | 09-19-80 | 82-11(10-25-82) | Closed 2 |
| Bellefonte 1 | TVA | 50-438 | CP | II | 09-16-80 | 82-14(06-15-82) | Closed 3 |
| | | | | | 12-12-80 | | |
| | | | | | 04-02-81 | | |
| | | | | | 08-13-81 | | |
| | | | | | 11-09-81 | | |
| Bellefonte 2 | TVA | 50-439 | CP | II | 09-16-80 | 82-14(06-15-82) | Closed 3 |
| | | | | | 12-12-80 | | |
| | | | | | 04-02-81 | | |
| | | | | | 08-13-81 | | |
| | | | | | 11-09-81 | | |
| Big Rock Point 1 | CPC | 50-155 | OL | III | 08-15-80 | 80-10(09-25-80) | Closed 2 |
| Braidwood 1 | CECO | 50-456 | CP | III | 07-23-80 | 85020(04-30-85) | Closed 4 |
| | | | | | 09-15-80 | | |
| | | | | | 01-09-81 | | |
| | | | | | 04-10-81 | | |
| | | | | | 04-30-81 | | |
| | | | | | 08-29-84 | | |
| Braidwood 2 | CECO | 50-457 | CP | III | 07-23-80 | 85021(04-30-85) | Closed 4 |
| | | | | | 09-15-80 | | |
| | | | | | 01-09-81 | | |
| | | | | | 04-10-81 | | |
| | | | | | 04-30-81 | | |
| | | | | | 08-29-84 | | |
| Browns Ferry 1 | TVA | 50-259 | OL | II | 09-12-80 | 81-35(12-18-81) | Closed 2 |
| Browns Ferry 2 | TVA | 50-260 | OL | II | 09-12-80 | 81-35(12-18-81) | Closed 2 |
| Browns Ferry 3 | TVA | 50-296 | OL | II | 09-12-80 | 81-35(12-18-81) | Closed 2 |
| Brunswick 1 | CP&L | 50-325 | OL | II | 08-19-80 | | Closed 2 |
| Brunswick 2 | CP&L | 50-324 | OL | II | 08-19-80 | | Closed 2 |

See notes at end of table.

TABLE B.1 (contd.)

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|------------------|---------|--------|--------------------|---------------|--|-------------------------------|-------------------------------------|
| Byron 1 | CECO | 50-454 | OL | III | 07-23-80 09-15-80 01-09-81 04-10-81 04-30-81 08-29-84 | 84-69(10-10-84) | Closed 4 |
| Byron 2 | CECO | 50-455 | CP | III | 07-23-80 09-15-80 01-09-81 04-10-81 04-30-81 08-29-84 | 84-47(10-10-84) | Closed 4 |
| Callaway 1 | UE | 50-483 | OL | III | 09-09-80 | 81-17(08-13-81) | Closed 2 |
| Callaway 2 | UE | 50-486 | CD | III | 09-09-80 | | Closed 1 |
| Calvert Cliffs 1 | BG&E | 50-317 | OL | I | 08-21-80 | 80-26(02-11-81) | Closed 2 |
| Calvert Cliffs 2 | BG&E | 50-318 | OL | I | 08-21-80 | 80-22(02-11-81) | Closed 2 |
| Catawba 1 | DUPCO | 50-413 | OL | II | 08-20-80 | | Closed 2 |
| Catawba 2 | DUPCO | 50-414 | CP | II | 08-20-80 | | Closed 2 |
| Cherokee 1 | DUPCO | 50-491 | CD | II | 08-14-80 | | Closed 1 |
| Cherokee 2 | DUPCO | 50-492 | CD | II | 08-14-80 | | Closed 1 |
| Cherokee 3 | DUPCO | 50-493 | CD | II | 08-14-80 | | Closed 1 |
| Clinton 1 | IP | 50-461 | CP | III | 09-16-80 | 81-11(06-19-81) | Closed 2 |
| Clinton 2 | IP | 50-462 | CHI | III | 09-16-80 | | Closed 1 |
| Comanche Peak 1 | TUGCO | 50-445 | CP | IV | 08-29-80 11-19-80 05-07-81 08-04-81 10-07-81 12-09-81 | 84-22(10-02-84) | Closed 4 |

See notes at end of table.

TABLE B.1 (contd.)

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|-----------------|---------|--------|-----------------|------------|--|----------------------------|-------------------------------|
| Comanche Peak 2 | TUGCO | 50-446 | CP | IV | 08-29-80 11-19-80 05-07-81 08-04-81 10-07-81 12-09-81 | 84-07(10-02-84) | Closed 4 |
| Cook 1 | IMECO | 50-315 | OL | III | 09-08-80 | 80-13(10-22-80) | Closed 2 |
| Cook 2 | IMECO | 50-316 | OL | III | 09-08-80 | 80-11(10-22-80) | Closed 2 |
| Cooper Station | NPPD | 50-298 | OL | IV | 08-06-80 | 80-12(08-29-80) | Closed 2 |
| Crystal River 3 | FP | 50-302 | OL | II | 08-05-80 | | Closed 2 |
| Davis-Besse 1 | TECO | 50-346 | OL | III | 09-12-80 | 80-25(10-14-80) | Closed 2 |
| Diablo Canyon 1 | PG&E | 50-275 | OL | V | 09-22-80 | 81-06(04-03-81) | Closed 2 |
| Diablo Canyon 2 | PG&E | 50-323 | OL | V | 09-22-80 | 81-06(04-03-81) | Closed 2 |
| Dresden 1 | CECO | 50-010 | SDI | III | 09-15-80 | | Closed 1 |
| Dresden 2 | CECO | 50-237 | OL | III | 09-15-80 | 84-03(04-10-84) | Closed 2 |
| Dresden 3 | CECO | 50-249 | OL | III | 09-15-80 | 84-02(04-10-84) | Closed 2 |
| Duane Arnold | IELPCO | 50-331 | OL | III | 08-29-80 | | Closed 2 |
| Farley 1 | APCO | 50-348 | OL | II | 09-16-80 09-24-80 12-18-81 | 83-31(01-10-84) | Closed 4 |
| Farley 2 | APCO | 50-364 | OL | II | 09-16-80 09-24-80 10-28-80 12-18-81 | 83-29(01-10-84) | Closed 4 |
| Fermi 2 | DECO | 50-341 | OL | III | 09-15-80 | | Closed 2 |
| FitzPatrick | PASNY | 50-333 | OL | I | 08-12-80 | 81-06(03-23-81) | Closed 2 |
| Forked River | JCP&L | 50-363 | CD | I | | | Closed 1 |
| Fort Calhoun 1 | OPPD | 50-285 | OL | IV | 08-08-80 | 81-14(07-23-81) | Closed 2 |
| Fort St. Vrain | PSCC | 50-267 | OL | IV | 09-18-80 | | Closed 2 |
| Ginna | RG&E | 50-244 | OL | I | 09-10-80 11-17-80 | 81-11(07-31-81) | Closed 4 |
| Grand Gulf 1 | MP&L | 50-416 | OL | II | 09-17-80 10-15-80 | | Closed 2 |

See notes at end of table.

TABLE B.1 (contd.)

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|----------------|---------|--------|-----------------|------------|--|----------------------------|-------------------------------|
| Grand Gulf 2 | MP&L | 50-417 | CHI | II | 09-17-80 10-15-80 | | Closed 1 |
| Haddam Neck | CYAPCO | 50-213 | OL | I | 09-15-80 | 85-13(09-05-85) | Closed 4 |
| Harris 1 | CP&L | 50-400 | CP | II | 09-12-80 | | Closed 2 |
| Harris 2 | CP&L | 50-401 | CHI | II | 09-12-80 | | Closed 1 |
| Harris 3 | CP&L | 50-402 | CHI | II | 09-12-80 | | Closed 1 |
| Harris 4 | CP&L | 50-403 | CHI | II | 09-12-80 | | Closed 1 |
| Hartsville A-1 | TVA | 50-518 | CD | II | 09-12-80 | | Closed 1 |
| Hartsville A-2 | TVA | 50-519 | CD | II | 02-10-81 | | Closed 1 |
| Hartsville B-1 | TVA | 50-520 | CD | II | 06-15-81 | | Closed 1 |
| Hartsville B-2 | TVA | 50-521 | CD | II | 08-14-81 10-30-81 02-19-82 | | Closed 1 |
| Hatch 1 | GPC | 50-321 | OL | II | 09-12-80 | | Closed 2 |
| Hatch 2 | GPC | 50-366 | OL | II | 09-12-80 | | Closed 2 |
| Hope Creek 1 | PSE&G | 50-354 | CP | I | 09-03-80 11-14-80 12-23-80 11-04-83 | | Closed 2 |
| Hope Creek 2 | PSE&G | 50-355 | CHI | I | 09-03-80 11-14-80 12-23-80 11-04-83 | | Closed 1 |
| Humboldt Bay 3 | PG&E | 50-133 | SDI | V | 09-08-80 | | Closed 1 |
| Indian Point 1 | ConEd | 50-003 | SDI | I | 09-15-80 | | Closed 1 |
| Indian Point 2 | ConEd | 50-247 | OL | I | 09-15-80 03-03-81 | 85-07(04-22-85) | Closed 4 |
| Indian Point 3 | PASNY | 50-286 | OL | I | 09-12-80 02-10-81 03-03-81 06-24-82 | | Closed 4 |
| Jamesport 1 | LILCO | 50-516 | CD | I | 09-16-80 | | Closed 1 |
| Jamesport 2 | LILCO | 50-517 | CD | I | 09-16-80 | | Closed 1 |

See notes at end of table.

TABLE B.1 (contd.)

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|-------------------|---------|--------|--------------------|---------------|-----------------------------|-------------------------------|-------------------------------------|
| Kewaunee | WPS | 50-305 | OL | III | 09-19-80 | 80-28(01-15-81) | Closed 4 |
| La Crosse | DPC | 50-409 | OL | III | 08-08-80 | | Closed 2 |
| LaSalle 1 | CECO | 50-373 | OL | III | 09-15-80 | | Closed 2 |
| LaSalle 2 | CECO | 50-374 | OL | III | 09-15-80 | 83-08(04-06-83) | Closed 2 |
| Limerick 1 | PECO | 50-352 | OL | I | 09-10-80 | 84-01(02-17-84) | Closed 2 |
| Limerick 2 | PECO | 50-353 | CP | I | 09-10-80 | 84-02(02-17-84) | Closed 2 |
| Maine Yankee | MYAPCO | 50-309 | OL | I | 09-04-80 | | Closed 2 |
| Marble Hill 1 | PSI | 50-546 | CHI | III | 09-15-80 | | Closed 1 |
| Marble Hill 2 | PSI | 50-547 | CHI | III | 09-15-80 | | Closed 1 |
| McGuire 1 | DUPCO | 50-369 | OL | II | 08-20-80 | 80-33(12-11-80) | Closed 2 |
| McGuire 2 | DUPCO | 50-370 | OL | II | 08-20-80 | 80-18(12-11-80) | Closed 2 |
| Midland 1 | CPC | 50-329 | CHI | III | 09-22-80 | | Closed 1 |
| Midland 2 | CPC | 50-330 | CHI | III | 09-22-80 | | Closed 1 |
| Millstone 1 | NNECO | 50-245 | OL | I | 09-15-80 | | Closed 2 |
| Millstone 2 | NNECO | 50-336 | OL | I | 09-15-80 | | Closed 2 |
| Millstone 3 | NNECO | 50-423 | CP | I | 09-15-80 | 82-02(03-11-82) | Closed 2 |
| Monticello | NSP | 50-263 | OL | III | 09-12-80 | 80-20(01-16-81) | Closed 2 |
| Nine Mile Point 1 | NMP | 50-220 | OL | I | 09-11-80 | | Closed 2 |
| Nine Mile Point 2 | NMP | 50-410 | CP | I | 09-11-80 | | Closed 2 |
| | | | | | 10-30-80 | | |
| North Anna 1 | VEPCO | 50-338 | OL | II | 09-15-80 | 82-40(02-07-83) | Closed 3 |
| North Anna 2 | VEPCO | 50-339 | OL | II | 09-15-80 | 82-40(02-07-83) | Closed 3 |
| North Anna 3 | VEPCO | 50-404 | CD | II | 08-27-80 | | Closed 1 |
| | | | | | 09-01-82 | | |
| North Anna 4 | VEPCO | 50-405 | CD | II | 08-27-80 | | Closed 1 |
| | | | | | 09-01-82 | | |
| Oconee 1 | DUPCO | 50-269 | OL | II | 08-14-80 | 80-32(11-03-80) | Closed 2 |
| Oconee 2 | DUPCO | 50-270 | OL | II | 08-14-80 | 80-28(11-03-80) | Closed 2 |
| Oconee 3 | DUPCO | 50-287 | OL | II | 08-14-80 | 80-25(11-03-80) | Closed 2 |
| Oyster Creek 1 | JCP&L | 50-219 | OL | I | 08-28-80 | | Closed 2 |
| Palisades | CPC | 50-255 | OL | III | 08-12-80 | 80-21(11-21-80) | Closed 2 |

See notes at end of table.

TABLE B.1 (contd.)

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|------------------|---------|--------|--------------------|---------------|-----------------------------|-------------------------------|-------------------------------------|
| Palo Verde 1 | APSCO | 50-528 | OL | V | 09-15-80 | 83-08(03-30-83) | Closed 2 |
| Palo Verde 2 | APSCO | 50-529 | CP | V | 09-15-80 | 83-04(03-30-83) | Closed 2 |
| Palo Verde 3 | APSCO | 50-530 | CP | V | 09-15-80 | 83-03(03-30-83) | Closed 2 |
| Peach Bottom 2 | PECO | 50-277 | OL | I | 09-10-80 | 84-26(09-21-84) | Closed 3 |
| Peach Bottom 3 | PECO | 50-278 | OL | I | 09-10-80 | 84-22(09-21-84) | Closed 3 |
| Perkins 1 | DUPCO | 50-488 | CD | II | 08-14-80 | | Closed 1 |
| Perkins 2 | DUPCO | 50-489 | CD | II | 08-14-80 | | Closed 1 |
| Perkins 3 | DUPCO | 50-490 | CD | II | 08-14-80 | | Closed 1 |
| Perry 1 | CEI | 50-440 | CP | III | 09-04-80 | | Closed 2 |
| Perry 2 | CEI | 50-441 | CP | III | 09-04-80 | | Closed 2 |
| Phipps Bend 1 | TVA | 50-553 | CD | II | 09-12-80 | | Closed 1 |
| Phipps Bend 2 | TVA | 50-554 | CD | II | 02-10-81 | | Closed 1 |
| | | | | | 06-15-81 | | |
| | | | | | 08-14-81 | | |
| | | | | | 10-30-81 | | |
| | | | | | 02-19-82 | | |
| Pilgrim 1 | BECO | 50-293 | OL | I | 08-08-80 | | Closed 2 |
| Point Beach 1 | WEPCO | 50-266 | OL | III | 09-16-80 | 80-20(12-17-80) | Closed 4 |
| Point Beach 2 | WEPCO | 50-301 | OL | III | 09-16-80 | 80-20(12-17-80) | Closed 4 |
| Prairie Island 1 | NSP | 50-282 | OL | III | 09-12-80 | 82-05(04-19-82) | Closed 4 |
| | | | | | 12-11-80 | | |
| Prairie Island 2 | NSP | 50-306 | OL | III | 09-12-80 | 82-05(04-19-82) | Closed 4 |
| | | | | | 12-11-80 | | |
| Quad Cities 1 | CECO | 50-254 | OL | III | 09-15-80 | | Closed 2 |
| Quad Cities 2 | CECO | 50-265 | OL | III | 09-15-80 | | Closed 2 |
| Rancho Seco 1 | SMUD | 50-312 | OL | V | 09-15-80 | 80-27(10-22-80) | Closed 3 |
| River Bend 1 | GSU | 50-458 | LPTL | IV | 09-19-80 | | Closed 2 |
| River Bend 2 | GSU | 50-459 | CD | IV | 09-19-80 | | Closed 1 |
| Robinson 2 | CP&L | 50-261 | OL | II | 08-21-80 | 80-29(11-10-80) | Closed 2 |
| | | | | | 09-30-80 | | |
| Salem 1 | PSE&G | 50-272 | OL | I | 09-05-80 | 80-23(12-03-80) | Closed 3 |
| | | | | | 10-14-80 | | |
| Salem 2 | PSE&G | 50-311 | OL | I | 09-05-80 | 80-18(12-03-80) | Closed 3 |
| | | | | | 10-14-80 | | |

See notes at end of table.

TABLE B.1 (contd.)

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|---------------|---------|--------|-----------------|------------|--|----------------------------|-------------------------------|
| San Onofre 1 | SCE | 50-206 | OL | V | 09-05-80 11-18-81 | 81-41(12-30-81) | Closed 4 |
| San Onofre 2 | SCE | 50-361 | OL | V | 09-11-80 | 81-07(05-22-81) | Closed 2 |
| San Onofre 3 | SCE | 50-362 | OL | V | 09-11-80 | 81-02(05-22-81) | Closed 2 |
| Seabrook 1 | PSNH | 50-443 | CP | I | 08-22-80 | 82-04(07-07-82) | Closed 2 |
| Seabrook 2 | PSNH | 50-444 | CP | I | 08-22-80 | 82-04(07-07-82) | Closed 2 |
| Sequoyah 1 | TVA | 50-327 | OL | II | 09-16-80 12-12-80 04-02-81 08-13-81 11-09-81 01-20-83 | 81-09(03-19-81) | Open |
| Sequoyah 2 | TVA | 50-328 | OL | II | 09-16-80 12-12-80 04-02-81 08-13-81 11-09-81 01-20-83 | 81-08(03-19-81) | Open |
| Shoreham | LILCO | 50-322 | LPTL | I | 10-10-80 | 81-22(01-14-82) | Closed 2 |
| South Texas 1 | HL&P | 50-498 | CP | IV | 09-09-80 | 81-32(11-12-81) | Closed 2 |
| South Texas 2 | HL&P | 50-499 | CP | IV | 09-09-80 | 81-32(11-12-81) | Closed 2 |
| St. Lucie 1 | FPL | 50-335 | OL | II | 09-12-80 | 80-36(01-29-81) | Closed 3 |
| St. Lucie 2 | FPL | 50-389 | OL | II | 09-15-80 11-13-80 | 80-16(12-15-80) | Closed 3 |
| Sterling | RG&E | 50-485 | CD | I | | | Closed 1 |
| Summer 1 | SCE&G | 50-395 | OL | II | 09-11-80 | 81-04(03-09-81) | Closed 2 |
| Surry 1 | VEPCO | 50-280 | OL | II | 09-15-80 | 84-09(03-23-84) | Closed 2 |
| Surry 2 | VEPCO | 50-281 | OL | II | 09-15-80 | 84-09(03-23-84) | Closed 2 |
| Susquehanna 1 | PP&L | 50-387 | OL | I | 09-23-80 11-03-80 | 82-08(04-08-82) | Closed 3 |
| Susquehanna 2 | PP&L | 50-388 | OL | I | 09-23-80 11-03-80 | 82-04(05-19-82) | Closed 3 |
| TMI 1 | Met-Ed | 50-289 | OL | I | 09-02-80 | 80-29(05-12-81) | Closed 2 |
| TMI 2 | Met-Ed | 50-320 | SDI | I | 09-30-80 | | Closed 1 |

See notes at end of table.

TABLE B.1 (contd.)

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|------------------|---------|--------|--------------------|---------------|--|-------------------------------|-------------------------------------|
| Trojan | PGE | 50-344 | OL | V | 09-15-80 | 80-25(11-03-80) | Closed 2 |
| Turkey Point 3 | FPL | 50-250 | OL | II | 09-16-80 03-31-81 | 84-14(06-15-84) | Closed 4 |
| Turkey Point 4 | FPL | 50-251 | OL | II | 09-16-80 03-31-81 | 84-14(06-15-84) | Closed 4 |
| Vermont Yankee 1 | VYNP | 50-271 | OL | I | 08-22-80 | | Closed 2 |
| Vogtle 1 | GPC | 50-424 | CP | II | 09-16-80 | 81-15(01-28-82) | Closed 2 |
| Vogtle 2 | GPC | 50-425 | CP | II | 09-16-80 | 81-15(01-28-82) | Closed 2 |
| WNP 1 | WPPSS | 50-460 | CP | V | 09-08-80 | 80-13(11-21-80) | Closed 2 |
| WNP 2 | WPPSS | 50-397 | OL | V | 09-15-80 | 81-02(02-19-81) | Closed 2 |
| WNP 3 | WPPSS | 50-508 | CP | V | 10-01-80 | 82-03(02-26-82) | Closed 3 |
| WNP 4 | WPPSS | 50-513 | CHI | V | 09-08-80 | | Closed 1 |
| WNP 5 | WPPSS | 50-509 | CHI | V | 10-01-80 | | Closed 1 |
| Waterford 3 | LP&L | 50-382 | OL | IV | 09-09-80 10-15-80 | | Closed 2 |
| Watts Bar 1 | TVA | 50-390 | CP | II | 09-16-80 12-12-80 04-02-81 08-13-81 11-09-81 06-02-82 03-30-83 11-19-85 | 83-46(11-22-83) | Closed 4 |
| Watts Bar 2 | TVA | 50-391 | CP | II | 09-16-80 12-12-80 04-02-81 08-13-81 11-09-81 06-02-82 03-30-83 11-19-85 | 83-35(11-22-83) | Closed 4 |
| Wolf Creek 1 | KG&E | 50-482 | OL | IV | 09-09-80 | 84-01(02-14-84) | Closed 2 |

See notes at end of table.

TABLE B.1 (contd.)

| Facility | Utility | Docket | Facility Status | NRC Region | Utility Response Date | Inspection Report and Date | Closeout Status and Criterion |
|----------------|---------|--------|-----------------|------------|-----------------------|----------------------------|-------------------------------|
| Yankee-Rowe 1 | YAECO | 50-029 | OL | I | 08-29-80 | 80-20(01-28-81) | Closed 2 |
| Yellow Creek 1 | TVA | 50-566 | CHI | II | 09-16-80 | | Closed 1 |
| Yellow Creek 2 | TVA | 50-567 | CHI | II | 12-12-80 | | Closed 1 |
| | | | | | 04-02-81 | | |
| | | | | | 08-13-81 | | |
| | | | | | 11-09-81 | | |
| Zimmer 1 | CG&E | 50-358 | CD | III | 09-02-80 | | Closed 1 |
| Zion 1 | CECO | 50-295 | OL | III | 09-15-80 | 80-20(11-28-80) | Closed 4 |
| Zion 2 | CECO | 50-304 | OL | III | 09-15-80 | 80-21(11-28-80) | Closed 4 |

Notes:

1. Facility Status is based on References 1, 2, and 3, Page B-10.
2. The following abbreviations apply to facility status:

CD, Cancelled; CHI, Construction Halted Indefinitely; CP, Construction Permit; LPTL, Low Power Testing License; OL, Operating License; SDI, Shut Down Indefinitely.

3. Refer to Page 4 for Bulletin Closeout Criteria.

REFERENCES

1. United States Nuclear Regulatory Commission, Licensed Operating Reactors, Status Summary Report, Data as of 09-30-85, NUREG-0020, Volume 9, Number 10, October 1985.
2. United States Nuclear Regulatory Commission, Nuclear Power Plants, Construction Status Report, Data as of 06-30-82, NUREG-0030, Volume 6, Number 2, October 1982.
3. United States Nuclear Regulatory Commission, Listing of Inactive Current Holders of Construction Permits, Letter dated May 29, 1985, to Richard A. Lofy (Parameter, Inc.) from Robert L. Baer (NRC/IE HQ).
4. United States Nuclear Regulatory Commission, Code of Federal Regulations, Energy, Title 10, Chapter 1, January 1, 1985, cited as 10CFR 0.735-1.

APPENDIX C

Proposed Followup Item

Region II

Sequoyah 1,2

IE inspection report 81-09/81-08 of 03-19-81 holds the bulletin open. Open status was confirmed by NRC/IE in letter to Parameter, Inc. (R.S. Dean) from R.L. Baer (IE) of February 12, 1986. Closeout is to be included in a future inspection report.

APPENDIX D

TABLE D.1 IDENTIFICATION OF AFFECTED SYSTEMS, NUMBER OF TYPE W-2 SWITCHES AND NUMBER OF FAILURES

| Facility | Affected Systems | Number of Switches: | |
|---------------|--------------------------------|------------------------|--------|
| | | Used | Failed |
| Braidwood 1,2 | Primary Containment HVAC | 16 | |
| | Auxiliary Feedwater | 4 | |
| | Essential Service Water | 4 | |
| | Component Cooling | 8 | |
| | Containment Spray | 4 | |
| | Safety Injection | 4 | |
| | Residual Heat Removal | 4 | |
| | Boron Thermal Regeneration | 2 | |
| | Chemical and Volume Control | 6 | |
| | Boric Acid Processing | 2 | |
| | Reactor Coolant | 24 | |
| | Main Steam | 4 | |
| | Diesel Generator Room | | |
| | Ventilation | 4 | |
| | Switchgear Room Ventilation | 12 | |
| | Containment Purge | 4 | |
| | Auxiliary Power | 24 | |
| | Diesel Generator | 12 | |
| | Auxiliary Building Ventilation | 16* | |
| | Control Room Ventilation | 6* | |
| | Chilled Water | 4* | |
| | Essential Service Water | 18* | |
| | Total | 182 | |
| Byron 1,2 | Primary Containment HVAC | 16 | |
| | Auxiliary Feedwater | 4 | |
| | Essential Service Water | 4 | |
| | Component Cooling | 8 | |
| | Containment Spray | 4 | |
| | Safety Injection | 4 | |
| | Residual Heat Removal | 4 | |
| | Boron Thermal Regeneration | 2 | |
| | Chemical and Volume Control | 6 | |
| | Boric Acid Processing | 2 | |
| | Reactor Coolant | 24 | |

See notes at end of table.

TABLE D.1 (contd)

| Facility | Affected Systems | Number of Switches: | |
|----------------------|---|------------------------|--------|
| | | Used | Failed |
| Byron 1,2 (contd) | Main Steam | 4 | |
| | Diesel Generator Room | | |
| | Ventilation | 4 | |
| | Switchgear Room Ventilation | 12 | |
| | Containment Purge | 4 | |
| | Auxiliary Power | 24 | |
| | Diesel Generator | 12 | |
| | Auxiliary Building Ventilation | 16* | |
| | Control Room Ventilation | 6* | |
| | Chilled Water | 4* | |
| | Essential Service Water | 18* | |
| | Total | 182 | |
| Comanche Peak 1,2 | Electrical System (alternate offsite and onsite 6.9KV breakers) | 8 | |
| | Service Water | 4 | |
| | Safety Injection | 8 | |
| | Containment Spray | 12 | |
| | Containment Vent | 2* | |
| | Component Cooling Water | 4 | |
| | Safety Chiller Water | 4 | |
| | Residual Heat Removal | 4 | |
| | Chemical and Volume Control | 4 | |
| | Main Steam Reheat | 8 | |
| | Main Feedwater | 24 | |
| | Auxiliary Feedwater | 4 | |
| | Safeguard and Electrical Area Vent | 48 | |
| | Auxiliary Building and Fuel Building Vent | 8 | |
| | Uncontrolled and Miscellaneous Areas Vent | 8 | |
| | Primary Plant Vent | 2* | |
| | Control Room and Facilities Vent | 20* | |
| | Total | 172 | |
| Farley 1,2 | Electrical | 14 | |
| | Reactor Trip | 4 | |
| | Total | 18 | |

See notes at end of table.

TABLE D.1 (contd)

| Facility | Affected Systems | Number of Switches: | |
|----------------|---|------------------------|--------|
| | | Used | Failed |
| Ginna | Safety Injection | 4 | |
| | Containment Spray | 2 | |
| | Component Cooling Water | 2 | |
| | Auxiliary Feedwater | 2 | |
| | Residual Heat Removal | 2 | |
| | Service Water | 4 | |
| | Containment Vent | 4 | |
| | Diesel Generator Supply | 4 | |
| | Total | 24 | |
| Haddam Neck | Containment Air Recirculation | 4 | |
| | Service Water | 4 | |
| | High Pressure Safety Injection | 2 | |
| | Low Pressure Safety Injection | 2 | |
| | Charging Pumps | 2 | |
| | Emergency Diesel Generators | 2 | |
| | Primary Water Transfer | 2 | |
| | Total | 18 | |
| Indian Point 2 | Service Water | 8 | |
| | Component Cooling | 3 | |
| | Residual Heat Removal | 2 | |
| | Emergency Power Systems (includes MCC's) | 10 | |
| | Containment Recirculation | 5 | |
| | Safety Injection | 4 | |
| | Containment Spray | 2 | |
| | Auxiliary Feedwater | 2 | |
| | Recirculation Pumps | 2 | |
| | Total | 38 | 0 |
| Indian Point 3 | Safety Injection | 5 | |
| | Auxiliary Coolant | 5 | |
| | Containment Spray | 2 | |
| | Containment Ventilation | 5 | |
| | Service Water | 6 | |
| | Feedwater | 2 | |
| | Electrical Distribution | 13 | |
| | Total | 38 | 0 |

See notes at end of table.

TABLE D.1 (contd)

| Facility | Affected Systems | Number of Switches: | |
|--------------------|---|------------------------|--------|
| | | Used | Failed |
| Kewaunee | 4150V Supply & Distribution | | |
| | Diesel Generators | | |
| | Component Cooling | | |
| | Containment Spray | | |
| | Residual Heat Removal | | |
| | Safety Injection | | |
| | Service Water | | |
| | Reactor Building Vent | | |
| | Feedwater & Auxiliary Feedwater | | |
| | Total | 27 | 0 |
| Point Beach 1,2 | Residual Heat Removal | 4 | |
| | Containment Spray | 4 | |
| | Containment Cooling Fans | 8 | |
| | Service Water | 6 | |
| | Auxiliary Feedwater | 2 | |
| | Safety Injection | 4 | |
| | Component Cooling | 4 | |
| | Supply Breaker | 4 | |
| | Tie Breaker | 2 | |
| | Total | 38 | 0 |
| Prairie Island 1,2 | (Not identified) | 42 | 0 |
| San Onofre 1 | Safety Injection | 3 | 0 |
| Sequoyah 1,2 | Main Steam including Generator Blowdown | | |
| | Main and Auxiliary Feedwater | | |
| | High-pressure Fire Protection | | |
| | Diesel-generator, Turbine, Auxiliary | | |
| | Control and Reactor Buildings Ventilation | | |
| | Control Building, Heating and Air | | |
| | Conditioning | | |
| | Auxiliary Building, Additional Equipment | | |
| | Building, and Fuel Handling, Heat and Air | | |
| | Conditioning | | |
| | Associated Electrical Systems | | |
| | Chemical and Volume Control | | |
| | Safety Injection | | |
| | Emergency Gas Treatment | | |
| | Essential Raw Cooling Water | | |
| | Reactor Coolant | | |
| | Component Cooling | | |
| | Containment Spray System | | |
| | Residual Heat Removal | | |
| | Total | 130 | 0 |

See notes at end of table.

TABLE D.1 (contd)

| Facility | Affected Systems | Number of Switches: | |
|------------------|------------------------------------|------------------------|--------|
| | | Used | Failed |
| Turkey Point 3,4 | Component Cooling Water | 6 | |
| | Safety Injection | 8 | |
| | Residual Heat Removal | 4 | |
| | Containment Spray | 4 | |
| | Intake Cooling Water | 6 | |
| | Startup Transformer Breaker | 4 | |
| | Load Center Feeder Breaker | 8 | |
| | Emergency Startup Transfer Breaker | 2 | |
| | Total | 42 | 0 |
| Watts Bar 1,2 | Volume Control | | |
| | Safety Injection | | |
| | Emergency Gas Treatment | | |
| | Residual Heat Removal | | |
| | Containment Spray | | |
| | Auxiliary Feedwater | | |
| | Essential Raw Cooling Water | | |
| | Ventilation | | |
| | Air Conditioning | | |
| | Reactor Coolant | | |
| | Total | 67 | |
| Zion 1,2 | Auxiliary Power | | |
| | Component Cooling | | |
| | Containment Spray | | |
| | Auxiliary Feedwater | | |
| | Residual Heat Removal | | |
| | Reactor Ventilation | | |
| | Safety Injection | | |
| | Service Water | | |
| | Volume Control | | |
| | Total | 47 | 0 |

Notes:

1. An affected system is a safety-related system containing a subject Type W-2 switch.
2. The information given in this table is required per Action Item 1 and the second last paragraph of IEB 80-20.
3. Blanks indicate information not given.
4. For twin units, numbers are totals for both units.

5. Switches common to twin units are identified with asterisks (*).
6. No failures were reported as a result of the testing required by the bulletin.

APPENDIX E

Abbreviations

| | |
|--------|---|
| AEPCO | American Electric Power Services Corporation |
| AFW | Auxiliary Feedwater |
| APCO | Alabama Power Company |
| AP&L | Arkansas Power and Light Company |
| APSCO | Arizona Public Service Company |
| BECO | Boston Edison Company |
| BG&E | Baltimore Gas and Electric Company |
| CD | Cancelled |
| CECO | Commonwealth Edison Company |
| CEI | Cleveland Electric Illuminating Company |
| CFR | Code of Federal Regulations |
| CG&E | Cincinnati Gas and Electric Company |
| CHI | Construction Halted Indefinitely |
| ConEd | Consolidated Edison Company of New York, Inc. |
| CP | Construction Permit |
| CPC | Consumers Power Company |
| CP&L | Carolina Power and Light Company |
| CR | Contractor Report |
| CYAPCO | Connecticut Yankee Atomic Power Company |
| DECO | Detroit Edison Company |
| DLC | Duquesne Light Company |
| DPC | Dairyland Power Cooperative |
| DUPCO | Duke Power Company |
| FP | Florida Power Corporation |
| FPL | Florida Power & Light Company |
| GAO | Government Accounting Office |
| GPC | Georgia Power Company |
| GSU | Gulf States Utilities Company |
| HL&P | Houston Lighting and Power Company |
| IE | (See NRC/IE) |
| IEB | Inspection and Enforcement Bulletin (NRC) |
| IELPCO | Iowa Electric Light and Power Company |
| IMECO | Indiana and Michigan Electric Company |
| IP | Illinois Power Company |
| IR | Inspection Report (NRC/IE) |
| JCP&L | Jersey Central Power and Light Company |
| KG&E | Kansas Gas and Electric Company |
| LER | Licensee Event Report |

| | |
|----------|--|
| LILCO | Long Island Lighting Company |
| LP&L | Louisiana Power and Light Company |
| LPTL | Low Power Testing License |
| Met-Ed | Metropolitan Edison Company |
| MP&L | Mississippi Power and Light Company |
| MYAPCO | Maine Yankee Atomic Power Company |
| NIPSCO | Northern Indiana Public Service Company |
| NMP | Niagara Mohawk Power Company |
| NNECO | Northeast Nuclear Energy Company |
| NPPD | Nebraska Public Power District |
| NRC/IE | Nuclear Regulatory Commission/ Office of Inspection & Enforcement |
| NRR | Office of Nuclear Reactor Regulation, NRC |
| NSP | Northern States Power Company |
| NU | Northeast Utilities |
| OL | Operating License |
| OPPD | Omaha Public Power District |
| PASNY | Power Authority of the State of New York |
| PECO | Philadelphia Electric Company |
| PGE | Portland General Electric Company |
| PG&E | Pacific Gas and Electric Company |
| PP&L | Pennsylvania Power and Light Company |
| PSCC | Public Service Company of Colorado |
| PSE&G | Public Service Electric and Gas Company |
| PSI | Public Service Indiana |
| PSNH | Public Service Company of New Hampshire |
| R | Region (NRC) |
| RG&E | Rochester Gas and Electric Corporation |
| SCE | Southern California Edison Company |
| SCE&G | South Carolina Electric and Gas Company |
| SDI | Shut Down Indefinitely |
| SMUD | Sacramento Municipal Utility District |
| SNUPPS | Standardized Nuclear Unit Power Plant Systems |
| TECO | Toledo Edison Company |
| TMI | Three Mile Island |
| TUGCO | Texas Utilities Generating Company |
| TVA | Tennessee Valley Authority |
| UE | Union Electric Company |
| VEPCO | Virginia Electric and Power Company |
| VYNP | Vermont Yankee Nuclear Power Corporation |
| <u>W</u> | Westinghouse Electric Corporation |
| WEPCO | Wisconsin Electric Power Company |
| WNP | Washington Nuclear Project |
| WNSD | Westinghouse Nuclear Service Division |
| WPPSS | Washington Public Power Supply System |
| WPS | Wisconsin Public Service Corporation |
| YAECO | Yankee Atomic Electric Company |

| | | | | | |
|--|--|---|---|---|--|
| NRC FORM 335 (2-84) NRCM 1102, 3201, 3202 SEE INSTRUCTIONS ON THE REVERSE | | U.S. NUCLEAR REGULATORY COMMISSION BIBLIOGRAPHIC DATA SHEET | | 1. REPORT NUMBER (Assigned by TIDC add Vol. No., if any) NUREG/CR-3962 PARAMETER IE-150 | |
| 2. TITLE AND SUBTITLE Closeout of IE Bulletin 80-20: Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches | | | 3. LEAVE BLANK | | |
| 5. AUTHOR(S) R. S. Dean, W. J. Foley, A. Hennick | | | 4. DATE REPORT COMPLETED MONTH: April YEAR: 1986 | | |
| 7. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) PARAMETER, Inc. 13380 Watertown Plank Road Elm Grove, Wisconsin 53122 | | | 6. DATE REPORT ISSUED MONTH: June YEAR: 1986 | | |
| 10. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code) Division of Emergency Preparedness and Engineering Response Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555 | | | 8. PROJECT/TASK WORK UNIT NUMBER Task Order No. 003 | | |
| | | | 9. FIN OR GRANT NUMBER B8729 | | |
| | | | 11a. TYPE OF REPORT Technical | | |
| | | | b. PERIOD COVERED (Inclusive dates) 8/1/85 - 4/28/86 | | |
| 12. SUPPLEMENTARY NOTES | | | | | |
| 13. ABSTRACT (200 words or less) On June 18, 1980, Commonwealth Edison Company submitted Licensee Event Report (LER) 50-295/80-24 to the NRC, describing a malfunction of a Westinghouse Type W-2 control switch important to safety at Zion Unit 1. On the same date, Westinghouse submitted a preliminary issue of Technical Bulletin NSD-TB-80-9 to the NRC on the subject switches. On July 31, 1980, IE Bulletin 80-20 was issued to all power plant licensees and permit holders, requiring them to take specific actions and report results. Evaluation of utility responses and NRC/IE inspection reports shows that the bulletin can be closed out per specific criteria for 122 (98%) of the 124 current facilities to which it was issued. A followup item for the remaining two facilities is proposed for use by NRC/IE, to ensure satisfactory completion of corrective action. | | | | | |
| 14. DOCUMENT ANALYSIS - a. KEYWORDS/DESCRIPTORS Closeout of IE Bulletin 80-20 | | | | 15. AVAILABILITY STATEMENT Unlimited | |
| b. IDENTIFIERS/OPEN ENDED TERMS | | | | 16. SECURITY CLASSIFICATION (This page) Unclassified (This report) Unclassified | |
| | | | | 17. NUMBER OF PAGES | |
| | | | | 18. PRICE | |