



Framingham Union Hospital

115 Lincoln St., Framingham, Massachusetts 01701 • (617) 879-7111

A Community Teaching Hospital Affiliated with Boston University Medical Center

June 13, 1986

Nuclear Regulatory Commission
Region I
Nuclear Materials Section
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Sir:

Please find enclosed the results of the pre-operational tests performed on the Picker C-9 cobalt teletherapy equipment located at 475 Franklin Street, Framingham, MA 01701 and licensed to the Framingham Union Hospital, 115 Lincoln Street Framingham, MA.

If there is need for any additional material or any questions please call me at (617) 481-1121. Thank you.

Sincerely

Harold Jennison
Director of Planning

HJ:bab

U.S. MAIL
FEE EXEMPT BRANCH

'86 JUN 25 AM 9:35

RECEIVED

FEE EXEMPT

J. J. Survey

"OFFICIAL RECORD COPY"

1986 JUN 18 PM 3:29

ML10

RECEIVED-REGION 1

105681

JUN 18 1986

RECEIVED BY LFMS	
Date	6/25/86
Lcg	Jun 18 I
By	J. Kimbrey
Date Completed	6/25/86

8612030593 860905
REG1 LIC30
20-10621-02 PDR

June 9, 1986

Mr. Harold Jennison
Coordinator of Planning
Framingham Union Hospital
119 Lincoln St.
Framingham, MA 01701

Reference: NRC Lic. # 20-10621-02

Subject: Tests and Measurements: Installation
of new Co-60 source.


Enclosed are the results of the pre-operational tests and radiation survey performed on the Picker C-9 cobalt teletherapy facility located in 475 Franklin St., Framingham, MA.

The tests were started on May 16, 1986 immediately following the installation of the new source by AMS (Advanced Medical Systems, Inc.). Two copies of this report must be sent to the NRC (Region I, Nuclear Materials Section, 631 Park Ave., King of Prussia, Pennsylvania 19406).

Enclosures:

1. Teletherapy Unit Tests
2. Teletherapy Head Survey
3. (3) sketches of facility environs
4. Radiation Survey around facility
5. Copy of Emergency Posting at door of treatment room
6. Copy of Wipe Test by AMS
7. Copy of Certificate of Measurement by AMS
8. Copy of Receipt of old sources by AMS
9. Five Year Inspection and Preventative Maintenance Report

It is my conclusion that this cobalt facility is in compliance with the conditions of the license, in particular, conditions 13 to 26, at this time,



M. M. Castro, Ph.D.

Radiation Oncology Physicist, ABR-Certified

1986 JUN 18 PM 3 29

RECEIVED-REGION I

REPORT OF TELETHERAPY TESTS AND SURVEYS

Licensee Framingham Union Hospital
Address 115 Lincoln St., Framingham, MA.
License # 20-10621-02

TELETHERAPY TESTS

Yes The interlock on the door(s) to the teletherapy room was tested and found to function properly. When a door was opened with the source "ON", the source returned to the "OFF" position and could not be turned "ON" again until the door was closed and the system reset at the control panel.

Patient viewing through door view port via mirror in room is satisfactory.

Yes The teletherapy source "ON-OFF" indicators, both at the source housing and on the teletherapy machine control panel, were tested and found to function properly.

An independent GM monitor is installed in the treatment room, and is functioning properly.

Yes The teletherapy treatment timing device was tested and found to be accurate and to return the source to the "OFF" position when the preset time elapsed.

Yes Electrical and/or mechanical stops installed to limit the orientation of the teletherapy head with the source "ON" were tested and found to function properly. The limitations are:

(1) IF beam central axis passes through the isocenter, treatment can be carried out provided that beam is not directed above the horizontal.

(2) IF the central axis is off the isocenter then treatment can only be carried out as long as the beam is directed toward the floor.


(3) When the CA and the isocenter coincide, the beam stop fully intercepts the beam.

Figure F-1 TELE THERAPY HEAD SURVEY


(Source in "OFF" position.
Measurements taken one meter
from source)

Top View-Showing
orientation
of Views A through D


Position No.	Radiation Level (mR/hr)
View A	
1	<u>1.65</u>
2	<u>0.76</u>
3	<u>2.55</u>
4	<u>1.07</u>
View B	
5	<u>0.71</u>
6	<u>1.28</u>
7	<u>1.78</u>
8	<u>0.76</u>
View C	
9	<u>0.38</u>
10	<u>0.51</u>
View D	
11	<u>0.51</u>
12	<u>1.63</u>
13	<u>1.63</u>
14	<u>0.76</u>
Average value	<u>1.12</u>
Maximum value	<u>2.55</u>




View A-Vertical
from left side




View B-Vertical
from left front



View C-Vertical
from front



View D-Vertical
from right front



Date of survey 5/16/86
Instrument used Victoreon #491

Manufacturer's name & model number of teletherapy source AMS-3801

Date of installation 5/16/86


OUTPUT 9721 RHM
 RMM

Date of output measurement 5/16/86

OUTSIDE
SHRUB

D-2

D-1




Rm 203
Doctor's
Office

N

J

(UPPER LEVEL)



Cobalt
Control
Area A

(GROUND
LEVEL)

OUTSIDE
SHRUB

D

(Lower
Level)

M

Pump &
Switch
Room

FILL
DIMENSIONS
approximate

Ground

Room 203
Doctors Office


I

J (UPPER LEVEL)

Radio-
therapist's
Office

B

(Ground
Level)



Doctors
Office

E, F

(LOWER
LEVEL)

L

Rm. 050
Doctors
Office

FILL
(Dimensions
approximate)

K

Rm. 020
Doctors
Office

TELE THERAPY FACILITY SURVEY

Field Size Used: 25" X 25"

(Ref. # 20-10621-02)

Phantom Used: Water

Beam catcher used? Yes

Survey Meter: Victoreon 491

POSITION Refer to sketches	RESTRICTED AREA?	BEAM ANGULATION (deg)	MAXIMUM RAD'N LEVEL mR/hr	REMARKS
A-1	Yes	90	1.22	
		60	2.24	
		30	0.61	
		0	0.20	
		330	0.05	
		300	0.05	
		270	0.05	
A-2	Yes	90	0.82	
		60	3.77	
		30	1.22	
		0	0.15	
		330	0.10	
		300	0.05	
		270	0.04	
B	Yes	90	0.23	
		60	0.61	
		30	0.36	
		0	0.15	
		330	0.03	
		300	0.02	
		270	0.05	
C	Yes	90	0.46	
		60	0.41	
		30	0.41	
		0	0.82	

Control
Typical
operator's
position

Control
1' from
wall

Radi therapist
office

X-ray
room

TELE THERAPY FACILITY SURVEY

Field Size Used: _____

(Ref. # _____)

Phantom Used: _____

Beam catcher used? _____

Survey Meter: _____

POSITION Refer to sketches	RESTRIC- TED AREA?	BEAM ANGULATION (deg)	MAXIMUM RAD'N LEVEL mR/hr	REMARKS
		330	0.92	
		300	1.12	
		270	0.82	
D-1	No	90	0	1' from accessible
OUTSIDE SHRUB AREA		60	0	wall (shrub growth
		30	0	very dense)
		0	0.18	
		330	0.51	
		300	3.32	
		270	6.12	
D-2	No	90	0	at pedestrian walk
OUTSIDE SHRUB AREA		60	0	
		30	0	
		0	0	
		330	0.015	
		300	0.10	
		270	0.15	
E-1	No	90	0.20	at secretary's chair
Room 102		60	0.26	
		30	0.36	
		0	0.41	
		330	0.41	
		300	0.51	
		270	0.41	
E-2	No	90	0.41	edge of wall counter

TELE THERAPY FACILITY SURVEY

Field Size Used: _____

(Ref. # _____)

Phantom Used: _____

Beam catcher used? _____

Survey Meter: _____

POSITION Refer to sketches	RESTRIC- TED AREA?	BEAM ANGULATION (deg)	MAXIMUM RAD'N LEVEL mR/hr	REMARKS
		60	0.77	
		30	0.71	
		0	0.71	
		330	0.61	
		300	0.77	
		270	0.66	
E-3	No	90	1.22	1' from wall of secretary's area
		60	1.17	
		30	0.92	
		0	0.61	
		330	0.46	
		300	0.46	
		270	0.46	
F	No	90	1.33	1' from wall
		60	1.12	
		30	0.56	
		0	0.36	
		330	0.10	
		300	0.10	
		270	0.05	
G	No	90	0.61	1' from wall
		60	0.46	
		30	0.05	
		0	0	
		330	0	

TELE THERAPY FACILITY SURVEY

Field Size Used: _____

(Ref. # _____)

Phantom Used: _____

Beam catcher used? _____

Survey Meter: _____

POSITION Refer to sketches	RESTRIC- TED AREA?	BEAM ANGULATION (deg)	MAXIMUM RAD'N LEVEL mR/hr	REMARKS
		300	0	
		270	0	
H	Yes	90	2.6	Occupancy = 0.
		60	6.1	
		30	1.33	
		0	0.36	
		330	0.10	
		300	0.06	
		270	0.05	
J	No	90	0.61	I, J are office 203.
		60	0.13	Max. readings are in
		30	0.02	Doctor's office.
		0	0.02	Measurements taken
UPPER Level		330	-	1' from floor.
		300	0.15	
		270	0.71	
K, L	No	90	0.05	Measurements at 6'
		60	0.02	from floor. Surveyed
		30	0.01	2 offices (020 & 050),
		0	0.01	utility room and toilet.
LOWER Level		330	0.01	
		300	0.01	
		270	0.01	
K, L		0°	0.013	← off beam stop.

June 12, 1986

EMERGENCY PROCEDURE
IN CASE OF
BEAM CONTROL FAILURE

If the light signals indicate that the beam control mechanism has failed to terminate the exposure at the end of the present time (for example, if the red light stays on and/or the green signal does not light up) the source may still be in the "ON" position. The following steps are to be carried out in a calm manner.

FOR THE RADIATION THERAPY TECHNICIAN

1. Open the door to the treatment room.
2. If the patient is ambulatory direct him to get off the table and leave the room.
3. If the patient is not ambulatory:
Enter the treatment room but avoid exposure to the useful beam.
Pull the treatment table as far away from the useful beam as possible.
Transfer the patient to a stretcher and remove him from the room.
4. Close the door.
5. Turn off the main switch at the control panel.
6. Notify the radiation therapist and radiation protection supervisor at once.

1. Dr. Joseph Ferrucci	872-3684
2. Rhe Etta Plante	263-6689
3. Dr. L. Inker	879-7111 ext.2601
4. Harold Jennison	879-7111 ext.4012
5. Dr. M.M. Castro	793-6550
	799-8245

FOR THE RADIATION PROTECTION SUPERVISOR

1. Secure a portable survey meter. Check to see that the meter is functioning properly.
2. Turn the power on and open the door a few inches.
3. Stand behind the door and insert the survey meter into the door opening to test whether in fact the source is still in the "ON" position.
4. If the source is still "ON" enter the room and manually turn the source "OFF" as per manufacturer's instructions. Avoid intercepting the useful beam with any part of your body.
5. Adjust the limiting diaphragms to the smallest field size.
6. Close the door to the treatment room. Turn off the power. Lock the control panel. Post a sign warning people not to enter.
7. Notify the equipment manufacturer's representative.



Advanced Medical Systems, Inc.

1020 London Road
Cleveland, OH 44110
(216) 692-3268

Framingham Union Hospital
475 Franklin Street
Framingham, MA. 01701

CERTIFICATE OF WIPE TESTING OF RADIOISOTOPE SOURCE

This is to certify that the radioisotope source identified as **ADVANCED MEDICAL SYSTEMS, INC.**, Catalog No. AMS-3802, Serial No. AMS-2550 Cobalt-60 Therapy Source and to be installed in Picker Model No. 590-E, Serial No. 182 Therapy Unit, was wipe tested on 14th January, 1986 and found to have .00171 microcurie of removable contamination, as determined by comparison of the wipe with a standard Cobalt-60 source of .0518 microcurie in a Picker Model 2804 Welltype Scintillation Detector and a Picker Model 628433 Spectroscaler.

Signed: Josephine S. Powell

Josephine S. Powell

Dated: January 20th, 1986



Advanced Medical Systems, Inc.

1020 London Road
Cleveland, OH 44110
(216) 692-3268

Framingham Union Hospital
475 Franklin Street
Framingham, MA. 01701

CERTIFICATE OF MEASUREMENT COBALT-60 SOURCES

CATALOG NO. AMS-3802
SERIAL NO. AMS-2550

This is to certify that the radioisotope source as identified above was measured at the Advanced Medical Systems, Inc., 1020 London Road Cleveland, Ohio, U.S.A., in such a fashion that the measurement is equivalent to that obtained when the source is installed in a Picker Corporation Catalog Number 6296 60-Cobalt Beam Therapy Treatment equipment with Catalog Number 3706 beam defining device of 25 cm by 25 cm aperture at a distance of 80 cm.

Under these conditions this source was found to have a radiation output in free air of .4932 roentgens per hour at one meter on 14th January, 1986.

The attached decay table for this radioisotope will be useful in estimating the activity at future dates.

This source contained 4681 curies on 1st. January, 1986.

Signed: Josephine S. Powell
Josephine S. Powell
Dated: January 20th, 1986.

The measurement reported is for invoicing purposes only and A.M.S. Inc, assumes no responsibility for results of exposures computed with this value.



Advanced Medical Systems, Inc.


1020 London Road
Cleveland, OH 44110
(216) 692-3268

Framingham Union Hospital
475 Franklin Street
Framingham, MA. 01701

Radiation Therapy Department (Cobalt)

Received from the above-named facility as of 5-16-86
~~100~~ 60-Cobalt teletherapy source, Model Number 3802/200A, Serial
Number: PX-2325 2.38-7 200A
2. PK-687

Advanced Medical Systems, Inc., is authorized to receive the above-mentioned source under N.R.C. License number 34-19089-01.

Signed: 
for Advanced Medical Systems, Inc.

Dated: 5-16-86



Advanced Medical Systems, Inc.

1020 London Road
Cleveland, Ohio 44110
(216) 692-3268

PG 1.

TELETHERAPY UNIT FIVE YEAR INSPECTION & PREVENTATIVE MAINTENANCE REPORT

CUSTOMER: Framingham Union Hospital/475 Franklin Street/Framingham, MA. 01701
(HOSPITAL OR DOCTOR) (LOCATION)

TYPE OF UNIT: CAT. NO. 6296 HEAD 590-E SERIAL NO. 182
DATE OF INSPECTION: 5-5-86 LICENSED ENGINEER A.E. JORDAN

The following items have been inspected and the listed action taken or recommended as indicated. None of the recommended items require that the source be removed for their correction.

I. SOURCE HEAD

- A. Check for significant radioactive contamination
 - () None Detected
 - () See Notes
- B. Shutter Rotor Bearings
 - 1. Inboard
 - () Lubricated () N/A
 - () Replaced
 - 2. OutBoard
 - () Lubricated () N/A
 - () Replaced
- C. Shutter Rotor
 - () Cleaned
 - () Other - See Notes - ROTAR REPLACED
- D. Shutter Rotor Cavity
 - () Cleaned
 - () Other - See Notes
- E. Shutter Rotor Return Spring
 - () Replaced
- F. Shutter Rotor Stops
 - "ON" Position () OK () Adjusted () Replaced
 - "OFF" Position () OK () Adjusted () Replaced
- G. Shutter Rotor Drive Mechanism
 - () Lubricated () Voltage (72.0 Volts)
 - () Deficiency See Notes () V Belt Replaced
- H. Head Leakage Survey (16 Points at 1 meter from source)
 - Average Leakage 1.01 mrhm
 - Highest Point Reading 2.5 mrhm

II. COLLIMATING DEVICE

- A. General Condition: "GOOD" D X VANE LIMIT SWITCH NEEDED
ADJUSTMENT - TESTED OK
D Y VANE NEEDED LUBED BADLY. TESTED OK



FIVE YEAR INSPECTION AND PREVENTATIVE MAINTENANCE REPORT

B. Field Size Indicators - Calibration

1. Distance at which calibrated

() 55cm. () 60cm. () 75cm. (X) 80cm. () 95cm.

2. Test Size

Dials Indicated

Light Field

4cm. x 4cm.

4 X 4

3.9 X 3.9

10cm. x 10cm.

10 X 10

10.0 X 10.0

18cm. x 18cm.

18 X 18

18.0 X 18.0

25cm. x 25cm.

25 X 25

25.1 X 25.2

C. Distance Localizer Calibration

Setting

Indicates

40cm.

40

55cm.

55

60cm.

60

75cm.

75

80cm.

80

95cm.

95

D. X-Ray film taken 80 cm. from source with actual field size of

10 X 10

Lines scribed on film indicate edges of light field.

E. Collimator accessories

- 1. Front Pointer (X)OK ()Needs Repair - See Notes
- 2. Back Pointer (X)OK ()Needs Repair - See Notes
- 3. Pin and Arc ()OK ()Needs Repair - See Notes
- 4. Wedge Filters (X)OK ()Needs Repair - See Notes
- 5. Breast Cone ()OK ()Needs Repair - See Notes
- 6. Beam Shaping Block Holder (X)OK ()Needs Repair - See Notes
- 7. Extenders (Trimmers) (X)OK ()Needs Repair - See Notes
- 8. Other POST (X)OK ()Needs Repair - See Notes

III. UNIT IN GENERAL

A. Unit is in good working order
recommend service contract for proper
maintenance of unit

B. Isocenter - The true isocenter has been determined to be at a distance of _____ cm. from the end of the collimator. The isocentric accuracy of the center of the beam was determined to be + or - _____ mm.
() see Notes and Recommendations which may improve accuracy.

C. Safety Modifications

- (X) All modifications recommended by Picker and AMS, Inc. have been made.
- () The following safety modifications to this unit are recommended by Picker and AMS, Inc. but have not yet been completed. Your local AMS service representative will contact you regarding the following:

- 1. SERVICE CONTRACT
- 2. _____
- 3. _____
- 4. _____



PG. B1

FIVE YEAR INSPECTION AND PREVENTATIVE MAINTENANCE REPORT

D. Treatment Timer Operation

Timer Set for:

30 Seconds

60 Seconds

120 Seconds

() See Notes and Recommendations

Actual Time:

X 30

60

120

- NONE - 27

E. Source Transit Time

On 2.0 Sec.

Off 1.5 Sec.

F. Operational Tests

1. Shutter opens and completely closes at 0,90,180, and 270 or at maximum angles in both directions allowable for this particular installation.

(X) OK

() See Notes

2. Where applicable that shutter will not open beyond allowable angles for this particular installation (X)OK () See Notes

3. Timer switch properly closes the shutter. (X)OK () See Notes

4. "Shutter Closes" or "Emergency" button properly closes the shutter (X)OK () See Notes

5. Shutter closes when main power is turned off and does not reopen when power is restored. (X)OK () See Notes

6. Shutter closes when room door is opened and the shutter does not reopen when the door is reclosed. (X)OK () See Notes

7. Where applicable, back pointer, collimator and localizer lights function properly and are calibrated properly. (X)OK () See Notes

8. Control panel and room warning lights works properly. (X)OK () Repaired () See Notes

9. All control functions work properly (Rotation, Skip Scan, etc.). OK (X)

G. Mechanical Inspection

1. Structural Defects 2.5

(X) None Noted

() Repairs Needed-See Notes

2. Bolts

(X) All Correctly tightened

(X) Adjustments made

() Defective - See Notes

H. Electrical Inspection

Wiring (X)OK () Replaced - See Notes

Components (X)OK () Replaced - See Notes

I. Six (6) Rocker Switches replaced on VG8 Control (Rotational Units)

() Replaced

(X) Not Applicable



FIVE YEAR INSPECTION AND PREVENTATIVE MAINTENANCE REPORT

J. General Safety

- Unit is safe to operate, however, whether or not the unit is accurate enough for treatment purposes is a determination which must be made by the radiotherapist.
- Unit UNSAFE to operate or treat - see below for recommendations:

- NONE -	10	3.7	10.0
140	18	25.1	18.0
256	25	25.1	25.1

IV. Table

- A. Locks
 - 1. Transverse
 - OK () Repaired X () See Notes
 - 2. Longitudinal
 - OK () Repaired () See Notes
 - 3. Floor
 - OK () Repaired 56
 - () N/A () See Notes 5
- B. Vertical Drive Clutch or Motor Mount
 - OK () Repaired 15 () See Notes
- C. Chain Tension & Condition
 - OK () Adjusted X () See Notes
- D. General
 - 1. Hardware Tightened X
 - () 2. Lubricated as Necessary
 - () 3. Checked for signs of Binding and Unusual wear.
- E. Safety Service Notes
 - () Performed X () See Notes

V. NOTES AND RECOMMENDATIONS

- A. COLLIMATOR BRAKE PAD TO BE REPLACED. OK X
- B.
- D. LUBRICATED
- X
- X

DATE INSPECTION COMPLETED: 5-16-86

BY ADVANCED MEDICAL SYSTEMS, INC. LICENSED ENGINEER: K.E. JORGAN

REPORT EXPLAINED TO AND COPY RECEIVED BY: [Signature]

NOTE: N/A - NOT APPLICABLE



ATC Medical Group

One Factory Row
Geneva, Ohio 44041
(216) 466-4671

SERVICE REPORT NO. 3157

CUSTOMER: Framingham Union Hospital		ADDRESS: 475 Franklin Street Framingham, MA 01701	PHONE: (617) 875-5919
---	--	---	-------------------------------------

SERVICE REQUESTED BY: Dr. Ferrucci	EQUIPMENT TYPE: C-9	P.O. NO. JOB NO. 885-16	METER READINGS H/V FIL
DATE 1 / 1	AM <input type="checkbox"/> PM <input type="checkbox"/>	WORK CATEGORY <input type="checkbox"/> INSTALLATION <input checked="" type="checkbox"/> WARRANTY <input type="checkbox"/> MODIFICATION <input type="checkbox"/> SERVICE CONTRACT	<input type="checkbox"/> REMEDIAL MAINTENANCE <input type="checkbox"/> PURCHASE ORDER <input type="checkbox"/> PREVENTIVE MAINTENANCE <input type="checkbox"/> OTHER

SERVICED BY: Keith Jordan	EMP. NO.	FAULTS/SYMPTOMS <i>Source exchange Due</i>
-------------------------------------	----------	---

DATE	IN	OUT	HOURS	CAUSE
5/15/86	8:00	9:00	1.0	
5/16/86	6:30	3:30	12.0	
/ /				
/ /				
/ /				
/ /				

TOTAL	
SHOP HOURS	
TRAVEL HOURS	
TOTAL HOURS	<i>* Replaced Rotax</i>

Performed all PMJ checks and adjustments.

CUSTOMER'S SIGNATURE: <i>[Signature]</i>	DATE: <i>11/86</i>
---	-----------------------

CONTINUE ON BACK

SELECTION: William O. Miller, Chief
License Fee Management Branch
Office of Administration

John E. Glenn, Chief
Nuclear Materials Section B
Division of Engineering and
Technical Programs

03028891
02300
5/89

LICENSE FEE TRANSMITTAL

A. REGION I

Teletherapy Survey

1. APPLICATION ATTACHED

Applicant/Licensee: Framingham Union Hospital
Application Dated: 6/13/86
Control No.: 105681
License No.: 20-10621-02

2. FEE ATTACHED

Amount: 0
Check No.: 0

3. COMMENTS

Signed Bronda P. Latchek
Date 6/19/86

B. LICENSE FEE MANAGEMENT BRANCH

1. Fee Category and Amount: TA

FEE EXEMPT

TA Survey

2. Correct Fee Paid. Application may be processed for:

Amendment ✓
Renewal _____
License _____

Signed Kimberley
Date 6/25/86