

Commonwealth Edison Company  
Byron Generating Station  
450 North German Church Road  
Byron, IL 61010-9794  
Tel 815-234-5441

Public 16-01

March 5, 1998

**ComEd**

LTR: BYRON 98-0075  
FILE: 1.10.0101

Mr. A. B. Beach  
Region III Administrator  
U.S. Nuclear Regulatory Commission  
Region III  
801 Warrenville Road  
Lisle, IL 60532-4251

PRIORITY ROUTING

First	Second
RA	RC
DRA	EOC
DRP	BOA
DRS	QI
DNMS	PAO
DRMA	

FILE *has*

SUBJECT: Byron Nuclear Power Station  
Change in Scope of the B1R08 Hydrolazing Project  
NRC Docket Number 50-454, 50-455

REFERENCE: Letter from Geoffrey E. Grant, Director Division of  
Reactor Projects U.S. N.R.C. to K. Graesser, Site Vice  
President Byron Station, Commonwealth Edison Company  
dated August 1, 1997

Lear Mr. Beach:

We are notifying you of a change in the scope of the B1R08 hydrolazing activities for Byron Station from that documented during the June 20, 1997 Predecisional Enforcement Conference. In the June 20, 1997 Predecisional Enforcement Conference, Byron Station informed the NRC that the station would hydrolaze the containment floor drain system.


After reviewing the scope of the project to inspect and hydrolaze the RF system during B1R08, it was determined that the floor drains in both the Regenerative Heat Exchanger and Excess Letdown Heat Exchanger rooms would not be inspected and hydrolazed. Additionally, the floor drain located in the Incore Instrumentation room was not hydrolazed during the outage as planned due to it being plugged.

Access to the containment floor drains in the Regenerative and Excess Letdown Heat Exchanger Rooms is limited at this time based on ALARA concerns. The areas are considered "High Radiation" areas due to elevated dose rates. Additionally, access to these areas is difficult, requires the removal of floor plugs, and would require designation of each area as a confined space. As for the drain located in the Incore Instrumentation room, a temporary alteration was installed in the cleanout line located in the room to allow for sufficient water flow into the leak detection sump. This flowpath was verified to be functional by running water through the cleanout line. Future actions for the containment floor drains in the Regenerative and Excess Letdown Heat Exchanger rooms are being evaluated for Unit 1 and Unit 2.

9803160002 980305  
PDR ADOCK 05000454  
PDR

p:\98byltr\980075.wpf

A Unicom Company



MAR 09 1998

LTR: BYRON 98-0075

March 5, 1998

Page 2

Instrumentation room, a temporary alteration was installed in the cleanout line located in the room to allow for sufficient water flow into the leak detection sump. This flowpath was verified to be functional by running water through the cleanout line. Future actions for the containment floor drains in the Regenerative and Excess Letdown Heat Exchanger rooms are being evaluated for Unit 1 and Unit 2.

If you have any questions related to this matter, please contact Daryl Prisby at (815)234-5441 extension 2659.

Sincerely,

*for K. L. Graesser*  
K. L. Graesser  
Site Vice President  
Byron Nuclear Power Station

KLG/DP/clb

cc: E. W. Cobey, Senior Resident Inspector, Byron  
J. B. Hickman, Byron Project Manager - NRR  
M. J. Jordan, Reactor Project Chief - RIII  
F. Niziolek, Division of Engineering - IDNS

LTR: BYRON 98-0075

March 5, 1998

Page 3

bcc: Licensing Operations Director