NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB NO. 3150-0104 (4-95) EXPIRES 04/30/98							-0104						
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)									ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. REPORTED LESSONS LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (T-6 F33), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT				
0	FACILITY NAME (1) Point Beach Nuclear Plant, Unit 1						PRODUCTION CONTROL	Mary Table Mark Co.	THE STREET, SHOP	DOCKET NUMBER (2) PAGE (3)			PAGE (3)
TITLE (4)	- D-G-G	OII 140		THE PARTY OF THE P	TIT C T		- COUNTY TO SERVICE STATE OF THE SERVICE STATE OF T		Lanna	030002			
		e Tec	hni	cal Specifi	cation	s Surv	reill	lance	of	Contai	nment	Spra	ay
Logic	OFFICENCY AND A STATE OF	1057	·			T ornor		Manuer monte monte	J				
EAE	NT DATE	(6)		LER NUMBER (6)		REPO	RT DATE	(7)			ACILITIES IN	-	-
MONTH	DAY	YEAR	SEQUENTIAL REVISION YEAR NUMBER NUMBER		MONTH	DAY	YEAR			ET NUMBER			
				1		-		-	-	ITY NAME		05000301 DOCKET NUMBER	
02	13	98	98	THE RESIDENCE HEAVE SHARE THE PROPERTY OF THE PARTY OF TH	00	03	16	98	_		CHEROLOGICA CHICAGO	THE REAL PROPERTY.	05000
OPERA'			THIS	REPORT IS SUBMITTED	PURSUANT			NTS OF 1					
MODE	(0)	N	20.2201(b)			20.2203(a)	(2)(v)		X 50.73(a)(2		?)(i)		50.73(a)(2)(viii)
POW				20.2203(a)(1)		20.2203(a)(3)(i)		50.73(a)(2)(ii)			50.73(a)(2)(x)		
LEVEL	(10)	075		20.2203(a)(2)(i)		20.2203(a)	(3)(ii)			50.73(a)(2	50.73(a)(2)(iii)		73.71
				20.2203(a)(2)(ii)		20.2203(a)	-			50.73(a)(2	MARKET TORK DAY DEFENDED FOR FACE AND		OTHER
				20.2203(a)(2)(iii)					50.73(a)(2				
				20.2203(a)(2)(iv)	NAME OF THE OWNER, OF THE OWNER, OF THE OWNER, OF THE OWNER, OWNER, OWNER, OWNER, OWNER, OWNER, OWNER, OWNER,	50.36(n)(2	STEWN SERVICE STATES	DANIER CHIEFE	-	50.73(a)(2	(Or III III	MC FORM SOCK
NAME	ONE SEASON CARD ACCORDING				LICENSEE C	ONTACT FOR	THIS LI	ER (12)		TELEPHON	NE NUMBER (Include	Area Code)
Curtis A. Castell, Licensing Engineer (414) 221-2019													
CAUSE	SYSTEM	COMP	UNIFORMATION SECURES	COMPLETE ONE LINE FO	after the techniques and the second	MODEL CONTROL OF THE PARTY NAMED IN	AND THE RESIDENCE OF THE RESIDENCE	The state of the s	na mentenangen	IS REPORT (13	MANUFAC	THOCO	T REPORTABLE
CAUSE	STSIEN	COMP	ONENT	MANUFACTURER	TO NPRD	MODELESSPERSORS	CAUSI	515	EM	COMPONENT	MANUFAC	TORER	TO NPRDS
	-	-						-	-				
	DECEMBER OF STREET	e i	IDDI EM	ENTAL DEBORT EXPECT	ED (14)		Lorannona	PC STREET	EVP	CTED	MONTH	DAY	YEAR
SUPPLEMENTAL REPORT EXPECTED (14) YES					X	NO		SUBN	ISSION	MONTH	DAT	TEAN	
				SUBMISSION DATE).	A service and the service as a				DAT	E (15)			
ABSTRAC	T (Limit	to 1400 ap	aces, i	.e., approximately 15 sir	gle-spaced t	ypewritten li	nes) (16	CODE	9 4 4 4	on rone	rt was	in	itiated
As a result of ongoing GL 96-01 reviews, a condition report was initiated on February 13, 1998, to document that circuit testing of the containment													
				potentially									
13,	1998	3, the	e de	etermination	was n	made th	nat '	this	sit	uation	consti	itut	ed a
missed Technical Specifications surveillance, Unit 1 was at 75% power and													
Unit 2 was at 100% power. The test discrepancy is based on a potentially													
	undetectable safety logic switch failure associated with containment spray actuation logic. This is considered a missed Technical												
Specifications surveillance required by Technical Specifications table													
	15.4.1-1 item 27 for channel functional test. Special testing of the												
containment spray actuation circuitry to verify proper continuity of the													
bis	bistable trip switches was performed on February 14, 1998, prior to expiration of the 24-hour allowance for the missed surveillance, which is												
contained in Technical Specification 15.4.0.3. This proved that the													
switches are in the proper position and fully operable. Corrective													
actions are being implemented to perform the bistable trip switch													

continuity verification during each required quarterly functional test

per Technical Specifications Table 15.4.1-1 item 27.

9803300424 980316 PDR ADOCK 05000266 S PDR

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
Point Beach Nuclear Plant, Unit 1	05000266	YEAR SEQUENTIAL REVISION NUMBER NUMBER	2 OF 5
		98 - 010 - 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Event Description:

Nuclear Regulatory Commission Generic Letter 96-01 requires licensees to verify that logic circuit testing is being performed in accordance with Technical Specifications requirements. As a result of ongoing GL 96-01 reviews, a condition report (CR 98-0572) was initiated on February 13, 1998, to document that circuit testing of the containment spray logic was potentially inadequate. At 1345 hours on February 13, 1998, the determination was made that this situation constituted a missed Technical Specifications surveillance, Unit 1 was at 75% power and Unit 2 was at 100% power.

The test discrepancy is based on a potentially undetectable safety logic switch failure associated with containment spray actuation logic. The automatic containment spray actuation logic is based on completion of two, two out of three bistable logic combinations. During performance of analog testing of the high containment pressure containment spray actuation logic bistables in accordance with Technical Specifications Table 15.4.1-1 item 27, the bistable switch is placed in the "Trip" position. Placing the bistable switch in "Trip" position causes the actuation logic relay to be connected to an external power source through the bistable trip switch. This causes the logic relay to be in the tripped position which is the energized state for this relay.

After the bistable trip switch is returned to normal, the external power source is disconnected, but the test does not include verification that the logic relay is reconnected to the bistable. The failure to verify the continuity of this switch was caused by this circuitry being different than other similar circuitry. The containment spray actuation circuitry requires energization to initiate the actions, other circuitry of this type requires deenergization to initiate actions. Therefore, if continuity of the bistable trip switches is not reestablished after testing the other types of circuitry (that are deenergize-to-trip), the affected channel would remain in the tripped state.

A review of the outage transmitter calibrations and quarterly analog rack calibrations for the containment spray actuation circuitry revealed that these tests do not verify the bistable to logic relay connection is intact through the bistable trip switch. The quarterly testing required per Technical Specifications Table 15.4.1-1 item 27 is performed in accordance with the FSAR description for analog testing. Although, the bistable trip switch contact is returned to the normal position after the functional test is complete, the channel functional test for high containment pressure containment spray actuation is considered to be not fully met because of the failure to verify continuity of the switch after it is placed back in the normal position. This is considered a missed Technical Specification surveillance required by Technical Specifications Table 15.4.1-1 item 27 for channel functional test (quarterly).

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Point Beach Nuclear Plant, Unit 1	05000266	YEAR		REVISION NUMBER	E
		98	- 010 -	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Special testing of the containment spray actuation circuitry to verify proper continuity of the bistable trip switches was performed on February 14, 1998, prior to expiration of the 24-hour allowance for the missed surveillance contained in Technical Specification 15.4.0.3. This proved that the switches are in the proper position and fully operable.

Corrective actions are being implemented to perform the bistable trip switch continuity verification during each required quarterly functional test per Technical Specifications Table 15.4.1-1 item 27.

Component and System Description:

The containment spray system is actuated by the coincidence of two sets of two out of three "hi-hi" containment pressure signals. Technical Specifications Table 15.3.5-1 item 2(a) lists the setting limit for containment spray as </=30 psig. The bistables are identified as PC-945B, PC-946B, PC-947B, PC-948B, PC-949B and PC-950B.

Cause:

This event was caused by the failure to adequately verify the bistable trip switch position after it is placed back in the "normal" position after quarterly functional testing of the containment pressure containment spray actuation bistables.

Corrective Actions:

The bistable trip switch continuity was verified within 24 hours of the determination that this testing was not adequate and was considered a missed surveillance in accordance with the Point Beach Technical Specifications.

The appropriate test procedures will be changed to verify the trip switch continuity during or after the applicable Technical Specifications surveillance tests as necessary to properly verify circuit operability.

Reportability:

This event is being reported in accordance with the requirements of 10 CFR 50.73(a)(2)(i)(B), "Any operation or condition prohibited by the plant's Technical Specifications."

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Point Beach Nuclear Plant, Unit 1	05000266	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		98	- 010 -	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Safety Assessment:

The potential exists that containment spray was, at some time in the past, unknowingly inoperable because the trip switches could have been inoperable and the bistables may not have been connected to the logic relays. This condition is highly improbable because it would require at least two switches to be inoperable or one switch and another independent failure (of a containment pressure channel) to occur to prevent spray operation. The switches are known to be highly reliable with gold contacts. Additionally, verification of switch continuity on February 14, 1998, showed that all six (6) channels in each Unit are operable.

System and Component Identifiers

The Energy Industry Identification System component function identifier for each component/system referred to in this report are as follows:

Component/System	Identifie
Plant Protection System	JC
Relay	RLY
Hand Switch	HS
Containment Spray System	BE

Similar Occurrences:

A search of previously submitted licensee event reports (within the past two years) similar to this situation for PBNP was conducted. The specific criterion used was based on a search for licensee event reports that were submitted due to inadequately implemented Technical Specifications surveillance/sampling requirements:

- 266/97-043-00 Inadequate Technical Specification Surveillance of Reactor Trip System Interlocks
- 266/97-016-00 Steam Generator Level Logic Not Tested in Accordance with the Technical Specifications
- 266/97-012-00 Diesel-Driven Fire Pump Day Tank Not Sampled In Accordance With Technical Specifications
- 266/97-011-00 Containment Fan Cooler Accident Fans Not Tested In Accordance With Technical Specifications
- 266/97-005-00 1SI-852A Not Tested In Accordance With Technical Specifications

NRC FORM 386A (4-95) U.S. NUCLEAR REGULATORY COMMISSION

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
Point Beach Nuclear Plant, Unit 1	05000266	YEAR SEQUENTIAL REVISION NUMBER	5 OF 5
		98 - 010 - 00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

- 266/97-003-00 Spare Containment Penetrations Not Leak Tested In Accordance With Technical Specifications
- 266/96-014-00 Steam Generator Blowdown Sample Not Performed In Accordance With Technical Specifications
- 266/96-012-00 EDG Fuel Oil System Tests Not Performed In Accordance With Technical Specifications
- 266/96-008-00 Missed Full Pressure Test Of Containment Airlock