(RC Farm 366 9-83)			LIC	ENSE	E EVE	NT RE	PORT	(LER)	U.S. N	UCLEAR APPROVE EXPIRES	REGULAT D OMB NG 8/31/85	ORY COMM 0. 3150010	IISSION M
ACILITY NAME (	1)	AND A THE OCCUPATION AND A DESIGN	and the particular second second of		to be deferred out to the			10	DOCKET NUMBE	R (2)	kan manun afan	PAG	E (3)
Wolf Cre	ek Genera	ting Stati	on				****		0   5   0   0	1014	1812	1 OF	019
Technica	al Specifi	cation Vio	lation	- Inc	perab	le Fi	re Bai	rriers Ca	used By	Perso	onne1	Error	S
EVENT DATE	E (5)	LER NUMBER (	5)	RE	PORT DATE	(7)	and 1000 an eight das to	OTHER	FACILITIES INV	DLVED (B	8)		
MONTH DAY	YEAR YEAR	NUMBER	NUMBER	MONTH	DAY	YEAR		FACILITY NAM	AES	DOCK	ET NUMBE	H(S)	
01 21 11 6			- 011	017		017				0 10	1010		
0 2 1 0	THIS RE		D PURSUANT 1	TO THE R	EQUIREME	NTS OF 10	CFR &: (0	Check one or more i	of the following) (	11)	1010	101	
MODE (9)	1 20.	.402(b)		20.405	(c)			50,73(a)(2)(iv)	en et were er state statt forreet et		73.71(6)	ande frederinge offen	
POWER	20.	.405(s)(1)(i)		50.38(c	)(1)			50.73(a)(2)(v)			73.71(c)		
(10) 1	1010 20.	.405(a)(1)(ii)		50.38(c	)(2)			50.73(a)(2)(vii)		-	OTHER (S) below and	pecify in Abi in Text, NRG	tract C Form
	20	.405(a)(1)(iii)	X	60.73ia	)(2)(1)		-	60.73(s)(2)(viii)(	A)		366A)		
	20.	.405(s)(1)(iv)		50.73(a	)(2)(ii)			50.73(a)(2)(viii)(	5)				
	20	.49(0)(0)(1)(4)	L	ICENSEE	CONTACT	FOR THIS	LER (12)		ann an Aonaich ann a An Aire an Ionaire				
NAME Mori	in G Wil	liame _ Su	nerinte	ndent	of P	oquila	tory	Quality		TELEP	HONE NUM	ABER	
PICT 1	un o. wii	ar	id Admin	istra	itive	Servi	ces	Quarrey	3 1 1 6	316	5141-	18 18	1311
	1	COMPLETE	ONE LINE FOR	EACH C	OMPONENT	FAILURE	DESCRIBE	D IN THIS REPOR	13)				
CAUSE SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS	ļ		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REP	ORTABLE NPRDS		
ВҚР	SIEIAL	X191919	N	ļ	*****								
BKQ	SEAL	X 9 9 9 9	N										
aleka manga mangana sa mina minangan sa		SUPPLEME	NTAL REPORT	EXPECT	ED (14)			an arata an in Argan (Arma farin it) at a 1988	EXPEC	TED	MONT	H DAY	YEAR
X YES (14 yes,	complete EXPECTED	SUBMISSION DATE	)		NO		-		DATE	(15)	012	2 1 15	818
On s brea pene fire deli situ Spec revi corr Thes aspe Prop of k revi corr Thes	several occ ached fire etration se e door bloc ineated by ations are cifications sed Licens sed Licens ective ac se events of the gram Defic key elemen iew, the es cective ac	casions du barriers eals, hole cked open. Technical e consider s and are see Event tion taken occurred d e fire pro iency 87-0 ts of the xistence o tion plan are simila	ring Fel were di: s in fl In ead Specif ed to b being r Report as a r ue to p tection l was d fire pr f nonco is bein r to th	bruar scove oors, ch in icati e con eport (LER) esult erson prog evelc otect nform g imp ose d	y and red. wall stance on 3. dition is b ied pu is b ied pu ied pu is b ied pu ied pu	March These s of e, the 7.11 ns pro- rsuan eing hese rrors In M o pro- rogra ilico ted w sed i	h, 198 e situ build: e appr were p bhibit t to 1 submit events in fa arch, vide a m. Du ne RTV ith ve n LERS	87, situat ations in ings, abar copriate of promptly ed by the LØCFR 50. ted to up ted te ted to up ted te ted to up ted te ted te te ted te te te ted te te te ted te te te te te te te te te te te te te te te te t	tions inv nvolved f ndoned co correctiv initiated plant's 73(a)(2) pdate the comply v ternal Op tic revie course of als was istance.	volvi fire pondui ve me d. T s Tec (i) (B e sta vith perat ew an of th ident	ng t, an asure hese hnica ). T tus o vario ions d upg is ified	d a s his f us rade . A	
NRC Form 301	87071505 PDR ADC	122 37 87070 36K 05000	B 4B2 DR								¢U.8.GP	0:1984-0-45	4-481/18

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)
		YEAR SEQUENTIAL REVISION NUMBER NUMBER	
Wolf Creek Generating Station	0 15 10 10 10 14 18 13	2 8 7 - 0 1 10 - 0 11	0 2 OF 0 9

## Introduction

RC Form 366A

On several occasions during February and March, 1987, situations involving breached fire barriers were discovered. In each instance, the appropriate corrective measures were promptly initiated. Technical Specification (T/S) 3.7.11 requires that all fire barrier penetrations separating safety related fire-areas or separating portions of redundant systems important to safe shutdown with a fire area and all sealing devices in fire-rated assembly penetrations be operable, or that a fire watch of the affected area be established. These situations are considered to be conditions prohibited by the plant's Technical Specifications and are being reported pursuant to 10CFR 50.73(a)(2)(i)(B).

This revised Licensee Event Report (LER) is being submitted to update the status of corrective action taken as a result of these events. In May, 1987, during a systematic review and upgrade of key elements of the fire protection program, the existence of nonconforming silicone RTV foam penetration seals was identified. The revised portions of this LER provide information concerning this discovery and editorial changes to the original LER.

## Description of Events and Immediate Corrective Actions

## 1. Breached penetrations originally dispositioned on Nonconformance Report (NCR) 1SN52281C

NCR ISN52281C was written in December, 1984. This NCR was written on 22 penetration seals because of a lack of document traceability. Appropriate corrective actions were completed in January, 1985. All penetrations discussed in this section are listed on this NCR.

On February 16, 1987, at approximately 1030 CST, fire barrier penetration 321W0130 was found to be breached. This five inch diameter penetration serves as part of the required fire barrier between two fire zones on the 1984 foot elevation of the Control Building [NA]. The penetration service is a one inch fire protection pipe. Following this discovery, an hourly fire watch was established, and a corrective work request was written to seal the penetration.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104 EXPIRES: 8/31/8-5

ACILITY NAN	ME (1)	DOCKET NUMBER (2)	LER NUMBER (6) PAGE (3)
			VEAR SEQUENTIAL REVISION NUMBER NUMBER
Wolf	Creek Generating Station	0 15 10 10 10 14 18 12	817 - 01110 - 011 013 PF 0 10
EXT (If more a	pece is required, use additional NRC Form 3864/g/ (17)	1-1-1-1-1-141012	
	Review of the history of pen inspected in January, 1987. discovery that penetration 1 this discovery is provided i 1987, inspection did not ide properly sealed. As a resul the Fire Protection Speciali walkdown of all penetrations 321WØ1Ø9, 321WØ080, and 141W that the penetrations have b operating license on March 1	etration 321W0130, r This inspection was 33W2104 was not seal n Licensee Event Rep entify the fact that t of this occurrence st on March 11 and 1 addressed in NCR 18 2491 were found to b een unsealed since i 1, 1985.	revealed that it had also been a conducted as a result of the led. (Further discussion of cort 87-ØØ1.) The January, this penetration was not a walkdown was conducted by 12, 1987. During this SN52281C, penetrations be breached. It is assumed issuance of the facility
	Investigations have also rev 321W0080 had been inspected Specification surveillance p and Sealing Devices". STS M Specification Surveillance R that a visual inspection of electrical) of sealed penetr months. This Surveillance R inspection of an additional apparent changes in appearan initial inspection. During included penetrations 321W01 penetration seal was found t additional ten percent of ea no further discrepancies ide identified as not being seal was not identified as a test completed surveillance proce 321W0130 was initiated. Pen identified as having been br personnel.	ealed that penetration Fall, 1986, during procedure STS MT-026, MT-026 was performed requirement 4.7.11.1 at least ten percent ation be performed a requirement further of ten percent of each nee or abnormal degra the initial ten perc 30, 321W0109, and 32 to be damaged. Because ach type of sealed per entified. Although p red during the initial edure. Consequently metrations 321W0109 a reached because of per	ions 321W0130, 321W0109, and ng performance of Technical 'Fire Barrier Penetrations to satisfy Technical 'c', which requires, in part, t of each type (mechanical and at least once per eighteen necessitates a visual type of sealed penetration if adation is found during the cent inspection, which 21W0080, an electrical use of this damaged seal, an enetration was inspected with penetration 321W0130 was al inspection, this discovery the review process of the , no repair of penetration and 321W0080 were not ersonnel error by maintenance
	- Figure 1 depicts the chronol	ogical order of the	se events.

NRC Form 366A (9-83)

LICENSEE EVENT R	EPORT	(LER)	TEXT	CONTINUATION
------------------	-------	-------	------	--------------

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

EXPIRES 8/31/86

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)	PAGE (3)				
		YEAR SEQUENTIAL REVISION					
Wolf Creek Generating Station	0 15 10 10 10 1 4 18 12	817-0110-011	0 4 0 0 9				
TEXT (If more spece is required, use additional NRC Form 385A's) (17)		ad an and an and an and an and a second consideration of the second consistence of the second s	and the second sec				

# 2. Fire barrier breaches caused by holes that are not designed penetration closures.

A deficiency identified on February 16, 1987, involved a one-inch diameter hole in the floor slab between the 2000 foot and 2026 foot elevation of the Auxiliary Building [NF]. On December 18, 1986, a corrective work request was initiated to repair several abandoned core drills. At that time, it was not recognized that these deficiencies affected the operability of required fire barriers, and the work request was classified as not requiring a Fire Protection Review. On February 16, when preparing to implement this corrective work request, construction personnel questioned the Fire Protection Specialist concerning this classification. Upon review, it was determined that one of the core drills in the floor slab of the 2026 foot elevation of the Auxiliary Building constituted a breach of a required fire barrier. A fire watch of the affected area was promptly established.

On February 19, 1987, a deficiency involving a hole approximately 2 inches in diameter in the wall between the 2026 elevation of the Auxiliary Building and the south end of the Turbine Building [NM] was identified. Upon discovery, a fire watch of the area was established, and a corrective work request was initiated to repair the hole.

On March 9, 1987, it was discovered that an approximate two inch diameter penetration, believed to be an abandoned conduit, existed in the east wall of Room 3416, Access Control and Electrical Equipment Air Conditioning Units Room Number 2, on the 2016 foot elevation of the Control Building. This condition represented a breach of a required fire barrier between adjacent fire zones. A fire watch of the area was promptly established and a corrective work request was initiated to grout the penetration.

The exact time when these three holes through concrete were made could not be identified. It is assumed that the conditions have existed since before receipt of the facility operating license.

RC Form 366A

NRC Form 366A (9-83)	REPORT	EPORT (LER) TEXT CONTINUA								UATION APPROVED C EXPIRES 8/									MB NO. 3150-0104							
FACILITY NAME (1)	ak na kana kana kana kana kana kana kan	NEW YORK WATCH WATCH WATCH WATCH AND A CONTRACT AND					DOCKET NUMBER (2)						LER NUMBER (6)									PAGE (3)				
												YE	AR		SEQU	MBE	ALR		REVI	SION					In Second or product	
Wolf Creek	Generating	Station		0	5	0	10	0	14	18	12	8	7		0	1	0	-	0	1	0	15	OF	0	19	

## 3. Personnel errors involving failure to comply with fire protection procedures.

On February 19, 1987, at approximately 1545 CST, a deviation from fire protection procedural requirements was discovered. During the review and close-out cycle of a corrective work request package, it was determined that copies of necessary Fire Protection Impairment Control Permits were not included in the package. Fire Protection Impairment Control Permits are utilized to track fire protection impairments and to establish the necessary precautions (e.g., fire watch) when an impairment is planned or discovered. A review of both the Fire Impairment Logs and Fire Protection Impairment Control Permits revealed that the proper permits had not been obtained to complete the activities associated with this corrective work request. During performance of this work, a total of seven T/S required penetrations were breached and then resealed by construction personnel during the month of April, 1986. Following discovery of this T/S violation on February 19, the affected areas were inspected and it was verified that the penetrations had been properly re-sealed.

On March 4, 1987, a Nuclear Regulatory Commission Resident Reactor Inspector identified that Fire Door 34031 was blocked open by a hose but did not have a Fire Impairment Control Permit. The Control Room was notified of the situation, and informed that the door should be closed. Investigation revealed that construction personnel had opened the door and placed a hose through it while performing a Corrective Work Request without first obtaining a fire permit. A previous similar occurrence is discussed in Licensee Event Report 86-050-00.

On March 11, 1987, during an inspection by the Fire Protection Specialist, penetration 321W0091 was identified as breached. Following this discovery, a fire watch was established and a corrective work request was initiated to seal the penetration. An investigation revealed that a video camera cable had been run through this penetration in Fall, 1986, by Health Physics personnel without first obtaining a Fire Impairment Control Permit.

These events occurred as a result of cognitive personnel error by personnel who failed to obtain the proper Fire Impairment Permits when rendering a fire barrier inoperable. These errors are contrary to administrative procedures governing Fire Protection Impairment Control. Upon discovery of each breached fire barrier, immediate corrective actions were taken in accordance with T/S Requirements.

Construction craft personnel have been retrained on the requirements of the administrative procedure governing Fire Protection Impairment Control. In addition, the administrative procedure has been added to required reading for Health Physics personnel as a reminder of the Impairment Control Requirements.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION														
FACILITY NAME (1)	DOCKET	NUMBER	4 (2)		-	and an and a state of the	LEP	NUM	BER (6		1	os substant	PAGE	3)
					t	YEAR		SEQUE	NTIAL	RN	EVISION UMBER		TI	
Wolf Creek Concreting Station	0 15	0.10	101	1181	2	817		01	110		011	016	OF	010
TEXT IN more space is required, use additional NRC Form 306A's) (17)		010	10	40	6	017		U	10		5 1 1	010	1-1	019
LONG-TERM CORRECTIVE ACTIONS AND S	SUBSE	QUEN'	T D	ISCOV	ERI	ES								1
Internal Operations Program Defici- to provide a systematic review and program. Initially, the correctiv- the following:	iency d upg ve ac	(IO) rade tion	PD) of s pl	87-Ø key Lanne	l w ele d a	as d ment s pa	leve ts c art	of	bed the the	in 1 fir IO	March e pro PD in	n, l otec nclu	987 tion ded	
<ol> <li>Review and revision of the 1 (STS MT-026) for inspection criteria.</li> </ol>	rechn of f	ical ire	Spe barı	ecifi riers	cat to	ion ent	sur nanc	vei ce s	llla spec	nce ific	prox c ins	cedu spec	re tio	n
2. Train inspection personnel of	on the	e rev	vise	ed in	spe	ctic	on c	crit	eri	a.				
<ol> <li>Conduct an inspection of all any discrepancies are expedi</li> </ol>	l des itiou	ign sly d	fire	e bar ected	rie d.	r pe	enet	trat	ion	s ai	nd er	nsur	9	
4. Label all Technical Specific may be clearly identifiable	catio durin	n fi ng fi	re k utur	barri e ins	er spe	pene ctic	etra	atic	ons	so t	chat	the	Y	
During the inspection of design finspection criteria of STS MT-026, penetrations were rejected for var damaged damming boards. As a prece established in safety related area evaluation and rework activities w	ire ba a nu cious cautic as of were p	arrie umber reas onary the proce	er p r of sons y me pow eedi	benet sil: s, pr easure ver b ng.	rat icon ima e, loc	ions ne R rily fire k wh	s ut TV du wa nile	foa foa ne t ntch e fu	zin m s o m es irth	g th eal iss: were er i	ne re ing c inspe	evise or ectio	ed	
Subsequently, while reworking the with silicone RTV foam seals were and extent of these problems, a Ta disciplines was established to dev Task Force temporarily halted insp corrective measures which included seal inspections per IOPD 87-01 an development of rework plans.	disc ident ask Fo velop pectio I, in ad an	repar tifie orce an e on ar part eval	nt p ed. enha nd r t, a luat	Deneti In composed inced rework in exp ion composed	rat orde d o con k ac pans of c	ions er t f pe crec ctiv sion curr	o d ersc tiv iti of ent	addi lete onne es th se	tio rmin ctio and e so al	nal rom on p est cope	prot the n vari alan. abli of nolc	olems atur ous Th shed foan gy f	a ne 1 for	

.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOG	DOCKET NUMBER (2)							-		LE	RNL	MBE	R (6)		-						
									YE	A R		SEQ	UENT	R		NUM	BER					
Wolf Creek Generating Station	0	5	10	10	10	14	18	12	8	7		0	11	0		01	1	0	17	OF	0	19
TENT IN many superior is and deal use additional ADP From Set 4/1/191	COLUMN PROPERTY OF	-	-			-dectro			here's and		diam served	Bernet weather	Concession of		Acore							

An inspection of foam seals involving removal of the damming boards was performed starting on May 5, 1987. This inspection of forty (40) accessible randomly selected penetrations resulted in thirteen (13) seals rejected for insufficient foam depth and nine (9) seals rejected for voids or shrinkage. Based upon an Engineering evaluation of the materials and installation procedures, repair of the deficient seals with silicone RTV foam has been determined to be acceptable, with stringent inspection of the cured foam product behind all damming boards and sample selection of the repaired seal population for future surveillance inspections. Alternate materials for new and replacement penetration seals will be evaluated for use as enhancements to the existing design. An expanded corrective action plan including the inspection of foam seals, involving the removal of the damming boards, is now planned as part of IOPD 87-01. Upon conclusion of all corrective actions, currently projected as the end of 1987, a summary report will be provided in a supplement to this Licensee Event Report.

#### ANALYSIS OF EVENTS

RC Form 366A

Each breached fire barrier penetration and failure to comply with fire protection procedures represents a potential path for heat and products of combustion to be transmitted to adjacent fire zones. However, each safe shutdown area is served by the Fire Detection System, which would have generated an alarm in the Main Control Room had a fire occurred in any one of these areas. Additionally, fire watches have been establihsed in safety related areas of the power block. A previous similar occurrence of a breached penetration seal is discussed in Licensee Event Report (LER) 87-001. At the time LER 87-001 was originally prepared, the situation was believed to be an isolated case. A revision to LER 87-001 was submitted on March 24, 1987.







Bart D. Withers President and Chief Executive Officer

July 8, 1987

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

> Letter: WM 87-0183 Re: Docket No. 50-482 Subj: Licensee Event Report 87-010-01

Gentlemen:

The attached Licensee Event Report (LER) is submitted pursuant to 10 CFR 50.73 (a) (2) (i) concerning a Technical Specification violation. This report is a revision to LER 87-010-00 which was submitted March 18, 1987.

Very truly yours,

Bart D. Withers Presient and Chief Executive Officer

BDW: jad

Attachment

cc: PO'Connor (2) RMartin JCummins

IE22