(9-83)	366																U	.S. NI	JCLE	ARA	REGU	LATO	RY COM	MISS	ION
										O. 3150-	0104														
FACILITY	NAME (1	1)	NAMES AND ADDRESS OF TAXABLE PARTY.												De	OCKE	TNU	IBER	(2)				PA	GE (3	3)
Sequ	oyah,	, Uni	t 2												0	)   5	510	10	10	13	312	18	1 0	FO	14
TITLE 14 Read	tor '	Trip	Signa	ls Ge	enera	ted Fr	rom	Ele	ctrom	agne	ti	c Int	erf	ere	nce	Ca	use	d	Bv	We	1d	ing			
Acti	vity	Adja	icent	To So	ource	Range	e Nu	iclea	ar In	stru	me	nt Ca	bli	ng					~ ,			0			
EVE	EVENT DATE (5) LER NUMBER (6) REPORT DATE (7) OTHER FACILITIES INV										INVO	VOLVED (8)													
MONTH DAY YEAR YEAR SEQUENTIAL REVISION MONTH DAY								YEAR	_		FA	CILIT	YNAM	ES			DOCKET NUMBER(S)								
											0	15	10	10	0	1	1								
0 2	1 2											0	15	10	10	0	1	1							
OPE	RATING		THIS REP	PORT IS S	UBMITTE	D PURSUA	NT TO	THE R	EQUIREM	ENTS OF	10	CFR 8: /0	Chack o	one or	more of	f the	fallowi	ng) (1	1)						
		10	20.0	402(b)		-		20.405(	c)			XX	50.7	3(a)(2	(iv)				-	- 7	3.71(b	1)			
LEVE		0.0	20.	405(a)(1)(		-		50.36(c)	1(1)			-	50.7	3(8)(2	(wiii)				-	- '	3.71(0	1 /500	ite in A	hetrac	
1101	·····		20.	405(a)(1)(	111)	1		50.73(#	)(2)(i)			-	50.7	3(a)(2	(viii)(A				-	1 0 3	BIOW B	ind in	Text, NI	C FO	irm
			20.	405(a)(1)(	(w)			50.73(a	)(2)(ii)				50.7	3(a)(2)	(viii)(B)	)									
			20.	405(a)(1)(	v)			50.73(a	)(2)(iii)				50.7	3(a)(2	(x)										
	******						LIC	ENSEE	CONTACT	FOR TH	115 1	LER (12)													And the second second
NAME																-		0.0.0	TEI	LEPH	ONE	NUMB	ER		
																A	MEAC	300							
T. F	. Phi	iter,	Plan	t Rep	porti	ng Sec	ctic	n								16		15	8	14	13	-	715	18	15
				CC	OMPLETE	ONE LINE	FORE	ACH CO	OMPONEN	TFAILU	RE	DESCRIBE	DIN	THIS P	REPORT	1 (13)			T						
CAUSE	SYSTEM	COMP	ONENT	TUP	JFAC- RER	TO NPRI	DS			CAU	SE	SYSTEM	co	MPON	ENT	N	TURE	AC- R	F	TO	NPRD	LE S			
	1	1			11		_	******					1	1	1			1	_			-			
			11									1	1	1	1			1			_			_	
				1	SUPPLEM	ENTAL REP	PORTE	XPECTI	ED (14)							-	E×	PECT	ED		MO	NTH	DAY	YE	EAR
YE	s (If yes, c	complete l	XPECTED	SUBMISS	ION DATE	E/		x	X NO								SUE DA	TE (	10N 15)			1	1		1
ABSTRA	At sou act was pro gen cou ass int com sou can tri att ele the and wil noi Wes	to 1400 m 0021 rce m uate in m gress erate ld no istan- erfer monen rce m erfer rce m erfer istan- rce m istan- rce m istan- istan- rce m istan-	EST, range the h mode ( s. At e two ot hav nt shi rence nt cool could se suf gnal ( ted to magnet urrence ety of quire nterfo	on F (SR) high- b at 003 more ve be ift o and oling not ffici on SR o the tic, ce of f the long erenc NIS	ely filteen ebrua char flux the t 0 EST reac en ca perat found wate be lo ent e inst susc and f these -terr e. T	ary 12 anel N trip time o f and tor t aused tions d weld er sys ocated electr trumen ceptib freque se eve eral p m syst This w Gamma	, 14 -31 bis f tl aga rip by sup ting ttem l for coma ttat billi ency ents bubl 	989, rectabl he e in a sig an a ervi hea r th gnet ion, ty o int had be tric	unit eived e and event, it 003 nals. ctual sor a progra t exe tic in The of the cerfer i no s Redu lware accor cs equ	2 N a s alt alt alt alt alt alt alt alt alt alt	int int int int int int int int int int	lear ke of ate a ough r char se spi ase i ase i ted to the rs. I t is rence cause lesign that of SI es to ed by	Ins f su a re no ( nne) ikes in r b ic Aux Alth we! (EN e of n to eres adv R the read	stru each cord l N. s W neu den xil hou; l1 () f t o e for ver rip duc e u;	umen icie tor e al -31 ere tron tify jary gh t to to to he S lect e, i se a sig e sy pgra	ta tre sp of f the mee ge SR tro it aff ade	tion ma ip rat ike a lux he uil ac en spi sta is ect ls em of	n S gni sig d H nat sou d fr tua d t kir cor cau sus	ys tu na is ing in that is ang is in that is is is is is is is is is is is is is	ter de l. we by vo tr is ud he ter tr et ter tr et ter tr et ter ter	m ( to Ure enoo whi uni of ch lta wel eac ed he by ibi	NIS nit in ugh ch t 2 the ge dir tor that alt noi lift	at to a to a b s s s t t h s e s y to	5	
	00.P.00	9031 DR	7012 ADOCI	0 89 K 05	0309 0003 PD	28	9												1	R	2.	2		9	

NRC Form 366A (9-83)	ENT REPORT (LER) TEXT CONTINU	JATIO	N	U.S.	AP EX	PROVED C	MB N	TORY CO 10. 3150-1	MMISSIC 0104	N
FACILITY NAME (1)	DOCKET NUMBER (2)		L	ER NUMBER (6	)		PAGE (3)			
		YEAR		SEQUENTIAL		REVISION		T		-
Sequoyah, Unit 2	0 5 0 0 3 2 8	8 9	-	0 0 1	_	0 0	0	2 OF	014	
TEXT (If more space is required, use additional NRC Form 366A's) (	17)									

## DESCRIPTION OF EVENT

On February 12, 1989, at 0021 EST with unit 2 in mode 6 (0-percent power, 0 psig, 92 degrees F), a reactor trip signal was generated by the reactor protection system (EIIS Code JC) from the source range (SR) nuclear instrument (EIIS Code IG) high-neutron flux trip.

At 0021 EST, on February 12, 1989, unit 2 Nuclear Instrumentation System (NIS) SR channel N-31, received a spike of sufficient magnitude to actuate the high-flux trip bistable (100,000 counts per second) and to generate a reactor trip signal. Unit 2 was in mode 6 (refueling) at the time of the event, although no core alterations were in progress. At 0030 and again at 0039, channel N-31 spiked high enough to generate two more reactor trip signals. Prior to this event, fuel movement had been suspended due to the fuel transfer system being out of service. The unit 2 operators concluded that the signals were not the result of an actual neutron flux increase due to a normal reading on channel N-32 and the abnormal shape of the spike on channel N-31. The unit 2 assistant shift operations supervisor (ASOS) identified a potential source of the interference as welding in progress in the Auxiliary Building, which is common to both Sequoyah units, on elevation 714 by the component cooling water system (CCS) (EIIS Code CC) heat exchangers. The welders stopped work, and as a preplanned sequence, struck an arc to check the effect on NIS SR instrumentation. Only very small spikes occurred on channel N-31 and slightly larger spikes were noted on channel N-32, but these were not large enough to cause a reactor trip signal. The ASOS also noted that personnel were changing the eddy current probe for steam generator No. 4 activity inside the unit 2 containment at the time of the event.

### CAUSE OF EVENTS

The SR high-flux reactor trip signals that occurred on February 12, 1989 were caused by noise induced into the unit 2 SR channel N-31 cabling that resulted in exceeding the high-flux reactor trip setpoint monitored by the reactor protection system (RPS). The noise was apparently caused by welding at a high frequency in the vicinity of the unit 2 SR cabling.

The root cause of the SR spiking is attributed to the high noise susceptibility of the NIS design to electrostatic, electromagnetic, and radio frequency interferences. The SR is particularly sensitive to noise interference because it has a low-level pulse signal that is transmitted over long lengths of cabling--from the detectors mounted in containment to the preamplifier mounted outside containment and on to the nuclear instrument cabinet located in the main control room.

Although the actual voltage source could not be located for this event, it is well documented that welding can cause sufficient electromagnetic interference (EMI) to generate a reactor trip signal on SP instrumentation. Even such devices as heat guns (when operated in close proximity to the detector cables) have been shown to cause some affect on the SR channels.

NRC Form 366A (9-83)	/ENT REPORT (LER) TEXT CONTINU	JATIO	N	U.S	APP EXP	ROVED O	MB NO. 3	Y CO	MMISS 0104	ION	
FACILITY NAME (1)	DOCKET NUMBER (2)	DOCKET NUMBER (2)						PAGE (3)			
		YEAR		SEQUENTIAL		NUMBER		T			
Sequoyah, Unit 2	0 5 0 0 3 2 8	8 9	_	0 0 1	_	0 0	0 3	OF	0	4	

### ANALYSIS OF EVENT

This report is submitted pursuant to the requirements of 10 CFR 50.73, paragraph a.2.iv, as a condition that resulted in an automatic actuation of the RPS. The NRC Operations Center was notified of the reactor trip signals on February 12, 1989, at 0351 EST pursuant to 10 CFR 50.72, paragraph b.2.ii.

The RPS is provided with a SR high flux reactor trip signal to ensure that a controlled power increase into the "power range" is maintained. The SR trip is provided to ensure the operators maintain control of the reactor power increase during a startup by monitoring the reactor neutron count rate and generating a reactor trip signal when required. This is implemented by two SR excore detectors and backed up by two intermediate-range excore detectors that monitor the core neutron level. If either detector provides a signal to the RPS that is above the setpoint limit (manually blocked for a controlled power increase), a reactor trip will occur to shutdown the reactor. During these events, however, the SR signal was not a result of a high neutron count rate, but a result of noise induced in the SR cabling of sufficient magnitude to exceed the reactor trip setpoint. Reactor trip breaker actuation did not occur during these events because they were already open. The reactor trip logic responded correctly by providing a reactor trip signal as the noise induced in the cabling exceeded the trip setpoint. Therefore, it is concluded that the occurrence of these events had no adverse affect on the health and safety of the general public.

## CORRECTIVE ACTION

Immediate operator action was to confirm the trip signal was not the result of neutron monitoring. Subsequent operator actions were to suspend any suspect welding activities in the containment and initiate troubleshooting to locate the noise source.

Interim recurrence control was a small adjustment of the discriminator operating bias point for the SR channel to a higher setting to provide greater discrimination against unwanted background noise and gamma signals while still ensuring proper neutron flux monitoring. This change allows for greater channel reliability by reducing relative noise susceptibility. Additionally, due to noise problems on both SR channels during previous unit outages, coupling capacitors were added between the preamplifiers and ground to eliminate increased noise levels occurring during outages. Design change request 3078 was written to insulate the SR cable/detector from the source/intermediate range detector housing. The existing design has the SR and intermediate-range outside cable shields tied together at the detectors and at the instrument drawers in the control room. This results in a ground loop and a system that is more

Reduction of SR trip signals caused by noise will require long-term system hardware changes to reduce system susceptibility to noise interference. This

NRC / orm 366A (9-83)	NT REPORT (LER) TEXT CONTINU	ATIO	N	U.S	API EXF	PROVED C	MB N	O. 311	COM	104	SION
FACILITY NAME (1)	DOCKET NUMBER (2)		LE	R NUMBER (	5)	and the state is the strategy of the		PA	GE (	3)	
		YEAR		NUMBER		NUMBER					
Sequoyah, Unit 2	0 5 0 0 3 2 8	8 9	_	0 0 1	-	010	0	4	OF	0	4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

will be accomplished by the upgrade of the existing Westinghouse NIS with Gamma-Metrics equipment. This upgrade is scheduled during the cycle 4 outages for both units. Although the Gamma-Metrics NIS is being installed to meet Regulatory Guide 1.97 postaccident monitoring requirements, its installation should reduce many of the problems caused by noise interference. These problems should be mitigated because the Gamma-Metrics equipment offers enhanced system design features by employing techniques to minimize system noise susceptibility.

## ADDITIONAL INFORMATION

There have been three previously reported occurrences of reactor trip signals generated from SR detectors as a result of EMI - SQR0-50-327/82131, /88019 and /88022.

## COMMITMENTS

Reference LER 327/88019 for installation of the Gamma-Metrics system.

0191R

# TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant Post Office Box 2000 Soddy-Daisy, Tennessee 37379

March 9, 1989

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 2 - DOCKET NO. 50-328 - FACILITY OPERATING LICENSE DPR-79 - LICENSEE EVENT REPORT (LER) 328/89001

The enclosed LER provides details concerning a nuclear instrumentation source range (SR) reactor trip signal generated by electromagnetic interference from welding activity adjacent to SR cabling. This event is reported in accordance with 10 CFR 50.73, paragraph a.2.iv.

my laturk S./J. Smith Plant Manager

Enclosure cc (Enclosure): J. Nelson Grace, Regional Administrator U. S. Nuclear Regulatory Commission Suite 2900

> 101 Marietta Street, NW Atlanta, Georgia 30323

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, Sequoyah Nuclear Plant

1572