NRC Form 366 (9-83)	CLEAR REGULATORY COMMISSION APPROVED OMB NO. 3160-0104 EXPIRES: 8/31/86											
FACILITY NAME (1)	ana	an Priston State Anna Priston	and an interface of the sector sector of the sec				DOCKET NUMBER	1 (2) PAGE (3)				
Beaver Valley	Power Stati	on, Un	it 2				0 5 0 0	10 4 11 2 1 OF 01 3				
TITLE (4)	Due te a le	In Low	al Conditi	on in	the	21D Stop	Concept	and an early an early and a second				
Reactor Irip	Due to a Lo-	-TO Teve	er condici	on in	the	ZID SLEA	u General	10.				
EVENT DATE (5)	FACILITIES INVOLVED (8) MES DOCKET NUMBER(S)											
MONTH DAT TEAM TE	UNTH DAY YEAR YEAR NUMBER NUMBER NUMBER MONTH DAY YEAR FACILITY NAMES											
				. 1		N/A						
1 0 2 9 8 7 8	7 d 3 4	00	1 1 3 0	8 7		N/A		0 5 0 0 0 0				
OPERATING 1 THI	S REPORT IS SUBMITTED	PURSUANT	TO THE REQUIREME	NTS OF 10	CFR \$: (6	Check one or more	of the following) (1	(1)				
MODE (B)	20.402(b)		20.405(c)		X	60.73(a)(2)(iv)		73.71(b)				
LEVEL 0.0.8	20.406(a)(1)(i)		50.36(c)(1)			60.73(a)(2)(v)	73.71(c)					
	20.405(a)(1)(iii)		50 73(e)(2)(i)		Channa and	50.73(a)(2)(viii)	(4)	below end in Text, NRC Form				
	20.406(a)(1)(iv)	-	50.73(e)(2)(ii)			50.73(a)(2)(viii)	(8)	5000				
	20.405(a)(1)(v)		50.73(a)(2)(iii)			50.73(a)(2)(x)						
**************************************	L	1	ICENSEE CONTACT	FOR THIS	LER (12)	L		A				
William S. La	cey, Plant M	lanager					AREA CODE	TELEPHONE NUMBER				
	COMPLETE	ONE LINE FOR	EACH COMPONENT	FAILURE	DESCRIBE	D IN THIS REPOR	RT (13)	1.01.41.21-1.11.21.218				
CAUSE SYSTEM COMPONEN	IT MANUFAC- TURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPRDS				
X SIM LICIV	M 1 2 0	N										
YES (If yes, complete EXPEC ABSTRACT (Limit to 1400 spaces,	SUPPLEME TED SUBMISSION DATE (a. approximately fifteen (NTAL REPORT	EXPECTED (14)			· · ·	EXPECT SUBMISS DATE (1	ED ION 5)				
On 10/29 erratic Operatio dispatch "B" 5th Pump and At 0145 flow. A unsucces increase At 0145 emergenc trip on operator Operation response I&C pers LCVs. T proper co Operatic safety i type of	/87 at 013 level swin ns and Ins ed to inve Point Heat Main Feed hours, Con start att sful. The s and heat hours, the y shutdown Lo-Lo Leve s stabiliz of the "F onnel adju the other I operation. ons personn mplication event was 30407 8711 ADOCK 0500	5 hour gs in trumer stigat er isc water idensat empt of er isc er er isc er isc er er isc er er isc er er isc er er isc er er e	rs, with the "B" ht & Cont te. At (olated or Pump (MH te Polish on the 21 5th Point olations MFP tripp commenced the 21B S e plant s The cause n the respond the respond the respond the respond the respond the publ ously an	the 5th rol 142 n ext P) P 1C Co theat in to bed of theat in to bed of stear in HO eater ve gut t of ic as alyzo	plan Poin (I&C hour reme bertu was onder the e on loo of the training this s a n ed in	nt at 98 ht Heate c) perso cs, extre- high I irbation bypasse hsate Pu- isolat: entire ' bw suct: er at 0: herator TANDBY ' is even vel Con- the "B" in were nce has s event result n FSAR	3% react er were onnel we faction level. hs were ed to im ump was ion caus "B" heat ion pres 147 hour occurre using th t was in trol Val 5th Poi also ch been pr . There of this 15.2.7.	cor power, observed. ere steam to the Heater Drain also noted. mprove MFP sed level ter train. ssure. An rs, a reactor ed. The he Emergency mproper lves (LCV). int Heater hecked for rovided to e were no event. This				

URC Form 386A	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION										
FACILITY NAME (1)	DOCKET NUMBER (2)		LER	NUMBER (8)	BER (8)			PAGE (3)			
Beaver Valley Power Station, Unit 2		YEAR	5	NUMBER	REV	SION		T			
	0 5 0 0 0 411	2 81 7		0314	- 0	0	012	OF	03		

TEXT (If more space is required, use additional NRC Form 388A's) (17)

On 10/29/87 at 0135 hours, with the plant in POWER OPERATION (Operational Mode 1) at 98% reactor power, erratic level swings in the "B" 5th Point Heater were observed with accompanying high and low level alarms. Operations personnel and Instrument & Control (I&C) personnel were dispatched to investigate and restore proper level operation. At 0142 hours, extraction steam to the "B" 5th Point Heater isolated on extreme high level. At this time, Heater Drain Pump motor amps were observed swinging and Main Feedwater Pump (MFP) suction pressure was observed to be low. At 0145 hours, the Condensate Polishing System was bypassed to allow more condensate flow to the MFPs to improve main feedwater flow. A start on the 21C Condensate Pump was attempted, however, this attempt was unsuccessful because the Condensate Pump motor breaker was not fully racked in on its electrical bus. The "B" 5th Point Heater isolation caused increased cooling and condensation in the other heaters in the "B" heater train, subsequently resulting in isolations of the "B" 4th Point, 3rd Point, 2nd Point and 1st Point heaters. At 0145 hours, the 21A MFP tripped on low suction pressure. The 21A MFP was restarted, but tripped within 10 seconds on low suction pressure. An emergency shutdown in accordance with Abnormal Operating Procedure (AOP) 2.51.1 "Emergency Shutdown" was commenced. At 0147 hours, a reactor trip on Lo-Lo Level in the 21B Steam Generator occurred as a result of the decrease in main feedwater flow. The Auxiliary Feedwater System actuated and the operators utilized the Emergency Operating Procedures to stabilize the plant in HOT STANDBY (Operational Mode 3).

The cause for this event was attributed to improper response of the "B" 5th Point Heater Level Control Valves (LCV) [High Level Control Valve: 2HDL-LCV124B1, Masoneilan Model 12810 and Normal Level Control Valve: 2HDL-LCV124B2, Masoneilan Model 12830]. I&C personnel have adjusted the response of the LCVs for proper level control. These corrective actions were verified during the subsequent plant startup. The other LCVs in the "B" Heater Train were also checked and adjusted as necessary. Proper operation of these valves was also verified during the subsequent plant startup. The cause for the failure of the 21C Condensate Pump to start was due to the breaker not being fully racked in the 4160V Bus. The cause for the trip of the 21A MFP after it was started following the initial trip, was due to the continued presence of the low suction pressure trip signal. The attempt to improve feedwater flow by bypassing the Condensate Polishing System was unsuccessful because of mechanical problems with the Condensate Polishing Bypass Valve [2CNM-DCV100], which were subsequently identified on 11/10/87 and will be detailed in a future LER. This valve was subsequently replaced.

19-631 LICENSEE EVEN	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION													U.S. N	J.S. NUCLEAR REGULATORY COMMISSI APPROVED OMB NO 3150-0104 EXPIRES 8/31/85						
FACILITY NAME (1)		DOCKET NUMBER (2)							LER NUMBE					R (6)			PAGE (3)				
Beaver Valley Power Station, U	nit 2									YEAR	1	SEQUENTI		AL	1	NUMBER					
		0	15	10	10	0	14	111	2	81	1-	0	13	4	_	do	d	OF	013		

As a result of this event, in addition to the corrective actions listed above regarding the "B" Heater Train Level Control Valves, administrative guidance has been provided to the Operations shifts. This administrative guidance consists of two Special Operating Orders (SOO) requiring the operators to: 1) set up the EHC System to run the turbine back sufficiently to sustain operation on one MFP trip and to start the Startup Feed Pump (2FWS-P24), if a MFP trips, and 2) "bump" the associated piece of equipment every time a breaker is racked off and racked back on a bus, to ensure availability for operation (if plant conditions do not permit the "bumping", a caution tag will be placed on the control switch for the associated equipment indicating that the equipment has not been functionally checked). This second SOO will be in effect until permanent incorporation into the Switching Procedures.

There were no safety implications to the public as a result of this event. This type of event has been previously analyzed in FSAR Section 15.2.7 "Loss of Normal Feedwater Flow". The Auxiliary Feedwater System actuated on the Lo-Lo Level condition in the 21B Steam Generator in accordance with the system design to maintain a heat sink for decay heat removal.

There have been six (6) previous reactor trips which were initiated by Lo-Lo level conditions in one seam generator or by a Low Level condition coincident with a steam flow/feed flow mismatch.



Telephone (412) 393-6000

Nuclear Group P.O. Box 4 Shippingport, PA 15077-0004

> November 30, 1987 ND3SPM:0103

Beaver Valley Power Station, Unit No. 2 Docket No. 50-412, License No. NPF-73 LER 87-034-00

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 87-034-00, 10 CFR 50.73.a.2.iv, "Reactor Trip Due to a Lo-Lo Level Condition in the 21B Steam Generator".

Very truly yours,

Wm. S. Lacev Plant Manager

tlu

Attachment

November 30, 1987 ND3SPM:0103 Page two

cc: Mr. William T. Russell Regional Administrator United States Nuclear Regulatory Commission Region 1 King of Prussia, PA 19406

C. A. Roteck, Ohio Edison

Mr. Peter Tam, BVPS Licensing Project Manager United States Nuclear Regulatory Commission Washington, DC 20555

J. Beall, Nuclear Regulatory Commission, BVPS Senior Resident Inspector

Mr. Alex Timme, CAPCO Nuclear Projects Coordinator Toledo Edison

INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

G. E. Muckle, Factory Mutual Engineering, Pittsburgh

Mr. J. N. Steinmetz, Operating Plant Projects Manager Mid Atlantic Area Westinghouse Electric Corporation Energy Systems Service Division Box 355 Pittsburgh, PA 15230

American Nuclear Insurers c/o Dottie Sherman, ANI Library The Exchange Suite 245 270 Farmington Avenue Farmington, CT 06032