

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) BIG ROCK POINT PLANT										DOCKET NUMBER (2) 0 5 0 0 0 1 5 5										PAGE (3) 1 OF 2									
TITLE (4) REACTOR TRIP CAUSED BY FAILURE OF INTERMEDIATE RANGE NEUTRON MONITORING CHANNEL																													
EVENT DATE (5)						LER NUMBER (6)						REPORT DATE (7)						OTHER FACILITIES INVOLVED (8)											
MONTH		DAY		YEAR		YEAR		SEQUENTIAL NUMBER		REVISION NUMBER		MONTH		DAY		YEAR		FACILITY NAMES											
																		N/A											
1 1		2 3		8 7		8 7		0 1		2 0		0 1		2 1		0 8		7		N/A									
OPERATING MODE (9) N						THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)																							
POWER LEVEL (10) 0 0 0						20.402(b)						20.405(a)						<input checked="" type="checkbox"/> 80.73(a)(2)(iv)						73.71(b)					
						20.405(a)(1)(i)						80.39(a)(1)						80.73(a)(2)(v)						73.71(a)					
						20.405(a)(1)(ii)						80.39(a)(2)						80.73(a)(2)(vi)						OTHER (Specify in Abstract below and in Text, NRC Form 300a.)					
						20.405(a)(1)(iii)						80.73(a)(2)(i)						80.73(a)(2)(vii)(A)											
						20.405(a)(1)(iv)						80.73(a)(2)(ii)						80.73(a)(2)(vii)(B)											
20.405(a)(1)(v)						80.73(a)(2)(iii)						80.73(a)(2)(iii)																	
LICENSEE CONTACT FOR THIS LER (12)																													
NAME R J Alexander, Technical Engineer																TELEPHONE NUMBER 6 1 6 5 4 7 - 6 5 3 7													
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																													
CAUSE		SYSTEM		COMPONENT		MANUFACTURER		REPORTABLE TO NRC				CAUSE		SYSTEM		COMPONENT		MANUFACTURER		REPORTABLE TO NRC									
B		I G		A M P G O 8 0 N																									
SUPPLEMENTAL REPORT EXPECTED (14)																EXPECTED SUBMISSION DATE (15)		MONTH		DAY		YEAR							
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)																<input checked="" type="checkbox"/> NO													

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On November 23, 1987 plant startup was in progress following a planned maintenance outage. At 0350 hours, an intermediate range neutron monitoring channel failed upscale causing a short period reactor trip. Power level at the time of the trip was less than 10E-6 percent during an approach to critical. All control rods withdrawn at time of the trip successfully inserted. Cause is attributed to amplifier electronic tube failure due to age.

Following change-out of the amplifier and testing, restart commenced.

This is not considered a reactor trip while critical per INPO reporting criteria.

8712140315 871210
PDR ADOCK 05000155
S DCD

IE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
BIG ROCK POINT PLANT	0 5 0 0 0 1 5 5	8 7	— 0 1 2	— 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Description

On November 23, 1987 plant startup was in progress following a planned maintenance outage. At 0350 hours during an approach to critical, an intermediate range neutron monitoring channel (IG) failed upscale causing a short period channel trip. This short period trip (one out of two logic) initiated a reactor protection system (JC) actuation causing a reactor trip. Power level at the time of the trip was less than 10E-6 percent. All control rods (AA) withdrawn at the time of the trip successfully inserted and no other engineered safety features were challenged by the event.

Cause

The cause of the trip is attributed to the failure of a General Electric (G080) intermediate range logarithmic amplifier, Model 105X339G1.

Corrective Actions

Following the trip, the failed logarithmic amplifier was replaced with a spare, tested and channel returned to service. Coupling integrity checks were performed on the control rods and a restart commenced at 1300 hours. Investigation and repair activities of the failed amplifier concluded a failed electrometer tube due to normal in use degradation. Following replacement of the tube the amplifier was calibrated, tested and returned to stock to be used as a spare.

Actions to Prevent Recurrence

Plans are being made to change out the intermediate range neutron channels during the 1988 Refueling Outage to the new General Electric "NUMAC" line. The new components are expected to have a decreased failure rate over the existing tube-type instrumentation in use since 1962. Additionally, the modification will also include an upgrade of the short period "one out of two" logic for reactor trip to a "two out of three" scheme. This will prevent single channel failures from causing a reactor trip and also permit maintenance and testing during reactor operation.

Safety Assessment

There were no adverse safety consequences of this event, since the challenge to the reactor protection system was successful and reactor power was very low.



Consumers
Power

**POWERING
MICHIGAN'S PROGRESS**

General Offices: 1945 West Parnall Road, Jackson, MI 49201 • (517) 788-0550

December 10, 1987

Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

DOCKET 50-155 - LICENSE DPR-6 - BIG ROCK POINT PLANT -
LICENSEE EVENT REPORT 87-012 - REACTOR TRIP CAUSED BY
FAILURE OF INTERMEDIATE RANGE NEUTRON MONITORING CHANNEL

Licensee Event Report (LER) 87-012 (Reactor Trip Caused by Failure of
Intermediate Range Neutron Monitoring Channel) is attached. This event is
reportable to the NRC per 10CFR50.73(a)(2)(iv).

Ralph R. Frisch
Senior Licensing Analyst

CC Administrator, Region III, NRC
NRC Resident Inspector - Big Rock Point Plant

Attachment

IE22
1/1