DUKE POWER COMPANY P.O. BOX 33189

CHARLOTTE, N.C. 28242

HAL B. TUCKER VIGE PRESIDENT NUCLEAR PRODUCTION TELEPHONE (704) 373-4531

December 14, 1987

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: McGuire Nuclear Station, Units 1 and 2

Docket No. 50-369, -370 Special Report Pursuant To

Technical Specifications 3.7.14.a, Commitment and 6.9.2

Gentlemen:

Please find attached a special report concerning a Safe Shutdown Facility wide range pressure transmitter that was determined to be inoperable on November 8, 1987. This report is required to be submitted because the inoperability of the instrument constitutes a missed commitment.

If there are any questions concerning this matter, please contact Steve LeRoy of our Licensing staff at (704) 373-6233.

Very truly yours,

Hal B. Tucker

SEL/186/jgc

Attachment

xc: Dr. J. Nelson Grace
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, GA 30323

Mr. Darl Hood U.S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Washington, D.C. 20555 INPO Records Center Suite 1500 1100 Circle 75 Parkway Atlanta, GA 30339

Mr. W.T. Orders NRC Resident Inspector McGuire Nuclear Station Duke Power Company
McGuire Nuclear Station
Special Report Concerning
Inoperability of Safe Shutdown Facility
Reactor Coolant Wide Range Transmitter

On November 18, 1987 at 1130, Operations found the Safe Shutdown Facility (SSF) Reactor Coolant (NC) system wide range transmitter (1NCLP5121) out of calibration. A work request was written to repair and calibrate the instrument. Instrument and Electrical personnel attempted to calibrate 1NCLP5121 but the transmitter could not be adjusted to within specified tolerance. A research of the work request history for this transmitter revealed this failure to be the first failure of 1NCLP5121.

Because the transmitter is a Foxboro manufactured split architecture type instrument, a replacement transmitter was not available on-site and has been requisitioned, (very few of this type of transmitter are used at McGuire). Expected delivery is the week of December 7, 1987. Upon receipt of the transmitter, it will be installed and calibrated. A loop calibration will also be performed and the transmitter will be returned to service. The replacement transmitter is also being added to station warehouse stocks to ensure availability for any future replacements.

Compensatory measures relating to Technical Specification 3.7.14.a have been performed since the discovery of the inoperable transmitter.

This incident is considered to be of no significance with respect to the health and safety of the public.