•

.

	CARDONAL PLANT INTRODUCTION AND TRANSPORTED INTO AND AND AND AND AND AND AND AND A DATA AND A DATA AND A DATA A				
REPORT NO.: 99901146/89-01	INSPECTION DATE: 3/27 - 3/30/89	INSPECTION ON-SITE HOURS: 48			
CORRESPONDENCE ADDRESS: Square D Company Barbara Sines, Plant Manager 3700 6th Street South West Cedar Rapids, Iowa 52404					
ORGANIZATIONAL CONTACT: MI TELEPHONE N'AMBER: 31	r. M. Douglas, QC Manager 19-365-4631				
NUCLEAR INDUSTRY ACTIVITY:	Molded case circuit breaker	S			
	7				
ASSIGNED INSPECTOR:	Naidu, Reactor Inspection Se 5-1), VIB, DRIS, NRR	ction No.1 Date			
OTHER INSPECTOR(S): H.M. DRIS	Wescott, Special Projects Se	ction, VIB,			
APPROVED BY: E. T. Baker, DRIS, NRR	Chief, RIS-1, Vendor Inspect	ion Branch, <u>6/6/89</u> Date			
INSPECTION BASES AND SCOPE:					
A. BASES: 10 CFR Part	21, 10 CFR 50 Appendix B				
selected areas; obser	mplementation of the quality ved the manufacture and test circuit tests performed on a rcuit breaker.	ing of circuit breakers:			
PLANT SITE APPLICABILITY:	Potentially all reactor site	s.			
8906160106 890614 PDR QA999 EMVSQUAR 99901146 PDC					

-

REP NO.		INSPECTION RESULTS:	PAGE 2 of 9
Α.	VIOLATIONS:		
	None		
Β.	NONCONFORMANCES:		
	None		
с.	STATUS OF PREVIOUS INS	PECTION FINDINGS:	
	Two unresolved items p	ertaining to the Square D (SD), Cedar Rapids, Iowa,

plant were identified during a routine inspection at the SD Peru, Indiana, plant. These two unresolved items are documented in NRC Inspection Report No. 99900367/88-01.

These items could not be resolved in a timely manner prior to the conclusion of the inspection and remain open.

D. OTHER FINDINGS AND COMMENTS:

1. Background Information

Commercial grade molded case circuit breakers (CBs) between the ranges of 3 amperes (A) to 4000 A are manufactured at the Cedar Rapids plant under a quality assurance program compatible in many aspects with the 10 CFR 50 Appendix B requirements. The CBs are furnished to the SD plant located in Peru, Indiana, where the CBs are dedicated for Class 1E applications. SD, Peru, also assembles motor control centers and furnishes them as Class 1E equipment. Spare CBs furnished by SD, Cedar Rapids are dedicated at the SD, Peru facility and supplied as Class 1E equipment. To date, all purchase orders for spare. As have been issued to SD, Peru, who in turn obtained the CBs all ommercial grade items with certificates of conformance from SD, Cedar Rapids. Other SD facilities manufacturing components utilized in nuclear power plants are:

SD Monroe, North Carolina: Transformers up to 5000 kVA with up to 34.5 KV maximum primary voltage SD Raleigh, North Carolina: Electrical contactors and motor

starters

REPORT NO.: 999	01146	5/89-01	INSPE RESUL	CTION .TS:	PAGE 3 of 9
	SD F	Raleigh, North Car	olina:	Electrical relays	
	SD A	Ashville, North Ca	rolina:	Electrical relays	
	The SD Cedar Rapids, Iowa, plant utilizes approximately 26,000 square feet and employes 800 persons. This facility has its own electrical generator to produce the necessary voltage and current to conduct short circuit tests on low and medium voltage CBs.				its own current
2.	Plar	nt Tour			
		inspectors, accoming facility and o		by SD personnel, toured the m the following:	anufac-
	a.		ents. F	vere conducted by individuals Procedures, with acceptance c vorkstation.	
	b. Every CB was subjected to final tests.				
	c.			vendors were properly identi aspections were readily disce	
	d.	All items stored	were ad	dequately identified.	
3.	Revi	iew of Control of	Purchase	ed Material	
	rece subs matc trar denc The	eipt. The transac sequent relevant r brials at the rece saction numbers, oting incomplete i inspectors noted	tion num ecords. iving an receipt nformati the rele	receive a "transaction" numb mber is the link to trace all The inspectors observed tha rea were identified with eith inspection reports or red ta ion to perform receipt inspec evant information on the foll reviewed the relevant documen	the t all er gs tion. owing
	ā.	Kreider Corporat switch actuators	ion, Spr identif 9081139.	5002279, dated January 31, 19 ringfield, Ohio, for the supp fied as Part No. 48117-096-04 . The items had been inspect	ly of
	b.	SD PO 6002408, d Shiller Park, 11	ated Feb linois,	for the supply of silver spr	ings, ings to

EPORT 0.: 9990114	6/89-01	INSPECTION RESULTS:	PAGE 4 of 9
	Drawing No. 4 springs.	8030-314-04. No problems w	were identified on these
с.	Spring Company	2, dated January 19, 1989, t ny, Muskegon, Michigan, for s to Drawing No. 48030-261-0	the supply of trip
d.	Company, Inco	7, dated July 10, 1988, to S prporated, Woodville, Wiscor to Drawing No. 48161-032-02-	nsin, for the supply of
e.	Products, Sat to Drawing No initially ide 1989. Receip did not confo discussions a confirmed that The transact March 28, 198	A dated February 15, 1989, 1 int Paul, Minnesota, for the 2.29407-00173, Revision 278 entified with Transaction No ot inspection identified that orm to Drawing No. 48030-314 and inspections conducted by at the parts were to Drawing ion tag was changed from 908 39. The error was corrected with the consent of the eng	e supply of inserts B. This material was c. 9081126 on March 22, at this material 4-04. Subsequent y the assigned engineer g No. 29407-00173. B1126 to 9087701 on d electronically on
f.	Manufacturing magnet slides One hundred i 1989. Receip had dimension properly. Th No. 9066057, forwarded to part. After that the part that the vent during the re notified the	8, dated January 17, 1989, 1 9, Minneapolis, Minnesota, 1 s to Drawing No. 48131-112-0 thirty-two pieces were recer pt inspection observed that hal problems and the parts were with the adverse inspection the cognizant engineer resp an evaluation, the cognizant ts were usable as-is. It was dor be notified of the defice eceipt, along with samples of vendor on March 15, 1989, 1 before shipping any future	for the supply of 100 D2-Y, Revision E718. ived on March 7, all the 132 pieces were not formed ort, for Transaction n findings, was ponsible for that nt engineer determined as also recommended ciencies identified of the parts. SD to correct the
in	the computer p	termined that the approved program to enable purchasing ed. However, if material is	to buy only from vendors

۱

REPORT NO.: 999011	46/89-01	INSPECTION RESULTS:	PAGE 5 of 9		
is ur su th Bu Ma be Pu ne	not identified in the computer program, then, first piece inspection is mandatory. The issuance of the received material is controlled until such time that the assigned engineer is satisfied that the supplied material is acceptable. The inspectors determined that the above activities were in compliance with Standard Practice Bulletin (SPB) 317 titled, "Vendor Selection for Productive Material," dated May 5, 1988, which establishes the guidelines to be used for selecting vendors and SPB 315 titled, "Issuance of Purchase Orders," dated May 4, 1988, which defines the requirements necessary for issuance of a PO.				
Th fa CE wo ap	acture of components as. Operators perfo ork to procedures, w oplicable procedure hspectors examined t	panied by SD personnel, observed the required to assemble FA type molded rming the work periodically inspecte hich defined acceptance criteria. T was posted at the workstation. The he components and the inspections be conents at the following workstations	d case ed the The eing		
a.	48124-331-57. T determine the ac contact to the t	azed to terminal identified as Part the requirement at this station was t cceptability of the braze attaching t cerminal. To accomplish this, five p every hour for the following attribut	to the pieces		
	 Verify that sides. 	the solder flow was adequate on the	ree		
	(2) The contact	is brazed straight on the terminal.			
		neck to verify that the minimum conta 0.140 millimeter.	act		
b.	After riveting t	being riveted to the mechanical hous the cradle assembly to the mechanica tributes were verified:			
	(1) Check the g	prease on the subassembly.			
	(2) Proper roll	l on the rivets.			
	(3) Inspect the	e left housing for cut-off area.			

REPORT NO.: 99901146/89-01		/89-01	INSPECTION RESULTS:	PAGE 6 of 9
	c.	356-50-54. A assembled to metal on thre determine tha values stated	ninal assembly identified as at this operation, after the the terminal, the formed he e specimens are measured wi at the formed heights are wi fon the procedure. The pro variety of assemblies deper	e bi-metal is eights of the bi- ith a gauge to ithin the acceptable ocedure specifies the
	d.	The magnetic adjusted duri operation.	trip is calibrated on each ng a trip-trip-hold-trip-ho	pole of the CB and old-trip cycle of
	e.	automated ope CB and automa If the calibr acceptable va a different s is calibrated to cool the b	verload trip on each CB is ration. The machine is pro- tically adjust the calibrat ration cannot be adjusted to lue in two attempts, then to tation. At this station, to manually, left for a speci- i-metallic strip, and after time, the trip setting is	ogrammed to test the tion in two attempts. o conform to the the CB is diverted to the thermal overload ific period of time r the elapse of a
		inspections w SD representa	rs observed that the results were being documented on ins atives stated that the in-pr d stored for at least six mo	spection reports. rocess reports are
5.	Obse	ervations of St	nort Circuit Tests	
	two one rep When sub: exp mel trij the thro thro	three-phase Ki from the produ laced with a con- subjected to sequently exam- erienced extension ted. It was po- pped the CB. H ionized air ca bugh the normal bugh the top, o	SD performed rated short of L 36225 type molded case CB action lot. The rear cover bunterfeit cover to simulate 25,000 A, the new one tripp ined and determined operable sive damage. The line side ostulated that the short cin dowever, during the short cin dowever, during the short cin aused by the high current, I channels provided in the g causing a phase to phase sho f the line side cable termine	Bs. One was a new on the second CB was e a refurbished one. ped and was e. The tampered one terminal leads rouit current incuit interruption, instead of escaping genuine CB, escaped ort resulting in

REPORT NO.: 999	901146/89-01	INSPECTION RESULTS:	PACE 7 of 9
6.	The control of rew drawings and remov Paragraph 3.4.5 of "Changes to previo tions, including e other modules or o procedure is compi titled, "Report Pr which states, in p Engineer shall be	of Design Changes visions to drawings, distrib ving obsolete drawings from f the SD QA manual. Paragra busly verified designs shall evaluations of the effects o components of the overall eq lemented by an Engineering P rocedure for Design Document part, in paragraph IIB, "The responsible for changes whi plants, such as, resolution	use are addressed in ph 3.4.5 states, require verifica- f those changes on uipment." This rocedure EP-2 s," dated May 1987, Existing Product ch affect the

customer or other plants, such as, resolution of performance problems, product upgrades and design enhancements." The inspectors observed that drawings were revised after an Engineering Change Notice (ECN) was initiated describing the change to that component. The ECN is circulated to the cognizant engineer for review and approval. In the interim, while the review process is in progress, the original of the drawing is annotated to preclude inadvertent use of the drawing while the ECN was being reviewed. The inspectors selected five drawings, examined the control of ECNs and determined the following:

- a. Revision H, dated October 10, 1988, to Drawing No. 48124-120 was accomplished with ECN F711. ECN F711, dated January 11, 1989, was initiated to change the load end venting of certain FA type CBs by using slotted load barriers.
- b. Revision D, dated May 4, 1988, to Drawing NO. A48124 120 was accomplished with ECN U288. ECN U288 was initiated on April 13, 1988, to provide tolerances to the length of the line end barrier.
- c. Revision C, dated November 11, 1988, to Drawing No. A8124-237 was accomplished with ECN F726, dated December 20, 1988. ECN F726 approved gold plated wire and switch assemblies.
- d. Revision F, dated December 19, 1988, to Drawing No. A48117-D24 was accomplished with ECN F733, dated February 3, 1989. ECN F733 increased the tolerance on the width of the handle shield for certain KA type CBs.

1

REPORT NO.: 99	901146/89-01	INSPECTION RESULTS:	PAGE 8 of 9	
	was accomplished modified the dra handle shields s	d December 19, 1988, to with ECN F733, dated Fe wings of the inner and o o that handles intended ufactured by using the s	for KCL and FA type	
7.	Review of Calibration	System		
	The inspectors reviewed Square D QA Manual Criterion XII, "Control of Measuring and Test Equipment" dated May 16, 1978. Review of calibration certificates established that standards used for calibration of electrical and mechanical instruments were traceable to the National Bureau of Standards. It was noted that the certification for the standard used to calibrate electrical meters (Fluke) did not have the calibration data sheets to substantiate the certificate. It is the inspectors understanding that the data sheets would be requested.			
	boards" identified as verify breaker trip t before their due date indicated that the la 1987, and was due for been performed. The located for FE No. 65 performed during this	facility the inspector r FE No. 6423 and FE No. imes on overload, had no s. The calibration card st calibration was perfor calibration in August 1 calibration card and rec 22. Calibration of the inspection and determin pancies were identified.	6522, used to ot been calibrated d for FE No. 6423 ormed February 6, 1988, which had not cords could not be two mag boards were ned to be within	
8.	Review of Audits			
	The inspectors reviewed the corporate QA audit for 1988. Several findings were documented pertaining to calibration and storing of materials. Response to the findings indicated that action was being taken to correct the findings. Additionally, the inspectors reviewed the internal audit schedule, preparation of audit forms, conduct of audit, and review of the 1987 in-house audits which appeared to be satisfactory.			
	Virginia Electric Pow	er audit of the SD facil wer Company approving the Normally customer aud Peru, Indiana.	e QA program by letter	

×.

*

REPORT NO.: 99901146/89-01	INSPECTION RESULTS:	PAGE 9 of 9
Evaluation/Certificat various ratings appli vendor. The inspecto Evaluation Report" of February 1989 and per	d the purchasing department "Vendor ion Program" procedure describing th ed to vendors prior to becoming a ce r also reviewed one "Vendor Certific Data Metalcraft, Incorporated, date formed a review of the approved supp screpancies were identified.	rtified ation/ d,
E. EXIT MEETING:		
The inspectors met with in explained the scope and pu inspection findings.	dividuals identified under persons or rpose of the inspection and discusse	ontacted, d the
F. PERSONS CONTACTED:		
 G. Q. Lofgren *B. Sines *M. Douglas L. Serbousek *G. Gregory *P. Zimmerman *P. Rainbow *K. Chown K. Slagle D. Smith 	Corporate Quality Manager Plant Manager Quality Manager Marketing Manager Chief Engineer Customer Service Supervisor Customer Service Manufacturing Manager Quality Engineer Quality Engineer Quality Assurance Technician	30. 1989.