

# The Light company

Houston Lighting & Power

P.O. Box 1700 Houston, Texas 77001 (713) 228-9211

August 11, 1989  
ST-HL-AE-3197  
File No.: G26  
10CFR50.73

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

South Texas Project Electric Generating Station  
Unit 2  
Docket No. STN 50-499  
Licensee Event Report 89-017 Regarding  
a Reactor Trip and Partial Loss of  
Offsite Power Due to a Main Transformer Failure

Pursuant to 10CFR50.73, Houston Lighting & Power (HL&P) submits the attached Licensee Event Report 89-017 regarding a reactor trip and partial loss of offsite power due to a main transformer failure. This event did not have any adverse impact on the health and safety of the public.

If you should have any questions on this matter, please contact Mr. C. A. Ayala at (512) 972-8628.

G.E. Vaughn  
G. E. Vaughn *by [Signature]*  
Vice President  
Nuclear Operations

GEV/BEM/eg

Attachment: South Texas, Unit 2  
LER 89-017

8908210249 890811  
PDR ADOCK 05000499  
S PDC

NL.LER89017.U2

A Subsidiary of Houston Industries Incorporated

IE22  
1/1

cc:

Regional Administrator, Region IV  
Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011

George Dick, Project Manager  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555

Jack E. Bess  
Senior Resident Inspector-Unit 1  
c/o U. S. Nuclear Regulatory Commission  
P. O. Box 910  
Bay City, TX 77414

J. I. Tapia  
Senior Resident Inspector-Unit 2  
c/o U. S. Nuclear Regulatory Commission  
P. O. Box 910  
Bay City, TX 77414

J. R. Newman, Esquire  
Newman & Holtzinger, P.C.  
1615 L Street, N.W.  
Washington, DC 20036

R. L. Range/R. P. Verret  
Central Power & Light Company  
P. O. Box 2121  
Corpus Christi, TX 78403

R. John Miner (2 copies)  
Chief Operating Officer  
City of Austin Electric Utility  
721 Barton Springs Road  
Austin, TX 78704

R. J. Costello/M. T. Hardt  
City Public Service Board  
P. O. Box 1771  
San Antonio, TX 78296

Rufus S. Scott  
Associate General Counsel  
Houston Lighting & Power Company  
P. O. Box 1700  
Houston, TX 77001

INPO  
Records Center  
1100 Circle 75 Parkway  
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, NY 11713

D. R. Lacker  
Bureau of Radiation Control  
Texas Department of Health  
1199 West 89th Street  
Austin, TX 78756-3189

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) South Texas, Unit 2 DOCKET NUMBER (2) 050004991 OF 03

TITLE (4) Reactor Trip and Partial Loss of Offsite Power Due to a Main Transformer Failure

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)	
07	13	89	89	017	000	08	11	89		05000	

OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)									
1		20.402(b)		20.406(c)	X	50.73(e)(2)(iv)		73.71(b)			
POWER LEVEL (10)	0.99	20.406(e)(1)(i)		50.36(c)(1)		50.73(e)(2)(v)		73.71(e)			
		20.406(e)(1)(ii)		50.30(e)(2)		50.73(e)(2)(vii)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)			
		20.406(e)(1)(iii)		50.73(e)(2)(ii)		50.73(e)(2)(viii)(A)					
		20.406(e)(1)(iv)		50.73(e)(2)(iii)		50.73(e)(2)(viii)(B)					
		20.406(e)(1)(v)		50.73(e)(2)(iii)		50.73(e)(2)(ix)					

LICENSEE CONTACT FOR THIS LER (12)  
NAME Charles Ayala - Supervising Licensing Engineer TELEPHONE NUMBER 512 972-8628

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC'S	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC'S		
X											

SUPPLEMENTAL REPORT EXPECTED (14)  
YES (If yes, complete EXPECTED SUBMISSION DATE) X NO  
EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On July 13, 1989, Unit 2 was in Mode 1 at 99 percent power. At 2002 hours, an internal fault occurred in the Unit 2 Main Step-Up Transformer 2A. The protective relays tripped the turbine and actuated the switchyard and generator breakers to clear the fault. The reactor tripped on the turbine trip. The plant was brought to an orderly cooldown with no unexpected primary system post trip transients. The investigation of the transformer failure is ongoing. The most probable cause was failure of the high side, phase A bushing. The transformer will be returned to the manufacturer for repair and the bushing and transformer will be analyzed further to determine the cause of this event.

NL.LER89017.U2



## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
South Texas, Unit 2	0500049989	0	17	00	02	OF	03

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT:

On July 13, 1989, Unit 2 was in Mode 1 at 99 percent power. At 2002 hours, an internal fault occurred in the Unit 2 Main Step-Up Transformer (MST) 2A. The main transformer differential relay and primary side pilot wire differential relays actuated the main transformer lockout relay which tripped the generator breaker, the offsite power feeds from the switchyard, the Auxiliary Transformer, and the main turbine. The reactor tripped on the turbine trip. Loss of power to the Auxiliary Transformer resulted in a loss of power to the Engineered Safety Features Train A bus and the non safety-related auxiliary busses which feed the reactor coolant pumps. The Engineered Safety Features Train A Standby Diesel Generator 21 started and loaded as expected. The Auxiliary Feedwater System actuated on low steam generator level. Primary system temperature was maintained with auxiliary feedwater flow and steam generator power operated relief valves on natural circulation. Power was subsequently restored to the auxiliary busses via the Standby Transformers. The NRC was notified pursuant to 10CFR50.72 at 2303 hours on July 13, 1989.

Subsequent investigation revealed that MST 2A had an internal fault in the area of the phase A high voltage bushing. The fault was cleared in approximately 2.5 cycles; however, major damage occurred to the transformer. The upper tank ruptured expelling most of the oil into the oil sump. Analysis of the transformer oil indicated that it did not contain significant quantities of polychlorinated biphenyl (PCB) and did not represent an environmental hazard. There was no fire or personnel injuries. Internals of the transformer, particularly the no load tap changer and the phase A high voltage bushing were severely damaged. Arcing tracks were noted from the tail piece of the bushing upwards to the grounding sleeve and the top of the tank in the bushing area. The core and windings appeared to be in good condition. The high voltage bushings were removed and will be analyzed to determine the cause of the failure. The transformer will be returned to the manufacturer for repair and failure analysis.

The South Texas Project utilizes two main transformers in parallel per unit. MST 2B has been inspected and tested and determined to be undamaged from this event. Following the disconnection of MST 2A Unit 2 was restarted on July 19, 1989 and is capable of operating at up to approximately 65 percent power.

CAUSE OF EVENT:

The most probable cause of this event was the failure of the phase A high voltage bushing in MST 2A. Investigation of the transformer and bushing is ongoing. If further information regarding the cause of this event becomes available, a supplement to this LER will be provided.

NL.LER89017.U2

