U. S. NUCLEAR REGULATORY COMMISSION REGION I

Report No. 50-245/89-13

Docket No. 50-245

License No. DPR-21 Category C

Licensee: Northeast Nuclear Energy Company P. O. Box 270 Hartford, Connecticut 06101

Facility Name: Millstone Nuclear Generating Station Unit 1

Meeting At: NRC Region I, King of Prussia, Pennsylvania

Meeting Conducted: June 21, 1989

Prepared by:

P. O'Connell, Radiation Specialist, FRPS, FRSSB

6-29-89 date

G-29-89 date

Approved by:

W. Pasciak, Chief, Facilities Radiation Protection Section, Facilities Radiological Safety and Safeguards Branch

Meeting Summary: Enforcement Conference at NRC Region I, King of Prussia, Pennsylvania, on June 21, 1989. to discuss the findings of NRC Inspection Report No. 50-245/89-13. The topics discussed related to the shipment of a high pressure pump and trailer with removable external radioactive contamination from the licensee's reactor site to a vendor site in Mcorestown, New Jersey.

The meeting was attended by NRC and licensee management and lasted for approximately two hours.

DETAILS

1. Participants

1.1 Northeast Nuclear Energy Company

- H. Haynes, Station Services Superintendent, Millstone
- S. Scace, Station Superintendent, Millstone
- F. Sears, Vice President, Nuclear & Environmental Engineering
- J. Sullivan, Health Physics Operations Supervisor, Millstone
- G. Van Noordennen, Licensing Supervisor, Millstone

NRC Personnel 1.2

- M. Boyle, Senior Project Manager, NRR
- R. Bellamy, Chief, FRSSB, RI
- M. Knapp, Director, DRSS, RI
- J. Gutierrez, Regional Council, RI
- L. Kolonawski, Resident Inspector, Millstone Unit One
- P. O'Connell, Radiation Specialist, RI W. Pasciak, Chief, FRPS, RI W. Thomas, Radiation Specialist, RI

- E. Wenzinger Sr., Chief, DRP Br. 1, RI

2.0 Purpose

The Enforcement Conference was held at the request of NRC Region I to discuss the circumstances relating to the shipment of a high pressure pump and trailer, which had removable external contamination, from the licensee's reactor site to a vendor's site in Moorestown, New Jersey. The discussions at this meeting focused on: the identified apparent violations, their safety significance, the root cause of the event, and licensee corrective actions to prevent recurrence.

3.0 Licensee Presentation

Licenses management began their presentation by emphasizing that they are committed to making the necessary changes in their program to preclude recurrence of this type of incident. The licensee stated that prior to this incident they made several improvements in their Health Physics Program. The improvements included the reorganizing of the Health Physics Department into two groups, Operations and Support; increased staffing to reduce the need for contractor Health Physics support; and a general upgrade of Health Physics procedures. Licensee management stated that this incident. demonstrated that their program still has some weaknesses, particularly in the area of management review of proposed work activities.

Licensee personnel provided the NRC with handouts which provided an outline of the event and the licensee's corrective actions. These handouts are included in this report as Attachment 1. Licensee personnel reviewed with NRC management the chronology of the incident, the root causes of the incident, related radiological survey and calculation data, and the licensee's assessment of the safety significance of this incident. The licensee also reviewed the corrective actions which the licensee has implemented. These actions included adopting an interim policy of surveying all vehicles prior to their leaving the site and having upper plant management reemphasize the importance of thorough reviews of new procedures or other changes by the Plant Operations Review Committee (See Attachment 2). The licensee also provided timely notification to other utilities of the incident in order to decrease the possibility of a similar incident happening elsewhere (See Attachment 3).

Licensee evaluation of long term corrective actions was still in progress. The licensee committed that the final long term corrective actions will be developed and implemented by September 1, 1989.

4.0 Concluding Statements

Licensee management stated that they had no additional qualifying information for the findings presented in NRC Inspection Report No. 50-245/89-13.

NRC Region I management acknowledged that the actions presented appeared to be responsive to the NRC's concerns. NRC Region I management stated that the licensee would be informed of the need for and the nature of appropriate enforcement action relative to this incident at a later time.

Attachment 1.

*

Docket No. 50-245

Enforcement Conference

CONTAMINATION OF THE WESTINGHOUSE HYDROLAZER SYSTEM USED AT MILLSTONE UNIT ONE

NORTHEAST NUCLEAR ENERGY COMPANY JUNE 21, 1989

TABLE OF CONTENTS

I.	DESCRIPTION OF EVENT	1
II.	CAUSE OF EVENT	2
ш.	ANALYSIS OF EVENT	2
IV.	ASSESSMENT OF SAFETY SIGNIFICANCE	6
V.	CORRECTIVE ACTION	8

ATTACHMENTS

JE
Hydrolaze Trailer Location Hydrolaze Trailer Location Hydrolaze Water Supply
10
2

Hydrolaze System Design Hydrolaze Trailer – Back and Side View

III. ATTACHMENT THREE

PAGE 1 OF 2

PAGE 2 OF 2

Radiological Data: Isotopic Analyses of Water Supply

IV. ATTACHMENT FOUR

Radiological Data: Water Supply Hose

V. ATTACHMENT FIVE

Radiological Data: Hydrolazer Trailer Survey of May 15, 1989

VI. ATTACHMENT SIX

: ···

*

PAGE 1 OF 9	Radiological Data: Survey of Hydrolaze Trailer Water Tank and Trailer
PAGE 2 OF 9	Radiological Data: Survey of Hydrolaze Trailer Water Tank and Trailer
PAGE 3 OF 9	Radiological Data: Survey of Hydrolaze Trailer
PAGE 4 OF 9	Radiological Data: Survey of Hydrolaze Trailer
PAGE 5 OF 9	Radiological Data: Survey of Hydrolaze Trailer
PAGE 6 OF 9	Smear Locations for May 15, 1989 Survey by Westinghouse
PAGE 7 OF 9	Radiological Data: Survey of Hydrolaze trailer
PAGE 8 OF 9	Smear Locations for May 17, 1989 Survey by Westinghouse
PAGE 9 OF 9	Radiological Data: Isotopic Analyses of samples

VII. ATTACHMENT SEVEN

PAGE 1 OF 3	Smear Survey of Hose Section at Millstone
PAGE 2 OF 3	Radiological Data: Smear Survey of Hose Section
PAGE 3 OF 3	Radiological Data: Isotopic Analyses of Pressure Hose Smears

VIII. ATTACHMENT EIGHT

Radiological Data: Isotopic Analyses of Reactor Water and Cavity Wall

IX. ATTACHMENT NINE

PAGE 1 OF 2	Radiological Data: Area Survey of Trailer Locale at Unit 1
PAGE 2 OF 2	Radiological Data: Area Survey of Trailer Locale at Unit 1

X. ATTACHMENT TEN

Calculations

CONTAMINATION OF THE WESTINGHOUSE HYDROLAZER SYSTEM USED AT MILLSTONE UNIT ONE

DESCRIPTION OF EVENT

On Monday, May 15, 1989 a Westinghouse hydrolazer trailer being temporarily stored at the Westinghouse maintenance facility in Moorestown, New Jersey was found by Westinghouse to be radioactively contaminated. Westinghouse notified NNECo on May 15, 1989 and stated they believed the contamination originated at Millstone Station. The hydrolazer trailer had been used at Millstone Unit One to decontaminate the refueling cavity.

Investigation of radiological survey data, operating logs and discussions with involved personnel addressed four possible causes of the contamination. These four possible causes are:

- 1. The hydrolazer water tank was internally contaminated due to it's prior use at Consolidated Edison's Indian Point Unit Two.
- Contaminated water was supplied to the hydrolazer water tank at Millstone One.
- The hydrolazer water tank and trailer were intentionally contaminated by others.
- 4. Water from the reactor cavity was inadvertently siphoned, or drained back into the hydrolazing unit.

After review it has been concluded that the fourth possible cause is most likely. Further rationale for this conclusion is provided in the Analysis of Event section of this report.

Other than the hydrolazer unit, no people or facilities, were contaminated from this event. Appropriate NRC, State of Connecticut DEP notifications were made on May 16,1989 in accordance with requirements of 10 CFR 50.72.

Our evaluation indicated this was not reportable per 10CFR 50.73.

Chronology

Date	Event
May 4,1989	Westinghouse hydrolazer crew onsite.
May 5	Equipment setup.
May 8	"Upper Drywell Shielding" (Cattle Chute) hydrolazed (refueling equipment)
May 10	Reactor Cavity hydrolazed.
May 11	Westinghouse equipment and crew leave site.

May 12	Hydrolazer trailer arrives at Westinghouse maintenance facility in
	Moorestown, N.J.
May 15	Westinghouse Survey of trailer reveals contamination in the hydrolazer tank and on the trailer.

CAUSE OF EVENT

Millstone procedures SHP 4917 <u>Unconditional Radiological Release of Material For</u> <u>Unrestricted Use</u> and HP905/2905/3905 <u>Control And Accountability of Radioactive Material</u> provide instruction for controlling and accounting for radioactive material and to provide a means for the unconditional release of material from contaminated areas for unrestricted use.

These H.P procedures successfully address the majority of possible contamination circumstances. However, they did not effectively deal with the contamination of the hydrolazer trailer because they do not address situations in which a possible, but unintentional flow path from a contaminated area to a clean area could exist.

The hydrolazing activity in question and all similar activities are performed using approved procedures. These procedures require Plant Operations Review Committee (PORC) review and approval. This review process is considered to be effective at Millstone. However, in this instance the process failed to identify the potential siphoning scenario and to cause sufficient safeguards to be implemented.

ANALYSIS OF EVENT

For operation at Millstone Unit One, the hydrolazer trailer was situated outside of the Reactor Building at the railway access as illustrated in Attachment One. As shown in Attachment One, water was supplied from the demineralized water storage tank to the hydrolazer supply tank. The hydrolazer pump discharge line was run into the Reactor Building, and up approximately 100 feet to the refuel floor where the hydrolazing was performed. Page 3 of Attachment One is a schematic of the water supply.

The hydrolazer trailer consists of a 60 gallon supply tank, a pump, and a diesel engine. Attachment Two is a diagram of the trailer. There are three connections to the tank: an inlet located on one end at the top, a pump suction located on the bottom center, and a bypass line located near the bottom, below the inlet line. The tank is vented to atmosphere through a vent panel near the top of the tank. The bypass line has an in-line valve and connects the discharge side of the pump back to the tank. Tank level is normally regulated by an inlet float valve. However, it was learned from Westinghouse that the float was not operable during the period of May 4 – May 12, 1989 and tank level was being maintained by the equipment operator through visual inspection. The hydrolazer pump is a positive displacement pump designed to deliver discharge pressures up to 11,000 PSI.

Three types of hydrolazing attachments were used. They were a 'remote lance' for the upper

drywell shielding, a 'control gun' in the cavity, and a 'flex lance' in the cavity drains. The control gun has a trigger to shut off water flow while the remote and flex lances have no local control of water flow. During the hydrolazer activity there were periods when these attachments were required to be submerged. The remote lance was underwater during the entire effort to decontaminate the upper drywell shielding. The flex lance was submerged while cleaning the drains. The control gun was used in "open air" and not normally submerged.

Operation of all three hydrolazing attachments required coordination between the person hydrolazing and the pump operator at the trailer in order to regulate line pressure. The lance operator communicated hy hand signals to a worker at the reactor cavity rail, who communicated to the pump operator via headset. The pump operator controls pressure by varying the speed of the diesel engine.

Radiological data

Six categories of radiological survey data were evaluated as listed below:

- 1. water supply;
- 2. the water supply hose;
- the hydrolazer trailer including the tank, pump, diesel and fuel tank, and interconnecting lines;
- the pressure hose;
- 5. reactor cavity water and wall;
- 6. area surveys.

All contamination survey data are included in Attachments Three through Ten. The significance of the data for each category is discussed below.

<u>Water supply</u> – Water samples taken from the demineralized water storage tank and the condensate storage tank show no radioactivity and no identifying peaks when isotopically analyzed. Results of week'y CST samples were the same for May 2, May 9, and May 15. Based on this, the water supply was eliminated from consideration as the source of contamination.

<u>Water supply hose</u> – The two sections of water supply hose used during the decon activity were obtained from the Millstone warehouse. Smear surveys of the inside and outside of the two sections of supply hose showed no radioactive contamination. One of the hoses was smeared internally at the center by cutting open the hose. These sample results confirm that the water supply was free of radioactive contamination.

<u>Cavity Water</u> – Reactor water samples routinely show the isotopes of Cr-51, Mn-54, Co-58, Fe-59, Co-60, Zn-65, and Cs-137. Zinc-65 is the predominant isotope. Unit 1 uses the zinc injection process to reduce Co-60 deposition and ultimately lower radiation levels throughout the reactor coolant system associated piping. An isotopic analysis of a smear of the cavity wall showed the same isotopes except for Cs-137. The relative abundance of Zn-65 in the cavity wall sample is much smaller although it is still almost 15% of the total activity. Variation of the Zn-65 relative abundance would occur because of mixing from other sources of water such as the spent fuel pool and because of differing plateout characteristics of different isotopes. Routine Unit One rad waste samples show typical isotopic mixes with 40–70% Zn-65. Thus the values of 20–65% relative abundances of Zn-65 seen in the hydrolazer tank, on the trailer, and in the pressure hoses would be within the expected range of values for contamination by cavity water.

<u>Hydrolazer trailer</u> – All the survey results on pages one through eight of Attachment Six are Westinghouse results provided to NNECo. The highest level of contamination was inside the tank below the supply inlet near the bypass inlet. There was also contamination inside the inlet connector on both sides of the supply valve, inside the bypass line on both sides of the bypass valve, and inside the tank outlet fitting for the pump suction line. The interior of the suction line from the tank to the pump was not contaminated except for some small amount of contamination in the line near the tank. These levels and distribution of contamination suggests that the contamination could have entered the tank either through the inlet supply line or through the bypass line. Since there is a lack of evidence of supply water contamination, the bypass line becomes the suspected route of contamination. Moreover, the absence of any significant level of contamination in the pump suction line suggests contamination of the tank after completion of pumping activities. There is also contamination on the tank, on the tank mount structures, and on the deck of the trailer under and around the tank. External contamination is thought to have occurred as a result of draining the supply tank by the Westinghouse operators in preparation for transporting the unit offsite.

NNECo obtained smears from Westinghouse of the trailer deck, the interior of the supply line inlet fitting, both sides of the water filter located inside the tank on the outlet line and of the vacuum hose used to clean the inside of the tank. Westinghouse also provided a crud sample from the bottom of the tank and residual water from the pump supply line. All samples were isotopically analyzed and found to have isotopes common to Millstone Unit One. The most predominant isotope identified was Zn–65 with a relative abundance ranging from 20–65%. This finding makes Unit One cavity water the primary suspect for the source of contamination discussed further below.

<u>Pressure hose</u> – Six sections of high pressure hose were used. Five sections of the hose and all the lances were found to be externally contaminated when the equipment was being disassembled. The external contamination was attributed to contamination originating on the refuel floor, therefore this was not cause for concern at the time. This equipment was not released by NNECo. One section of hose was clean and released to Westinghouse. After the trailer contamination was discovered by Westinghouse on May 15, the five sections were checked internally by inserting Q-tips in the ends. All five were internally contaminated. The section of hose kept by Westinghouse was subsequently found to have internal contamination. Isotopic analyses of smears of the hoses showed the same characteristic isotopic mix as the tank contamination samples.

Area surveys - A survey for removable contamination of the area where the hydrolazer had

been operated was initiated upon notification by Westinghouse. Attachment Nine page 1 provides the details of this survey. No detectable contamination was found.

A survey for fixed contamination was conducted on May 17. The survey indicated one spot of contamination of approximately 2 cm² in area (Attachment Nine Page 2). Analysis of the contaminated asphalt indicated Zn-65, C0-58 and Co-60.

Discussion of possible scenarios and conclusions reached

As previously mentioned four possible contamination scenarios have been considered:

- 1. The hydrolazer water tank was internally contaminated due to it's prior use at Indian Point Two. This has been discounted based on discussion with Consolidated Edisons personnel and radiological data from that facility.
- 2. Contaminated water was supplied to the hydrolazer water tank at Millstone One. This has been discounted by radiological data.
- 3. The hydrolazer water tank and trailer were intentionally contaminated by others.

This possibility is discounted for the following reasons:

- The Westinghouse contractor was the only bidder on the cavity decon work and a minimum number of people on-site knew of the crew's function. The general decon contractor declined to bid on this activity. Additionally there is no evidence of any animosity between contractor and any personnel while they were on site.
- The door to the railway access hatch was for the most part closed during the time period in question which would make it quite difficult to obtain a sample of primary water and pass through radiation detection equipment to exit the containment building unnoticed.
- 4. Water from the reactor cavity, was inadvertently siphoned or drained back into the hydrolazer unit. This is considered the probable scenario.

Discussion of the probable scenario

It has not been possible to identify the specific system operation which caused this event. From discussions with Westinghouse personnel, no specific operational sequence could be identified that caused feedback. Certain factors are supportive of the feedback or siphoning scenario. These factors include a system pathway which could have allowed feedback, a pattern of contamination which follows that pathway, and isotopic analysis from contamination samples which clearly indicate Millstone Unit One cavity water as the primary contaminant.

ASSESSMENT OF SAFETY SIGNIFICANCE

Maximum potential doses resulting from the hydrolazer trailer contamination were estimated based on post-incident surveys. Four dose categories were established – public dose due to release of contaminated water, internal dose to a worker, internal dose to a member of the public, and skin dose to a worker. In each category, considered conservative assumptions were made to postulate the worst case dose scenario. For this reason the doses are considered maximum potential doses.

All of the maximum potential dose estimates are well within the 10 CFR 20 whole body limits of 500 mRem in a year for a member of the public and 1,250 mRem in a quarter for a worker and the skin dose limit of 7,500 mRem in a quarter for a worker.

1. Public dose due to off-site release of liquids via the storm drains

MAXIMUM INDIVIDUAL:

WHOLE BODY:	2.69E-3	mRem
GI (MAX ORGAN):	7.92E-3	mRem

POPULATION:

WHOLE BODY:

7.28E-3 person Rem

2. Internal dose to worker:

WHOLE BODY: 0.3 mRem GJ (MAX ORGAN): 0.8 mRem

3. Internal dose to public:

WHOLE BODY: 0.03 mRem GI (MAX ORGAN): 0.09 mRem

4. Skin dose to worker:

38 mRem (5 cm radius)

Methodology and Assumptions for Determining Doses

1. Public dose from off-site release

The release pathway was from water spilling and draining out of the hydrolaze tank, onto the ground, into the yard storm drain, and out to the discharge quarry. It was assumed that the total volume of the tank (60 gal) with a radionuclide concentration equal to cavity water (0.1 uCi/cc) was released. The computer code LADTAP2 was used to calculate the public doses

resulting from this release. The actual dose will probably be lower because the cavity water activity concentration of 0.1 uCi/cc is the upper limit of measurements taken of the cavity water. Also, the 60 gallon release of cavity water is an upper limit because of the dilution with supply water.

2. Internal dose to worker

The worst scenario for intake of radioactive material would be transfer of contamination from the trailer deck onto a hand and then transferred to food being eaten. The following assumptions were made:

- The average trailer deck contamination of 15,000 DPM/100 cm² seen in the trailer survey is 10% of the activity deposited before being washed off by rain.
- Contamination from a 1,000 cm² area was transferred by contact to a hand.
- Ten percent of the hand contamination was ingested.

With these assumptions an intake of 0.08 uCi is postulated.Using the isotopic mix seen in the trailer smears and the dose conversion factors from Regulatory Guide 1.109, the internal dose was calculated. All Westinghouse personnel involved in this evolution recieved a whole body count upon leaving the site with no indication of internal activity.

3. Internal dose to public

The public internal dose was calculated in the same way as worker internal dose. With the public dose however the activity is reduced by a factor of ten because of wash-off prior to leaving the site.

4. Skin dose

It was assumed that a 100 cm² area of deck contamination of 150,000 DPM/100 cm² was transferred to a 5 cm diameter circle of skin. The activity was assumed to reside on the skin for 24 hours. Using the isotopic mix seen in the trailer smears and the Code VARSKIN the skin dose was calculated.

Based on the above, NNECo concluded that this event was not significant with respect to the actual consequences to plant personnel or the public.

CORRECTIVE ACTION: Immediate

Following discovery of the contamination incident, meetings were held between the Health Physics Supervisor and the Radiation Protection Supervisors to discuss the hydrolazer release from the site and to obtain input on program weaknesses which need to be resolved. During these meetings, requirements were established for surveys of any equipment with a potential for contamination due to a positive interface with a contaminated area/system.

As an interim measure to prevent recurrence NNECo has instituted a program for surveying all vehicles leaving the protected area.

To make station supervision aware of the situation, the Station Superintendent has issued a memo to all members of the unit PORCs. This event is to be used to reemphasize the need for comprehensive evaluations of new and contractor procedures with an emphasis on the "What if..." possibilities. This memo was copied to the Superintendent of the Haddam Neck Station.

To make other utilities aware of the possibility of such an unanticipated contamination occurrence, a NETWORK entry was prepared and issued.

In addition this report was reviewed by Haddam Neck management. It was determined that sufficient controls are in place to prevent a similar event from happening at that facility.

Corrective Action: Long Term

Evaluation of long term corrective action is in progress. By September 1, 1989 Millstone will have implemented final corrective actions that will address both the upgrade of our radiological controls program, to insure contaminated equipment is not released from the Millstone site and enhancements in work control processes that are deemed appropriate based on our detailed event analysis.

ATTACHMENT ONE PAGE 1 OF 3

HYDROLAZE TRAILER LOCATION

* *

.



HYDROLAZE TRAILER LOCATION

*

-



ATTACHMENT ONE PAGE 2 OF 3

ATTACHMENT ONE PAGE 3 OF 3

HYDROLAZE WATER SUPPLY



ATTACHMENT TWO PAGE 1 OF 2

HYDROLAZE SYSTEM DESIGN

•. :



ATTACHMENT TWO

PAGE 2 OF 2

HYDROLAZE TRAILER - BACK AND SIDE VIEWS

:



RADIOLOGICAL DATA: ISOTOPIC ANALYSES OF WATER SUPPLY

Sample	Date	Volume	Count Time	Results
CST	5/2/89	1,000 ml	30 min	No radionuclides identified
CST	5/9/89	1,000 ml	30 min	No radionuclides identified
CST'	5/16/89	1,000 ml	30 min	No radionuclides identified
DWST ²	5/15/89	1,000 ml	30 min	No radionuclides identified
DWST ²	5/18/89	1,000 ml	30 min	K-40 only

1) Condensate Storage Tank

2) Demineralized Water Storage Tank sampled via valve 1-DW-117

Analyses performed at Millstone Nuclear Power Station

ATTACHMENT FOUR

RADIOLOGICAL DATA: WATER SUPPLY HOSE

Surveys Performed by Millstone Nuclear Power Station

Removable Contamination

Sample	Date	Results (dpm/100cm ²)
External	5/15/89	<1000 βγ <20 α
Internal	5/15/89	<1000 βγ <20 α
External – Large Area	5/15/89	<1000 βγ <20 α
Connectors	5/15/89	<1000 βγ <20 α

Fixed Contamination

Sample	Date	Results (dpm/frisk)
External	5/15/89	$<$ 5000 by <100 α (both hoses)
Internal	5/18/89	\angle 5000 by <100 α (one hose)

Isotopic Analyses of Smears

Sample	Date	Count time	Results
External	5/15/89	10 mir.	No radionuclides identified (both hoses)
Internal	5/18/89	10 min	No radionuclides identified

ATTACHMENT FIVE

BADIOLOGICAL DATA: HYDROLAZE TRAILER SURVEY OF MAY 15, 1989

.

Survey on May 15, 1989 by Westinghouse



No.	dpm/100cm ²	Location
1	1263	Water Inlet Fittings
2	1663	Water Inlet Inside
3	10863	Water Inlet Inside
4	2863	Inside Lid
5	1963	Tank Fitting for Suction Hose
6	550	Inside Suction Hose Tank End
7	<mda< td=""><td>Inside Suction Hose Pump End</td></mda<>	Inside Suction Hose Pump End
8	<mda< td=""><td>Pump Inlet</td></mda<>	Pump Inlet
9	15413	Bypass Hose by Water Tank
10	5125	Tank Fitting for Bypass
11	<mda< td=""><td>Bypass Hose by Valve</td></mda<>	Bypass Hose by Valve
12	1188	Inside Bypass Valve Tank
13	438	Inside Bypass Valve Pump
14	<mda< td=""><td>Plunger</td></mda<>	Plunger
15	<mda< td=""><td>Plunger</td></mda<>	Plunger
16	<mda< td=""><td>Plunger</td></mda<>	Plunger
17	<mda< td=""><td>Plunger Housing Base</td></mda<>	Plunger Housing Base
18	<mda< td=""><td>Plunger Housing Base</td></mda<>	Plunger Housing Base
19	-MDA-	Water Outlet

RADIOLOGICAL DATA: SURVEY OF HYDROLAZE TRAILER WATER TANK AND TRAILER EXTERNAL CONTAMINATION

Survey on May 15, 1989 by Westinghouse



All results in dpm/100cm² (MDA = minumum detectable activity)

Smear Number	Results	Smear Number	Results
1	<mda< td=""><td>18</td><td>15538</td></mda<>	18	15538
2	<mda< td=""><td>19</td><td>4538</td></mda<>	19	4538
3	613	20	<mda< td=""></mda<>
4	<mda< td=""><td>21</td><td>438</td></mda<>	21	438
5	1063	22	<mda< td=""></mda<>
6	<mda< td=""><td>23</td><td><mda< td=""></mda<></td></mda<>	23	<mda< td=""></mda<>
7	<mda< td=""><td>24</td><td><mda< td=""></mda<></td></mda<>	24	<mda< td=""></mda<>
8	<mda< td=""><td>25</td><td>2538</td></mda<>	25	2538
9	300	26	1200
10	600	27	2875

ATTACHMENT SIX PAGE 2 OF 9

RADIOLOGICAL DATA: SURVEY OF HYDROLAZE TRAILER WATER TANK AND TRAILER

Internal Contamination and Dose Rates

Survey on May 15, 1989 by Westinghouse



. .



All results in dpm / 100cm² (MDA = minumum detectable activity)

<u>Smear #</u>	Results		
11	675		
12	1150		
13	3400		
14	9925		
15	225088		
16	813		
17	3788		

RADIOLOGICAL DATA: SURVEY OF HYDROLAZE TRAILER EXTERNAL CONTAMINATION AND DOSE RATES

S irvey on May 15, 1989 by Westinghouse



All results in dpm/100cm2

(MDA = minimum detectable activity)

Smear #	Results
28	<mda< td=""></mda<>
29	<mda< td=""></mda<>
30	<mda< td=""></mda<>
31	<mda< td=""></mda<>
32	<mda< td=""></mda<>
33	<mda< td=""></mda<>
34	<mda< td=""></mda<>
35	<mda< td=""></mda<>
36	<mda< td=""></mda<>
37	<mda< td=""></mda<>
38	<mda< td=""></mda<>
39	<mda< td=""></mda<>
40	<mda< td=""></mda<>

RADIOLOGICAL DATA: SURVEY OF HYDROLAZE TRAILER EXTERNAL CONTAMINATION AND DOSE RATES

Survey on May 17, 1989 By Westinghouse

All results in dpm/100cm2

(MDA = minimum detectable activity)

<u>Smear #</u>	Results
41	<mda< td=""></mda<>
42	<mda< td=""></mda<>
43	363
44	338
45	<mda< td=""></mda<>
46	<mda< td=""></mda<>
47	<mda< td=""></mda<>
48	<mda< td=""></mda<>
49	<mda< td=""></mda<>
50	<mda< td=""></mda<>
51	<mda< td=""></mda<>
52	<mda< td=""></mda<>
53	26375
54	<mda< td=""></mda<>

ATTACHMENT SIX PAGE 5 OF 9

RADIOLOGICAL DATA: SURVEY OF HYDROLAZE TRAILER PUMP SIDE OF TRAILER

. . :

Survey on May 15, 1989 by Westinghouse

All results in dpm/100cm2 (MDA = minimum detectable activity)

Smear #	Results	<u>Smear #</u>	Results	Smear #	Results	Smear #	Results
55	500	62	<mda< td=""><td>71</td><td>25075</td><td>81</td><td><mda< td=""></mda<></td></mda<>	71	25075	81	<mda< td=""></mda<>
55	1213	63	<mda< td=""><td>72</td><td>7437</td><td></td><td></td></mda<>	72	7437		
57	<mda< td=""><td>64</td><td><mda< td=""><td>73</td><td><mda< td=""><td></td><td></td></mda<></td></mda<></td></mda<>	64	<mda< td=""><td>73</td><td><mda< td=""><td></td><td></td></mda<></td></mda<>	73	<mda< td=""><td></td><td></td></mda<>		
58	<mda< td=""><td>65</td><td><mda< td=""><td>74</td><td><mda< td=""><td></td><td></td></mda<></td></mda<></td></mda<>	65	<mda< td=""><td>74</td><td><mda< td=""><td></td><td></td></mda<></td></mda<>	74	<mda< td=""><td></td><td></td></mda<>		
59	<mda< td=""><td>66</td><td><mda< td=""><td>75</td><td>9613</td><td></td><td></td></mda<></td></mda<>	66	<mda< td=""><td>75</td><td>9613</td><td></td><td></td></mda<>	75	9613		
60	<mda< td=""><td>67</td><td><mda< td=""><td>77</td><td>300</td><td></td><td></td></mda<></td></mda<>	67	<mda< td=""><td>77</td><td>300</td><td></td><td></td></mda<>	77	300		
61	<mda< td=""><td>68</td><td><mda< td=""><td>78</td><td>288</td><td></td><td></td></mda<></td></mda<>	68	<mda< td=""><td>78</td><td>288</td><td></td><td></td></mda<>	78	288		
62	<mda< td=""><td>69</td><td><mda< td=""><td>79</td><td><mda< td=""><td></td><td></td></mda<></td></mda<></td></mda<>	69	<mda< td=""><td>79</td><td><mda< td=""><td></td><td></td></mda<></td></mda<>	79	<mda< td=""><td></td><td></td></mda<>		
63	<mda< td=""><td>70</td><td>1525</td><td>80</td><td><mda< td=""><td></td><td></td></mda<></td></mda<>	70	1525	80	<mda< td=""><td></td><td></td></mda<>		

ATTACHMENT SIX

PAGE 6 OF 9

SMEAR LOCATIONS FOR MAY 15, 1989 SURVEY BY WESTINGHOUSE

Ministration and a second	And Del Statistical Land		
1	Outside of	water	tank

Smear Location

- 2 See Figure 3
- See Figure 4 See Figure
- 5 See Figure
- 6 See Figure
- 7 See Figure
- 8 See Figure
- 9 See Figure
- 10 Outside of water tank
- 11 Inside of water tank
- 12 See Figure
- 13. See Figure
- 14 See Figure
- 15 See Figure
- 16 See Figure
- 17 See Figure
- 18 Trailer deck
- 19 Trailer deck
- 20 Water tank mount
- 21 Face of water block
- 22 Face of water block
- 23 Water tank mount
- 24 Water tank mount
- 25 Trailer frame 25
- Trailer frame
- 26 Trailer frame 27
- Trailer frame 28
- Trailer frame 29
- Trailer frame 30 Trailer frame
- 31 Trailer frame
- 32 Motor Cover
- 33 Motor Cover
- 34 Motor Cover
- 35 Motor Cover
- 36 Pulley Cover
- 37 **Pulley Cover**
- 39 **Pulley** Cover 39
- Pulley Cover
- 40 Top of motor cover

- Smear Location 41 Trailer frame Trailer frame 42 43 Trailer frame 44 Tank mount - outside 45 End of water tank 46 Fuel Tank 47 Fuel Tank 48 Fuel Tank 49 Fuel Tank 50 Radiator cover 51 Radiator cover 52 Radiator cover 53 Trailer deck 54 Trailer deck 55 End of tank - outside 56 Water tank mount 57 Water supply line 58 Pump 59 Pump 60 Pump 61 Fuel tank 62 Fuel tank 63 Pulley cover 64 Pulley Cover 65 Face of motor cover 66 Face of motor cover 67 Face of motor cover 68 Trailer frame 69 Trailer frame 70 Trailer frame 71 Trailer deck 72 Trailer deck 73 Trailer deck 74 Trailer deck 75 Trailer deck 76 Trailer deck
 - 77 Trailer deck
 - 78 Trailer deck
 - 79 Fluid end of pump
- 80 Fluid end of pump 81
 - Fluid end of pump

ATTACHMENT SIX PAGE 7 OF 9

RADIOLOGICAL DATA: SURVEY OF HYDROLAZE TRAILER

Survey on May 17, 1989 by Westinghouse

All results in dpm/100cm2

Smear #	Results	Smear#	Results
1	10863	11	<mda< td=""></mda<>
2	1663	12	1963
3	2863	13	<mda< td=""></mda<>
4	1263	14	10038
5	15413	15	<mda< td=""></mda<>
6	388	16	<mda< td=""></mda<>
7	438	17	<mda< td=""></mda<>
8	1188	18	<mda< td=""></mda<>
9	5125	19	<mda< td=""></mda<>
10	550		

(MDA = minimum detectable activity)

ATTACHMENT SIX PAGE 8 OF 9

SMEAR LOCATIONS FOR MAY 17, 1989 SURVEY BY WESTINGHOUSE

Smear # Location

- 1 Water inlet inside
- 2 Wate inler inside
- 3 Inside vent lid
- 4 Water inlet fitting
- 5 Bypass hose by water tank
- 6 Bypass hose by pump
- 7 Inside bypass valve pump side
- 8 Inside bypass valve tank side
- 9 Tank fitting for bypass
- 10 Inside suction hose tank end
- 11 Inside suction hose pump end
- .12 Tank fitting for suction hose
- 13 Pump inlet
- 14 Water outlet
- 15 Plunger housing base
- 16 Plunger housing base
- 17 Plunger
- 18 Plunger
- 19 Plunger

RA	DIOLOG	ICAL DA	TA: ISO1	TOPIC AN	VALYSES	OF SAN	IPLES
Sample	1	2	3	4	5	<u>6</u>	I
Activity µCi (unless noted)	5.3E-2	1.5E-2	3.2E-2	5.5E-3	1.3E-3	9.5E-2	5.4E-3 (µCi/ml)
% Of Total Activity For							
Co-58	. 2.4	NI	2.2	NI	NI	1.4	1.7
Co-60	36.9	21.3	31.3	30.6	44.8	30.1	30.6
Cr-51	18.0	17.1	15.9	22.2	NI	15.0	17.7
Fe-59	4.8	7.3	7.4	NI	NI	6.4	8.1
Mn-54	15.3	17.6	17.7	18.0	15.8	15.6	19.2
Zn-65	22.4	36.6	25.6	29.4	39.2	31.5	23.1

NI = not identified

Sample identification

- 1 Smear of trailer
- 2 Smear of water filter inside tank on outlet line (pump side)
- 3 Smear of water filter inside tank on outlet line (tank side)
- 4 Smear of vacuum hose used to clean inside of tank
- 5 Smear of inside of inlet line outboard of valve
- 6 Crud from bottom of tank
- 7 Water sample from tank

All samples were obtained by Westinghouse All analyses were performed at Millstone

ATTACHMENT SEVEN PAGE 1 OF 3

SMEAR SURVEY OF HOSE SECTIONS AT MILLSTONE

Hose connection swipe samples from Unit I Cavity Decon Hydrolazer Hose

lose #	<u>Smear #</u>	internal (dpm/"Q-Tip")2	Smear #	External(dpm/Smear) ²
1	1	25,000	11	5.000
	2	90,000	12	30,000
2	3	5,000	13	15.000
	4	30,000	14	450,000
3	5	2.000	15	<1.000
	6	2,000	16	<1,000
4	7	10,000	17	<1.000
	8	10,000	18	<1,000
5	9	25,000	19	<1.000
	10	20,000	20	<1,000

Results of May 17, 1989 survey of sections of hose #51

Two cuts were made in the hose and cotton (Q-Tips) swabs were used to sample the interior of the hose. The saw used had a new blade.

Cotton Swabs of hose (cut) ends: (Measured thru 8 mils of plastic)

Q-Tip	<u>CCPM</u> ²
#1	700
#2	100
#3	1200
#4	100

1 - Alpha contamination not detectable in any sample

2 - Beta-Gamma activity

RADIOLOGICAL DATA: SMEAR SURVEY OF HOSE SECTION

Survey on May 15, 1989 by Westinghouse

SMEAR #	DPM/100cm ²	
1	4900	
2	<mda< td=""></mda<>	
3	<mda< td=""></mda<>	
4	<mda< td=""></mda<>	
5	<mda< td=""></mda<>	
6	<mda< td=""></mda<>	
7	<mda< td=""></mda<>	
8	5050	

MDA = minimum detectable activity

ATTACHMENT SEVEN PAGE 3 OF 3

RADIOLOGICAL DATA: ISOTOPIC ANALYSES OF PRESSURE HOSE SMEARS

Sample	1	2	3	4	5	6	Z
Actitivity (μ Ci)	3.4E-3	3.1E-2	2.7E-1	1.5E-1	4.7E-2	4.0E-3	1.1E-1
% Of Total Activity							
Co58	NI	NI	2.1	1.6	1.4	NI	1.6
Co-60	. 27.9	16.5	22.3	26.3	26.8	42.1	27.3
Cr51	NI	9.9	18.9	13.8	20.9	NI	21.8
Fe-59	NI	NI	12.2	6.2	6.8	NI	6.7
Mn-54	21.2	8.9	20.7	13.7	18.0	22.3	17.0
Zn-65	51.0	64.7	23.8	38.4	26.1	35.6	25.6

NI = Not Identified

Smear identification:

- 1 Hose end taken May 15 Millstone
- 2 Inside swab of hose #3 taken on May 15 Millstone
- 3 External smear of cavity hose taken on May 17 Millstone
- 4 Inside of cavity hose taken on May 17 Millstone
- 5 Swab #1 of hose #5 Millstone
- 6 -- Swab #2 of hose #5 -- Millstone
- 7 Swab #3 of hose #5 Millstone

All analyses were performed at Millstone

ATTACHMENT EIGHT

RADIOLOGICAL DATA: ISOTOPIC ANALYSES OF REACTOR WATER AND CAVITY WALL

SAMPLE	1	2	<u>3</u>	4
Activity mCi/ml (unless noted)	1.0E-2	1.1E-2	2.1E-2	3.1E00(mCi)
% OF TOTAL ACTIVITY				
Co-58	0.4	0.5	1.0	2.4
Co-60	2.0	1.5	3.2	20.3
Cr-51	0.8	0.3	1.2	15.9
Fe-59	NI	NI	1.5	18.4
Mn-54	1.3	1.2	4.1	28.7
Zn-65	93.8	94.8	88.3	14.3
Cs-137	1.7	1.7	0.7	NI

NI = Not Identified

Sample Identification:

1 – Reactor Water		May	3 -	Millstone	Unit	1
2 - Reactor Water		May S	9	Millstone	Unit	1
3 - Reactor Water		May 1	10 -	Millstone	Unit	1
4 - Reactor Cavity Wall	-	May 1	17 -	Millstone	Unit	1

All analyses were performed at Millstone

ATTACHMENT NINE PAGE 1 OF 2

RADIOLOGICAL DATA: AREA SURVEY OF TRAILER LOCALE AT UNIT 1

Survey on May 15, 1989 By Millstone

RADIOLOGICAL DATA: AREA SURVEY OF TRAILER LOCALE AT UNIT 1

Survey on May 17, 1989 By Millstone

*, .

ATTACHMENT 9 PAGE 2 OF 2

CALCULATIONS:

1. Public dose:

(60 gal) X (0.1 μ Ci/gm) x (4 x 10³ gm/gal) = 24 mCi released

See LADTAP2 printout for dose results.

2. Internal dose:

(15,000 DPM/100 cm²) x 10 = 150,000 DPM/100 cm² initial contamination

(150,000 DPM/100 cm²) x (1,00 cm²) = 1,500,00 DPM on contaminated hand (150,000 DPM for public)

The following values were used to calculate dose

 $(1,500,000 \text{ DPM}) \ge 0.1 = 150,000 \text{ DPM}$ (0.08 µCi) ingested (0.008 µCi for public)

	<u>%</u>	μСі	mRem/µCi/(RG-1.109)	mRem
Co-60	20	0.016	4.7	0.075
Zn-65	20	0.016	7.0	0.112
Co-58	3	0.0024	1.7	0.004
Mn-54	25	0.02	0.9	0.018
Cr-51	16	0.013	0	0
Fe-59	16	0.013	4.0	0.052
			TOTAL:	0.261

For the maximum organ dose the ratio of maximum organ to whole body dose found by LADTAP2 was used to factor the internal whole body dose.

 $\frac{7.92 \times 10^{3}}{2.69 \times 10^{3}}$ X 0.3 mRem = 0.9 mRem (GI ORGAN)

3. Skin dose

(150,00 DPM/100 cm²) x 100 cm² = 150,00 DPM on skin

Used with 5 cm² radius on skin and 24 hour exposure in VARSKIN

See VARSKIN printout for dose results.

Attachment 2.

NORTHEAST UTILITIES NECTIOUT LIGHT AND POWER COM WESTERN MASSACHUSETTS ELECTRIC COMPANY HOLY OKE WATER POWER COMPANY NONTHEAST LITELITIES BERVICE COMPANY ORTHEAST NUCLEAR ENDING COMPAN

June 20, 1989 MP-13224

TO: From:

.5 . 6

care S.E. Scace Station Superintendent Millstone Nuclear Power Station (Ext 4300)

Subject: Procedure Review Approval Process

PORC MEMBERS

By now you should all be aware of the recent incident in which a contaminated hydrolazer trailer was released from the site without being surveyed. Your Superintendent has additional details of the event.

An extensive investigation of the activities for which the trailer was used concluded that the contamination most likely resulted from water siphoning back to the trailer from the refuel cavity during a period of hydrolazer inactivity.

The decontamination work was done using a vendor procedure reviewed and approved by PORC.

This emphasizes the need to ask the WHAT IF questions, especially when reviewing new and third party procedures. I realize that we can never address all possible scenarios which might occur, but I feel that we can increase our efforts to step back, take a good look and ask "What if?"

I have asked each superintendent to use this incident to reinforce the need to thoroughly examine and question these types of issues as they come before PORC.

SES/fdd

cc: W.D.Romberg D.B. Miller Jr. ATTACHMENT 3.

INTEROFFICE MEMORANDUM

Date: 15-Jun-1989 03:51pm EST From: MICHAEL R. STROUT STROUMR AT A1 AT BERLN1 Dept: NUCLEAR OPERATIONS Tel No:

TO: Harry F. Haynes

. ... 2

· · · ·

(HAYNEHF AT A1 AT MP0001)

Subject: NUCLEAR NETWORK OPERATING EXPERIENCE ENTRY

UNIT.									 											 		.MILLSTONE UNIT ONE
EVENT	r r	AC	T	E					 											 		.MAY 16,1989
NSSS/	AI	Ξ.							 											 	 	.GE/EBASCO
RATIN	VG.								 											 		.654MWe
DATE	OI	7	C	01	MI	MI	EI	R	 I.A	L	0	P	E	R	A	T	I	10	٩.	 	 	 .DECEMBER 26, 1970

Millstone Nuclear Power Station conducted a hydrolase decontamination of the Unit 1 cavity during May 1989. During the work process it is postulated that siphoning occured feeding contaminated water back through the hose to the pump and supply tank. The hydrolaser unit was positioned outside of the reactor building in a clean area on the 14'-6" elevation while the decontamination was conducted on the refueling floor 108' elevation. The hydrolaser trailer was released without survey since it had been in a clean area. Millstone was notified of the hydrolaser unit contamination once it was surveyed at the vendor facility. Millstone continues to investigate this occurrence.