NUREG-0040 Vol. 13, No. 1

LICENSEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT

QUARTERLY REPORT January 1989 - March 1989

AR REGU

UNITED STATES NUCLEAR REGULATORY COMMISSION

8905120182 890430 PDR NUREG 0040 R PDR

Available from

*

Superintendent of Documents U.S. Government Printing Office Post Office Box 37082 Washington, D.C. 20013-7082

A year's subscription consists of 4 issues for this publication.

Single copies of this publication are available from National Technical Information Service, Springfield, VA 22161

NUREG-0040 Vol. 13, No. 1

LICENSEE CONTRACTOR AND VENDOR INSPECTION STATUS REPORT

QUARTERLY REPORT January 1989 - March 1989

Manuscript Completed: April 1989 Date Published: April 1989

Division of Reactor Inspection and Safeguards Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, DC 20555

-00



TABLE OF CONTENTS

		Page
1.	Preface	v
2.	Reporting Format	vii
3.	Index	ix
4.	Inspection Reports	1
5.	List of Sclected Bulletins and Information Notices Concerning Adequacy of Vendor Audits and Quality of Vendor Products	71
6.	Table of Vendor Inspections Related to Reactor Plants	72

A fundamental premise of the Nuclear Regulatory Commission's (NRC) nuclear facility licensing and inspection program is that licensees are responsible for the proper construction and safe operation of their nuclear power plants. The total government-industry system for the inspection of nuclear facilities has been designed to provide for multiple levels of inspection and verification. Licensees, contractors, and vendors each participate in a quality verification process in accordance with requirements prescribed by, or consistent with, NRC rules and regulations. The NRC inspects to determine whether its requirements are being met by a licensee and his contractors, while the great bulk of the inspection activity is performed by the industry within the framework of ongoing quality verification programs.

In implementing this multilayered approach, a licensee is responsible for developing a detailed quality assurance (QA) plan. This plan includes the QA programs of the licensee's contractors and vendors. The NRC reviews the licensee's and contractor's QA plans to determine that implementation of the proposed QA program would be satisfactory and responsive to NRC regulations.

In the case of the principal licensee contractors, such as nuclear steam supply system designers and architect engineering firms, the NRC encourages submittal of a description of corporate-wide QA programs for review and acceptance by the NRC. Once accepted by NRC, a corporate QA program of a licensee's contractor will be acceptable for all license applications that incorporate the program by reference in a Safety Analysis Report (SAR). In such cases, a contractors's QA program will not be reviewed by the NRC as part of the licensing review process, provided that the incorporation in the SAR is without change or modification. However, new or revised regulations, Regulatory Guides, or Standard Review Plans affecting QA program controls may be applied by the NRC to previously accepted QA programs.

When design and construction activities were high, firms designing nuclear steam supply systems, architect engineering firms designing nuclear power plants, and certain selected major equipment vendors were inspected on a regular basis by NRC to ascertain through direct observation of selected activities whether these design firms and vendors were satisfactorily implementing the accepted QA program. However, with the substantial decline of new plant design activities, the inspection of QA program implementation has been deemphasized. Instead, the NRC vendor inspection focus has been shifted to vendor activities associated with nuclear plant operation, maintenance, and modifications. Inspection emphasis in now placed on the quality of the vendor products including hardware fabrication, licensee-

PREFACE

vendor interfaces, environmental qualification of equipment, and equipment problems found during operation and corrective action. If nonconformances with NRC requirements and regulations are found, the inspected organization is requested to take appropriate corrective action and to institute preventive measures to preclude recurrence. If generic implications are identified, NRC assures that affected licensees are expeditiously informed.

In addition to the above, the Vendor Program Branch has begun inspections at licensee facilities covering the areas of procurement of replacement parts for use in safety-related systems and licensee/vendor interface programs as requested in Generic Letter 83-28. This edition of the White Book contains copies of the inspection reports of inspections completed to date. Subsequent issues will contain those reports that are issued in the quarterly report period covered by that White Book.

In the past, NRC issued confirming letters to the principal contractors to indicate that NRC inspections have confirmed satisfactory implementation of the accepted QA programs. Licensees and applicants could, at their option, use the letters to fulfill their obligation under 10 CFR 50 Appendix B, Criterion VII, that requires them to perform initial source evaluation audits and subsequent periodic audits to verify QA program implementation. However, based on the above described change in nuclear plant design and construction activities, NRC will no longer issue confirming letters to principal contractors since future NRC vendor program inspections will focus on selected areas rather than addressing the implementation of their respective QA programs. Therefore, confirming letters that have already exceeded their three year effective period will not be renewed. Confirming letters issued less than three years ago will remain in effect until the stated effective period expires. Therefore, as the confirming letters expire, licensees and applicants will no longer be allowed to take credit for the NRC acceptance of the implementation of a principal contractor's QA program. Licensees continue to be responsible for the conduct of initial source evaluation audits and subsequent periodic audits to verify QA program implementation.

The White Book will continue to be published and will contain copies of all vendor inspections issued during the calendar quarter specified. The vendor inspection reports list the nuclear facilities to which the results are applicable thereby informing licensees and vendors of potential problems. In addition, the affected NRC Regional Offices are notified of any significant problem areas that may require special attention. The White Book also contains a list of selected Bulletins and Information Notices involving vendor issues.

The White Book contains information normally used to establish a "qualified suppliers" list; however, the information contained in this document is not adequate nor is it intended to stand by itself as a basis for qualification of suppliers.

Correspondence with contractors and vendors relative to the inspection data contained in the White Book is placed in the USNRC Public Document Room, located in Washington, D.C.

ORGANIZATION: COMPANY, DIVISION CITY, STATE

N

•

		NAMES AN AND ADDRESS OF A DESCRIPTION OF A			
REPORT NO.: Docket/Year/Sequence	INSPECTION DATE:	INSPECTION ON-SITE HOURS:			
CORRESPONDENCE ADDRESS:	Corporate Name Division ATTN: Name/Title Address City, State Zip Code				
ORGANIZATIONAL CONTACT: I TELEPHONE NUMBER:	Name/Title Telephone Number				
NUCLEAR INDUSTRY ACTIVITY: Description of type of components, equipment, or services supplied.					
ASSIGNED INSPECTOR: Name/Vendor Program Branch Section Date					
OTHER INSPECTOR(S): Name, APPROVED BY:	/Vendor Program Branch S	Section			
Name/Chief	- Section/Vendor Program	n Branch Date			
 INSPECTION BASES AND SCOPE: A. <u>BASES</u>: Pertain to the inspection criteria that are applicable to the activity being inspected; i.e., 10 CFR Part 21, Appendix B to 10 CFR Part 50 and Safety Analysis Report or Topical Report commitments. B. <u>SCOPE</u>: Summarizes the specific areas that were reviewed, and/or identifies plant systems, equipment or specific components that were inspected. For reactive (identified problem) inspections, the scope summarizes the problem that caused the inspection to be performed. 					
PLANT SITE APPLICABILITY: List plant name and docket numbers of licensed facilities for which equipment, services, or records were examined during the inspection.					

4

ORCANIZATION: ORGANIZATION CITY, STATE

REPORT NO.:		INSPECTION RESULTS:	PAGE 2 of 2			
Α.	A. <u>VIOLATIONS</u> : Shown here are any inspection results determined to be in violation of Federal Regulations (such as 10 CFR Part 21) that are applicable to the organization being inspected.					
Β.	NONCONFORMANCES: Shown here are any inspection results determined to be in nonconformance with applicable commitments to NRC requirements. In addition to identifying the applicable NRC requirements, the specific industry codes and standards, company QA manual sections, or operating procedures which are used to implement these commitments may be referenced.					
c.	UNRESOLVED ITEMS: Shown information is required items or whether a violar be resolved during subsec	here are inspection results about whi in order to determine whether they are tion or nonconformance may exist. Suc quent inspections.	ich more e acceptable ch items will			
D.	STATUS OF PREVIOUS INSPECTION FINDINGS: This section is used to identify the status of previously identified violations, items of nonconformance, and/or unresolved items until they are closed by appropriate action. For all such items, and if closed, include a brief statement concerning action which closed the item. If this section is omitted, all previous inspection findings have been closed.					
Ε.	INSPECTION FINDINGS AND O significant information of "Inspection Scope." Incl concerning a violation or limitations or depth of i and special circumstances For reactive inspections, disposition or status of inspection to be performe	OTHER COMMENTS: This section is used concerning the inspection areas identi- luded are such items as mitigating cin nonconformance, or statements concer- inspection (sample size, type of revie s or concerns identified for possible this section will be used to summari- the condition of event which caused to ed.	to provide ified under roumstances rning the ew performed followup). ize the the			
F.	PERSONS CONTACTED: Typed	1, Name, Title				
	*present during exit meet	ing				
	(EXPLANATION	SAMPLE PAGE OF FORMAT AND TERMINOLOGY)				

INDEX

FACILITY	REPORT NUMBER	PAGE
Auma Reister KG Mulheim, West Germany	99901134/88-01	1
Combustion Engineering Incorporated Windsor, Connecticut	99900401/88-01	9
Copes-Vulcan Lake City, Pennsylvania	99900080/88-01	19
Ebasco Services Incorporated New York, New York	99900505/89-01	27
Klochner-Moeller Bonn 1, Federal Republic of Germany	999001133/88-01	43
Westinghouse Electric Corporation Pittsburgh, Pennsylvania	99900404/88-02	51
Westinghouse Electric Corporation Pensacola, Florida	99900104/88-01	59
Westinghouse Electric Corporation Pittsburgh, Pennsylvania	99900005/88-01	67

INSPECTION REPORTS



RENC	EPORT	99901134/88-01	INSPECTION RESULTS:	PAGE 2 of
Α.	VIO	LATIONS:		
	No	violations were ident	ified during this inspection.	
Β.	NON	CONFORMANCES :		
	No	nonconformances were	identified during this inspection.	
С.	UNR	ESOLVED ITEMS:		
	No	unresolved items were	identified during this inspection.	
D.	INS	PECTION FINDINGS AND (OTHER COMMENTS:	
	1.	Background Informat	ion	
		electric motor drive 26 years. Auma has Stuttgart, where won actuators are manufa they have supplied a including fossil and including the United SAN type actuators s Institute of Electri 323-1974, IEEE 344-1	en actuators to operate valves for ap a branch factory in Osrfildern, a su rm gear boxes, quarter turn actuators actured. Representatives of Auma star actuators for several industrial appl d nuclear power plants in several cour d States. Documents indicate that SA successfully withstood the test requir ical and Electronic Engineers (IEEE) s 1975, and IEEE 382-1972.	proximately ourb of and small ted that ications ntries, I and rements of standards
		SAI type actuators, are suitable for ins power plants. SAN to outside the contains qualified to meet Ke on IEEE-382, IEEE-32 and KTA-3504.	which have no aluminium on their hous stallation inside the containments of type actuators are suitable for insta- ment. SAN and SAI type actuators were ern Tecnische Anlagen (KTA) requiremen 23, IEEE-467, EPRI NP-2129-1981, EPRI-	sings, nuclear llation e also nts based -1558,
		Nine SAI type actuat to operate stainless installation in the at the Trojan Nuclea	tors were manufactured, tested, and su s steel valves manufactured by Kerotes Steam Generator Blowdown Modification ar Power Plant located in Portland, On	upplied st for System regon.
	2.	Plant Tour		
		The inspector toured storage of purchased	the plant in the areas of machining,	assembly,

REPORT NO.: 9	99901134/88-01	INSPECTION RESULTS:	PAGE 3 of 8		
	area, and the resear tests are being perf assemblers, in-proce test technicians, ar were knowledgeable i	rch and development area where end-of- formed. The inspector interviewed cor ess roving quality control (QC) inspec nd determined that the individuals int in the work they performed.	-life mponent ctors and terviewed		
3.	Quality Assurance Pr	rogram			
	The inspector review Auma and determined Appendix B to 10 CFF and his representation	wed the quality assurance (QA) program that it basically meets the requirement \$ 50. The principal functions of the ives are the following:	n of ents of QA manager		
	a. Control of pure subvendors and	chased materials, including audits of receipt inspections on incoming mater	rial.		
	b. First piece inst thereafter on m inspections.	spections and random sampling inspect machined parts, including roving in-p	ions rocess		
	c. Measurement and	d testing, including control of calib	ration.		
	d. Functional test	ting.			
	e. Final testing.				
	f. Packaging and s	shipping.			
	g. QA documentatio	on.			
	h. Retention of do	ocuments.			
4.	Reviews of Control of Purchased Materials				
	All raw materials, purchased from vendo Periodic audits are Incoming receipt ins Accepted material is automated storeroom, by automated systems	including rotors and stators for motor ors approved by the quality assurance required to be performed on these ver spections are performed on material re adequately identified and transferre Components from the storeroom are re	rs, are department. ndurs. eceived. ed to an retrieved		

REPORT NO.: 99901134/88-01	INSPECTION RESULTS:	PAGE 4 of 8
		And the second se

5. Review of Inspections Performed

The inspector observed the implementation of the inspection program in the following areas:

a. Receipt Inspections

Incoming receipt inspections are performed on all purchased components. Depending on the quantity and complexity, the components are either subjected to 100 percent inspection or statistical sampling. Rotor and stator assemblies for electric motors are purchased from two vendors. Procedure KV-1-5-14-2 GB Revision 2, dated March 18, 1985, entitled "Incoming Goods -Inspection of Motor Components for MDN/MDI Type Motors" is the applicable document used during receipt inspections. This procedure contains instructions for visual inspections and electrical test measurements. A check list attached to the procedure is required to be completed to document the results of the inspection. Rotors and stators failing to meet the established criteria are rejected and returned to the vendor.

b. In-process Inspections

In-process inspections were being routinely performed by roving quality control (QC) inspectors throughout the plant. The inspector observed one cast iron component being inspected after being machined. The component was rejected for flaws on the machined surface, identified as a nonconforming item and segregated. The inspector observed dimensional checks being performed on a randomly selected component on which all the machining operations had been completed. The checks were being performed by a computer-assisted, automatic comparator machine in which the critical dimensions on the relevant drawing were programmed.

The QA manager informed the inspector that if a purchased component is identified to be defective and is rejected during in-process inspections, the component is returned to the vendor. Inspections for the replacement components from the vendor are required to start from the initial step of the inspection procedure. OPCANIZATION . ALIMA PETSTER KG

REPORT	99901134/88-01	INSPECTION RESULTS:	PAGE 5 of 8
	The measuring i observed to hav of calibration that the calibr current.	instruments used in the ins e calibration stickers to and the due date. The ins ation stickers on the meas	spections were indicate the date spector observed suring devices were
6.	Review of corrective	Action	
	The inspector verific process relative to was rejected on Marc dated June 8, 1988, motor assembly, seri- was observed to be b The 1.1 kilowatt (KW intended for LOOVISA purchased from Stahl Auma returned the de along with a copy of determined that a wi vendor supplied a re This motor was tester requirements.	ied the implementation of the rejected material by selected in the rejected material by selected is a selected material by selected is a selected material by selected is a selected by selected that during the selected is a selected by selected is a selected by selected	the nonconformance cting a motor which ce Report (NCR) M175, e final tests of the asured no-load current s (A) instead of 2.6 A. 90/4-75 type motor was inland. The motor was 1d, on March 10, 1988. or on June 13, 1988 mined the motor and short circuited. The rial number 184720. the specification
7.	Review of Quality As	surance Records	
	The inspector review relevant to the supp Portland General Ele operate stainless st installed in the mod Trojan Nuclear Power of the actuators are	ved the following quality a bly of nine SAI 25 type val ectric Company. The actuat ceel valve actuators manufa lified Steam Generator Blow Plant located in Oregon. 4987-69293 to 4987-69301.	assurance records lve actuators to the tors are intended to actured by Kenotest w Down System at the The serial numbers . The quality assurance

The inspection records consisted of the following documents:

Incoming receipt inspection checklist to indicate that the electric motors received from the vendor were inspected to Procedures KV 1-5-14-2. The motor windings have Class 1. H insulation.

REPORT NO.:	r 99901134	/88-	01		1NSPECTION RESULTS:	PAGE 6 of 8
	2	2.	Chec of e 1-5-1	k list lectri 15-2.	documenting the results of the final cal motor assemblies performed to Pro	inspection cedure KV-
	3	3.	Fina 17-2	l test	results of assembled motors to Proce	dure KV-1-5-
	4	1.	Checi accor Nover for and inst	k list rdance mber 1 the ac Inspec ructio	s documenting the results of tests pe to Procedure KV-1-3-33-0 Revision 0, 1, 1987. This procedure, exclusively tuators supplied to Trojan, entitled tion of Auma Actuators Type SA/SAN/SA ons for the following tests:	rformed in dated developed "Final Test I" provided
			a.	Gener	al instructions to follow the procedu	re.
			b.	Visua	1 inspection of the actuator.	
			с.	Insul	ation resistance test of the motor.	
			d.	High	voltage test.	
			e.	Manua drive	l operation and automatic change over on demand.	to electric
			f.	Funct	ional tests.	
			g.	Locke	ed rotor current measurements.	
			h.	Outpu cent cent	it torque closing and opening, measure of nominal voltage (under voltage) ar nominal voltage (over voltage).	ed at 70 per- nd 110 per-
			i.	Setti the c opera	ing the torque switch and the limit sw open and close positions. Number of t ate the limit switch was nine.	vitches for curns to
			j.	Air-t	tightness test.	
			k.	Check	k the operation of all options ordered	1.
			1.	Final	l inspection.	
			m.	Inspe	ection of painting.	

REPORT NO.: 99901	134/88-01	INSPECTION RESULTS:	PAGE 7 of 8
b.	Certifications		
	The documentat	ion contained the following certificat	tions:
	 Certification calibration in the test current and accordance (VDE) and German state 	tion dated January 12, 1988 certifying on of electrical and mechanical instru- sting of the actuators supplied to Tro- nd that the instruments were calibrate e to Vereinigte Deutsche Ectrotechnise Deutsche Industrie Normen (DIN), which andards.	y that the uments used ojan, were ed in che Verein ch are
	2. Certificat material u was purcha quality as to audits	tion dated January 12, 1988, stated thused in the manufacture of the Trojan ased by imposing the requirements of t ssurance manual. The subvendors were by Auma QA personnel.	nat all actuators the Auma subjected
	 Certificat personnel given to 	tion to indicate that all inspection a were qualified and trained. Records individuals on various subjects were a	and test of training available.
с.	Review of Desig	gn Changes	
	The inspector in facture of Auma to the required The only change material was ch swell when it of the support pla type of materia determined to b torque switch w 13 1-4021 becau to wear. Auma invalidate the	reviewed the design changes made in the actuators after the actuators were on ments of IEEE-323, IEEE-344, and IEEE- es were in the materials used. The set hanged from EPD to 70NBR because EPD scame into contact with grease. To fat ate for the torque switch mechanism,) al is being used instead of AI Mg 3F26 be weak. The material for the pinion was changed from X12 Cr MOS 17 1-41-C4 use the latter was determined to be mon had determined that the above changes original seismic and environmental qu	ne manu- qualified -382 in 1979. ealing started to pricate (5 Cr Ni 189 5, which was of the 4 to X20 Cr pre resistant s do not ualifications.
d.	Deviation Report One deviation in in the document list SSAI-01-02 on the worm sha	report (DR), dated December 22, 1987, tation package. The DR identified tha 2 indicated 2 x 19 Belleville springs aft of the SAI actuators. According 1	was included at parts are installed to test

RI	EPORT 0.: 99901134/88-01	INSPECTION RESULTS:	PAGE 8 of 8	
	reports, TB-N star washers we for the SA1-25 was to assemble test reports.	1-1-198, dated October 14, 1982 and R5 ere installed between the Belleville s type actuator. Corrective action rec e the Belleville washers in accordance	541/85/57, springs commended e with the	
Ε.	. EXIT INTERVIEW:			
	The inspector met with persons identified in Section F and discussed the scope and findings of the inspection.			
F.	. PERSONS CONTACTED:			
	R. Dinse, Managing Director K. P. Herr, Technical Director, Sales H. Weber, Marketing Director G. Waldenmaier, Manager, Quality Assurance H. G. Woesner, Research Engineer			

CRGANIZATION: COMBUSTION ENGINEERING, INC. POWER SYSTEMS GROUP WINDSOR, CONNECTICUT

	generality were named and a many more specify water and a state of a state of a state of the state of the state of a stat					
REPORT NO.: 99900401/88-01	INSPECTION DATE: 11/8-10/88	INSPECTION ON-SITE HOURS: 16				
CORRESPONDENCE ADDRESS: Nr. Nuc Com Pow 100 Wir ORGANIZATIONAL CONTACT: Mr. TELEPHONE NUMBER: (203	CORRESPONDENCE ADDRESS: Mr. Walter D. Mawhinney, Vice President Nuclear Quality Systems Combustion Engineering, Inc. Power Systems Group 1000 Prospect Hill Road Windsor, Connecticut 06095 ORGANIZATIONAL CONTACT: Mr. Thomas R. Swift, Manager, Nuclear Quality Systems					
NUCLEAR INDUSTRY ACTIVITY: and has support service cont	CE has had NSSS contracts for cracts for approximately 40 rea	16 domestic reactors, ctors worldwide.				
ASSIGNED INSPECTOR: R. C. M Inspe	Wilson, Engineer, Special Projection Section	/ <u>9/89</u> Date				
OTHER INSPECTOR(S):						
APPROVED BY: Uldis Potapovs Section, Ver	, Chief, Special Projects Inspection Branch, DRIS, N	ection Date				
INSPECTION BASES AND SCOPE:						
A. <u>BASES</u> : 10 CFR Parts 21	and 50					
B. <u>SCOPE</u> : This inspection moisture effects on the trical connectors used Reactor Vessel Level Mo Engineering.	was made as a result of an all environmental qualification of in Core Exit Thermocouple (CET nitoring (RVLM) systems supplie	legation concerning f Litton-Veam elec-) systems and ed by Combustion				
PLANT SITE APPLICABILITY: N report.	umerous; see Section E.4 and Ta	able I at end of				

ORGANIZATION: COMBUSTION ENGINEERING, INC. POWER SYSTEMS GROUP

WINDSOR, CONNECTICUT

REPORT NO.: 99900401/88-01	INSPECTION RESULTS:	PAGE 2 of 10
-------------------------------	------------------------	--------------

A. VIOLATIONS:

None

B. NONCONFORMANCES:

None

C. UNRESOLVED ITEMS:

None

D. STATUS OF PREVIOUS INSPECTION FINDINGS:

None are applicable to the scope of this inspection; none were addressed during this inspection.

- E. INSPECTION FINDINGS AND OTHER COMMENTS:
 - 1. Allegation scope

The allegation consists of two specific concerns, both relating to multi-pin electrical connectors supplied by CE as portions of instrumentation systems required to be environmentally qualified to 10 CFR 50.49. The concerns are as follows:

- a. It was alleged that Core Exit Thermocouple systems are subject to signal errors larger than reported by CE based on qualification test report CE NPSD-230-P. Qualification can only be accomplished by a retrofitted improvement for the original connectors or use of an improved connector, either of which prevents moisture ingress into the connector.
- b. It was alleged that Reactor Vessel Level Monitoring systems supplied by CE and using the Heated Junction Thermocouple (HJTC) principle require periodic testing to maintain qualification because an undersized connector gasket can permit moisture ingress. Undersized gaskets may have been manufactured undersized or may have been compressed during service.

These two concerns were conveyed to CE and were addressed during this inspection.

ORGANIZATION: COMBUSTION ENGINEERING, INC. POWER SYSTEMS GROUP WINDSOR, CONNECTICUT

REPORT NO.: 99900401/88-01	INSPECTION RESULTS:	PAGE 3 of 10
		Company of the second

2. Core Exit Thermocouple System

The CE Core Exit Thermocouple (CET) system is intended to satisfy Regulatory Guide 1.97, and must be environmentally qualified for Loss of Coolant Accidents (LOCAs) and other accidents. The area of concern is a connector that electrically and mechanically joins two multi-conductor, mineral-insulated, metal-jacketed cables, one from the core exit thermocouples and the other to the containment electrical penetration assemblies. The connector is exposed to the containment atmosphere.

CE's original CET connector environmental qualification is based on qualification report CE NPSD-230-P, "Class 1E Qualification of the Core Exit Thermocouple - Mineral Insulated Cables," April 1983 (Proprietary). It covers testing of 8-pin size 20 connectors in the CIR series manufactured by Veam Division of Litton Systems, Inc. used with cable manufactured by Electronic Resources Division Inc. of Whittaker Corp. Size 16 connectors are similar. This report had been reviewed previously during EQ inspections of licensees, and it was reviewed again during this inspection.

Report CE NPSD-230-P documents moisture ingress into the connectors tested. Post-test inspection is reported showing that the face seal gasket was completely degraded, and that the elastomeric inserts used to support pins and sockets were covered with a flaky gray material produced by interaction of the elastomer with borated water which "had obviously leaked into the connector."

A variety of anomalous behaviors occurred during the LOCA test. In evaluating them the inspector reviewed the detailed test report TR-ESE-495 (Proprietary) dated January 7, 1983 and original strip chart recordings of the thermocouple signals. Of particular concern was the impact of periodic cable insulation resistance measurements at 50 vdc, which appeared to charge the cables and cause spurious signal spikes for as long as an hour after voltage application. These tests also decalibrated the recorder amplifiers; the recorder was in fact replaced with a different type midway through the 30-day LOCA test. Thermocouples showed different time responses to temperature changes because of varying thermal masses and junction types (grounded and ungrounded); when intervals between actual temperature changes were rather small, the slowest response thermocouple signal deviated considerably from others because of obvious time lags. The temperature cycling was reduced by more closely controlling the temperature in the reference oven. ORGANIZATION: COMBUSTION ENGINEERING, INC. POWER SYSTEMS GROUP WINDSOR. CONNECTICUT

REPORT NO.: 99900401/88-01	INSPECTION RESULTS:	PAGE 4 of 10
Anomalies were proce test procedure 00000 September 1, 1982. dated October 14, 19 thermocouple signal the test procedure (essed for these abnormalities as requi D-ESE-391 Rev. 01 (Proprietary) dated In particular, Notice of Anomaly No. 082 states the following reason for ap errors greater than the ±22°F allowed (of the order of 45°F):	ired by 2 oparent 1 by
"It is proposed transients crea exposed to a st and humidity or for stored char	d that Meger (sic) testing prior to in ated a capacitor. When the specimen w team environment the Litton connector r wetting of the pins created leakage rge."	nitiating vas leaked paths
Qualification report concluding that the signals caused by in considered in the ev chart excerpts demor in CE NPSD-230-P. E 180-190 foot Chromel connector resistance	t CE NPSD-230-P also discussed this an temporary perturbation of the thermoon sulation resistance checks should not valuation of CET system performance. Astrating the transient behavior are to Bench tests with line resistances simulated 1/Alumel cables and a simulated 1000 of the further showed acceptable performance.	nomaly, couple t be Strip included ulating ohms ce.
Qualification report tion thus convey the qualification of the The connectors are e system accuracy of d ingress and disinted sient spikes as larg This report was issu	t CE NPSD-230-P and its supporting doc e following representations concerning e Litton-Veam connectors in the CET sy environmentally qualified for an overa 22°F; the connectors experienced mois gration of the face seal gasket; and the ge as 45°F had been evaluated as a test and in April 1983.	cumenta- g LOCA ystem. all sture tran- st anomaly.
The attention of the Reactor Vessel Level Section E.3 of this heater current throut tance of a moisture CE then proceeded wit connector for RVLM t	e CE engineers then apparently focused I Monitoring (RVLM) system addressed is inspection report. The RVLM system is ugh the connectors, so the low insular filled connector was recognized as un ith activities intended to develop a ' use, as described in Section E.3 below	d on the in feeds tion resis- nacceptable. "dry" w.
In October 1985 CE f possibility that moi generate a "battery	formed a small task force to investiga isture ingress into the CET connectors effect," such that the LOCA test 45°	ate the s could F spikes

DRGANIZATION:	COMBUSTION ENGINEERING, 1	INC.
	POWER SYSTEMS GROUP	
	LITNINCOU CONNECTICUT	

REPORT NO.: 99900401/88-01	INSPECTION RESULTS:	PAGE 5 of 10
may have be force was u and in Dece was perform (Proprietar dated May 2 to the NRC test" conne The signal uously moni so that the including a errors, a 1 resistance	en real rather than anomalous p nable to rule out the possibili mber 1985 recommended explorato ed late in 1986 as reported in by), undated but distributed to 1, 1987. A summary of the test by letter dated May 22, 1987. ectors in thermocouple circuits emfs from the thermocouples in tored while the connectors were effects of varying amounts of very thin film could be observ ong run of cable was coiled in from thermocouple to connector)	performance. The task ty of a battery effect, ry testing. Such testing NPSD-230-P Supplement 1 customers by letters ing was also transmitted In the "battery effect were thoroughly wetted. a 400°F oven were contin- dried in a 200°F oven, moisture down to and ved. To maximize the oven (1000 ohms
The supplem Litton-Veam in the CET attributed previous ra this error inspection to show tha The inspect satisfactor Branch to a and (2) the	ental test showed that moisture connector can produce spurious system, as had been observed in to anomalies. The May 1987 let ragraph provided analyses to sh in CET systems. Another CE let - November 9, 1988 - provides a t in fact the originally claime or reviewed all of this materia y subject to ongoing review of ddress (1) the acceptability of basis for subsequently reducin	ingress into the signal spikes of 45°F the 1982 testing but ters cited in the ow the acceptability of ter issued during this idditional data analysis d ±22°F is indeed valid. I and found it to be the NRC Plant Systems the quoted ±45°F error ing the error to ±22°F.
The inspect portion of	or concludes that CE's activiti the allegation appear adequate.	es with respect to the CET
3. Reactor Ves	sel Level Monitoring System	
The CE Read tion of nor vessel leve rounded by into HJTC o transmitted	tor Vessel Level Monitoring (RV mal and Heated Junction Thermoc 1, on the premise that an HJTC water than by steam. As noted onnectors is unacceptable becau through the connectors.	LM) system uses a combina- ouples (HJTCs) to monitor will be cooler if sur- above, moisture ingress se of the heater current

ORGANIZATION: COMBUSTION ENGINEERING, INC. POWER SYSTEMS GROUP WINDSOR. CONNECTICUT

REPORT NO.: 99900401/88-01	INSPECTION RESULTS:	PAGE 6 of 10
CE developed two RVLM use. Each u Litton-Veam gaske tured by Union Ca One of the altern RVLM cable manufa Whittaker Corpora connector that ap gasket. The insp for this connecto Class 1E Qualific (ERD) Electrical November 1984 (Pr 16-26-00200-2 and addressed. The d respect to gasket the test specimen One test specimen deviation was add Hartwood Formal R Testing of Class Assemblies" dated selectively revie and Notice of Dev test report, docu loosely mated dur ation test specim a subsequent 24 h leakage was cause irradiation test. cation for ten cy	alternatives to the Litton-Veam connect ses an inorganic Grafoil gasket in plac t. Grafoil is a graphite gasket materi- rbide Corporation. atives is a connector supplied by the C cturer, Electronic Resources Division I tion. This is a conventional type three plies a positive loading force to the G ector reviewed the qualification docume r, including report CE NPSD-275-P "Summ ation Test of the Electronic Resources Connectors and Mineral Insulated Cable" oprietary). The test specimens were mo -4. Both CET and RVLM applications we ocumentation was found satisfactory. W compression by repeated connects/disco s were subjected to ten mechanical cycle admitted water during the LOCA test. ressed in the qualification report and eport No. 558-1572, "Nuclear Qualificat 1E ERI Mineral Insulated Cable and Conne October 31, 1984 (Proprietary) which w wed by the inspector. Change of Proced iation No. 8, both contained in Appendi ment that the leaking connector had bee ing incoming inspection after the gamma ing the LOCA test, and was retorqued. ens did not leak during the 30-day LOCA our submergence test, it was assumed th d by shipping or handling damage to or It appears reascnable to assume type cles aging.	or for e of the al manufac- ET and nc. of aded rafoil ntation ary Report: Division dated dels re ith nnects, es. This in NTS ion ector as ure No. 6 x B of the n found irradi- Since the test or at the from the qualifi-
Litton-Veam conne a Grafoil gasket gasket with a thr connector plug af	ctor to (1) replace the elastomeric gas and (2) add provisions for loading the eaded arrangement that is tightened on ter the bayonet joint between plug and	ket with Grafoil the receptacle

ORGANIZATION: COMBUSTION ENCINEERING, INC. POWER SYSTEMS GROUP WINDSOK, CONNECTICUT

REPORT NO.: 99900401/88-01	INSPECTION RESULTS:	PAGE 7 of 10
The connector is sea to keep its mineral designed to be added connectors, whereas manufacture. Enviro on the ERD connector addressing differenc	1-welded to the metal-sheathed cable insulation dry. The retrofit modific to existing cables with integral Lit the ERD connector could only be used nmental qualification of the retrofit qualification testing supplemented b es in the two designs.	in order ation was ton-Veam for new was based y analysis
The CE qualification "Qualification Summa Litton Connectors," the RDE connector qu and analyses of diff several tests perfor by analysis of torqu Radiation and therma addressed mechanical thermal cycling, vib test specimens had ru inspector concluded based on a reasonable by 10 CFR 50.49 para	report for the retrofit is CE NPSD-2 ry Report for the Grafuil Gasket Retr May 1985 (Proprietary). This report alification report by providing descr erences in the two designs and by des med on the retrofit design. LOCA was es, densities, seal pressures, and the laging were also addressed by analys cycling (Grafoil gasket and Bellevil ration aging, and seismic. One of the eceived radiation and temperature agin that qualification of the retrofit de- e combination of test and analysis as graph (f)(2).	96-P, ofit for supplements iptions cribing addressed e like. is. Tests le spring), e four ng. The sign is allowed
The RVLM portion of cation of the Litton- thin, the clamping do bottoming instead of assuring that the gas travel of the thread mated to its receptad the inspector questic instruction 0000-CCE- Connector Grafoil Gas CE stated that contro proper fit. In addit tions, which addresse and receptacle, state nut rotates past cams gasket partially rein action is completed. evident between the o	the allegation deals with the retrofit -Veam connector. If the Grafoil gask evice may simply achieve a metal-to-me loading the gasket. A possible metho sket is thick enough is to ensure that ed clamp before bottoming is less with cle than with the unmated plug. In the oned CE personnel and also reviewed in -GL80-14, Revision 02, "Guidelines for sket Retrofit," dated November 11, 198 of gasket dimensions and density as tion, step 8.1.3. of the installation es the bayonet action of joining the es "Observe a tactile click as the cou s." The tactile click occurs when the ieves compression as the bayonet coupl Finally, if the gasket is loaded a g clamp locking sleeve and coupling slee	t modifi- et is too etal od of t the h the plug his regard hstallation r Litton 35. ssure instruc- plug upling e grafoil ling gap is eve

ORGANIZATION: COMBUSTION ENGINEERING, INC. POWER SYSTEMS GROUP WINDSOR CONNECTICUT

REPORT NO.: 99900401/88-01	INSPECTION RESULTS:	PAGE 8 of 10
	The second second state of the second s	CONTRACTOR AND A REAL PROPERTY OF A PARTY OF

Although the gap is not mentioned in the installation instruction, it is shown in Figure 1 of the instruction. With respect to compression of the gasket during use, the type qualification limit of ten disconnect cycles and the information described above appear adequate. However, modification of the installation manual to address the gap to specify a minimum dimension, and to alert plant maintenance personnel to address the tactile click and minimum gap each time a connector is reconnected, would appear to be reasonable enhancements.

The inspector concludes that CE's activities with respect to the RVLM portion of the allegation appear reasonable. Adequate qualification basis appears to exist for both the retrofit and ERD connector designs. The retrofit installation instructions also appear to be adequate to ensure Grafoil gasket loading, although they could be enhanced as noted in the previous paragraph.

The inspector noted that various other designs had been considered prior to CE's decision to proceed with the selected retrofit designed. These were not reviewed since only the retrofit design considered was supplied to customers and claimed to be environmentally qualified. Comparison of alternate designs was outside the scope of the inspection except for the similarity argument described above in qualification of the retrofit design.

4. Conclusions

Both parts of the allegations clearly address legitimate technical concerns. The inspector concludes that in each case CE has acted in a reasonable manner and has adequately addressed the area of concern. No violation or nonconformances were identified, either directly related to the allegation or in other inspected areas.

Table I of this inspection report shows the domestic plants using Combustion Engineering CET or RVLM systems, together with the type of connector believed used in each case.

The following plants are also known to have used Litton-Veam connectors in applications other than CE-supplied CET or RVLM systems:

URGANIZATION:	COMBUSTION ENGINEERING, INC.	
	POWER SYSTEMS GROUP	

REPORT NO.: 999	00401/88-01	INSPECTION RESULTS:		PAGE 9 of 10
	<u>Plant</u> Haddam Neck Main Yankee Millstone 3 Documentation re establish LOCA q for any applicat circuits. Furth indicates unsuit qualification.	Docket No. 50-213 50-309 50-423 viewed during this i ualification of uncl ion other than very er, the connector be ability for any othe	Litton-Veam Conne head vent solenoi non-CE CET system transmitter seals nspection clearly doe amped Litton-Veam cor low voltage thermocou havior during the LOC r use requiring LOCA	ector Usage id valves n s, other es not nnectors uple CA tests
 F. <u>PERSONS CONTACTED</u>: W. D. Mawhinney, Vice President, Nuclear Quality Systems *J. J. Holloway, Vice President, Nuclear Services *T. R. Swift, Manager, Nuclear Quality Systems *W. A. Goodwin, Director, Nuclear Quality Systems *S. A. Toelle, Manager, Licensing *J. M. Burger, Nanager, Mechanical Systems E. A. Siegel, Manager, Plant Structures *J. M. Betancourt, Senior Consulting Engineer, Licensing *D. M. Amidon, Engineer, Quality Programs 				

ORGANIZATION: COMBUS POWER WINDSO	TION ENGINEERING, IN SYSTEMS GROUP R. CONNECTICUT	IC.	
REPORT NO.: 99900401/88-01	INSPECT RESULTS	ION :	PAGE 10 of 10
TAB	LE I. PLANT USEAGE O IN CET AND RVL	F CE CONNECTORS M SYSTEMS	annan margaran ann ann ann ann ann ann ann ann ann
Plant(s)	Docket No.(s)	CET System Conn. Type	RVLM System Conn. Clamped
Braidwood 1, 2 Byron 1, 2 Catawba 1, 2 Comanche Peak 1, 2 D.C. Cook 1, 2 Farley 1, 2 Fort Calhoun Haddam Neck Indian Point (future) McGuire 1, 2 Millstone 2 Millstone 3 Palo Verde 1, 2, 3 Prairie Island 1, 2 St. Lucie 1, 2 Salem 1, 2 Salem 1, 2 Saummer Trojan Turkey Point 3, 4 WNP-3 Zion 1, 2	50-456, 457 454, 455 413, 414 445, 446 315, 316 348, 364 285 213 247 369, 370 336 423 528, 529, 530 282, 306 335, 389 272, 311 361, 362 498, 499 395 344 250, 251 508 295, 304	N/A N/A Litton-clamped N/A ERD Litton Litton Litton-clamped Litton Litton Litton Litton Litton Litton Litton Litton Litton Litton Litton ERD Litton ERD Litton ERD	only HJTCs only HJTCs N/A (DP) Yes N/A (DP) Yes Yes N/A (DP) Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes

N/A designates system and connectors not supplied by CE. DP designates differential pressure level instrument.

REPORT INSPECTION INSPECTION ON-SITE HOURS: 68 NO.: 99900080/88-01 DATE: November 7-11, 1988 CORRESPONDENCE ADDRESS: Copes-Vulcan Martin and Rice Avenues Lake City, Pennsylvania 16423 ORGANIZATIONAL CONTACT: Mr. Dale Mays, QA Director (814) 774-3151 TELEPHONE NUMBER: NUCLEAR INDUSTRY ACTIVITY: The majority of Copes-Vulcan's current work is in the design and manufacturing of valve assemblies used in military nuclear applications and the manufacture of piece-part valve assembly replacement parts for commercial nuclear applications (e.g., valve trim). ASSIGNED INSPECTOR: 1,221 Petrosino, Reactive Inspection Section J. J./ Date No. 1 (RIS-1) OTHER INSPECTOR(S): J. A. Gavula, NRC Region III, Division of Reactor Safety T. L. Tinkel, NRC Consultant Daker, Chief, RIS-1, Vendor Inspection Branch APPROVED BY: INSPECTION BASES AND SCOPE: BASES: 10 CFR Part 21 and Appendix B to 10 CFR Part 50. Α. SCOPE: This inspection was conducted as a result of piping systems at Β. Prairie Island that were found to be outside of their safety analysis report design limits. PLANT SITE APPLICABILITY: All plants.

REPONO.:)RT : 99900080/88-01	INSPECTION RESULTS:	PAGE 2 of 8	
Α.	VIOLATION:			
	Contrary to Section of a defect" of 10 C of its commercial nu assembly center-of-g for valves supplied information had been resulted in a 10 CFR	21.21 "Notification of failure to comply FR Part 21, Copes-Vulcan (C-V) failed to clear valve assembly customers of incorre ravity and/or weight information on all o to customers prior to November 28, 1979. adequately evaluated at the time it would Part 21 report (88-01-01).	or existence notify all ct valve f its drawings If the d have	
	This is a Severity L	evel III Violation (Supplement VII).		
Β.	NONCONFORMANCE :			
	Contrary to Criterio Part 50 , Copes-Vulc weight determination other than the indiv	n III "Design Control," of Appendix B to a an failed to ensure that its center-of-gra s were checked for technical adequacy by idual who performed the work (88-01-02).	10 CFR avity and someone	
С.	UNRESOLVED ITEMS:			
	None.			
D.	STATUS OF PREVIOUS I	NSPECTION FINDINGS:		
	Not reviewed during this inspection.			
Ε.	OTHER COMMENTS:			
	1. Entrance and Ex	it Neetings		
	The NRC inspect the scope of th November 7, 198 observations, a Copes-Vulcan co be affected by center-of-gravi cause an evalua NRC licensee fa	or informed the Copes-Vulcan representative is inspection during the entrance meeting 8 and summarized his inspection findings, nd NRC staff concerns during the exit meet mmitted to identify all of its customers we certain incorrect valve assembly weight are ty information and notify each so that the tion to be performed or to notify the applicities.	ve of on ting. who may nd/or ey may licable	
	2. Background of W	eight and Center-of-Gravity Issue		
	The NRC concern Power Company (applicability o	was identified in part during a 1988 Nort Prairie Island) engineering review regardi f the seismic issues discussed in NRC Bull	thern States ing the letin 79-14.	
in excess a subsected tenter			anna a' failte ann an t-ann a	

REPORT	INSPECTION	
NO.: 99900080/88-01	RESULTS:	PAGE 3 of 8
nenena - neuronfelantelarena kenar herrikarena kenar herriaren erriaren erriaren erriaren erriaren erriaren an Arrieren	а кладрактона дечака на полиника и прократка и на бито у украти на при трани и на полини и на полини на полини По кладракто на полини и на полини и на полини и на бито у украти на полини и на полини на полини на полини на п	NAMES AND ADDRESS AND ADDRESS A

During the Prairie Island engineering review of its seismic piping system analyses, design basis information for one specific C-V valve could not be found. As a result, the engineering consultant, Fluor Daniel (F-D), requested the valve design information from C-V. Prior to F-D receiving the valve design information from C-V, the original design basis documents were found by F-D, who compared the information to the original seismic analyses input and found the data to be consistent. However, after receiving and reviewing the new C-V design information, F-D noted that it contained different, nonconservative valve assembly weights and center-of-gravity (CG) data. As an example, the original small bore C-V valve assembly information showed a specific valve assembly weight to be 170 pounds and its CG to be just above 5 inches from the datum point. Conversely, the new C-V valve assembly information indicated the same valve to weigh 240 pounds and have a CG of 19 inches from the datum point.

The new C-V supplied weights and CG data were then inserted into the original stress calculation at Prairie Island. As a result of the new analyses, several Prairie Island piping system stresses were found to exceed the Final Safety Analysis Report (FSAR) requirements. In one instance stresses increased from approximately 32,000 psi to approximately 161,000 psi.

The NRC Vendor Inspection Branch reviewed the circumstances surrounding the issue. The inspection identified, in part, that C-V valve assembly weights and center-of-gravity data given on customer design drawings shipped prior to November 28, 1979 could be incorrect. There is no one reason for the incorrect values. However, a few contributors are the failure to include the mass of the operator in the weight and CG calculation, using the CG for the valve and bonnet only, and not accounting for a forged valve body instead of a cast valve body.

Note: Subsequent to the NRC inspection at C-V, the Region III NRC inspector identified that a similar condition was present at D. C. Cook Units 1 and 2. The overstress condition exceeded the D. C. Cook FSAR design limits.

3. Potentially Reportable 10 CFR Part 21 Items

Section 21.21 "Notification of Failure to Comply or Existence of a Defect," of 10 CFR Part 21 requires in part, that each individual, corporation, partnership or other entity subject to Part 21 adopt appropriate procedures to provide for evaluating deviations or

REPORT NO.: 99	900080/88-01	INSPECTION RESULTS:	PAGE 4 of 8
	informing the licens licensee or purchase	see or purchaser of the deviation er may cause the deviation to be	on so that the e evaluated.
	Contrary to this, is problems with its co ated with its valve nuclear power plants either evaluate the purchasers. This is	t was iden ified that C-V became enter-of-gravity data and/or we assemblies that were shipped to s prior to Notember 28, 1979, an deviation or to notify all the sue is identified in Violation 8	e aware of ights associ- o numerous nd failed to applicable 88-01-01.
	Based on a review of it appears that the identified in Novemb by the Farley Nuclea regarding the C-V va sales agent then rev the Farley architect then contacted the of to advise them that drawings and asked W this point Westingho or written correspon must go through W. approximately 42 que unclear as to what a based on information	f documents and discussions with issue of incorrect CG data and, ber of 1979 to a C-V sales agent ar Plant based on a CG and/or we alve assembly drawings for Farle viewed the C-V drawings and subm t-engineer, Bechtel Power Corpor original purchaser, Westinghouse they had received uncontrolled Westinghouse for additional info cuse (W) notified C-V that any f indence or information of a techn Bechtel, at this time, had iden estionable C-V drawings to W; ho additional W or Bechtel actions in available at C-V.	h C-V personnel, /or weights was t in Alabama eight concern ey. The C-V mitted them to ration, who e Corporation, revised ormation. At further verbal nical nature ntified owever, it is were performed
4.	Design Control Criterion III, "Desirequires, in part the verifying or checkin verifying or checkin than those who perfo	ign Control," of Appendix B to 1 hat design control measures will ng the technical adequacy of the ng process will be performed by ormed the original design.	10 CFR Part 50 1 provide for e design. The personnel other
	and associated weigh the same engineer wh his own work. This	some C-V calculations for valve hts it was noted that the C-V pr no performs the CG and weight ca issue is identified in Nonconfo	assembly CG data ractice is to have alculations verify ormance 88-01-02.
	Weight and CG calcu	lations that were reviewed are a	as follows:
	3/4-1458-R	DRAWING NO.	
	1-IA56-R5 1-IA56-RE	L-137918 L-137968	

REPORT NO.: 9990008	0/88-01	INSPECTION RESULTS:	PAGE 5 cf 8
	VALVE ID	DRAWING NO.	
2	-IA58-RE 1-ID56-R 1-ID58-R 2-ID58-R	L-138049 B-132315 B-132318 B-132338	
Addition reviewed sections accelera verify n seismic appropri as well these ev non-repr for the into the calculat	ally, some C-V val . These analyses for assumed horiz tions. Fundamenta on-participation of event. Simplified ate assumptions. as other valve acc aluations. The pr esentative weight valve discussed in seismic evaluatio ions reviewed were	lve/operator assembly analyses were evaluated various critical valve contal and vertical static al frequencies were also determined to of the valve/operator assembly during d analytical techniques were used wit The CG's and weights of the operator cessories, were properly included in reviously discovered issue of and center of gravity calculations in item E.2 above was not carried over ons. Some of the C-V seismic	.0 1 a .h .s,
a. C-V inc 14G	calculation No. 1 luded valves: 3IA M48SEZ.	10.3.119, dated March 31, 1977, which A58RGP, 2IA58RG, 2RA56RE, 8RA36RG, an	d
b.	C-V calculation included valves: 1IA58RE, 1IA38RE 3IA58RGP, 3WA42R	No. 10.3.132, dated October 20, 1978 3/4 IA58RE, 1WA42DD, 1IA56RE, 1IRA S, 2RA42RD, 2RA56DD, 2RA56RE, 2IA58R KE, and 4RA58RGA.	, which 58RD, G,
с.	C-V calculation included valve:	No. 10.3.337, dated February 14, 198 D-100-160, 2 inch, class 1500.	6, which
d.	C-V calculation valves: 2RA42DD	(No ID), dated May 25, 1978, which i) and 21A58RE.	ncludes
5. <u>Cus</u>	tomer Notification	s and Scope	
It west that West The Nove safe cust CG at t	was determined by t C-V had not noti tinghouse, of the time frame for th ember 28, 1979. T ety-related valve tomers prior to No information. The the Prairie Island	the NRC inspector and the C-V repres fied any of its customers, other tha problem regarding incorrect weight a be problem has been established as pr he scope of the problem includes all assembly drawings that were provided ovember 29, 1979 that included weight significance of the problem was obvi nuclear plant where a reanalysis of	entative n nd CG data. ior to C-V to s and/or ous some

REPORT NO.: 9990C080/88-01	INSPECTION RESULTS:	PAGE 6 of 8
safety-related pipin and CG's revealed pi limits.	g systems in 1988 using the co ping system stresses that exce	orrect weights eeded the design
It was noted that the in 1979-1980 on all of the C-V and W meet determined that the at the C-V facility meeting that W appear problem. However, W made aware of this de	e C-V staff implemented correct of its <u>in-house</u> drawings after ting in November of 1979. The M and C-V meeting occurred on in Pennsylvania. It was at th rs to have been formally notif appears to be the only C-V cu eviation.	ctive actions r completion e NRC inspector November 28, 1979 his W documented fied of the istomer that was
As a result of discussion committed to compile exception of \underline{W} , since notify each customer	ssions between C-V and NRC sta a list of all its customers, e W is already aware of the pr within 30 days of the NRC's e	aff, C-V has with the coblem, and to exit meeting.
Following is a partia supplied based on inf lists:	al list of licensees and the t formation available from C-V's	ype of valves valve user
Acrynonyms		
FW - Feedwater Valve AO - Air Operated Val MO - Motor Operated V FWB - Feedwater bypa	SV - Sampling V Ive MT - Manual Thr Valve SD - Steam Dump ss valve BOP - Balance o	alve ottling of Plant
Plant	Known Valv	e Application
Beaver Valley 1 Beaver Valley 2 Bellefonte Braidwood 1 & 2 Browns Ferry 1 Byron 1 & 2 Callaway Calvert Cliffs 1 & 2 Comanche Peak 1 & 2 Comanche Peak 2 Cook 1 & 2 Crystal River 3 Davis-Besse Diablo Canyon 1 & 2 Dresden 2 & 2	FW, AO, MO FW, AO, SV FW AO, MO, SV BOP AO, MO, SV FW, AO, FW SD, BOP FW, AO, SV FW, AO, SV FW, AO, SV BOP BOP BOP FW, AO, SD FW, BOP	, SV, BOP , BOP , MT, SD, BOP , MT, BOP B, BOP , BOP , BOP

REPORT NO.: 999	00080/88-01	INSPECTION RESULTS:	PAGE 7 of 8
REPORT NO.: 999	Plant Farley 1 & 2 Fort Calhoun Ginna Harris Indian Point 2 & 3 Kewaunee Limerick 1 & 2 Maine Yankee McGuire 1 & 2 Millstone 1, 2, & 3 Montice 10 Nine Mile Point 1 Nine Mile Point 2 North Anna 1 & 2 Palisades Perry Pilgrim Point Beach 1 & 2 Quad Cities 1 & 2 River Bend 1 Robinson 2 Salem 1 & 2 Salem 1 & 2 Salem 1 & 2 Salem 1 & 2 Sun Onofre 2 & 3 Seabrook Sequoyah 1 & 2 Shoreham South Texas 1 & 2 St. Lucie 1 St. Lucie 2 Summer 1 Surry 1 & 2 Susquehanna Trojan Turkey Point 3 & 4 Vogtle 1 & 2 Watts Bar	INSPECTION RESULTS:	<pre>Known Valve Application AO, BOP BOP FW, AO, BOP FW, AO, SV, BOP FW, AO, SV, BOP FW, AO, BOP FW, SD BOP FW, BOP FW, BOP FW, BOP FW, BOP FW, BOP FW, BOP FW, BOP FW, BOP FW, BOP FW, AO, SD, BOP FW, AO, SD, BOP FW, AO, FWB, BOP FW, AO, FWB, BOP FW, AO, SV, BOP FW, AO, SV, BOP FW, AO, SV, BOP FW, AO, SV, BOP FW, AO, SD, BOP FW, AO, SD, BOP FW, AO, SD, BOP FW, AO, SD, BOP FW, AO, SV, BOP FW, AO, SD, BOP FW, AO, SV, BOP SPC, AO, SD, BOP FW, AO, SV, BOP FW, AO, SD, BOP FW, AO, SV, BOP FW, AO, SD, BOP FW, AO, SD, BOP FW, AO, SV, BOP FW, AO, SD, BOP FW, AO, SV, BOP SV, AO, SD, BOP FV, AO, SD, BOP FW, AO, SV, BOP SV, AO, SD, BOP</pre>
	Watts Bar Wolf Creek Zion 1 & 2		SV, AO, SD, BOP FW, AO, FWB, BOP AO, BOP

REPORT	INSPECTION	
NO.: 99900080/88-01	RESULTS:	PAGE 8 of 8

6. Sliding Stem Friction Forces

Recently, NRC Information Notice (IN) 88-94, was issued regarding valve stem packing friction forces. Fisher Controls notified the NRC of its concern with valve stem packing friction forces which increase due to use of graphite or graphite/asbestos packing in valves that were originally supplied with teflon packing, and of licensees replacing preformed valve stem packing with graphite ribbon packing. One aspect of this inspection was to verify whether C-V explicity accounted for valve stem friction forces. It was found that C-V does account for the added forces; therefore, this area was classified as satisfactory.

F. PERSONNEL CONTACTED:

NAME

Dale Mays Tim Kunkle Chuck Dundon Allan Shea Norman Mattson T. J. Billings J. R. Scarpelli J. Clifford TITLE

QA Manager Product Design Manager Sr. Contract Engineer Sr. Design Engineer Valve Contract Manager NDT Specialist QA Supervisor Sales Engineer
NEW	YORK, NEW Y	/ORK		and a second state of the second
REPORT NO.: 99900505/89-0	1	INSPECTION DATE: January 23-27, 19	INSPECTIO	DN HOURS: 42
CORRESPONDENCE ADD	RESS: Mr. (Qual Ebaso Two W New Y	Charles R. Healy, Direct ity Assurance co Services Incorporated World Trade Center York, New York 10048	tor 1	
RGANIZATIONAL CONTACT: Mr. Sal Sparacino, Manager, QA Engineering ELEPHONE NUMBER: (212)839-2457				
activities for sev	eral nuclea	r projects.		
ASSIGNED INSPECTOR	: R.L. Pe Section I	hat Petty /r ttis, Jr., Reactive Insp No. 1, Vendor Inspection	pection n Branch	3/22/89 Date
APPROVED BY:	: T. Tinke	, Reactive Inspection S	ection No. 1, VIB	3/23/89 Date
INSPECTION BASES A	ND SCOPE:			
A. <u>BASES</u> : 10 C "Nuclear Qua	FR Part 50, lity Assura	Appendix B, Ebasco Top nce Program Manual," an	ical Report ETR-1 d 10 CFR Part 21.	001
B. <u>SCOPE</u> : Foll personnel re Steam Electr	ow-up inspe garding Eba ic Station	ction to review records sco's procurement activ (SES) during the period	, procedures and ities at the Wate 1981-1983.	interview rford 3
PLANT SITE APPLICA	BILITY: Wa	terford 3 SES (50-382).		

REP NO.	CRT : 99900505/89-01	INSPECTION RESULTS:	PAGE 2 of 15
réasolation se statutation	ANNER MET MENNEN MENNEN VER KERTER KERTER KAN DER KERTER MENNEN VER BERKEN VER KERTER KERTER VER KERTER KERTER	993 M 1997 M 199	
Α.	VICLATION:		
	Contrary to Section 21.31 of placed two purchase orders safety-related electrical m the requirements of 10 CFR (89-01-01).	of 10 CFR Part 21, Ebasco Services 1 (POs), WP3-13587 and WP3-137680 for material for Waterford 3 SES without 21 on the purchase order to the sup	Incorporated specifying pplier
	This is classified as a Sev	erity Level IV violation (Supplemer	t VII).
B.	NONCONFORMANCE:		
	Contrary to Ebasco Services "E," dated April 20, 1978, Ebasco placed 35 safety-rel supplier being on Ebasco's	Incorporated Procedure No. ASP-I-5 "Quality Assurance Evaluation of Su ated POs with the Gismo Company wit Approved Suppliers List (89-01-02).	, Issue ppliers," hout the
С.	UNRESOLVED ITEM:		
	The NRC inspector was unabl Ebasco New York Quality Ass rejected by Ebasco but late Suppliers List (89-01-03).	e to review supplier evaluations pe urance personnel for suppliers prev r approved and placed on Ebasco's A	rformed by fously pproved
D.	STATUS OF PREVIOUS INSPECTI	ON FINDINGS:	
	Not Applicable		
E.	INSPECTION FINDINGS AND OTH	ER COMMENTS:	
	The inspection was performe performed at Ebasco, New Yo which was prompted by a com- ment of Labor (DOL) by a fo The complaint alleges that its internal procedures in and component suppliers for claims that certain supplie safety-related components a the alleger claims, because suppliers and any delays co construction schedule, Ebas evaluate these suppliers who	d as a follow-up to an earlier insp rk (NRC Inspection Report No. 99900 plaint of discrimination filed with rmer Ebasco employee and referred t Ebasco had violated 10 CFR 50, Appe the evaluation and approval of cert the Waterford 3 SES. Specifically rs were found unsatisfactory for su nd materials in the 1981-83 time fr Ebasco had already placed POs with uld impact unfavorably on the Water co sent other auditors (unqualified o subsequently found them to be sat	ection 505/88-01), the Depart- o the NRC. ndix B, and ain material , the alleger pplying ame. Further, these ford 3 SES) to isfactory.

REPORT NO.: 99900505/89-01	INSPECTION RESULTS:	PAGE 3 of 15
	TEXAND LANDING VERY STREND VERY RICH AS VERY DARK AND TAKEN AND THE TEXANDER OF TAXABLE AND THE TAXABLE AND TAXABL	NUMBER OF STREET, STOLEN OF STREET, STREET

To determine the validity of the above allegations, an NRC inspection was performed at the Ebasco New York office in August 1988 to review the pertinent records and related procedures. Immediately prior to the inspection, the NRC inspectors met with the alleger to identify more clearly the specific records and areas of concern. The results of this inspection are documented in NRC Inspection Report No. 99900505/88-01, dated September 28, 1988.

As a result, it was further determined by the NRC that an additional inspection be performed at the Waterford 3 SES to review Ebasco's procurement documents generated during this period in order to determine the safety-related significance, if any, associated with the alleger's concerns since these documents were not available during the August 1988 inspection. This report documents that review.

1. Review of the Ebasco New York and Waterford 3 SES Approved Suppliers Lists (ASL)

It was alleged that Ebasco maintained a "supplementary Approved Supplier List (ASL)," known as the "Waterford 3 list," that included suppliers who could not be approved due to the lack of a 10 CFR 50, Appendix B quality assurance program. However, due to the exigencies of the construction schedule, these suppliers were nevertheless utilized to provide safety-related components and materials for the waterford 3 SES project.

Background

The NRC inspectors reviewed the Ebasco files on-site that contained the list of approved suppliers used for the Waterford 3 SES project. It was determined that Ebasco maintained two separate lists for the reason that suppliers contained on the Waterford 3 SES project list were unique to the project, and that the cost incurred by Ebasco to audit these suppliers would not be shared by other Ebasco projects. The NRC inspectors reviewed both ASLs covering the period 1978-1984 and determined that suppliers utilized for safety-related materials at Waterford 3 SES were, with several exceptions noted, qualified to be included on Ebasco's ASL. The Ebasco New York ASLs and supplements reviewed were as follows: December 31, 1981; March 31, 1982; May 3, 1982; June 1, 1982; July 19, 1982; August 16, 1982; September 30, 1982; December 30, 1982; February 1, 1983; March 31, 1983; June 30, 1983; August 1, 1983; September 30, 1983; and December 30, 1983. The Ebasco Waterford 3 SES ASLs reviewed were

REPORT INSPECTION NO.: 99900505/89-01 RESULTS: PAGE 4 of 15

> as follows: January 6, 1982; June 3, 1982; November 22, 1982; March 9, 1983; June 17, 1983; September 8, 1983; and December 15, 1983. Safety-related suppliers are those suppliers deemed capable by Ebasco to provide permanent plant material and equipment in accordance with the guidelines established by the Ebasco Licensing Department to be ASME Code Class 1, 2, 3, Seismic, or Electrical Class 1E. Nonsafety-related applies to all other permanent plant idems.

According to Paragraph 7.1.3 of Ebasco Procedure No. QAP-9, Revision 1, dated September 29, 1978, "Quality Assurance Vendor Evaluations," qualified suppliers are placed on the ASL by an Ebasco review of their Quality Assurance (QA) Program. An initial or pre-award audit is then conducted for those first time suppliers placed on the ASL, with a follow-up audit performed three years later, as determined by the Ebasco Vendor Evaluation Group Leader. Suppliers included on the ASL, according to Paragraph 10.1.1, are those whose documented quality program and facility are considered "Satisfactory" in accordance with Ebasco Procedure No. QAP-9, Paragraph 7.7.1 and therefore authorized to receive a nuclear safety-related PO. At the end of the suppliers periodic audit date, the supplier must be reaudited or dropped from the ASL.

It was noted that not all suppliers listed on the Ebasco Waterford 3 SES ASL were required to implement or maintain a full 10 CFR 50, Appendix B QA program. In some cases, the quality requirements applicable to an order were defined in a procurement specification that was referenced in the basic PO to a supplier. The range of supplier quality programs required by these procurement specifications varied from some that were very limited to some that essentially required a complete 10 CFR 50, Appendix B program. Examples of suppliers with whom Ebasco used a procurement specification to define supplier QA program requirements included: Appleton Electric, Wheatland Tube, Picoma Industries, Conduit Pipe Products, Crouse Hinds Company, Gismo Company, and the O. Z. Gedney Company. All suppliers were included on the Waterford 3 SES "Supplemental" ASL and were scheduled for reaudit in early 1983. In each case, POs reviewed were for safety-related electrical material (i.e., galvanized rigid steel conduit, fittings, couplings and related interface material) and were placed by Ebasco during the 1978-1984 period time frame. Those POs referenced Ebasco project specifications which in-turn referenced the QA requirements in accordance with Ebasco Specification 860-80, "QA Requirements for Suppliers of Safety-Related

REPORT NO.: 99900505/89-01	INSPECTION RESULTS:	PAGE 5 of 15
Equipment and Servic Kequirements for Sup specifications reter LOU-1564.065, .066, .403.	ces," or Specification 860-72, "Qualit opliers of Equipment and Services." P enced for the POs reviewed were as fo .068, .124F, .249A, .249D, .249R, .27	y Control Project 11ows: 10, and
Specification 860-72 a 10 CFR 50, Appendi and then invokes 10 applications, wherea 50, Appendix B, and Specifications refer were imposed with th requiring the suppli Control (QC) manual contract award, a re performed by Ebasco	e outlines the QA requirements (which ix B program) for nonsafety-related ap CFR 50, Appendix B, for all safety-re- as 860-80 imposes the requirements of 10 CFR Part 21. In five of the nine renced, either 860-80, or 860-72 speci- be balance referencing only a paragrap for to submit a controlled copy of his with his bid for Ebasco review. Price eview of the supplier's facility would to evaluate the supplier's quality pr	resemble plications lated 10 CFR LOU fications bh Quality or to i be rogram.
Ebasco's acceptance mentioned above rais approving suppliers Appendix B, QA progr equipped to handle a to the nature of the (i. , galvanized ri QA program incorpora to the product furni cation various techr receipt inspection, with the intent of A	of a "Limited QA" program for supplied sed concerns with the alleger that Eba without their having a full 10 CFR 50 cam. It should be noted that supplier full 10 CFR 50, Appendix B, QA progre- item being supplied to Waterford 3 S igid conduit) were required to have a sting only those items of Appendix B a ished. In addition, Ebasco invoked by nical and quality requirements (codes, tests, etc.) necessary to achieve con appendix B.	ers isco was 's not am, due EES "limited" applicable specifi- , standards, mpliance
This methodology is Appendix B which sta appendix apply to al functions of those s addition, Criterion the program shall pr their importance to applied to these sup to meet applicable r relative safety sign inspectors did not r extent that their QA of Appendix B.	discussed in the Introduction to 10 (ites, "the pertinent requirements of t lactivities affecting the safety-rel stuctures, systems, and components." II, "Quality Assurance Program," stat rovide control to an extent consistent safety. Therefore, the "Limited QA" opliers in the late 1970 time frame ap regulatory requirements considering the ificance of the material purchased. review each supplier's QA file to deter a program complied with the applicable	CFR 50, this lated In tes that t with program opeared the The NRC ermine the portions

NU.: 99900505/89-01 RESULTS:	PAGE 6 of 15
------------------------------	--------------

It was noted during the inspection that 35 safety-related POs were placed by Ebasco with the Gismo Company for various electrical interface material without the supplier's appearing on the ASL. These POs were placed during the period May 1978 through June 1980. A review of Ebasco's AS's also indicated that Gismo appeared on the ASL prior to and after the time period referenced. As a result, Nonconformance 89-01-02 was identified during this part of the inspection.

2. Purchase Order Review - 10 CFR Part 21

During the NRC review of safety-related POs generated by Ebasco, it was observed that the majority of the POs invoked the requirements of 10 CFR 21 on the supplier. However, two POs failed to specify that Part 21 applied: PO WP3-137680, dated December 15, 1983, to Appleton Electric and WP3-13587, dated December 4, 1983, to Crouse Hinds (both for safety-related electrical interface material). As a result, Violation 89-01-01 was identified during this part of the inspection.

3. Review of Ebasco Performed Supplier Evaluations

In a letter dated March 8, 1983 from Mr. M. Brooks (Ebasco Site) to Mr. R. Williams (Ebasco, New York), it was discussed that several "key" suppliers of safety-related electrical material, soon due for reaudit have been rejected by New York Quality Assurance due to the suppliers' inability to comply with 10 CFR 50, Appendix B requirements. The suppliers referenced were the following: Conduit Pipe Products, Picoma Industries, Wheatland Tube Company, O. Z. Gedney Company, Crouse Hinds Company, Electromark, Gismo, and Appleton Electric. A review of the Ebasco Waterford 3 SES ASL, dated December 15, 1983 indicated that all eight suppliers were included on the ASL. The basis for placing these suppliers on the ASL was supplier audits performed by Ebasco New York auditors during the period March - May 1983. As a result, these suppliers were deemed satisfactory and were placed on the ASL despite earlier rejection of these suppliers.

The NRC inspectors were unable to review the Ebasco audits performed since the files are located at Ebasco's New York office. As a result, Unresolved Item 89-01-03 was identified and will be reviewed during a future inspection at Ebasco New York.

NO.: 99	90050	5/89-(01	INSPECTION RESULTS:	PAGE 7 of 15
4.	Rev	iew of	f the Rotoha	ammer Company	
	Info Ebas pure appr Ebas of 1 ind fol	ormati sco in chased roved sco en 10 CFF icated lowing	ion obtained dicated that supplier. sployee as t 21; howeve i "not report Ebasco doo	d by the NRC during the August 1988 in at safety-related valve stem extension Rotohammer Company who, at the time, w In addition, this breakdown was viewe being reportable to the NRC under the er, the nonconformance reports generat rtable." In order to review this cond cumentation was reviewed by the inspec	nspection of material was was not an ed by an provisions ted by Ebasco cern, the ctors:
	a.	Purc plac this	chase Order ed with Rot purchase c	NY 403568. This was the initial Ebas tohammer on January 11, 1977. A revie order indicated the following:	sco PO ew of
		(1)	The PO was extension nonsafety-	s placed for various quantities of val equipment which was classified as related.	lve stem
		(2)	The PC inv 2, dated J valve stem seismic va tions and non-nuclea The specif "Quality C and Servic quality co equipment states tha vendor's q requiremen	woked Ebasco specification LOU-1564.12 anuary 11, 1977. This specification in extensions for non-nuclear seismic a lives. Paragraph 5 addresses seismic states that seismic I valves shall be ir, nonsafety, but shall be seismicall fication also invokes Ebasco specifica ontrol Requirements for Suppliers of es," which states that this document introl requirements applicable to supp and their subvendors. In addition, 8 it for safety-related material and ser uality control program shall also mee its of 10 CFR 50, Appendix B.	24, Revision applies to and non- considera- considered y supported. tion 860-72, Equipment covers liers of 660-72 vices, the t the
		(3)	Fourteen s Ebasco New plement 14 identified	upplements were issued against the in York (Supplement 1, dated May 11, 19 , dated May 3, 1984). None of these the material as safety-related.	itial PO by 77 and Sup- supplements
	b.	Ebas W3-3 orde	co Nonconfo 995 were re red under E	rmance Reports (NCRs) W3-3828, W3-393 viewed which were generated against m basco PO NY 403568.	O, and aterial

REPORT NO.: 99900505/89-0	1	INSPECTION RESULTS:	PAGE 8 of 15
(1)	NCR W3-382 indicated separate Receiving nonconform and suppl 1981 to Ma not an app expired in the mater material with requalify 1980 to Ju to obtain specification was not re CFR 21. Support the reportable produced linspection the noncommaterial Rotohammer remote low which uti further re were prime and serves	28, dated May 19, 1982. A review of the material was shipped to Waterford lots and each documented by a separate Report (MRR). The description of the mance stated that all material was man ied by Rotohanmer and received between ay 19, 1982, during which time Rotohan proved supplier since their qualificat n March 1980. The temporary dispositi ial was for Ebasco QC to confirm that was in an acceptable status at the tim then to process the material on a con asis. The recommended disposition was the supplier, review past history fro une 1982 to determine any negative tre Certificates of Compliance (CoC) to a tions. The NCR also indicated that the eportable under either 10 CFR 50.55(e) The NRC inspectors requested documenta he basis for the item being considered e;" however, documentation could not he by LP&L representatives during the n. The NRC inspector reviewed the nat informance and concluded that, although had been procured as nonsafety-related r material is used to operate valves cation via a mechanical linkage arrang lizes a yoke and universal type joint eview of the application indicated val arily located outside of primary conta d a passive function.	this NCR in 11 Material Material Material March 20, mmer was tion ion of the me of nditional to m March ends, and the ne item) or 10 ation to d "not be ture of n the d, from a gement A lves ainment
(2)	NCR W3-39 supplied by a separ nonconform received an unapprotection the NCR w	30, dated June 21, 1982. This materia in three separate lots, and each docum rate NRR. The description of the mance stated that safety class materia on MRRs 204245, 205234, and 206028 was oved supplier. The reportatility bloc as marked "not reportable."	al was nented al s from ck on
(3)	NCR W3-39 supplied No. 20681	95, dated June 24, 1982. This materia in one lot and documented by Ebasco of 7. The nature of the nonconforming co	al was MRR ondition

REPORT NO.: 99900505/89-01		INSPECTION RESULTS:	PAGE 9 of 15
wa Th MR sp	s again e suppl R No. 20 ecificat	that Rotohammer was an unapproved sup ier provided a CoC, dated June 11, 198 06817), verifying compliance to Ebasco tion LOU 1564.124F and the PO.	plier. 2 (for
As a re discuss reporta formal1 potenti	sult, Et ed in NG ble unde y docume al safet	basco's decision that the nonconforman CRs W3-3828, W3-3930, and W3-3995 were er 10 CFR 50.55(e) or 10 CFR 21, altho ented, appeared to be consistent with ty significance of the item.	ces not ugh not the
c. Documen	tation f	for PO WP3-8515	
(1) <u>PO</u> th in bo Th we or we stand	WP3-851 e Ebasco dicated xes and e order re equal iginal o re speci ated con d PO WP3	5. This PO was placed with Rotohamme Waterford 3 SES on April 8, 1982. A that the PO was for valve stem extens universal joints and was ordered as s required a CoC stating that the mater to or better than material supplied order (NY 403568), and the provisions fied. The Rotohammer CoC, dated Apri formance to Ebasco specification LOU -8515.	r by review ion gear afety-related. ials supplied on the of 10 CFR 21 1 20, 1982, 1564.124F
(2) NCI Rot des Rot Eba pre "no mer	k W3-375 cohammer riewing cermine sign spe cohammer isco let viously of repor	4. This NCR was issued on May 5, 198 not being an approved supplier and re their past history from March 1980 to any negative trends, and to obtain a d cification. The NCR disposition evalu- was reaudited and found to be satisfa- ter E823/298, dated June 28, 1982. As the reportability block on the NCR w table" and the documented basis for su ot available during the inspection.	2 due to ecommended June 1982 to CoC to the uation stated actory per s stated was checked uch a state-
(3) Eba (EE dis the ini sup not per	sco mem asco QA cussing inspec tially plier; reaudi iod. R	o, dated May 18, 1982. A memo from J. Site Supervisor) to R. Hyme (Ebasco C NCRs W3-3745 and W3-3754 was reviewed tion. This memo stated that Rotohamme evaluated and was considered to be an however, for some unknown reason, Roto ted at the end of their three year qua ecommended action was to reaudit Rotoh	Gutierrez A New York) during er was acceptable chammer was alification nammer and

REPORT NO.: 99900505/89-01	INSPECTION RESULTS:	PAGE 10 of 15
-------------------------------	------------------------	---------------

to ensure that appropriate personnel responsible for review and approval of POs are retrained on the procedures. As a result, Ebasco Material Receipt Inspection Report (MRIR) No. 82-03654 was issued on August 12, 1982 to accept the material which had been receipt inspected on MRR No. 204352. The material was accepted by Ebasco site QC.

d. Documentation for PO WP3-8653

This PO was placed with Rotohammer by Ebasco site personnel on April 28, 1982. The order was for a valve stem extension yoke adaptor and was ordered safety-related with 10 CFR 21 invoked. A CoC was required and received on April 30, 1982 certifying that the material was equal to or better than that supplied on PO NY 403568. Again, as in the past, an NCR was issued (NCR W3-3745, dated April 30, 1982) stating that Rotohammer was not listed on the Ebasco ASL, and therefore not an approved supplier. Temporary disposition included vibroetching the material to show identification and maintain traceability prior to conditional release which was requested on Log No. 82-078 and issued on May 18, 1982. The document cited NCR W3-3745 and stated that the material was required to support project start-up requirements with the approval based on the completion of the vibroetching. Ebasco MRIR No. 82-01875 was issued on May 21, 1982 and the material conditionally accepted by Ebasco site OC.

e. Approved Supplier Status

Based on a review of the ASLs and other related documentation, the NRC inspectors confirmed that Rotohammer was not an approved supplier from March 1980 to June 1982. LP&L computer data bases ZBS and PKG were queried in an attempt to independently identify which safety-related POs were issued to Rotohammer during this period. A review of this data indicated that PO WP3-9146, dated July 1, 1982, was the next PO issued to Rotohammer after the issuance of WP3-8653 on April 28, 1982. Based on a review of other information, WP3-9146 was issued to Rotohammer after they were qualified as an approved supplier. A number of additional POs were issued, but the sequential number of the orders indicates they would have been issued after WP3-9146. It was noted that PO WP3-9146 was subsequently renumbered as WP3-9146A by a PO supplement. This was done because another PO with the same

REPORT NO.: 99900505/89-01	INSPECTION RESULTS:	PAGE 11 of 15
WP3-9146 num Fittings. Th fied all Rote received dur approved sup f. Classificatio	per was inadvertently issued to Capita his review confirmed that Ebasco comple phammer material (POs WP3-8515 and 8653 ing the affected period when they were plier. on of Rotohammer Material as Safety-Re	l Valve and etely identi-) ordered or not an lated
The NRC inspe attempt to be cance of mate stated that in extension man because of an that equipmen procured as s Rotohammer st ment and furt cases, the va be operated in cases, the va of a failure a result, the supplier, alt constitute a provisions of self-identified action was ta material, a r identified du reaudit of Ro program and in to June 1982, by LP&L, but Suppliers Lis	ectors interviewed several LP&L personnetter understand the application and serial ordered on the affected POs. LP& the apparent reason that Rotohammer valuerial was ordered safety-related by Et administrative procurement definition tattached to safety-related valves shafety-related. They also stated that tem extensions are utilized outside prochemore primarily have a passive function is in a lower radiation area the luced radiation exposure during operation of the Rotohammer remote operator link purchase of this material from an unachough a procedural nonconformance, may reportable condition to the NRC under 10 CFR 21. Since this condition was ed internally by Ebasco and proper corken by Ebasco to satisfactorily disposion conformance to Ebasco procedures was ring this part of the inspection. The tohammer in June 1982 reviewed Rotoham ts implementation for the period of Mathematical was for which Rotohammer was not on the Application was not on the Application was not on the Application.	nel in an ifety signifi- L personnel ve stem asco was which stated nould also be valves with mary contain- ion. In most the valves to In some nus on. From would not ves the event age. As pproved not the rective ition the not Ebasco mer's QA rcch 198C received proved
5. Review of the J. C	. White Company	

During the NRC inspection at Ebasco in August 1988, additional questions concerning the activities which led LP&L to issue a Signifiant Construction Deficiency (SCD) Report to the NRC was

REPORT NO.: 99900505/89-01	INSPECTION RESULTS:	PAGE 12 of 15
reviewed. The J.	C. White Company manufactures	s material known
as "TUBE TRACKS" a	nd related hardware used by W	Waterford 3 SES to
house and support	instrumentation of both safe	ty and

nonsafety-related tubing. The POs reviewed were designated as safety-related with 10 CFR 21 specified and Ebasco specification 860-78 which identifies the QA requirements for nuclear safety-related items and services. This specification requires the supplier to have a documented QA program which complies with the requirements of 10 CFR 50, Appendix B. In addition, certification supporting the material's mill test reports and certification of the material's chemical and physical specifications were also required from the supplier. Two POs to J. C. White were reviewed by the NRC inspectors (WP3-2646, dated June 8, 1979 and WP3-2953, dated August 24, 1979). In both cases the material was procured safety-related with 10 CFR 21 specified. The material ordered comprised various tube track components such as yoke clamps and fasteners.

The POs specified that the material for the angles, channels, flat steel sections, and fittings be ASTM A-569 and/or A-570 and hot dipped galvanized in accordance with ASTN A-123. Solid stainless steel tube clamps were specified to be 304 stainless to ASTM A-479, while the yoke and bundle clamps were specified to be 304 stainless to ASTM A-240. During the process, additional supplements to the original PO were issued by Ebasco changing the previous material specifications and downgrading the previous PO to nonsafety-related. In addition, a later supplement to PO WP3-2646, Ebasco reclassified the material again as nonsafety-related. A similar series of events occurred for PO WP3-2953 also. An explanation for this inconsistency could not be provided by LP&L during the inspection.

J. C. White provided certification for material ordered, however, could not in all cases provided certification documenting the mill test reports, as required by the PO. This lack of certification led to concerns about the chemical and physical properties of some of the tube track material and also the affect this may have on seismic performance. As a result, NCR WP3-2749 was issued on June 10, 1981 and was forwarded to LP&L on July 21, 1981 by Ebasco as potentially reportable incident No. 49. Ebasco QA report LOU-4294 evaluated NCR W3-2749 for reportability and concluded it was reportable under 10 CFR 50.55(e) and that, until reviewed further, the physical material properties of both ASTM A-569 and A-570 are questionable due to the fact that J. C. White's cuality program, conditionally accepted by Ebasco on

REPORT NO.: 99900505/89-01	INSPECTION RESULTS:	PAGE 13 of 15
August 15, 1978, was the manufacture of f WP3-1608, 2646, 2953	s not being implemented by J. C. White tube track and channel for the follow 3, 4464, and 5829.	e for ing POs:
The recommended disp subvendor's document and to evaluate chem acceptability of mat Ebasco audit of J. C material was not man Appendix B, as requi 860-78 which specifi condition eventually NRC. The final repo	position was to review J. C. White and tation for compliance with ASTN A-569 mical properties and requirements for terial. In addition, the NCR stated to White on May 22, 1981 noted that to bufactured in accordance with 10 CFR 5 red by the PO referencing Ebasco spec- tes the requirements of Appendix B. To led LP&L to issue SCD Report No. 35 ort was issued on August 29, 1983.	i it's and A-570 that an ube track iO, tification this to the
Un December 22, 1981 J. C. White which wa January 8, 1982. Th actions to the May a was signed by the Eb initiated a Design C struction drawings o Revisions 1 and 2, d drawings to establis tube track material stresses in the mate least conservative m	, Ebasco performed a follow-up QA and is documented in Ebasco letter E654/58 is letter stated that J. C. White's cond July audits were found satisfactor asco Vendor Evaluation Group Leader. Thange Notice (DCN) to the Waterford 3 in May 4, 1982 (DCN-NYC-IC-833), inclu- ated August 19, 1982. These DCNs cha h maximum cantilever support spans for which presumably would not violate ma- rial based upon Waterford 3 SES recei- aterial specification (i.e., ASTM A-5	lit of 9, dated corrective y and Ebasco con- ding nged or the ximum ving the 69).
In order to provide for material that wa material that was av test program was ini physical properties Results from these t track material for a seismic.	a technical resolution that would be s already installed in the plant as w ailable for installation, an extensiv tiated by Ebasco to determine the che of the tube track material that had b ests were used to justify the use of ny of the designed applications, incl	satisfactory ell as e material mical and een supplied. the tube uding
This was documented provides background certification concern NCR stated that an in testing on tube trac .21 percent while AS of .15 percent. The	in NCR W3-6599 issued on July 26, 198 information relative to the material ns originally identified in NCR W3-27 ndependent laboratory (Lucius Pitkin) k fittings and found carbon levels as TM A-569 specifies a maximum carbon c evaluation of the high carbon condit	3 and 49. The performed high as ontent ion

REPOR NO.:	RT 99900505/89-01	INSPECTION RESULTS:	PAGE 14 of 15
	indicated that due the existing materi- was acceptable. At W. Yaeger, dated Ma engineering (Ebasco J. C. White tube tr 1 applications. Th fittings would be s tion of both chemic Attachment 2 to the dated May 5, 1983) testing of the J. C concluded that base including an evalua the applications, t support the Waterfo satisfactorily.	to the application of the fittings and al being weldable, the higher carbon of tachment 1 to the NCR (memo to J. DeBr rch 17, 1983) stated that materials ap) had been working on a program to upg ack fittings so that they can be used e memo further indicated that 315 J. (hipped to Fitkin Laboratories for ver- al and physical material properties. NCR (memo from L. Patrick to J. DeBru discussed the results of the Pitkin La . White fittings. In summary, the mer d on the data obtained from this test tion of the service and load requireme he tube track material could be used f rd 3 instrumentation tubing systems	d with content ruin to oplication grade for Seismic C. White ifica- uin, aboratory no ing, ents for to
	A 1986 Tube Track c better understand p The review indicate spacer clamps, the with commercial gra steel). It appears the items listed in Ebasco POs is that	atalog was reviewed during the inspect roducts supplied commercially by J. C. d that with the exception of solid sta items identified in the catalog were a de materials (e.g., 18-8 stainless and that the main technical difference be the catalog and the items listed in a Ebasco invoked a material upgrade by a	tion to . White. ainless manufactured d carbon etween the specifying
	ASTM materials for commercial grade ma	manufacturing certain items instead of terials to be used during manufacturing	f allowing
	As a result of the NRC r Company's QA program, it satisfactorily resolved rective action taken by	eview of concerns raised with the J. appears that the concerns identified based upon Ebasco reaudits and adequatebasco, J. C. White, and LP&L.	C. White were te cor-

REPORT NO.: 99900505/89-01	INSPECTION RESULTS:	PAGE 15 of 15
F. <u>PERSONS CONTACTED</u> : Louisiana Power and Lig #* L. W. Laughlin, Lice #* N. S. Carns, Plant M #* J. J. Zabritski, Ope #* L. F. Lubinski, Proc #* M. A. Triggs, Nuclea #* L. L. Bass #* G. M. Davis, Events #* J. E. Howard, Procurv #* D. V. Gallodoro, Pro # J. R. McGaha D. Gilley, Maintenan R. Bennet, QA Superv T. Gerretts, QA Manay J. Sleger, Nuclear Si W. Morgan, QA Audit S	ht nsing anager rations QA Manager urement Representative r Records Manager ssistant Plant Manager ement Programs Manager curement Engineer curement Engineer isor ger afety Review Manager Supervisor	
<pre>#* Robert L. Pettis, Jr. #* Terrence L. Tinkel, N # W. F. Smith, NRC Sen* # E. William Brach, Chi * T. R. Staker, NRC Res</pre>	, Senior Reactor Engineer, NRC NRC Consultant ior Resident Inspector, Waterford 3 ief, Vendor Inspection Branch, NRC sident Inspector, Waterford 3	
*Attended entrance meeting #Attended exit meeting		

BONN 1. FEDERAL REPUBLIC OF GERMANY REPORT INSPECTION **INSPECTION** NO.: 99901133/88-01 DATE: November 17-18, 1988 ON-SITE HOURS: 16 CORRESPONDENCE ADDRESS: Klockner-Moeller Hein-Moeller Strasse 7-11 Bonn 1, Federal Republic of Germany D-5300 ORGANIZATIONAL CONTACT: K. Rademacher (0228) 002-674 TELEPHONE NUMBER: NUCLEAR INDUSTRY ACTIVITY: Manufacturer of contactors, low voltage circuit breakers, and motor control centers. ASSIGNED INSPECTOR: K. R. Naidu, Reactive Inspection Section Date No. 1 (RIS-1) OTHER INSPECTOR(S): None 21.0 APPROVED BY: E. T. Baker, Chief, RIS-1, Vendor Inspection Branch Date INSPECTION BASES AND SCOPE: Α. BASES: 10 CFR 50 Appendix B SCOPE: Review the implementation of the Quality Assurance Program in 6. selected areas including design changes to circuit breakers manufactured and supplied to LaSalle County Station Nuclear Power Plant. PLANT SITE APPLICABILITY: LaSalle County Station (50-373, 374); Grand Gulf (50-416, 417); North Anna (50-269, 270); Zion (50-295, 304) and Monticello (50-263).

ORGANIZATION: KLOCKNER-MOELLER

NO.:	DRT : 99901133/88-01	INSPECTION RESULTS:	PAGE 2 of 8
۵	VIDIATIONS	Trapere norma preventi da trans de la preventa superan a vyskoli na di se kan na konisca za di a preventi serva	มหาวาทราย (สมหาราช สามารถสมมาณสมมาณสมมาณสมหารถาง สามารถสมหาราช สามารถาง
·	No violations were ident:	ified during this inspection	n
R	NONCONFORMANCES.	inted out ing this inspection	"•
0.	No nonconformances sere	identified during this just	ection
C	UNRESOLVED ITEMS.	recent real out my tilts map	ceron.
	No upresolved items were	identified during this incl	pection
3	INSPECTION FINDINGS AND (OTHER COMMENTS.	pectron.
	1. Background Informat	ion	
	Klockner-Moeller (Ka Germany (FRG), manu breakers, contactors centers (MCCs). K& and other countries contactors, and mole at LaSalle County Si K&M also supplied so Monticello nuclear p This inspection was K&M quality assurant change control and During the preparat obtained the follow	&M), headquartered in Bonn, factures low voltage switch s, electric motor starters, M has numerous manufacturing In 1977, K&M supplied MCG ded case circuit breakers (H tation (LSCS) Units 1 and 2 witchgear to Grand Gulf, Non power plants. conducted to verify the implice program in selected areas testing. ion phase of the inspection ing model numbers on the var	Federal Republic of gear such as circuit and mctor control g facilities in FRG Cs with starters, CBs) for installation located in lilinois. rth Anna, Zion, and plementation of the s, including design , the inspector rious types of
	a. <u>Circuit Breake</u> NZM H6 - 63/Z I NZM H6 - 63/Z I NZM H6 - 63/Z I NZM H6 - 63/Z I	<u>rs</u> M6 - 6.6 - 32 - ODI - CNA M6 - 2.1 - 12 - OBI - CNA M6 - 3.7 - 20 - OBI - CNA M6 - 15 - 120 - OBI - CNA	
	b. <u>Thermal Overloo</u> 20 - 3.7/K - 1	ads Used With CB's	

REPORT NO.: 99	901133/88-01	INSPECTION RESULTS:		PAGE 3 of 8
	c. <u>Contactors</u> ZO - 14/K Z2 - 40/K DIL - 0 - 22 DIL - 2V - 22 DIL - 3 - 22 DIL - 3 - 22 DIL - COLB - 22	- NA - NA 2 - NA 2 - NA 2 - NA 2 - NA		
	At K&M, it was expla above are manufactur 400 kilometers from in Bonn; the ZO type Werke Bayenthal fact kilometers from Bonn	ained that the contactor red at a different plant Bonn. The NZM H6 type e thermal overloads are ility located in Cologne n.	rs mentioned in CBs are manufa manufactured , approximate	n c t actured in the ly 20
	Some of the salient	features of the K&M CBs	are as follow	ws:
	a. The front covers any unusual disc visible. Such (K&M stated that their CBs. Cons not usable.	s of the CBs are transpa coloration of the main of CBs are removed from ser they do not sell replac sequently, the CBs are o	arent. As such contacts is rea rvice and disca cement spare pa liscarded if th	n, adily arded. arts for ney are
	b. Each CB is subje sampling technic	ected to a final test. ques to test assembled C	K&M does not e Bs.	employ
	c. The shunt trip c continuous curre	coil used in the CBs are ent operation.	e rated for	
2.	Plant Tours			
	The inspector, accom facilities in Bonn a implementation of th material and the fin	npanied by the QA manage and Werke Bayenthal to o ne inspection program, s nal tests.	er, toured the observe the segregation of	
	a. Incoming Receip	ot Inspection		
	The plant at Ba November 11, 19 springs are uti The computer se number of sprin	ayenthal had received 10 088 from Schmiede Knecht ilized in the assembly o elected the Acceptable Q ngs to be tested based o	,715 springs c , a subvendor. f NZM H6 type uality Level f n the lot size	n These CBs. for the e of

REPORT NO.: 99901133/88-01	INSPECTION RESULTS:	PAGE 4 of 8
-------------------------------	------------------------	-------------

11,000. The springs were inspected to the relevant drawing, Z23-300-62, utilizing Incoming Inspection Procedure, PV 123-60, dated February 5, 1987. The procedure provided the nominal length of the spring and the force in newtons to elongate the spring to a specified length. The tools utilized to perform the inspection were observed to have current calibration stickers. The receipt inspection did not identify any unacceptable springs within the tested sample.

b. In-Process Inspections

The inspector observed in-process inspections being performed at both the plants. Specifically, the inspector observed the inspection being performed on an auxiliary switch upper part subassembly at the Cologne plant. The smoothness of the movement of the contact was verified. The operating mechanism was turned ON and OFF three times, and to the ON and TRIP position three times. Samples of the terminals of the CBs were subjected to inspections. A test apparatus was available to test the strength of the terminals.

c. Mechanical Tests

The following mechanical tests were being performed after the operating mechanism was assembled as required by the applicable procedure. The procedure provided the minimum and maximum acceptable standards, including the units of measurement of the variables.

- The correct operation of the moving contacts was verified. This verification ensured that the moving contacts mate with the stationary contacts.
- (2) The start and end positions of the trip bar were verified.
- (3) The change of state of the auxiliary switch contacts was observed.
- (4) The integrated force required to trip the CB was measured to determine if it was within the acceptable value specified in the procedure.

REPORT NO.: 99	901133/88-01	INSPECTION RESULTS:	PAGE 5 of 8
	d. <u>Control of Reje</u>	ected Material	
	Components reje in red colored inspections, fi and other switc summary data on number rejected percent of the The assembly pr is identified a	ected during the inspections were place baskets. In addition to the in-proce- nal inspections are performed on each subset components. Each factory provi- the number of switches tested and the . If the number of rejects exceeds S production run, production is stopped ocess can commence only after the pro- nd corrected.	ced ess cB ides ne i. bblem
3.	Review of the K&M QA	Program	
	The Quality Assuranc B to 10 CFR 50. In covers servicing and control (QC) represe each manufacturing f service, testing and developed for each o personnel to impleme	e (QA) program basically conforms to addition to the 18 criteria, the QA p statistical techniques. QA and qual nectives are assigned responsibilitie acility in the areas of development, shipping. Detailed procedures have f the various activities for the QA/Q nt.	Appendix rogram ity s in research, been C
	The changes to desig prescribed in their (QA representatives by is placed on QA during manufactured to ensure Codes to identify the such as contactors an	n drawings are controlled in the mann QA program and require the concurrence efore they are issued for production. ng the life testing of the various pr re that the products perform satisfac a date of manufacture are stamped on nd overloads to provide traceability.	er e of Emphasis oducts torily. components
4.	Review of Control of	Design Changes	
	The inspector obtaine of CB's and the trip to the inspection. NZM H6 type molded ca the NZM H6 type CB.	ed specific details on three differen mechanisms for the CBs installed at The inspector reviewed the design cha ase CBs and ZM6 type trip mechanisms	t types LSCS prior nges for used in
	a. Drawing 1Z 123 - contained the fo	- 74-XII for molded case CBs, type NZM pollowing revisions:	М Нб,
	(1) On July 27,	, 1977, the drawing was redrawn.	
	(2) Revision i table was a	- August 18, 1982. The continuous conded.	urrent
NATURA AND A MARKAGENER AND A DESCRIPTION OF A DESCRIPTIO	alinaan mii 4000 mii 2000 mii	n ya anana anan ana ana ana ana ana ana	ann anna 2019 ann an ann a' bhaing " ann ann a' bh

BONN

REPORT NO.: 99901133/88-01	INSPECTION RESULTS:	PAGE 6 of 8
(3) Rev shu	ion k - March 13, 1984. The cutout view trip was added.	of the
(4) Rev the	ion 1 - November 7, 1986. The handle to witch from the rear of the CB was delete	operate d.
(5) Rev the (CS sup Lab	ion m - June 12, 1987. The label to ind B complies with the Canadian Standards A was deleted. The label was considered fluous because there is a label for Unde atories.	icate that ssociation rwriters
b. Drawing the NZM	23-70-I showing the ZM6 type trip mecha type CB contained the following revisio	nism for ns:
(1) Red	wn on December 22, 1978.	
(2) Rev che	ion ab - November 23, 1979. Special par ical industry deleted.	t for
(3) Rev mod	ion ac - December 12, 1979. The trip ba fied.	r Was
(4) Rev mec	sion ad - March 24, 1982. Special type o unism suitable for 400 HZ was added.	f trip
(5) Rev rev	ion ae - July 26, 1982. K&M instruction sed to change the calibration method.	was
(6) Rev mec	sion af - September 8, 1982. The cover o anism was added to the drawing.	f the trip
(7) Rev bin The	sion ag - February 2, 1983. The screw to talic terminal had a washer and a spring washer was deleted.	hold the washer.
(8) Rev pin the the cur	sion ah - May 5, 1984. The surface of th on the trip bar which press the trip bar CB was changed. The distance between the trip bar can be adjusted to respond to th ent.	e three to trip pin and e trip
The insp containe engineer	ctor observed that the revisions to the d the signatures of the draftsman and the K&M determined by engineering judgment	rawings chief that the
		-

REPORT NO.: 999011	33/88-01	INSPECTION RESULTS:	PAG	E 7 of 8
	changes wer qualificati	e minor and would not affe on of the CD and the trip	ct the seismic attachment.	
5. <u>Fi</u>	nal Tests			
Fi ur sa	nal tests are its, thermal t lient features	performed on each of the t rip units, and CBs. The f tested:	hermal magnetic tr ollowing are the	ip
a.	Trip Units			
	The thermal have differ magnetic tr without the following f	magnetic trip units and the ent style numbers. The de- ip unit is such that it can thermal or the magnetic e eatures are verified:	he thermal trip un sign of the therma nnot be assembled lement in it. The	its 1
	(1) Air ga	p of the coil.		
	(2) Inspec welded	tion to determine that the	contact is adequa	tely
	(3) Uniform	mity of the three poles.		
	(4) Contac	t screws are tight.		
b.	Circuit Bre	akers		
	The followin manufacture	ng are some of the tests pe d.	erformed on each C	В
	(1) The CB cycles Accepta and slo	is subjected to two fast a and the time periods to op able fast operate time is 2 ow switch time is 3000 ms.	and two slow ON/OF perate are measure 200 milliseconds (1	F d. ms)
	(2) The ope overvo	eration of the shunt trip u Itage conditions.	unit with reduced	and
	(3) The ope undervo handle positio Electro	eration of the undervoltage oltage coil is energized fr is turned from the "OFF" p on. The German Vereinigte otechnischeverein (VDE) sta	trip unit. The for the moment the osition to the "O Deutsche ndards require the	CB N" at

REP.	DRT : 99901133/88-0	INSPECTION RESULTS:	PAGE 8 of 8
		the voltage to the undervoltage coil be remo the CB is in the "OFF" position.	ved when
	(4)	Every CB manufactured is subjected to an ins resistance test. For one second, 2.64 KV is between the terminals $R-U/S-V/T-W$ with the C the open position and between the terminals R-S/S-T/T-ground with the CB in the closed p where R, S, and T are the line side terminal and T are the load side terminals.	ulation applied B in osition, s and U, V,
	6. Review of	Audit Performed By British Standards Institu	tion
	The inspe Standards January 6 K&M durin to satisf United Ki and are r the neces K&M Bonn exist to tribution visible, between t	tor reviewed the audit performed by the Brit Institution (BSI). Report 86/3856/A02, date 1987, documents the visit of two assessors January 6-8, 1987. The objective of the vi BSI that the components distributed through gdom (UK) are procured from a quality assure gularly audited and tested. BSI also verifi ary authority for quality was visibly delega ead Office to the UK operations, and that pr nsure that the responsibility for initiation amendment, and authorization is readily app or the flow of all ouality and associated do e Head Office and other manufacturing facili	ish d to sit was K&M d source ed that ted by the ocedures , dis- arent and cuments ties.
	The repor	contained no adverse findings.	
Ε.	EXIT INTERVIEW		
	The inspector the scope and	et with persons identified in Section F and indings of the inspection.	discussed
F.	PERSONS CONTAC	<u>ED</u> :	
	 *K. Rademacher *W. Lange H. Behr V. Vogt H. Goerke K. Pawloski 	Quality Assurance Manager Quality Assurance Group Leader Quality Assurance Manager, Division E Director, Werke Bayenthal Quality Assurance Manager, Werke Bayent Incoming Receipt Inspector, Werke Bayen	hal thal
	* Denotes the November 18,	ndividuals who attended the exit meeting on 1988.	

REPORT NO.: 99900404/88-02	INSPECTION DATE: 11/16-17/88	INSPECTION ON-SITE HOURS: 30			
CORRESPONDENCE ADDRESS: Mr. Carlo L. Caso, General Manager Westinghouse Electric Corporation Nuclear and Advanced Technology Division Post Office Box 355 Pittsburgh, Pennsylvania 15230					
ORGANIZATIONAL CONTACT: TELEPHONE NUMBER:	Mr. David Alsing, Manager, Qu (412) 892-3708	ality Assurance			
for nuclear power plants	NUCLEAR INDUSTRY ACTIVINY: Westinghouse provides NSSS components and services for nuclear power plants.				
ASSIGNED INSPECTOR: W. F	ASSIGNED INSPECTOR: W. P. Haass, Special Projects Inspection Section Date				
OTHER INSPECTOR(S): R. C	. Jones, Jr., RXB/NRR				
APPROVED BY: U. Potapovs, Chief, SPIS, Vendor Inspection Branch Date					
INSPECTION BASES AND SCOP	Ε:				
A. <u>BASES</u> : 10 CFR Part	50.				
SCOPE: Review records regarding an allegation concerning the Westinghouse evaluation model for reflood following a LOCA; review the Potential Item File System to assess the procedures and their implementation to resolve safety concerns; and review other files in the same technical area that could assist in the above two areas.					
LANT SITE APPLICABILITY: All nuclear plants with Westinghouse PWR-type NSSSs.					

ORGANIZATION:	WESTINGHOUSE ELECTRIC CORPORATION	
	PITTSBURGH, PENNSYLVANIA	

REPO NO.:	RT 99900404/88-02	INSPECTION RESULTS:	PAGE 2 of 8
Α.	VIOLATIONS:		
	None		
Β.	NONCONFORMANCES:		
	None		
С.	UNRESOLVED ITEMS:		
	None		
D.	OTHER FINDINGS AND COMMEN	ITS:	
	1. Allegation on the We	estinghouse evaluation model for	r WREFLOOD
	An allegation was re evaluation model for Appendix K. The iss period of a large br the logic in the WRE characteristic cold top of the downcomer	eceived by NRC that alleged the WREFLOOD was in violation of t sues centered on the calculation reak LOCA and were specifically EFLOOD code and the calculation leg volume necessary to establ r (referred to as VOLRSD) were	Westinghouse 10 CFR 50.46 n of the refill concerned that of the ish flow at the in error.
	To evaluate the spec Potential Item (PI) WREFLOOD," which was	cific concerns raised, the insp File 86-029 entitled, "Hot Wal s opened to address the concern	ectors reviewed 1 Delay Model in s raised by the

WREFLOOD," which was opened to address the concerns raised by the alleger. Westinghouse Calc Notes SEC-SA-2306-CO and SEC-SD-064-CO, which were referenced in the PI file, were also reviewed. This PI file was opened on August 29, 1986 in response to a request by another Westinghouse employee; the alleger apparently did not request that a PI file be opened. Westinghouse completed its evaluation of the issues and closed the PI file on May 12, 1988.

With respect to the possibility of a logic error in the WREFLOOD code, our review concluded that the code logic is as described in WCAP-8471-P-A, "The Westinghouse ECCS Evaluation Model: Supplemental Information." Specifically, execution of the code is delayed for a period of time associated with the transport time of the accumulator water from the injection point to the lower plenum. Following this delay period, the calculation is started

REPORT NO.: 99900404/88-02	INSFECTION RESULTS:	PAGE 3 of 8
ABIYOS MARKANININ MARKANING MARKANING MARKANING NA APPROXIMATION POLICIAN COLUMNIC AND ADDRESS AND ADDRESS ADDRE	No server of the s	THERE IS A REAL PROPERTY OF A RE

and all injected water is placed directly in the lower plenum. Thus, the alleger's observation that water is placed directly in the lower plenum is correct. However, use of the transport time delay to account for the lack of detailed cold leg modeling in the WREFLOOD code has been previously accepted by the staff and does properly account for the effects of water accumulation in the cold leg. Therefore, the inspectors concluded that there is no logic error in the code.

The calculations of the VOLRSD parameter and the transport time delay were also reexamined by Westinghouse in Calc Note SEC-SA-2306-CO. While the specific value for VOLRSD used in the Westinghouse evaluation model is provided in WCAP-8471-P-A, it was not apparent to the inspectors that the specific calculations for this parameter were examined by the staff during the initial review. Thus, the inspectors performed a review of the Calc Note to determine whether the VOLRSD parameter is calculated appropriately.

Consistent with the overall Westinghouse evaluation model approach, it was assumed that the refill/reflood transient can be viewed as a quasi-steady state process. Using this assumption, and considering the fact that the reactor coolant pumps are still coasting down, injected flow is directed towards the vessel and a void fraction within the cold leg is calculated using a standard two-phase flow model. This void fraction is then integrated over the cold leg piping volume (yielding a value of 43.92 cubic feet) which is then multiplied by the number of unbroken loops to determine the value of VOLRSD. From this result, the transport time delay is determined and used for all plant calculations. In fact, it is only this time delay which impacts the WREFLOOD calculation; the VOLRSD parameter, although input, has no impact on the results.

The constant value for the cold leg transport time delay is based on a specific piping length from the accumulator injection point to the reactor vessel, a specific diameter, and a specific injection rate. As alleged, plant specific parameters, such as the actual size for the injection nozzle or the actual injection flow rate, could impact this result. While not addressed within the Calc Note, this issue was discussed with Westinghouse personnel. Review of drawings and other plant specific information by the inspectors indicated that the assumptions made for the evaluation model calculations would likely result in a conservative estimate of the delay time for all plants. Thus, use of the same transport time delay for all plant types is acceptable.

REPORT NO.: 999	900404/88-02	INSPECTION RESULTS:	PAGE 4 of 8
	Therefore, it was concluded that the general approach used by Westinghouse in its evaluation model for WREFLOOD is consistent with that approved by the staff and no logic error exists. The specific calculational techniques used to determine VOLRSD, and more impor- tantly, the cold leg transport time delay, were appropriate. Thus, the allegations raised could not be substantiated.		
2.	Review of the Potential Item File System		
	The inspectors reviewed the procedures governing the processing of an employee-identified safety concern by Westinghouse. The top procedure is:		
	- WRD-OPR-19.0, ' Safety Hazards Safety Question	"Identification and Reporting of Subs , Significant Deficiencies, and Unrev ns," Rev. 3, dated November 1, 1988	tantial iewed
	Each technical group tion/guidance (IG) of employee reporting a documents on this su and Operations Impro Safeguards Engineer sistent with the top latter group which to immediate manager for Westinghouse procedure dure. The procedure for anonymity if des	p in turn has developed and issued an document that provides more specific a safety concern. The groups that ha abject include Product Licensing, Ris ovement, Operating Plant Licensing Su ing and Development. All IG document p procedure with the exception of the required reporting of a safety concer irst; this IG document reflected the ure and had not been revised to the 1 e had been modified to provide greate sired.	instruc- steps for an ve issued IG k Management pport, and s were con- one for the n to the earlier ater proce- r assurance
	The inspectors also orientation of new e employees, and the l documents had not be reporting of safety house indicated that were given to provid	reviewed the Westinghouse video tape employees and the periodic training o NSD Orientation Manual for new employ een revised to incorporate the new pr concerns to assure anonymity. Howev t at the time of presentation, oral c de employees with the latest instruct	used for f existing ees. Both ocedure for er, Westing- orrections ions.
	The inspectors noted porting of safety co Part 21 regulation to employees to see.	d that the proper revised procedure f oncerns was included in a posting of that appeared in conspicuous location	or the re- the 10 CFR s for all

PITTSBURGH, PENNSYLVANIA			
REPORT NO.: 99900404/88-02	INSPECTION RESULTS:	PAGE 5 of 8	
The procedure invol potentially adverse supervisor, or any Review Committee (S need only be report position is empower employee is require ment the concern. Operation (JCO) is point, a Potential evaluating the conc person with experti The technical exper and prepares a basi is recommended, the the technical exper the concerned emplo	ves the reporting of any to safety by the employed other manager, or the Sector RC). If anonymity is des ed to the SRC Secretary st ed to assure the employee ed to complete a form or with The preparation of a Just also required by the proce Item file is opened and re- ern is assigned to a manager se in the area of the cond to performs the necessary as for close-out or report as for close-out or report basis is reviewed by the t, the immediate manager, oyee. If any one member of	condition adverse or e to the immediate retary of the Safety ired, then the condition ince the person in that 's confidentiality. The rite a letter to docu- ification for Continued edure. At this esponsibility for ger and a technical cern. analysis and evaluation ability. If the former Secretary of the SRC, another manager, and f this group disagrees,	
the matter is refer latter is recommend following review by If the SRC determin then the appropriat the provisions of 1 matter is not repor safety concern can and including the d reporting under Par	red to the SRC for further ed, the matter is forwards the technical expert's ma es that the matter is repor e steps are taken to repor 0 CFR Part 21. If the SRC table and the concerned em be elevated to higher leve ivision Vice-President who t 21. At this point, a fi	r consideration. If the ed to the SRC directly anager. Drtable to the NRC, of the matter under C determines that the mployee disagrees, the els of management up to b is responsible for inal decision is made.	
The inspectors indi steps that an emplo documented form. W an internal letter eral Manager as a r resolve employee sa contemplated to pro inspectors reviewed subject dated Febru	cated that the full extent yee might wish to follow w estinghouse stated that it to all employees from the eminder of the options ava fety concerns. The issuar vide the specifics of the a prior internal letter t ary 19, 1976.	t of the procedural was not provided in t was planned to issue Vice President and Gen- ailable to identify and nce of a brochure is full process. The to all employees on this	
Other Westinghouse sion and the Nuclea Committees for anal	divisions including the Nu r Fuel Division have their ysis and evaluation of emr	iclear Components Divi- r own Safety Review	

REPORT NG.: SS90040	4/88-02	INSPLCTION RESULTS:	PAGE C of E
how res are and	ever, all matter olved by the Nuc subject to the have developed	s involving questions of reportability lear and Advanced Technology SRC. All requirements of the top procedure (WRD their own 10 cocuments.	/ arc 1 divisions)-OPR-19.0)
As act to are in fil is	noted above, NRC ivity unless a so be reportable. A not kept informa process are affec e is opened. Ut involved; however	is not informed regarding the total P arety concern has been evaluated and o restinghouse indicated that generally of regarding PI matters unless safety offed, or a JCO cannot be written at of ilities will be informed if a commerci r, and when a Technical Bulletin is is	I file Etermined utilities Evaluations E time a PI al decision sued.
S. Rev	iew of Potential	Item Files	
Seve	Eraî Fl tiles wer file system. The	re reviewed to examine implementation files reviewed, and their current st	of the atus were:
PI-8 F1-5 F1-5 F1-8 F1-8 F1-8 F1-8 F1-8 F1-8	86-012: Long ler 84-204: ECCS Eva (Closed) 85-209: KUST Ter 86-039: Hot Wall 88-039: Hot Wall 87-042: Reduced 86-024: Long Ter 87-039: Fuel Qua 88-047: LOCA Lin 86-031: 3-Loop D	m Cooling - Generic (Open) aluation Model for 14 Ft Cores perature in LOCA Analysis (Closed) Delay Model (Closed) Delay in NAEFLGCD (Open) Temperature Feturn to Power (Closed) m Cooling Doron (Closed) Tification hon-Conservation, Grid s and Seismic Spectra (Open) its, SG Tube Plugging Limits (Open) AkT Max SI (Closed)	
The that or e form	inspectors revie dCCs were writt ssentially resol ed were proper.	wed the contents of these PI files to en and, for those issues which were c ved, that the analyses and evaluation	ensure lused s per-
in y to b were iete suff reso were conc and	eneral, the insp e property imple performed. PT (letters request icient information lution or current acceptable. For luded that the energy met NRC requirement	ectors found the process for resolving Lented and that sound engineering eva- files 84-264, 86-018 and 87-042 appear ting opening of the FI were missing); or was available, or referenced, to the t status of the issues. All JCOs rever r those PIs which were closed, the ins- valuations performed were technically ents.	g PI files luations red incomp- however, rack reweu spectors sound













521









91 71 521











REPORT NO.: 99900404/88-02	INSPECTION RESULTS:	PAGE 7 of 8	
Several generic items were raised by the inspectors, and discuss- with Westinghouse personnel, based on the review of these files. One issue was related to "margin tracking." The inspectors noted that some of the JCOs and evaluations identified DNB or LOCA peak cladding temperature penalties. Plant specific safety analyses were then reviewed to assure that sufficient margin to applicible regulatory criteria existed to accommodate these penalties. Since it appeared that several penalties could have been identified, the inspectors questioned how the accumulated effect of these penalties are tracked. Westinghouse personnel described the various mechanisms used, including the use of safety analysis checklists, to assure that adequate margins are available in plant specific safety evaluations. Based upon these discussions, the inspectors concluded that the processes used for "margin tracking" are acceptable.			
During the review of PI file 87-042, the inspectors noted that an employee raised concerns regarding the use of PRA methodology to resolve this issue. The specific issue raised by this PI was that LOCA loads did not consider the reduced reactor coolant system temperatures that would result during a Reduced Temperature Return to Power (RTRP) maneuver. Reduced temperatures could increase LOCA loads beyond those analyzed. This issue was resolved by first noting that the licensing basis for LOCA load calculations is based on 10C percent nominal power operation and does not need to account for normal plant maneuvers, such as startup, cooldown or RTRP, and secondly, using PRA methodology and the guidance in NUREG-0933, demonstrating that an RTRP maneuver would not result in a signifi- cant impact on public health and safety due to the limited time it is used. The inspectors reviewed the resolution provided within the PI file and concluded that the approach taken was consistent with regulatory requirements.			
The inspectors discu is a general method analyses and evaluat for those issues wit basis issues, a PRA significance of the pursued in a determi the inspectors conclu- reliance on the PRA concerns.	ssed with Westinghouse personnel w used to resolve PI issues. It was ions are performed in a determinis hin the licensing basis. For beyo approach may be used to determine issue. Since design basis issues nistic manner consistent with the uded that Westinghouse is not plac approach to resolve employee-ident	hether PRA stated that tic manner nd design the safety are being regulations, ing undue ified	



REPORT INSPECTION INSPECTION NO.: 99900104/88-01 DATE: 10/4-6/88 ON-SITE HOURS: 60 CORRESPONDENCE ADDRESS: Mr. Jose M. Martinez Product Assurance Manager Westinghouse Electric Corporation Nuclear Components Division Post Office Box 1313 Pensacola, Florida 32514 ORGANIZATIONAL CONTACT: Mr. Jose M. Martinez, Product Assurance Manager TELEPHONE NUMBER: (904) 474-4340 NUCLEAR INDUSTRY ACTIVITY: Westinghouse manufactures NSSS components for nuclear power plants. 1/10/39 ASSIGNED INSPECTOR: Un W. P. Haass, Special Projects Inspection Section Date (SPIS) OTHER INSPECTOR(S): R. W. Woodruff, NRR: OEAB K. R. Wichman, NRR: EMTB R. Cid CSN APPROVED BY: Potapovs, Chief, SPIS, Vendor Inspection Branch 1-10-80 Date INSPECTION BASES AND SCOPE: A. BASES: 10 CFR 50 Appendix and 10 CFR 21. Β. SCOPE: Review manufacturing and quality assurance procedures and records to identify the controls and their implementation for assuring that steam generators ready for shipment do not contain loose parts and other manufacturing debris; review examples of steam generator manufacturing work in progress; identify the interface between NCD and utility licensees and Westinghouse NSD regarding installation and servicing; and review procedures and their implementation for determining the reportability of defects to NRC under 10 CFR Part 21. PLANT SITE APPLICABILITY: All nuclear plants with Westinghouse PWR-type NSSSs.

ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION PENSACOLA, FLORIDA

ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION PENSACOLA, FLORIDA

REP NO.	ORT : 99900104/88-01	INSPECTION RESULTS:	PAGE 2 of 7
Α.	VIOLATION:		
	None		
В.	NONCONFORMANCES:		
	None		
С.	UNRESOLVED ITEMS:		
	None		
D.	OTHER FINDINGS AND COMMEN	NTS:	

1. General Control Techniques for Loose Parts and Debris

Assurance that loose parts and manufacturing debris are not present in the complete steam generator is provided by multiple inspections performed just prior to each step in the assembly process that results in an inaccessible area. As appropriate, barriers are inserted to preclude subsequent intrusion of such items as the assembly process continues. Assembly of the steam generator is accomplished in two major parts: the lower assembly and the upper assembly. When the lower shell and tube sheet assembly is completed, it is thoroughly cleaned and inspected for loose parts and debris prior to insertion of the wrapper and tube support plate "A" assembly. Following insertion of the wrapper assembly, inspection of the resulting annulus is performed and a protective barrier is set in place. Prior to insertion of each succeeding tube support plate, cleaning and inspection are again performed. Finally, the tubes are inserted, expanded, and sealwelded, and both ends of the lower assembly are cleaned and inspected and covered with protective barriers. In a similar fashion, the upper assembly is completed. Joining of the upper and lower assemblies is accomplished with a girth weld.

Following final assembly, access to the steam generator internals is provided by means of a manhole located in the upper assembly. Personnel entry is monitored 24 hours a day at this point in the manufacturing process and a log is maintained of all items, personal as well as manufacturing aids and installed hardware items, that ingress and egress the steam generator.

13
ORGANIZATION: WESTINCHOUSE ELECTRIC CORPORATION PENSACOLA, FLORIDA

REPORT NO.: 99	900104/88-01	INSPECTION RESULTS:	PAGE 3 of 7
	As a final check p while positioned b for falling loose	prior to shipment, the completed steam on the steam of th	generator, istening
	Westinghouse NSD of loose parts in a s prior to operation Retrieval (FOSAR) licensees is not k	toes offer a separate program for detect team generator subsequent to installati . It is called the Foreign Object Sear program. The extent of FORSAR use by u known at this time.	tion of ion and och and itility
2.	Steam Generator Re	sponsibilities	
	The Westinghouse N the manufacturing manual for operati the units as reque Westinghouse Nucle	uclear Components Division in Pensacola of the steam generator units and also p on. Installation and subsequent servic sted by the utility customer is provide ar Services Division in Monroeville, Pe	performs provides a ing of ed by the ennsylvania.
3.	Cleanliness Proced	ures	
	From the time stea facility until the in Pensacola, the removal of all loo	m generators were manufactured at the T present time where the units are manuf procedures in use to assure cleanliness se parts and debris are as follows:	ampa actured and
	a. Process Speci Cleaning Stea through Decem for cleaning generator prin	fication 83318 PA, "Instructions for Fi m Generator," dated January 20, 1969 (I ber 20, 1987 (Change 8), provides instr the primary and secondary sides of the or to shipment.	nal ssue 1) uctions steam
	b. Process Speci Generator Low instructions assemblies pr final assembly	fication 83318 PE, "Cleaning of the Ste er and Upper Shell Assemblies," provide for cleaning of the lower and upper she ior to assembly, during assembly, and a Y.	am s 11 fter
	The above instruct directed primarily penetrant chemicals loose rust, paint, "Loose parts" is no	ions were used at the Tampa facility an toward the removal of contamination fr s, oil, grease, metal chips, grinding d slag, scale, sandblasting abrasive, or of identified as an item of concern; ra	d are om dye ust, dirt. ther,

ORGANIZATION:	WESTINGHOUS	E ELECTRIC	CORPORATION
	PENSACOLA,	FLORIDA	

REPORT NO.: 99900104/88-01	INSPECTION RESULTS:	PAGE 4 of 7
references materials d general deb	are made to removal of equipment, rem etrimental to the subsequent operation ris, and foreign debris.	noval of all on of the unit,
c. Detail Cleani dated for cl assemb final	ed Manufacturing Procedure DMP-5562, ig of Steam Generator Lower and Upper December 21, 1987 Revision 5, provide eaning of the steam generator lower a lies prior to assembly, during assemb assembly.	"Protection and r Shell Assemblies," es instructions and upper shell oly and after
d. Qualit Requir Assemb Revisi cleanl genera	Inspection Procedure QiP-3364, "Cleaments for Steam Generator Lower and lies (Secondary Side)," dated January on 3, provides instructions for QC-ty iness at various steps in the assemb- tor.	eanliness Upper Shell v 18, 1988 vpe checks of ly of the steam
The above p facility an Tampa instr make specif	rocedures are currently in use at the 1 address similar cleanliness require 1ctions; however, in addition, the pr 1c reference to the removal of loose	e Pensacola ements as the rocedures do parts.
In summary, cleanliness assembly up increased c be noted th steam gener observed la examples in Unit 1 (Mar Unit 2 (Feb manufacture Tampa facil manufacture very limite their first	the evolution of the procedural cont of the steam generator units during to and including final assembly demo oncern for the presence of loose part at the initial incidence of loose part ators attributed to the manufacturing rgely in the 1982 to present time fra clude Point Beach Unit 1 (November 19 ch 1983), Harris Unit 1 (August 1986) ruary 1988). All of these steam gene d prior to 1980 either at Westinghous ities. Operating experience with mon d steam generators from the Pensacola d in that these units generally have refueling outage or have not operate	trols to assure the stages of onstrates ts. It should rts in Westinghouse g process was ame. Specific 982), Watts Bar), and Catawba erator units were se's Lester or re recently a facility is not reached ed at all.
4. Improvement	s in Loose Parts Control	
Since the m manufacturi incidence o	elocation of the Westinghouse steam g ng facilities from Tampa to Pensacola f several loose parts events at opera	generator a and the ating nuclear

ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION PENSACOLA, FLORIDA

REPORT NO.: 99900104/88-01	INSPECTION RESULTS:	PAGE 5 of 7

power plants, a greater sensitivity to the possible presence of loose parts in steam generator units ready for shipment was established. As noted above, procedures for controlling loose parts were strengthened to provide increased sensitivity to shop personnel to this concern. Also, during the assembly process, a hold point was established for the ASME Authorized Nuclear Inspector to perform a check for cleanliness and the presence of loose parts. Finally, with the joining of the lower and upper steam generator shells, a round-the-clock monitor was stationed at the manway ingress point to maintain a log of all temporary hardware items and personnel belongings to assure items were not inadvertently left in the unit.

The inspectors concluded that Westinghouse had taken some positive steps to increase the assurance that loose parts in completed steam generators would be better controlled for replacement steam generators.

5. Review of Records

The inspectors selected three steam generator units manufactured over the past 10 years for review of the routing sheets to determine the degree of conformance of cleanliness and loose parts controls relative to procedural requirements. The units selected were:

- a. Catawba Unit 2 which was shipped in January 1980 from the Tampa facility.
- b. Vogtle Unit 2 for which manufacturing was initiated at the Tampa facility and completed at the Pensacola facility and shipped in October 1982.
- c. Indian Point Unit 3 which was completely manufactured at the Pensacola facility and will be shipped shortly.

The records indicated that at appropriate points in the assembly process the cleanliness and quality procedures were invoked and signed off. Customer hold points for a cleanliness check were noted as were those for the ASME/ANI. No significant differences in the number of cleanliness checks could be identified although as stated above there were differences in the degree of emphasis given in the applicable procedure regarding the concern for loose ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION PENSACOLA, FLORIDA

	RESULTS: PAGE 6 of 7
--	----------------------

parts. Despite the adequacy of controls in place, several instances have been identified in which the presence of loose parts was attributable to the manufacturing process. These instances included those steam generator units listed in Section 3 above. Westinghouse indicated that these units were manufactured prior to 1980 when the rate of steam generator manufacture was of the order of 30 units per year. The volume of production coupled with the lack of high sensitivity to the loose parts problem which arose in the 1982 to present time frame was cited as the most probable cause of the loose parts instances identified.

6. Reportability of Defects

The inspectors reviewed the procedures applicable to the Pensacola facility for the reporting of defects in safety related components under 10 CFR Part 21. The governing procedures are:

- WRD-OPR-19.0, Rev. 2, "Identification and Reporting of Substantial Safety Hazards, Significant Deficiencies, and Unreviewed Safety Questions," dated December 1, 1985.
- PQ-02-007, Rev. 2, same title as above, dated September 1, 1988.

The latter procedure is referenced in the Nuclear Components Division QA Program Manual in paragraph 16.4, "Significant Deficiencies."

The safety-related components in the steam generator are the tubes, tube sheet, shell, and lower head. The wrapper, the tube support plates, anti-vibration bars, and moisture separators are considered to be nonsafety-related.

The following examples of defects and their analyses were reviewed with regard to reportability:

 Feedwater Ring Backing Ring (1983): A concern was raised due to the potential loosening of the weld backing ring as a result of incomplete fusion during the welding process. Analysis determined that no portion of the backing ring could exit the feedwater ring (sparger) and enter the steam generator tube area, and that excess wear of the feedwater ring could not occur.

ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION PENSACOLA, FLORIDA

.

REP NC.	ORT : 99900104/88-01	INSPECTION RESULTS:	PAGE 7 of 7
	The problem was	determined to be unique to	the Model F design.
	 Bottom Mounted I beam weld failed pressure vessel occurrence was a performed. 	nstrumentation Columns (198 I that held an instrumentati penetration. It was determ in anomaly and an appropriat	4): An electron on column to the nined that this e repair was
	- Tube Ovality (19 tubes precluded tube bend area. bending process.	77): Improper ovality of t insertion of the anti-vibra Corrective action was take This was not a safety con	he steam generator tion bars at the n for the tube cern.
	The inspectors cond of 10 CFR Part 21 a the steam generator on the review of se be properly control evaluated for repor	luded that the procedures f and their applicability to t were consistent with NRC r everal examples, the Part 21 led and the instances of de tability.	or implementation he components of equirements. Based system appeared to fects were properly
Ε.	PERSONS CONTACTED		
	Westinghouse NCD		
	 * + Jose M. Martinez, Pr + John P. Mortara, Teo + B. R. Smelstoys, Ger * + Thomas A. Billman, Q * + E. Thompson, Manufact * + John Bell, Manufactu * + D. Harmon, QA Engine * D. Ford, Design Engi * A. Owens, Area Manag J. Gillespie, Manufa 	oduct Assurance Manager chnical Services Manager leal Manager luality Assurance Engineer cturing Engineer learing Engineer ering Manager neering Manager lear learing Manager	
	NRC		
	* + Walter P. Haass, Sen * + Roger W. Woodruff, S * + Keith Wichman, Secti * + Rafael Cid, NRC Assi	nior Reactor Engineer/VIB enior Reactor Systems Engin on Leader/ENTB gnee/CdeSN	eer/EAB
	* Attended entrance meet + Attended exit meeting	ing	

ALC: N

ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION COMMERCIAL NUCLEAR FUEL DIVISION PITTSEURGH, PENNSYLVANIA

FILISDORO									
REPORT NO.: 99900005/88-01	INSPECTION DATE: 12/14-15, 1988	INSPECTION ON-SITE HOURS: 16							
CORRESPONDENCE ADDRESS: Mr. Mead D'Amore, General Manager Westinghouse Electric Corporation Commercial Nuclear Fuel Division Post Office Box 355 Pittsburgh, Pennsylvania 15230									
ORGANIZATIONAL CONTACT: Mr. R. Cost, Manager of Quality Assurance TELEPHONE NUMBER: (412) 374-2359									
NUCLEAR INDUSTRY ACTIVIT General Electric, and Co	Y: Nuclear fuel assembly supplimoustion Engineering designed re	er for Westinghouse, actors.							
ASSIGNED INSPECTOR: Robert L Pettis Vr. for 3/10/89 R. L. Cilimberg, Reactive Inspection Section No. 1 Date									
OTHER INSPECTOR(S): Non APPROVED BY: E. T. Bake Branch	e et L Pottistr. for r, Section Chief, RIS-1, Vendor	3/10/89 Inspection Date							
INSPECTION BASES AND SCO	PE;	na ann an an an Anna ann an Anna ann ann							
A. <u>BASES</u> : 10 CFR 50,	Appendix B and 10 CFR 21								
B. <u>SCOPE</u> : Review rec rods for rod clust Callaway, and Maan	ords pertaining to the manufactu er control assemblies (RCCAs) fo shan (Taiwan).	re of hafnium control r Wolf Creek,							
PLANT SITE APPLICABILITY (Taiwan), and other reac	: Wolf Creek (50-482), Callaway tor facilities with fuel supplie	(50-483), Maanshan d by Westinghouse.							

ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION COMMERCIAL NUCLEAR FUEL DIVISION PITTSBURGH, PENNSYLVANIA

REP(NO.	DRT 99900005/88-01	INSPECTION RESULTS:	PAGE 2 of 4
an a shine an an an an an a	NIE CYTYNE HARCENTRE LE CONSTANTIAU CHARTAN YN CHARTAN RAW, MAENAR A CYMAR A MAE'R AR A CYMAR A CYMAR A RAW A Yn Cyfryng Harcenn ffel y Porton yn ferfan yn gynar yn ferfan yn ferfan yn ferfan yn ferfan yn ferfan yn ferfan		
Α.	VIOLATIONS:		
	None		
Β.	NONCONFORMANCES :		
	None		
С.	UNRESOLVED ITEMS:		
	None		
D.	STATUS OF PREVIOUS INSPI	ECTION FINDINGS:	
	Not applicable.		

E. INSPECTION FINDINGS AND OTHER COMMENTS:

- The Nuclear Regulatory Commission (NRC) staff informed Westinghouse (W) management representatives of the scope of the inspection during the entrance meeting on December 14, 1988, and summarized the inspection findings during the exit meeting on December 15, 1988.
- 2. Background

Karl Hurst, Manager of RCS Components Licensing and other W staff advised the NRC by telephone on November 23, 1988, of a hafnium swelling incident that was discovered during eddy current (EC) testing of RCCAs at Wolf Creek. The EC testing was performed by Combustion Engineering to measure wear between the control rod cladding and the guide tube. During the testing, bump anomalies were discovered in the 304 stainless steel cladding on the control rods. W believes that the swelling of the cladding is caused by hydriding of the hafnium by hydrogen which evolved from the reactor coolant and diffused through the stainless steel cladding. W estimates that the swelling that could result from complete hydriding of the hafnium would cause an increase in scram time that is still below the Wolf Creek technical specification. The NRC inspection discussed in Sections 3 and 4 of this report did not identify any nonconformances with requirements for hafnium rod traceability and certification, and stated that the hafnium swelling was not related to manufacturing.

ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION CONMERCIAL NUCLEAR FUEL DIVISION PITTSBURCH, PENNSYLVANIA

REPORT NO.: 99900005/88-01	INSPECTION RESULTS:	PAGE 3 of 4

3. Document Review

The inspector reviewed the computer lists in the W hafnium rod traceability system to determine what hafnium rods were used to manufacture the RCCAs which exhibited swelling in Maanshan 1, Wolf Creek, and Callaway. Hafnium ingot analysis and final product chemistry for 960 pieces of hafnium supplied to W by Western Zirconium Incorporated was selected at random for detailed review. The inspector determined that the certified data met W requirements for hafnium chemistry including a hydrogen specification of 60 parts per million (maximum). The same quality material was used to manufacture the RCCAs for Maanshan 1, Wolf Creek, and Callaway. The document review did not identify any deviations from W QA program requirements.

4. Hafnium Sweeling

The inspector met with Howard Menke, W Manager of Product Design to discuss what W had described as bump anamolies in RCCAs inspected during the third refueling outage at Wolf Creek. Mr. Menke summarized the information contained in a December 8, 1988, letter to C. E. Rossi of the NRC from Mr. W. J. Johnson, Manager of the W Nuclear Safety Department. W reviewed all manufacturing and assembly procedures as well as the fabrication inspection requirements for hafnium RCCAs. W concluded that inspection would have detected any as-built defects, therefore, manufacturing was considered to be an unlikely contributor to the bump anamolies.

Hafnium hydriding was identified as the most likely mechanism which led to the conditions reported at Wolf Creek. Hydriding occurs when hydrogen comes in contact with hafnium. Hydrogen from the reactor coolant diffuses through the stainless steel cladding and reacts with the hafnium to form hafnium hydride.

The results of the W investigation of the hafnium localized swelling phemomena covers all W supplied nuclear plants which use this type material and new information is currently being reported to the NRC. W has recommended continued operation of affected plants through three eighteen month or four annual cycles since W believes that current information does not indicate the existence of a substantial safety hazard. ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION COMMERCIAL NUCLEAR FUEL DIVISION PITTSBURGH, PENNSYLVANIA

REPORT INSPECTION NO.: 99900005/88-01 RESULTS:	PAGE 4 of 4
---	-------------

PERSONS CONTACTED: F.

- *W. Fortnett
- *J. Higginbotham *H. Menke *R. Pollard

- *L. Reiland

0

*R. Ripley, Union Electric

*Attended exit meeting.

Selected Bulletins or Information Notices Concerning Adequacy of Vendor Audits and Quality of Vendor Products

1.	Information	Notice	No.	89-02:	Criminal Prosecution of Licensee's Former President for Intentional Safety Violations
2.	Information	Notice	No.	89-11:	Failure of DC Motor-Operated Valves to Develop Rated Torque Because of Improper Cable Sizing
3.	Information	Notice	No.	89-18:	Criminal Prosecution of Wrongdoing Committed by Suppliers of Nuclear Products or Services
4.	Information	Notice	No.	89-20:	Weld Failure in a Pump of Byron-Jackson Design
5.	Information	Notice	No.	89-21:	Changes in Performance Characteristics of Molded-Case Circuit Breakers
6.	Information	Notice	No.	89-22:	Questionable Certification of Fasteners
7.	Information	Notice	No.	89-23:	Environmental Qualification of Litton-Veam CIR Series Electrical Connectors
8.	Information	Notice	No.	89-29:	Potential Failure of ASEA Brown Boveri Circuit Breakers During Seismic Event

71

at an A

ġ

VENDOR INSPECTIONS RELATED TO REACTOR PLANTS

													-					-	*		
1 1	1	C	1	G	1	K	1	L	1	М	1	N	1	T	1	W	1	W	1	1	1
1 1	1	A	1.	R	1	Ε	1	A	1	D		0	1	R	1	A	1	0	1	I	1
: 1	1	L	1	A	1	W	1	S		N	1	R	4	0		T	1	L	1	۵	1
I PLANTS	1	L	1	N	1	A	1	A			1	T	1	J	1	E	1	F	1	N	1
1 1	1	A	1	D	1	U	1	L	1	1	1	Н	1	A	1	R	1		1		1
1 1	1	Ņ	1		1	N	1	L	1	C	1		1	N	1	F	1	C	1		1
1	1	A	1	6	1	E	1	E	1	E	1	R	1		1	0	1	R	1		1
1	1	1	1		1	Ł	1		1	1		14	-		1	n D	1	E c	1		1
			1	L	1		1		1	5	1	N	1		1	v	1	C V	-		1
I VENDORS I	1		1	r	1		1		1	U	1	n	1		1		1		1		1
	1		1		1				•		1				1		1				
1	1		1		1		1		1		1.				1		1.		-1-		-
1 Ques Reictor	1		1		1		1		-		1		1	X	ì		1		1		
HUNG NEISTER	1		1		1		1		1		1				1		1				
					-!-		-1-				-!-								- : -		-1
Combustion Faminperion		Numerous Facilities - Refer to														1					
1 Power Systems Group		Table I of Inspection Report																			
			- -		- ; -		- : -		- } -		- -		- ; -				- ; -		- -		- ;
1 Copes Vulcan	1		AI	1 1	uc	lear	Po	wer	P	lant	5										
1	1		1		ţ		1		1		1				1				1		1
	-1-		- ; -		- ; -		- ; -		- } -		- { -		- 1		-1-		- 1 -		- ; -		- {
: Ebasco Services	1		ł		1						1		1		1	X	1		1		1
	1		1		1		1				1		1		1		1		-		1
	-1-		- ; -		-1		- 1 -		- 1		- }-		- ; -		- 1	****	- 1		- 1 -		-
Klockner-Moeller			1	X		X	1	X	1	X	1	X	1		1		1		1	X	1
1	1		1		1		1		1		1				1		1		1		1
	- : -		- 11		- : :				-						1						-
Westinghouse Elec. Corp.	1	X	-		1		1				-				1		-	*	-		
Commercial Nuclear Fuels	1						1		1		1				1						_
Hestinghours Fire Core	1		A	1 .		lear	pi	ant			Lin		0.0	house	1						
Westinghouse tiet, Lorp.	-		PI	IR-T	VP	p Nu	- 14	ent	5+	e a c fi	Sur	only	R. C.	vster	2.0						1
I MUCIERI & MOVANCED IECH,			- 1.		14		-1-		- 1.		-1-		- 1				-1		-]		- 1
1 Westinghouse Fler Core			0	11 1	lur	lear	p	ant	5	with	bis	esti	0.0	house	e						1
Luclear Connonents Div	1		FI	IR-T	VD	e Nu	cle	Par	Sti	869	Sui	001	S	vste	85						
Auciear Components Div Law-likbe auciear pream pubbly bys																					

This periodical covers the results of inspection performed by the NRC's Vendor Inspection Branch that have been distributed to the inspected organization during the period from January 1989 through March 1989.

HAC FORM 335 U.A. NUCLEAR REQULATORY COMMISSION	1. REPORT NUMBER (Assigned by)	PPHB: DPS, add Vol. No., Hany)
NACH 1102. BIRLIOGRADUIC DATA CHEFT	NUD 50-00/0	
3201, 3202 DIDLIOGRAFHIC DATA SILLI	Vol. 13. No. 1	
SEE INSTRUCTIONS ON THE REVENSE	1 164 VE BLANK	
Licensee Contractor and Vendor Inspection Status Report,	J LEAVE BLOWN	
Quarterly Report January 1989 - March 1989		
	4 DATE REPORT	TCOMPLETED
A AUTHORIS	April	1989
	6. DATE REPO	DRT ISSUED
	MONTH	YEAR
	April	1989
7 PERFORMING ORGANIZATION NAME AND MAYLING ADDRESS (Incive ZID Code)	8. PROJECT/TASK/WORK UNIT N	UMBER
Division of Reactor Inspection and Safeguards	9 FIN OR GRANT NUMB	samentaryonal instruction and south and sold and south and s
Office of Nuclear Reactor Regulation		
U.S. Nuclear Regulatory Commission		
Washington, D.C. 2000		
10. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Include Zip Code)	118 TYPE OF REPORT	
	Quarterly	
Same as 7. above	D PERIOD COVERED (Inclusive de	tes)
	January 1989 -	March 1989
12 SUPPLEMENTARY NOTES	Ann. mannersonannen mensen annersoner	And a second of the second s
13. 48578.477 (90) weat a (au)	and the second	
the period from January 1989 through March 1989.		15 AVAILABILITY
		STATEMENT
vendor inspection		Unlimited
		16 SECURITY CLASSIFICATION
D IDENTIFIERS/OPEN ENDED TERMS		(Thu page) Unclassified
		Unclassified
		17 NUMBER OF PAGES
		18 PRICE

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D.C. 20555

OFFICIAL BUSINESS PENALTY FOR PRIVATE USE, \$300 SPECIAL FOURTH CLASS RATE POSTAGE & FEES PAID USNRC PERMIT No. G-67

120555139531 1 IANINV US NRC-OADM DIV FOIA & PUBLICATIONS SVCS TPS PDR-NUREG P-209 WASHINGTON DC 20555