

U. S. NUCLEAR REGULATORY COMMISSION  
REGION I

Report No. 50-333/89-80

Docket No. 50-333

License No. DPR-59

Licensee: New York Power Authority  
P. O. Box 41  
Lycoming, New York 13093

Facility Name: James A. FitzPatrick Nuclear Power Plant

Inspection At: Scriba, New York

Inspection Conducted: May 1-26, 1989

Team Members: H. Gray, Senior Reactor Engineer, DRS, Region I  
J. Lara, Reactor Engineer, DRS, Region I  
C. Woodard, Reactor Engineer, DRS, Region I  
R. Barkley, Reactor Engineer, DRP, Region I  
C. E. Morris, Electrical Engineer, NRR  
A. Perez, Nuclear Regulatory Body of Spain (observer)  
G. Toman, NRC Consultant, ERC International  
G. Morris, NRC Consultant, ERC International  
D. Prevatte, NRC Consultant, ERC International  
A. Goyal, NRC Consultant, ERC International

Team Leader: Jack Stromides 8/17/89  
for V. Koshy, Senior Reactor Engineer, DRS, date  
Region I

Approved by: Jack Stromides 8/17/89  
for J. Durr, Chief, Engineering Branch, DRS date

Inspection Summary: See Executive Summary in Section 1.0.

## TABLE OF CONTENTS

|   | <u>Page</u> |
|---|-------------|
| 1.0 Executive Summary .....                                       | 1           |
| 2.0 Introduction and Background .....                             | 5           |
| 3.0 Inspection Objective and Methodology .....                    | 5           |
| 4.0 Details of Inspection of Electric Power Systems .....         | 7           |
| 4.1 General Review of Design Features .....                       | 7           |
| 4.2 Verification of As Built Drawings .....                       | 7           |
| 4.2.1 4kV Switchgear .....  | 7           |
| 4.2.2 600V AC Load Centers .....                                  | 8           |
| 4.2.3 600V Motor Control Centers and<br>Distribution Panels ..... | 10          |
| 4.2.4 419/125V DC System .....                                    | 13          |
| 4.2.5 Diesel Auxiliary Systems .....                              | 15          |
| 4.3 Electrical System Operation .....                             | 16          |
| 4.3.1 Procedures .....  | 16          |
| 4.3.2 Testing .....   | 19          |
| 4.3.3 Administrative Controls .....                               | 20          |
| 4.3.4 EDG Support Systems .....                                   | 22          |
| 4.3.5 HVAC for Electrical Switchgear Area .....                   | 24          |
| 4.3.6 Electrical Systems Training .....                           | 25          |
| 4.4 Electrical Configuration Control and Plant Modifications .... | 26          |
| 4.4.1 Administrative Controls on Electrical<br>Load Growth .....  | 26          |
| 4.4.2 Review of Modification Packages .....                       | 28          |
| 4.5 Review of Protection and Coordination .....                   | 30          |
| 4.5.1 Offsite Power System and 4.16kV<br>Electrical System .....  | 30          |
| 4.5.2 600V AC Electrical System .....                             | 32          |
| 4.5.3 125V DC System .....  | 34          |
| 4.6 Electrical System Stability .....                             | 36          |
| 4.6.1 Undervoltage Study .....                                    | 36          |
| 4.6.2 Offsite Power System .....                                  | 36          |
| 4.6.3 600V Design Calculations .....                              | 38          |

|   |   |    |
|---|---|----|
| 4.7                                     | Maintenance .....   | 41 |
| 4.7.1                                   | Offsite Power System and 4.16kV AC<br>Electrical System ..... | 41 |
| 4.7.2                                   | 600V AC Electrical System .....                               | 41 |
| 4.7.3                                   | 419/125V DC System .....                                      | 44 |
| 4.7.4                                   | Diesel Generator Maintenance Program .....                    | 46 |
| 4.7.5                                   | Air System .....  | 47 |
| 4.8                                     | Emergency Diesel Generator .....                              | 48 |
| 4.8.1                                   | Cooling System .....  | 48 |
| 4.8.2                                   | Fuel System .....   | 49 |
| 4.8.3                                   | Air System .....  | 55 |
| 4.8.4                                   | Electrical Controls .....                                     | 57 |
| 4.8.5                                   | Long Term Operation .....                                     | 57 |
| 4.9                                     | Reactor Building Closed Loop Cooling Water System .....       | 58 |
| 5.0                                     | Unresolved Items .....  | 61 |
| 6.0                                     | Exit .....  | 61 |
| Attachment 1 - AC One Line Drawing      |   |    |
| Attachment 2 - 419V DC One Line Drawing |   |    |
| Attachment 3 - 125V DC One Line Drawing |   |    |
| Attachment 4 - Calculation Reviewed     |   |    |
| Attachment 5 - Persons Contacted        |   |    |

## 1.0 EXECUTIVE SUMMARY

A team of NRC inspectors and contractor personnel conducted a Safety System Functional Inspection (SSFI) at the James A. Fitzpatrick Nuclear Power Plant, Scriba, New York, to assess the electrical power system including the Emergency Diesel Generators and their support systems. During this inspection, the SSFI team reviewed design bases, surveillance and calibration, maintenance, system operations, and associated procedures.

The team determined that the site engineering staff was very knowledgeable in the maintenance and operation of the plant. However, certain weaknesses were noted in design-bases evaluations and in the lack of attention to details in drawing control, surveillance testing, and maintenance activities.

Significant deficiencies identified during the inspection include those listed below.

- The design bases for the plant assumes that the Reactor Building Closed Loop Cooling Water (RBCLCW) system is a closed loop system inside the containment. However, under certain emergency conditions (e.g., loss of power to the RBCLCW pumps), an automatic action connects the emergency service water system to the RBCLCW systems thereby opening the RBCLCW system to the outside environment. Furthermore, the RBCLCW system is not protected against a high energy line break and is not equipped with containment isolation valves.
- A programmatic deficiency was formed in the electrical area regarding the updating of electrical one line drawings to reflect the as-built equipment ratings and sizes.
- The level gauges for the fuel in the Diesel Generator fuel day tank were not calibrated to a standard. Also, numerous concerns were identified with regard to the emergency diesel generator fuel supply, air, and dc electrical control systems.
- Although the emergency diesel generator maintenance had been significantly improved, a documented formal maintenance program and procedures had not been developed.
- The checklist used during operator rounds showed an unacceptably low acceptance value for dc battery voltage.
- The dc breakers, the undervoltage relay for the dc bus and the check valve in the control air for the reactor building closed cooling water system isolation valves were never tested to demonstrate the capability of performing their specific safety functions.
- The original HVAC design calculations for the switchgear enclosure did not adequately consider function during a high energy line break in the reactor building.
- There was not an integrated up to date calculation to support the protection and coordination of the electrical system.

- There was not a thorough evaluation to support a modification performed in 1981, which resulted in the diesel generator room drains being plugged and the potential for spreading an oil fire into adjacent diesel generator rooms if the sprinkler system was actuated.

Significant strengths identified during the inspection include these listed below:

- The team found that the program of developing cognizant engineers is an effective program to provide more attention to design details and operational requirements.
- The team concluded that surveillance and calibration testing for electrical equipment was generally acceptable except for the discrepancies addressed in Section 4.7.

Based on the concerns raised in this inspection the licensee committed to take the following corrective actions.

| <u>Action</u>  | <u>Scheduled Completion</u>       |
|--|-----------------------------------|
| • Field Survey of AC and DC loads (4.2.4 and 4.2.3)                                | November 1, 1986                  |
| • On line program to update electrical load configuration and design bases (4.4.1) | End of 1990                       |
| • Maintenance program for emergency diesel generator (4.7.4)                       | Prior to refueling outage in 1990 |
| • Fuel day tank level switch changes (4.8.2.1)                                     | End of 1989                       |
| • DC breaker testing (4.7.3)   | Mini outage of 1989               |

#### Summary of Inspection Findings

| <u>Area</u>                                    | <u>Section</u> | <u>Number 50-333/</u> |
|--|----------------|-----------------------|
| A. <u>Violations</u>                           |                |                       |
| 1. Reactor Building Closed Loop Cooling System | 4.9            | 89-80-01              |
| 2. Inadequate Procedures                       |                | 89-80-02              |
| 2.1 Day Tank level switch calibration          | 4.8.2.7        |                       |
| 2.2 Backup air supply to EDG                   | 4.8.3.2        |                       |
| 2.3 Minimum acceptable voltage for 125V DC     | 4.3.4          |                       |
| 2.4 EDG annunciator response                   | 4.3.1.2        |                       |
| 3. Inadequate Drawing Control                  |                | 89-80-03              |
| 3.1 AC Discrepancies                           | 4.2.3          |                       |
| 3.2 DC Discrepancies                           | 4.2.4          |                       |

|     |  |                    |          |
|-----|--|--------------------|----------|
| 4.  | Inadequate Testing   |                    | 89-80-04 |
|     | 4.1 125V DC circuit breakers   | 4.7.3              |          |
|     | 4.2 125V DC undervoltage alarm   | 4.7.3              |          |
|     | 4.3 Check valve in the air system for<br>RBCCW system isolation                  | 4.7.5              |          |
| 5.  | Inadequate Design Control  |                    | 89-80-05 |
|     | 5.1 Plugging of floor drains in DG room  | 4.4.2.3            |          |
|     | 5.2 Reactor building MCC<br>Environmental Enclosures                             | 4.4.2.2            |          |
| 6.  | Inadequate Control of Diesel Oil<br>Procurement (Non Cited)                      | 4.8.2.8            | 89-80-06 |
| B.  | <u>Unresolved Items</u>  |                    |          |
| 1.  | RBCLCW Isolation Valve Air Supply Design   | 4.7.5              | 89-80-16 |
| 2.  | Electrical Load Growth Control and<br>Updating of Electrical Design Calculations | 4.4.1              | 89-80-12 |
| 3.  | Reactor Building MCC Enclosure Cooling<br>Unit Testing                           | 4.4.2.2            | 89-80-08 |
| 4.  | Adequacy of EDG room drains  | 4.4.2.3            | 89-80-09 |
| 5.  | Residual Voltage Transfer  | 4.5.2              | 89-80-13 |
| 6.  | 4160 Volt Breaker Control Circuit<br>Coordination                                | 4.5.1.5            | 89-80-10 |
| 7.  | 600 Volt System Voltage<br>Operating Range                                       | 4.6.3.e<br>4.6.3.f | 89-80-11 |
| 8.  | Annunciator Response Procedure not at<br>EDG Panels                              | 4.3.1.3            | 89-80-07 |
| 9.  | DG Load Testing  | 4.3.2              | 89-80-14 |
| 10. | a. Fuel Oil Day Tank Level Switch Logic  | 4.8.2.1            | 89-80-18 |
|     | b. Fuel Oil Day Tank Level Switch Positions                                      | 4.8.2.2            | 89-80-18 |
|     | c. Fuel Filter Design/Operation  | 4.8.2.4            | 89-80-18 |
|     | d. Diesel Fuel Technical Specifications  | 4.8.2.5            | 89-80-18 |
|     | e. Diesel Fuel Consumption Test  | 4.8.2.6            | 89-80-18 |
| 11. | Lube Oil Sampling  | 4.7.4              | 89-80-15 |

12. Unrestrained Equipment 4.2.4 89-80-17

C. Observations

- |   |                      |
|---|----------------------|
| 1. Fuse Control   | 4.2.2 & 4.2.3        |
| 2. Wire Bend Radius   | 4.2.2                |
| 3. Control of Void (Superseded) Documents                             | 4.2.3 & 4.2.2        |
| 4. RBCLCW Isolation Valve Air Supply Testing                          | 4.7.5                |
| 5. Diesel Starting Air  | 4.8.3.2              |
| 6. Transfer of Offsite Power Sources                                  | 4.3.3.1              |
| 7. Coordination of CRD Pump Breaker<br>and Transformer Feeder Breaker | 4.5.2.2 &<br>4.5.2.3 |
| 8. Preventive Maintenance for 600V MCCs                               | 4.7.2                |
| 9. Breaker Reclosing  | 4.7.2.2              |
| 10. 4160 Volt Switchgear Interrupting<br>Capability                   | 4.5.1.3              |
| 11. DG Room Ventilation Procedure                                     | 4.8.3.3              |
| 12. Emergency Fuel Shutoff  | 4.8.2.3              |
| 13. EDG Governor Modification for Self<br>Sustaining Operation        | 4.8.4                |
| 14. Long Term Operational Procedure for EDG                           | 4.8.5                |

## 2.0 INTRODUCTION AND BACKGROUND

The electric power systems (onsite, offsite and emergency diesel generators) are important to the safety of a nuclear power plant and must be designed and maintained accordingly. The safety function of each electrical system is to provide adequate electrical power when called upon for the safe operation of the plant under all operating modes including anticipated operational occurrences and postulated accidents. To achieve this safety function, 10CFR 50, Appendix A, General Design Criteria 17 and 18 for electric power systems specify design requirements and the required provisions for the periodic inspection and testing of electric power systems.

The Final Safety Analysis Report (FSAR), Chapter 8, Electric Power Systems, describes how these design requirements are met. It also specifies the licensee's commitments with respect to the applicable Regulatory Guides (RGs) and industry standards such as the Institute of Electrical and Electronics Engineers (IEEE) Standards.

Following the issuance of the Operating License, plant modifications can be made which involve significant changes in the configuration of the electric power systems. These modifications may involve substantial load growth of the electric power systems, and adequate controls must be exercised to assure the electrical power systems stay within their rated load capacity. Overloading the electrical systems could adversely affect the functioning of the protective relays and coordination of the interrupting devices. Uncontrolled load growth also could create bus undervoltage conditions that may trip out or damage motors and result in unnecessary bus transfers that may cause other operational transients. Therefore, plant modifications should be evaluated to ensure that their effect on the electrical systems is in accordance with General Design Criteria 17 and 18 and FSAR commitments.

Types of significant changes in the configuration of electric power systems that might adversely affect the performance of these systems are: a transfer of a large load from one bus to another; replacement of system components such as breakers and fuses with a component having different functional characteristics; and changes in the set point of protective relays or breakers. All such changes should be reviewed to ensure the integrity of the electrical system.

## 3.0 INSPECTION OBJECTIVE AND METHODOLOGY

The objective of the Safety System Functional Inspection (SSFI) at Fitzpatrick was to assess the operational readiness of the electrical system, including the emergency diesel generators and their support systems, and to evaluate the following

- The adequacy of the electrical system to perform the safety functions required by its design bases.
- Effectiveness of testing and calibration to assure the electrical system will perform the required safety functions.

- Effectiveness of maintenance of components to ensure system reliability under postulated accident conditions.
- Adequacy of human factor considerations related to electrical system and emergency diesel generator procedures to ensure proper operation under normal and accident conditions.

To accomplish this objective, the SSFI team verified that the physical configuration, including modifications, conforms to the current electrical drawings and that the evaluations of the configuration are correct and that they support the required functioning of the electric power system. The team reviewed the adequacy of the safety related electrical distribution system with respect to the following factors affecting system availability: (1) selectivity among the various protective devices that respond to overload; (2) sensitivity and speed of response of the protective devices considering the characteristics and criticality of the protected equipment; (3) accuracy of the coordination curves in representing the types, ratings, and settings of the devices actually present in the plant; (4) adherence to the principal that no single failure (including a failure of a circuit breaker, fuse, protective relay, or instrument transformer) can disable more than one redundant safe-shutdown train; and (5) absence of apparent credible common cause multi-train failure modes in those cases where complete selective coordination cannot practically be achieved.

Primary emphasis was placed on the safety buses and connected loads, including 4160V ac, 600V ac, 125V dc and 419V dc systems. A selected sample of Class 1E and Non 1E buses as indicated in Attachments 1, 2 and 3, were physically inspected to collect as-built data on relay set points, load configurations and equipment ratings. These data were compared to electrical one line drawings, protective device setpoint calculations and load studies. The licensee's analyses on selected protective relaying and breaker coordination were reviewed and field verified to determine the electrical system capability to limit the effects of electrical faults.

The diesel generator support systems, air start, cooling, and fuel systems were reviewed to determine if the current configuration supports the design bases and if these systems are maintained to support the emergency operation of the diesel generators.

Selected electrical modifications were reviewed in detail to verify that appropriate controls for the assurance of quality were in effect and that adequate safety evaluations were performed by the licensee to ensure that no unreviewed safety questions exist, as defined in 10 CFR 50.59.

The onsite electrical power systems, emergency diesel generators and the 125V battery load calculations were reviewed to verify the systems' capability to respond to design basis events.

The team witnessed the technical specification surveillance on diesel generator loading and evaluated nonlicensed operator skills and training.

## 4.0 DETAILS OF INSPECTION

### 4.1 General Review Of Design Features

#### 4.1.1 Offsite Power Systems and 4160-Volt System

The J. A. FitzPatrick Nuclear Power Plant is connected to four transmission lines: two 345-kV lines and two 115-kV lines. At the JAFNPP transmission substation, the 345-kV lines connect to a common bus via airblast circuit breakers. The main transformer for the generator, actually two transformers in parallel (T1A and T1B), connect directly to the 345-kV bus. The generator and the normal service transformer (T4) connect to the 22.8-kV side of the main transformer. The two 115-kV lines are connected to a common bus via oil circuit breakers. Two reserve station service transformers are connected to the 115-kV bus. A disconnect switch is located in the bus between the two transmission line connections so that each reserve transformer could be connected independently to a 115-kV transmission line. (See oneline diagram in Attachment 1). However, under normal conditions, the disconnect switch is normally closed so that if either transmission line trips (i.e., the circuit breaker at each end of the line opens automatically), the two reserve transformers will be fed from the remaining line. All of the 345-kV and 115-kV lines are connected to the Niagara Mohawk transmission system.

The 4160V system is normally fed from the 345-kV system from the two secondary windings of T4. This transformer is provided with a 19-step load tap changer to maintain the secondary 4160 volt within 1 1/2%. The "X" winding feeds the two 4-kV buses associated with the recirculation pump motor-generator sets. The "Y" winding feeds the two normal 4-kV buses through a bus tap. Each of the normal 4-kV buses subfeeds to its respective safety-related bus through two 250-MVA circuit breakers in series. Under abnormal operating conditions or from shutdown through startup, each normal 4-kV bus also can be fed separately from the 115-kV system from the reserve power transformers associated with that division (either T2 or T3). The voltage on this transformer is controlled by the Niagara Mohawk Power load dispatcher.

The onsite emergency supply for each safety-related bus consists of two 3250 kVA diesel driven generators per bus with a unique forced paralleling circuit design. No deficiencies were observed in this area.

### 4.2 Verification Of As-Built Drawings

#### 4.2.1 Offsite Power Systems and 4-kV Switchgear

The team reviewed selected portions of the offsite switchyards, main and reserve power transformers, and the 4160V switchgear. The as-built single line drawings and the equipment were compared and no deficiencies were noted, except for the concerns on the offsite power system addressed in Sections 4.3.1.1 and 4.3.3.1.

#### 4.2.2 600-Volt AC Load Centers

The team physically inspected Unit substation L-16 and verified the equipment ratings by observing the nameplate data. All the incoming feeders and load circuit breakers were checked for equipment data and cleanliness. The team's specific findings are discussed below.

##### Lack of a Fuse Control Program

The team reviewed all the control fuses associated with load center L-16 to verify their rating and type. In a number of cases, information could not be collected because the fuse label was not visible. The team found that the ampere rating of the fuses agreed with that specified on the design documents, but the type was not always consistent (see Section 4.2.3 for similar finding). The inspection team determined that the licensee does not have a fuse control program in place.

Without a fuse control program to ensure that the proper ampere rating and type of fuse is used, a loss of coordination could occur. The licensee responded by issuing a standing order on this subject and is implementing a fuse replacement program to ensure the correct rating and type of fuse.

- Discrepancies Between Nameplate Data and Design Documents

The inspection team identified the following discrepancies between the circuit breaker nameplate data and the information on the design documents.

- Unit compartment 703C (feeder for MCC 116100) breaker trip devices had settings of 80 A, 85 A, and 90 A, whereas the single line drawings and manufacturers' drawings showed these settings to be 40 A. The licensee confirmed this as an error in documentation and has rectified the situation.
- Unit compartment 704C (feeder for Bus 116300) breaker nameplate identified the breaker to be rated for 225 V, whereas the required nominal rating should have been 600 V. The licensee discussed the matter with the manufacturer, GE, who confirmed that the subject breaker was actually a 600-volt circuit breaker. GE will provide a new nameplate stating the correct rating.

- Load Center Spare Breakers

The team found that spare breakers were left in the drawn-out position as a permanent arrangement. The team was concerned that this could compromise the integrity of the substation with respect to ingress of dust and vermin: dust could cause long-term contamination of the unit substation, whereas the latter could result in insulation deterioration and possibly short circuits. In addition, the partially drawn-out

position of the breakers, especially those at a higher level, is a configuration that was not analyzed for seismic forces. In response to this finding, the licensee initiated prompt action to ensure that the practice of keeping the spare breaker pulled out is no longer followed.

- Update of Manufacturer's Drawings

The manufacturers' drawings have not been updated since 1971 and did not reflect the present plant configuration. This resulted in a number of discrepancies between these drawings and the as-built load center. The team noted that the Design Document Control Program did not require that out-of-date drawings be identified as void or superseded. The licensee should evaluate this situation and establish the necessary controls.

- Circuit Breaker Overcurrent Settings

The team found that series overcurrent settings on two breakers varied considerably between the phases of each breaker as shown below:

- a. Unit 702B - Incoming Feeder Overcurrent Release 2A
  - Phase A: 1280 A
  - Phase B: 1280 A
  - Phase C: 1600 A
- b. Unit 704A - Feeder for Bus 116200 Overcurrent Release 1B
  - Phase A: 560 A
  - Phase B: 320 A
  - Phase C: 600 A

The variance was the result of recalibration during preventive maintenance. However, when substantial drift between phases occurs over time and is not attended to, it can possibly result in maloperation as this drift is indicative of a change in performance of that particular overcurrent trip mechanism. Present preventive maintenance procedures only require that the breaker operate within a particular time frame for a specified current value. In the event the test shows that it operates outside this time range, an adjustment is made without noting the new setting of the graduated scale on the overcurrent release. Therefore, the device would be allowed to drift over time without any acknowledgment of this change in setting.

The drifting of the overcurrent releases made visual inspection of the settings unreliable. Since no record was kept or displayed of the last setting, the equipment was susceptible to unauthorized adjustments that could affect the safety of the plant. The licensee stated that this information would be recorded in the future and these data reviewed by the maintenance engineer.

- Cable Bend Radius

During a random inspection of unit substation L-14, the team noted that the power cable for the reactor building cooling water pump 15P-2B had a 180° bend with a bending radius of about 3 inches. The licensee agreed that this was less than the minimum bend radius recommended by the manufacturer, Okonite. Although this switchgear serves only non-safetyrelated loads, the licensee committed to rectify the situation and to look at other potential areas for this problem.

#### 4.2.3 600V Motor Control Centers and Distribution Panels

The team inspected Motor Control Center MCC C161 and verified the equipment ratings by opening the starter compartment doors and noting the data on the various nameplates. All but two of the compartments were checked for equipment data and cleanliness. The teams findings are discussed below.

- Lack of a Fuse Control Program

A number of the compartments had been modified with an additional control fuse installed for remote shutdown requirements. Although the control fuses were of the same rating, the type of added fuse was different in each circuit. From discussions with various personnel, it was clear that there was no fuse replacement program in place that would ensure that a fuse of the proper rating and type was installed. This finding applies to the following MCC C161 compartments:

- OA2, OA3, OB1, OB2, OB3, OC1, OC2, OC3, OD2, OE1, and OE3.

Control schematic drawings typically specified only the current rating and not the type of fuse.

The licensee acknowledged the absence of a fuse control program to ensure that the proper ampere rating and type of fuse is utilized (see Section 4.2.2 for licensee corrective action).

- Update of Manufacturer's Drawings

There were a number of discrepancies in the nameplates on the compartment doors, single lines, and manufacturers' drawings as follows:

- The manufacturer's outline drawing indicated that compartment OD4 should be SPARE; the actual nameplate indicated that the compartment fed a lighting panel.
- The manufacturer's drawing indicated "BLANK" for one compartment; the team found instead two nameplates, one indicating "SPARE" and the other "REACTOR BUILDING DISTRIBUTION PANEL RB-AC-6". The licensee considers the manufacturers' drawings as information drawings and are not subjected to the normal update process.

This approach can lead to problems when significant modifications are made to the MCCs. The licensee should evaluate this situation to determine if modifications to their drawing control system are appropriate.

- Inadequate Drawing Control

A number of MCC compartments had discrepancies between the actual motor rating and that given on the one line diagram 11825FD-15, Rev. 15.

| <u>Compartment</u> | <u>One Line Equipment</u> |             | <u>Actual</u> |
|--------------------|---------------------------|-------------|---------------|
| OB1                | 1.3 hp                    | 10-MOV-012B | 1.6 hp        |
| OB2                | 4.0 hp                    | 10-MOV-089  | 1.0 hp        |
| OC3                | 3.9 hp                    | 10-MOV-926B | 2.0 hp        |

The above discrepancies constitute a violation of 10 CFR 50 Appendix B Criterion V which requires that activities affecting quality be prescribed by controlled drawings (50-333/89-80-03.3). Other examples of the same violation are addressed in Section 4.2.4. The licensee committed to perform a walkdown of the AC loads prior to the end of 1990. The updating of the calculation and respective drawings are addressed in Section 4.4.1.

The team noted that in the case of the MCC drawings, the manufacturer's drawings have been updated since 1971 to reflect the present plant configuration. However, the team found that load/relay data such as full load current, short circuit rating and CR123 heater had not been incorporated in the updated drawings.

- Overload Relays

The team verified all the overload relay and heater element size data. Per JAF Preventive Maintenance Procedure MP-56.1, the heaters were to be selected at 300% of rated motor current for Class 1E motor operated valves (MOV's). For other loads, such as fans and pumps, the normal industry practice of approximately 100% full load current times the motor service factor is followed.

The use of 300% setting for heater elements is inadequate as it generally fails to provide adequate protection. This is especially true for stall (locked rotor current) protection. As MOV motors are most likely to require locked rotor protection, the present practice of using 300% heaters is technically unsound. A sustained locked rotor current can cause permanent damage to the motor. The following inconsistencies were found for MOV's:

| <u>Unit</u> | <u>MOV Rating<br/>(hp/FLA)(A)</u> | <u>OL Relay<br/>Type</u> | <u>Heater</u> | <u>Heater<br/>Rating(A)</u> | <u>Heater/Rating<br/>Ratio(%)</u> |
|-------------|-----------------------------------|--------------------------|---------------|-----------------------------|-----------------------------------|
| OA2         | 2.6/4.7                           | CR124K028                | 3 X K16.3B    | 14.1                        | 306                               |
| OA3         | 2.6/4.7                           | CR124K028                | 3 X K13.6B    | 11.7                        | 250                               |
| OB1         | 1.63/3.2                          | CR124K028                | 3 X K9.63A    | 8.37                        | 262                               |
| OB2         | 1.0/2.2                           | CR124K028                | 3 X K6.42A    | 5.69                        | 259                               |
| OB3         | 2.6/4.6                           | CR124K028                | 3 X K16.3B    | 14.1                        | 306                               |
| OB4         | 0.66/0.73                         |                          | 3 X C2.20A    | 2.1                         | 300                               |
| OC1         | 0.13/0.76                         | CR124C024                | 3 X C2.20A    | 2.1                         | 276                               |
| OC2         | 0.13/0.76                         | CR124C024                | 3 X C2.20A    | 2.1                         | 276                               |
| OC3         | 2.0/2.8                           | CR124K028                | 3 X K9.63A    | 8.37                        | 299                               |
| OD2         | 4.0/6                             | CR124K028                | 3 X K19.4B    | 16.9                        | 282                               |
| OE1         | 0.133/0.43                        | CR124C024                | 3 X C0.43A    | 0.41                        | 95*                               |
| OE3         |                                   | CR124K028                | 3 X K9.63A    | 8.37                        | SPARE                             |

\* Non-1E valve

On presenting the above heater/rating ratios to the licensee, the team was informed that those sections of PM-56.1 that provided the criteria for sizing the heaters were being revised and the proposed procedure was described to the team. The proposed changes if implemented will satisfy the team's concerns.

Some of the above motor data was taken from the motor nameplates that were accessible; whereas the licensee personnel provided balance from MOVATS Data Sheets and the Master Equipment List (MEL). The licensee informed the team that the MEL was a controlled document and should reflect the existing plant configuration. However, the following differences were noted:

| <u>Valve</u> | <u>Actual</u>   | <u>MEL</u>    |
|--------------|-----------------|---------------|
| 10MOV-26B    | 3.9 hp<br>4.9 A | 2 hp<br>2.8 A |
| 10MOV-31B    | 3.2 hp<br>4.2 A | 4 hp<br>6 A   |

Apparently some MOVs had been changed in the field, but the MEL was not updated. The licensee indicated that this may have been due to work in progress. The team considered this is an example of a break-down in the plant program for updating the Master Equipment List. This does not pose a significant concern, as the design changes and operations are done according to the electrical one line drawings.

#### • Cable Installation

The cables in the vertical wiring compartment of the MCC were found bundled together but not supported to the sides of the MCC compartment. All the wiring inside the MCC had been bundled and supported; no sharp corners or edges were found and the cables are tagged in the wireway

for identification. In a number of cases, spare cables were bent with very small radii and were not attached to the side of the wiring compartment. Although the cables are still susceptible to movement, the use of strong terminal strips provided the necessary support to the cable termination.

The cables as they are installed and used do not compromise safety; however, clamping of the cables to the sides of the MCC cable compartment would protect the cables from movement. The use of spare cables which have been bent with a very small radii should be reviewed before their use in the future. These are some good industry practices worthy of attention.

- MCC Verification

The team physically inspected Distribution Panel 71ACB3 and verified equipment ratings by opening the panel door and noting the rating of the breakers. The team also visually checked the panel for missing cover plates, cleanliness, and general upkeep. The breaker data agreed with the single line diagram, Dwg. No. 11825-FE-1AD. The team checked the circuit list on the inside of the panel door and noted a few discrepancies between this list and the controlled single line diagram. The maintenance department stated that this list was not a controlled document.

- Void or Superseded Drawings

The licensee provided Schematic drawings to the team to review the controls related to equipment covered by this inspection. The team found that the vendor's schematic drawings had not been kept up to date. There was no notification of this on the subject drawings. The team was subsequently informed that only the "ESK" series drawings were valid. The team considered the fact that the drawings that are not updated are not identified as void or superseded is a deficiency in the Document Control Program. The licensee utilizes their drawings only for reference. The engineers that the team interacted with were knowledgeable about this fact. However, this can be a problem in the future if the drawings are not identified to be obsolete.

#### 4.2.4 419/125 Vdc System

The team selected the 'B' 125 Vdc and 419 Vdc systems to assess the licensee's dc system configuration controls. The team performed a walkdown of selected Battery Control Boards (BCB), Battery Motor Control Centers (BMCC) and distribution panels to collect as-built data to verify engineering calculations and fuse, cable and battery sizing. The team used this information to review the overall protection and coordination of the dc system. The findings are described below.

Review of as-built drawings resulted in identified discrepancies between the 125 Vdc one line diagrams and actual field installation of circuit breakers and motor nameplate data. The discrepancies identified are listed below (Section 4.2.3 addresses other discrepancies in the ac area):

| <u>Bus</u>               | <u>Load</u> | <u>One Line Drawing</u> | <u>Actual Installation</u> |
|--------------------------|-------------|-------------------------|----------------------------|
| Circuit Breaker Ratings: |             |                         |                            |
| BMCC-2                   | 23P-141     | 20 A                    | 15 A                       |
| BMCC-4                   | 23MOV-25    | 30 A                    | 40 A                       |
| BMCC-4                   | 23MOV-122   | 20 A                    | 30 A                       |
| Motor Horsepower:        |             |                         |                            |
| BMCC-2                   | 23P-141     | 1.0 hp                  | 1.3 hp                     |
| BMCC-4                   | 23MOV-122   | .66 hp                  | 2.89 hp                    |

These discrepancies were presented to the licensee for evaluation during the inspection period. The licensee's initial evaluation indicated that some of these discrepancies dated back to initial installation and one line drawings had never been revised for the as-built configuration. The licensee issued Work Requests and Drawing Change Requests to accurately document the field installations with the one line drawings. The team agreed with the licensee determination that the discrepancies did not present a current safety concern in terms of equipment operability. The above discrepancies constitute a violation of 10CFR 50 Appendix B Criterion V which requires that activities affecting quality be accomplished in accordance with controlled drawings. (50-333/89-80-03.2).

The licensee committed to perform a complete walkdown of the DC loads prior to the end of 1990. The updating of the calculations and respective drawings are addressed in Section 4.4.1.

During the walkdown the team observed that MCC-165 cubicle OA1, load 02MOV-53B (13.3 hp motor) had a size 1 starter installed, as specified in plant drawings. The team questioned the licensee as to whether the installed starter was undersized since National Electrical Manufacturers Association (NEMA) standards recommend a size 2 starter for motors rated higher than 10 hp. This 13.3 hp motor has a service period of less than 1 minute and draws approximately 15 full load amps. To avoid overheating of the contactor the motor full load current should not exceed the continuous ampere rating of the starter. The continuous ampere rating for a size 1 starter is 27A. Therefore, the licensee concluded that the starter size was adequate for the motor size and its service. The team reviewed the sizing of the motor overload heaters to determine if they were sized to protect the motor in an overload condition. The team determined that the overloads

were sized at approximately 300%. Even though this approach does not pose any immediate safety concerns, a sustained locked rotor current would cause permanent undetected damage to the motor. (See Section 4.2.3, overload relays, for a related finding).

The team observed unrestrained equipment on wheels in the 'B' battery charger room within close proximity to safety-related equipment without their wheels choked. This equipment included a battery load bank, transformer and tool cart. The team questioned the storage of this equipment on wheels in an area where it could have an impact on safety-related equipment during a seismic event. The licensee stated that Fitzpatrick internal memorandum JSOP 88-037 adequately addressed the storage requirements for such equipment and that the observed equipment was stored in accordance with the stated requirements. The team reviewed the memorandum which indicated that such equipment was only required to be stored a distance of 4 feet from safety-related equipment and their wheels were not required to be choked. The team questioned the technical basis for such guidelines since it is possible for medium weight equipment to move a distance of greater than 4 feet during a design basis seismic event. The licensee stated that it would review its policy on the storage of equipment near safety-related equipment. This is an Unresolved item (50-333/89-80-17).

#### 4.2.5 Diesel Auxiliary Systems

The following discrepancies were discovered between plant drawings documents and the actual hardware in the field:

1. Drawing OP 22-2, Rev. 4, Flow Path For Air Start Lines For The Emergency Diesel Generators, System 93:
  - a. Flexible hoses were shown between the air bank piping and the diesel skid piping. These hoses did not exist.
  - b. Solenoid valves SOV 1B and 2B were shown as two-way valves whereas three-way valves were installed.
  - c. The tagging of the following items is reversed from one side of the engine to the other:
    - Pressure switches PS-11B and PS-12B
    - Pressure switches PS-13B and PS-14B.
  - d. The following items are not tagged:
    - Solenoid valves SOV 1B and 2B
    - Manual valve 51B.

2. Drawing OP 22-1, Rev. 7, Flow Path Fuel Oil Lines Emergency Diesel Generators System 93 - The tagging of level indicators LI-101BL and LI-101BR for the fuel oil storage tank is reversed.
3. Drawings 11825-7, 65-350, 351, and 352, all Rev. 1 - The installation of the backup air supplies for the RBCLCW system containment isolation valves incorporates vent valves between the solenoids and the actuators. The drawings do not show these valves.

Some of these discrepancies had already been identified by the licensee at the time of the inspection and drawing corrections had been initiated. The above discrepancies should not cause any significant concerns. The licensee agreed to correct all the deficiencies addressed above.

### 4.3 Electrical System Operation

#### 4.3.1 Procedures

##### 4.3.1.1 Offsite Power System and 4.16-kV Electrical System

During a manual transfer between the two alternate sources of offsite power at JAFNPP, two separate sections of the local transmission system are effectively paralleled through a 4-kV bus. When a voltage difference or phase angle difference exists on these sources at the 4 kV bus just before paralleling, large currents will flow through the 4-kV bus when both offsite supply breakers are closed. The paralleling is of short duration (i.e., long enough for the operator to be sure that paralleling has occurred, after which the original source breaker is opened). The manual transfer is a make-before-break operation that is used to prevent a momentary power interruption to the loads during the transfer. The automatic fast transfer that occurs at the time of a station trip, is a break-before-make operation and is less desirable than a make-before-break operation because it can cause surges and has the potential for needless trippings of plant equipment, including the main unit.

In previous correspondence with the NRC [New York Power Authority (NYPA) letter JPN-89021, April 27, 1989], the licensee stated that during a slow manual transfer, Bus 10300 can experience circulating currents of 3587A and Bus 10400 can experience 3116A. The team's review of the relay settings for the inverse time overcurrent relays for the 10300 bus indicated that this relay could operate in as few as 3.7 seconds.

When the 10300 bus is fed from both sources during a transfer, the operator may unknowingly be in a race with the overcurrent (IAC) relay for the 10302 bus tap. Similarly, the IAC for the 10402 breaker is starting to operate during a manual transfer but at a much slower pace. (The exact time is not given in the relay technical manual.) The team was not able to find an example where this time race condition

had caused a tripping to date; however, the potential exists for the 10302 breaker to trip by overcurrent relay during a manual transfer. The 10302 breaker connects the bus to the normal station service transformer. Tripping of this breaker by IAC during a transfer would not upset the station if the reserve feed breaker (10312) remained closed. However, during a manual transfer at unit startup, a possibility exists that the operator will trip the reserve feed (breaker 10312) just when the IAC trips the 10302 breaker. Such a tripping will cause the loss of one train of safety-related power and could lead to a plant trip if the condensate pump and other important plant loads were lost.

The 4160-volt operating procedure, F-OP-46A, discusses the steps that are required by the control room operators to transfer the station auxiliaries between the two offsite power sources. Both Sections E and F of that procedure contain explicit cautions that the transfer should be made quickly since the undervoltage relays may time out in 9 or 45 seconds, depending upon whether or not a LOCA occurs. An explicit note is contained in these sections that the transfer should be made without hesitation to reduce the probability of the breaker tripping on high current. This note should have a more explicit caution because the overcurrent relays may trip in as few as 3.7 seconds.

The team further believed that (1) operators should be made aware of the potential for unwanted IAC relay operation when the 4-kV source phase angles or voltages are significantly different; (2) guidance should be provided to show when the margin for error between a successful transfer and a station trip (i.e., 1 or 2 seconds) is too small, and (3) action should be taken either to alleviate the potential for 150% of pickup current being experienced during transfers or to set the IAC relays such that they are not in a race with the operator. These actions would improve the reliability of the power source transfer to the buses.

#### 4.3.1.2 Annunciator Response Procedures

The control room annunciator response procedures for the diesel generators do not provide sufficient information to the operator to be of any significant value in responding to the alarms. Specifically, they do not enumerate the most probable causes for each individual alarm nor specify operator actions to identify the causes and corrective actions for the alarm conditions. The following are examples:

1. Annunciator Response Procedure ARP 09-8-4-4, EDG B Fuel Tank Level or Transfer Pump Switch Off Normal

The procedure states the probable cause of the "EDG B fuel tank level or transfer pump switch off normal" is "Improper fuel oil tank level..." This is not a cause but rather a reiteration of the alarm description itself. The team considered this description to be of no use.

If the alarm is for low level, probable causes could be failure of the transfer pumps, clogging of the transfer pump strainers, improper valve lineup, emptying of the main fuel oil tank from which the pumps draw, or failure of the level switch providing the alarm. If the alarm is for high level, probable causes could be failure of a pump shutoff level switch or failure of the alarm level switch.

Operator action statements such as: "If necessary, restore fuel oil tank level to normal." and "Initiate a work request for any necessary corrective maintenance" are vague. Instead, for the low level condition, the operator actions could be, to determine the actual level in the tank and, if the immediate operation of the diesel is threatened, to take the necessary steps to provide fuel to the tank from another source, such as cross connecting from the other diesel. The procedure also should include actions such as checking to see if the pumps are operating, if their breakers are tripped, if the fuel oil supply valves are properly aligned, if the strainers are plugged, or if there is fuel in the main storage tank, etc.

2. Annunciator Response Procedure ARP 09-8-4-11, EDG B Engine Trouble or Shutdown

This alarm is actuated in the control room when any one of 12 alarms for various engine parameters is actuated at the local diesel generator annunciator panel. One of these alarms, the engine automatic shutdown, is actuated by seven different engine/generator conditions. Each of the parameters or conditions represented by these alarms can have a myriad of causes. Yet, the procedure lists only two very general conditions as probable causes: "1. Abnormal system condition which inhibits operability of EDG." and "2. Engine or generator fault which results in engine shutdown." As in the first example, these are restatements of the basic alarm description, not causes.

The "Operator Action" section of this procedure tells the operator, in effect, to identify and correct the cause of the alarm. Such direction is superfluous and is of no value to the operator.

The purpose of annunciator procedures is to provide pre-thought-out operator guidance based on the most probable alarm scenarios. If the procedures are not sufficiently detailed, they result in unnecessary delays while the operator searches for direction that is not there and then ultimately takes action based solely on his own initiative. This is the mode of operation the annunciator procedures are specifically intended to preclude. The above 2 discrepancies constitute a violation of 10CFR 50 Appendix B Criterion V which requires procedures appropriate to the circumstance. See further examples of this violation in Section 4.3.4, 4.8.3.2 and 4.8.3.7 of this report. (50-333/89-80-02.4).

#### 4.3.1.3 Annunciator Procedures Not at EDG Panel Locations

The annunciator panels for the diesel generators are located at the engine skids. They contain the individual alarms that actuate an "Engine Trouble or Shutdown" alarm in the control room. To determine the specific alarm, the operator must go to the local panel and read the individual annunciator. The team observed that response procedures for these annunciators were not provided at these local panels where they are intended to be used.

At the conclusion of the inspection, the licensee agreed to place the procedures at the local panels. This is an unresolved item pending NRC verification of the licensee action to locate the annunciator response procedure. (50-333/89-80-07).

#### 4.3.2 4160 Volt Emergency Power Supply System

The team physically inspected the licensee's 4160 Volt emergency power supply system which consists of four diesel generators powering two emergency buses. The team inspected the condition of the diesel generator support systems (i.e., fuel, starting air and ventilation) and reviewed the daily inspection of the diesel generators and support systems by the Operations Department. It was noted that Operations personnel verified the fuel oil storage tank levels and ensured that the air receivers for the diesel generator air starting system were pressurized and free of moisture.

The team reviewed Surveillance Test Procedure ST-9C, "Emergency AC Power Load Sequencing Test and 4 KV Emergency Power System Voltage Relays Instrument Functional Test", Revision 8 which tests the load sequencers for the Emergency Diesel Generators. The procedure verifies that all the loads described in the Final Safety Analysis Report (FSAR) are properly sequenced within the required time constraints. The team also reviewed the Abnormal Operating Procedures regarding the loss of 4160V buses 10500 and 10600.

The team reviewed the normal monthly surveillance test on the diesel generators, ST-9B, "EDG Full Load Test and ESW Pump Operability Test". The team noted that the procedure meets all applicable test requirements and that the engine is loaded on a continuous basis to a load that would be experienced in the worst case event of a Loss of Coolant Accident coincident with a Loss of Offsite Power. The procedure contains a caution stating that operation of any diesel generator at a load of 2000 kW should be avoided since excessive wear of the turbo-charger clutch mechanism occurs at this point. Furthermore, to ensure that the operators are well aware of this warning, a caution statement is clearly labeled on the main control board next to the diesel generator controls. The team noted that in the event of a Loss of Coolant Accident (LOCA) coincident with a Loss of Offsite Power, the peak load on each diesel generator pair is estimated to be approximately 4000 KW (2000 KW per Generator). The team discussed this finding with the licensee

who stated that the precaution statement was meant to avoid normal operation at this load level to avoid excessive wear to the turbo-charger clutch assembly; however, the manufacturer does certify the engine for operation in this range for a minimum of 200 hours. Because the load demand of the 4160 Volt emergency buses following a LOCA drops off rapidly, operation of the diesel generators in the 2000 kW range will be very limited; therefore, no safety concern exists with the operation of the EDGs at this load for short time intervals.

On May 23, 1989, the team observed performance of a surveillance test in accordance with procedure ST-9B, Rev. 26, "EDG Full Load Test and ESW Pump Operability Test". The team observed the preoperational checks of the diesel generators and their support systems. The team noted that the day tank level indicating gauges 93-LI-102A, B, C and D were out of calibration. When the fuel transfer pumps shutoff set-point of 95% was reached (terminating pump operation), the indicators read between the 100 and 105 percent level. It was determined at a later time that the level indicators are calibrated on a 2-year interval and that the drift in the calibration of the gauge would not affect EDG operability.

The team witnessed, from the control room and at the EDG panel, the starting and paralleling of each of the diesel generators. An anomaly was noted during the operation of the engines; the low fuel oil pressure sensor of EDG D was malfunctioning and annunciated an alarm in the control room. The inspectors noted that the alarm had been previously tagged as deficient, an outstanding work request had been initiated (WRED 93/64016) and it is scheduled to be repaired during the next plant outage. Personnel associated with the test were knowledgeable of the procedure and performed all tasks required in an orderly and professional manner.

The team reviewed surveillance test ST-9F which is performed during refueling outages and consists of automatically starting and loading the EDGs. The team reviewed the latest completed test results to evaluate the response of the units to an automatic start signal. Review indicated that the procedure data sheets record only the time that the loads receive their automatic start signal. The test does not require that the 4-kV bus voltage be monitored nor does it require that an oscillograph be used to verify that the voltage transient remains within specification and that the motors come up to speed within their required accelerating time. This is an unresolved item. (Open Item 50-333/89-80-14).

#### 4.3.3 Administrative Controls

##### 4.3.3.1 Transfer of Offsite Power Sources

On May 2 and May 11, 1989, the team members met with licensee station and engineering personnel to discuss the history of manual 115-kV power supply transfer problems and the remedies being pursued. The

SSFI team asked if the station operator requested the system operator to raise the 115-kV voltage at the time of manual transfers. The licensee responded that the 115-kV system is operated by Niagara Mohawk; however, JAFNPP operations is governed by the licensee's power system operator. Requests for transmission line voltage changes must be passed through the licensee's system operator to the Niagara Mohawk system operator. Therefore, the changes to the 115-kV system voltage, if they are possible under the conditions existing at the time of the request, are difficult to implement. During the meeting, the licensee stated that Niagara Mohawk had temporarily installed a 345-kV to 115-kV transmission transformer at the Oswego substation that had improved the phase angle difference between 115-kV and 345-kV sources at the site from 25 degrees to 2.5 degrees. This transformer was installed for transmission system purposes and not to cause a specific effect at Fitzpatrick.

The temporary installation of a transmission transformer at Niagara Mohawk's Oswego transmission substation provided relief from the relatively large phase angle difference between Fitzpatrick's 115-kV and 345-kV feeds. This transformer was later removed to substitute for a transformer failure at another location on the Niagara Mohawk system. If switching is required at Fitzpatrick when the Oswego transformer is out of service (as it was at the time of inspection) the phase angle will return to 17° to 25° and high currents will again flow through the transfer buses.

The unique nature of the Fitzpatrick technical specification for the 115-kV system, which requires transferring the emergency bus loads to the reserve station source transformers upon declaring a diesel generator inoperable, causes unnecessary possibilities for switching errors and problems that could result in reactor upset conditions. The team agreed with the licensee that, based on the power reliability of the Fitzpatrick's EDGs, this requirement to transfer power sources under these conditions is neither wise nor desirable. The NRC office of Nuclear Reactor Regulations (NRR) has indicated that relief will be granted from this technical specification requirement. After this requirement is removed, the only times that transfer of sources will be required is at plant startup and shutdown.

With regard to the difficulties that occur when attempting to match a low 4-kV voltage on the reserve station service transformer with the normal station service transformer, the Oswego transformer also may provide relief. The team suggested that the licensee investigate the ability of Niagara Mohawk to increase the 115-kV system voltage upon request. The Niagara Mohawk system operator may have sufficient control of the transmission system to be able to improve the 115-kV system voltage. In addition, the licensee should complete the current effort on the evaluation of changing the 90% undervoltage setpoint, the evaluation of changing the taps on the reserve station service transformers, and evaluate the effects of paralleling with up to a 5%

difference in 4-kV source voltages. During this inspection, representatives of the licensee and Niagara Mohawk met to discuss improving coordination and communications between the two systems supporting JAFNPP.

#### 4.3.3.2 Operator Control of 600-Volt Circuits

The licensee provided Schematic drawings to the team to review the controls related to equipment covered by this inspection. The team found that the vendor schematic drawings had not been kept up to date. There were no stamps on these drawings to indicate that they were outdated and therefore obsolete. The team was subsequently informed that only the "ESK" series of drawings were current and controlled.

The team noted that the control schemes reviewed enabled the automatic logic (where provided) to bypass the operator control switch. There was no "AUTO" logic position evident on the drawings; therefore, the operator actions can easily be overridden by the automatic logic.

The ability to control a device from two or more remote locations simultaneously is not considered by the team to be a safe practice. It appeared that there was no predefined protocol built into the plant controls. This design logic provides a potential for confusion in case of maloperations and/or abnormal operating conditions because control location is not controlled.

On the 600V switchgear feeder for the Control Rod Drive (CRD) drive water pumps, the remote automatic logic and the main control panel handswitch can operate the breaker in both the plugged-in and test position. In the test position, maintenance may be working on the circuit breaker and therefore a remote signal could be a hazard. The team was informed that there were sufficient administrative controls in place to prevent this from happening. This control philosophy also provides the potential for leaving a circuit breaker in the test position. The operator may not be aware of this as the remote controls would operate as required. This problem may go unnoticed and affect systems with a number of pumps, fans, heaters, etc., in parallel that are connected to a common header, duct, vessel, etc. This configuration requires strict compliance to the procedures.

#### 4.3.4 Diesel Generator Support Systems

The team reviewed the design of the ventilation system for the Diesel Generator room, as well as the relevant operating procedure. No deficiencies were noted with the system design, operation, or maintenance status. However, the team did note that two work requests, WRED 76/56068 & 56069 had been outstanding for almost 2 years with regard to the inoperability of two dampers that isolate the ventilation

system supply to the EDG switchgear rooms in the event of an actuation of the carbon dioxide system in the room. Discussions with the licensee indicated that the work requests cannot be resolved and closed out until a modification, scheduled for completion at the next available plant outage (scheduled for September 1989), is completed. This condition does not pose a significant concern at the present time. Resolution of these work requests is being tracked by the licensee's normal work tracking process.

The team also reviewed the arrangement of the controllers for the diesel generator ventilation system and the preventive maintenance conducted on the controllers. The controllers are checked on an annual basis using preventive Maintenance Procedure MP 56.1.

The team questioned the licensee concerning the sizing of the CO<sub>2</sub> fire extinguishing system for the emergency diesel generator switchgear rooms. The licensee supplied an internal memorandum, TS-79-392, as well as Preoperational Test Procedure 76-B, "CO<sub>2</sub> System", dated May 15, 1974, concerning the testing of the CO<sub>2</sub> fire suppression system for the EDG switchgear rooms and other areas in the plant equipped with CO<sub>2</sub> systems. The memorandum indicated that the CO<sub>2</sub> system for these rooms was preoperationally tested and that the system provided a CO<sub>2</sub> concentration greater than 50% during its initial pressurization of the room and a 30% concentration 20 minutes after discharge. These concentrations agreed with the design requirements of the system. No deficiencies were identified.

The team reviewed the sizing of the ventilation system for the diesel generator rooms to determine its adequacy. Discussions with the licensee revealed that a special test of the diesel generator ventilation system was conducted in August 1988 in response to a recommendation made by the manufacturer, Morrison-Knudsen Corporation. The test was recommended because the vendor's original estimate of the radiant heat losses from the EDGs was in error in the nonconservative direction. As a result, the licensee performed Preoperational Test (POT) Procedure 92A, "EDG Room Ventilation Capacity Test," on August 23, 1988, for the B & D diesel generator rooms. Results of the test indicated that the ventilation system was adequate to remove sufficient heat from the diesel generator rooms to maintain the room temperature below 122° F, as recommended by the manufacturer, assuming the worst case outside air temperature of 93° F. The inspector reviewed the procedure and the Nuclear Safety Evaluation for the test. No deficiencies were noted.

To ensure that Operations personnel have access to vital equipment in the Diesel Generator building, the inspector confirmed that the operators are provided security keys to the entrances to the building. In addition, the team observed that the licensee performs an audit of those keys annually.

### Station Battery/LPCI Batteries

The team reviewed the design of the ventilation system for the battery rooms for the 125V station batteries as well as the LPCI 419V batteries. The team also reviewed the Abnormal Operating Procedures regarding the loss of the DC and uninterruptable power source system and surveillance test procedure F-ST-19, Rev. 4, "Battery Room Ventilation Equipment Operability Test," which was conducted on May 4, 1989. All essential components of the system were signed off and the system was returned to its normal lineup upon completion of the test. In addition, the team reviewed ISP-87, Rev. 5, "Battery Room Ventilation Temperature and Differential Pressure Instrument Calibration". The procedure was implemented to verify the operability of the battery room ventilation and differential pressure instruments. The team confirmed that the temperature indicating instruments were properly adjusted to ensure that the battery room was not subjected to excessively high or low temperatures and that in the event of a ventilation or heating system failure, an annunciator in the control room would actuate. To confirm that proper preventive maintenance of the equipment was conducted, the team verified that the battery room fans (as well as the fans for the EDG rooms) were included in the licensee's preventive maintenance program and that the equipment had been serviced at the prescribed interval. No deficiencies were noted.

The team examined the condition of all of the batteries during their tours of the battery rooms, and also examined the condition of the connecting cables on the batteries. The team noted that the Operations daily round sheets contained provisions for monitoring key parameters of the 125V system; however, the licensee does not record 419 Volt battery system parameters during the operators daily rounds. This concern was raised to licensee management and they agreed to incorporate a check of the system voltage during the daily operator rounds.

The team did note that the auxiliary operator's daily rounds sheet, ODSO-17, "Auxiliary Operator Plant Tour and Operator Logs", Revision 6 stated that the minimum acceptable value for the 125V dc system was 90 Volts. The Fitzpatrick design basis for minimum battery voltage at discharge is 105 Volts. (calculation F1-85-038). This was not an acceptable voltage level for the system. This finding constitutes a violation of 10 CFR 50 Appendix B Criterion V which requires procedures appropriate to the circumstance. (50-333/89-80-02.3).

#### 4.3.5 HVAC for Electrical Switchgear Area

The team toured the east and west electric bays of the Turbine Building which house the essential 600V load centers, various vital motor control centers, and the Reactor Protection System motor generator sets. The team reviewed the ventilation system design for the rooms as well as the position of the exhaust dampers for the room. The team noted that the filters for the fan units are inspected on a monthly basis

and the fan motors and controllers are surveilled annually under Preventative Maintenance Procedures MP 101.04 and MP 56.1, respectively. The team noted that these units are not routinely monitored by the licensee but, unlike the battery room ventilation system components, are normally in an operating versus a standby mode.

The team reviewed the calculations regarding the heat load in the electric bay areas and noted that the cooling units for these areas were of adequate size for the rooms. It was noted that the units are in the licensee's preventive maintenance program and periodically are lubricated and have their filters checked. The team questioned the licensee regarding their use of space heaters in their motor control centers and vital switchgear. The licensee stated that enclosure space heaters have never been installed in the facility because of mild humidity environment that is present year round.

#### 4.3.6 Electrical Systems Training

The team reviewed and discussed the licensee's training program with regard to the station electrical system with several members of the licensee's training organization. The team reviewed the licensee's replacement operator qualification cards with respect to training in the electrical area. The operator qualification cards on the Emergency Service Water System, AC Electrical Distribution, DC Electrical Distribution, Administration Building and Battery Room Ventilation and Emergency AC Power were reviewed. These qualification cards were comprehensive and sufficiently tested the operator of his knowledge in the electrical area.

The team also reviewed replacement operator examinations 5 and 8 which contained questions regarding the operation of the various portions of the electrical system as well as the Emergency Service Water System. The questions were comprehensive and addressed important areas of the electrical system.

The team also spoke with a licensee training representative about the event scenarios affecting the plant electrical system which are run on the licensee's new plant simulator. It was noted that the licensee recently had placed considerable emphasis on these scenarios due to previously identified deficiencies in the operator's training in the electrical area. Up until late last year, the licensee performed simulator training on another plant simulator whose electrical system was completely different from the design at FitzPatrick). The scenarios were well documented and contained a feedback mechanism to ensure that deficiencies with the simulator were communicated to the simulator support staff for their correction.

In response to previously defined deficiencies in operator knowledge of the electrical system as well as specific training requests from the Operations Department, the Training Department upgraded their training program in the areas of electrical circuit breaker operation,

4160 Volt automatic bus transfers and the 345 kV and 115 kV tone and carrier systems. The team reviewed these training materials for these areas and found them to be well formulated and challenging in content. No deficiencies were noted.

In summary, training in the electrical area for the licensed operators appeared to be comprehensive and is improving significantly at the station.

#### 4.4 Electrical Configuration Control And Plant Modifications

##### 4.4.1 Administrative Controls on Electrical Load Growth

The team reviewed the licensee program for engineering designs and modifications. The plant and Engineering and Design Procedures (EDP) listed below were reviewed:

EDP-1, "Procedure for Design/Engineering Activities"  
 EDP-3, "Design Verification Procedure"  
 WACP 10.1.6, "Control of Modifications and Component Changes"  
 WACP 10.1.18, "Control of the Plant Master Equipment List (MEL)"

These procedures define the responsibilities of engineers and other personnel performing design activities and plant modifications. These procedures apply to design activities in all disciplines. Enclosure 6.1 of EDP-1 lists the minimum design inputs required to be considered. This design input checklist specifies 45 items to be considered including equipment qualification requirements per 10CFR 50.49, electrical separation requirements and impact on installed equipment. Upon completion of modifications the responsible engineers are required to ensure that as-built drawings are revised accordingly and changes to the Master Equipment List (MEL) are completed for all installed, retired, or removed components. Although the current design process requires that various design inputs be reviewed, it does not have a mechanism to ensure that plant calculations affected by modifications are updated to ensure that they are maintained up-to-date and accurate. This leaves the potential for existing calculations to become obsolete after such equipment as circuit breakers, transformers, motors, and other electrical equipment is replaced. This condition was noted during this inspection with regard to the calculations which were reviewed. Calculations dating from the early 1970's were no longer accurate as a result of plant modifications.

The licensee committed to provide an on-line program by the end of 1989 to capture electrical load growth. An overall program to update electrical design bases on short-circuit calculations, voltage drop calculations, etc. will be in place by the end of 1990. This is an unresolved item (50-333/89-80-12)

#### 4.4.1.1 4160-Volt System

The load on the diesel generators was reviewed in 1987 in a calculation prepared by Stone & Webster, AE for the project. The calculation assumed the horsepower on the motor nameplates and also included losses associated with the unit substation transformers. A review by the SSFI team of the pump curves associated with the safety-related pumps driven by 4-kV motors indicated that it might be possible to draw higher than nameplate horsepower with the RHR and core spray pump motors, depending upon possible flow conditions. However, this oversight in the calculational assumptions does not appear to be significant since the total load on the diesel generator pairs was approximately 80% of the total continuous rating of the generators; allowing sufficient margin to more than offset this potential increase in load.

#### 4.4.1.2 Battery Capacity

Station batteries A and B provide control power to the Emergency Diesel Generators (EDGs), Class 1E 4160V and 600V switchgear, 125V dc BCBs, BMCCs, and distribution panels. The original station batteries, Gould Type NCX-2250 AH, were replaced with batteries of a larger capacity (NCX-2400 AH) in 1983. In 1985 plant modification F1-85-038 reduced the number of cells in the batteries from 60 to 58 cells. This modification was implemented to reduce the dc bus voltage during a battery equalizing charge while increasing the individual cell voltages to achieve better cell performance characteristics. In April 1989 the licensee completed an additional battery capacity study taking into account the full effects of battery temperature as recommended by IEEE 485-1983. Results of this study indicated that there was less excess capacity than expected according to the calculation for the above modification. To address this finding the licensee proposed several actions which are briefly summarized below:

- Implement a modification to increase battery room minimum temperature to 70 F.
- Reinstall the two cells that were removed as part of modification F1-85-038 when battery capacity tests indicate that the battery capacity can be expected to decrease below 90% of rated capacity.
- Initiate plans for replacing of the present battery when the capacity decreased below 85% of rated capacity.

The licensee is also evaluating the possibility of performing a battery capacity test during the 1989 mini-outage instead of during the 1990 refueling outage. The licensee is tracking this activity for completion.

#### 4.4.2 Review of Modification Packages

##### 4.4.2.1 Modification F1-84-041, Second Level Undervoltage Protection

Plant modification F1-84-041 was implemented during the last refueling outage; though it was not closed pending verification of documentation. The team reviewed the installation, wiring and elementary diagrams, technical manuals, safety evaluation, system description, and calibration records for selected devices.

The team had the following minor comments:

- a. The team found an elementary diagram that incorrectly identified the normal contact position of the undervoltage relay. The correct contact position was indicated on the installation wiring diagram.
- b. The technical manual contained two different manufacturers' instruction bulletins for the 27 device undervoltage relay. One bulletin did not apply to the actual 27N relay installed during this modification. The licensee stated this discrepancy will be corrected.

##### 4.4.2.2 Inadequate Design of Reactor Building Environmental Enclosures

Plant Modification F1-84-005 was implemented to provide environmental enclosures to protect the two LPCI uninterruptable power supply charger/inverter systems and the two 600-Vac emergency power switchgear substations in the reactor building from the effects of high-energy line breaks (HELB). The licensee did not exercise adequate control in the design and implementation of this modification.

In designing the cooling system for the environmental enclosures, the ability of the cooling units to function in the HELB environment (approximately 170°F peak temperature) was not properly considered. In response to team inquiries, it was determined that the units would trip at 145°F and that they would not automatically reset as the temperature decreased. This had the potential of causing failure of power supplies to several safety-related components common to both trains of ECCS (common mode failure). As a result of this discovery, the licensee made a report to the NRC in accordance with the requirements of 10CFR50.72. Immediate modifications were made to the design of the control logic of the cooling unit compressors to provide automatic reset when the temperature dropped below approximately 140°F, and the licensee performed an analysis which they stated shows this would not produce unacceptable temperatures inside the enclosures. This is a violation of 10CFR 50 Appendix B Criterion III which states that requirements and design bases be translated into instructions. Another example of this violation is addressed in Section 4.4.2.3. (50-333/89-80-05.2).

Although this concern produced an immediate response, other problems and potential problems also were identified as follows:

1. In determining the accident heat load on the enclosures, no consideration was made of the heat load from the external source of the HELB environment itself.
2. The heat load from the cooling equipment was not correctly considered.
3. The units were tested at ambient conditions and no extrapolations were made to accident conditions. Therefore, the test results did not confirm the capability of the design. Extrapolations made during the inspection purported to confirm the capacity of the unit. However, the licensee could not confirm various questionable assumptions and methods used.

This is an unresolved item (50-333/89-80-08).

#### 4.4.2.3 Plugging of Floor Drains in Both Diesel Generator Divisions

In or about 1981, floor drains were plugged in the diesel generator rooms. The licensee stated that this modification was made to preclude accidental release of chromated EDG jacket water into the environment. No modification package or 10CFR50.59 Safety Evaluation was produced for this modification. As a result, the safe shutdown capability for the plant in case of fire required by 10CFR 50, Appendix R was potentially compromised as described below.

With an oil fire in either the "B" or "C" diesel generator rooms, there is the potential for failure of both divisions of onsite emergency AC power should the combustible material spread to the adjacent room. 10CFR 50, Appendix R requires that one train of equipment necessary to achieve hot shutdown must be maintained free of fire damage by a single fire, and NFPA Codes require that sufficient drainage be provided to remove all liquids from a fire area for the maximum flow conditions.

The uncontrolled modification to plug the floor drains in the diesel generator room, resulted in an as-found configuration that could spread the fire. If an oil fire occurred in either the "B" or "C" rooms it had the potential to spread into the opposite division as the result of the room flooding. This potentially could cause loss of both trains of onsite emergency power.

The actuation of the sprinklers, would provide the mechanism to spread flood the room up to the tops of the curbs. At this point, the water and oil could spillover into the adjacent room. Since oil floats on water, the first liquid to spill over would likely be oil, thereby creating a flammable liquid fire hazard in that room. Per the licensee's calculation, even with the equipment drains that were open in the rooms, if half the sprinklers were assumed actuated, spillover

would occur in approximately 20 minutes. At the conclusion of the inspection, the drain plugs were being removed. The failure to factor in the design bases is a violation of 10CFR 50 Appendix B Criterion III which states that requirements and design bases be translated into instructions. (50-333/89-80-05.1).

The team questioned whether there was sufficient drainage even with the plugs removed to prevent spillover with the maximum design sprinkler flowrate as required by NFPA codes. No evidence could be produced that this was ever considered as a part of the original design. A new calculation was performed during the inspection, but it was inconclusive since it did not address the issue in question, spillover into the adjacent diesel generator room, and it failed to consider the common drain lines from the floor drains as possible restriction points. This is an Unresolved Item (50-333/89-80-09).

Subsequent to the inspection the licensee indicated that when all but 2 drains were plugged, the spray from the fire protection system can spill over to the adjacent room. The licensee believes that the fire will be extinguished by the spray before it can spread to the adjacent room due to the high ignition point of diesel oil. The licensee did not support this conclusion.

#### 4.5 REVIEW OF PROTECTION AND COORDINATION

##### 4.5.1 4160-Volt System

##### 4.5.1.1 Diesel Generator Electrical Protection

Each diesel generator is provided with multiple sets of diverse electrical protection, including differential protection, overcurrent protection with voltage restraint, reverse power protection, and loss of field protection. The overcurrent protection setpoints were selected to permit the diesel generator to supply over 200% of rated load if the bus voltage remains at 100%. However, for a bus fault with the bus voltage dropping to 0 volts, the diesel generator breaker will trip in less than 2 seconds when the diesel generator tries to provide a fault current of 3200 A

The reverse power protection is provided to trip the generator and circuit breaker when the diesel driving power is lost and the generator tries to function as a motor. This is especially important for this plant because of the unique forced parallel arrangement of the two diesel generators. If one unit of the two unit combination, is driven to 200 rpm by its air system without starting, the tie breaker between units will still close. The team noted that the contacts from these relays go to the diesel control circuit before being relayed back to the generator output breaker control circuit. This additional relay path slightly decreases the reliability of the circuit, but during this relaying time, however short it may be, the diesel will continue to be motored by the generator until it is tripped off by the work power protection.

#### 4.5.1.2 4160-Volt Motor Protection

The team reviewed the selection of the setpoints on the 4000V safety-related motor overcurrent relays. The selection process was documented in formal calculations consisting of superimposed motor and relay time-current characteristic curves. The original designer had obtained thermal characteristics from the motor manufacturer for each of the safety-related 4000V motors as well as estimates for the acceleration times for the two motors which are automatically loaded onto the diesel generators following an accident signal. This acceleration calculation assumed a starting voltage drop to 70% of motor rating and recovery to 90% of rated voltage within 1 second.

The relay circuits were designed to alarm on small overloads and trip on overloads of approximately 175% of rated load. Although the alarm setpoint for the Residual Heat Removal (RHR) service water pump motors appeared to be set low (109% of rating) compared to its service factor of 1.15, a closer review of the pump brake horsepower curve by the team indicated that this setpoint was adequate because the maximum normal load on the motor would only be approximately 93% of motor rating.

#### 4.5.1.3 4160-Volt Switchgear Interrupting Capability

The 4160-volt switchgear consists of metal clad gear with circuit breakers rated for 4760 volts maximum and 250 MVA interrupting capability. There are four sources of short circuit current that can feed the safety-related gear. The main power supply consists of a double source of the 345-kV system and the main plant generator. The reserve source comes from the 115-kV system which normally feeds the plant only during shutdown. The large motors could also contribute to a fault. Each month during diesel surveillance two EDG units are paralleled with the offsite supply for at least one hour per pair. The team reviewed the short circuit calculation that had been prepared to justify the short circuit interrupting capability of the 4160-volt switchgear while the diesel generators are connected to the system. The team found that the licensee had assumed incorrect system contribution, incorrect transformer impedance, and incorrect motor contribution. The team independently estimated the contribution from all sources and estimated that the switchgear would not have sufficient interrupting capability for this application. Neither the licensee nor its consultant was able to produce an analysis that could confirm the adequacy of the 4160-volt switchgear interrupting capability by the close of this inspection.

Subsequent to the inspection the licensee informed the team that interrupting capability is a concern only when EDGs are connected to the system for monthly surveillance testing. However, no action is planned to be taken as such a fault during testing is a low probability. The team was not concerned with the two offsite sources paralleled at the same time, since it was a transient condition.

#### 4.5.1.4 Undervoltage/Overcurrent Relay Coordination

The 4.16-kV switchgear is provided with an undervoltage relay that will operate when the voltage at the 4.16-kV bus drops below 75% for more than 2.5 seconds. Once this relay operates, the 4.16-kV incoming feeder breaker is tripped and the diesel generators are started and connected to the 4.16-kV bus to pick up the necessary loads. This delay is to ensure that in case of a fault on the 4.16-kV system, the fault is cleared by overcurrent relays and the inadvertent connecting of the diesel generators onto a faulted system is avoided.

The licensee provided calculations based on minimum system impedance (maximum short circuit level) and confirmed that proper coordination exists between the overcurrent and undervoltage relays. The licensee had not reviewed the case of maximum system impedance (minimum short circuit level). The team considers the settings to be adequate, however an evaluation would ensure that there is no possibility of maloperation of these two types of devices.

#### 4.5.1.5 4160-Volt Switchgear Control Circuit Power

The safety-related 4160V switchgear is controlled with circuits powered from the 125-Vdc system. The main dc distribution panel subfeeds a remote distribution panel in the diesel generator relay room through a 225A circuit breaker. The branch circuit breaker feeding the safety-related switchgear dc control power bus is a 40-A thermal magnetic molded-case circuit breaker.

Each individual 4160-volt circuit breaker control circuit consists of two subcircuits for the close and trip circuits which are fed from the control circuit power bus through 15-ampere and 35-ampere fuses, respectively. Those circuits associated with the remote shutdown circuits are fed from two sets of fuses for each subcircuit.

Prior to this inspection, the licensee had not considered coordination between the 35-ampere fuse and the 40-ampere circuit breaker. Upon plotting the time-current characteristics of both devices, it was clear that inadequate coordination exists between these devices.

Exacerbating this situation, is the fact that some of the remote shutdown circuits may contain a slow-blow fuse type, making it conceivable that a fault on a trip circuit could result in loss of automatic control for the entire switchgear. This is an Unresolved Item. Additional coordination problems with 125 Vdc systems discussed in Section 4.5.3 are related to this issue. (50-333/89-80-10).

#### 4.5.2 600-Vac Electrical System

The licensee provided the team with protective relay coordination curves for the 4.16-kV feeder breaker 10660 for 600V transformers T14 and T16 feeding 600-volt unit substations L-16 and L-26, respectively. In addition, protective relay curves for the 600-volt feeders to the MCCs and motors on L-16 also were reviewed.

1. The setting of the overcurrent relays for the incoming feeder of L-16 was shown differently on Calculations E5-2 and E-130 (Curve No. 12966-60-E-103084-2) for the same devices. It was confirmed that the curves on Calculation E-130 for 600-volt unit substation L-16 were correct. The margin between the relays on the incoming feeder breaker (11602) and the 400-A feeder (11612) is minimal for the short time elements and should be increased for reliable, coordinated operation. The licensee has recognized this and has committed to prepare new coordination curves. This is an improvement of the existing coordination.
2. The relay curve on Calculation E-120 for CRD pump feeder breaker (11616) was based on a GE Type IB-3 overcurrent device, whereas the actual device is a GE MicroVersaTrip. Therefore, the presented trip curve was invalid. This discrepancy occurred due to a site modification in which the old GE overcurrent devices were being replaced by the new MicroVersaTrip devices. The licensee is now preparing new coordination curves. The cursory review of the present setting did not reveal any significant concerns.
3. The setting of the overcurrent relays on the 4.16-kV transformer feeder breaker (10660) and the incoming feeders of 600-volt unit substations L26 and L16 were checked for proper setting/operation as follows:

- a. Overcurrent Check

The team found that the relay settings did not sufficiently take into account the cumulative effect of the load current of the second 600-volt transformer, the additional margin required for Star/Delta conversion, and the IAC51 relay resetting margin required during clearing of a fault by downstream breakers. The licensee committed to review the curves and modify settings as necessary. This would improve the coordination.

- b. Residual Voltage Transfer Check

During a residual voltage (RV) transfer, the 600V loads are disconnected from one source of power, and after the residual voltage has decayed to 25%, the alternate source is connected. This transfer time results in the motors slowing down (motors that are controlled by contactors would be completely disconnected), and the subsequent, simultaneous reacceleration of all the 600V motors would result in currents of 4.5 times full load current (as estimated by the licensee in Calculation E-69) until the motors have reaccelerated (the licensee is unable to provide any calculation establishing this time period). In addition, the voltage on the 600-volt buses would be much less than 90% rated voltage, the normal minimum design point.

The team estimated that there is a possibility that, during a residual voltage transfer, the overcurrent relays on the 4.16-kV feeder (10660) and the unit substations L-16 and L-26 could operate and lock out the corresponding buses. This would defeat the purpose of the RV transfer.

The ability of the 4.16-kV bus undervoltage relay to override the undervoltage effects during a RV transfer had not been verified by the licensee and the licensee was unable to provide the magnitude and duration of the undervoltage condition during the RV transfer.

The licensee is now considering performing a transient stability study that will provide the necessary data for proper setting of the above relays. This is an Unresolved Item (50-333/89-80-13).

c. Motor Starting Check

The team reviewed the overcurrent device setting on 600V incoming feeder 11602 to verify if sufficient margin existed for starting the largest load on a fully loaded bus. The team confirmed that the settings are adequate and sufficient margin exists for proper coordination.

4. Feeder to MCC C161

Calculation E-124 shows coordination curves between the 600V switchgear breaker 11606 and 40 Amp feeder breaker to distribution panel 71ACB3, the largest feeder in use on this MCC. The curves are coordinated, but the margins are minimal when resetting requirements of the 600V switchgear breaker 11606 are taken into account. In addition, the MCC contains a 70 Amp breaker which is not being used at present. If it is used, the setting of the overcurrent elements on the 600-volt switchgear breaker 11606 should be reviewed.

4.5.3 125 Vdc System

Stone and Webster Engineering Corporation studies dated 1971 calculated the battery cable feeder size required to limit the available battery short circuit fault current at the Battery Control Boards (BCBs) to less than 20,000 A. The team requested for review an updated dc system short circuit study to verify that the available fault current would be below the dc bus molded case circuit breaker short circuit interrupting ratings. The licensee provided calculations that documented the available fault currents throughout the dc system as well as circuit breaker coordination.

The team noted that the Class 1E batteries lacked protective devices such as fuses or circuit breakers to provide a disconnecting means from the dc bus during maintenance and potential pole-to-pole short circuit faults. The licensee design philosophy was that such faults were highly unlikely due to physical separation of the battery terminals. The dc system is ungrounded and detected ground faults are alarmed in the control room. Review indicated that the calculated short circuit faults at the B BCBs, B MCCs, and distribution panels do not exceed the corresponding circuit breaker interrupting ratings. The licensee's position is that even in the unlikely event of a pole-to-pole fault downstream of the batteries, these circuit breakers would be able to clear the fault. This design philosophy places additional importance on having a well coordinated dc system to systematically isolate any faulted circuit.

The team reviewed the licensee's dc coordination study to ascertain whether the system was designed such that any circuit fault could be cleared with minimum interruption to the system. Review of the study indicated that circuit breaker coordination could only be established between the BCBs and distribution panels 71DC-A4 and B4. Coordination could not be established for bolted bus faults for other BMCCs and distribution panels since most of these breakers are of the thermal magnetic type that has fixed instantaneous, nonadjustable settings. In the two cases in which coordination was established, upstream circuit breakers have adjustable-instantaneous settings and are set at the highest setting. The licensee concluded that for the more likely type of fault, such as a high impedance fault for which the short circuit current would be less than for a bolted phase to phase fault, circuit breaker coordination is achieved. However, further review by the team indicated that coordination could still not be established between dc circuit breakers feeding protective fuse circuits in 600 and 4160 V switchgear. See Section 4.5.1.5 for further details.

The team requested for review the licensee's calculations documenting the available voltages at load terminals during starting of essential loads to verify that they had adequate voltage to perform their intended function. The following observations were noted in the review of the calculations:

- a. Circuit breaker control voltages for the 4.16 kV switchgear were calculated to be at 93.2 volts minimum during the 2 hr. battery duty cycle. These values are within the operating voltage range of the 4.16 kV breakers with 70 to 140V dc for trip coils and 90 to 130V dc for closing coils.
- b. Based on the required MOV starting torques and the results of voltage studies for essential loads, there is sufficient voltage to develop the required torque to allow the MOV to perform its operating function.

No deficiencies were identified.

## 4.6 Electrical System Stability

### 4.6.1 Undervoltage Studies

The original voltage study for the JAFNPP was performed in 1969 using the 115-kV system from the Lighthouse Hill substation. In this study, the licensee concluded that the 4-kV emergency core cooling loads would have to be sequenced on the bus to limit the voltage drop at the 600V bus to 90%. This study was updated in 1976 in response to the industry experience on degraded grid voltage studies. This study also was limited to the voltage seen at the safety-related buses and not at the equipment terminals. In 1980, in response to an NRC inquiry, the terminal voltage at select (worst case) safety-related equipment was calculated. In 1982, additional calculations were performed for motor terminal voltages during starting conditions.

The results of the voltage calculations were used to select the transformer tap settings and the degraded voltage relay settings.

The team also reviewed the 90% undervoltage relay and timer scheme. Two time-delay circuits are used: a 9-second delay under accident conditions and a 45-second delay for nonaccident, manual transfer. The 9- and 45-second timers for this system are Agastat time delay relays. The undervoltage relays that initiate the time delay relays are ITE Brown Boveri Circuit Shield under voltage relays. Their settings were marked as 110% pickup and 99% dropout.

No discrepancies were observed.

### 4.6.2 Offsite Power System

Under most system connections, a long electrical distance exists between the 345-kV and 115-kV terminals when viewed from the JAFNPP substation. There are no transformers between the 115-kV and 345-kV systems that are electrically close to JAFNPP. Therefore, phase angle differences of 17 to 25 degrees have occurred between the 115-kV and 345-kV systems. In addition, the 115-kV system could experience relatively low voltage while the 345-kV system is experiencing relatively high voltage.

The transmission system conditions have presented no significant problem during normal operation. However, when it has been necessary to manually switch station auxiliary load (both safety and non-safety loads) from the reserve transformers to the normal service transformer and back again, operational difficulties have occurred. During the transfers, the 115-kV and 345-kV sources are paralleled through the 4-kV distribution buses for the plant. When the sources are paralleled, the 4-kV buses experience significant overloads for short periods because of the phase angle difference between the 115-kV and 345-kV sources. A low voltage condition on the 115-kV system presents another switching problem when attempting to connect the auxiliary load to

the normal station service transformer, T4. The 4-kV voltage on transformer T4 must be adjusted downward by way of a load tap changer (the station reserve transformers, T2 and T3, have no load tap changers) to nearly match the 4-kV voltage on the buses resulting from the 115-kV voltage condition. Although the voltage on the 115-kV system is stable and will not change appreciably from variations in 4-kV loads, the voltage on the 4-kV side of the normal station service transformer, T4, decreases as the auxiliary load is transferred to it. This condition can cause the 4-kV voltage to drop below the setting of the 90% undervoltage relays for 9 seconds, which initiates an automatic start of the emergency diesel generators. Although the station operator can adjust the voltage on the 4-kV side of the T4 transformer by the load tap changer, the taps do not move rapidly enough to prevent the voltage from momentarily dropping below the undervoltage relay settings. If the voltage returns to normal before the diesel generator voltage is up to 75%, the load will remain on the T4 source and will not automatically transfer to the generator. In the two automatic diesel starting events that occurred on June 11, 1987 and September 12, 1987, the 4-kV voltage returned to normal before the diesel generator attained the 75% voltage level.

The JAFNPP Technical Specifications require the 4-kV safety loads to be transferred from the normal station service transformer source to the reserve station service transformer whenever the associated emergency diesel generator is declared inoperable. Because of the requirement, needless transfers of emergency loads occur, causing additional opportunities for switching problems to occur. This requirement is unique to JAFNPP and is not required of any other nuclear power plant in the United States. The requirement appears to have originated from concern about the reliability of the unique emergency diesel generator system at JAFNPP. In this system, there are two sets of two emergency generators. During the startup of each generator set, the leads of the two generators are paralleled to force synchronization of the machines. Thereafter, the bus breakers for the generators are closed and the paralleling breaker is opened. The parallel generator system is used to provide sufficient power for the total emergency loads.

In response to the two events in 1987 when automatic actuations of the emergency generators occurred, the licensee requested two changes to the Technical Specifications:

1. Relief from the requirement to transfer the emergency buses to the reserve sources upon an emergency generator becoming inoperable, and
2. Permission to install a 45-second delay timer on the 90% undervoltage actuation system for the emergency diesel generator for use during manual transfer of the emergency buses. The 45-second delay would be in service only during manual transfers (without an accident signal present) and would allow sufficient time for the load tap changer on the normal station feed to restore the 4-kV voltage to acceptable levels.

In addition to the above, the licensee is in the process of evaluating three other techniques for eliminating manual transfer problems:

- Changing the no load taps on the station reserve transformers to cause an improved 4-kV voltage,
- Reducing the 90% undervoltage relay setting such that a larger margin exists between the operating voltage and the trip point at the time of manual transfer (this requires increasing the conductor size of some feeder circuits so that the voltage at the equipment is not unacceptably low), and
- Evaluating if manual transfers can be made with up to a 5% difference in the 4-kV voltages of the normal service source and the reserve service source.

Any of the above solutions can resolve the manual transfer problems. The NRC office of NRR has been looking into this matter.

#### 4.6.3 600-Volt Design Calculations

The licensee provided the electrical calculations for the 600-volt electrical system. These calculations date back over the last 15 years. Some of these calculations reflect the state of the plant during construction stage, whereas others are based on actual as-built data. Because these calculations cover a long period of time, they use inputs from one another and are not adequately referenced for traceability. In some cases, obsolete data was utilized in newer calculations. Therefore, even though a calculation may be relatively new, use of old data compromises its validity. In addition, obsolete calculations were not identified as void and superseded and are an indication of deficiencies in the electrical design basis documents. A few examples follow:

- a. Calculation E-67, Load Flow Study (Coordination) was reviewed for Bus L-16. This calculation was performed in November 1971 and it has not been updated. MCC C166 has not been included in this study. MCC C161 load data does not reflect the actual plant loads. Similar discrepancies were noted on other MCCs. Although the differences in load data were not substantial, they could affect other calculations if the information is later used elsewhere. The team was subsequently informed that the calculation was obsolete and that new studies were available. The new study, E77-01, Emergency Diesel Generator Load Review, was also found to contain errors for MCC C161. The licensee committed to update this calculation. Based on the current loading of the diesel generator, these errors do not raise any significant concerns.

- b. Calculation E-69, Voltage Profile Study, documents the full load for Load Centers L25/26 as 46.9 A each and for L15/L16 as 72 A each. There is no reference as to the source of these calculations that were performed in 1973. This study does not address the effects of transient currents and torques during the fast open transfers but rather only addresses steady state conditions. As the major risks in such transfers are the transient effects, this study cannot be considered adequate. In the case of the residual voltage transfer, the scheme adopted is to shed and sequence all the 4.16-kV loads and reaccelerate only the 600-volt loads. However, there are no calculations for establishing the voltages, currents, and reacceleration times for these 600-volt motors. Other problem areas such as contactor dropout and over-current relay operation have also not been addressed. As a result of the team's concerns, the licensee is now considering performing computer-based transient stability studies that will address these above issues. This will be a supplemental analysis to the computerized electrical data analysis that had been already planned by the licensee for 1990.
- c. Calculation E-77, Voltage Profile - Emergency Buses, was performed in September 1976. There are no references for the equipment and load data shown on page 2 of this calculation. In addition, there is no source reference for the variation in the grid voltage between 115 kV and 122 kV. There was no evidence provided to verify that the computer program used for this calculation has been validated. The licensee has stated that its contractor, Stone & Webster, can verify the accuracy of the program used. A documented verification can better support the conclusion.
- d. Calculation E-81, Undervoltage Study of Class 1E MCC Control Circuits, addresses only the undervoltage operation of the MCC control circuits and does not address the effect of capacitive currents to prevent dropout of the contactors. The licensee provided a calculation indicating a maximum cable length of about 2878 feet. According to E-81, the longest cable length is only 1650 feet and therefore there should not be a problem with regard to capacitive currents on control of 120-volt control circuits.
- e. The licensee was requested to provide the short circuit calculations for 600-volt unit substation L-16 and MCC C161. The licensee could not locate these calculations at the start of this inspection. During the last days of the inspection, the calculations were finally located. The calculations do not take into account that the voltage on the 600V system can go as high as 635 volts and therefore would result in higher short circuit currents. The team estimated that at 635V the rating of the switchgear on L-16 would be adequate. However, as the margins are minimal, the licensee has committed to verify this for all the 600-volt buses. This is an unresolved item (50-333/89-80- ).

The calculations suggest that the short circuit rating of the equipment on the MCCs is 22,000 A. In view of the fact that there are feeders with only molded case circuit breakers (no starters), the maximum interrupting rating for these feeders is only 18,000 A and not 22,000 A. The equipment rating on MCC C161 is adequate, taking all the above factors into account. Here again, the short circuit level could be higher on other MCCs as the MCC analyzed has a long feeder cable of 379 feet which helps reduce the fault current.

- f. While carrying out the above analyses, the licensee assumed that the grid voltages will be within the values specified in the FSAR. These values are 345 kV to 370 kV and 115 kV to 122 kV. Plant records (BOP log) and direct readings of the meters in the control room by the team and the licensee have shown the plant to be operating at values higher than those stated in the FSAR. This higher value affects the short circuit levels on all the buses and could result in an unacceptable short circuit level situation. At present, there are no alarms or instructions in the main control room for operating the plant with grid voltages above the maximum values in the FSAR. The grid voltages are under the control of the Load Dispatch Center. Operators should be made aware that high voltages can compromise the safe operation of electrical equipment and request necessary corrections be made by the Load Dispatch Center if an overvoltage condition persists.

The licensee was requested to confirm that the 600V equipment is capable of operating satisfactorily at the maximum voltage of 635V. The licensee confirmed that the 600V unit substation switchgear is rated for 22,000 A at 635V and no derating is necessary. The licensee is investigating the continuous and interrupting capability of the switchgear and control gear above 600V. This is an Unresolved Item (50-333/89-80-11).

Electrical system analyses are carried out to ensure that the equipment and systems are capable of performing their design function. These analyses, coupled with the capabilities verified and warranted by manufacturers, provide the necessary framework within which the system, components and structures will operate satisfactorily. Inaccurate, obsolete, missing, or invalid calculations may expose equipment to conditions it was not designed to operate under and could possibly jeopardize the safety of the plant.

Subsequent to the inspections, the licensee informed that interim controls will be placed to reduce the voltage at 600V MCCs. This is achieved through reduced voltages at the 4-kV level. The following long term corrective actions are also considered.

1. Analyze air circuit breaker and MCC breakers' interrupting ratings at greater than nominal voltage (600 VAC).
2. Evaluate changing transformer taps at the 600V level via the modification process to maintain 600V buses at approximately 600 VAC with acceptable 4-kV voltages being maintained.

#### 4.7 Maintenance

##### 4.7.1 Offsite Power System and 4160-Volt System

The licensee has recently formalized the preventative and predictive maintenance it performs on the reserve power transformers T2 and T3. This maintenance has been in practice at Fitzpatrick since the early 1970s. Analyses of oil and gas samples have been trended since that time. Since 1988, the licensee has analyzed these samples on a system-wide basis instead of sending the sample to an outside laboratory. Minor procedural inconsistencies noted by the team, such as the delivery locations for the oil and gas samples, had not interfered with the correct processing of the samples.

Although no formal procedures were in place for the main and normal service transformers T1A, T1B, and T4, these transformers also were being subjected to the oil and gas analyses.

Formal preventive maintenance (PM) procedures exist for the safety-related 4160V switchgear and incorporate the recommendations published by the manufacturer of the switchgear and the circuit breakers.

Formal surveillance procedures have been implemented at Fitzpatrick to verify the setpoint and calibration of the undervoltage, overcurrent, and timing relays used on the 4160-volt system. No discrepancies were found by the team in this area and the recorded data was within acceptable limits.

##### 4.7.2 600-Volt ac Electrical System

Discussions with licensee personnel indicated that a formal preventive maintenance program is not in place for the 600V Class 1E systems, components, and structures. Such a program is required to ensure that maintenance is carried out in a pre-planned, organized manner so that all the systems, components, and structures are suitably attended to in order to ensure proper operation. Such a program would track, record, verify, and clearly define the time duration between maintenance and the applicable sections of the relevant PM procedure for such maintenance. Currently, the maintenance strategy and rationale behind maintenance work are not clear. Work Request instructions are given under "Special Instructions" by quoting only the relevant sections of applicable PM procedures.

The absence of a formal program can eventually result in degraded performance of equipment not subjected to scheduled preventive maintenance. Furthermore, the misapplication or omission of relevant PM activities increase in the absence of a formalized PM program. Although no hardware deficiencies were identified as a result of the lack of a formalized maintenance program for 600-volt ac systems, the licensee should strongly consider development and implementation of such a program in order to ensure that effective maintenance will continue to be performed in the future.

#### 4.7.2.1 Maintenance Procedures

The team reviewed the following preventive maintenance procedures:

- MP-55.2 "600-volt Load Center Maintenance"
- MP-55.1 "600-volt Air Circuit Breakers"
- MP-56.1 "600-volt Motor Control Centers"
- MP-101.09 "600-volt Motors"
- MP-59.3 "600-volt Limitorque Motor Operators"

The team found that the procedures are comprehensive and that adequate provisions had been made for taking corrective action if equipment degradation is detected. However, the following shortcomings were noted:

- a. MP-55.1, "600-volt Air Circuit Breakers", does not require maintenance personnel to note the existing and/or the new setting of the overcurrent devices on the breakers. This shortcoming has enabled the setting of the overcurrent devices to drift between different phases of the same breaker. In one case (non-safety-related breaker), the setting was outside the range of the trip device and it could affect reliable operation of the breaker. In a number of cases, it was found that the setting, as per the calibration on the trip device, was quite different from the desired setting. Repeated calibration over the years had allowed the device to drift without attracting any attention to a potential future problem. In response to the team's concern, the licensee immediately initiated a modification to the procedure to note the old and new settings when calibrating the trip device. Current test records indicate an acceptable trip characteristic.
- b. MP-56.1, "600-volt Motor Control Centers", has instructions for sizing the overcurrent heater elements for MOVs. This procedure was reviewed with licensee personnel and it was determined that it did not reflect the true requirements; it will be revised to more clearly explain the sizing method. Sizing of the overcurrent heater elements for MOVs was under review by the licensee prior to the start of this inspection. The licensee has stated that a revised procedure will be issued when that review has been completed. (See Section 4.2.3 for a related finding)

- c. MP-59.3, "Motor Operated Valves," Section 8.8.2, has a provision for entering the required stroke time. However, in the two cases reviewed, 10MOV-148B and 10MOV-149B, this was not provided in the Preventive Maintenance Work Request. Monitoring the stroke time in the preventive maintenance would enable early detection of incipient failures.

#### 4.7.2.2 Control of Replacement Parts

The heater elements for overcurrent relays are commercially available items and whose lack of performance can compromise the function of safety systems. These items do not have any manufacturer's identification mark when purchased. The only mark is a rubber-stamped serial number on the heaters and the box in which they are supplied. The team reviewed NYPA's procurement practices for these heaters. It was determined that the licensee is procuring heaters directly from the manufacturer, General Electric, with appropriate procurement controls. In addition, the heaters undergo a calibration test prior to use in the starter. From this sample, it appears that adequate care has been taken in using commercial grade elements in safety-related systems.

In view of the fact that molded case breakers are not designed to interrupt more than one severe fault, licensee personnel were asked what action would be taken in response to a fault on an MCC feeder. At present, the Operations group first determines the nature of the fault by looking for damage, smoke, etc. If the operators believe that the fault may have been a transient or minor trouble, they may close the breaker again depending on the plant conditions or requirements. If operating flexibility is adequate, the operations will generally ask the Maintenance to investigate the fault/problem first. Once Maintenance is involved, it appears they will always check out the circuit and equipment thoroughly before closing the breaker. In any case, a Work Authorization will be prepared and the activity will be controlled according to plant procedures.

However, there is no specific instruction available to the operators or maintenance staff with respect to necessary action on an MCC feeder after it trips on a fault. All personnel are cautious about not closing the breaker without checking. However, it was not clear if operating and maintenance personnel were aware of the single operation limitation of the molded-case breakers in clearing heavy fault currents. The consequences of closing the molded-case breakers onto a heavy fault, after having just cleared one, can be catastrophic. Therefore, utmost caution should be exercised and personnel should be made aware of the limitations and risks associated with operation of molded-case breakers after clearing heavy short-circuit currents.

### 4.7.3 419/125 Vdc System

The Fitzpatrick design which relies on the dc bus molded case circuit breakers to isolate the battery from the system upon a fault places additional emphasis on the reliability of these devices. It is therefore essential that these protective devices be well maintained with a preventive maintenance program to provide reasonable assurance that they will operate when required within stated operating times for circuit protection. During the team's review of maintenance activities within the dc system, the licensee was unable to provide any evidence of calibration or testing of these breakers to demonstrate the required trip characteristics. The consequences of circuit breakers not operating within their required operating bands could result in the loss of a dc bus upstream of the breaker. A properly coordinated electrical system along with well maintained circuit breakers substantially improves the system reliability. In response to the team's findings the licensee has initiated plans to test the circuit breakers in BMCC-6 during the 1989 mini-outage. The licensee also plans to initiate a full testing program and schedule to verify that the breakers are capable of performing as designed. Nevertheless, the present lack of dc circuit breaker testing on a periodic basis does not meet the testing requirements addressed in the technical specifications. Failure to perform periodic testing of the dc molded case circuit breakers constitutes a violation of FitzPatrick Technical Specification Requirement 6.8A which requires that written procedures be established and implemented for safety related protective circuits. (50-333/89-80-04.1). Two other examples of inadequate testing are addressed in this section and 4.7.5.

The current dc system design does not provide any undervoltage relay alarm to alert the operators that the 125 Vdc battery is reaching an unacceptably low voltage level. Local and remote indication of the system voltage is provided. However, the only alarm provided to indicate a low system voltage is from an internal battery charger low output voltage sensing relay. The sensing relay is designed to dropout when the charger output voltage drops below the factory installed setting of 120 Vdc. The team requested for review the calibration records to determine that the device is maintained such that it would be able to perform its alarm function. The licensee was unable to provide any records to indicate that the sensing relay had ever been calibrated at any time since its installation. Presently the charger testing procedures require opening the charger output breaker to verify that the relay alarms in the control room. This testing method, however, does not verify that the relay will drop out at 120 Vdc but rather only verifies that it will dropout on a total loss of output voltage. Failure to calibrate the charger low output voltage sensing relay to verify its ability to perform its alarm function does not meet the calibration requirements referenced in the technical specifications.

Failure to perform periodic calibration of the charger voltage sensing relays constitutes a violation of FitzPatrick Technical Specification Requirement 6.8A which requires that written procedures be established and implemented for safety related protective circuits. (50-333/89-80-04.2).

During a walkdown of the 125 Vdc batteries the team observed signs of corrosion on cell 32 of battery 71SB-2. The licensee took as-found resistance measurements for connections between cells 31 to 36 prior to cleaning this connection. These readings were found to be within the acceptance criteria of less than 60 micro ohms. The team reviewed the licensee's battery maintenance procedures to determine the level of scheduled preventive maintenance performed for both the 125 and 419 Vdc batteries. Review indicated that the licensee was not recording resistance measurements between battery bus connections and the verification of torque values for cell connections on a scheduled periodic interval. These attributes are included in current maintenance procedures and were performed subsequent to initial installation of the battery. However, they are not performed within a preventive maintenance program but only as corrective actions when the need arises. This battery maintenance practice does not follow the manufacturer's recommendations or the current industry practice of performing these activities on an annual basis.

The licensee conducts performance discharge tests on both the 125 and 419 Vdc batteries every five years to detect changes in the battery capacities. In addition, a service test is performed every 18 months to verify the battery's ability to satisfy the design requirements of the battery duty cycle. These tests are performed to comply with technical specification requirements. The team reviewed the following battery test procedures:

- MST-71.21, "125 VDC Station Battery Performance and Charger Surveillance Test"
- MST-71.22, "LPCI Independent Power Supply Performance Discharge Test"
- MP-71.20, "125 VDC Station Battery Service Test and Charger Performance Test"

Review of these procedures revealed inconsistencies in the required initial conditions before the conducting of these tests. The technical specifications require that performance and service tests be performed in accordance with RG 1.129 which endorses IEEE 450-1975. This standard requires that no equalizing charge be given to the batteries before conducting the performance discharge test. Review of procedure MST-71.21 revealed that the licensee currently equalizes the 125V battery before conducting the test in contradiction of the IEEE 450 initial condition requirements. The team questioned the licensee as to the validity of the test results since the battery is charged to its optimum condition before tested therefore biasing the results. The licensee stated that the ability of the battery to carry its

design load is tested, in an as-found condition, without an equalizing charge every 18 months via the service test and that this test is in accordance with technical specification requirements. Furthermore, the licensee contended that the IEEE 450-1987 version allows an equalizing charge prior to the performance discharge test if a service test also is performed on a periodic interval. Therefore, licensee stated that it was in conformance with the technical specification testing requirements. Following discussions with NRR the team concluded that even though the licensee's testing methodology differed from that specified in the IEEE 450-1975 standard, testing via the 1987 version was acceptable and met the intent of the technical specification requirements. However, the team pointed out to the licensee that this performance discharge testing method was not consistent between the 125 and 419 Vdc batteries. The 419 Vdc battery is not subjected to an equalizing charge as is the 125 V battery prior to testing. The licensee stated that procedures would be revised to achieve consistency between the battery test methods. A technical specification change will also be proposed to clarify the testing standard that will be utilized.

#### 4.7.4 EDG Maintenance Program

The vendor instructions and manuals applicable to the diesel engine and generator were complete and available for reference by maintenance planners and others involved in EDG maintenance. The maintenance procedures series MP-52 covers maintenance work on engine and generator components including fuel oil transfer pumps, turbocharger, lube oil cooler, and other mechanical and electrical preventive maintenance.

The diesels have performed with a high degree of reliability and availability which are indicators of effective maintenance. During the past 5 years, the licensee has been systematically analyzing and replacing subcomponents on the EDGs. These actions, coupled with testing and controls on engine fuel oil and engine lube oil, have further improved EDG reliability.

The licensee does not have an overall procedure or program outlining the essential attributes of the EDG maintenance program but relies on the initiative of involved individuals for defining the task and scheduling it. There are two problems with the lack of an EDG maintenance program. First, if individuals presently contributing to favorable results move to other positions, work continuity could be interrupted. Second, quality assurance and management have no written program for use in auditing or controlling EDG maintenance activities to ensure that required tasks continue to be performed. The licensee committed to preparing an EDG maintenance program before the 1990 refuel outage.

One specific discrepancy was noted in the area of Diesel Generator lube oil sampling. The condition of the diesel generator lubricating oil profoundly affects the wear and, hence, the performance of the engine. It also provides a mechanism for detecting excessive wear or impending failure. Currently, the lube oil is being sampled and analyzed quarterly, but the sampling is not being done in accordance with a formal, written procedure. Since this is a safety-significant activity that provides information on diesel engine reliability, it should be prescribed by a documented procedure.

Such a procedure should prescribe the frequency and method of performance, and the acceptance criteria, among other things. This procedure should prescribe such details as sample locations, sample sizes, engine condition (operating or idle), and oil condition (hot or engine standby temperature), etc. At the conclusion of the inspection, the licensee had prepared a draft procedure addressing most of these considerations. This is an Unresolved Item (50-333/89-30-15).

#### EDG and ESW Monthly Test

The plant technical specification requires monthly surveillance testing of the Emergency Diesel Generators (EDG) and Emergency Service Water (ESW) pumps. The inspectors also observed the EDG testing on May 23, 1989 noted that the test was conducted in accordance with procedure ST-9B. With the exception of minor instrument problems, the diesels started and performed as expected by review of the plant technical specification and diesel generator technical manuals. Work requests were generated to correct the instrument or indicator problems.

#### 4.7.5 Testing and Design of Reactor Building Closed Loop Cooling Water System Containment Isolation Valve's Safety-Related Air Supply

The surveillance testing of the backup air supplies for containment isolation valves in the reactor building closed loop cooling water system (RBCLCW) was inadequate to demonstrate operability of the valves.

The drywell supply and return lines for the RBCLCW system are equipped with air-operated containment isolation valves. Since these valves fail open on loss of their non-safety-related air supply, they are provided with safety-related backup air supplies.

The licensee has recognized the need to perform surveillance testing of the backup air supplies, and testing was being performed that did verify the ability of the backup supply to cycle the valves closed two times. However, this testing did not address the other aspect of the backup air supply's fundamental function, holding the valves shut for the duration of the accident.

To fulfill the hold shut function, three basic parameters must be considered:

- (1) the minimum pressure required to hold the valves shut.
- (2) the pressure loss due to leakage out of the system. The test incorporates no provisions for maintaining the backup air supply isolated from the main air supply for a period of time while monitoring the pressure drop to determine the actual leakage rate, and
- (3) the pressure loss due to the worst-case post-accident temperature drop in the reactor building.

It appears that the last two of these parameters were not considered in the design, and hence the pressure margin they would require was not incorporated into the acceptance criteria of the test. This design deficiency is an Unresolved Item (50-333/89-80-16)

The safety-related to non-safety-related boundary in the system, the inlet check valve, was not periodically tested to demonstrate its capability to function. Instead, the system was isolated at the manual valve upstream of the check valve. This is a violation 6.8A which requires that written procedures be established and implemented for testing the safety-related protective circuits. (50-333/89-80-04.3).

## 4.8 Emergency Diesel Generator

### 4.8.1 Cooling System

The Emergency Service Water (ESW) system provides the cooling for the emergency diesel generators. The EDG design data indicate the diesel engine releases heat to the ESW cooling water at the rate of  $8.2 \times 10^6$  BTU per hour. The inspector examined the ESW system and ESW heat exchanger to establish how heat removal capability had been verified by previous system testing and by the EDG monthly tests. During monthly diesel engine test runs, the ESW system pumps supply water to the ESW heat exchanger for each diesel engine. During a plant emergency, the ESW pumps also can supply the Reactor Building Closed Loop Cooling Water System (RBCLCW) as shown on drawing 11825-FM-46A. Flow to each diesel engine ESW heat exchanger is limited to approximately 700 gallons per minute through a 2.04 inch diameter flow orifice with excess pump capacity being diverted back to the pump suction bay. The preoperational tests performed in June 1974 demonstrated adequate ESW system flow and pressure capability with various system lineups. The testing verified that the ESW pumps and piping had the required capacity to deliver water to the diesel engines above the minimum flow and pressure requirements. During diesel operation, ESW flow is indicated at the engine by flow meters 46FIS-102(A-D). During the May 1989 diesel test, the ESW temperature increase of 18°F through the heat exchanger indicated at least 50% more heat removal capacity than that required to remove heat rejected by the diesel water cooling system. The team concluded that the ESW system has been verified to have the capacity to remove EDG generated heat.

## 4.8.2 Fuel Systems

### 4.8.2.1 Fuel Oil Day Tank Level Switch Logic

The setpoints for the fuel oil day tank low-level alarms are below the start setpoints for both the lead and the backup fuel oil transfer pumps. With this design, if the lead pump fails to maintain the tank level, the backup pump will start and the alarm will not be actuated. The second pump must also fail to maintain the level before the alarm will be actuated. The alarm setpoint should actually be set between the starting setpoints for the pumps such that both the alarm and the backup pump will be actuated when the lead pump fails to maintain the level. This arrangement is logical and consistent with other redundant design features in the plant.

At the close of the inspection, the licensee initiated a design change package to provide an alarm when the first pump was out of service. This is an Unresolved Item (50-333/89-80-18).

### 4.8.2.2 Fuel Oil Day Tank Level Switch Positions

The level switches on the fuel oil day tank, which control the fuel oil transfer pumps, and the low-level alarm are located in such positions that there is not sufficient fuel for diesel generator operation at full load for 3 hours as specified in the Bases Section of the Technical Specification. In addition, they provide an alarm only minutes before all the fuel will be exhausted.

At the nominal full load fuel consumption rate of 180 gallons per hour, 540 gallons of fuel are required to operate for 3 hours. The level switch locations are such that, under the worst of normal conditions, when the level is at the starting point for the back up transfer pump, there would be sufficient fuel in the tanks for only a few minutes of operation. The low level alarm setpoint, which should be keyed to the Technical Specification Bases, is even lower, providing an alarm only as the tank is completely drained.

To resolve this problem the licensee should provide a low-level alarm setpoint above the Technical Specification Bases value while, at the same time, the licensee should coordinate this solution with the resolution of the logic problem described in Section 4.8.2.1. Since, given the limitations of the tank size and the level switch design, the tank cannot reasonably be maintained above 3 hours worth of fuel, a downward revision of the Technical Qualification Bases value will also be required. However, it still should be maintained as high as practicable to provide sufficient time for the operator to respond to a low-level alarm in the midst of an accident situation before the tank runs out. The licensee agreed to request a change to the Technical Specifications Bases by September 1, 1989. This is an Unresolved Item (50-333/89-80-18).

#### 4.8.2.3 Emergency Fuel Shutoff

It is common practice in diesel engine design to provide an emergency fuel shutoff knob to stop the engine if normal controls fail. This is provided because diesel engines have a history of running out of control and causing fires associated with fuel line ruptures. In the nuclear industry, both types of accidents have occurred.

The licensee's engines are equipped with a red pull knob on the engine skid labeled "Fuel Cutoff Pull." However, the knob will shut off fuel only from the motor-driven pump. The engine-driven pump will continue to supply more than adequate fuel to operate at full load.

The licensee had previously recognized this problem and, at the time of the inspection, had begun the modification process to resolve it. However, the modification being considered was not adequate. It would change the cutoff valve from the motor-driven pump line to the engine-driven pump line. With this design, a second action of turning off the motor-driven pump would be required to completely shut off the fuel. This is contrary to standard industry practice and would create unnecessary risk to an operator not specifically oriented with the peculiarities of this machine. Even if the operator was aware, it would require additional time to achieve fuel shutoff, and it may even be impossible if the second control were rendered inaccessible by the condition that prompted the emergency shutdown.

At the close of the inspection, the licensee committed to evaluate this item along with the other diesel generator fuel system items, to take appropriate corrective action, and as an interim measure, place a warning sign at the knob explaining its limitations.

#### 4.8.2.4 Fuel Filter Design/Operation

The team noted that there are no differential pressure instruments provided to indicate plugging of the fuel supply duplex filters. In an accident situation, there would be no indication of plugging until engine performance had begun to deteriorate.

In addition, even if plugging were suspected as the cause of the deterioration - and there are many other possible causes -- the operator could not shift from one filter to the other for diagnosis or for filter changeout because the lineup currently being used is with the filter unit in the "both" position. In this lineup, both filters would be loaded and a shift would cause further deterioration of EDG performance.

The standard operating mode of duplex filters is with one filter on-line and the other in standby. The design intent is that when the on-line filter becomes plugged, the lineup can be switched to the clean filter to allow continued operation while the plugged filter is changed. The current lineup of these filters in the "both" position defeats this capability.

Plugging of fuel filters/strainers is a high probability threat to emergency diesel generators during an accident when they may be operated for long periods, drawing the fuel tanks down to low levels which require refilling. This creates the potential to introduce new contaminants into the tanks and to stir up the existing sediment, thus increasing the loading rate of the filters/strainers. Since all of the tanks may be refilled at about the same time, there is the potential for simultaneous plugging in all of the units, thus producing a potential common mode failure.

During review of this concern, the team found conflicting information concerning the installed filters. One excerpt from the vendor manual described them as "designed to filter 100 gallons per hour when filtering to capacity using clean oil through both clean elements." Since the engine uses approximately 180 gallons per hour at full load, this would imply that both the engine-driven and motor-driven fuel supply systems operating through both filter units in the "both" position would be required to supply the engine. Even then, there would be very little margin for anticipated loading. The team raised this concern for prompt action.

A drawing of the filter unit from the same manual has a note, "Pressure drop across complete filter will not exceed 5.0 psi when operating to capacity of 5 gpm of clean fuel oil at 68 degrees F thru clean element." It is not clear if this rating is with the unit in the "single" or the "both" position, but the drawing shows the unit in the "single" position.

At the end of the inspection, there was still uncertainty about the filter capacity. However, if the motor-driven and engine-driven fuel systems are redundant as described in various plant documents, and if the filter units are properly designed such that they can be operated in the "single" position, then each filter element must have the capacity to pass full flow at engine overload conditions, with sufficient margin to allow a reasonable degree of loading before becoming overloaded. The licensee agreed to rectify fuel problems by the 1991 refueling outage. Prompt resolution of the filter capacity is needed. This is an Unresolved Item (50-333/89-80-18).

#### 4.8.2.5 Technical Specification on Diesel Generator Fuel

Technical Specification 3.9.C., Diesel Fuel, requires a minimum of 64,000 gallons of diesel fuel be on site for each operable pair of diesel generators at any time the reactor is critical. The quantity is verified monthly using procedure F-ST-9A and also after each operation of the diesel using procedure F-OP-22. These procedures require that the levels in the tanks be determined by dipstick and that the local and remote level instruments indicate less than 7 inches differential from the dipstick indication. This translates to a nominal error in these instruments of as much as plus or minus 1500 gallons per tank (8.33 hours operating time at full load).

The same instruments are used for making routine checks every shift of the underground storage tank levels, with the results recorded in the Operations Log No. 2 rounds sheets (procedure ODS No. 17). However, unlike other critical parameters recorded on these sheets, there is no stated minimum allowable level and, therefore, no accounting for the possible instrument error. The only standard available for comparison is the tank graph in procedure F-ST-9A, "Diesel Fuel Oil Quantity Check", which also does not reflect instrument error. The team was concerned that each tank could be as much as 1500 gallons below the Technical Specification minimum, whereas the shift round sheets would still indicate acceptable levels when compared with the tank graph.

The licensee maintains that the purpose of the shiftly rounds is not to determine if the level drops below the Technical Specification minimum, but rather to detect trends in the levels. The licensee stated that only the monthly test is intended to verify being above this minimum.

The shift round sheets should include acceptance criteria, and the acceptance criteria should incorporate sufficient margin to include instrument error. This is an Unresolved Item (50-333/89-80-XX).

#### 4.8.2.6 Inadequate Diesel Generator Fuel Consumption Test

The fuel consumption rates of the diesel generators have never been properly verified by testing. Although the licensee performed tests during plant startup, they were not performed properly and therefore, the data provides unreliable indication and in one case indicates an unacceptable consumption rate.

The licensee has previously estimated the rate of fuel consumption by measuring the drop in level in the main fuel oil storage tanks during timed runs of the diesels. The testing was in error for the following reasons:

1. The tests were performed only at an overload condition, thereby precluding comparison of the data with the full load consumption rate upon which the Technical Specifications were based. The resultant test data were not evaluated against valid acceptance criteria. The test results were accepted although one engine had a consumption rate more than twice the rate to satisfy the Technical Specification Bases of 7 days full load operation with the required quantity of fuel on site.
2. The fuel consumed was determined by measuring the level change in the main storage tanks. Given the relatively short duration of the tests, this method is not sufficiently precise. Since the tanks are large (36,000 gallons) horizontal cylinders, a very small error in level measurement would produce a large error in volume.

3. The design of the fuel oil day tank level control instrumentation (described in Sections 4.8.5.2 and 4.8.2.2 of this report) may have induced errors of as much as 500 gallons.

The licensee has taken the position that such testing is not required. However, the licensee's performance of the test during the plant startup indicates its original recognition of this requirement.

The importance of this test can best be appreciated in view of the very small available design margin. If the actual fuel consumption exceeds the advertised rate by less than 1%, the minimum required fuel on site is insufficient to satisfy the Technical Specification Bases. For at least one of the engines, the only available data indicate it is exceeding this rate by more than 100%. At the conclusion of the inspection, the licensee agreed to perform these tests before the end of 1989. This is an Unresolved Item (50-333/89-80-18)).

#### 4.8.2.7 Improper Calibration of Fuel Oil Day Tank Level Instruments

The procedure for calibration of the level instrumentation and controls for the diesel generator fuel oil day tanks is incorrect. This creates the potential for not meeting the Technical Specification Bases requirement of 3 hours rated load capability from the day tank.

The tanks are each equipped with six level switches for control of the fuel oil transfer pumps and the tank level alarms, and one level instrument providing indication at the engine control panel. These instruments are calibrated using Procedure No. F-IMP-93.6, Emergency Diesel Generator Fuel Oil Day Tank Level Functional Test, Revision 2, dated 10/2/85.

There are four basic inadequacies in the procedure. First, it does not use a legitimate standard for calibration of the installed level instrument. At the beginning of the procedure, the tank is filled to "approximately 100% full." The procedure does not specify how to determine "full." The licensee stated that 100% full is determined by filling until the transfer pump cutout level switch stops the pump. This is taken as the 100% level, and the installed level instrument (93-LI-102) is adjusted to indicate 100% full. Since the accuracy of the level switches is not known, and indeed is what is being calibrated in this procedure, it is not legitimate to use them as the standard for producing a calibration point. Typical standards which could be used to calibrate such instruments include differential pressure gauge, a temporary sight glass, a dipstick, or a tape.

Second, the one calibration point for the installed level instrument as described above is the only calibration point taken. Therefore, the error rate of the level instrument cannot be detected. The instruments usually have at least a two-point calibration. The industry norm for such an instrument is five points.

The third inadequacy noted is that the procedure does not provide any requirement or space on the documentation form for noting the "as left" indication of the level switches.

The fourth inadequacy is that the procedure uses the incorrectly calibrated installed level instrument as the standard for the subsequent calibration of the level switches that control of the transfer pumps and the alarms. This is done by lowering and raising the level in the tank and noting, per the installed instrument, the actuation levels of the switches. This creates the potential for calibrating the instrument to a device that is not in calibration. This finding constitutes a violation of 10 CFR 50 Appendix B Criterion V which requires procedures appropriate to the circumstance (50-333/89-80-02.1). This is another example of inadequate procedures. Further examples are addressed in Sections 4.3.1.2, 4.8.3.2 and 4.3.4.

#### 4.8.2.3 Quality Control of Emergency Diesel Generator Fuel Oil

In evaluating the licensee's means for ensuring the proper fuel oil for the EDG units the team reviewed the EDG manufacturer's fuel oil recommendations, the licensee's EDG technical specification fuel oil requirements, and fuel oil purchase order specifications. The team also verified the quality of fuel oil purchased and fuel oil stored in the EDG tanks. Following are the findings:

- The EDG manufacturer's recommendations for the fuel specifications are essentially the same as those cited in American Society for Testing and Materials (ASTM) Standard D1975 for No. 2 diesel fuel.
- The licensee's technical specification requirements for diesel fuel are in agreement with ASTM D 975 except for two parameters. The ASTM specification limit for water and sediment is 0.05% and for ash is 0.01% whereas the licensee's technical specification limit is 0.5% for water and sediment and 0.1% for ash. This appears to be an error. The licensee has agreed to request for a technical specification change.
- The licensee's fuel oil purchase orders require EDG fuel in accordance with specification ASTM D 1975. The vendor is required to provide a certificate of compliance.
- Fuel analysis supplied by the vendor and those made by the licensee on a routine periodic basis provide evidence of fuel which meets the ASTM Standard D1975 requirements. However, the team observed that the licensee's program provides no means for the verification of new fuel before adding it to the storage tanks.

NRC Regulatory Guide 1.137 Part C.2.b suggests that prior to adding new fuel to the supply tanks that onsite samples of the fuel be taken for testing of the specific or API gravity, water and sediment, and viscosity. Fuel oil is added to the storage tanks on a quarterly basis. The current practice is to accept fuel on the basis of a fuel ticket certification that the fuel delivered is in conformance with the ASTM Standard D975. No onsite samples of the new fuel are taken. Quality control has not been involved in fuel receipt and quality assurance has not audited the fuel supplier. During this inspection, the licensee prepared a Receipt Inspection Procedure (QAI 7.0, Appendix 7.9) for #2 diesel fuel oil consistent with RG 1.137 and trained selected individuals in application of the procedure.

The diesel fuel in each storage tank is sampled monthly by the Chemistry Department in accordance with the technical specification 4.9.C.1 requirement. Results of the analysis are received approximately three weeks after the sample is taken. Therefore, if an improper fuel had been supplied, a period of seven weeks could pass prior to identification of the problem. The lack of testing new fuel for quality is a violation of 10CFR 50, Appendix Criterion VII, "Control of Purchased Material, Equipment and Services" in that measures were not established to assure that purchased material (diesel fuel) conformed to the procurement documents. This violation is not cited in Appendix A to this report on the basis that the licensee took prompt corrective action, chemistry samples taken monthly according to the technical specification indicated that high quality fuel had been supplied to the plant on a regular basis, and the violation, if cited, would be a Severity Level IV or V.

#### 4.8.3 Air Systems

##### 4.8.3.1 Emergency Diesel Generator Air Starting Reservoir Capacity Test

The FSAR in part 8.6.3 states that each EDG engine has the capability for 10 engine starts from the air start system without the air compressors recharging the air system. The air start system includes 2 redundant sets of 5 air tanks and an air compressor to provide 200 psi maximum pressure to four air start motors that initiate diesel engine rotation. In September 1988, the starting capacity of 1 set of 5 tanks on EDG "C" was tested yielding seven successful engine starts where the initial tank pressure was 184 psi. The engine did not start with an initial tank pressure of 56 psi. The initial air start from 184 psi caused a 28 psi drop of tank pressure to 156 psi. Successive pressure drops on starting were less than 28 psi; the last start requiring a tank pressure drop of 15 psi. During this inspection, the pressure drop on starting the "D" diesel was approximately 50 psi from the initial level of 200 psi. The team asked if this observation invalidated the applicability of the "C" diesel tests to engines A, B and D. The licensee agreed to evaluate this situation by starting each diesel with approximately 180 psi air pressure and measuring the pressure drop to start during the next monthly diesel test.

#### 4.8.3.2 Inadequate Procedure for Switching Diesel Generator Starting Air Banks

The normal lineup of the diesel generator starting air banks is with half of the reservoir (five accumulators) on-line to start the unit and the other half isolated in the standby mode. The procedure for switching air banks (procedure number F-OP-22, Diesel Generator Emergency Power) does not recognize the operating scenario in which the on-line bank has been depleted. It recognizes only the scenario in which the on-line bank is not depleted, such as normal shifting to achieve even wear on the compressors.

The proper sequencing of the air bank isolation valves for each of these scenarios is the opposite of the other. In the first scenario, when the on-line bank has been depleted, such as for unsuccessful start attempts, the on-line air bank isolation valve should be closed before the standby air bank isolation valve is opened, to prevent losing the air from the standby air bank to the depleted on-line air bank. In the second scenario in which the unit is in normal standby, the isolation valve for the standby air bank should be opened before the on-line air bank isolation valve is closed, to prevent momentarily rendering the unit inoperable. The operating procedure addresses only the latter case. There are no instructions in this or other procedures for the unsuccessful start attempt case. Since this case is the reason for having the backup reservoir in the first place, the procedure is incomplete.

The procedure contains a built-in dilemma for an operator. This was demonstrated during several conversations with the licensee. When asked what valve sequence would be used to line up the standby bank if the on-line bank had been depleted, an operator responded with the correct sequence, but it was contrary to the directions given in the operating procedure. When the same situation was posed to operations management, they also indicated that the operator should proceed with what he believes is the correct sequence. This is in direct conflict with the principle of "verbatim compliance".

The operating procedure should be revised to differentiate between the two operating modes for the system and should provide clear operating instructions for each. This finding constitutes a violation of 10 CFR 50 Appendix B Criterion V which requires that activities affecting quality shall be prescribed by procedures appropriate to the circumstance. (50-333/89-80-02.2).

#### 4.8.3.3 Diesel Generator HVAC Design Requirements/Operating Procedure Conflict

Operating Procedure Number EOP-60, "Diesel Generator Room Ventilation," contains a statement that the HVAC is not required for the operation of the diesel generators. The licensee was asked to provide an analysis which demonstrated this capability. At the conclusion of the inspection, this analysis had not been provided.

Subsequent to the inspection, the licensee determined that the statement about the HVAC conclusion cannot be supported; the licensee will remove the statement from the procedure.

#### 4.8.4 Emergency Diesel Generator Electrical Control

The team reviewed the EDG electrical starting, running, and shutdown control circuits in order to assess their functions in providing for the reliable operation of the EDG units during their normal LOOP/LOCA accident scenario.

The electrical control circuits for each pair of EDG units is from a separate division 125V dc battery circuit through two circuit breakers, a knife switch, fuses, cable and wiring. Starting of the EDG is initiated by either the LOOP or LOCA redundant relay contact signal inputs into the 125V dc control circuit. The starting signal actuates switching devices to provide 125V dc to the air start solenoid, governor booster pump, governor shutdown solenoid, fuel prime pump, generator field flash, and the circuit breaker closing coil. When the EDG is started and is providing power to the LOOP/LOCA loads, it is no longer dependent upon the 125V dc power (self-sustaining) except for the automatic shutdown circuit. Loss of voltage in this circuit either as a consequence of protective relay function or circuit failure (such as fuse, circuit breaker, etc.) will de-energize the governor shutdown solenoid which causes the governor hydraulics to drive the governor to the engine fuel shutoff position thereby causing the EDG to shutdown. According to the Woodward Governor Technical Manual, the shutdown solenoid could provide shutdown function either by being energized or de-energized. The licensee identified this potential problem in October 1987. However, no specific action had been taken to evaluate/resolve this potential problem before this inspection. The licensee currently plans to conduct a design review and evaluation in this area to find changes that could improve EDG reliability.

#### 4.8.5 EDG Long Term Operation

Since the function of the EDG units is to provide emergency power for safe shutdown of the plant in the event that normal or reserve station power is unavailable, the team assessed the procedures provided to operators to enhance LOOP/LOCA long-term operation. Licensee procedure F-OP-22, "Diesel Generator Emergency Power" gives the operator with detailed procedures for the pre-operational alignment, startup, normal monthly testing, and shutdown of the EDG units. These procedures appear to be adequate in most areas, including the normal short-run operational testing of the machines, but they appear to be deficient in providing the operators instructions for the potential long-term operation of the units. These procedures only provide for the routine monitoring of EDG parameters such as engine temperatures and oil pressure, and for adding oil and switching fuel transfer pumps. Some of the areas of procedural deficiencies noted during this brief review are the following:

- no instructions on how to bring the second EDG on line and load it if it initially fails to start and can subsequently be started
- no instructions on how to transfer loads and shutdown an EDG
- no instructions for the emergency starting and operation of an EDG if 125V dc control power is lost or a circuit failure occurs
- no instructions on how to change fuel oil filters with the engine running
- no instructions on how to operate without the DC motor driven fuel pump
- no instructions when to order replacement diesel fuel

The licensee committed to address the above deficiencies by the end of 1989.

#### 4.9 Reactor Building Closed Loop Cooling Water System

In reviewing the adequacy of the emergency service water (ESW) system for cooling the diesel generators, the team discovered that the system is connected with the reactor building closed loop cooling water (RBCLCW) system. The ESW systems feed into the RBCLCW systems whenever the pressure in the RBCLCW falls to 40 psi. A loss of offsite power can also prompt this automatic actuation. The designs of these two systems are such that, in a LOCA, large direct leakage paths may be opened from the containment to the reactor building and to Lake Ontario if the RBCLCW system is faulted.

During normal operation, the RBCLCW system provides cooling water to two heat loads inside the reactor containment: the drywell coolers and the recirculation pump and motor coolers. Both of these loads are non-safety-related and the RBCLCW piping to these loads is non-safety-related and not protected against the effects of high energy line break.

Each of the containment penetrations for the RBCLCW lines is provided with one air-operated isolation valve outside containment that was added in response to NUREG-0737. The supply lines are each equipped with one check valve. The air-operated valves are actuated only by operator action. There is no automatic actuation.

The ESW to RBCLCW system crosstie is through two normally closed motor operated valves in the return side of the system. These open automatically upon sensing a low pressure (less than 40 psi) in RBCLCW, allowing the ESW system to supply the RBCLCW loads on loss of power to the non-1E powered RBCLCW pumps.

The concern with this design is as follows: During a LOCA, the RBCLCW piping inside the drywell may be ruptured due to the HELB effects. As a result, the water in the system may drain out, and the pressure in the system will drop below the ESW system crosstie actuation point. When these valves open, a large direct leakage path will exist from the containment vessel to Lake Ontario.

A second less-direct leakage path would also exist through the open vent on the RBCLCW head tank. Although leakage from this path would be processed by the standby gas treatment system, this system is designed to process only the design-basis leak, which is much less than the leakage which could potentially occur through the 1-inch diameter head tank vent. Therefore, the 10 CFR 100 limits could potentially be exceeded.

The licensee contended that in such a case the operator would detect radiation in the ESW effluent and would close the containment isolation valves. However, since this is not the only potential source of radiation in the ESW system, the operator could not necessarily identify this as the source. In addition, since the other instruments on the RBCLCW system which might give further evidence of system rupture are not powered from Class 1E power sources, they would not necessarily be available.

The licensee also contended that leakage through the head tank vent would be detected by the reactor building area radiation monitors. However, in a LOCA, these monitors could all be overranged even with normal leakage. Therefore, their ability to detect this leakage is questioned.

The licensee has also contended that since the RBCLCW system is closed inside containment, this problem does not exist. The system is indeed closed during normal operation. However, since this system's piping is not protected from HELB and is in close proximity to primary system piping at several locations, without an analysis that shows otherwise, it must be assumed to be ruptured by the LOCA effects and not to remain closed.

The following requirements were in the public record at the time of the original plant license, and (b) and (c) were specifically designated as requirements for this plant by a letter from the Atomic Energy Commission to the licensee dated December 18, 1972.

- a. 10CFR 50, Appendix A, Criterion 10 (1967 version), Containment, requires that "The containment structure shall be designed to sustain the initial effects of gross equipment failures, such as a loss of coolant boundary break, without loss of required integrity and, together with the other engineered safety features as may be necessary, to retain for as long as the situation requires the functional capability to protect the public."

- b. 10CFR 50, Appendix A, Criterion 40 (1967 version), Missile Protection, requires that "Protection for engineered safety features [such as the containment and its appurtenances] shall be provided against dynamic effects and missiles that might result from plant equipment failures."
- c. 10CFR 50, Appendix A, Criterion 42 (1967 version), Engineered Safety Features Performance Capability, requires that "Engineered safety features shall be designed so that the capability of each component and system to perform its required function is not impaired by the effects of a loss-of-coolant-accident."

In addition to the basic oversights in the original design, there are several other related shortcomings in the design of the NUREG-0737 modifications that were performed as follows:

- (1) GDC-56 requires that automatic isolation valves shall be designed to take the position upon power failure that provides greater safety; in the case of these valves, that position would be closed. These valves fail open on loss of air.

The licensee takes the position that "fail open" was used to comply with the NUREG-0737 requirement that non-safety-related systems which could be used for accident mitigation (the drywell coolers) be made available to the maximum extent practicable. This argument assumes that this criterion and the containment isolation criterion are mutually exclusive. However, they are not and both can be satisfied. Even if they could not, the criterion related to the basic safety requirement would take precedence.

Additionally, the drywell coolers would be effective for mitigation only for the case of a small-break LOCA, which is of no threat to the integrity of the RBCLCW system piping and therefore of no concern in this situation. For the large-break LOCA, which is the accident of concern, the drywell coolers would be ineffective for three reasons: (i) their capacity is insignificant compared to the heat load of this LOCA; (ii) their fans are not designed to operate in a DBA LOCA environment; and (iii) they may be incapacitated by the loss of the RBCLCW system, which is the focus of this finding.

- 2. The design criteria for the safety-related backup air supplies for the containment isolation valves did not include consideration of the air leakage from the system for the duration of the accident and the loss in pressure due to worst-case reactor building cooling post-accident (according to the licensee's analysis the temperature may drop to 32° F) as described in Section 5.3.2.2. Therefore, they could be undersized.
- 3. GDC 56 requires that isolation valves outside the containment be located as close to the containment as practical. These are not so located.

10CFR 50, Appendix A, Criterion 56 (version as amended October 27, 1978), Primary Containment Isolation, requires that "isolation valves outside containment shall be located as close to the containment as practical and upon loss of actuating power, automatic isolation valves shall be designed to take the position that provides greater safety." These requirements were applicable at the time these modifications were made. Therefore, this is a Violation (50-333/89-80-01).

In response to this observation, at the close of the inspection, the licensee agreed to the following short-term actions: The emergency operating procedures would be immediately changed to instruct the operator to close all of the RBCLCW containment isolation valves upon coincident indication of a LOCA and the actuation of the RBCLCW/ESW cross-tie valves. Although this is acceptable for the short term, it may not be an acceptable long-term solution since it depends on operator action during the initial stages of the accident, and because it only addresses the automatic isolation shortcoming of the design and not the others.

In a subsequent correspondence, the licensee committed to leak test the check valve in the air system for the RBCLCW valve and establish the adequacy of the back up air cylinders for the valve.

#### 5.0 UNRESOLVED ITEMS

Unresolved items are matters for which more information is required in order to ascertain whether they are acceptable, violations, or deviations. Unresolved items are discussed in Section 4.


#### 6.0 EXIT INTERVIEW

At the conclusion of the inspection on May 26, 1989, the inspection team met with the licensee representatives, denoted in Attachment 5. The team leader summarized the scope and findings of the inspection at the time.

The team gave no written material to the licensee.





419 V DC ONE LINE DRAWING



\* DENOTES BUS/EMPT/LOADS  
 AS-BUILT VERIFIED

93-EDG

125 Vdc SYSTEM



\* Bus/Eqpt/Loads which were as-built verified

## ATTACHMENT 4

## CALCULATIONS REVIEWED

| <u>Calc. No.</u> | <u>Date</u> | <u>Title/Subject</u>   |
|------------------|-------------|--|
| 11825-E-19       | 4/8/69      | Heat Release - 4-kV Emergency Switchgear   |
| 11825-E-24       | 7/8/69      | HVAC Loads on Emergency Bus - Estimate   |
| 11825-38         | 4/22/70     | Heat Release During Emergency - 600-V Unit Substation  |
| 12966-PE(N)-026  | 4/13/82     | Effect of Equipment Heat Load on the Reactor Building for the First 24 Hours Post LOCA and Post HELB                     |
| 12966-PE(N)-024  | 4/13/82     | Reactor Building Long Term Temperature, Post LOCA & Post HELB  |
| 001              | 5/18/89     | Determination of Post HELB Transient Heat Flux Into the Load Center Enclosure, L-15 and L-16 Inside the Reactor Building |
| None             | 5/19/89     | Extrapolation of Environmental Enclosure Performance to HELB Conditions  |
| JAF-89-019       | 5/19/89     | Environmental Enclosures Heat Load and Capacity Evaluation   |
| 9017-1           | 5/11/89     | Potential Flooding Impact for EDG Room Sprinkler Actuation with Floor Drains Plugged                                     |
| 00               | 4/18/89     | Evaluation of Impact of Flooding Inside Emergency Diesel Generator Rooms on Safety-Related Equipment                     |
| E-120            | 4/7/72      | Buses 11500 (L15) & 11600 (L16), FDRS 11516 & 11616 to Control Rod Drive Water PP  |
| E-124            | 5/11/72     | Bus 11600 (L16), Feeder 11606 to MCC C161  |
| E-125            | 4/6/72      | Bus 11600 (L16), Feeder 11608 to MCC C161  |
| E-126            | 4/6/72      | Bus 11600 (L16), Feeder 11610 to MCC C161  |
| E-130            | 4/6/72      | Bus 11600 (L16), Bus Coordination  |
| E-241            | 8/10/72     | Bus 10500 SWGR H05 & Bus 10600 SWGR H06, Bus Coordination  |

| <u>Calc. No.</u> | <u>Date</u> | <u>Title/Subject</u>   |
|------------------|-------------|--|
| E-242            | 4/10/72     | 350 Hp Service Water Pump, Feeders 10510, 10520, 10610 & 10620                 |
| E-243            | 4/10/72     | 1250 Hp Core Spray Pump, Feeders 10530 & 10630                                 |
| E-244            | 4/10/72     | 1000 Hp RHR Pump, FDRS 10640, 10650, 10540 & 10550                             |
| E-252            | 2/16/73     | BUS 10500 SWGR H05 & Bus 10600 SWGR H06, Engine/Gen.                           |
| 11825-E-4        | 10/3/88     | 4KV Motor List   |
| 11825-E-14       | 2/20/69     | Short Circuit Calculation - Isolated Phase Bus                                 |
| 11825-E-16       | 4/4/69      | Automatic Start & Seq. Loading of Emerg. Gen. System - Study                   |
| 11825-E-17       | 4/4/69      | Estimated Diesel Gen. Loads for Post Accident Conditions                       |
| 11825-E-19       | 4/8/69      | Heat Release - 4KV Emergency Switchgear  |
| 11825-E-20       | 4/8/69      | 4KV Bus Sizes & Total Load   |
| 11825-E-33       | 11/29/68    | Aux. Pwr. Transformer Fault Duties S.S. 4160V Switchgear                       |
| 11825-E-34       | 1/29/69     | 4160V Switchgear Fault Duties  |
| 11825-E-43       | 11/25/70    | 5KV Motor Leads  |
| 11825-E-44       | 11/25/70    | Diesel Generator Leads Cable Size Calculation                                  |
| 11825-E-45       | 11/25/70    | Bus Tie Cable Size Calculation   |
| 11825-E-46       | 11/25/70    | 4KV Transformer Cable Size Calculation   |
| 11825-E-63       | 8/10/72     | Load on Bus 10300  |
| 11825-E-66       | 1/23/73     | Fault Calculations on 4KV Bkrs. with Diesels                                   |
| 11825-E-67       | 11/16/71    | 600V System - 600V Loads   |
| 11825-E-69       | 3/20/73     | Voltage Profile Study  |
| 11825.10-E-77    | 3/25/87     | Voltage Profile - Emergency Buses Fed from Reserve Station Service Transformer |
| 11825.10-E-81    | 6/25/77     | Undervoltage Study of Class 1E Equipments MCC Control Ckts                     |

| <u>Calc. No.</u> | <u>Date</u> | <u>Title/Subject</u>   |
|------------------|-------------|--|
| 14620-E-77-01    | 3/25/87     | Emergency Diesel Generator Load Review   |
| 832955-E5        | 8/14/86     | Protective Device Settings 600V - L25 & L26<br>Feeders to 71TS-7, Feeders 12502 & 12602,<br>4.16KV - Feeders 10560 & 10600 |
| E-48             | 3/7/72      | Short Circuit Rating of BMCC 1&2   |
| JAF-89-022       | 5/24/89     | DC Voltages at Critical Loads  |
| JAF-89-024       | 5/24/89     | DC System Coordination and Short Circuit<br>Calculations   |

ATTACHMENT 5

1.0 PERSONS CONTACTED

1.1 NEW YORK POWER AUTHORITY (NYPA)  
J. A. FITZPATRICK NUCLEAR POWER PLANT (JAFNPP)

T. Anderson, Electrical Engineer (WPO)  
\*R. Baker, Maintenance Superintendent  
\*R. Beedle, Vice President, Nuclear Support  
F. Bloise, Electrical Engineer  
P. Brozenich, Operations Shift Supervisor  
W. Childs, Senior Licensing Engineer  
\*A. Ettliger, Director, Design  
\*W. Fernandez, Resident Manager  
\*J. Gray, Licensing Manager  
L. Guaquil, Director, Project Engineering (WPO)  
\*M. Hansen, Plant Engineer  
A. Heath, Fire Protection Engineer  
T. Herrmann, Plant Engineering Supervisor, Mechanical  
\*R. Hladik, Plant Engineer  
D. Holliday, Plant QA  
\*R. Houston, Electrical Engineer  
N. Hoy, Plant Engineering Supervisor  
T. Hunt, I&C Chief Technician  
N. Johnson, Maintenance Planner  
D. Keeper, I&C General Supervisor  
\*H. Keith, I&C Superintendent  
W. Kenner, Senior Nuclear Operator  
K. Kilpack, Construction Supervisor  
\*R. Lasino, Superintendent of Power  
J. Lazarus, Plant Engineer  
\*R. Locy, Operations Superintendent  
R. Lowe, I&C Superintendent  
B. Marks, Maintenance Engineer  
K. Moody, Plant Engineer  
\*S. Mukerjee, Electrical Engineer (WPO)  
D. Nacamuli, I&C Supervisor  
R. Patch, QA Superintendent  
S. Rokerya, Licensing Engineer  
\*D. Ruddy, Plant Engineering Supervisor, Electrical/I&C  
S. Scott, I&C Supervisor  
\*D. Simpson, Training Superintendent  
D. Squires, Operations Shift Supervisor  
G. Tasick, QA Supervisor  
K. Vehstedt, MOV Engineer (WPO)  
\*V. Walz, Technical Services Superintendent  
J. Wieroski, Technical Training Supervisor

\*Present at exit meeting on May 26, 1989.

1.2 STONE AND WEBSTER (SWEC)

D. Patel, Senior Electrical Engineer

1.3 U.S. NUCLEAR REGULATORY COMMISSION

R. Plasse, Resident Inspector

\*W. Schmidt, Senior Resident Inspector

\*J. Strosnider, Chief, Engineering Branch

\*H. Wang, Project Engineer, NRR

1.4 REGULATORY BODY OF SPAIN

A. Perez

\*Present at exit meeting on May 26, 1989.