#### U.S. NUCLEAR REGULATORY COMMISSION

## REGION III

Reports No. 030-00302/89001(DRSS); 030-02274/89001(DRSS)

Docket Nos. 030-00302; 030-02274 Licenses No. 24-00481-04; 24-00481-05

Categories: G3; G

. .

Priorities: I; III

Licensee: Ellis Fischel State Cancer Center (EFSCC) 115 Business Loop 70 West Columbia, MO 65201

Inspection At: 115 Business Loop 70 West Columbia, MO 65201

Inspection Conducted: April 4-5, 1989

Enforcement Conference: April 25, 1989

Inspectors: C. C. Casey

Radiation Specialist C. F. Frazier License Reviewer

Allent. Case

Reviewed By:

Section 2 Benes. Maltet

D. J. Sreniawski, Chief

Nuclear Materials Safety

Bruce S. Mallett, Ph.D., Chief Approved By: Nuclear Materials Safety Branch

Inspection Summary

Inspection on April 4-5, 1989 (Reports No. 030-00302/89001(DRSS); 030-02274/89001(DRSS))

Areas Inspected: This special unannounced inspection was performed in response to irregularities in personnel changes identified by a license reviewer in the May 25, 1989 renewal application for the 24-00481-05 license. The reviewer subsequently learned that the licensee was using an unauthorized Radiation Safety Officer, that the licensee had no authorized user for the teletherapy license and the Chairman of the Radiation Safety Committee had been two

8905240486 890512 REG3 LIC30 PNU 24-00481-04

Date

unauthorized individuals since February 1985. The inspection included a review of the licensee's organization; enforcement history; training; radiological protection procedures; facilities; security of licensed materials; instrumentation; personnel radiation exposure control; sealed source inventory and leak tests; internal audits; molybdenum-99 breakthrough tests; radioactive package receipt and surveys; area surveys waste disposal; teletherapy monthly spot checks and annual full calibrations; notifications and reports; postings and labelings; and independent measurements. <u>Results</u>: Of the areas inspected, 12 violations and seven areas of concern were identified:

## 1. License No. 24-00481-05

. •

- a. License Condition No. 19 of Amendment No. 35 individuals who were not approved by NRC acted as Chairpersons of the Radiation Safety Committee (Section 5).
- b. 10 CFR 35.13(c) failure to obtain an amendment to the license prior to changing Radiation Safety Officers (Section 5).
- c. 10 CFR 35.13(e) failure to obtain an amendment to the license prior to changing location of the waste storage area (Section 5).
- d. 10 CFR 35.204(b) improper implementation of the molybdenum-99 breakthrough test procedure (Section 5).
- e. 10 CFR 35.315(a)(8) personnel who prepared and administered therapy doses of iodine-131 were not assayed for thyroid burden (Section 6).
- f. 10 CFR 35.315(a)(4) failure to measure dose rates in certain restricted and unrestricted areas after patients had received radiopharmaceutical therapy (Section 5).
- g. 10 CFR 35.22(a)(2) Radiation Safety Committee failed to meet during the third quarter of 1988 (Section 5).
- h. 10 CFR 19.13(b) an individual was not provided with information regarding exposure to radiation in spite of repeated requests for this information (Section 6).
- 2. License No. 24-00481-04
  - a. License Condition No. 12.A of Amendment No. 31 ~ unauthorized physicians used licensed material (Section 5).
  - b. 10 CFR 35.615(d)(3) failure to test teletherapy radiation monitors with a dedicated check source (Section 5).
  - c. 10 CFR 35.615(d)(1) failure of a teletherapy radiation monitor to provide visible notice of a partially exposed source (Section 5).

d. 10 CFR 20.401(a) - failure to record complete NRC Form-5 information for one individual (Section 6).

- 3. Areas of Concern
  - a. There is a need for adequate management staff oversight of both licensed programs to assure safe operations and compliance.
  - b. It appears that the Radiation Safety Officer (RSO) does not have sufficient time to devote to the radiation safety programs due to extensive patient care related duties in medical physics.
  - c. The three physics technologists have to use spare ring badges that are not in their names - concern was raised about control of these badges and potential exposure tracking problems.
  - d. It appears that there is a need to assure an atmosphere where employees can freely raise safety concerns without fear of reprisal.
  - e. The cobalt-60 source in the Picker Model 6096A teletherapy unit malfunctioned on April 4, 1989 does the licensee plan to repair or dispose of the unit?
  - f. The TV screen display for the Theratron 80 was scrambled as of April 4, 1989 - concern was raised regarding whether it had been repaired.
  - g. A therapy technologist hired April 1988 had to use an extra spare badge for four months before obtaining a badge in his own name. Concern was expressed regarding the potential for problems with control of such badges and tracking the exposures they record.

#### DETAILS

## 1. Persons Contacted

\*+Ronald G. Vincent, M.D. Medical Center Director \*+Denise J. Noonan, Ph.D., Radiation Safety Officer (RSO) and Senior Medical Physicist +Jaya Soni, M.D., Chairperson, Radiation Safety Committee Olin Smith, Nuclear Medicine Technologist Kay Glass, Radiation Therapy Technologist William White, Medical Physicist

+Denotes preliminary exit interview attendees on April 5, 1988. \*Denotes enforcement conference attendees on April 25, 1989.

### 2. Purpose of Inspection

This special unannounced inspection was performed in response to irregularities in personnel changes identified by a license reviewer in the May 25, 1988 renewal application for the 24-00481-05 license. The followup inspection addressed issues pertaining to the irregularities in the personnel changes as well as elements normally addressed in a routine inspection.

## 3. Organization

Ronald G. Vincent, M.D., Medical Center Director Denise J. Noonan, Ph.D., Radiation Safety Officer Jaya Soni, M.D., Chairperson, Radiation Safety Committee Mary Lee, M.D., Authorized User George Wilson, M.D., Authorized User Charles Blackwell, M.D., Authorized User Thomas Sullivan, M.S., Teletherapy Physicist (as of April 26, 1989)

The nuclear medicine technologist reports to Drs. Soni, Lee, Wilson, and Blackwell. The therapy technologists report to Dr. Lee. All technologists also report to Dr. Noonan, for purposes of the licensed programs. Dr. Noonan reports to the Radiation Safety Committee and directly to Dr. Vincent.

# 4. Licensed Programs and Enforcement History

a. 24-00481-05 license: License was originally issued on September 7, 1965. License became a Type A broad scope with Amendment No. 31 dated December 16, 1977. The license was renewed in its entirety on January 25, 1989 via Amendment No. 38, which also removed its broad scope authority. They are currently authorized to use byproduct material in 10 CFR 35.100, 35.200, 35.300, and 35.400, and materials identified in 10 CFR 31.11 (kits). They currently perform 60-80 studies per month, about 98% of which use technetium-99m related products. About 10 patients per year are treated with <30 millicuries (mCi) iodine-131 as capsules and 0-4 patients per year are treated with 30-300 mCi iodine-131 as capsules. About 4 brachytherapies are performed per year, mostly with radium (disposed of 3/89) and rarely with iridium-192. Cesium-137 sources have been ordered. One 1.3 Ci molybdenum-99/technetium-99m generator is received each week.

The enforcement history for License 24-00481-05 includes:

- (1) Last inspection on April 14, 1987, no violations identified.
- (2) Inspection on February 4-5, 1985, 3 violations and 1 area of concern (intimidation), violations as follows: failure to lock the nuclear medicine hot lab when unattended; failure to calibrate a survey meter on annual basis; failure to survey elution and preparation areas during certain months.
- (3) Inspection on June 7-10, 1982, no violations identified. This inspection also examined allegations received in March 1981:
  - (a) Dummy iridium seeds placed on the chairs of the radiation safety staff.
  - (b) Sabotage of office equipment with foul smelling substance.
  - (c) Intimidation and harassment of the radiation safety staff.

These problems appeared to have been resolved during inspection.

- (4) 1978-1980 "the Richter case" the licensee released a patient who still contained 4 implanted Ir-192 seeds. Their then RSO (Dr. Richter) notified NRC, was subsequently fired for making the report and the courts ruled the licensee violated 10 CFR 19.16(c) in discharging him.
- (5) Inspection on January 17-18, 1980, 3 violations identified: failure to issue film badges at monthly intervals; failure to record extremity exposures to an individual; failure to properly record personnel radiation exposures in accordance with Form NRC-5. (Performed in response to allegations regarding improper changing of film badges and workers overexposed from radium and P-32 therapies.)
- b. 24-00481-04 license: License was originally issued on July 6, 1962 and was last renewed in its entirety on June 6, 1988 via Amendment No. 31. Two teletherapy units are authorized for medical use as described in 10 CFR 35.600. The Picker Model 6096A is authorized for 5000 Ci but contains 1115 Ci and has not been used on patients

since February 2, 1989. It is used as a backup unit normally. The AECL Theratron 80 is authorized for 5500 Ci but contains 2440 Ci and has not been used on patients since February 9, 1989, due to lack of a teletherapy physicist. The Picker was normally used for one patient every 3 months. The Theratron was used as backup for the licensee's Siemens accelerator and was used on about 15 patients for about 4 days per month.

The enforcement history for License 24-00481-04 includes:

- (1) Last inspection on April 4, 1987, no violations identified.
- (2) Inspection on February 4-5, 1985, no violations identified.
- (3) Inspection on June 7-10, 1982, no violations identified.
- (4) Inspection on September 5-6, 1979, one violation, failure to leak test sealed cobalt-60 source in timely manner.
- (5) April 29, 1980 Immediate Action Letter issued stopping use of Picker unit until re-calibrated.

#### 5. Routine Inspection Elements

Routine inspection elements for both licensed programs were included in the inspection.

The licensee's internal audits for the nuclear medicine program consist of quarterly visits from their consultants, Radiation Consultants of Mid-America. Reports resulting from these audits were reviewed and the scope of each audit appeared to be comprehensive. However, although the consultant noted several minor potential problem areas, none of the violations identified by the NRC inspector during this inspection were found by the consultant prior to inspection.

The licensee's training program appears to be generally adequate. The licensee uses videos, slides, handouts, lectures, one-on-one discussions, audio cassettes from the Society of Nuclear Medicine, NRC publications, and periodic "dry-run" drills for teletherapy as training tools. Personnel interviewed appeared to be well-trained and were aware of their rights and responsibilities as radiation workers according to 10 CFR 19.12. Training includes the ancillary staff, as appropriate, and records of training for caregivers, as specified in 10 CFR 35.310 and 10 CFR 35.410. Records showing training for teletherapy personnel according to 10 CFR 35.610 were reviewed and found to be adequate. Retraining sessions are offered at least annually and all training is coordinated through the RSO and consultants.

Minutes from Radiation Safety Committee (RSC) meetings were reviewed from 1987-1389. Until January 25, 1989, the licensee had a Type A broad scope license but no new authorized users were approved and the

research program was inactive. Membership of the Committee appears adequate with one exception. One of the main functions of the RSC is to administer the institution's radioactive material program including the approval and disapproval of proposed radioactive materials users and uses. The Chairman of the RSC has an essential radiation safety function in that he or she directs the charter for the RSC. License Condition 19 of Amendment 35 for the 24-00481-05 license requires the licensee to use material in accordance with statements, representations, and procedures contained in a letter dated May 2, 1983. The letter dated May 2, 1983 states that Jose Pacheco, M.D. would be Chairman of the Radiation Safety Committee. However, on February 22, 1985 Dr. Jose M. Sala became the Chairman of the RSC and in July 1988 Dr. Jaya Soni became the Chairperson of the RSC. Neither Dr. Sala nor Dr. Soni were approved by NRC to chair the RSC. This constitutes a violation of License Condition 19 of Amendment No. 35 for the 24-00481-05 license which requires the Chairman of the RSC to be Jose Pacheco, M.D.

RSC meetings have been held quarterly with the exception of the third quarter of 1988 when a meeting was not held. This constitutes a violation of 10 CFR 35.22(a)(2) which requires that each medical institution establish a Radiation Safety Committee to oversee the use of byproduct material and requires the Committee to meet quarterly.

Staffing for both licensed programs was reviewed. 10 CFR 35.13(c) requires that a licensee obtain an amendment prior to changing its Radiation Safety Officer (RSO). License Condition No. 12C of Amendment No. 37 for the 24-00481-05 license and License Condition No. 11 of Amendment No. 31 for the 24-00481-04 license require the RSO to be Jose Maria Sala, M.D. However, during the period from July 1, 1988 through January 25, 1989 the licensee had no authorized RSO. This constitutes a violation of 10 CFR 35.13(c) which requires that a licensee obtain an amendment prior to changing its RSO.

License Condition No. 12A of Amendment No. 31 for the 24-00481-04 license names Jose M. Sala as the authorized user. However, from July 1, 1988 through January 25, 1989, two physicians other than Jose M. Sala, M.D. functioned as authorized users, including prescribing cobalt-60 teletherapy treatments for humans (Attachment A). Both physicians' credentials were reviewed and both were found to be qualified to administer cobalt-60 teletherapy treatments for humans. This constitutes a viclation of License Condition No. 12A of Amendment No. 31 for the 24-00481-04 license which names Jose M. Sala as the authorized user.

The licensee's radiological protection procedures appeared to be adequate in that they included the use of protective clothing, disposable gloves, vial and syringe labels and shields, assaying of patient doses prior to administration, and other protective measures.

Leak tests and inventories for the licensee's sealed sources, including two cobalt-60 teletherapy sources and several submillicurie dose calibrator reference sources, appeared to be adequate. The inspectors noted, however, that the licensee used a radium-226 standard to obtain efficiency when counting and calculating leak tests for the cobalt-60 sources. The inspectors suggested that the use of a cobalt-60 standard, which the licensee possessed, would yield better test results. The licensee agreed to consider this suggestion.

The licensee possesses a variety of survey instruments, including a Keithley digital ionization chamber. In addition, the licensee possesses an electrometer and chambers sufficient to perform required output tests and calibrations on the two cobalt-60 teletherapy units. K and S Associates calibrates the electrometer and chambers, which was last performed on February 6, 1989. Radiation Consultants of Mid-America calibrates the survey instruments for suclear medicine and the licensee calibrates its own survey meters in-house for the teletherapy license. These calibrations appeared to be adequate.

The licensee also possesses two Eberline ESI 2 radiation monitors, one for each of its two cobalt-60 teletherapy rooms. Both monitors have a backup battery power supply. 10 CFR 35.615(d)(3) requires that a licensee install in each teletherapy room a permanent radiation monitor capable of continuously monitoring beam status. Each radiation monitor must also be checked with a dedicated check source for proper operation each day before the teletherapy unit is used for treatment of patients. In addition, 10 CFR 35.615(d)(1) requires that a radiation monitor must provide visible notice of a teletherapy unit malfunction that results in an exposed or partially exposed source. Although the licensee possesses the required radiation monitors, they were not checked with a dedicated check source for proper operation on each day of use from April 14, 1987 through April 5, 1989. The monitors were checked once per month during this time. On April 4, 1989 the Picker Model 6096A teletherapy source malfunctioned and remained partially exposed for approximately ten minutes. However, the radiation monitor failed to provide visible notice of this malfunction, in that its green lights were lit ("safe condition beam off") instead of its red lights ("unsafe condition - beam on"). The failure to test each radiation monitor with a check source each day prior to use of the teletherapy units on patients and the failure of the radiation monitor to provide visible notice of a partially exposed source constitute violations of 10 CFR 35.615(d)(3) and 10 CFR 35.615(d)(1), respectively.

The licensee's procedures and records for receiving and surveying packages of radioactive material were reviewed and found to be adequate. No packages with unusual radiation levels or significant contamination have been received, according to the nuclear medicine technologist.

The licensee uses a 1.3 curie generator, received weekly, to obtain its technetium-99m. Tests of the licensee's dose calibrator, including accuracy, linearity, and constancy checks, appeared to be adequate. When asked by the inspector, the nuclear medicine technologist (NMT) stated that he tested each eluate for molybdenum-99 contamination and recorded the results. During the inspector's review of the molybdenum-99 test records and procedures, it became apparent that the licensee was not calculating molybdenum-99 concentration correctly. The licensee uses a Squibb CRC-17 radioisotope dose calibrator (Attachment B) whose molybdenum-99 (moly) assay procedure requires that the net moly reading be multiplied by a correction factor (to correct for canister shielding effects) and then divided by the technetium-99m activity to obtain moly-99 concentration. The NMT told the inspectors, when asked, that he had never used the correction factor to correct his moly reading for canister shielding effects. Therefore, his readings from April 14, 1987 through April 5, 1989 were calculated too low by a factor of 3.5. The improper implementation of the moly assay procedure constitutes a violation of 10 CFR 35.204(b) which requires that a licensee that uses molybdenum-99/technetium-99m generators for preparing a technetium-99m radiopharmaceutical measure the molybdenum concentration in each eluate. The inspectors re-calculated one moly issay per month from April 1987 through March 1989 using the 3.5 correction factor and did not find a value higher than the Part 35 limit of 0.15 microcuries moly-99 per millicurie technetium-99m.

The licensee's area survey procedures and records were reviewed for the nuclear medicine program. The licensee appears to be performing its daily surveys, weekly surveys, and weekly wipe tests in accordance with 10 CFR 35.70. The inspector suggested that the licensee take more than just one wipe test sample each week. The licensee agreed to consider this suggestion. The licensee's surveys for patients receiving radiopharmaceutical and brachytherapy treatments were reviewed. As the licensee has cesium-137 tiorapy sources on order and very rarely performs an iridium-192 inplant, the inspectors focussed on radiopharmaceutical therapies. 10 CFR 35.315(a)(4), requires that for each patient receiving radiopharmaceutical therapy and hospitalized for compliance with 35.75, a licensee shall, promptly after administration of the dosage, measure the dose rates in contiguous restricted and unrestricted areas with a radiation measurement instrument to demonstrate compliance with the requirements of 10 CFR 20. However, the licensee failed to perform these required surveys for patients who received radiopharmaceutical thrrapy as follows: 106.8 millicuries on 4/25/87; 211.4 mCi on 5/20/87; 207 mCi on 8/3/87; 313 mCi on 9/21/87; 101.4 mCi on 10/19/87; 263 mCi on 12/21/87. This constitutes a violation of 10 CFR 35.315(a)(4) which requires that for each patient receiving radiopharmaceutical therapy and hospitalized for compliance with 35.75, a licensee shall promptly after administration of the dosage, measure the dose rates in contiguous restricted and unrestricted areas with a radiation measurement instrument to demonstrate compliance with the requirements of 10 CFR 20.

The licensee's facilities were inspected, including the nuclear medicine department, both cobalt-60 teletherapy rooms, areas adjacent to the teletherapy rooms, and the waste storage areas. Security and access control to these facilities appeared to adequately prevent access by unauthorized persons. The hot lab, waste areas, and teletherapy rooms are locked unless in use and the keys are stored remotely. The teletherapy rooms each had viewing windows, television camera viewing systems, door interlocks, door lights indicating beam status, and appropriate emergency response instructions posted at the console area. Door and console interlocks were tested by the inspectors and found to be adequate except for the Picker Model 6096A unit, whose source remained partially open for about ten minutes during the demonstration. The source subsequently retracted and the room was locked. The licensee agreed to not use the Picker unit until it had been repaired and calibrated, as verified in a Confirmatory Action Letter issued by Region III to EFSCC on April 14, 1989 (Attachment C). Postings and labelings required by 10 CFR 19 and 20 were in evidence throughout the facilities and appeared to be adequate. The licensee's handling of recent experiences, if any, with misadministrations, thefts and losses, incidents, notifications, and reports were reviewed and found to be adequate.

During the inspection, it became apparent that the licensee had added a waste storage facility that was not approved in the license. This constitutes a violation of 10 CFR 35.13(e) which requires that a licensee obtain a license amendment before it adds to or changes the areas of use identified in the application or on the license. Application for the 24-00481-05 license dated May 25, 1988 requires that wastes be stored in Room No. 143. However, on March 31, 1989, the licensee began using Room 26 for storage of spent generators and radioactive wastes in addition to Room No. 143, without benefit of an amendment to the license.

The licensee's waste disposal procedures, surveys, and records were reviewed and found to be adequate. Most radwaste consists of spent generators and various dry solids, such as syringes, needles, vials, gloves, and paper contaminated with technetium-99m products. Occasionally, non-byproduct materials are used. Wastes are segregated according to half-life when appropriate and stored until background levels are reached. The licensee then surveys the wastes, defaces labels, and disposes of them as normal trash. Generators are stored for 18 weeks and then returned to the vendor. The iriduim-192 seeds from a rare implant are held for decay or re-used or returned to the vendor. Wastes accumulated from a hospitalized iodine-131 therapy patient are held for decay until they reach background levels and then surveyed and discarded. Liquid wastes are not generated to a significant degree. No radioactivity in effluents is released to unrestricted areas.

During inspection of the teletherapy program, full calibration and monthly spot check procedures and records were reviewed. Full calibrations are performed annually, usually in April, by an authorized teletherapy physicist. The full calibrations reviewed included parameters listed in 10 CFR 35.632 and appeared to be adequate. Spot checks have been performed monthly, as required, and included parameters described in 10 CFR 25.634. American Association of Physicists in Medicine (AAPM) procedures are employed. An output check on the Picker Model 6096A unit in April 1988 measured 35.16 rads per minute, which was within 1% of the calculated exposure. An output check on the Theratron 80 on February 24, 1989 showed 59.58 rads per minute measured versus 59.629 rads per minute calculated, which is within 1% error. The licensee participates in protocol tests through M. D. Anderson Hospital in Houston, an AAPM -Padiological Physics Center, but the RSO could not locate these records during the inspection. No spot checks were performed on either unit during March 1989 due to a temporary vacancy in the teletherapy physicist

position. No patients were treated on either unit during this time. On April 26, 1989, Tom Sullivan, M.S., was authorized by NRC to be the teletherapy physicist.

A written prescription for teletherapy treatment signed by a therapy physician is used. The technologists perform the initial dose calculations on computer and treatment begins. Before the second treatment, Dr. Noonan and/or Mr. White checks these calculations. The chart is then checked weekly until treatment is concluded and a final chart check of treatment parameters, especially given or "delivered" dose is performed. No misadministrations have occurred since the previous inspection April 14, 1987. The inspection and servicing required by 10 CFR 35.647 was last performed on the Theratron 80 March 10, 1988 and on the Picker 6096A in February 1985 by Neutron Products, Inc. When problems occur with the units, the licensee obtains services from authorized persons. No cobalt-60 sources have been transferred since the last inspection.

Independent measurements were performed using an NRC Xetex 305B, S  $^{\prime}\mathrm{N}$  013167 as follows:

- a. Picker 6096A teletherapy unit all areas surrounding the head measured 2 millirem per hour (mR/hr) or less at one meter; during "beam on," adjacent area surveys were 0.1-0.2 (background) except for 1.6 mR/hr at the common wall in the Theratron room and 0.5 mR/hr at the surface of the viewing window near the console.
- b. Theratron 80 teletherapy unit all areas surrounding the head measured 2 mR/hr or less t one meter; during "beam on," adjacent area surveys were are ground except for 0.9 mR/hr at the wall of the adjacent wis room.
- c. Hot lab 0.2 mR/hr at standing distance from generator (shielded) and 0 5 mR/hr at standing distance from shielded waste.
- d. Waste Storage Room No. 26 0.2-0.4 mR/hr at standing distance from spent generators.

Nine violations were identified.

#### Personnel Radiation Exposure Control

a. External Exposures

The licensee provides film badges and thermoluminescent dosimeters (TLDs) to measure rad ation dose to each radiation worker's whole body and extremities (hands). On August 1, 1988, the licensee changed its badge supplier from Landauer to Siemens, both NVLAP accredited vendors. Badges are furnished and processed on a monthly frequency. The RSO reviews reports on receipt and has begun to post them. The inspectors reviewed exposure reports from December 1987 through February 1987. On the nuclear medicine license, the highest annual whole body reading recorded was 660 millirem and the highest

annual extremity dose recorded was 7280 millirem. On the teletherapy licerce, the highest annual whole body dose recorded was 60 millirem, whi may have included radium-226 and/or accelerator exposure. No do exceeding NRC limits were observed.

NRC Form 5 data was complete for all badged individuals except one. Records for a therapy technologist, whose badge incept date was August 1988, did not indicate his social security number and date of birth, which is information required by NRC Form 5 in accordance with 10 CFR 20.401(a). This constitutes a violation of 10 CFR 20.401(a) which requires that each licensee maintain records showing radiation exposures on Form NRC 5 or on clear and legible records containing all the information required by Form NRC 5.

During the inspection, a radiation worker told the inspectors that, on several occasions during the period from April 14, 1987 through late February 1989, he had requested his radiation exposure records. but was not advised of his radiation exposure. The worker indicated that some of his requests had been made at least one year apart. The inspectors reviewed personnel exposure reports for this individual and confirmed that he was badged and received exposures to both his whole body and extremity badges during this time. The individual stated that he had requested these records from the former Radiation Safety Officers, who no longer work for EFSCC. Neither the current RSO nor the Medical Center Director were able to dispute this individual's claim that he had not been provided with his radiation exposure records during the period from April 14, 1987 through late February 1989. This constitutes a violation of 10 CFR 19.13(b) which requires that at the request of any worker each licensee shall advise such worker annually of the worker's exposure to radiation or radioactive material as shown in records maintained by the license pursuant to 20.401(a) and (c).

#### b. Internal Exposures

At EFSCC, internal exposure could occur from the preparation or administration of radioactive indine-131 in therapeutic quantities which would require hospitalization of the patient, i.e., activities of 30 millicuries or more. On six occasions in late 1987, the licensee administered dosages of more than 30 millicuries of encapsulated iodine-131 to patients, but did not perform bioassay measurements on the staff who prepared and administered these dosages to determine whether any accidental uptake had occurred. This constitutes a violation of 10 CFR 35.315(a)(8) which requires that for each patient receiving radiopharmaceutical therapy and hospitalized for compliance with 35.75, a licensee shall measure the thyroid burden of each individual who helped prepare or administer a dosage of iodine-131 within three days after administering the dosage. These dosages of iodine-131 were administered as follows: 106.8 mCi on 4/25/87; 211.4 mCi on 5/20/87; 207 mCi on 8/3/87; 313 mCi on 9/21/87; 101.4 mCi on 10/19/87; 263 mCi on 12/21/87.

Three violations were identified.

#### 7. Exit Interview

An exit interview was held on April 5, 197 with Dr. Vincent, Dr. Soni, and Dr. Noonan. The apparent violations areas of concern, and other recommendations were discussed as well a the NRC policy regarding possible escalated enforcement.

#### 8. Enforcement Conference

An Enforcement Conference was held in the Region III office on April 25, 1989. The licensee was represented by Dr. Vincent and Dr. Noonan of Ellis Fischei State Cuncer Center. The NRC was represented by Mr. A. Bert Davis and others of the Region III staff. The licensee was informed that the violations are being considered in the aggregate for escalated enforcement action. During the meeting, the NRC enforcement policy and the proposed violations and areas of concern were discussed. The licensee presented their conclusions and corrective actions. The licensee acknowledged the proposed violations and concerns and believes that their planned corrective actions will preclude future noncompliance. Mr. Davis requested that the licensee respond to NRC within one week regarding whether they would be retaining an outside consultant's assistance to review their entire radiation safety program. The response should also include a brief description of the RSO's duties to reflect whether she is being allotted sufficient time to devote to the radiation safety program.

#### Attachments:

- A. EFSCC treatment plans
- B. Squibb Moly Check Procedure
- C. CAL to EFSCC dated 4/14/88

1 ATTACHMENT A, PAGE.005 2 APR+20 '89 15:20 FROM OPD CLINIC Weinzeel, Mary **Treatment Planning** 538583 \* ELLIS FISCHUL STATE CANCER CENTER Columbia, Missouri 65203 88-F-0 Nedy: Rt-side, metastatic Ca. lymph nodes. DEFINITIVE O PALLIATION O PREOP O POSTOP O PROPHYLACTIC 1 3 4 Ð 6 dheva Unit Quality 1.25Mr Rt neck Site 1800 Dose 200 Daily Tumor Dose 67 Fractions Duration (wk) 1+ Treatment Days par 5 week (\_, 2, 3, 4, 5) Boost Plan HP=PA. Field Arrangement COMMENTS 5. SAD/SSD 1. Appositional 2. AP-P.A-Rt & La Lat. 8. Three Field 6. Rotation 7. Wedge 8. Tangential 4. Box much Depths O Split Course Simulation O Clinical A Individual Biocking O Cast O Bolus O Contour O Computer Plan O Re-evaluation O Spinal Cord O Rest Weckly CBC Radiation Oncologint August 1500 Date 7-20-88 PAGE 1

ATTACHMENT AZ . . APR 20 '89 15:21 FROM OPD CLINIC PAGE.006 Greer, LovadA **Treatment Planning** 535010 ELLIS FISCHEL STATE CANCER CENTER 42 - F-N Columbia, Missouri 65203 Rf. side locally advanted disease. Breast : Y PALLIATION O PREOP O POSTOP O PROPHYLACTIC O DEFINITIVE 6 6 2 3 4 PickerScoo Unit Quality 25MV Rf .sup sty Rt Everist Bite axilla. 3000 3000 Dose 200 200 Daily Tumor Dose 15 Fractions Duration (wk) 3 3 Treatment Days per 5 5 week (1, 2, 8, 4, 5) Boost Plan APdreer APANECY Field Arrangement COMMENTS 5. SAD/SSD 1. Appositional 2. AP-PA-Rt & Lt Lat. 6. Rotation 3. Three Field 7. Wedge 8. Tangential 4. Box Depths Donax Drock Clinical O Individual Blocking O Cast O Bolus O Contour O Computer Plan O Split Course O Simulation O Rest Be evaluation O Spinal Cord\_ Weeksly dsc. Salt 7-7-81 Date. Radiation Oncologist PAGE 1 \*\* TOTAL PAGE.006 \*\*

施

4

Attachment A3 APR.20 '89 15:18 FROM OPD CLINIC Krest, Geraldine **Treatment Planning** 539228 4 ELLIS FISCHEL STATE CANCER CENTER 45 - F-N Columbia, Missouri 65203 Head and Neels: oval tongue, et side by cell ca. SIP hemistessectory. DEFINITIVE O PALLIATION O PREOP O POSTOP O PROPHYLACTIC Boost б 6 the va thera' theva. Unit 1-25 MY. 1.25MP Quality 1.25 MV Headt Head, 8 Bril Site neels neels SUP el 50 40 4000 1000 Dose 200 200 de 0 Daily Tumor Dose 5 25 xo Fractions Duration (wk) 4 Š Treatment Days per 5 5 week (1, 2, 3, 4, 5) les. NO Boost Plan AP Divect. FERF Field Arrangement mia 5. SADISED John COMMENTS 1. Appositional 2. AP-PA-Rt & Lt Lat. 6. Rotation 82 3. Three Field 7. Wedge 8. Tangential 4. Box mid Depths 3 ans O Cast O Bolus O Contour O Computer Plan O Split Course Individual Blocking Simulation O Clinical O Rest O Re-evaluation O Spinal Cord \_\_\_ Weekly aBC. Jag W Soui 6-27-81 Date Radiation Oncologist. PAGE 1

Attachment Ay

for the second s	HUMA	R	1	BITE		11	Ry	A +1	N	3	67	- H	X.N
• TUMOR DOSE	SSD. SAT ENERGY			OY	1	80		1.25 Mer	1	80	1	1.25 ME	
	FELD	IZE	JAU	SET.	TING		2.5×	9.5	9×10	8	SX	9.5	9×1
	es a series	+ 120		HE	AD		27	1	D		90		0
	GUNTER ANGLE ROTATION				210 0				Prov				
	CODCH ROTATEAN					11	1990/101	1 .1	-	U		1.1	
	BLOCKS COMPENSATOR					Yes.		1.00		15as		IND.	
	NSD (rets)												
	TRUE AREA BOUTV. SQ.												
	WEDGE No. WEDGE FACTOR												
	TAR	-	DEP	THD	OSE				78				78
PROGRESS NOTES	MON	TOR	1	TI	E	1	2.03						2.03
(kgs) Hb/Het WBC PLTS.	1981	DI	SPTH	1		1	Cardenan Contraction	5cm				Scu	
-30-12-5/34.7-73.252,000	1	Tne	TE	DATE	REGN.	MU/	DMAX	TUNOR	and the state of t	MU/	DMAX	NOMUT	
	12		Tal			2000				In Coll	100	10.	
	1	16	10	1	ga_	12.00	128	100		10.02	1000	na	1/ 1001
1- 1340/ 3640 - 5.9 - 323,000	12	16-	251	2	AD.	8.00	129	100		9.03	129	100	4-00
	3	de:	30	3	ap	2.03	129	100		2,05	429	100	600
	4	10 -	11	4	30	2.03	129	100		8:03	129	100	800
and a second					-				stain	day 5	11		
definition of the second s	6	17.	5	8	G	2.03	129	100		2.03	129	100	1000
and the second se	L	7	+6	9	13	12.03	49	100		203	129	100	1200
2.728.2 4 182.44	10	10	-	110	1	103	19 13	100		2.03	120	100	1400
9.9 - 13.2/ 57.3 - 7 4 - 292,000	+ 6	+1-	18	10.	go	03	120	100		503	1.28	Inci	1600
	0	Ti	0	dia	gr-	1.03	107	100		1-03	1000 1	100	1800
	19	17	-11	14	sp-	2.00	1029	100		100	1509	100	1000
	10	2	12	15	199	13.00	129	100		12.00	1239	100	KADO
13-123/36.5- 4-7-294,000	111-	17.	13	16	50	2.03	129	100		R.03	129	100	2200
	12	17.	44	17	a.	2.03	1/29	100		2,03	129	100	2400
	1/2	12.	45	18	40	203	129	100		2.03	09	100	2600
	111	0	10	12/	1 min	503	120	1100	TALES, LANSING THEY BELLEVE	2,03	120	100	3800
	1-17		Y.R.	21	7	200	1 30	18-11		503	120	100	3000
	15	17.	47	plan.	gn.	100	120	Vac		203	107	100	1200
20-12-7/36-3-6-1-281.60	14	17	BR	12.7	92	1.03	larg_	1001		3 85	120	100	adua
/	17	17-	RI	124	p	R.0.7	129	100		1	Kar y	1.00	
	118	2	21	125	50	2.00	129	100		P.00	18.2	100	5600
	19	8	11	35	ga	2.00	129	100		- pole . Q	129	100	13900
	30	8	2	36	1a	12,05	129	100		2.0	3 129	100	4000
P-2 4.5/24.5- 35-139.000	21	8	-3	37	6	12.03	129	100		2.03	129	100	4260
	.7.9	8	4	38	1	2,03	120	100		203	1 id g	100	4400
	2.	0	100	20	1gr	2.13	42.0	100		203	129	100	4600
	1-12	-10	10	410	-gez	00	Ind	Inn		203	120	100	4800
	24	17	0	70	P	00	68 9	100		120	3129	100	5700
	25	8	-19	10	10	price	1dd	1100		- px. 55	210-1	100	10000
			-										
			-										+
	1	-	-		-		1						
		-	1	-	1	-	1						
							1						
A BREAKE STOLEN AND A BREAK \$ 10 YO THE ADDREAM STOLEN AND A	1										1		
		-	1		1								
and the second set of the second s			1	1			1	1					
		-	-	1	1								
		-	-									-	
		-			+								
		-	-										
	1			1	-	_					+		
			-										1
and the second se					1								
No. 1			-	1						1			
					. A second				and the second second	and		and a second second	and the second s

1 A

		Attachment As
, HPR. 20 '89 15:20 FROM OPD CLINIC	1 .1	PAGE.004
3 AP Suprday		
- 80 125mer	ne	
19.5 K 5.7 100K8		
Vec No		
To an and the land when the land and the second sec		
and have been added and the second se	an - free	
87.3	a subser men men men and men	
3.57	Adv	
Ben MUI DANS TUMOR	MU/ DMAX TUMOR	Technical Notes
MUT D MAX DOST TIME D MAA DOST	Time	17/28/88: 242749
1355 329 200 - an of the De		2 note the tak
30 220 200 400		3
1258 200 200 800 VW FIRK		4
A Service and a service of the servi		0
258 220 200 1000		D
3.58 229 200 1200		R
3.58 829 200 1400		9
358 229 200 K.00 V 24 19/21		10 7/100 01-
3.58 229 500 1800	- 1000	11
8.50 2.39 200 2000		12
358 229 200 2300		13
258 239 200 2400 AL		147/P1/22
350328200 0600 10 112		15 destral der
3,20 338 000 1800		16
15 228 200 2000		17
1258 Dav 2100 Bulan		10 7/1/11 14 2
351 220 BAU BOD		120 1001 1000 2
358 2-8 200 3800		21
258 20 100 4000		22 (
350 228 200 4200	a. x x x condi	60-k = \$87/25/87: hetan
9 58 228 200 \$4000 TVSL	And Part and	24 8 1 88 A
8 58 3.28 200 4600 34 95/2		25 00
5 9 228 200 4800		26
20 Xan Scolar 25 41416		100 21 21 88 4
		20 6 1 4 20 6 9 60
		30
		81
1		32
		88
		84
		35
		36
		31
		39
		40
		41
		42
	I we be and a day and	and the second state of th

# **SQUIBB** CRC-17 RADIOISOTOPE DOSE CALIBRATOR Operation Manual



Manufactured for

E. R. Squibb & Sons, Inc. Princeton, New Jersey 08540 by Capintec, Inc. For technical assistance:

ROT X 15 Milletron, Inc., a subsidiary of Capintec, 540 A:pha Drive, Pittsburgh, PA 15238. Telephone: 412-781-5300-

Attachment B,

412 - 963 1988

\* CRC is a registered tradename of Capintec, Inc.

Attachment B2

which is supplied with the instrument. Be sure to place the sample in the center axis of the chamber when measurements are made without the dipper or when measurements of extremely high activity are anticipated.

#### CAUTION

Refer to Sections 3.3 and 3.4 for details concerning accuracy of measurement.

#### 5.3.3 MO ASSAY PROCEDURE

Procedure to assay a low level contamination of Molybdenum Mo 99 in solution of Technetium Tc 99m and the characteristics of the assay canister are described in this section.

#### Description

The Assay Kit consists of a lead canister of the proper dimension to accept a 30 milliliter vial, and an insertion holder. The characteristics of the canister are such that the 99m Tc reading is reduced to less than 10-6 of the unshielded reading while the "Mo reading is reduced by approximately 65%.

The allowable level of 99 Mo contamination in technetium Tc 99m is generally considered to be one part per thousand at the time of injection. The procedure is carried out by simply taking two readings on the day's elution of 99mTc, one shielded and one unshielded. If the shielded reading  $\times 3.5$  (or  $\times 5$ , see procedure 4 below) is not lower than the unshielded reading by a factor of 10', the required purity does not exist.

#### Assay Procedure

1) Push 200µCi Range button.

EXAMPLE

se are no radioisotopes near the cali-Be sur 2) ush OTHER and set the calibration brato knob (al to 030 (or 080).

Since 080 is also the calibration number for 99m Tc, the 99m Tc push button may be selected at this point and left in position for the entire assay procedure.

- 3) Place the Mo Assav Canister gently into the chamber well (without the sample in it). Read and record the background, B.
- Insert the elution vial into the Mo Assay Canister 4) and take reading of Mo component, M.
- Subtract the background from the reading with the sample in the canister, then multiply the number by 3.5 (or multiply the number by 5, if calibration knob is set to 080) to cotain contamination of 99 Mo in the 96 m Tc vial. Activity of "Mo = 3.5 (M-B); @ cal setting 030

or Activity of "Mo = 5.0 (M-B); @ c.al setting 080

Push 99m Tc push button or push OTHER and set 6) the calibration knob dial to 080. Take out the sample vial from the Mo Assay Canister. Select appropriate Activity Range for 99mTc sample. Insert the vial into the ionization chamber well by using the plastic dipper (without any shield around the vial). Record the activity of 99mTc.

The contamination of "Mo in "" Tc must be less than 0.1%. It is considered to be a good practice to work with solutions having less than one part of 99 Mo contamination in 10,000 parts of 99m Tc.

Measurement	Calibration Setting	Meter Reading	Activity		
Background (with the Assay Canister in Well)	0 <u>30</u> (080)	-00.2µCi (-00.1µCi)			
Mo 99 Contamination in Tc 99m (Tc 99m Vial in the Assay Canister)	<u>030</u> (080)	+02.4μCi (+1.7μCi)	2.4 - (-0.2) = 2.6 $2.6\mu\text{Ci} \times 3.5 = 9.1\mu\text{Ci}^{\circ}$ $\begin{pmatrix} 1.7 - (-0.1) = 1.8\\ 1.8\mu\text{Ci} \times 5 = 9.\mu\text{Ci} \end{pmatrix}$		
Tc 99m (No Vial Shield)	080	100.0mCi	100mCi		

Tc 99m Activity 100mCi

\*Leakage radiation from \*\*\*\* Tc is reduced to less than 0.0001% of the original value when the semTc vial is inserted into the Mo Assay Canister. The effect from the leakage radiation on the Mo

assay measurement is up to 0.0005% of the 99mTc activity, e.g., effect from 100mCi 99mTc on the <sup>99</sup>Mo contamination measurement will be less than 0.5µCi.

CONFIRMATORY ACTION LETTER

CAL-RIII-89-011

Attachment C

# APR 1 1 1989

Ellis Fischel State Cancer Center ATTN: Ronald Vincent, M.D. 115 Business Loop, 70 West Columbia, MO 65203 License No. 24-00481-04

Gentlemen:

This refers to the telephone conversation between you and D. J. Sreniawski of this office on April 13, 1989 regarding your Picker 6096A cobalt-60 teletherapy unit which remained partially in the "beam on" position for approximately 10 minutes on April 4, 1989 during our inspection at your facility. The source subsequently retracted into the shielded "beam off" position.

Based on that conversation, it is our understanding that you will not use the Picker 6096A unit for any purpose until you:

- Complete repair efforts on the teletherapy unit. (We understand this repair is being conducted by an appropriately licensed service contractor.)
- Calibrate the unit following repairs in accordance with requirements in 10 CFR 35.632. This calibration will be performed by a physicist qualified in accordance with 10 CFR 35.961, who is also authorized as a teletherapy physicist on your license.
- Notify this office when the teletherapy unit has been repaired and calibrated.

Issuance of this Confirmatory Action Letter does not preclude the issuance of an Order requiring implementation of the above commitments. If your understanding differs from that set forth above, please call this office by telephone (312) 790-5500.

Sincerely,

Original signed by A. Bort Davis

A. Bert Davis Regional Administrator

cc: Denise Noonan, Ph.D. DCD/DCB (RIDS) bac: J. Clifford, EDO J. Lieberman, OE L. Chandler, OGC R. Bernero, NMSS J. Austin, NMSS RIII RILLIC RIII RIII Bim Mallett asev Srenkawski Davis INT CONFIRMATORY ACTION LETTER