

Don K. Schopter Senior Vice President 312-269-6078

> May 14, 1998 Project No. 9583-100

#### Docket No. 50-423

Northeast Nuclear Energy Company Millstone Nuclear Power Station, Unit No. 3 Independent Corrective Action Verification Program


United States Nuclear Regulatory Commission Attention: Document Control Desk Washington, D.C. 20555

I have enclosed the following discrepancy reports (DRs) identified during our review activities for the ICAVP. These DRs are being distributed in accordance with the Communications Protocol, PI-MP3-01.

I have enclosed the following thirty-six (36) DRs for which the NU resolutions have been reviewed and accepted by S&L.

DR No. DR-MP3-0097 DR No. DR-MP3-0242 DR No. DR-MP3-0244 DR No. DR-MP3-0245 DR No. DR-MP3-0287 DR No. DR-MP3-0294 DR No. DR-MP3-0359 DR No. DR-MP3-0367 DR No. DR-MP3-0368 DR No. DR-MP3-0377 DR No. DR-MP3-0489 DR No. DR-MP3-0503 DR No. DR-MP3-0549 DR No. DR-MP3-0553 DR No. DR-MP3-0584 DR No. DR-MP3-0588 DR No. DR-MP3-0632 DR No. DR-MP3-0648 DR No. DR-MP3-0695 DR No. DR-MP3-0826 DR No. DR-MP3-0832 DR No. DR-MP3-0871 DR No. DR-MP3-0925 DR No. DR-MP3-0983 DR No. DR-MP3-1015 DR No. DR-MP3-1018

1) App2



United States Nuclear Regulatory Commission Document Control Desk

· . . .

May 14, 1998 Project No. \$583-100 Page 2

DR No. DR-MP3-1051 DR No. DR-MP3-1068 DR No. DR-MP3-1076 DR No. DR-MP3-1081 DR No. DR MP3-1082 DR No. DR-MP3-1083 DR No. DR-MP3-1084 DR No. DR-MP3-1085 DR No. DR-MP3-1087 DR No. DR-MP3-1094

I have also enclosed one (1) DR for which the NU resolution has been reviewed but not accepted. S&L comments on this resolution has been provided.

DR No. DR-MP3-0667

Please direct any questions to me at (312) 269-6078.

Yours very truly,

D. K. Schopfer SeniorVice President and ICAVP Manager

DKS:spr Enclosures Copies: E. Imbro (1/1) Deputy Director, ICAVP Oversight T. Concannon (1/1) Nuclear Energy Advisory Council J. Fougere (1/1) NU m:\icavpleorr/98/ur0514-a.doc

# ICAVP Discrepancy Report

DR No. DR-MP3-0097

maistone onit 5	Discrepa	ancy Rep	ort		
Review Group: Review Element:		INNAMO VIRABILI ICLAMIN	DR RESOL	UTION ACCEP	TED
	Piping Design			Potential Opera	ability Issue
Discrepancy Type:				O Yes	
System/Process:				No	
NRC Significance level:	4			Date FAXed to M	
				Date Publish	
Discrepancy:	Calculation NP(	F)-X7926 - Pi	pe Supports	and valve	
Description:	In the process of 2, including Calo we noted the fol	f reviewing C culation Chan	alculation 12 ge Notice (0	2179-NP(F)-)	(7926 Rev. through 6
	<ul> <li>(i) CCN #6, dated 9/13/96 revised the piping stress analysis to incorporate containment displacement effects associated with various accident scenarios, as defined by Calculation No. 12179-NS(B)-168, Rev. 1, 'Containment Displacement Profiles'. The NUPIPE piping model has been reanalyzed to address the containment displacement effects. Consequently pipe support loads are revised based on the new analysis. However, no support summary has been provided in the calculation, and there is no indication that the revised support loads have been transmitted to Pipe Support Engineering for evaluation.</li> <li>(ii) CCN #6, dated 9/13/96 references Stress Data Package SDP-QSS Rev. 0, dated 1-14-83. However, CCN #3, dated 9/17/85 already evaluated the impact of revisions 1 through 3 of the Stress Data Package. CCN#6 does not reflect the appropriate revision of the stress data package. The latest revision of the Data Package is Rev. 6.</li> </ul>				
	(iii) CCN #1, dat to time history fo 3QSS*V7 and 30 acceleration valu reported in CCN no justification pr values.	rces exceede 2SS*V3. The es, however, #1 still excee	d allowable calcuation r the reduced d the allowa	s of 3.0 g's for ecomputes n d acceleration able of 3.0 g's	or valves educed n levels 5. There is
		Valid	Invalid	Review	Data
Initiator:	Jain, R. C.	gamma	[7]	Needed	Date 8/29/97
	Neri, Anthony A	B	H	H	9/2/97
	Schopfer, Don K		H		9/8/97
	Singh, Anand K		H	H	9/8/97
Date:					
INVALID:					
Date:	5/12/98	Normal Add Sector (Annual Add Sector (Add Sector (Add Sector (Add Sector (Add Sector (Add Sector (Add Sector (A	A PARTICIPATION AND THE ADDRESS OF THE		NAMEN CONTRACTOR
RESOLUTION:	First Response				

ID: M3-IRF-00483

Printed 5/14/98 9:11:40 AM

# ICAVP Discrepancy Report

#### Disposition:

NU has concluded that Discrepancy Report DR-MP3-0097, Items (ii) and (iii) have identified conditions not previously discovered by NU which require correction. Condition Report (CR) M3-97-3247 was written to provide the necessary corrective actions to resolve these issues. The calculation will be revised to properly address the identified conditions. NU has also concluded that Item (i) does not represent a discrepant condition. CCN Number 6 to Calculation 12179-NP(F)-X7926 Rev. 2 was prepared in accordance with the QSS, RSS and SI stress reconciliation program established in 1996 to address the increased containment ambient temperature affects on those systems. That program was based on a phased approach to calculations. Phase 1 calculations were used as a preliminary design input to allow review and disposition of potential modifications for equipment and pipe support commodities in parallel with the stress analysis calculation preparation. Phase II calculations were prepared as interim documents, usually CCN's, which would document the final design, including the independent review, but which would not include all of the information typically provided in a calculation of record. information which enhances the auditability of the document. Phase III calculations are in process of being prepared and will satisfy the Design Control Manual requirement to be comprehended without an assisted review. The subject CCN 6 is a Phase II calculation which is scheduled to be updated to a Phase III status approximately November 1997. Support load summaries were therefore not included in CCN 6; rather they were provided to the appropriate engineering parties via controlled transmittals. Load summaries will, however, be included in the Phase III calculation. Refer to NU letter CES-96-218 (attached) for details of the phased approach for calculation preparation. Significance level criteria do not apply to item i as this is not a discrepant condition.

As stated in Item ii, Calculation X7926 CCN 6 has an incorrect reference to the QSS-SDP. When the change was issued, QSS-SDP Rev. 4 was the latest issued revision for the Stress Data Package (SDP). Revisions 5 and 6 of the SDP calculation were issued after CCN 6 to the stress calculation, as part of the review and update process for all SDPs, and as stated in pages 3 and 5 of the SDP calculation. This formal process was performed on all QA Category 1 SDPs as a function of the Configuration Management Program (CMP) to re-institute the SDPs as the controlled input for QA Category I stress calculations. As explained in the SDP calculations, before start of the CMP, SDPs were frozen in 1986 and were not kept current. Since the current SDPs were revised as a backfit, the reference to the SDP provided in the associated stress calculations is outdated. This was understood as part of the backfit program and is explained in the current revisions to the SDPs. Therefore, this discrepancy is limited to the referenced calculation, and do not represent a programmatic weakness

With respect to Item iii, the process used for determining acceptable valve accelerations is documented in the project criteria document NETM-49, 'Procedure for

Verification/Resolution of Equipment Nozzle Loads and Valve Accelerations,' which includes instructions for resolving valve accelerations which exceed the 3.0 g threshold requirement. Resolution of valve acceleration acceptability issues was documented in the Valve Acceleration Index controlled by the Mechanical Equipment Group. There was no requirement to update the stress calculation if the valve accelerations were determined to be acceptable. In this case, however, the technical justification contained a mathematics error which invalidates the conclusions. Therefore the discrepancy is valid due to an error in calculating combined accelerations, and not due to a programmatic deficiency.

#### Conclusion:

NU has concluded that Discrepancy Report DR-MP3-0097, Items (ii) and (iii) have identified conditions not previously discovered by NU which require correction. Condition Report (CR) M3-97-3247 was written to provide the necessary corrective actions to resolve these issues. The calculation will be revised to properly address the identified conditions. NU has also concluded that Item (i) does not represent a discrepant condition.

#### Follow Up to First Response

ID: M3-IRF-01125

#### Disposition:

This IRF is a follow-up to IRF-MP3-0483. Condition Report (CR) M3-97-3247 corrective action plan has been approved to ensure that calculation 12179-NS(B)-168 will be revised to correct the deficient conditions. The justifications for the 3QSS\*V3 and V7 valve accelerations will be updated to provide the basis for acceptance. The calculation will be revised to reference the appropriate revision of the Stress Data Package. The disposition of item (i) remains as stated in IRF-MP3-0483.

#### Conclusion:

This IRF is a follow-up to IRF-MP3-0483. Condition Report (CR) M3-97-3247 corrective action plan has been approved to ensure that calculation 12179-NS(B)-168 will be revised to correct the deficient condition. The justifications for the 3QSS\*V3 and V7 valve accelerations will be updated to provide the basis for acceptance. The calculation will be revised to reference the appropriate revision of the Stress Data Package. The disposition of item (i) remains as stated in IRF-MP3-0483.

#### Second Response

ID: M3-IRF-02278

#### Disposition:

NU has concluded that the issues reported in DR-MP3-0097 have identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. This supplement to IRFs-

MP3-0483 and 1125 responds to the issues stated in S&L's request for follow-up.

IRF-MP3-1125 incorrectly referenced calculation 12179-NS(B)-168 rather than calculation 12179-NP(F)-7926. The correct calculation number was entered in CR M3-97-3247. That the calculation was incorrectly identified as a pipe support calculation, rather than a pipe stress calculation, is of no consequence to the processing or disposition of the CR.

NU concurs that the worst case is the Operating Basis Earthquake (OBE) rather than the Safe Shutdown Earthquake (SSE), but the objective of a Reportability Determination is to assess the operability of the component during an accident condition. Since this is a function review, rather than a design basis review, this assessment required the use of SSE.

The Seismic Qualification Report is a vendor package that is not routinely revised to account for minor changes or errors. As stated in the approved corrective action plan for CR M3-97-3247, the justification for the valve accelerations in calculation 12179-NP(F)-X7926 must be updated to provide the basis for their acceptance. Therefore the traceable path to show acceleration acceptability will be accomplished by these corrective actions.

#### Conclusion:

NU has concluded that the issues reported in DR-MP3-0097 have identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. This is a supplement to IRFs-MP3-0483 and 1125. IRF-MP3-1125 incorrectly referenced calculation 12179-NS(B)-168 rather than calculation 12179-NP(F)-7926. CR M3-97-3247 also incorrectly identified calculation 12179- NP(F)-7926 as a pipe support calculation, rather than a pipe stress calculation, but this is of no consequence. NU concurs that the worst case is the OBE rather than the SSE, but the objective of a Reportability Determination is to assess the ability of the component to function during an accident condition, which requires use of the SSE values. The Seismic Qualification Report is a vendor package that is not routinely revised to account for minor changes or errors. As stated in the approved corrective action plan for CR M3-97-3247. the justification for the valve accelerations in calculation 12179-NP(F)-X7926 must be updated to provide the basis for their acceptance. Therefore the traceable path to show acceleration acceptability will be accomplished by these corrective actions.

Previously identified by NU? Resolution Pendin	_	-	No		iscrepant Conditions Solution Unresolve		<ul><li>No</li><li>No</li></ul>
initiator: VT Lead: VT Mgr:	Oison, P.R. Neri, Anthon Schopfer, Do Singh, Anan	y A on K d K	NO	Acceptable	Not Acceptable	Review Needed	Date 5/12/98 5/12/98 5/12/98

SL Comments: First Response

ID: M3-IRF-00483 and follow up M3-IRF-01125

Note: The Following discrepancies required corrective action on the response provided in Response ID: M3-IRF-01125.

1. NU response in M3-IRF-01125 incorrectly identifies calculation 12179-NS(B)-168.

The correct calculation number is 12179-NP(F)-7926 Rev. 2,CCN-6. CR-M3-97-3247 does identify the correct calculation but labels this a pipe support calculation. The subject calculation is a pipe stress calculation.

2. Reportability Evaluation CR No. M3-97-3247 page 1 of 1 SRSS 0f the seismic plus time history accelerations in each of the 3 directions yields 3.85, 2.63, 3.22 (worst case is OBE not SSE) g's in the X, Y and Z directions respectively. SRSS of these 3 components yields a vector accleration of 5.66 (not 5.39) g's versus 5.19 g's allowable. Seismic qualification report D0057-1,3,4 and 5 shows enough margin for valve stresses But the operaror has been qualified only for a 3g acceleration (Seismic qualification envelope B-0037).

We concur with NU that there is no programatic requirement for updating the stress calculation provided that the acceleration levels were determined to be acceptable. However, no tracable path for the resolution is provided in the Seismic Qualification Report, or in the stress calculation.

Second Response

ID: M3-IRF-02278

The corrective action outlined in CR M3-97-3247 to update the affected calculation is acceptable.

Northeast Utilities		AVP		DR No. DR-I	WIP 3-0242
Millstone Unit 3	Discrepar	ncy Repo	ort		
Review Group:	Configuration	alan kanan da kanan kanan kanan kana kana	DR RESOLU	TION ACCEPTI	ED
Review Element:	System Installation		P	otential Operat	ulity leeue
	Electrical Design			) Yes	mity reade
Discrepancy Type:				No No	
System/Process:					
NRC Significance level:	4		Da	ite FAXed to NI	J:
				Date Published	d: 10/30/97
Discrepancy:	Differences in Su	pport Drawin	gs and TSO	2 Data	
Description:	1. Drawing EE-34 for Tray 3T114O. A307-26.				
	2. Several tray su provide for the un standard support support location d 8). Therefore, it TSO2. Example: are shown – TSO (typical situation of	ique identific type and the inewings (EE is not possil for tray 3TX 2 lists the A1	cation of a su specific loca -34-DX Rev. ble to recond 214N, three	apport based ation show 8 and EE-34 ile these sup type "A105"	on on the 4DY Rev. ports with supports
	<ol> <li>F-E-20188 add drawing was not I additional conduit this support) for th</li> <li>Trays 3TX703N Fuel Building. Th</li> </ol>	isted as impa loads (no of ne tray suppo l and 3TX70	acted and no ther conduits ort was made 6N are vertic	are support on any the cal risers loc	the ed from drawing. ated in the
	EE-34 HM, Rev. 3 embedded strut. detail of the draw tray risers.	3. The supp The tray is in	orts are direct	ct attachmen	it angles to the
				Review	
		Valid	Invalid	Needed	Date
	Sarver, T. L.	$\boxtimes$			10/15/97
	Neri, Anthony A				10/15/97
	Schopfer, Don K				10/20/97
IRC Chmn:	Singh, Anand K				10/27/97
Date:					
INVALID:					
Date:	5/13/98				GAMAN DIA CONTRACTOR
	NU has concluded identified a condit requires correctio in NRC letter B16 20 criteria and for concerns and me has been written f RP-4.	tion not prev n. This discr 901 and 170 and to have ets the Unit 3	iously discove epancy mee 010. It has be no operabilit 3 deferral cri	vered by NU ts the criteria een screened y or reportat iteria. CR M	which a specified d per U3 P bility 3-98-0495
	SECOND RESPO	NSE:			

ICAVP	DR No. DR-MP3-0242
Discrepancy Report	
NU has concluded that these issu	represent a discrepant condition. Les are deferrable based on corrective actions in Bin CR M3- post startup. NU considers the b be significance level 4. tion is; ) shows tray support A306-26 at list this support, but lists a ave mark numbers which on of a support based on a ecific location shown on the I-DX Rev. 8 and EE-34DY Rev. to reconcile these supports with 4N, three type "A105" supports supports as -47, -53, 41. ay support A104 however, the ed and no mention of the r conduits are supported from was made on any the drawing. are vertical risers located in the hown on Support Detail Drawing s are direct attachment angles to alled in accordance with the s not list any supports are issues are labeling, TS02 and
<ul> <li>3TC1140 (corrected from 3T1140) Item 2; DCN DM3-S-0195-93 is p adds the support numbers to draw concluded that this issue does not condition. A DCN will be required drawing EE-34DX.</li> <li>Item 3; the problem description of the approval of the conduit attack problem solution approves the attack additional weight of the conduit a increase the adequacy of the sup load. The E&amp;DCR refers to calculand is posted as a CCD to add the drawing EE-34GP, drawings do n concluded that this issue does not condition.</li> <li>Item 4; the original discrepancy d These non Q trays are installed p 34HM thus the adequacy. A DCN unique support numbers on drawi for trays 3TX703N and 3TX706N U3 PI 20 section 1.3.2 e defines t will be completed during the next</li> </ul>	<ul> <li>a) is A306-26.</li> <li>b) is A306-26.</li> <li>b) oosted as a CCD against and wing EE-34DY. NU has at represent a discrepant.</li> <li>b) to add the support numbers to the tray support. The tachment including the nd adds a lateral brace to port because of the additional lation 12179-SEO-BE-52.595 e supports to the support detail of indicate loads. NU has the represent a discrepant will be issued that assigns ing EE-34EV for the supports and in TS02.</li> </ul>
	Discrepancy Report NU has concluded that the new is Report, DR-MP3-0242 does not NU has concluded that these issues overall classification of the DR to The original discrepancy descript 1. Drawing EE-34DT Rev. 7 (C-4 for Tray 3T114O. TSO2 does not A307-26. 2. Several tray supports do not h provide for the unique identificati standard support type and the sp support location drawings (EE-34 8). Therefore, it is not possible TSO2. Example: for tray 3TX214 are shown – TSO2 lists the A105 (typical situation with 34DY). 3. F-E-20188 adds conduits to tra drawing was not listed as impact additional conduit loads (no othe this support) for the tray support 4. Trays 3TX703N and 3TX706N Fuel Building. These trays are sl EE-34 HM, Rev. 3. The supports embedded strut. The tray is instati detail of the drawing. TSO2 does tray risers. Further investigation has determin adequate and that the remaining minor drawing updating as follow item1; TSO2 will be corrected to 3TC1140 (corrected from 3T1140 item 2; DCN DM3-S-0195-93 is p adds the support numbers to draw concluded that this issue does no condition. A DCN will be required drawing EE-34GP, drawings do no concluded that this issue does no condition approves the at additional weight of the conduit at increase the adequacy of the sup load. The E&DCR refers to calcu and is posted as a CCD to add th drawing EE-34GP, drawings do no concluded that this issue does no condition. Item 4; the original discrepancy do These non Q trays are installed p 34HM thus the adequacy. A DCN unique support numbers on drawi for trays 3TX703N and 3TX706N U3 PI 20 section 1.3.2 e defines for

Northeast Utilities Millstone Unit 3	ICA Discrepar	AVP ncy Repo		No. DR-M	AP3-0242
	prior to startup. The prior to startup that plant systems for to basis. NU concludes that accordance with U criteria does not a condition.CR M3-6 The corrective act issues post startup NU considers the	it would inhi safe operati t the assign J3 PI 20 sec pply to the r 98-0495 was ions in Bin 0. overall class	bit operations for ons in accordant ment of priority tion 1.3.2 e.Sig new issue as this s closed to Bin ( CR M3-98-0217	4 is correct nificance le s is not a d CR M3-98- Will correct	g the e design t and in evel liscrepant 0217.
Previously Identified by NU?	Yes No	And interest of the other states in the other	iscrepant Conditio	m? Yes	No
Resolution Pending	PO Yes INO		solution Unresolve	-	<ul><li>No</li></ul>
VT Mgr:	Klaic, N Neri, Anthony A Schopfer, Don K Singh, Anand K 5/13/98	Acceptable	Not Acceptable	Review Needed	Date 5/13/98 5/13/98 5/14/98
SL Comments:	Adequacy of the tr addittional conduit	and tray ris			ne
	SECOND RESPO S & L concurs with provided reference	NU's dispo		the review	v of the

lortheast Utilities	IC.	AVP		DR No. DR	-MP3-0244
Aillstone Unit 3	Discrepa	ncy Repo	ort		
Review Group:	Configuration	EADDAWY INCOMENTS OF LOSS OF	DR RESOL	UTION ACCEPT	ED
Review Element:				Potential Opera	bility lesue
	Electrical Design			O Yes	winty moute
	Installation Requiremen	nts		No No	
System/Process:					
NRC Significance level:	4		D	ate FAXed to N	IU:
				Date Publishe	d: 10/18/97
Discrepancy:	Conduit not supp	orted in acco	rdance with	standards	and the data of the data and the operation of the second second second second second second second second second
Description:	Conduit 3CC4911 junction box) 3HV conduit from the box. This length Drawing BE-52X6	VK*PNLCHL1 junction box exceeds the	1B. The first is approximation allowable 3	support on tately four fee	this at from the
				Review	
		Valid	Invalid	Needed	Date
	Sarver, T. L.				9/30/97
	Neri, Anthony A				10/1/97
	Schopfer, Don K				10/13/97
IRC Chmn:	Singh, Anand K				10/14/97
Date:					
INVALID:					
Date: RESOLUTION:	5/13/58 NU has conclude				
	NU has conclude DR-Mi <sup>3</sup> 3-0244, hi LEVEL 4 conditio meets the criteria has been screene found to have no section 1.3.2.e of The first support from 3HVK <sup>*</sup> PNLC practice of condu seismic qualificat the additional con the support spaci spans. Design do deviation from the was closed to CR issue are included post startup. The	as identified in which requires operability of U3 PI 20 de on conduit 30 CHL1B, which it support at ion concerns induit reaction ng on the con- cumentation e standard in M3-98-0137 d in CR M3-9 re is no affect	a CONFIRM irres correction NRC letter I ment 11 of L reportabilitit ferral criteria CC491PB2 i h deviates fr Millstone Un as a result to the pane nduit is well will be updat stallation de 2. The correct 8-0137 which it on License	ED SIGNIFI on. This disc 316901 and J3 PI-20 crite y concerns a a. s more than for the stand of this devia d is insignific within the all ted to reflect tails. CR M3 ctive actions ch will be cor or Design E	CANCE prepancy 17010. It eria and and meets 3 feet dard s no tion since cant and lowable t this 9-98-2092 for this mpleted Basis.
	NU has conclude DR-MIP3-0244, has LEVEL 4 condition meets the criteria has been screene found to have no section 1.3.2.e of The first support of from 3HVK*PNLC practice of condu- seismic qualification the additional con- the support spacin spans. Design do deviation from the was closed to CR issue are included	as identified in which requires operability of U3 PI 20 de on conduit 30 CHL1B, which it support at ion concerns induit reaction ng on the con- cumentation e standard in M3-98-0137 d in CR M3-9 re is no affect	a CONFIRM irres correction NRC letter I ment 11 of L reportabilitit ferral criteria CC491PB2 i h deviates fr Millstone Un as a result to the pane nduit is well will be updat stallation de 2. The correct 8-0137 which it on License	IED SIGNIFI on. This disc 316901 and J3 PI-20 crite y concerns a a. s more than om the stand it 3. There is of this devia of this devia d is insignific within the all ted to reflect tails. CR M3 ctive actions ch will be cor	CANCE prepancy 17010. It eria and and meets 3 feet dard s no tion since cant and lowable t this 9-98-2092 for this mpleted Basis.
RESOLUTION:	NU has conclude DR-MIP3-0244, ha LEVEL 4 condition meets the criteria has been screene found to have no section 1.3.2.e of The first support of from 3HVK PNLO practice of condu- seismic qualification the additional con- the support spacin spans. Design do deviation from the was closed to CR issue are included post startup. There O Yes (*) No	as identified on which requires a specified in operability of U3 PI 20 de on conduit 30 CHL1B, which it support at ison concerns induit reaction ng on the con- cumentation e standard in M3-98-0137 d in CR M3-9 re is no affect	a CONFIRM irres correcti NRC letter I ment 11 of L r reportabilit ferral criteria CC491PB2 i h deviates fr Millstone Un as a result to the pane nduit is well will be upda stallation de 2. The corre 08-0137 which t on License	IED SIGNIFI on. This disc 316901 and J3 PI-20 critic y concerns a a. s more than for the stand it 3. There is of this devia d is insignific within the all ted to reflect tails. CR M3 ctive actions ch will be cor or Design E dition? Yes	CANCE prepancy 17010. It eria and and meets 3 feet dard s no tion since cant and lowable t this 3-98-2092 for this mpleted asis.
RESOLUTION:	NU has conclude DR-MI <sup>3</sup> 3-0244, has LEVEL 4 condition meets the criteria has been screene found to have no section 1.3.2.e of The first support of from 3HVK "PNLO practice of condu- seismic qualification the additional con- the support spacial spans. Design do deviation from the was closed to CR issue are included post startup. Ther O Yes () No	as identified on which requires a specified in operability of U3 PI 20 de on conduit 30 CHL1B, which it support at ison concerns induit reaction ng on the con- cumentation e standard in M3-98-0137 d in CR M3-9 re is no affect	a CONFIRM irres correcti NRC letter I ment 11 of L r reportabilit ferral criteria CC491PB2 i h deviates fr Millstone Un as a result to the pane nduit is well will be upda stallation de 2. The corre 08-0137 which t on License	IED SIGNIFI on. This disc 316901 and J3 PI-20 critic y concerns a a. s more than for the stand it 3. There is of this devia dis insignific within the all ted to reflect tails. CR M3 ctive actions ch will be cor or Design E dition? Yes olved? Yes	CANCE prepancy 17010. It eria and and meets 3 feet dard s no tion since cant and lowable t this 3-98-2092 for this mpleted asis.
RESOLUTION: Previously Identif* d by NU? Resolution Pending Initiator:	NU has conclude DR-Mi <sup>3</sup> 3-0244, hi LEVEL 4 conditio meets the criteria has been screene found to have no section 1.3.2.e of The first support of from 3HVK "PNLO practice of condu seismic qualificat the additional con the support spacial spans. Design do deviation from the was closed to CR issue are included post startup. Ther Yes No Yes No	as identified on which requires operability of U3 PI 20 de on conduit 30 CHL1B, which it support at ion concerns induit reaction ng on the con- cumentation e standard in M3-98-0137 d in CR M3-9 re is no affect Non Di- Res	a CONFIRM irres correcti NRC letter I ment 11 of L r reportabilit ferral criteria CC491PB2 i h deviates fr Millstone Un as a result to the pane nduit is well will be upda stallation de c. The corre 8-0137 which to n License iscrepant Com	IED SIGNIFI on. This disc 316901 and J3 PI-20 critic y concerns a a. s more than for the stand it 3. There is of this devia dis insignific within the all ted to reflect tails. CR M3 ctive actions ch will be cor or Design E dition? Yes olved? Yes	CANCE prepancy 17010. It eria and and meets 3 feet dard s no tion since cant and lowable t this -98-2092 for this mpleted Basis.
RESOLUTION: Previously identif:* J by NU? Resolution Pending Initiator: VT Lead:	NU has conclude DR-MI <sup>3</sup> 3-0244, ha LEVEL 4 conditio meets the criteria has been screene found to have no section 1.3.2.e of The first support of from 3HVK*PNLC practice of condu seismic qualificat the additional con the support spacial spans. Design do deviation from the was closed to CR issue are included post startup. Ther Ves No No Naic, N Nerl, Anthony A	as identified on which requires operability of U3 PI 20 de on conduit 30 CHL1B, which it support at ion concerns iduit reaction on the con- cumentation e standard in M3-98-0137 d in CR M3-9 re is no affect Non Di Res Acceptable	a CONFIRM irres correcti NRC letter I ment 11 of L r reportabilit ferral criteria CC491PB2 i h deviates fr Millstone Un as a result to the pane nduit is well will be upda stallation de c. The corre 8-0137 which to n License iscrepant Com	IED SIGNIFI on. This disc 316901 and J3 PI-20 critic y concerns a a. s more than for the stand it 3. There is of this devia dis insignific within the all ted to reflect tails. CR M3 ctive actions ch will be cor or Design E dition? Yes olved? Yes	CANCE prepancy 17010. It eria and and meets 3 feet dard s no tion since cant and lowable t this 9-98-2092 for this mpleted Basis. S No S No Date
RESOLUTION: Previously Identified by NU? Resolution Pending Initiator: VT Lead: VT Mgr:	NU has conclude DR-MI <sup>3</sup> 3-0244, ha LEVEL 4 conditio meets the criteria has been screene found to have no section 1.3.2.e of The first support of from 3HVK <sup>*</sup> PNLC practice of condu seismic qualificat the additional con the support spacin spans. Design do deviation from the was closed to CR issue are included post startup. Ther Yes No PC Yes No Klaic, N Neri, Anthony A Schopfer, Don K	as identified on which requires operability of U3 PI 20 de on conduit 30 CHL1B, which it support at ion concerns iduit reaction on the con- cumentation e standard in M3-98-0137 d in CR M3-9 re is no affect Non Di Res Acceptable	a CONFIRM irres correcti NRC letter I ment 11 of L r reportabilit ferral criteria CC491PB2 i h deviates fr Millstone Un as a result to the pane nduit is well will be upda stallation de c. The corre 8-0137 which to n License iscrepant Com	IED SIGNIFI on. This disc 316901 and J3 PI-20 critic y concerns a a. s more than for the stand it 3. There is of this devia dis insignific within the all ted to reflect tails. CR M3 ctive actions ch will be cor or Design E dition? Yes olved? Yes	CANCE prepancy 17010. It eria and and meets 3 feet dard s no tion since cant and lowable t this 3-98-2092 for this mpleted asis. S No S No Date 5/13/98
RESOLUTION: Previously identif: d by NU? Resolution Pending initiator: VT Lead: VT Lead: VT Mgr:	NU has conclude DR-MI <sup>3</sup> 3-0244, ha LEVEL 4 conditio meets the criteria has been screene found to have no section 1.3.2.e of The first support of from 3HVK*PNLC practice of condu seismic qualificat the additional con the support spacial spans. Design do deviation from the was closed to CR issue are included post startup. Ther Ves No No Naic, N Nerl, Anthony A	as identified on which requires operability of U3 PI 20 de on conduit 30 CHL1B, which it support at ion concerns induit reaction ng on the con- cumentation e standard in M3-98-0137 d in CR M3-9 re is no affect Non Di- Res	a CONFIRM irres correcti NRC letter I ment 11 of L r reportabilit ferral criteria CC491PB2 i h deviates fr Millstone Un as a result to the pane nduit is well will be upda stallation de c. The corre 8-0137 which to n License iscrepant Com	IED SIGNIFI on. This disc 316901 and J3 PI-20 critic y concerns a a. s more than for the stand it 3. There is of this devia dis insignific within the all ted to reflect tails. CR M3 ctive actions ch will be cor or Design E dition? Yes olved? Yes	CANCE prepancy 17010. It eria and and meets 3 feet dard s no tion since cant and lowable t this 9-98-2092 for this mpleted Basis. (*) No s (*) No Date 5/13/98 5/13/98

# ICAVP Discrepancy Report

DR No. DR-MP3-0244

verspan is minor when the magnitude of the reaction and other adjacent spans. Therefore, this is not deemed to be a re-start issue.

ortheast Utilities	ICAVP	DR No. DR-MP3-0245		
illstone Unit 3	<b>Discrepancy Rep</b>	ort		
Review Group:	Configuration	DR RESOLUTION ACCEPTED		
Review Element:	System Installation	Potential Operability Issue		
Discipline:	Electrical Design	Potential Operability Issue		
Discrepancy Type:	Installation Implementation	No		
System/Process:	QSS	. 140		
NRC Significance level:	4	Date FAXed to NU:		
		Date Published: 1/18/98		
Discrepancy:	Tray Supports not in accorda			
		omalies were identified during the		
	1. F-E-15019 added a 16 inch extension to the vertical legs of tray support C016A-141 and a dummy horizontal at 15 feet 8 inches on these two extensions. Also added were two sections of PS-204 strut at elevation 15 ft. 8 in. and at 18 ft. 4 in. between C016A-141 and C168A-140. These were identified as PS-203 in the FE, but PS-204 was found to be installed. The PS-204 members are identified as conduit support CB-1122. The FE is not listed as affecting drawing EE-34KW, although it directly does, and no other change document could be located that implemented this modification.			
	a new horizontal member at a supports C058D-070 and C05 34LA, Rev. 5). This is identif There is no specific member no conduit designated 3CX42	ch conduit (3CX420NA) attached to elevation 19 ft. 9 in. between 58-055 (Reference drawing EE- fied on the FE as support CB-1713. called out on support CB-1713 and 20NA is in this location. There is a to a vertical member installed		
	CB-4519. The described sup	e tray support which is identified as port does not exist in the field and reviewed made such modifications.		
	C058D-070 and C058-055 an (Reference drawing EE-34LA bracing was to be installed, th accordance with the design for EE-34JB; but is a single piece	Rev. 5). In all cases where the ne installed bracing is not in or "W" bracing as shown on drawing e of angle iron. No open change this document that were available		
	tray support C068A-124, and 3CK901NE4 is attached. No and conduit 3CX402BD can n	conduit is attached to the support not be identified in this area. This rt CB-4655 for conduit 3CX402BD;		
	onto tray support C068A-133	e welding of two pieces of PS-201 to be used as conduit support CB- ion of the installed support differs		

# ICAVP Discrepancy Report

that addresses this deviation.

DR No. DR-MP3-0245

# 6. N-CS-1395 was written to address the addition of "W" bracing described on F-E-43555 to supports C068A-133 and C077B-134. This bracing is correctly installed on half of the shelves, but on the remainder only a single piece of angle iron has been installed which is not consistent with the design detail for the required bracing. This N-CS is not listed in GRITS as affecting drawing EE-34LC despite the fact that these supports are shown on that drawing and it is expected that this is where the bracing will ultimately be shown. No open document could be identified

7. Conduit 3CK124PB2 is attached to the embedded strut between the seventh and eighth shelves of tray support C077B-134 (Reference drawing EE-34LC, Rev. 4). This type of installation to an embed is customarily (has been done in numerous similar cases previously reviewed) identified and analyzed as part of an FE. No change documents could be identified for this attachment.

8. F-E-43110 was written to add "W" bracing between supports C105A-264 and C105B-280 (reference drawing EE-34LF, Rev.
5) at the sixth and eleventh levels of the C105A support. Based on the field observation the FE is not correct in that the bracing should be at the seventh and twelfth levels.

9. A section of PS-201 was added between C119-177 and C119-178 (Reference Drawing EE-34LG, Rev. 4) for lighting fixtures. These is also a lighting outlet on the bottom member of support C119-177. No open change control documentation reviewed addresses this addition to the supports.

10. F-E-15019 has a direct impact on support C168A-140 which is shown on dwg EE-34LJ, Rev. 7. The FE was to extend the east vertical leg of the support by welding an addition(16 inch piece of strut)onto the existing member. Field observation revealed the east vertical member was not extended by welding but was installed as a longer piece. Further the FE which impact the design of this support shown on the referenced drawing was not posted as an open document on the drawing.

11. Drawing EE-34EF Rev. 9, Section view AA (located @ J-6) refers to drawing EE-34 JU. Drawing cannot be retrieved. Listed as "New" from 1988. Cannot verify bracing for support R294-020.

			Valid	invalid	Needed	Date
	Initiator:	Sarver, T. L.				1/6/98
	VT Lead:	Neri, Anthony A				1/6/98
	VT Mgr:	Schopfer, Don K				1/12/98
	IRC Chmn:	Singh, Anand K				1/14/98
	Date:					
	INVALID:					
No. of the local division of the local divis	Date:	5/12/98	NAME OF CONTRACTORS OF	NATIONAL MAY AN ANY ANY ANY ANY ANY ANY ANY ANY AN	SAMATA BARANG SAMA AND SAMA SAMA SAMA SAMA SAMA SAMA SAMA SAM	anananan en anan en an an an an

Printed 5/14/98 9:13:28 AM

Northeast Utilities	ICAVP	DR No. DR-MP3-024
Millstone Unit 3	Discrepancy Report	
RESOLUTI	NU has concluded that the issues in Report, DR-MP3-0245, have identities SIGNIFICANCE LEVEL 4 condition Items 1 & 10 meet the criteria spect and 17010. It has been screened point Disposition Continuation: criteria and operability or reportability concerns U3 PI-20 deferral criteria. Item # 1. generate an administrative DCN to affected documents EE-34KW and Support Log CB-1122 by supplement the details. Also, the DCN will clarit regarding the PS-204 installed in life administrative paper change only to Documents. The PS-204 member respect to Design Properties and the initiation of a DCN is deferrable as Nuclear Safety, Licensing Design E the safe operation of the Plant. Item will generate an administrative DCM applicable affected document EE-3 Support C168A-140 by supplement extension details. However, the DC installed condition regarding the ve C168A-140 which is a continuous m section with a splice plate. This Itel change only to correctly list Affecte installed configuration is structurally continuous vertical member. The in deferrable as these conditions do nu	fied CONFIRMED is which require correction. ified in NRC letter B16901 ber attachment 11 of U3 PI-20 ind found to have no and meets section 1.3.2.e of BIN CR M3-98-0137 will reference the applicable EE-34LJ and against Conduit inting E&DCR F-E-15019 for ify the as-installed condition eu of PS-203. This Item is an correctly list Affected is equivalent to PS-203 with herefore acceptable. The these conditions do not affect basis, Employee Concerns or # 10. BIN CR M3-98-0137 N in order to reference the 4LJ and against Cable Tray ing E&DCR F-E-15019 for the CN will also clarify the as- rtical leg on the East side of hember in lieu of an added m is an administrative paper d Documents. The as- y adequate since it is a initiation of a DCN is ot affect Nuclear Safety.
	Licensing Design Basis, Employee operation of the Plant.CR M3-98-20 98-0137. The corrective actions for completed post startup. There is no Basis.NU has concluded that items not represent discrepant conditions. clearly indicates on the cover page 1713 was actually deleted. This is of also does not list this support. CSL 29591 which issued the support det this location and field observation in shown on the CSL. The conduit that walked down and found to be labeled correct per the CSL and TSO2.Item provided the level where the installat bracing is required for various Cable E&DCR referenced drawing EE-34J bracing. A search in GRITS against CS-01424 which allows the substitut member for the two flat bar cross br 3CX402BD has been voided and no listed in TSO2. CSL's CB-4654 and this conduit attached. Conduit 3CK	92 was closed to BIN CR M3 CR M3-98-0137 will be affect on License or Design 2, 3, 4, 5, 6, 7, 8, 9, & 11, do Item # 2. E&DCR F-E-16954 that Conduit Support Log CB- consistent with TSO2, which CB-4519 lists E&DCR F-E- ails for conduit 3CX420NA at odicates it is installed as at is attached to CB-4519 was ad 3CX420NA, which is # 3. E&DCR N-CS-01395 ation of horizontal "W" a Tray Supports. The B, Det "W" for the cross at EE-34JB reveals E&DCR N- tion of a single angle racing.Item # 4. Conduit longer exists and is not I CB-4655 no longer show

P

# ICAVP Discrepancy Report

conduit

was deleted. Also, CSL CB-4655, lists F-E-41285 which supplements F-E-39292 for CB-4655 and this E&DCR also does not show 3CX402BD. TSO2 and the two CSL's, CB-4654 and CB-4655 are in agreement.

Item # 5. CSL CB-4762 lists E&DCR N-CS-02592 which modifies the support to show the attachment of a junction box and alters the configuration shown on F-E-40033. Also, a search of GRITS against drawing 25212-34011-CB4672 reveals the latest revision to CSL CB-4672 is Rev. 3 and that DCN DM3-S-0270-92 had been incorporated. Revision 3 is consistent with the As-installed condition observed in the field. Item # 6. A search of GRITS against drawing EE-34LC for outstanding Change Documents reveals that E&DCR N-CS-01395 is properly posted and the E&DCR also lists EE-34LC as an Affected Document. Therefore the documentation is correct. Further, E&DCR N-CS-01395 provided the level where the installation of horizontal "W" bracing is required fc/ various Cable Tray Supports. The E&DCR referenced drawing EE-34JB. Det "W" for the cross bracing. A search in GRITS against EE-34JB reveals that E&DCR N-CS-01424 allows the substitution of a single angle member for the two flat bar cross bracing. Item # 7. Conduit 3CK124PB2 is installed per CSL CB-1593 and attached to the embedded strut per the concrete attachment detail shown BE-52CN. This standard support does not require Engineering approval and therefore no "F-E" type E&DCR was required. Therefore, this is not a discrepant condition and no further action is required. Item # 8. The levels for installation of the "W" bracing for C105A and C105B as given in the E&DCR F-E-43110 are optional. The options are the 6th & 11th levels for C105A or the 7th & 12th level for C105B. Due to an existing conduit and support, the bracing could not be installed, at either support at level 6. The optional level 7 was utilized (i.e. installed at the 7th and 12th levels as described in this Item). Item # 9. The D.C. outlet box was added per DCN DM3-07-0673-97 along with the emergency light fixture. This DCN also updated the Cable and Raceway Program for Tray Support DN-C119-177 to account for the additional weight.Item # 11. A search in GRITS against drawing EE-34EF reveals E&DCR F-E-42385 which provided the details for the bracing of Tray Support R294-020 and the other supports in this area. This E&DCR has been incorporated onto EE-34EF, but there was not adequate space to include the elevation view and connection details on that drawing. At that time a new drawing, EE-34JU was under development and referenced on EE-34EF for the location of Section "A-A". Until EE-34JU is issued, the applicable information can be traced to the Change Documents against the drawing that it is referenced from, in this case EE-34EF. Therefore, the information necessary for verification of the bracing of Tray Support R294-020 is retrievable on E&DCR F-E-42385.

Freviously Identified by NU? () Yes () N	No	Non Discrepant Conditi	on? Yes	No No
Resolution Pending? Yes	No	Resolution Unresolv	ed? Yes	No No
Initiator: Klaic, N		Acceptable Not Acceptable	Review Needed	Date 5/12/98
Printed 5/14/98 9:13:30 AM				Page 4 of 5

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report			DR No. DR-MP3-0245		
VT Lead: VT Mgr:	Neri, Anthony A Schopfer, Don K Singh, Anand K 5/12/98				5/12/98 5/13/98 5/14/98	
SL Comments:	S & L has review and based on the conclusion that th	results of th	at review,	concurs with	the	

Printed 5/14/98 9:13:32 AM

Northeast Utilities Millstone Unit 3	IC/ Discrepa	AVP ncy Repo		DR No. DR-	MP3-0287
Review Group:	System		DR RESOLU	TION ACCEPT	ED
Review Element: Discipline: Discrepancy Type: System/Process: NRC Significance level:	I & C Design Calculation SWP			Potential Operat Yes No ate FAXed to N	U:
				Date Publishe	d: 11/17/97
Discrepancy:	Calculation 3-EN	G-106 data d	discrepancy.		
	instrument chann switches, providir conditioning cond water flow throug Page 6, item 7, "S switches are Seis application per IT However, the rea integrity and circu switches 3SWP*F signals to the con to indicate that the perform a safety be considered, as procedure NEAM 2.3 of this attacher should be include	ag start perm ensers, sign h the conder Seismic Effe mic Categor T Barton Se son for this of it integrity of TS36A & B trol building ere is suffici function. In the recomment 41 titled - S nent the effe	issives to the aling that the nsers. act (SE) state by I and quali- ismic Analys qualification in any. Per P&I are used to p air condition ent service w which case S ded by Attack etpoint Calcu- ect of vibratic	e control buil are is sufficie s that the sta fied for safet is Report R3 is to ensure p Ds EM-133D provide permi ing chiller co vater flow. Ho E component hment 4 of N ulations. Per on (seismic e actual setpo	ding air nt service art/trip y -580A-9. ohysical 0 & 151D issive ondensers ence, they at should IUSCo section offect)
			to and	Review	Data
Initiation	Hindia D	Valid	Invalid	Needed	Date 11/6/97
	Hindia, R.		E E	H	11/6/97
	Neri, Anthony A Schopfer, Don K		Н	H	11/7/97
	Singh, Anand K		H	Ц	11/13/97
Date:	Singer, Antend A		<u>L</u>		
Date:	5/12/98	an a	an a	ANALASASIN SALASAN ANY MANY SALASASI	06/07/00/07/07/07/07/07/07/07/07/07/07/07/
	RESPONSE # 1				

Disposition:

NU has concluded that Discrepancy Report, DR-MP3-0287, does not represent a discrepant condition. This Discrepancy Report identified the following issue. Calculation 3-ENG-106, Rev. 1, "Setpoint Determination for 3SWP\*FIS36A,B; 3SWP-FIS37A,B; and 3SWP-FIS118A,B" states the purpose of the calculation is to calculate instrument channel uncertainty for safety related 3SWP\*FIS36A & B flow switches however Seismic Effect (SE) are not included in the uncertainty determination for these components.

Per P&IDs EM-133D & 151D and the setpoint calculation the function of 3SWP\*FIS36A&E is to provide a start permissive to

# ICAVP Discrepancy Report

the control building air conditioning condenser, A or B respectively when adequate service water flow exists. The low flow trip setpoint has varied from 300 gpm to 200 gpm (363 gpm and 288 gpm including the instrument uncertainty from prior calculations SP-3SWP-17 and 3-ENG-106 Revision 00). In 3-ENG-106, Revision 01, Attachment A1, Carrier Building System and Services evaluated the condenser water low flow setpoint and acknowledged that this low flow trip setpoint will not adversely affect the reliability of the chillers if the chillers refrigerant compressor head pressure is monitored and does not exceed the compressor head pressure specification. Compressor head pressure is monitored by 3HVK\*PS52A, B, High Condenser Pressure Cutout, which is designated as Category I and required for proper operation of the chiller per Material, Equipment, And Parts List Program (MEPL) MP3-CD-1032. Instrument setpoint calculation SP-3HVK-8 establishes this setpoint in accordance with Carrier recommendations. . Furthermore, per MEPL evaluation MP3-CD-1071 the flow indicating switch automatic trip function is not safety-related and that the switch provides circuit continuity in the chiller circuit. Therefore, because this instrument does not perform a safety function seismic effects need not be included in its setpoint and Calculation 3-ENG-106 Revision 01, Section 6.7, Seismic Effect, stated that the seismic uncertainty from the ITT Barton Seismic Analysis Report R3-580A-9 would not to be included in the total probable error (uncertainty) determination. Note: The requirements of NEAM 41 identified in DR MP3-0287 are no longer used for determining instrument uncertainties / setpoints. SP-ST-EE-286, "Standard Specification for Guidelines for Calculating Instrument Uncertainties" provides criteria for uncertainty calculations.

Conclusion:

NU has concluded that Discrepancy Report, DR-MP3-0287, does not represent a discrepant condition. The safety function for 3SWP\*FIS36A,B has been evaluated by the Material, Equipment, And Parts List (MEPL) Program that classifies a components safety related function or augmented quality. It has been determined by MEPL MP3-CD-1071 that the automatic trip function of 3SWP\*FIS36A,B is not safety related therefore, the seismic effect errors are not included in the switch actuation uncertainty calculation.

Significance Level criteria do not apply as this is not considered a discrepant condition.

#### **RESPONSE #2**

#### Disposition:

NU has concluded that the issue reported in Discrepancy Report, DR-MP3-0287, has identified conditions not previously discovered by NU which require correction. Subsequent investigation into this DR has revealed that the chiller low flow trip setpoint is 253.6 gpm per Calculation Change

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Papart	DR No. DR-MP3-0287
Millstone Unit 3	Discrepancy Report	
	<ul> <li>Notice (CCN ) 01 dated November ENG-106 "Setpoint Determination 3SWP37A, B, 3SWP-FIS118A, B," the DR. This CCN referenced calci "MP3 - Service Water System - NF No. IV, Design Basis Summary Re 23, 1997, and 97-002 "Minimum R 3HCQ*ACUS1A/B and 3HVQ*ACL as the basis for revising the instrum referenced calculations established required for HVK heat exchanger p minimum Service Water Flow ava accidents. Calculation 97-041 "MP Determination of Minimum Availab Scenarios and Investigation of SW for Potential Cavitation or Choked minimum available flowrate for the approximately 350 gpm. This flown gpm should be used in the instrum ENG-106 to evaluate the margin b setpoint and the minimum flowrate</li> <li>In addition, Barton has provided a 580A, 581A, 583A Switches for Cla Power Plants" that replaces Seism This revised report identifies the m residual effect on the switch setpoint</li> </ul>	for 3SWP*FIS36A, B, " not 288.8 gpm as stated in ulations 90-069-1065 M3 RC Generic Letter 89-13, Item eport" CCN 06 dated October required Service Water Flow to JS2A/B and 3HVK*CHL 1A/B" ment process setpoint. The d the minimum flowrate performance and not the ilable during the various 23 Service Water System: ble Flows During Accident / Heat Exchanger Return Lines Flow" establishes the e various accidents as being rate and process limit of 200 nent setpoint calculation 3- between the low flow trip e available. revised qualification report R3 st Plan for ITT Barton Models ass 1E Service in Nuclear nic Analysis report R3-580A-9. naximum seismic event,
	Condition Report (CR) M3-98-1884 written to document and provide th to resolve the calculation discrepa	ne necessary corrective actions
	Plan for M3-98-1884 has been app issuance of CCN 02 dated April 9, 106. This CCN revised the calcula qualification report R3-580A-29 se and the minimum available flowrat 041. Applying the total probable er WC to the present low flowrate trip (253.6 gpm) results in a minimum gpm) and a maximum trip point of Whereas, the minimum Service W 29.91 inches (350 gpm) per calcula 8.3 inches (8.3 % of full scale) ma and the minimum operating condit maximum post seismic event, resi scale by three percent. The preser acceptable and does not change th calculation. Therefore, NU consider Level 4 issue.	proved and implemented by 1998, to calculation 3-ENG- tion by using the revised ismic residual value of 5 % te value from calculation 97- mor (TPE) of 5.92 inches of p setpoint of 15.69 inches trip point of 9.77 inches (200 21.61 inches (297.6 gpm). Vater flowrate available is ation 97-041 this equates to rgin petween the trip setpoint ions. This margin exceeds the dual effect of $\pm$ 5 % of full ht low flow trip setpoint is he conclusions of the
	Conclusion:	ended in Discrepancy Report
	NU has concluded that the issue re DR-MP3-0287, has identified cond discovered by NU that require corr	litions not previously

Northeast	Utilities
Millstone L	Jnit 3

98-1884 has been written with its corrective action plan approved and implemented that revised calculation 3-ENG-106 to resolve the calculation discrepancies.

Subsequent investigation into this DR has revealed that the chiller low flow trip setpoint is 253.6 gpm not 288.8 gpm as stated in the DR. It was also, determined that the minimum available flowrate of 297 gpm used in calculation 3-ENG-106 was in error, since the flowrate value used was based on the heat exchanger performance requirements and not on the minimum Service Water flowrate (350 gpm) available during the various accidents. Additionally, Barton has provided a revised qualification report that determines the post seismic event residual effect as having a maximum uncertainty value of  $\pm$  5% of full scale.

Using the minimum Service Water flowrate (350 gpm) available during the various accidents provides a margin between the trip setpoint and the minimum operating conditions of 8.3 inches or 8.3 % of full scale. This margin exceeds the maximum post seismic event, residual effect of  $\pm 5$  % of full scale by three percent. Therefore, the present flow trip setpoint is acceptable and does not change the conclusions of the calculation. Based upon this NU considers this to be a Significance Level 4 issue.

#### ADDENDUM TO RESPONSE # 2

Disposition:

NU has concluded that the issue reported in Discrepancy Report, DR-MP3-0287, has identified conditions not previously discovered by NU which require correction.

MEPL Determination MP3-CD-1071 in section 5.23 states "Flow indicating switches 3SWP\*FIS36A/B sense the flow downstream of the control room air conditioner chillers (3HVK\*CHL1A) and provide an interlock with the air conditioners. On a sensed low flow condition, these flow indicating switches will function to secure the control room air conditioners to prevent damage to the compressor. Although this automatic trip function is not safety-related, the flow indicating switch provides circuit continuity in the chiller circuit. For this reason 3SWP\*FIS36A/B should be Category I."

Although, the MEPL determination had determination has reached the proper conclusion, that the switches are classified as QA Category I, and that the trip function is only for equipment protection, the determination infers that the safety-related functionality is passive by stating that the safety-related function is only to maintain circuit continuity. It had inadvertently omitted that these switches provide a start permissive to the chillers when the Service Water flow is restored during a LOP event which is an active function. Additionally, calculation 3-ENG-106, Revision No. 01, Change No. 02, used this passive functionality statement as the basis for performing an evaluation on the

# ICAVP Discrepancy Report

seismic effect instead of including it in the square-root-sum-ofsquare equation within the instrument uncertainty calculation.

Condition Report (CR) M3-98-1884 dated April 9, 1998, has been revised to document and provide the necessary corrective actions to resolve the MEPL and calculation discrepancies. The corrective actions have been approved for post startup implementation. MEPL Determination MP3-CD-1071 and 3-ENG-106 will be revised to indicate the proper switch functionality and to include the seismic effect term in the uncertainty calculation. Calculation 3-ENG-106 conclusion remains valid since, the 8.3% margin that exists between the trip setpoint and the minimum operating conditions remains unaffected by this omission. This margin exceeds the maximum post seismic event, residual effect of + 5% of full scale by three percent. Therefore, the present flow trip setpoint is acceptable since, the omission did not change the conclusions of the calculation. NU considers these changes to be minor in nature that do not impact the design or licensing basis of any system. Based upon this NU considers overall subject of this DR to be a Significance Level 4 issue.

#### Conclusion:

NU has concluded that the issue reported in Discrepancy Report, DR-MP3-0287, has identified conditions not previously discovered by NU discovered by NU that required correction. Condition Report M3-98-1884 has been revised with its corrective action plan approved to revise MEPL Determination MP3-CD-1071 and calculation 3-ENG-106 to indicate the proper safety-related functionality for flow switches 3SWP\*FIS36A/B.

Calculation 3-ENG-106 conclusion remains valid since, the 8.3% margin that exist between the trip setpoint and the minimum operating conditions remains unaffected by this omission. This margin exceeds the maximum post seismic event, residual effect of + 5% of full scale by three percent. Therefore, the present flow trip setpoint is acceptable since, the omission did not change the conclusions of the calculation. NU considers these changes to be minor in nature that do not impact the design or licensing basis of any system. The corrective actions have been approved for post startup implementation. Based upon this NU considers overall subject of this DR to be a Significance Level 4 issue.

Previously Identified by NU?	0	Yes	۲	No	Non D	iscrepant Conditio	n? Yes	No
Resolution Pending	1?0	Yes	۲	No	Rei	solution Unresolve	d? Yes	No
Initiator: VT Lead: VT Mgr: IRC Chmn: Date:	Neri, Scho Singh	Anthon pfer, Do	on K d K		Acceptable	Not Acceptable	Review Needed	Date 5/12/98 5/12/98 5/12/98

SL Comments: RESPONSE # 1

Per logic diagrams LSK-22-12C, Rev. 11 & LSK-22-12E, Rev. 9 switch 3SWP\*FIS36A(B) stops chiller compressor for 3HVK\*CHL1A(B) if the flow detected is below normal flow. This is in agreement with NU drawing no. 25212-29061, Sh. 15, Rev. E (vendor drawing no. 12179-2176-430-061-015). Per Carrier letter dated May 27, 1988 "Condenser water flow affects the chillers refrigerant compressor head pressure. If head pressure is monitored and does not exceed the refrigerant head pressure specifications, for the chiller in question, the flow rate of condenser water will not adversely affect the reliability of the chiller". This letter is a part of attachment A1. This indicates the effect of the quantitative value of the SW flow is insignificant. However, per NU drawing no. 25212-29061, Sh. 15, Rev. E the switches in question are a part of start-stop circuit for the compressor. Hence, functionally the switches should be considered safety related.

Per page 7 of CCN No 6, dated 10-23-97, to calculation 90-069-1065M3, the minimum flow required for 3HVK\*CHL1A(B) is 297 GPM. Per section 13 of calculation 3-ENG-106, the low flow trip setpoint is 288.8 GPM. This trip setpoint is based on a Total Probable Error (TPE) of +/- 5.92 inches WC and a calculated dP of 9.77 inches WC.

Since the minimum flow requirements and the actual trip setpoint values are close to each other (namely 297 GPM vs. 288.8 GPM), impact of the drift due seismic effect component should be evaluated to verify proper operation of the chiller compressor after a seismic event. From the calculation the drift applied around the analytical limit of 200 GPM would allow the switches 3SWP\*FIS36A and B to function over a range of 126 to 254 GPM. Therefore the instrument uncertainty component around the actual setpoint of 288.8 GPM may trip the chiller compressor when the required minimum flow of 297 GPM exists. This could result in a condition where both trains of the Control Room cooling is rendered inoperable.

In-light of the above discussion it is possible that a seismic event could introduced an error to the loop uncertainty that is not analyzed by calculation 3-ENG-106 this could be detrimental to the chiller performance.

Please note that the significance level of the DR has been upgraded to level 3 based on the results from the most recent revision of calculation 90-069-1065M3. Other setpoints calculated in the setpoint calculation 3-ENG-106 also need to be re-reviewed in this light.

#### **RESPONSE #2**

Based on the writeup in response # 2 and addendum to response # 2 all the concerns identified in the DR have been addressed by CR change forms attached with NU's response. The significance

# ICAVP Discrepancy Report

DR No. DR-MP3-0287

level of the DR has been revised to Level 4.

# ICAVP

#### **Discrepancy Report** DR RESOLUTION ACCEPTED **Review Group: System Review Element: System Design** Potential Operability Issue **Discipline:** Piping Design O Yes **Discrepancy Type:** Calculation No System/Process: SWP NRC Significance level: 4 Date FAXed to NU: Date Published: 10/10/97 Discrepancy: Lack of documentation for qualification of tie rods Description: In the process of reviewing the following documents, (i) Pipe Stress Calculation 12179-NP(B)-X1900 Rev. 3 CCN's 1 to 3 (ii) Pipe Stress Calculation 12179-NP(B)-X53900, Rev. 5 (iii) Pipe Stress Calculation 12179-NP(B)-X53901, Rev. 6, CCN's 1 to 3 we noted the following discrepancy: Background: According to (i): Expansion Joint Data Sheet for Joint Mark No. 3SWP\*E1B, at Nodes 501 - 511, shows the tie rod load for the worst case Thermal condition to be 191,716 lbs. The actual tie rod load should be 19,716 lbs, which is the load at NP 511, the attachment point between the expansion joint and Strainer 3SWP\*STR1B (Inlet). Tie Rod loads for all other load cases correspond to the load at the Strainer inlet NP 511. Discrepancy: The thermal condition load for expansion joint (3SWP\*E1B) tie rods is numerically incorrect. Tie rod loads are documented in pipe stress calculations, but no documentation is provided for the qualification of tie rods for these loads. This is a generic discrepancy applicable to all the cases reviewed where expansion joints with tie rods are used, see for example (i to iii). Review Invalid Date Valid Needed 9/23/97 Initiator: Prakash, A $\boxtimes$ 9/24/97 VT Lead: Neri, Anthony A $\boxtimes$ 10/1/97 VT Mgr: Schopfer, Don K $\boxtimes$ 10/2/97 IRC Chmn: Singh, Anand K Date: INVALID: Date: 5/13/98 **RESOLUTION:** First Response ID: M3-IRF-00841

Printed 5/14/98 9:14:48 AM

Disposition:

Northeast	Utilities
Millstone L	Jnit 3

NU has concluded that Discrepancy Report, DR-MP3-0294, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010. It has been screened per attachment 11 of U3 PI-20 criteria and found to have no operability or reportability concerns and meets section 1.3.2.e of U3 PI 20 deferral criteria. Condition Report M3-98-2026 will be closed out to Bin CR M3-98-0138. The issues identified in DR-MP3-0294 are addressed as follows:

The qualification of all MP3 Tie Rods is found in the attached "Millstone Unit No. 3 Expansion Joint Modeling and Qualification Report" supplied by Stone & Webster and Senior Flexonics. This report is tied to EWR No. M396061. The remaining issue is the correction of the typographical error associated with the tie rod load for the worst case thermal condition for EJ 3SWP\*EJ1B. The load is listed at 191,716 lbs and it should be 19,716 lbs. This is a typo error only. This has no impact on the calculation as the typo error was not carried through any calculation.

Bin CR M3-98-0138 corrective actions will correct calculation 12179-NP(B)-X1900 post startup.

#### Conclusion:

NU has concluded that Discrepancy Report, DR-MP3-0294, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010. It has been screened per attachment 11 of U3 PI-20 criteria and found to have no operability or reportability concerns and meets section 1.3.2.e of U3 PI 20 deferral criteria. Condition Report M3-98-2026 will be closed out to Bin CR M3-98-0138. The issues identified in DR-MP3-0294 are addressed as follows: The qualification of all MP3 Tie Rods is found in the attached "Millstone Unit No. 3 Expansion Joint Modeling and Qualification Report" supplied by Stone & Webster and Senior Flexonics. This report is tied to EWR No. M396061. The remaining issue is the correction of the typographical error associated with the tie rod load for the worst case thermal condition for EJ 3SWP\*EJ1B. The load is listed at 191,716 lbs and it should be 19,716 lbs. This is a typo error only. This has no impact on the calculation as the typo error was not carried through any calculation. Bin CR M3-98-0138 corrective actions will correct calculation 12179-NP(B)-X1900 post startup.

Attachments:

1. Condition Report M3-98-2026 2. Millstone Unit No. 3 Expansion Joint Modeling and Qualification Report

Second Response ID: M3-IRF-02345

# ICAVP Discrepancy Report

#### Disposition:

NU has concluded that issue (i) reported in DR-MP3-0294 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. Correction of this issue will be performed in accordance with the corrective actions outlined in CR M3-98-2026. Condition Report M3-98-2026 will be closed out to Bin CR M3-98-0138. NU has concluded that the new issue reported in DR-MP3-0294 has identified a PREVIOUSLY DISCOVERED condition. Pursuant to a formal teleconference with S&L on 07 May 1998, the following information is provided to address the issue of discovery and incorporation of the recommendations detailed in a letter from Stone & Webster to NU, dated July 14, 1997, on the subject of "Expansion Joint Modeling and Qualification":

Discovery: CR M3-97-0836 was generated on 3/18/97 to address potentially generic deficencies in expansion joint modeling and qualification. As a result of this CR, the letter referenced in issue (ii) was generated.

Incorporation: The incorporation of the comprehensive review of MP3 expansion joints modeling and qualification into the MP3 program has been performed in calculation 97-ENG-01551C3 Rev 0. This calculation is currently in the final review process within S&W and will be transmitted to NU upon completion.

Note: The corrective actions associated with CR M3-97-0836 are scheduled for completion before MP3 Startup.

#### Conclusion:

NU has concluded that issue (i) reported in DR-MP3-0294 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. Correction of this issue will be performed in accordance with the corrective actions outlined in CR M3-98-2026. Condition Report M3-98-2026 will be closed out to Bin CR M3-98-0138.NU has concluded that the new issue reported in DR-MP3-0294 (See Background Section above ) has identified a PREVIOUSLY DISCOVERED condition. Pursuant to formal teleconference with S&L on 07 May 1998, the following information is provided to address the issue of discovery and incorporation of the recommendations detailed in a letter from Stone & Webster to NU, dated July 14, 1997, on the subject of "Expansion Joint Modeling and Qualification": Discovery: CR M3-97-0836 (See Atlached) was generated on 3/18/97 to address potentially generic deficencies in expansion joint modeling and qualification. As a result of this CR, the letter referenced in issue (ii) was generated.

Incorporation: The incorporation of the comprehensive review of MP3 expansion joints modeling and qualification into the MP3 program has been performed in calculation 97-ENG-01551C3 Rev 0. This calculation is currently in the final review process within S&W and will be transmitted to NU upon completion.

Note: The corrective actions associated with CR M3-97-0836

# ICAVP Discrepancy Report

are scheduled for completion before MP3 Startup.

Previously Identified by NU?	0	Yes	۲	No	Non D	iscrepant Conditio	m? Yes	<ul> <li>N</li> </ul>
Resolution Pendin	170	Yes	۲	No	Rea	solution Unresolve	nd? Yes	• N
Initiator: VT Lead: VT Mgr: IRC Chmn: Date: SL Comments:	Neri, Schoj Singh 5 First The (i) (ii) qual	Anthor pfer, D , Anan 5/13/9 t Res DR a typog gene ificati	on K d K 98 ponse addre graph eric is ion.	ssec nical ssue	of lack of c	Not Acceptable	for tie rod	
	Expa Ston to be resp 1997 Qua Data	ansio e & V e atta onse 7, on lificat ibase	n Joi Webs ched is a l the s ion",	nt M ter i with ette ubje and	and Senior I the respon r from Stone ct of "Expa a Millstone	rence to "Millst I Qualification F Flexonics. This ise. What is act e & Webster to insion Joint Mo Unit 3 Tied Ex se for tied expa	Report" sup report was tually attac NU, dated delling and cpansion Jo	pplied by suppose hed to t July 14 bint
	prov com used joints state	ides i puter I histo s. It d	mod prical loes I NU's	nme ellin ly by not p	endations fo g and quali y S&W to m provide the	r future tied expa fication, and de odel and qualif qualification of efore, NU's res	pansion joi escribes the fy tied expanded all MP3 Ti	nt e metho ansion e Rods
	Seco	ond R	espo	nse	:			
	docu	Iment ITIFI	tation ED C	for ON	tie rod qual DITION. Dis	nresolved issue lification - is a f scovery of the lo, and the asso	PREVIOUS condition is	SLY

Northeast Utilities	ICA	AVP		DR No. DR	-MP3-0359
Millstone Unit 3	Discrepar	ncy Rep	ort		
Review Group	: Configuration	Markolds Paragent and America	DR RESOL	UTION ACCEPT	TED
Review Element	: System Installation			Determini Comme	1.1114
Discipline	: Electrical Design			Potential Opera	
Discrepancy Type	Installation Implementati	on		O Yes	
System/Process	SWP			() No	
NRC Significance level	: 4		0	Date FAXed to N	W:
				Date Publishe	ed: 10/30/97
Discrepancy	Installation not ina	ccordance	with design (		
	The following disc		-		
	walkdowns:	repair con	union was ior	entined dunn	19
	<ol> <li>Conduit 3CX00 support ES-2000 a ES-2000 Rev. 2.</li> <li>concrete. Per Sta 4, the maximum a Contrary to this re next support is 5'-4</li> <li>The following mate configuration issued</li> <li>Several of the lo Manholes 3EMH-1 to standing water v as demonstrated b tray.</li> </ol>	as shown o This is a di ndard Supp Illowable sp quirement, 6". erial condit es: wer memb 3A and 13 which has a	n Conduit Su rect attachmo port Detail Dr ban to the net one of the at ion items we ers of the cal B show signit also immerse	pport Log 12 ent support tr rawing BE-52 xt support is s installed sp re noted;thes ble tray supp ficant signs of d the lower of	2179-FSK- ype DC to 2CA, Rev. 5 feet. bans to the se are not ports in of rust due cable tray
	2. Electrical Install				
		nat ducts (c ed until cat ft plugged, each mant	conduit embe ble is pulled a Contrary to hole 3EMH-1	dded in duct and spare du the above th 3A and 13B,	banks) icts and hree elevations
	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be le conduit sleeves in 20' and 21' as shore	hat ducts (c ed until cat ft plugged, each manh wn Drawing	conduit embe ble is pulled a Contrary to hole 3EMH-1 g EE-32L Rev	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a Review	banks) ucts and nree , elevations re not
bilister	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be le conduit sleeves in 20' and 21' as show plugged/sealed.	hat ducts (o ed until cat ft plugged, each mant wn Drawing Valid	conduit embe ble is pulled a Contrary to hole 3EMH-1	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a	banks) ucts and hree elevations ire not Date
	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be le conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L.	nat ducts (c ed until cat ft plugged. each manh wn Drawing Valid	conduit embe ble is pulled a Contrary to hole 3EMH-1 g EE-32L Rev	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a Review	banks) ucts and hree elevations re not Date 10/17/97
VT Lead:	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be lee conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L. Neri, Anthony A	nat ducts (c ed until cat ft plugged. each manh wn Drawing Valid	conduit embe ble is pulled a Contrary to hole 3EMH-1 g EE-32L Rev	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a Review	banks) ucts and nree elevations re not Date 10/17/97 10/17/97
VT Lead: VT Mgr:	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be le conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L. Neri, Anthony A Schopfer, Don K	nat ducts (c ed until cat ft plugged. each manh wn Drawing Valid	conduit embe ble is pulled a Contrary to hole 3EMH-1 g EE-32L Rev	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a Review	banks) ucts and nree elevations re not Date 10/17/97 10/17/97 10/20/97
VT Lead: VT Mg/: IRC Chmn:	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be lee conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L. Neri, Anthony A	nat ducts (o ed until cat ft plugged. each mant wn Drawing Valid	conduit embe ble is pulled a Contrary to hole 3EMH-1 g EE-32L Rev	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a Review	banks) ucts and hree elevations re not Date 10/17/97 10/17/97
VT Leed: VT Mgr: IRC Chmn: Date:	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be le conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L. Neri, Anthony A Schopfer, Don K	nat ducts (c ed until cat ft plugged. each manh wn Drawing Valid	conduit embe ble is pulled a Contrary to hole 3EMH-1 g EE-32L Rev	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a Review	banks) ucts and nree elevations re not Date 10/17/97 10/17/97 10/20/97
VT Leed: VT Mg/: IRC Chmn:	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be le conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L. Neri, Anthony A Schopfer, Don K	nat ducts (c ed until cat ft plugged. each manh wn Drawing Valid	conduit embe ble is pulled a Contrary to hole 3EMH-1 g EE-32L Rev	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a Review	banks) ucts and nree elevations re not Date 10/17/97 10/17/97 10/20/97
VT Leed: VT Mgr: IRC Chmn: Date:	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be lee conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L. Neri, Anthony A Schopfer, Don K Singh, Anand K	nat ducts (c ed until cat ft plugged. each manh wn Drawing Valid	conduit embe ble is pulled a Contrary to hole 3EMH-1 g EE-32L Rev	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) a Review	banks) ucts and nree elevations re not Date 10/17/97 10/17/97 10/20/97
VT Leed: VT Mg7: IRC Chmn: Date: INVALID: Date:	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be lee conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L. Neri, Anthony A Schopfer, Don K Singh, Anand K	Nat ducts (c ed until cat ft plugged. each mant wn Drawing Valid	Invalid	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) an Review Needed	banks) Jicts and hree elevations re not Date 10/17/97 10/27/97 10/27/97
VT Leed: VT Mg7: IRC Chmn: Date: INVALID: Date:	2. Electrical Install 3.1.5.6 indicates the shall remain plugg sleeves shall be lee conduit sleeves in 20' and 21' as show plugged/sealed. Sarver, T. L. Neri, Anthony A Schopfer, Don K Singh, Anand K	that the iss 359 has ide /EL 4 cond is section 1	sues reported entified a CO ition which re riteria specifi en screened have no ope .3.2.e of U3	dded in duct and spare du the above th 3A and 13B, v. 7 (H-10) al Review Needed	banks) icts and hree elevations re not Date 10/17/97 10/20/97 10/27/97 10/27/97 ection. ette: eant 11 of eportability ral criteria.

G

Northeast Utilities Millstone Unit 3	ICA Discrepan	VP Icy Repo		No. DR-N	AP3-0359
	maximum allowab SEO-SE-52.98, Re conduit lengths for location of the inst corrected. These of not have effect pla safety. The correct the issues of the D actions will be per 1. formally docum 2. remove the rust from future rusting 3. and plug open of assignment of prio 20 section 1.3.2 e. as defined in attac corrective actions	ev. 1. This ager than de allation. The discrepancies ant configure ive actions DR post star formed: ent the cond , verify inter conduits as prity 4 is conduits these disc	calculation justif esigned based on the material cond es identified in N ation, operation in Bin CR M3-98 tup. The followin duit over-span, grity, and protect required. NU be rect and in accorrepancies do no if U3 PI 20 and f	fies unsup n the type lition items 13-DRT-00 or personr 8-2239 will ng correction ct tray supp lieves that tradance with t meet the therefore the	ported and swiil be 0359 do hel address ve ports the th U3 PI criteria
Previously Identified by NU?	🔿 Yes 🔘 No		iscrepant Conditio		No No
Resolution Pending	g? Yes No	Re	solution Unresolve	d? Ves	No
VT Mgr:	Klaic, N Neri, Anthony A Schopfer, Don K Singh, Anand K 5/13/98	Acceptable	Not Acceptable	Review Needed	Date 5/13/98 5/14/98 5/14/98
SI. Comments:	S & L concurs with provided reference			the review	v of the

Page 2 of 2

.

Northeast	t Utilities
Millstone	Unit 3

**Review Group: System** DR RESOLUTION ACCEPTED Review Element: System Design Potential Operability issue Discipline: Electrical Design O Yes Discrepancy Type: Component Data No No System/Process: QSS NRC Significance level: 4 Date FAXed to NU: Date Published: 11/2/97 Discrepancy: Design Input Discrepancies Involving Motor Operated Valves 3QSS\*MOV34A and 3QSS\*MOV34B Description: A. Motor Operator Replacements for Valves 3QSS\*MOV34A and 3QSS\*MOV34B Motor operated valves 3QSS\*MOV34A and 3QSS\*MOV34B were changed from the original purchase specification from 0.13 to 0.33 horsepower. Neither Specification 2362.200-164 Add. 1 nor Production Maintenance Management System (PMMS) have been revised to reflect the changes in horsepower, motor torque. full load current, and locked rotor current to valves 3QSS\*MOV34A and 3QSS\*MOV34B. These documents should be revised. The affected voltage and thermal overload sizing Calculation 89-094-120E3 (Rev. 0, CCN 4) has evaluated both horsepower values, therefore the results of the calculation are not affected. B. Reliance Motor Curves for Valves 3QSS\*MOV34A and 3QSS\*MOV34B 1. Full load current can be obtained from the Reliance motor curve sheet (included in the motor operated valve calculations) in three places: the table, the header, and the curve itself. The values from these three places are usually different. In most cases, the motor operated valve Calculation 89-094-120E3 (Rev. 0, CCN 4) states that the full load current is obtained from a walkdown reading of the nameplate, therefore the full load current data shown in the Reliance motor curve sheet is not used. However, for valves 3QSS\*MOV34A and 3QSS\*MOV34B, the thermal overload heater analysis section of the calculation states that the full load current value was obtained from the Reliance motor curve sheet, but no indication is made to whether the table, the header, or the curve itself was used to obtain this value. The different full load current values are: Reliance Motor Curve - curve = 0.73 amperes Reliance Motor Curve - header = 1.0 amperes Reliance Motor Curve - table = 0.7 amperes Value used in the thermal overload relay sizing section of the calculation = 0.73 amperes. The use of 0.7 amperes has no affect on the calculation. The use of 1.0 amperes reduces the actuation time of the thermal

overload relay but the results of the calculation are not changed.

Printed 5/14/98 9:51:06 AM

namely that the thermal overload relay actuates prior to reaching Page 1 of 6

the motor's capability but after the valve actuator motor duty cycle.

Calculation 89-094-120E3 uses different full load current values (0.73 or 1.0 amperes) in the AC Motor Evaluation Checklist, Limitorque EEQ Walkdown Checklist, motor overload test record, and molded case circuit breaker test record sheets. In addition, the full load current values are different between the calculation, vendor Drawings 2362.200-164 -043 (Rev. C) and 2362.200-164-043A (Rev. B) (0.95 amperes) and Plant Design Data System (PDDS) (1.0 amperes). These documents should be revised to reflect the actual full load current.

2. For motor operated valves 3QSS\*MOV34A and 3QSS\*MOV34B, the Reliance motor curve in Calculation 89-094-120E3 (Rev. 0, CCN 4) indicates a locked rotor current value of 5.5 in the header of the curve but a locked rotor current value of 5.25 in the table of the curve. The calculation doesn't address which value is used or why it is used. In addition, Calculation 89-094-120E3 does not match the values shown in vendor Drawings 2362.200-164-043 (Rev. C) and 2362.200-164-043A (Rev. B) (5.0 amperes) and PDDS (5.8 amperes). The actual value of the locked rotor current should be used in these documents.

Calculation 89-094-120E3 used the value of 5.5 amperes in the thermai overload relay sizing and in the overload sections of the calculation. This provides more conservative results than using 5.25 amperes.

C. Motor Ampacities of Valves 3QSS\*MOV34A and 3QSS\*MOV34B

For motor operated valves 3QSS\*MOV34A and 3QSS\*MOV34B, Production Maintenance Management System (PMMS) has three ampacity categories and values for two ampacity attributes:

AFL = 0.39 ALR = 2.6 Amps = 0.13

Comparing the values in PMMS with other documents, "AFL" and "ALR" represent full load and locked rotor current, respectively. It appears that "Amps" represents the old horsepower of 0.13. "Amps" should be revised to reflect the actual motor attribute and value.

D. Stroke Time for Valves 3QSS\*MOV34A and 3QSS\*MOV34B

Motor operated valves 3QSS\*MOV34A and 3QSS\*MOV34B have stroke times which are not consistent between Calculation NM-027 Rev. 2 and either Specification 2362 200-164 Add. 1 or Calculation 89-094-120E3 (Rev. 0, CCN 4). Calculation 89-094-

Northeast Utilities	ICA	VP		DR No. DR	-MP3-0367
Millstone Unit 3	Discrepan	cy Repo	ort		
	120E3 is used to si adequate voltage e time in Calculation stroke time in Calc stroke time in Spec (maximum). The 4 results of the calcu actuate within the c In the thermal over 120E3, it reference stroke time. Calcu Calculation NM-02	exists at the NM-027 is ulation 89-0 cification 23 0 second s lation (i.e., duty cycle o load analys s Calculation lation 89-09	40 seconds 94-120E3 is 92-120E3 is 962.200-164 troke time d the thermal of the valve a sis section of on NM-027 a 94-120E3 ref	minals. The for these vas s 30 seconds Add. 1 is 30 oes not affer overload rel actuator mot f Calculation as the input s ferences Re	e stroke lves. The s and the seconds ct the ay will not or). 89-094- source for vision 1 of
	Revision 2. The la				
		Valid	Invalid	Review	
Initiator:	Kendall, D. J.			Needed	Date 10/15/97
	Neri, Anthony A		Н	Н	10/27/97
	Schopfer, Don K		H	Н	10/28/97
IRC Chmn:	Singh, Anand K				10/30/97
Date:					
INVALID:					
Date:	5/13/98	MANCHA MININA PARADONA	NC: BRANK BOY & REPORT OF CONTRACTOR	MANAGER CONTRACTOR SUCCESSION	PROVINCE AND AND ADDRESS OF
RESOLUTION:	Disposition:				
	NU has concluded in Report, DR-MP3-03 discovered by NU was meets the criteria s has been screened found to have no op section 1.3.2.e of U	867, has ide which requir pecified in per attache perability or	entified a correction NRC letter E ment 11 of L reportability	ndition not p n. This discr 316901 and J3 PI-20 crite y concerns a	reviously repancy 17010. It eria and
	Specification 2362. corrected to reflect load current, locked CR M3-98-2091 wa corrective actions o issues post startup. There is no affect o	the correct I rotor curre s closed to f Bin CR M n License o	horsepower ent and strok Bin CR M3- I3-98-0217 v or Design Ba	r, motor torq ke time. 98-0217. T will correct th asis.	ue, full he nese
	corrected to reflect load current, locked CR M3-98-2091 wa corrective actions o issues post startup. There is no affect o NU has concluded to of Discrepancy Rep previously discover	the correct rotor curre s closed to f Bin CR M n License of hat Items E ort, DR-MF	horsepower ent and strok Bin CR M3- 13-98-0217 v or Design Ba 3 and C and 23-0367 has	r, motor torg te time. 98-0217. The will correct the asis. part of Item identified a	ue, full he hese s A and D condition
	corrected to reflect load current, locked CR M3-98-2091 wa corrective actions o issues post startup. There is no affect o NU has concluded t of Discrepancy Rep	the correct rotor curre s closed to f Bin CR M n License of hat Items E ort, DR-MF ed by NU w ons are bein '004 was in sure proces	horsepower ent and strok Bin CR M3- I3-98-0217 v or Design Ba 3 and C and 23-0367 has which require ng performe itiated by El	r, motor torg e time. 98-0217. The will correct the asis. part of Item identified a es correction d as part of WA M3-953:	ue, full he hese s A and D condition DCR M3- 38. As

Northeast	Utilities
Millstone L	Jnit 3

Electrical Calculation, MOV8910-01542E3, Revision 0. Calculation MOV8910-01542E3 was initiated by DCR M3-97004. The values used for the new calculation are obtained through nameplate (walkdown) data or the motor curves, but the nameplate data takes precedence. The motor curve values are only used if nameplate data is unavailable. 3QSS\*MOV34A/B calculations have been performed using nameplate values. The nameplate FLC for 3QSS\*MOV34A/B is 1.0 amps. The nameplate LRC for 3QSS\*MOV34A/B is 5.5 amps.

The new MOV calculation uses the Reliance motor curves from the superseded calculation. There are differences between header, table and curve values, but per MOV-PI-4, "AC and DC Motor Terminal Voltage Evaluation", and MOV-PI-6, "Thermal Overload Sizing Evaluation", through reference to IEEE Std 1290-1996, the values taken from the vendor curves are always taken from the table.

All MOV modifications are being performed as part of DCR DM3-97004. DCR M3-97004 was initiated by EWA M3-95338. As part of the DCR closure process, PDDS will be updated to reflect correct values.

Discrepancy Report, DR-MP3-0543, has previously identified discrepancies in drawing 2362.200-164-043 Rev. C, and they are being corrected per CR M3-98-0965 (see M3-IRF-00925).

Item C:

All MOV modifications are being performed as part of DCR DM3-97004. DCR M3-97004 was initiated by EWA M3-95338. As part of the DCR closure process, PMMS will be updated to reflect correct values.

#### Item D:

Calculation 89-094-120E3 has been superseded by MOV8910-01542E3 Rev.0, and the new calculation makes no reference to calculation NM-027. Calculation MOV8910-01542E3 was initiated by DCR M3-97004.

NU has concluded that the issue reported in part of Item B of Discrepancy Report, DR-MP3-0367, does not represent a discrepant condition.

#### Item B:

Drawing 2362.200-164-43A does not exist in the drawing system database. It appears that the drawing of intent was 2362.200-164-43 Rev A, but this drawing has been superseded by Revision C.

Conclusion:

NU has concluded that part of Items A and D of Discrepancy Report, DR-MP3-0367, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010. It has been screened per attachment 11 of U3 PI-20 criteria and

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report	DR No. DR-MP3-0367
	found to have no operability or report section 1.3.2.e of U3 PI 20 deferral 2362.200-164 and calculation NM-0 the correct horsepower, motor torque rotor current and stroke time. The M3-98-0217 will correct these issue There is no affect on License or De	criteria. Specification 027 will be corrected to reflect ue, full load current, locked corrective actions of Bin CR as post startup.
	NU haz concluded that Items B and of Discrepancy Report, DR-MP3-03 previously discovered by NU which following items were prediscovered 95338 in response to GL89-10. M3 issues as a result.	367 has identified a condition requires correction. The by the initiation of EWA M3-
	Item A: All MOV modifications are being pe 97004. As part of the DCR closure updated to reflect correct values.	
	Item B : Calculation 89-094-120E3 has been Electrical Calculation, MOV8910-0 Calculation MOV8910-01542E3 wa 97004. The nameplate FLC for 30 The nameplate LRC for 30SS*MO values are used in the new calculat	1542E3, Revision 0. Is initiated by DCR M3- QSS*MOV34A/B is 1.0 amps. V34A/B is 5.5 amps. These
	The new MOV calculation uses the the superseded calculation. There a header, table and curve values, but Std 1290-1996, the values taken fro always taken from the table.	are differences between t through reference to IEEE
	All MOV modifications are being pe 97004. As part of the DCR closure updated to reflect correct values.	
	Discrepancy Report, DR-MP3-0543 discrepancies in drawing 2362.200 being corrected per CR M3-98-096	164-043 Rev. C, and they an
	Item C: All MOV modifications are being pe 97004. As part of the DCR Josure updated to reflect correct values.	
	Item D: Calculation 89-094-120E3 has been 01542E3 Rev.0, and the new calcu calculation NM-027.	
	NU has concluded that the issue re Discrepancy Report, DR-MP3-0367 discrepant condition.	

Northeast Utilities		CAVP		No. DR-N	1P3-0367		
Aillstone Unit 3	Discrepancy Report						
	Item B: Drawing 2362.200-164-43A does not exist in the drawing system database. It appears that the drawing of intent was 2362.200- 164-43 Rev A, but this drawing has been superseded by Revision C.						
Previously Identified by NU?	O Yes 🔘 M	Non D	Discrepant Condition? Yes		No No		
Resolution Pendin	g?) Yes 🔘 M	lo Res	olution Unresolve	d?O Yes	No		
VT Lead: VT Mgr:	Kendali, D. J. Neri, Anthony A Schopfer, Don K Singh, Anand K 5/13/98	Acceptable	Not Acceptable	Review Needed	Date 5/13/98 5/13/98 5/14/98		
SL Comments:	Discrepancies c Specification 23 Items A and D: NU agrees that is and will revise the Vendor Drawing Sargent & Lundy transmitted on a valid as it is an o Drawing 2362.20 Discrepancies c	62.200-164, a these are prev hese documer 2362.200-164 y concurs with in aperture cal butdated versi 00-164-043.	nd Calculation viously undiscov nts. 4-043A listed in NU that this dr nd by NU to Sar on (i.e., Revisio MS, PDDS, and	NM-027 list vered discre ltems B.1 awing, whic gent & Lun on B) of val	ted in epancies & B.2: ch was dy, is not id Vendor		
	120E3 listed in I NU's response s calculation in qu previously disco Calculation MOV 094-120E3). Sa 01542E3 adequa DR, however, th which is after the systems, therefor M3-95338 was w not address the makes a genera modifications ne	tates that the lestion (89-09- vered by NU ( /8910-01542E ingent & Lundy ately addresse is calculation e cutoff date of ore, these are written prior to specific discre- I statement th	discrepancies in 4-120E3), PDD3 (reference EWA 23 which supers 7 concurs that C es the discrepant was prepared on 16 May 27, 1997 still discrepant the cutoff date, epancies listed in at the motor op	S, and PMM A M3-95338 edes Calcu Calculation ncies listed in January for Wave conditions however, n this DR b erated valv	MS were and ulation 89- MOV8910 in this 9, 1998, 1 . EWA it does but only		

ICAVP DR No. DR-MP3-0368 Northeast Utilities Millstone Unit 3 **Discrepancy Report Review Group:** System DR RESOLUTION ACCEPTED **Review Element: System Design** Potential Operability Issue **Discipline:** Electrical Design O Yes Discrepancy Type: Component Data No No System/Process: RSS NRC Significance level: 4 Date FAXed to NU: Date Published: 11/2/97 Discrepancy: Motor Curve Discrepancies of RSS Motor Operated Valves Description: 1. For motor operated valves 3RSS\*MOV23A, 3RSS\*MOV23B. 3RSS\*MOV23C, and 3RSS\*MOV23D, the Reliance motor curve in the Calculation 89-094-120E3 (Rev. 0, CCN 4) shows a locked rotor current value of 3.5 amperes in the header of the curve and 3.15 amperes in the table of the curve. The value of 3.15 amperes is used in the calculations. The locked rotor current shown in Calculation 89-094-120E3 does not match the values shown in vendor Drawings 2362,200-164-043 (Rev. C) and 2362.200-164-043A (Rev. B) (5.0 amperes), Specification 2362.200-164 Add. 1 (2.6 amperes), and PDDS (2.6 amperes). These documents should be revised to reflect the actual motor data. 2. For each motor operated valve, the header on the Reliance motor curve refers to the insulation as "B" which does not agree with the purchase specifications which require an insulation rating of radiation resistant Class H. 3. In Calculation 89-094-120E3 (Rev. 0, CCN 4), the locked rotor current for valves 3RSS\*MOV20A, 3RSS\*MOV20B, 3RSS\*MOV20C, and 3RSS\*MOV20D varies between 5.25 amperes as shown in the table on the Reliance motor curve M2734 (dated 7/25/77) and 5.5 amperes which is shown on the undervoltage analysis, thermal overload heater analysis, AC motor evaluation checklist, and thermal overload relay checklist of the calculation. However, Calculation 89-094-120E3 only uses the 5.5 ampere value throughout its analyses (i.e., is consistent). This value results in a more conservative but acceptable voltage drop than when using 5.25 amperes. The use of either value meets the requirement that the thermal overload relay actuate before reaching the motor capability. 4. In Calculation 89-094-120E3 (Rev. 0, CCN 4) for valves 3RSS\*MOV20A, 3RSS\*MOV20B, 3RSS\*MOV20C, and 3RSS\*MOV20D, the Reliance motor curve shows a horsepower rating of 33 and the Limitorgue EEQ Walkdown Checklist, motor overload test record, and molded case circuit breaker test record sheets of Calculation 89-094-120E3 show a horsepower of 0.125 which does not match the value of 0.33 horsepower used in the undervoltage and thermal overload heater analysis of the calculation. These documents should be revised to reflect the actual motor horsepower. 5. Full load current can be obtained from the Reliance motor curve sheet (included in the motor operated valve calculations) in three places: the table, the header, and the curve itself. The values from these three places are usually different. In most Page 1 of 7

Northeast Utilities	ICAVP	DR No. DR-MP3-0366
Millstone Unit 3	Discrepancy Report	
	cases, the motor operated valve ca load current is obtained from a walk nameplate, therefore the full load cu Reliance motor curve sheet is not u 3RSS*MOV38A, 3RSS*MOV38B, 3 3RSS*MV8£38B the calculations st value was obtained from the Relian indication is made to whether the ta itself was used to obtain this value. current values are shown below for	kdown reading of the urrent data shown in the used. However, for valves URSS*MV8838A, and ate that the full load current ice motor curve sheet, but no uble, the header, or the curve The different full load
	Valves 3RSS*MOV38A and 3RSS Reliance Motor Curve - curve = 2.1 Reliance Motor Curve - header = 2 Reliance Motor Curve - table = 2.1 Value used in Calculation 89-094-1 amperes (If 2.3 amperes is used in the calcul relay actuation time decreases but it to actuate after the 40 second valve before the motor capacity which is 7	MOV38B: 1 amperes 23 amperes amperes 17E3 (Rev. 0, CCN 2) = 2.1 Ilation, the thermal overload it still meets the requirement a ctuator motor duty time bu
	Valves 3RSS*MV8838A and 3RSS Reliance Motor Curve - curve = 4.5 Reliance Motor Curve - header = 5 Reliance Motor Curve - table = 4.7 Value used in Calculation 89-094-1 amperes (If 4.7 or 5.2 amperes is used in the unchanged.)	5 amperes .2 amperes amperes 12E3 (Rev. 0, CCN 2) = 4.5
	The valves listed below show different motor curve header, table, and curve the full load current value used in C (Rev. 0, CCN 2) and Calculation 89- was obtained from the nameplate (i. full load current data was not used in Valves 3RSS*MV8837A and 3RSS Reliance Motor Curve - curve = 4.5 Reliance Motor Curve - header = 5. Reliance Motor Curve - header = 5. Reliance Motor Curve - table = 4.7 Value used in Calculation 89-094-3 (If 4.7 or 5.2 amperes is used in the	<ul> <li>re full load current values, bu alculations 89-094-332E3</li> <li>-094-120E3 (Rev. 0, CCN 4)</li> <li>.e., the Reliance motor curve n the calculations).</li> <li>*MV8837B:</li> <li>i amperes</li> <li>.2 amperes</li> <li>amperes</li> <li>32E3 = 4.5 amperes</li> </ul>
	<ul> <li>Valves 3RSS*MOV20A, 3RSS*MO</li> <li>3RSS*MOV20D:</li> <li>Reliance Motor Curve - curve = 0.7</li> <li>Reliance Motor Curve - header = 0.</li> <li>Reliance Motor Curve - table = 0.7</li> <li>Value used in Calculation 89-094-1:</li> <li>(if 0.7 amperes is used in the calcul unchanged.)</li> </ul>	V20B, 3RSS*MOV20C, & 5 amperes 75 amperes amperes 20E3 = 0.75 amperes

Northeast Utilities	IC	AVP	1	DR No. DR	MP3-0368
Millstone Unit 3	Discrepa	ncy Repo	ort		
	Valves 3RSS*M0 3RSS*MOV23D: Reliance Motor 0 Reliance Motor 0 Value used in Ca (If 0.6 or 0.55 an overload relay ac requirement to ac duty time but befor seconds.)	Curve - curve Curve - heade Curve - table alculation 89- hperes is use tuation time of cuate after the	= 0.6 amper er = 0.6 amper = 0.55 amper 094-120E3 = d in the calculation decreases but the 60 second	res res 0.39 ampe ulation, the t it it still mee valve actua	res hermal its the ator motor
	For valves 3RSS and 3RSS*MOV2 uses different full thermal overload Checklist, Limitor test record, and r than shown on th load current value Drawings 2362.20 (Rev. B) (0.95 an documents should	20D, Calculat load current heater analy que EEQ Wa nolded case e Reliance m es are differe 00-164-043 (In peres) and F	ion 89-094-1 values (0.39 sis, AC Moto alkdown Che circuit breake otor curve. nt between t Rev. C) and PMMS (0.39	20E3 (Rev. and 39) in or Evaluation cklist, motor er test recom In addition, he calculatio 2362.200-10 amperes).	0, CCN 4) the r overload d sheets the full on , vendor 54-043A These
		Valid	Invalid	Review	Date
Initiator:	Kendall, D. J.				10/17/97
	Neri, Anthony A			Н	10/27/97
	Schopfer, Don K		H	H	10/28/97
	Singh, Anand K				10/30/97
Date:					
INVALID:					
Date:	5/13/98		NIN THE AVERNMENT AND AND AND A	Andreamer or an Anna for Malerice	E-NAME TARAPAGNA AND A DATA AND A
RESOLUTION:					
	NU has conclude MP3-0368, has in by NU which requ criteria specified screened per atta have no operabili 1.3.2.e of U3 PI 2 Specification 236	dentified a co- lires correction in NRC letter in NRC letter in the chinement 11 of ty or reportation 20 deferral chine 2.200-164 Ad	ndition not p on. This disc B16901 and f U3 PI-20 cr bility concern iteria. dd. 1, lists th	reviously dis repancy me I 17010. It h riteria and fo is and meet e LRC for	scovered ets the as been bung to s section
	3RSS*MOV23A-I closed to Bin CR discrepancy post There is no affect	M3-98-0138 startup.	which will co	prrect the sp	
		d that nort of	Home 1 and	5 and all of	itome 3

NU has concluded that part of items 1 and 5 and all of items 3 and 4 of Discrepancy Report, DR-MP3-0368, has identified a condition previoulsy discovered by NU which requires correction.

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report	DR No. DR-MP3-0368
	Several items are redundant through beforehand. First, all calculations within this Di- superseded by MOV Electrical Cal- Revision 0. Second, the values us obtained through nameplate (walkd curves, but the nameplate data tak calculation uses the Reliance moto calculation. There are differences for curve values, but per MOV-PI-4, "/ Voltage Evaluation", and MOV-PI-4 Evaluation", through reference to 1 values taken from the vendor curv table. The motor curve table value data is unavailable. Third, DCR M3 all changes required for the implem (MOV) program. Any changes listed this DCR. DCR M3-97004 was init (attached).	screpancy Report have been culation, MOV8910-01542E3, sed for the new calculation are down) data or the motor tes precedence. The new MOV or curves from the superseded between header, table and AC and DC Motor Terminal 6, "Thermal Overload Sizing EEE Std 1290-1996, the es are always taken from the es are only used if nameplate 3-97004 was written to cover mentation of the GL89-10 ed as awaiting closeout are for
	Item 1: The motor curve locked rotor curre D is 3.15 amps. The inconsistency previously identified discrepancy, 0965 was written to correct drawing discrepancies. PDDS will be correct close-out.	within the drawing is a DR-MP3-0543. CR M3-98- g 2362.200-164-43
	Item 3: The nameplate locked rotor curren is 5.5 amps. This value is used in a calculation. The calculation was in	all phases of the new
	Item 4: The nameplate rating for 3RSS*Movel value is used in all phases of the name calculation was initiated by DCR Movel value by DCR Movel valu	OV20A-D is .33 Hp. This new calculation. The
	Item 5: The nameplate ratings for 3RSS*M and 12.0 amps LRC. The values of for 3RSS*MV8838A are 4.0 amps LRC (nameplate). The values of ff 3RSS*MV8838B are 4.0 amps FLC LRC (curve). The FLC for 3RSS*M the LRC is 25.3 amps. The namep 3RSS*MOV20A-D is .75 amps. Th 3RSS*MOV23A-D is .39 amps. All throughout the new calculation. The last section of item #5 is incor earlier. It appears as though the v 3RSS*MOV23A-D. Another section for 3RSS*MOV20A-D from calcula	of full and locked rotor current FLC (curve) and 25.5 amps ull and locked rotor current for C (nameplate) and 25.3 amps MV8837A/B is 4.0 amps and plate FLC value for the nameplate FLC value for II values are used consistently insistent with data presented valves of intention should be on of item 5 had listed the FLC

amps and 3RSS\*MOV23A-D as .39 amps. The nameplate FLC value for 3RSS\*MOV23A-D is .39 amps. Therefore, PMMS is

----

correct, but the drawings should be revised. The inconsistency Page 4 of 7

DONIS DO MOS COCO

# ICAVP Discrepancy Report

DR No. DR-MP3-0368

within the drawing is a previously identified discrepancy, DR-MP3-0543. CR M3-98-0965 was written to correct drawing 2362.200-164-43 discrepancies. If the valves of intention are 3RSS\*MOV20A-D, the nameplate FLC value is .75 amps. The vendor drawing will be corrected per CR M3-98-0965, and PMMS will be updated during the closure of the DCR M3-97004.

NU has concluded that the issue reported in part of items 1 and 5 and all of item 2 of Discrepancy Report, DR-MP3-0368, does not represent a discrepant condition.

### Item 1 and Item 5:

Discrepancies were noted on drawing 2362.200-164-043A. This drawing could not be located and does not exist within the drawing system database. It appears that the drawing of intent was 2362.200-164-43 Rev A, but this drawing has been superseded by Revision C.

### Item 2:

Only ~18% of all motor operated valves have an insulation rating of Class B. All other valves have an insulation rating of Class H. To compensate for the motor operators with a Class B rating, all calculations are performed with a 78 °C cutoff. Thus, all calculations are conservative. As the motor operators require replacement, they are replaced with Class H operators. All RSS valves are insulation class H.

### Conclusion:

NU has concluded that part of item 1 of Discrepancy Report, DR-MP3-0368, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010. It has been screened per attachment 11 of U3 PI-20 criteria and found to have no operability or reportability concerns and meets section 1.3.2.e of U3 PI 20 deferral criteria. Specification 2362.200-164 Add. 1, lists the LRC for 3RSS\*MOV23A-D as 2.6 amps. CR M3-98-2026 has been closed to Bin CR M3-98-0138 which will correct the specification discrepancy post startup. There is no affect on License or Design Basis.

NU has concluded that part of items 1 and 5 and all of items 3 and 4 of Discrepancy Report, DR-MP3-0368, has identified a condition previoulsy discovered by NU which requires correction.

### Item 1:

The motor curve locked rotor current, LRC, for 3RSS\*MOV23A-D is 3.15 amps. This value is used in all phases of the new calculation.

The inconsistency within the drawing is a previously identified discrepancy, DR-MP3-0543. CR M3-98-0965 was written to correct drawing 2362.200-164-43 discrepancies. PDDS will be corrected per DCR procedure upon close-out.

Item 3:

The nameplate locked rotor current, LRC, for 3RSS\*MOV20A-D

Page 5 of 7

	10	CAVP	DR	No. DR-	MP3-0368
Milistone Unit 3	Discrepa	ancy Repo	ort		
an channa a' faoinn an rumacha channa fao an a' faoinn dhan a' faoinn a channa a' faoinn a' faoinn a' faoinn a	is 5.5 amps. Thi	is value is use	d in all phases	of the new	NEW RESI OF CONTRACTOR OF CONTRACTOR
	calculation.				
	Item 4:				
	The nameplate value is used in Item 5:				This
	The nameplate and 12.0 amps for 3RSS*MV88 LRC (nameplate 3RSS*MV88388 LRC (curve). T the LRC is 25.3 3RSS*MOV20A 3RSS*MOV20A 3RSS*MOV23A throughout the r The vendor drate and PMMS will 97004. NU has conclud and all of item 2 represent a disc	LRC. The values 338A are 4.0 a e). The values B are 4.0 amp the FLC for 3R amps. The n A-D is .75 amp A-D is .39 amp new calculatio wing will still b be updated du	lues of full and I imps FLC (curve s of full and loci s FLC (namepla SS*MV8837A/F ameplate FLC v is. The nameplate s. All values ar in. be corrected per uring the closure sue reported in p icy Report, DR-	ocked roto e) and 25.5 ked rotor c ate) and 25 3 is 4.0 am value for ate FLC va e used cor CR M3-98 e of the DC	ar current 5 amps urrent for 5.3 amps aps and alue for hsistently 8-0965, CR M3-
	Discrepancies w drawing could n drawing system item 2: Only ~18% of a of Class B. All H. All RSS value	ot be located database. Il motor opera other valves h	and does not ex ated valves have have an insulation	kist within t e an insula	tion rating
Previously Identified by NU?	🔿 Yes 🔘 I	No Non D	iscrepant Conditio	m? Yes	No No
Resolution Pendin	g? Yes 💿 I	No Re	solution Unresolve	d? Yes	No No
				Review	
	Kendall, D. J.	Acceptable	Not Acceptable	Needed	Date
Initiator:	Neri, Anthony A				5/13/98
					5/13/98
VT Lead:					FIA AIDO
VT Lead: VT Mgr:	Schopfer, Don K Singh, Anand K		B		5/14/98
VT Lead: VT Mgr: IRC Chmn:	Schopfer, Don K Singh, Anand K				5/14/98
VT Lead: VT Mgr: IRC Chmn: Date:	Schopfer, Don K Singh, Anand K 5/13/98 Discrepancies c		ecification 2362	.200-164	
VT Lead: VT Mgr: IRC Chmn: Date:	Schopfer, Don K Singh, Anand K 5/13/98	concerning Spotting this is a previo			isted in

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report	DR No. DR-MP3-0368
	01542E3 (and were included in supe 112E3, 89-094-117E3, 89-094-120E3 legitimate design data, do not need t added to the calculation which addre & Lundy recommends that NU addre Calculation MOV8910-01542E3 for c	3, and 89-094-332E3) as o be corrected (or a note sses this error), and Sargent ss this in a future revision to
	Vendor Drawing 2362.200-164-043A Sargent & Lundy concurs with NU the transmitted on an aperture card by N valid as it is an outdated version (i.e. Drawing 2362.200-164-043.	at this drawing, which was IU to Sargent & Lundy, is not
	Discrepancies concerning Vendor Dr PMMS, PDDS, and Calculations 89- 89-094-120E3, and 89-094-332E3 lis NU's response states that the discrep documents were previously discover M3-95338 and Calculation MOV8910 Calculations 89-094-112E3, 89-094- 89-094-332E3). Sargent & Lundy co MOV8910-01542E3 adequately addr listed in this DR, however, this calcul January 9, 1998, which is after the co for Wave 1 systems, therefore, these conditions . EWA M3-95338 was wri however, it does not address the spe this DR but only makes a general sta operated valve modifications need to	094-112E3, 89-094-117E3, ated in Items 1, 3, 4, and 5: bancies identified on these ed by NU (reference EWA 0-01542E3 which supersedes 117E3, 89-094-120E3, and incurs that Calculation resses the discrepancies lation was prepared on utoff date of May 27, 1997, e are still discrepant itten prior to the cutoff date, icific discrepancies listed in itement that the motor

ð

# ICAVP Discrepancy Report

DR	No.	DR-	MP	3-0	377
2012	1801	PL 1 2		v v	

Discrepancy Repor

	Review Group:	System	DRF	RESOLUTION ACCEPTED	
		Electrical Design		Potential Operability Issue	
	Discrepancy Type: System/Process:			No	
	NRC Significance level:	4		Date FAXed to NU:	
-	Discrepancy	Motor Cupio	Discrepancies of SW/P	Date Published: 11/9/97 Motor Operated Valves	
	Exercic particy.	MOLOI CUIVE	Disciedancies of SVVP	MOLOI Operated valves	

Description:

1. Full load current can be obtained from the Reliance motor curve sheet (included in the motor operated valve calculations) in three places: the table, the header, and the curve itself. The values from these three places are usually different. The valves listed below show differences between the Reliance motor curve header, table, and curve full load current values, but the full load current value used in the calculations was obtained from the nameplate (i.e., the Reliance motor curve full load current data was not used in the calculations). These documents should be revised to reflect the latest motor data.

Valves 3SWP\*MOV24A, 3SWP\*MOV24B, 3SWP\*MOV24C, 3SWP\*MOV24D Reliance Motor Curve - curve = 0.35 amperes Reliance Motor Curve - header = 0.45 amperes Reliance Motor Curve - table = 0.45 amperes

Value used in Calc. 89-094-121E3 (Rev. 0, CCN 2) = 0.45 amperes

Valves 3SWP\*MOV50A, 3SWP\*MOV50B, 3SWP\*MOV102A, 3SWP\*MOV102B, 3SWP\*MOV102C, 3SWP\*MOV102D Reliance Motor Curve - curve = 2.4 amperes Reliance Motor Curve - header = 2.8 amperes Reliance Motor Curve - table = 2.55 amperes Value used in Calcs. 89-094-121E3 and 89-094-122E3 (Rev. 0, CCN 4) = 2.8 amperes

Valves 3SWP\*MOV54A, 3SWP\*MOV54B, 3SWP\*MOV54C, 3SWP\*MOV54D, 3SWP\*MOV57A, 3SWP\*MOV57B, 3SWP\*MOV57C, 3SWP\*MOV57D, 3SWP\*MOV71A, 3SWP\*MOV71B Reliance Motor Curve - curve = 0.7 amperes Reliance Motor Curve - header = 0.75 amperes Reliance Motor Curve - table = 0.7 amperes Value used in Calcs. 89-094-121E3 and 89-094-122E3 = 0.95 amperes

Valve 3SWP\*MOV115A Reliance Motor Curve - curve = 0.6 amperes Reliance Motor Curve - header = 0.6 amperes Reliance Motor Curve - table = 0.55 amperes Value used in Calc. 89-094-122E3 = 0.6 amperes

Valve 3SWP\*MOV115B Reliance Motor Curve - curve = 0.4 amperes Reliance Motor Curve - header = 0.45 amperes

Printed 5/14/98 10:09:07 AM

Page 1 of 7

Northeast	Utilities
Millstone	Unit 3

Reliance Motor Curve - table = 0.45 amperes Value used in Calc. 89-094-122E3 = 0.45 amperes

Valves 3SWP\*MOV130A, 3SWP\*MOV130B Reliance Motor Curve - curve = 0.6 amperes Reliance Motor Curve - header = 0.55 amperes Reliance Motor Curve - table = 0.54 amperes Value used in Calc. 89-094-122E3 = 0.55 amperes

With the exception of motor operated valves 3SWP\*MOV130A and 3SWP\*MOV130B (which are retired in place), the thermal overload relay sizing calculations used full load currents equal to or larger than the maximum full load currents shown in the Reliance motor curves, therefore, substituting any other values from the Reliance motor curves would not affect the results of the calculation.

2. For motor operated valve 3SWP\*MOV115A, the Reliance motor curve shows a locked rotor current value of 3.5 amperes in the header of the curve and a value of 3.15 amperes in the table of the curve. The value of 3.5 amperes is used in the calculations performed in Calculation 89-094-122E3 (Rev. 0, CCN 4), and this value provides more conservative results than the 3.15 ampere value.

Specification 2282.400-568 Add. 3 (Rev. 1), vendor Drawing 2282.400-568-96B, Plant Design Data System (PDDS), and Production Management Maintenance System (PMMS) reflect a value of 3.15 amperes.

These documents should be revised to reflect the actual motor locked rotor current.

3. For each motor operated valve, the header on the Reliance motor curve refers to the insulation as "B" which does not agree with the purchase specifications which require an insulation rating of radiation resistant Class H.

4. In Calculations 89-094-121E3 (Rev. 0, CCN 2) and Calculation 89-094-122E3 (Rev. 0, CCN 4), the locked rotor current of 5.25 amperes for valves 3SWP\*MOV54A, 3SWP\*MOV54B, 3SWP\*MOV54C, 3SWP\*MOV54D, 3SWP\*MOV57A, 3SWP\*MOV57B, 3SWP\*MOV57C, 3SWP\*MOV57D, 3SWP\*MOV71A, and 3SWP\*MOV71B does not match the value of 5 amperes shown in Specification 2362.200-164 Add. 1 (Rev. 2), vendor Drawings 2362.200-164-043 (Rev. C) and 2362.200-164-043A (Rev. B), and Piant Design Data System (PDDS). Calculations NL-038 (Rev. 2, CCN 6) and SP-M3-EE-342 (Rev. 1) also show 5 amperes for 3SWP\*MOV54A, 3SWP\*MOV54C, and 3SWP\*MOV71A. Use of the larger locked rotor currents provides more conservative

Printed 5/14/98 10:09:10 AM

Northeast	Utilities
Millstone I	Jnit 3

results (i.e., substituting 5 amperes for the 5.25 amperes will not affect the results of the calculation).

The documents should be revised to reflect the actual motor data.

			Valid	Invalid	Needed	Date
Initi	ator: Ke	andall, D. J.				10/17/97
VTL	ead: No	eri, Anthony A				10/27/97
VT	Mgr: So	chopfer, Don K				10/28/97
IRC C	hmn: Si	ngh, Anand K				11/5/97
	Date:					
INV	ALID:					

THE REAL PROPERTY OF THE PARTY OF THE

Date: 5/12/98

**RESOLUTION:** Disposition:

NU has concluded that part of items 2 and 4 Discrepancy Report, DR-MP3-0377, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010. It has been screened per attachment 11 of U3 PI-20 criteria and found to have no operability or reportability concerns and meets section 1.3.2.e of U3 PI 20 deferral criteria.

Specification 2282.400-568 Add. 3 (Rev.1), vendor drawing 2282.400-568-96B, specification 2362.200-164 Add. 1 (Rev. 2), vendor drawing 2362.200-164-043 (Rev. C), calculation NL-038 and specification SP-M3-EE-342 are discrepant and will be corrected post startup.

CR M3-98-2091 was closed to Bin CR M3-98-0217. The corrective actions in Bin CR M3-98-0217 will correct these issues post startup. There is no affect on License or Design Basis.

NU has concluded that item 1 and parts of items 2 and 4 of Discrepancy Report, DR-MP3-0377, has identified a condition previously discovered by NU which requires correction.

EWA M3-95338 was written in response to GL89-10. DCR M3-97004 (MOV Program)was initiated by EWA M3-95338. As part of the MOV program, Electrical Calculation MOV8910-01542E3 was issued.

Calculations 89-094-121E3 and 89-094-122E3 have been superseded by MOV Electrical Calculation MOV8910-01542E3. The values used for the new calculation are obtained through nameplate (wa!kdown) data or the motor curves, but the nameplate data takes precedence. The motor curve values are only used if nameplate data is unavailable. The new MOV calculation uses the Reliance motor curves from the superseded calculations. In some cases, there are differences between the header, table, and curve values, but per MOV-PI-4, "AC and DC Motor Terminal Voltage Evaluation", and MOV-PI-6, "Thermal Overload Sizing Evaluation," through reference to IEEE Std

Northeast Utilities	ICAVP	DR No. DR-MP3-0377
Millstone Unit 3	Discrepancy Report	
	1290-1996, the values taken from the taken from the table. Thus, consiste required, are used.	
	Item 1: The nameplate values are used in the Nameplate FLC for 3SWP*MOV24A Nameplate FLC for 3SWP*MOV50A nameplate FLC for 3SWP*MOV54A 3SWP*MOV71A/B is .95 amps. Nameplate FLC for 3SWP*MOV115 Nameplate FLC for 3SWP*MOV115 Nameplate FLC for 3SWP*MOV115 PDCR MP3-94-099 removed all elect operated valves 3SWP*MOV130A/E were manually placed in the normal from the GL89-10 program and all e	A-D is .45 amps. VB is 2.8 amps, and s 4.0 amps. A-D, 3SWP*MOV57A-D, and A is .60 amps. B is .45 amps. ctric service to motor 3. As such, these valves open position and removed
	Item 2: The nameplate data is used for the n LRC for 3SWP*MOV115A is 3.5 am DCR M3-97004 was written to cover implementation of the GL89-10 (MO was initiated by EWA M3-95338, "G Modifications" in response to GL89- PMMS and PDDS will be changed to before closeout.	nps. all changes required for the V) program. DCR M3-97004 eneric Motor Operated Valve 10. As per DCR procedure,
	Item 4: The curve table values are used for table LRC for 3SWP*MOV54A-D, 3 3SWP*MOV71A/B is 5.25 amps.	
	DCR M3-97004 was written to cover implementation of the GL89-10 (MC was initiated by EWA M3-95338, "G Modifications" in response to GL89- PMMS and PDDS will be changed to before closeout.	V) program. DCR M3-97004 eneric Motor Operated Valve 10. As per DCR procedure,
	NU has concluded that the issue rep item 4 of Discrepancy Report, DR-M a discrepant condition.	ported in item 3 and part of MP3-0377, does not represent
	Item 3: Only ~18% of all motor operated va of Class B. All other valves have an H. To compensate for the motor op all calculations are performed with a calculations are conservative. As the replacement, they are replaced with Table 4.1.1 and 4.1.2 of MOV calcu all SWP valves are insulation class	n insulation rating of Class perators with a Class B rating, a 78 °C cutoff. Thus, all ne motor operators require a Class H operators. Per lation MOV8910-01542E3,
	Item 4: Drawing 2362.200-164-043A could i	not be located within the

Printed 5/14/98 10:09:13 AM

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report	DR No. DR-MP3-0377
	drawing database. It appears that the 2362.200-164-043 Rev. A. This draw Rev. C, which is the other drawing list	wing was superseded by
	Conclusion: NU has concluded that part of items Report, DR-MP3-0377, has identified discovered by NU which requires con meets the criteria specified in NRC I has been screened per attachment 1 found to have no operability or repor section 1.3.2.e of U3 PI 20 deferrate 2282.400-568 Add. 3 (Rev.1), vendo 96B, specification 2362.200-164 Add 2362.200-164-043 (Rev. C), calculat SP-M3-EE-342 are discrepant and w The corrective actions in Bin CR M3 issues post startup. There is no affe Basis.	d a condition not previously rrection. This discrepancy etter B16901 and 17010. It 11 of U3 PI-20 criteria and tability concerns and meets criteria. Specification or drawing 2282.400-568- d. 1 (Rev. 2), vendor drawing tion NL-038 and specification vill be corrected post startup. -98-0217 will correct these
	NU has concluded that item 1 and p Discrepancy Report, DR-MP3-0377, previously discovered by NU which	has identified a condition
	EWA M3-95338 was written in response 97004 (MOV Program)was initiated of the MOV program, Electrical Calc was issued.	by EWA M3-95338. As part
	Item 1: The nameplate values are used in the	ne new calculation,
	MOV8910-01542E3. Nameplate FLC for 3SWP*MOV24A Nameplate FLC for 3SWP*MOV50A nameplate FLC for 3SWP*102A-D is Nameplate FLC for 3SWP*MOV54A	VB is 2.8 amps, and s 4.0 amps.

/57A-D, and 3SWP\*MOV71A/B is .95 amps. Nameplate FLC for 3SWP\*MOV115A is .60 amps. Nameplate FLC for 3SWP\*MOV115B is .45 amps. PDCR MP3-94-099 removed all electric service to motor operated valves 3SWP\*MOV130A/B. As such, these valves

were manually placed in the normal open position and removed from the GL89-10 program and all electrical calculations.

### Item 2:

The nameplate data is used for the new calculation, MOV8910-01542E3. Nameplate LRC for 3SWP\*MOV115A is 3.5 amps. DCR M3-97004 was written to cover all changes required for the implementation of the GL89-10 (MOV) program. DCR M3-97004 was initiated by EWA M3-95338, "Generic Motor Operated Valve Modifications" in response to GL89-10. As per DCR procedure, PMMS and PDDS will be changed to reflect the correct values before closeout.

### Item 4:

The curve table values are used for the new calculation. Curve

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report	DR No. DR-M	P3-0377			
NANCON MANAGAMBAN AND YOR MAY A MANA A MANA MANAGAMBAN AND AND AND AND AND AND AND AND AND A	anna an Anna a		RANAL PROPERTY OF CARACING			
	table LRC for 3SWP*MOV54A-D 3SWP*MOV71A/B is 5.25 amps.		d			
	PMMS and PDDS will be changed to reflect the correct values before closeout of DCR M3-97004.					
	NU has concluded that the issue item 4 of Discrepancy Report, DF a discrepant condition.					
	Item 3: Only ~18% of all motor operated of Class B. Per Table 4.1.1 and MOV8910-01542E3, all SWP va	d 4.1.2 of MOV calculation	on			
	Item 4:Drawing 2362.200-164-04 the drawing database. This draw which is the other drawing listed.	ving was superseded by				
Previously Identified by NU?	🔿 Yes 🛞 No 🛛 Non Discr	repant Condition? Yes	No No			
Resolution Pendin	g? Yes 🖲 No Resolu	tion Unresolved? Yes	No No			
Initiator:	Kendali, D. J.	Review ot Acceptable Needed	Date			
VT Lead:	Neri, Anthony A		5/12/98 5/12/98			
VT Mgr:	Schopfer, Don K		5/12/98			
IRC Chmn:	Singh, Anand K	E E				
Date:	5/12/98					
	Discrepancies concerning Vendo 2362.200-164-043, Specification PDDS, PMMS, Calculation NL-0 SP-M3-EE-342 listed in Items 2 NU agrees that these are discrep documents.	s 2282.400-568 & 2362. 38, and OPAL Database & 4:	200-164, Spec.			
	Calculation discrepancies listed in NU's response states that the discalculations in question (89-094- previously discovered by NU (ref Calculation MOV8910-01542E3 89-094-121E3 and 89-094-122E3 Calculation MOV8910-01542E3 discrepancies listed in this DR, h prepared on January 9, 1998, wh 27, 1997, for Wave 1 systems, th condition. EWA M3-95338 was but it does not address the speci but only makes a general statem modifications need to be perform	screpancies identified on 121E3 and 89-094-122E ference EWA M3-95338 which supersedes Calcu 3). Sargent & Lundy con adequately addresses th nowever, this calculation hich is after the cutoff da herefore, it is still a discr written prior to the cutoff fic discrepancies listed i nent that motor operated	3) were and lations neurs that was te of May repant f date, n this DR			
	Vendor Drawing 2362.200-043A listed in Item 4: Sargent & Lundy concurs with NU that this drawing, wh transmitted on an aperture card by NU to Sargent & Lu valid as it is an outdated version (i.e., Revision B) of v Drawing 2362.200-164-043.					

### Item 3:

NU's response acknowledges that the Reliance curves are incorrect regarding insulation rating and confirms that the correct rating is Class H. Based on NU's explanation, and the fact that the Reliance curve information concerning insulation rating is not used in the calculations, Sargent & Lundy agrees that this issue is non-discrepant. However, NU's response does not state why the Reliance curves, which are included in Calculation MOV8910-01542E3 (and were included in superseded Calculations 89-094-121E3 and 89-094-122E3) as legitimate design data, do not need to be corrected (or a note added to the calculation which address this error), and Sargent & Lundy recommends that NU address this in a future revision to Calculation MOV8910-01542E3 for clarification purposes.

Northeast Utilities	ICAV	P	1	DR No. DR-	MP3-0489
Millstone Unit 3	Discrepanc	y Repo	ort		
Review Group:			DR RESOLU	TION ACCEPT	ED
Review Element:			P	otential Operal	bility issue
	Mechanical Design			O Yes	
Discrepancy Type:				No No	
System/Process:					
NRC Significance level:	4		Da	te FAXed to N	U:
				Date Publishe	d: 11/13/97
Discrepancy:	QSS Minimum 'Wall	Calculati	on Reference	S	
Description.	<ul> <li>The minimum wall calculations reference ASME Section III, 1971 through 1973 Summer Addenda as the design code for piping. Reference 3 in the calculations reference Section NB- 3640 of this Code. Section NB of the Code is Class 1 piping requirements. The QSS lines are Class 2. Class 2 piping and components are designed under Section NC of the Code. The Section NC allowable stresses were used in the calculation. Because Section NC-3640 uses a similar equation for calculating the minimum wall as Section NB-3640, there is no affect on the conclusion. This is a documentation discrepancy.</li> <li>The calculations all reference a flow diagram (FSK) for the design pressure and temperature. The FSK series drawings has been classified "For Information Only." A review of the piping diagram and the line list, which superseded the FSKs, indicates the pressure and temperature are correct in all cases except for Calculation MW(F)-45. The discrepancy for this calculation is addressed in DR-MP3-0164. Since the pressures and temperatures used in the calculation are correct, the conclusions are not affected. This is a documentation discrepancy.</li> </ul>				
	The Minimum Wall C	alculatio	ne are		
		alculatio	nis are.		
	MW(B)-129, Rev. 0 MW(F)-027, Rev. 0 MW(F)-125, Rev. 1 MW(F)-321, Rev. 1	MW(F)	)-142, Rev. 0 -045, Rev. 0 -174 , Rev. 1		
				Review	
		Valid	Invalid	Needed	Date
	Langel, D.				10/31/97
	Neri, Anthony A	$\boxtimes$			10/31/97
	Schopfer, Don K	$\boxtimes$			11/6/97
IRC Chmn:	Singh, Anand K	$\boxtimes$			11/7/97
Date:					
INVALID:					
Date:	5/13/98	A BERNELLANET SCALE S	NEXTER BOLIES STREET BARY ALL DATES	ANT DESIGNATION OF THE OWNER OF THE OWNER OF THE	NEW PLANESSING
RESOLUTION:	Disposition:				
	NU has concluded the identified a CONFIRM which requires correct M3-IRF-01693 in it's criteria specified in N screened per U3 PI-2	MED SIG tion. Th entirety. RC lette	NIFICANCE is response s This discrep r B16901 and	LEVEL 4 co supersedes r ancy meets 17010. It h	ondition response the nas been

Printed 5/14/98 9:29:02 AM

Page 1 of 2

ortheast Utilities illstone Unit 3	IC/ Discrepa	AVP ncy Repo		No. DR-N	1P3-0489
	or reportability concerns and meets the Unit 3 deferral criteria. CR M3-98-0515 has been written to revise the referenced calculations to reference Section NC-3640 of the code.				
	Conclusion				
	NU has concluded identified a CONF which requires co M3-IRF-01693 in criteria specified screened per U3 or reportability co CR M3-98-0515 h calculations to ref	FIRMED SIG prrection. Th it's entirety. in NRC letter PI-20 criteria procerns and mas been write has been write	NIFICANCE LE is response sup This discrepan B16901 and 1 and found to h meets the Unit 3 tten to revise th	EVEL 4 con persedes re cy meets th 7010. It has ave no ope 3 deferral c e reference	dition sponse he s been erability riteria.
Previously Identified by NU?	🔿 Yes 🔘 No	Non D	iscrepant Conditio	n? Yes	No No
Resolution Pendin	g? Yes 🖲 No	Re	solution Unresolve	d?O Yes	No No
	Langel, D.	Acceptable	Not Acceptable	Review Needed	Date 5/13/98

Northeast	Utilities
Millstone L	Jnit 3

# **ICAVP**

**Discrepancy Report** 

Review Group:	Configuration		DR RESOLU	TION ACCEPT	ED
Discrepancy Type:	Electrical Design Installation Implementation	n	F	Potential Operat O Yes I No	oility Issue
System/Process: NRC Significance level:			D	ate FAXed to Ni Date Published	
Discrepancy:	Supports not in agr	eement wit	h design dra	wings.	
	The following devia				ted:
	1. Drawing DWG E calls for Detail H w anchorage. Suppo auxiliary beam is in	hich require rt C207-17	es gusset pla 2 does not h	ate at ceiling	
	2. Drawing EE-34K show horizontal Wi top and bottom inte Change Control Do this deviation.	37 5/8"L m emal 'X' bra	ember that is acing on sup	s installed be port C260-26	iween the 3. Open
	3. Three PS 204 m installed on the upp support C309A-017 design documents	per 4 ft. sed (reference	ction of the s e drawing EE	outh vertical -34 KP Rev.	leg of 4). No
		Valid	Invalid	Needed	Date
Initiator:	Sarver, T. L.				10/15/97
VT Lead:	Neri, Anthony A				10/16/97
VT Mgr:	Schopfer, Don K				10/20/97
IRC Chma:	Singh, Anand K				10/27/97
Date:					
INVALID:					

Date: 5/13/98

RESOLUTION: NU has concluded that Discrepancy Report, DR-MP3-0503, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010. It has been screened per U3 PI-20 criteria and found to have no operability or reportability concerns and meets the Unit 3 deferral criteria. CR M3-98-0513 has been written to develop and track resolution of this item per RP-4.

SECOND RESPONSE:

NU has concluded that the issues reported in Discrepancy Report DR-MP3-0503 have identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which require correction. Items 1 and 2 of the discrepancy report meet the criteria specified in NRC letter B16901 and 170010. Items 1 and 2 have been screened per attachment 11 of U3 PI 20 criteria and were found to have no operability or reportability

Northeast Utilities Millstone Unit 3	Disc		AVP hcy Repo		R No. DR-M	IP3-0503
	Item 1 of Tray Supp on drawing identify do condition, of the stiff which pred stiffener h states the document following: horizontal The horizo The memi this is con installed a Bin CR M items post NU has co 0503 is a 204 memi C309A-17	the disc port C20 g EE-34 pournent without fener pla cludes th as been mid hor drawing member ontal me ber size as intend 3-98-05 t startup poncluded NON-DI bers inst are det	repancy rep 7-172 is not KA. An ext ation that a success. H the reveals a ne stiffener satisfied by izontal W37 wever, revie EE-34KH f r between t ember is als and type is an administ led. 13 correctiv SCREPAN alled betwe ailed on E&	.3.2.e of U3 PI port states that a installed as pe ensive search w ddresses the ac owever, inspect a supplemental installation. The y the framing m 7 Dummy mem w of document or tray support he top and both o shown in Deta not referenced trative issue on e actions will ac sue reported in T condition. The een tray support DCR F-E-2392	a stiffener p r the details vas conduct ceptability of tion at the li- steel beam re intent of the mber. Item ber is not ation reveal 260 depicts om cross br ail G on EE- on the draw ly. The supp ddress these item 3 of Di e three horiz ts C309-32	late for given ed to of this ocation installed he n 2 s the a cacing. .34JA. vings, but port is e two R-MP3- contal PS and
Previously Identified by NU?	further act	No No		iscrepant Conditi	on? Yes	No No
Resolution Pending		No		solution Unresolv	~	<ul><li>No</li></ul>
Initiator:		. 40	Acceptable	Not Acceptable	Review	Date
	Neri, Anthony	уА				5/13/98
VT Mgr:	Schopfer, Do	on K		Н	H	5/14/98 5/14/98
IRC Chmn:	Singh, Ananc	dK	ñ	H	H	011400
Date:	5/13/9	8	-	-	-	
SL Comments:				e C207, C260 a configurations		
	SECOND	RESPO	NSE:			

theast Utilities	IC	AVP	D	R No. DR-	MP3-0549
stone Unit 3	Discrepa	ncy Repo	rt		
Review Group:	Configuration	alkonsenna kradina konsen ander ander and	DR RESOLUT	ION ACCEPT	ED
	System Installation		Po	tential Opera	bility Issue
	Electrical Design			O Yes	
	Installation Implementat	ion		No No	
System/Process: NRC Significance level:					
into organicance ieves.	•		Date	e FAXed to N	U:
			C	ate Publishe	d: 11/9/97
Discrepancy:	Installed supports	not in agree	ment with dra	wings	
Description:	1. A 1" conduit an horizontal member attachment is not	er of Cable Tr	ay Support A	308A-31.	This
	2. Detail. 8-8 of 0 is to be installed of STRAY-43. Walk	on the vertica	l legs of Cabi	e Tray Sup	port
	3. Local panel 3H the same vertical drawing EE-34DV drawing, and open could not be found	leg of Cable (Rev. 5). Th n change doc	Tray Support is attachment	STRAY-4: t is not show ring this ins	3 (Ref. wn on the
		Valid	Invalid	Review Needed	Date
Initiator:	Sarver, T. L.				10/28/97
VT Lead:	Neri, Anthony A		Н	Ē	10/28/97
	Schopfer, Don K		H	Н	10/30/97
	Singh, Anand K		ă	ă	11/4/97
Date:					
INVALID:					
Nete:	E /4 2 /0 0	andre manatikersen og skredetsom søder	ANNOLOGISMIC Y GANY BANKKOK A'Y MONIO		100-39911.0991000000000000000000000000000000
Date:	5/13/98 NU has concluded	d 4h =1 4h = '==		- 00 1100	0540
	have identified CC conditions which in the criteria specifi have been screen found to have no Section 1.3.2.e of Items 1, 2, & 3, re minor in nature an supports. A DCN	ONFIRMED S require correct ed in NRC le bed per attach operability or U3 PI-20 det present draw of do not affe will be issued nents will be	GNIFICANC tions. These ther B16901 a ment 11 of U reportability ferral criteria. ing discrepan ct the qualifie to make nec updated to inc	CE LEVEL 4 discrepan and 17010. U3 PI-20 cri concerns a ncies, which cation of the cessary con corporated	4 cies meet They teria and nd meets n are e rections the to CR M3-
	changes noted in 98-0137. The cor M3-98-0137 which these three items	rective action will be comp to be Signific	is for this issu pleted post st ance Level 4	artup.NU c	onsiders
Previously Identified by M12	changes noted in 98-0137. The cor M3-98-0137 which these three items affect on License	rective action h will be comp to be Signific or Design Ba	is for this issu pleted post st ance Level 4 sis.	artup.NU c issues. Ti	onsiders here is no
Previously Identified by NU? Resolution Pending	changes noted in 98-0137. The cor M3-98-0137 which these three items affect on License O Yes O No	nective action n will be comp to be Signific or Design Ba Non Dis	ns for this issu pleted post st ance Level 4 sis. crepant Conditi	artup.NU c issues. Ti ion? Yes	onsiders here is no
Previously Identified by NU? Resolution Pending	changes noted in 98-0137. The cor M3-98-0137 which these three items affect on License O Yes O No	nective action n will be comp to be Signific or Design Ba Non Dis	is for this issu pleted post st ance Level 4 sis.	artup.NU c issues. Ti ion? Yes ved? Yes	onsiders here is no
	changes noted in 98-0137. The cor M3-98-0137 which these three items affect on License Yes No Yes No	rective action h will be comp to be Signific or Design Ba Non Dis Resc	ns for this issu pleted post st ance Level 4 sis. crepant Conditi	artup.NU c issues. Ti ion? Yes ved? Yes Review	onsiders here is no

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report			DR No. DR-MP3-0549		
VT Mgr:	Nerr, Anthony A Schopfer, Don K Singh, Anand K				5/13/98 5/14/98	
Date: SL Comments:	5/13/98 S & L concurs with				ncies are	

minor and are not considered to be a re-start issues.

# ICAVP **Discrepancy Report**

### DR No. DR-MP3-0553

Po

**Review Group:** Configuration Review Element: System Design **Discipline:** Electrical Design Discrepancy Type: Drawing System/Process: RSS NRC Significance level: 4

# DR RESOLUTION ACCEPTED

tential	Operability	Issue
C	) Yes	
	No	

### Date FAXed to NU:

Date Published: 11/9/97

Discrepancy: Design Documents not in agreement

**Description:** 

1. A 1-inch diameter conduit for lighting is attached to south vertical leg of tray support G109-013. This attachment is not shown on the detail drawing EE-34JF, Rev.3. No referenced open change control documents for this drawing address this item.

2. Configuration of cable trays routed N-S as seen in Sections 2-2, 20-20, 21-21 and 22-22 on drawings EE-34R Rev. 10, EE-34S Rev. 11 and F-E-14937 cannot be resolved in field. The F-E shows eight trays: EE-34R shows seven trays. There are seven trays installed, but configuration does not match any reviewed document.

3. Drawing EE-34AU Rev. 6, incorrectly identifies trays. Cable Tray 3TC774P is not clearly located on this drawing. It should be located at coordinates B-7 and shown in Section 4-4 - but a "P-L" tray is shown instead.

4. Drawing EE-34AM Rev. 5 does not correctly depict cable tray locations. The "X" cable tray is incorrectly shown routing north and east past Col. Line 49.4 while the "K" cable tray is incorrectly shown stopping at Col. Line 49.4. The correct cable tray plan is as shown on drawing EE-34EN.

5. Cable tray 3TC757O was extended east along Col. Line 49.4 hy F-E-14714. The tray identification drawing EE-34BB Rev. 11, for "O-C2" trays was not corrected to show this change when Rev. 9 was performed incorporating the F-E.

6. Conduit Plan drawing EE-55B, Rev. 8 shows flow transmitter 3RSS\*FT38A 09 non-safety related (drawings has FT erroneously identified as 3RSS-FT38A).

7. Conduits 3CC764PA3, 3CC763PA2 and PB7 are 11/2" flexible conduits of approximately 4 feet long running between junction box 3JB\*7515 and valve 3RSS\*MV8838B. The Cable and Raceway Program indicates that these conduits are rigid.

8. The Cable and Raceway Program (TSO2) indicates that conduit 3CC763PC7 is supported by three supports. This 5-feet long conduit was observed to have only one support.

9. Conduit Support Log 12179-FSK-ES-0442, Rev. 2A shows conduit 3CK760NA in Section 1 of view looking west but does not appear in plan view. This causes the number of conduits shown in the two views of the same support to be different. Page 1 of 3

Printed 5/14/98 9:32:15 AM

# ICAVP Discrepancy Report

10. Conduit Support Log 12179-FSK-ES-5129, Rev. 2, lists conduit 3CC764PB1 and this conduit was observed in the field installed on this support. The Cable and Raceway Program (TSO2) does not list this conduit as supported by this support.

11. Conduit Support Log 12179-FSK-ES-1082, Rev. 1, lists conduit 3CX970PB1 and this conduit was observed in the field installed on this support. The Cable and Raceway Program (TSO2) does not list this conduit as supported by this support.

12. Conduit Support Log 12179-FSK-ES-1530, Rev. 1A, lists conduit 3CK765PF5 as supported on this support. The Cable and Raceway Program (TSO2) does not list this conduit as supported by this support.

13. Conduit Support Log 12179-FSK-ES-439 Rev. 3A lists conduit 3CK758PF as supported on this support. The Cable and Raceway Program (TSO2) does not list this conduit as supported by this support. TSO2 lists conduit 3CK758NA as supported by this support, however, the CSL does not include this conduit.

		Valid	Invalid	Needed	Date
initiator:	Sarver, T. L.				10/28/97
VT Lead:	Neri, Anthony A				10/28/97
VT Mgr:	Schopfer, Don K				10/30/97
IRC Chmn:	Singh, Anand K				11/4/97

### Date:

INVALID:

Date: 5/13/98

RESOLUTION: NU has concluded that Discrepancy Report, DR-MP3-0553, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010. It has been screened per U3 PI-20 criteria and found to have no operability or reportability concerns and meets the Unit 3 deferral criteria. CR M3-98-1063 has been written to develop and track resolution of this item per RP-4.

### SECOND RESPONSE:

NU has concluded that the issue reported in DR-MP3-0553 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition that requires correction.

Items 1, 2 & 8 meets the criteria specified in NRC letter B16901 and 17010. They have been screened per attachment 11 of U3 PI-20 criteria and found to have no operability or reportability concerns and meets section 1.3.2.e of U3 PI-20 deferral criteria based on the following discussion: Item 1: Design Engineering performed a walkdown of the general lighting conduit attached to the south leg of tray support C109-013. A search for outstanding Change Documents against D<sub>mg</sub>. 25212-35006 reveals nothing to substantiate the as-installed condition. Drawing 25212-35006

Printed 5/14/98 9:32:19 AM

Page 2 of 3

.

s s c 1 c r s t	Discrepan does show that out structural steel or t substantiate the in conduit is also atta 109-20 and G107- conduit and span not adversely affect	tlet box no. to cable tray stallation of inched to the 9. Based of	19 may be attac support", but d the conduit itse south leg of ca	loes not elf. Note tha		
s s c 1 c r s t	structural steel or t substantiate the in conduit is also atta 109-20 and G107- conduit and span on not adversely affect	to cable tray stallation of inched to the 9. Based of	the conduit itse south leg of ca	loes not elf. Note tha		
	supports. A DCN is o reflect the as-ins actually attached to 20)Item 2: Design determined the ins F-E 14937, which EE-34Q, Rev 13. EE-34R & EE-34S indicated in GR:TS these drawings are outstanding E&DC 20, 21-21, & 22-22 E&DCR F-E-1493 relocate the location of the end points of	ct the struct s required to stalled cond o 3 supports Engineerin stalled tray of is incorpora This E&DCF According S DATA base e not require CRS. Tray se 2 (EE-34S) a 7 . Clarification of the jog	ng supports, this tural adequacy o correct the ap- lition. (NOTE: t s. C 107-9, G10 g performed a configuration ag ted on Tray Arr R is not incorpor to DCM Chapte se (drawing cate ections 2-2(EE-3 are correct whe tion is required g in section 1-1,	weight of the s installatio of the cable plicable do his conduit 9-13 & G10 walkdown a rees with E angement I rated on dr er 7, Rev 6 egory code d to incorpo 34R), section n viewed w on EE-340 and for the	pports G- ne n does e tray cuments is 09- and E & DCR Drawing awings and as 3A), orate ons 20- rith to e addition	
	12 & X4 located i	in the West	tray bank.			
Previously Identified by NU?	O Yes O No		iscrepant Conditio		No	
Resolution Pending?	? Yes (1) No	Rei	solution Unresolve	Review	() No	
Initiator:	Klaic, N	Acceptable	Not Acceptable	Needed	Date	
VT Lead: /	Neri, Anthony A			Ц	5/13/98 5/14/98	
VT Mgr: 5	Schopfer, Don K		H	H	5/14/98	
IRC Chmn: S	Singh, Anand K	D	H	- D	and a state of the second	
Date:	5/12/98	-		-		
	Adequacy of tray supports needs to be verified for the additional loads ( items 1 & 8 ) and configuration changes ( item 2 ) .					
1	SECOND RESPO	NSE:				

Pump. and Heat Exchanger Exhuast System is in compliant with RG 1.52, Rev. 2, position C.1.c.         Per FSAR Table 6.5-1, the Supplementary Leak Collection Release System is in compliance with RG 1.52, Rev. 2, pos C.1.c.         Per RG 1.52 Position C.1.c, The design of each adsorber set should be based on the concentration and relative abundant the iodine species (elemental, particulate, and organic) whit should be consistent with the assumptions found in RG 1.3, and 1.25.         Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit should be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement.         Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i         Walid       Invalid         Needed       Initiator: Stout, M. D.         Valid       Invalid         NT Lead: Neri, Anthony A       Image: 100	Northeast Utilities Millstone Unit 3		ICAVP Discrepancy Report			1P3-0584	
Discrepancy Type: Component Data System/Process: HVX NRC Significance level: 4 Discrepancy: SLCRS and ABVS Filter Unit Iodine Loading and Adsorbent Quantity Description: During review of the Supplementary Leak Collection and Release System (SLCRS) filter Unit Iodine Loading and Adsorbent Quantity Description: During review of the Supplementary Leak Collection and Release System (SLCRS) filter Unit Iodine Loading and Adsorbent Quantity Building Ventilation System (ABVS) exhaust filter of 3HVR*FLT1A/B component data a discrepancy regarding th iodine loading and charcoal adsorbent quantity was identifie Per FSAR Table 1.8-1, Milistone complies with RG 1.52 Re "Design, Testing, and Maintenance Criteria for Engineerdo- Safety-Feature Atmosphere Cleanup System AIP filtration Adsorption Units of Light-Water-Cooled Nuclear Power Plar regulatory position C.1.c. Per FSAR Table 6.5-1, the Charging Pump, Component Co Pump, and Heat Exchanger Exhuast System is in complian with RG 1.52, Rev. 2, position C.1.c. Per FSAR Table 6.5-1, the Supplementary Leak Collection Release System is in compliance with RG 1.52, Rev. 2, pos C.1.c. Per RG 1.52 Position C.1.c. The design of each adsorber se should be based on the concentration and relative abundan the iodine species (elemental, particulate, and organic) whis should be consistent with the assumptions found in RG 1.3, and 1.25. Per RG 1.52, Rev. 2, Position C.3.1, The adsorption unit sho be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement. Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.1	Review Group:	System	Laboration active sour Classic Report Al	DR RESOLU	TION ACCEPTE	D	
Discrepancy Type: Component Date System/Process: HVX NRC Significance level: 4 Discrepancy: SLCRS and ABVS Filter Unit Iodine Loading and Adsorbent Quantity Description: During review of the Supplementary Leak Collection and Release System (SLCRS) filter units 3HVR*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter of 3HVR*FLT1A/B component data a discrepancy regaring th iodine loading and charcoal adsorbent quantity was identified Per FSAR Table 1.8-1, Millstone complies with RG 1.52 Rev Description: During review of the Supplementary Leak Collection and Release System (SLCRS) filter Unit SHVR*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter of 3HVR*FLT1A/B component data a discrepancy regaring th iodine loading and charcoal adsorbent quantity was identified Description. Testing, and Maintenance Criteria for Engineered- Safety-Feature Atmosphere Cleanup System Air Filtration and Adsorption Units of Light-Water-Cooled Nuclear Power Plan regulatory position C.1.c. Per FSAR Table 6.5-1, the Charging Pump, Component Co Pump, and Heat Exchanger Exhaust System is in compliant with RG 1.52, Rev. 2, position C.1.c. Per RG 1.52 Position C.1.c. The design of each adsorber set should be based on the concentration and relative abundand the iodine species (elemental, particulate, and organic) whis should be consistent with the assumptions found in RG 1.3, and 1.25. Per RG 1.52, Rev. 2, Position C.3.1, The adsorption unit sho be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement. Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qui of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.1 Valid Invali	Review Element:	System Design		P	otential Operabi	lity Issue	
System/Process: HVX       Disk FARD to NI:         NRC Significance level: 4       Date FARD to NI:         Discrepancy:       SLCRS and ABVS Filter Unit lodine Loading and Adsorbent Quantity         Description:       During review of the Supplementary Leak Collection and Release System (SLCRS) filter units 3HVR*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter 3HVR*FLT1A/B component data a discrepancy reparding th iodine loading and charcoal adsorbent quantity was identifie         Per FSAR Table 1.8-1, Millstone complies with RG 1.52 Rev Design, Testing, and Maintenance Criteria for Engineered- Safety-Feature Atmosphere Cleanup System Air Filtration a Adsorption Units of Light-Water-Cooled Nuclear Power Plar regulatory position C.1.c.         Per FSAR Table 6.5-1, the Charging Pump, Component Co Pump and Heat Exchanger Exhuast System is in compliant with RG 1.52, Rev. 2, position C.1.c.         Per FSAR Table 6.5-1, the Supplementary Leak Collection Release System is in compliance with RG 1.52, Rev. 2, pos C.1.c.         Per RG 1.52 Position C.1.c., The design of each adsorber se should be based on the concentration and relative abundan the iodine species (elementar), particular, abundan the iodine species (elementar), particular, abund organic), whi should be consistent with the assumptions found in RG 1.3, and 1.25.         Per RG 1.52, Rev. 2, Position C.3.1, The adsorption unit sh be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement.         Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response					-	,	
NRC Significance level: 4       Date FAXed to NU:         Discrepancy:       SLCRS and ABVS Filter Unit Iodine Loading and Adsorbent Quantity         Description:       During review of the Supplementary Leak Collection and Release System (SLCRS) filter units 3HVR*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter 3HVR*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter 3HVR*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter 3HVR*FLT3A/B and the iodine loading and charcoal adsorbent quantity was identified being and charcoal adsorbent quantity was identified being and charcoal adsorber quantity was identified being and charcoal adsorber quantity was identified being and charcoal adsorber of power Plant regulatory position C.1.c.         Per FSAR Table 6.5-1, the Charging Pump, Component Co Pump, and Heat Exchanger Exhuast System is in compliant with RG 1.52, Rev. 2, position C.1.c.         Per RG 1.52 Position C.1.c.         Per RG 1.52 Position C.1.c., The design of each adsorber set should be based on the concentration and relative abundam the iodine species (elemental, particulate, and organic) whit should be consistent with the assumptions found in RG 1.3, and 1.25.         Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit shit be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus table) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement.         Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total quitor that requirement.         Calculations that determine the total iodin					O No		
Discrepancy: SLCRS and ABVS Filter Unit Iodine Loading and Adsorbent Quantity Description: During review of the Supplementary Leak Collection and Release System (SLCRS) filter units 3HVR*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter of 3HVR*FLT1A/B component data a discrepancy regarding th iodine loading and charcoal adsorbent quantity was identifie Per FSAR Table 1.8-1, Millstone complies with RG 1.52 Rev Design, Testing, and Maintenance Criteria for Engineered- Safety-Feature Atmosphere Cleanup System Air Filtration a Adsorption Units of Light-Water-Cooled Nuclear Power Plan regulatory position C.1.c. Per FSAR Table 6.5-1, the Charging Pump, Component Co Pump. nd Heat Exchanger Exhuast System is in compliant with RG 1.52, Rev. 2, position C.1.c. Per FSAR Table 6.5-1, the Supplementary Leak Collection Release System is in compliance with RG 1.52, Rev. 2, pos C.1.c. Per RG 1.52 Position C.1.c, The design of each adsorber sa should be based on the concentration and relative abundam the iodine species (elemental, particulate, and organic) whits should be consistent with the assumptions found in RG 1.3, and 1.25. Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit shh be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement. Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3. Valid invalid invalid invalid inter Neede Initiator: Stoxt, M.D.							
Discrepancy: SLCRS and ABVS Filter Unit Iodine Loading and Adsorbent Quantity Description: During review of the Supplementary Leak Collection and Release System (SLCRS) filter units 3HVR*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter 3HVR*FLT1A/B component data a discrepancy regarding th iodine loading and charcoal adsorbent quantity was identifie Per FSAR Table 1.8-1, Millstone complies with RG 1.52 Re 'Design, Testing, and Maintenance Criteria for Engineered- Safety-Feature Atmosphere Cleanup System Air Filtration a Adsorption Units of Light-Water-Cooled Nuclear Power Plan regulatory position C.1.c. Per FSAR Table 6.5-1, the Charging Pump, Component Co Pump. nd Heat Exchanger Exhuast System is in complian with RG 1.52, Rev. 2, position C.1.c. Per FSAR Table 6.5-1, the Supplementary Leak Collection Release System is in compliance with RG 1.52, Rev. 2, pos C.1.c. Per RG 1.52 Position C.1.c, The design of each adsorber so should be based on the concentration and relative abundan the iodine species (elemental, particulate, and organic) while should be consistent with the assumptions found in RG 1.3, and 1.25. Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit sho be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement. Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.1 Review Needed Initiator: Stoxt, M.D.	NRC Significance level:	4		Da	te FAXed to NU	:	
Quantity         Description:       During review of the Supplementary Leak Collection and Release System (SLCRS) filter units 3H/R*FLT3A/B and th Auxiliary Building Ventilation System (ABVS) exhaust filter of 3HVR*FLT1A/B component data a discrepancy reparding th iodine loading and charcoal adsorbent quantity was identifie         Per FSAR Table 1.8-1, Millistone complies with RG 1.52 Ret Design, Testing, and Maintenance Criteria for Engineered- Safety-Feature Atmosphere Cleanup System Air Filtration a Adsorption Units of Light-Water-Cooled Nuclear Power Plan regulatory position C.1.c.         Per FSAR Table 6.5-1, the Charging Pump, Component Co Pump. and Heat Exchanger Exhuast System is in compliant with RG 1.52, Rev. 2, position C.1.c.         Per FSAR Table 6.5-1, the Supplementary Leak Collection Release System is in compliance with RG 1.52, Rev. 2, pos C.1.c.         Per RG 1.52 Position C.1.c. The design of each adsorber so should be based on the concentration and relative abundan the iodine species (elemental, particulate, and organic) while should be consistent with the assumptions found in RG 1.3, and 1.25.         Per RG 1.52, Rev. 2, Position C.3.1, The adsorption unit sho be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement.         Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.1					Date Published	: 11/6/97	
Release System (SLCRS) filter units 3HVR*FLT3A/B and th         Auxiliary Building Ventilation System (ABVS) exhaust filter u         3HVR*FLT1A/B component data a discrepancy regarding th         iodine loading and charcoal adsorbent quantity was identified         Per FSAR Table 1.8-1, Millstone complies with RG 1.52 Rev         'Design, Testing, and Maintenance Criteria for Engineered-Safety-Feature Atmosphere Cleanup System Air Filtration a         Adsorption Units of Light-Water-Cooled Nuclear Power Plan         regulatory position C.1.c.         Per FSAR Table 6.5-1, the Charging Pump, Component Co         Pump. not Heat Exchanger Exhuast System is in complian         with RG 1.52, Rev. 2, position C.1.c.         Per FSAR Table 6.5-1, the Supplementary Leak Collection         Release System is in compliance with RG 1.52, Rev. 2, pos         C.1.c.         Per RG 1.52 Position C.1.c, The design of each adsorber set         should be based on the concentration and relative abundan         the iodine species (elemental, particulate, and organic) white         should be consistent with the assumptions found in RG 1.3,         and 1.25.         Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit sho         be designed for a maximum loading of 2.5 mg of total iodin         (radioactive plus stable) per gram of activated carbon. FSA         Table 1.8-1 and Table 6.5-1 do not take exception to this	Discrepancy:		Filter Unit Id	odine Loadir	ng and Adsor	bent	
<ul> <li>Design, Testing, and Maintenance Criteria for Engineered-Safety-Feature Atmosphere Cleanup System Air Filtration a Adsorption Units of Light-Water-Cooled Nuclear Power Plan regulatory position C.1.c.</li> <li>Per FSAR Table 6.5-1, the Charging Pump, Component Co Pump. and Heat Exchanger Exhuast System is in compliant with RG 1.52, Rev. 2, position C.1.c.</li> <li>Per FSAR Table 6.5-1, the Supplementary Leak Collection Release System is in compliance with RG 1.52, Rev. 2, post C.1.c.</li> <li>Per RG 1.52 Position C.1.c, The design of each adsorber as should be based on the concentration and relative abundam the iodine species (elemental, particulate, and organic) whit should be consistent with the assumptions found in RG 1.3, and 1.25.</li> <li>Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit should be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement.</li> <li>Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i</li> </ul>	Description:	Release System (S Auxiliary Building ) 3HVR*FLT1A/B co	LCRS) filter /entilation S mponent da	r units 3HVF system (ABV ta a discrep	R*FLT3A/B and (S) exhaust find ancy regarding R*FLT3A/B and R*FLT3A/B and R*	nd the Iter units ng the	
Pump. and Heat Exchanger Exhuast System is in compliant with RG 1.52, Rev. 2, position C.1.c.         Per FSAR Table 6.5-1, the Supplementary Leak Collection Release System is in compliance with RG 1.52, Rev. 2, pos C.1.c.         Per RG 1.52 Position C.1.c, The design of each adsorber set should be based on the concentration and relative abundant the iodine species (elemental, particulate, and organic) white should be consistent with the assumptions found in RG 1.3, and 1.25.         Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit should be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement.         Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i         Walid       Invalid         Review       Needed         Initiator: Stout, M. D.       Invalid       Review		'Design, Testing, a Safety-Feature Atri Adsorption Units of	nd Maintena nosphere Cl f Light-Wate	eanup Syste	of for Engineer for Air Filtrati	red- on and	
Release System is in compliance with RG 1.52, Rev. 2, position C.1.c.         Per RG 1.52 Position C.1.c, The design of each adsorber sets should be based on the concentration and relative abundam the iodine species (elemental, particulate, and organic) which should be consistent with the assumptions found in RG 1.3, and 1.25.         Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit should be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement.         Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i         Walid       Invalid         Review Needed       Initiator: Stout, M. D.		Per FSAR Table 6.5-1, the Charging Pump, Component Cooling Pump, and Heat Exchanger Exhuast System is in compliance with RG 1.52, Rev. 2, position C.1.c.					
should be based on the concentration and relative abundan the iodine species (elemental, particulate, and organic) whic should be consistent with the assumptions found in RG 1.3, and 1.25. Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit sho be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement. Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i Neview Valid Invalid Needed Initiator: Stout, M. D.		Release System is	5-1, the Su in complian	pplementary nce with RG	Leak Collec 1.52, Rev. 2	tion and , position	
should be based on the concentration and relative abundan the iodine species (elemental, particulate, and organic) whic should be consistent with the assumptions found in RG 1.3, and 1.25. Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit sho be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement. Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i Neview Valid Invalid Needed Initiator: Stout, M. D.		Der DC 1 52 Desit	on C 1 c T	he design of	each adsort	er section	
should be consistent with the assumptions found in RG 1.3, and 1.25. Per RG 1.52, Rev. 2, Position C.3.i, The adsorption unit sho be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement. Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i Valid Invalid Review Needed Initiator: Stout, M. D.		should be based on the concentration and relative abundance of					
be designed for a maximum loading of 2.5 mg of total iodin (radioactive plus stable) per gram of activated carbon. FSA Table 1.8-1 and Table 6.5-1 do not take exception to this requirement. Calculations that determine the total iodine loading on the charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i Valid Invalid Review Needed Initiator: Stout, M. D.		should be consistent with the assumptions found in RG 1.3, 1.4,					
charcoal adsorber are not available per NU response in M3 00718. This information is needed to verify that the total qu of charcoal in the filter units meets the 2.5 mg of total iodin gram of activated carbon requirement of RG 1.52, Rev. 2, Position C.3.i Review Valid Invalid Needed Initiator: Stout, M. D.		be designed for a (radioactive plus s Table 1.8-1 and Ta	maximum lo table) per gr	ading of 2.5 ram of activ	ated carbon.	iodine FSAR	
Valid Invalid Needed		charcoal adsorber 00718. This inform of charcoal in the t gram of activated	are not ava nation is nee filter units m	ilable per N ded to verif neets the 2.5	U response in y that the tot 5 mg of total	n M3-IRF- al quantity odine per	
Initiator: Stout, M. D.			Mallet	Invalid		Date	
	laitistor	Stout M D				10/28/97	
				Н	Н	10/28/97	
VT Mgr: Schopfer, Don K 🛛 🗌 10			N	H		10/30/97	
IRC Chmn: Singh, Anand K			M	Ē	Ē	10/31/97	

# ICAVP **Discrepancy Report**

DR No. DR-MP3-0584


INVALID:

INTERCORD CONTRACTOR AND ADDRESS OF VEHICLE AND ADDRESS AND ADDRESS ADDR	
Date:	5/12/98
	NU has concluded that the Discrepancy Report, DR-MP3-0584, has identified a condition not previously discovered by NU which requires correction.
	DR-MP3-0584 identified issues with the iodine loading and charcoal capacity of the SLCRS filter units 3HVR*FLT3A/B and the ABVS filter units 3HVR*FLT1A/B. The ABVS and SLCRS filter units are required to be designed in accordance with Reg. Guide 1.52, Rev. 2 as stated in FSAR sections 6.2.3, 6.5, and 9.4.3. The degree of compliance with Reg. Guide 1.52 is provided in FSAR Tables 1.8-1 and 6.5-1. Specification 2170.430-065, "Specification for Special Filter Assemblues," states the design requirements for the SLCRS/ABVS filter including RG 1.52, Rev. 2 requirements. Specification 2170.430- 065 makes no exception to RG 1.52, Rev. 2 regarding iodine loading and charcoal quantity.
	CR M3-98-0691 was initiated to provide corrective action plan for the issue identified in DR-MP3-0584. CR M3-98-0691 corrective action plan requires a new calculation to determine the total iodine loading and resultant charcoal capacity. In addition, the corrective action plan requires a new calculation to determine the resulting heat load due to radioactive induced heat. DR-MP3- 0588 and DR-MP3-0724 identified issues with the filter unit water spray system with regard to requirements for charcoal adsorbent cooling. Following approval of the calculations the charcoal adsorbent capacity and cooling mechanisms will be evaluated for.
	compliance with Regulatory Guide 1.52, Rev. 2, positions C.1.c, C.3.i and C.3.k requirements and applicable FSAR sections. Positions C.1.c and C.3.i address the design criteria for charcoal adsorber units including the requirements for iodine removal. Position C.3.k addresses the design criteria for charcoal adsorber heat load removal due to radioactive induced heat which is a function of total iodine loading. The corrective actions will be completed prior to startup.
	NU considers the condition identified by DR-MP3-0584 to be a Significance Level 4 based on lack of calculations to provide justification of Reg. Guide 1.52, Rev. 2 requirements regarding iodine loading. Engineering Record Correspondence (ERC), 25212-ER-98-0129, "SLCRS and ABVS Filter Unit Iodine Loading and Adsorbent Quantity," Rev. 0, dated 4/10/98 provides an evaluation of the filter units while the formal calculations required by CR M3-98-0691 are being developed. ERC 25212-ER-98-0129 is conservatively based on a bounding 3-day iodine release assuming that sprays are ineffective in removing airborne iodine in containment atmosphere. ERC 25212-ER-98-0129 concludes that the post LOCA iodine loading on both filtration units is well below the maximum permissible loading of iodine per Regulatory Guide 1.52, Rev. 2, position C.3.i and the iodine removal capacity of the charcoal filter units

Northeast Utilities	ICAVP	DR No. DR-MP3-0584		
Millstone Unit 3	Discrepancy Report			
	is sufficient. Therefore based on the filter units meet their licensing and o Regulatory Guide 1.52, Rev. 2 requi loading and charcoal capacity.	lesign basis including		
	Attachments: CR M3-98-0691 ERC 25212-ER-98-0129, "SLCRS a Loading and Adsorbent Quantity," R			
	Supplemental Response (M3-IRF-2	347)		
	Per telephone conference between corrective action for Discrepancy Re revised. This response supplement	eport, DR-MP3-0584 will be		
	NU has concluded that the issue reported in DR-MP3-0058 identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. Condition Report (CR) M3-97-00 was written to provide a new calculation which determines total iodine loading and resultant charcoal capacity, and to compare the results against the requirements of the applications of Regulatory Guide 1.52 requirements. Contrary stated in M3-IRF-00975, these actions have been reschedue be completed post startup. The justification provided for the schedule change to "before RFO 6" states that Engineering Record of Correspondence (ERC) No. 25212-ER-98-0129 adoressed the concerns identified in DR-MP3-0584 relative Regulatory Guide 1.52 compliance to position C.3.i. The E documented that the SLCRS and ABVS adsorption filtratio are designed for a maximum loading of 2.5 mg of lodine part of activated carbon and therefore meet the requirement the Regulatory Guide.			
	The ERC was independently review Quality document. Formalizing the calculation will be performed post s on the results of the ERC and defer	esults of the ERC into a start-up, and is justified based		
	Attachments: Revised assignment 98002864-02			
	Revised assignment accordent			
Previously Identified by NU?	? Yes No Non Directory	ant Condition? Yes @ No		
Previously Identified by NU? Resolution Pendir		ant Condition? Yes () No		
Resolution Pendir	ng? Yes No Resolutio	n Unresolved? Yes () No Review Acceptable Needed Date 5/13/98		
Resolution Pendir Initiator: VT Lead:	ng? Yes No Resolutio	n Unresolved? Yes No Review Acceptable Needed Date 5/13/98		
Resolution Pendir Initiator: VT Lead: VT Mgr:	ng? Yes No Resolutio	n Unresolved? Yes () No Review Acceptable Needed Date 5/13/98		
Resolution Pendir Initiator: VT Lead: VT Mgr: IRC Chmn: Date:	rig? Yes No Resolution	n Unresolved? Yes No Review Acceptable Needed Date 5/13/98		

Printed 5/14/98 9:33:01 AM

# ICAVP Discrepancy Report

The methodology described in Reference 1 to estimate the MP3 SLCRS and ABVS iodine loading using the calculational parameters described in Reference 1 has been reviewed and appears to be conservative. The approach of NOT using the spray as an iodine removal mechanism increases the amount iodine postulated to leak from containment being taken-up by the filters.

Based on the results in ERC 25212-ER-98-0129, Rev. 0 this is considered to be a level 4 discrepancy.

Comments on Supplemental Response

None

Northeast Utilities	ICAVP	DR No. DR-MP3-0588
Millstone Unit 3	Discrepancy Re	port
Review Group: Review Element:	System Design	DR RESOLUTION ACCEPTED Potential Operability Issue
Discipline: Discrepancy Type: System/Process:		Yes     No
NRC Significance level:		Date FAXed to NU: Date Published: 11/6/97
Discrepancy:	SLCRS and ABVS Filter Ur	
	During the review of the Su Release System (SLCRS) f Auxiliary Building Ventilatio	pplementary Leak Collection and ilter units 3HVR*FLT3A/3B and the n System (ABVS) exhaust filter units ancy regarding adsorbent cooling was
	'Design, Testing, and Maint Safety-Feature Atmosphere	stone complies with RG 1.52 Rev. 2 enance Criteria for Engineered- e Cleanup System Air Filtration and /ater-Cooled Nuclear Power Plants' th the following exception:
	heat generation from collect the carbon bed temperature overflow, small capacity ES be designed without an air l is taken to the requirement single-failure criteria becau In addition, exception is tak	tions show that the maximum decay ted radioiodines is insufficient to rais above 250°F with no system F atmosphere cleanup systems may bleed cooling mechanism. Exception of any cooling mechanism satisfying se a backup mechanism is provided. en to provide humidity control for the cooling air flow which uses room air umidity.
	Pump, and Heat Exchange	Charging Pump, Component Cooling r Exhaust System is in partial Rev. 2, position C.3.k. Adsorbers em. See Section 1.8.
	Release System is in partia	Supplementary Leak Collection and I compliance with RG 1.52, Rev. 2, rovided with sprinkler system. See
	should consider possible ion autoignition that may result adsorbent and concomitant include a low-flow air bleed for the adsorber section or	The design of the adsorber section dine desorption and adsorbent from radioactivity-induced heat in th temperature rise. Acceptable design system, cooling coils, water sprays other cooling mechanisms. Any satisfy the single-failure criterion.
		ESF filter trains satisfies the in effect at the time of equipment
Printed 5/14/98 9:52:45 AM		on 4.9 Adsorbent Radioactive Decay active decay heating may be Page 1 o

Northeast	t Utilities
Millstone	Unit 3

significant, means shall be provided to remove this heat from the adsorbent beds to limit temperatures to values below which significant iodine desorption will not occur; maximum adsorber temperature shall not exceed 300 F. (NOTE: Consideration must be given to heat of adsorption in determining maximum adsorbent temperature). For this purpose a minimum circulatory air flow shall be available for all operational modes of the unit and shall be based on the maximum possible radioactivity loading on the adsorbent beds. Water spray or deluge systems are not acceptable for this purpose. The use of sprays is acceptable for fire protection (i.e., casualty loss) purposes.

The design air flow for filter units 3HVR\*FLT1A/1b is 30,000 cfm per P&ID EM-148A-24 and the design air flow for filter units 3HVR\*FLT3A/B is 9,500 cfm. At these air flows the filter units are not considered small capacity ESF atmosphere cleanup systems.

The exception to RG 1.52, Rev. 2, position C.3.k implies that there is a calculation that shows that the decay heat from collected radioiodines on the adsorber would not result in the bed temperature exceeding 250°F. UIR 2172 states that this calculation has not been found. The disposition of UIR states that a calculation is to be prepared for the control room filter units but does not address the SLCRS and ABVS filter units.

The use of a sprinkler system for adsorbent cooling per FSAR Table 6.5-1 does not meet the requirements of ANSI N509-1976 section 4.9 which states that water spray or deluge systems are not acceptable for this purpose.

		Valid	Invalid	Needed	Date
initiator:	Stout, M. D.				10/28/97
VT Lead:	Neri, Anthony A				10/28/97
VT Mgr:	Schopfer, Don K				10/30/97
IRC Chmn:	Singh, Anand K				10/31/97
Date:					

INVALID:

Date: 5/12/98

**RESOLUTION:** First Response (M3-IRF-0974)

NU has concluded that the issue reported in Discrepancy Report, DR-MP3-0588, does not represent a discrepant condition. Reg. Guide 1.52 revision 2 does not endorse ANSI N509-1976 position with regards to the use of water spray as an acceptable method of charcoal decay heat removal. Position C.3.k of R.G. 1.52 specifically clossifies water spray cooling of the adsorber section as an acceptable method of decay heat removal. Since Regulatory Guides are higher order documents than ANSI Standards and represent acceptable methods for implementing the NRC's regulations in Appendix A to 10CFR50, a water spray decay heat removal system is considered in compliance with MP3 Licensing basis.

# ICAVP Discrepancy Report

UIR 2172 is specifically referring to the Contro! Room filter units which do not have any decay heat removal mechanisms (i.e. water spray cooling of the adsorber section.) The "conservative calculations" will demonstrate that the decay heat removal systems are not required to prevent iodine desorption and adsorbent auto-ignition in accordance with Reg. Guide 1.52, revision 2.

FSAR Table 3.2-1 does not define the extent of compliance but rather is just a listing of applicable codes and standards. Extent of compliance is defined elsewhere in the FSAR (i.e. Tables 1.8-1, 1.9-1, 6.5-1).

Significance level criteria do not apply as this is not a discrepant condition.

Second Response (M3-IRF-1918)

NU has concluded that item 1 of Discrepancy Report DR-MP3-0588 has identified a condition not previously discovered by NU which requires correction

NU does not yet have a calculation that determines the need for mechanical cooling of the charcoal filters because of heat gain from decay of radioiodine. The attached ERC (Engineering Record Correspondence) 25212-ER-98-0103, prepared by SWEC, in conjunction with calculation 97-EBF-01955-M2, establishes the maximum heat generation rate in the MP3 safety related ventilation filters from deposition of radioactive iodines following a Loss-Of-Coolant Accident. This evaluation assumes that the maximum desorption temperature is 250 °F, which is 50 °F below the minimum desorption temperature of 300 °F,... and approximately 1/3 of the minimum code required carbon ignition temperature of 572 °F.

A formal calculation is in preparation, which will validate the assumption of a 250 °F maximum temperature. The calculation will be completed before mode 2. Meanwhile, the results of the referenced evaluation demonstrate that NU is in compliance with R. G. 1.52. Since the heat load from radiodecay in the MP3 filter units is below that which would lead to autoignition, there is no need for backup cooling. See also the attached review from the NU Radiological Assessment Branch.

Based on the information contained in 25212-ER-98-0103, and calculation 97-EB<sup>r</sup>-01955-M2, NU has concluded that the configuration of filter units 3HVR\*FLT1A/B and 3HVR\*FLT3A/B are in compliance with R. G. 1.52. The approved corrective action to CR-M3-98-0691 will develop a calculation to determine the heat load due to radioactive induced heat in the SLCRS and ABVS filter units. Corrective action is being tracked by AR 98002864-03.

NU considers items 2, 3, and 4 non-discrepant. Items 2 and 3 relate to use of fire protection water for adsorbent cooling, which

Printed 5/14/98 9:52:49 AM

Page 3 of 6

Northeast Utilities		AVP		No. DR-M	AP3-0528
Millstone Unit 3	Discrepa	incy Repo	ort		
	is not required, Concerning item (isolation valves filter equipment accessible to pla Room fire alarm appropriate isola System configur basis, therefore	<ul> <li>4, the "norm) are located rooms, as not ant operators, in a filter unit ation valve to e</li> </ul>	ally closed" del outside (and iso led. They are, who, in respons , must manually extinguish the f s to MP3 licens	uge valves blated from however, se to a Cor y open the ire.	s n) the ntrol esign
	Attachments: Engineering Red Radiological Ass 0103 Calculation 97-E	cord Corresponsessment Bran	ndence 25212-i ach Review of E	ER-98-010	3
	Supplemental R	esponse (M3-	IRF-2339)		
	Per telephone corrective action supplements M3	for DR-MP3-			
	NU has concluded that the issue reported in DR-MP3-0 identified a CONFIRMED SIGNIFICANCE LEVEL 3 con which requires correction.				
	As previously st Correspondence and ABVS filter heat load from r which would lea action for CR M determine heat SLCRS and AB completed post action for CR M will be revised to requirement to p references to us mechanism will completed befor 05.	25212-ER-98 units are in co adiodecay in t d to autoignitio 3-98-0691, wi load due to rai VS filter units. startup. Mear 3-98-0691, FS o take excepti provide backup e of fire prote be deleted. T	B-0103 establish mpliance with the charcoal filt on, and, furthe ill provide a for dioactive induc This corrective while, as addi SAR Table 1.8- on to the R.G. o cooling system ction water as a his corrective a	nes that the R.G. 1.52 ers is below more, com mal calcula ed heat in e action wit tional correct 1 and Tab 1.52, par. ( ms. Also, a cooling action will t	e SLCRS because w that rective ation to the II be ective le 6.5-1 C.3.k
	Attachments: Action Request	Report (A10)	for AR 9800286	54	
Previously Identified by NU?	O Yes O M	io Non D	iscrepant Conditio	m? Yes	No No
Resolution Pendin	g?) Yes 🔘 M	lo Rei	olution Unresolve	nd? Yes	No No
	Stout, M. D.	Acceptable	Not Acceptable	Review Needed	Date 5/12/98
	Neri, Anthony A		Ē		5/12/98
	Schopfer, Don K Singh, Anand K		R		5/12/98 5/13/98
					0/13/90

# ICAVP

## **Discrepancy Report** SL Comments: Comments on First Response NU's response does not adequately address the issues identified in the DR. 1) A calculation that determines the decay heat cooling requirements for filter units 3HVR\*FLT1A/1B and 3HVR\*FLT3A/3B is not available for review. 2) Calculation P(B)-1064, Rev. 0 'Water Flow Discharge Time vs. Water Level in Charcoal Filter Housing' does not address if the water discharge times calculated are adequate to provide sufficient water for adsorbent cooling. 3) The water sprays use fire protection water which may not be available post-accident when adsorbent cooling would be required. 4) P&ID EM-146C shows a normally closed isolation valve (3FPW-V119, -V120, -V122, -V123) upstream of the fire protection deluge valves (3FPW-FV70, 71, 72, 73) that would have to be manually opened to supply water to the filter unit water sprays. The valves are located on elevation 66'-6" in the auxiliary building outside the filter equipment rooms. This area may not be accessible after an accident when adsorbent cooling would be required to prevent iodine desorption and/or autoignition. NU's response does not adequately address heat load due to radiodecay. The exception to the requirement for "...any cooling mechanism satisfying single failure criteria ..." implies that either; (a) the heat load has been calculated to be below that which could lead to autoignition, or (b) autoignition is acceptable, and the resulting fire would be sucessfully extinguished by the fire protection system. UIR 2172 indicates that the heat load due to radiodecay has not been calculated for these filters. Therefore, additional information is needed to support the deviation from this requirement and the acceptability of the potential for autoignition. Comments on Second and Supplemental Responses REFERENCES (1) Engineering Record Correspondence 25212-98-0103, Rev. 0. (2) Calc. 97-EBF-01955-M2, Rev. 0 (3) Calc. MP3LOCA94-01048-R3, Rev. 2 The methodology described in Reference 1 to estimate the MP3 SLCRS peak heat loading using the calculational parameters of MP2 has been reviewed and appears to be conservative. However, the largest heat loading calculated in Reference 2, at

24 hours, may not be the peak value. The heat loading on the filter is a function of containment leakage and the radioactive decay of the various iodine isotopes I-131 through I-135, among other things. Each isotope of iodine, having its own decay rate, has its own peak heat generation rate. It is the sum of the heat generation rates that determines the peak heat generation rate experienced by the filter. From an examination of the summary

# ICAVP Discrepancy Report

DR No. DR-MP3-0588

table shown on page 21 of Reference 2 it is not evident the heat loading at 24 hours is the peak. The time steps do not appear to be fine enough for this determination. More calculations are required at time points around suspected peaks to demonstrate a maximum..

It is estimated that the cooling available due to leakage thru backdraft damper 3HVR\*DMPF13A/B (33 cfm @ 12.5 iwg), entering air temperature of approx 150 °F (120°F entering operating filter unit + temperature rise across heater + temperature rise across operating exhaust fan), and a leaving air temperature of 300°F is on the order of 5000 Btu/hr for the SLCRS filter units. This is sufficiently greater than the 800 Btu/hr heat generation rate contained in reference 1 to conclude that damper leakage will provide adequate airflow for adsorbent cooling for the SLCRS filter units. For the ABVS filter units, leakage thru damper 3HVR\*MOD28A/B would provide for ABVS filter unit adsorbent cooling.

FSAR Table 6.5-1 states that the filter units are in partial compliance with RG 1.52, Rev. 2 position C.3.k regarding absorbent cooling and that the absorbers are provided with a sprinkler system (water sprays). Since the water spray system is non-safety related and cannot be relied on for absorbent cooling this is considered to be a Level 3 discrepancy.

Northeast	t Utilities
Millstone	Unit 3

Review Group:			DR RESOL	UTION ACCEPTE	D
Review Element:	Corrective Action Process			Potential Operab	ility Issue
	Environmnental Qualification	١		O Yes	inty issue
Discrepancy Type:				No No	
System/Process:				- · · ·	
NRC Significance level:	4		1	Date FAXed to NU	1:
				Date Published	1: 11/22/97
Discrepancy:	Technical and Qualit	y Problem	ns with a Ca	alculation	
Description:	Condition Report (CF S&W calculation PR Equipment Qualificat action was taken for Assessment Branch calculation and was the results were acco or QAD output were were checked with si qualification files and	-220, Rev tion in the this CR s performe able to fo eptable. I not availa imilar res	vision 0, title ESF Build ince the NL d an indepe llow the cal in addition, able, the res ults in the N	ed "Radiation I ing". No corre D Radiological endent review culation and d where S&W re sults or assum IU electrical ed	evels for ective of the etermine eference ptions
	1. S&L nuclear and reviewed the technic determined that then package to complete calculation given the	al criticis e is not e ly confirm	ms of the ca nough docu n the techni	alculation and mentation in t ical adequacy	he CR of the
	If the comparison wit files meets the requi alternate calculations Revision 0, for safet showing consistency concerning the ident of input data, assum	rements f s, this ma y related y of result ification c	or design v by be used t use provide is is auditab of the calcul	erification by u o qualify PR-2 ed the docume ble and the crit ation, appropri	use of 20, ntation icisms iateness
	2. CR M3-97-1273 a calculation which do 1976. This guide is Program Topical Re commit to this guide the computer code a documentation or su appropriate), and the redesign of the recon criticisms indicates t meet Unit 3's licensi	also point not meet a commit port. Pre or ASME and run co pport for e fact that mbiner sh hat the qu	s out some Regulatory ment of NU sumably, S NQA-1. Ir build not be some of the the calcula hed among	aspects of the Gude 1.64 da I's Quality Ass &W either had any case, the found, the lack e assumptions ation did not re the other state	ated Juni urance I to e fact that c of (where flect the d
	The lack of sufficien "use as is" dispositio			CR package to	justify th
				Review	
		Valid	Invalid	Needed	Date
	Sheppard, R. P.				11/7/97
	Ryan, Thomas J	$\boxtimes$			11/7/97
	Schopfer, Don K	$\boxtimes$			11/10/9
IPC Chan	Singh, Anand K				11/18/9

# ICAVP Discrepancy Report

DR No. DR-MP3-0632

Date:

	 	 -
IN		

### Date: 5/12/98

**RESOLUTION:** Disposition:

NU has concluded that this issue reported in DR-MP3-0632 has identified a CONFIRMED SIGNIFICANCELEVEL 4 condition which requires correction. The approved corrective action plan in CR M3-98-0613 will be completed post startup and requires revising Calculation PR-220.

CR M3-98-0613, Section 5.1(Cause of Event) states that the calculation, issued in 1980, may not meet 1998 standards in terms of content, flow, format,etc., however, the criticisms identified in CR M3-97-1273 do not effect the results or conclusions of the calculation. NU has detailed an item-by-item response in CR M3-98-0613 to the CR M3-97-1273 criticisms. The item-by-item responses address S&L issues such as: 1) S&W references and QAD outputs, 2) the recombiner shed redesign, and 3) quality requirements in preparation of calculations meeting Unit 3 licensing basis.CRs M3-97-1273 and M3-98-0613 are linked in NU's Corrective Action Program database.

### Conclusion:

NU has concluded that this issue reported in DR-MP3-0632 has identified a CONFIRMED SIGNIFICANCELEVEL 4 condition which requires correction.

The approved corrective action plan in CR M3-98-0613 will be completed post startup and requires revising Calculation PR-220. CR M3-98-0613, Section 5.1(Cause of Event) states that the calculation, issued in 1980, may not meet 1998 standards in terms of content, flow, format,etc., however, the criticisms identified in CR M3-97-1273 do not effect the results or conclusions of the calculation. NU has detailed an item-by-item response in CR M3-98-0613 to the CR M3-97-1273 criticisms. The item-by-item responses address S&L issues such as: 1) S&W references and QAD outputs, 2) the recombiner shed redesign, and 3) quality requirements in preparation of calculations meeting Unit 3 licensing basis. CRs M3-97-1273 and M3-98-0613 are linked in the NU's Corrective Action Program database.

### Attachment:

00 110 00 0010

CR M3-80-0013.		
Previously identified by NU? () Yes () No	Non Discrepant Condition? Yes	No No
Resolution Pending? Yes  No	Resolution Unresolved? Yes	No
Initiator: Sheppard, R. P. VT Lead: Ryan, Thomas J	Acceptable Not Acceptable Needed	Date 5/12/98
		Deen 2 of 2

Frinted 5/14/98 9:34:00 AM

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report			DR No. DR-MP3-0632	
VT Lead: VT Mgr: IRC Chmn: Date:	Kyan, momas J Schopfer, Don K Singh, Anand K 5/12/98				5/12/98 5/12/98
SL Comments:	NU's item-by-item the resulting plan adequate. NU's s up is acceptable s found.	s to revise ca chedule for	alculation revising th	PR-220, Revise calculation	sion 0, are after start-

r ne 3 of 3

Northeast Utilities Millstone Unit 3	ICAV Discrepancy			DR No. DR	-MP3-0648
Review Group:	INTERCOMPANY PRODUCTS AND AND ADDRESS OF A DREAM AND ADDRESS OF		IN THE OWNER AND A DESCRIPTION OF THE OWNER	JTION ACCEPT	ED
Review Element:				otential Opera	
Discrepancy Type: System/Process:	QSS			<ul><li>No</li></ul>	
NRC Significance level:	NA		D	ate FAXed to N Date Publishe	
Discrepancy:	Calculation reference	discren	ancy		
	Calc. # 12179-BE-52		uncy		
	# 12179-BE-52WV,R following discrepancy 1. This calculation wa of equipment foundat calculation is a gener No. 12179-BE-52WV	is provid ion for J ic calcul	ed by NU to unction Box ation for the	confirm the No. 3QSS*J qualification	adequacy B27.This of Dwg.
	equipment could not				
		Mallet	Investid	Review	Dete
Initiator:	Klaic, N	Valid	Invalid	Needed	Date 11/22/97
	Neri, Anthony A	M	H	H	11/22/97
	Schopfer, Don K	M	H	H	12/1/97
	Singh, Anand K				12/3/97
Date:					
INVALID:					
Date:	5/13/98		NTABUNDA: MANENDONE & XAAD AAD	NAME AND ADDRESS OF THE OWNER OWNE	NONA SUPARIORY CARDAZAR
RESOLUTION:	NU has concluded the identified a condition requires correction. T in NRC letter B16901 20 criteria and found concerns and meets t has been written to de RP-4.	not prev his discr and 170 to have the Unit	iously discover epancy mee 010 It has be no operabilit 3 deferral cri	vered by NU ts the criteria en screened y or reportab teria. CR M3	which a specified per U3 Pl bility 3-98-0515
	SECOND RESPONS	E:			
	NU has concluded the	at the ov	erall issue re	ported in Di	screnancy

Report, DR-MP3-0648 does not represent a discrepant condition. The original discrepancy description is:Calc. # 12179-BE-52WV,R0 We have reviewed Millstone Unit 3 Equipment Foundation Calc. # 12179-BE-52WV,R0. Based on this review, we have noted the following discrepancy. 1. This calculation was provided by NU to confirm the adequacy of equipment foundation for Junction Box No. 3QSS\*JB27.This calculation is a generic calculation for the qualification of Dwg. No. 12179-BE-52WV. Specific calculations for the subject equipment could not be found in the aforementioned calculations. Subsequent investigation by NU has determined that specific calculations for each junction box do not exist. The drawing series BE-52 was

ortheast Utilities lillstone Unit 3		CAVP ancy Repo		No. DR-	MP3-0648	
	specifically developed to install a variety of JB sizes and locations. Each drawing would establish several box sizes, locations etc. A seismic calculation for each drawing was issued that justified the junction box installations generically. This encompassed the conditions that can be encountered. Calculation BE-52WV generically provides the justification for this JB.NU believes that providing a calculation which qualifies a standard support detail that encompass the actual conditions is adequate and that individual calculations are not necessary. These calculations were prepared and checked by discipline competent people expressly for this reason.Significance level criteria do not apply as this is not a discrepant condition.					
Previously Identified by NU?			iscrepant Conditio		O No	
Resolution Pendin	g? Yes 🔘	No Re	solution Unresolve	d? Yes	No	
VT Mgr:	Kiaic, N Neri, Anthony A Schopfer, Don K Singh, Anand K 5/13/98	Acceptable	Not Acceptable	Review Needed	Date 5/13/98 5/13/98 5/14/98	
	To defer this DI mounted is nee		that the junctio	n box is a	dequately	
	SECOND RES	PONSE:				
			sition regarding	the eener	de.	

Northeast Utilities Millstone Unit 3	IC/ Discrepar	AVP ncy Repo		DR No. DR	MP3-0695
Review Group:	System	ARTING AND ADDRESS CONTRACTOR	DR RESOLU	JTION ACCEPT	ED
Review Element: Discipline: Discrepancy Type: System/Process:	Mechanical Design Calculation		,	otential Opera Ves No	bility Issue
NRC Significance level:			D	ate FAXed to N	U:
				Date Publishe	d: 12/21/97
Discrepancy:	<b>RWST</b> Insulation		a di se baseri dan 1976 dani base basan sasa		
	FSAR Sec. 6.2.2. cooldown rate be Rev. 0 assumes to thermal insulation up and cooldown	less than 0.2 hat the RWS in order to 0	25F/day. Cal STs are cove conclude tha	culation P(R red with 6 in	)-931, ches of
	There are no desi RWSTs are cover	gn documen	its which der		at the
	There are no desi	gn documen	its which der		at the Date
Initiator:	There are no desi	gn documen red with 6 in Valid	ts which der ches of insul	ation. Review	
	There are no desi RWSTs are cover	gn documen red with 6 in Valid	ts which der ches of insul	ation. Review	Date
VT Lead:	There are no desi RWSTs are cover Wakeland, J. F.	gn documen red with 6 in Valid	ts which der ches of insul	ation. Review	Date 11/22/97
VT Lead: VT Mgr:	There are no desi RWSTs are cover Wakeland, J. F. Neri, Anthony A	gn documen red with 6 in Valid	ts which der ches of insul	ation. Review	Date 11/22/97 11/22/97
VT Lead: VT Mgr:	There are no desi RWSTs are cover Wakeland, J. F. Neri, Anthony A Schopfer, Don K	gn documen red with 6 in Valid	ts which der ches of insul	ation. Review	Date 11/22/97 11/22/97 12/1/97
VT Lead: VT Mgr: IRC Chmn:	There are no desi RWSTs are cover Wakeland, J. F. Neri, Anthony A Schopfer, Don K	gn documen red with 6 in Valid	ts which der ches of insul	ation. Review	Date 11/22/97 11/22/97 12/1/97
VT Lead: VT Mgr: IRC Chmn: Date:	There are no desi RWSTs are cover Wakeland, J. F. Neri, Anthony A Schopfer, Don K	gn documen red with 6 in Valid	ts which der ches of insul	ation. Review	Date 11/22/97 11/22/97 12/1/97
VT Lead: VT Mgr: IRC Chmn: Date: INVALID:	There are no desi RWSTs are cover Wakeland, J. F. Neri, Anthony A Schopfer, Don K Singh, Anand K	gn documen red with 6 in Valid	ts which der ches of insul	ation. Review	Date 11/22/97 11/22/97 12/1/97

### DISPOSITION:

NU has concluded that Discrepancy Report, DR-MP3-0695, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17019 It has been screened per U3 PI-20 criteria and found to have no operability or reportability concerns and meets the Unit 3 deferral criteria. CR M3-98-0515 has been written to develop and track resolution of this item per RP-4.

### CONCLUSION:

NU has concluded that Discrepancy Report, DR-MP3-0695, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010 It has been screened per U3 PI-20 criteria and found to have no operability or reportability concerns and meets the Unit 3 deferral criteria. CR M3-98-0515 has been written to develop and track resolution of this item per RP-4.

# ICAVP Discrepancy Report

# SECOND RESPONSE:

### DISPOSITION:

NU has concluded that the issue reported in DR-MP3-0695 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. The approved corrective action for CR M3-98-1093 will correct Calculation 931P(R), which incorrectly indicates 6" of insulation on the RWST.

The FSAR statement in section 6.2.2.2 applies to heat-up cases. Specification SP-ME-691, General Thermal Insulation, Table 1.1-3, indicates that the RWST was insulated with type J. 4" thick Owens Corning Foamglass. A review of Calc. 931P(R) indicates that 6" insulation with a conductivity of 0.38 Btu per inch per hour was used to calculate the heat-up rate of 0.133 °F. per day. If 4" thick insulation with a conductivity of 0.33 Btu per inch per hour (Corning Foamglass), is substituted, the calculation result changes to 0.163 °F. per day. There is, therefore, a considerable margin between the calculated value and the limit stated in the FSAR. Although Calculation 931P(R) contains various errors that affect the margin between the calculated data and the values stated in the FSAR, the revised final results are judged to be in compliance with the FSAR. Corrective action has been deferred to post startup, and will be tracked to completion by AR 98004262.

### CONCLUSION:

NU has concluded that the issue reported in DR-MP3-0695 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. The approved corrective action for CR-M3-98-1093 will correct Calculation 931P(R) post startup. Although Calculation 931P(R) contains various errors that affect the margin between the calculated data and the values stated in the FSAR, the revised final results are judged to be in compliance with the FSAR. Corrective action has been deferred to post startup, and will be tracked to completion by AR 98004262.

Previously Identified by NU?	🔿 Yes 🔘	No	Non D	iscrepant Conditio	m?() Yes	<ul> <li>No</li> </ul>
Resolution Pending	? Yes 💿	No	Rei	solution Unresolve	d? Yes	No
VT Lead: VT Mgr:	Wakeland, J. F. Neri, Anthony A Schopfer, Don K Singh, Anand K 5/12/98 FIRST RESPO			Not Acceptable	Review Needed	Date 5/12/98 5/12/98 5/12/98

Printed 5/14/98 9:35:35 AM

# ICAVP Discrepancy Report

Sargent & Lundy acknowledges that DR-MP3-0695 is a documentation issue only; however, this design documentation issue my not be defered until after Unit 3 restart.

The FSAR Section 6.2.2.2 requirement for a maximum RWST heat up/cooldown rate of 0.25F/day is a licensing requirement. This licensing requirement is met by Calculation P(R)-931 which assumes that the RWST is covered with 6 -inch thick insulation. Assurance that there is no Unreviewed Safey Question cannot be demostrated unless design documents are located for the 6-inch insulation thickness or a properly-documented walkdown is completed to verify the 6-inch insulation thickness.

SECOND RESPONSE:

Sargent & Lundy concurs that 4 inches of "type J" (Owens Corning Foamglass) would limit the RWST heat up/cooldown rate to less than 0.18F/day. Therefore, NU's evaluation in the second response to DR-MP3-0695 provides an assurance that the licensing commitment that RWST heat up/cooldown rate will be limited to 0.25F/day is met. Sargent & Lundy agrees that correction of RWST heat up/ cooldown calculation P(R)-931 (via CR M3-98-1093 and AR 98004262) can be diferred until after Unit 3 restart.

ortheast Utilities	ICAV			DR No. DR-	MP3-0826
listone Unit 3	Discrepancy	Report			
Review Group:		[	RRESOL	UTION ACCEPT	ED
Review Element:				Potential Ope	v issue
	Mechanical Design			O YES	.,
Discrepancy Type: System/Process:				No No	
NRC Significance lavel:					
			C	Date FAXed to Ni Date Publishe	
Discrepancy:	Comparison Between	PDDS and			
	components not listed			W-TITA TESUL	15 111
Description:	A comparison was ma following comments:	ade betweer	this P&	ID and PDDS	with the
		TRT1C(C-)	versus *	ning PDDS: STR1C in PD STR1D in PD	
	3EGF*V 3EGF*V 3EGF*V	955(A-), Re 956(A-), Re 957(A-), Re 958(A-), Re DIS22D (Ple	ief Valve ief Valve ief Valve ief Valve ase note	in PDDS: e *RV35A(A-) e *RV36A(A-) e *RV36A(A-) e *RV36A(A-) e *RV36A(A-) e that PDDS of GF-PDIS22,	
				only be a typ	0.)
	3EGF-FI		·····,		
	3EGF-FI	CV25B			
	Componente la	0000			
	Components in 3EGF*FI		ot snow	n on P&ID:	
	3EGF*F				
		and the first day and a strain of the second strain of the second		the set of a second set of the second second second second	
	3EGF-F	/31A			
	3EGF-F				
		Y31B			
	3EGF-F	Y31B S25A			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L	Y31B \$25A \$25B \$29A1			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B \$25A \$25B \$29A1 \$29A2			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B 525A 525B 529A1 529A2 525A1			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B 525A 525B 529A1 529A2 525A1 525A2			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B 525A 525B 529A1 529A2 525A1 525A2 525B1			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B 525A 525B 529A1 529A2 525A1 525A2 525B1 525B2			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B 525A 525B 529A1 529A2 525A1 525A2 525B1 525B2 525B1 525B2 529A1			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B 525A 525B 529A1 529A2 525A2 525A2 525B1 525B2 525B2 529A1 529A2			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B S25A S25B S29A1 S29A2 S25A1 S25A2 S25B1 S25B2 S29A1 S29A2 S29B1			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B S25A S25B S29A1 S29A2 S25A1 S25A2 S25B1 S25B2 S29A1 S29A2 S29B1 S29B2			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L	Y31B S25A S25B S29A1 S29A2 S25A1 S25A2 S25B1 S25B2 S29A1 S29A2 S29A1 S29B2 Y21A			
	3EGF-F 3EGF-L0	Y31B S25A S25B S29A1 S29A2 S25A1 S25A2 S25B1 S25B2 S29A1 S25B2 S29A1 S29B2 Y21A Y21B			
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-P 3EGF-P	Y31B S25A S25B S29A1 S29A2 S25A2 S25A2 S25B1 S25B2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29B1 S29B2 Y21A Y21B Y21C			
	3EGF-F 3EGF-L0	Y31B S25A S25B S29A1 S29A2 S25A2 S25A1 S25A2 S25B1 S25B2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S25B2 Y21A Y21B Y21C Y21D		Review	
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-P 3EGF-P 3EGF-P	V31B S25A S25B S29A1 S29A2 S25A2 S25A1 S25A2 S25B2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S25B2 S29A1 S29A2 S25B2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29B1 S29B2 Y21A Y21C Y21D Valid	Invalid	Review	Date
	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-P 3EGF-P 3EGF-P	V31B S25A S25B S29A1 S29A2 S25A1 S25A2 S25B1 S25B2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29B1 S29B2 V21A V21B V21C Valid	Invalid		12/19/97
VT Lead:	3EGF-F 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-L 3EGF-P 3EGF-P 3EGF-P	V31B S25A S25B S29A1 S29A2 S25A2 S25A1 S25A2 S25B2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S25B2 S29A1 S29A2 S25B2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29A1 S29A2 S29B1 S29B2 Y21A Y21C Y21D Valid			

Printed 5/14/98 9:36:41 AM

Page 1 of 4

Northeast Utilities Millstone Unit 3		AVP	-	DR No. DR-MP3-0820				
Millstone Unit 3 Discrepancy Report								
IRC Chmn:	Singh, Anand K				1/13/98			
Date:								
INVALID:								
Date:	5/12/98			NATAOUNTAINE AND A MENOR	ikan dalamini mili dargi sela Langen			
	First disposition: NU has conclude identified a condi requires correction in NRC letter B16 20 criteria and for concerns and me has been written RP-4. Conclusion: NU has conclude identified a condi requires correction in NRC letter B16 20 criteria and for concerns and me has been written in RP-4.	tion not prev in. This discre 3901 and 170 und to have r ets the Unit 3 to develop and d that Discre tion not prev in. This discre 3901 and 170 und to have r ets the Unit 3	pancy Repo pancy Repo pancy Repo pancy Repo pancy Repo pancy Repo pancy Repo pancy discore pancy mee pancy mee pancy mee pancy mee pancy repo pancy repo p	vered by NU ets the criteri en screened iteria. CR M olution of thi olution of thi ent, DR-MP3- vered by NU ets the criteri en screened y or reportal iteria. CR M	Which a specified d per U3 Pl- bility 3-98-0495 s item per 0826, has l which a specified d per U3 Pl- bility 3-98-0495			
	Second disposition NU has concluder identified a CONF which requires co	d that the iss FIRMED SIG						
	The original NU n incorrectly stated corrects that mist disposition and co	the backgrou ake and prov	and from DF	R-MP3-0796	This IRF			
	Items 1 and 2 me and 17010. They found to have no the Unit 3 deferra type of discrepan refueling outage of issues which will 1 attachment 11 is inhibit operations operations in acco NU concludes that accordance with 1 closed to Bin CR	have been s operability of I criteria. U3 cies which wi or later. Attac be completed to correct iss from aligning ordance with it the assignm J3 PI 20 sect	reportabilit PI 20 section II be complete thment 11 de prior to statues prior to the plant s the design to nent of prior tion 1.3.2 e.	U3 PI-20 cr y concerns a en 1.3.2 e de eted during t efines the ty rtup. The int startup that ystems for s basis. rity 4 is corre	iteria and and meets offines the the next ope of tent of would safe ect and in			
	The corrective ac will correct the st D" to "3EGF*STR	rainer design	ation from "	'3EGF*STR	T1C and			
	NU has concluded							

# ICAVP Discrepancy Report

SIGNIFICANCE LEVEL 4 conditions which have been corrected as follows;

Items 3,4,5,and 6; these relief valves are correctly listed in PDDS by their RV number and that the Vxxx number is listed as the alternate. Note that V957(A-) should be (B-) and that this applies to 3EGF\*RV35(B-) and that V958(A-) should be (B-) and that this applies to 3EGF\*F?V36(B-).

Item 7; 3EGF-PDIS22 does not appear in PDDS and that 3EGF-PDIS22D is listed in PDDS.

Items 8 and 9; 3EGF-FICV25A and B is listed in PDDS.

Items 10 and 11; the flow elements are shown on EM-117A, DCN DM3-00-1035-97 written on 7/30/97 added them.

Items 18 through 21 and 24; these numbers are not listed in PDDS.

NU has concluded that items 12 through 17, 22, 23 and 25 through 29 reported in DR-MP3-0826 have identified a NON-DISCREPANT condition.

Items 12 to 17; these are instrument rack cards which are not shown on the P&ID.

Itsm 22; is a duplicate of item 16.

Item 23; is a duplicate of item 17.

Items 25 to 29; these are instrument rack cards which are not shown on the P&ID.

### Conclusion:

NU has concluded that the issues reported in DR-MP3-0826 have identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. The corrective actions in Bin CR M3-98-0217 will correct these items post startup. Items 1 and 2 of this discrepancy meet the criteria specified in NRC letter B16901 and 17010. It has been screened per attachment 11 of U3 PI-20 criteria and found to have no operability or reportability concerns and meets section 1.3.2.e deferral criteria. NU has concluded that items 3 through 11, 18 through 21 and 24 reported in DR-MP3-0826 have identified a confirmed significance level 4 conditions which have been corrected in PDDS and the P&ID. NU has concluded that items 12 through 17, 22, 23 and 25 through 29 reported in DR-MP3-0826 have identified a nondiscrepant condition, these are instrument rack cards that are not shown on the P&ID or are duplicate discrepancies of items 16 and 17.

Previously Identified by NU?	Yes	۲	No	Non Discrepant Condition? Yes	۲	No
Resolution Pending?	Yes	۲	No	Resolution Unresolved? Yes	۲	No
				Review		

Printed 5/14/98 9:36:45 AM

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report			DR No. DR-MP3-0826		
VT Mgr:	Obersnel,Bojan. Neri, Anthony A Schopfer, Don K Singh, Anand K 5/12/98	Acceptable	Not Acceptable	Needed	Date 5/12/98 5/12/98 5/12/98	
SI. Comments:	S&L comment of The NU response discrepancy. Th 3HVR*V219 class	e M3-IRF-010 e subject of t	695 does not ad his NU respons			
	S&L comment of S&L agrees with Response Form, referenced Cond previously subm	the NU dispo Response M ition Report itted Response	osition as descri 13-IRF-02098 (c CR M3-98-0495 se M3-IRF-0169	bed in the opy of the was attac 95). S&L a	ched to also agree	

that the remaining issues meet the deferral criteria, and that the

corrective action can be completed after the startup.

Printed 5/14/98 9:36:47 AM

Northeast	t Utilities
Millstone	Unit 3

# CAVP Discrepancy Report

DR	No	DR-MP3-0832
DK	NO.	DK-MP 3-0032

SANDARY COLORADA WANA AMMIN'NY INSA DALAY CANANA MIN'NA MININA MININA MININA MININA MININA MININA MININA MININA	A STATE OF COMPACT AND	STATISTICS IN THE OWNER AND THE	ort	A STATE A STATE OF THE STATE OF T	COLUMN AND AND ADDRESS OF ADDRESS	
Review Group:			DR RESOLU	TION ACCEPT	ED	
Review Element:			P	otential Operal	bility issue	
	Piping Design			O Yes	,	
Discrepancy Type:				No No		
System/Process:						
NRC Significance level:	4		Di	ate FAXed to N	U:	
				Date Publishe	d: 1/10/98	
Discrepancy:	Conflicting Inform Drawings	ation Betwee	en PDDS an	d Pipe Isome	etric	
Description:	<ul> <li>Regarding P&amp;ID EM-177A, Rev.10, Pipe line numbers 3-E0 001-057-3 through 3-EGF-001-060-3, there is a discrepend that the applicable pipe design table, CL 0152, requires sch 40 weight pipe, but the PDDS system shows the pipe as schedule 10 weight. The isometric drawings are not definiti that they show 10s, 40s and 80s information. The isometric drawings are CP-360530 (9&amp;11) and CP-36053 (18&amp;20).</li> <li>Also, for pipe line numbers 3-EGF-002-028-3 and 3-EGF-0 031-3, PDDS show pipe wall thickness as standard weight.</li> </ul>					
	whereas pipe tabl isometrics CP-360	0252, CP-36				
	the wall schedule.	•		Devidence		
		Valid	Invalid	Review Needed	Date	
Initiator:	Russ,Earl.				12/18/97	
	Neri, Anthony A		L	H	12/19/97	
			Ц	Ц		
	Schopfer, Don K Singh, Anand K		Н	Ц	12/23/97 12/31/97	
					12/31/9/	
Date:						
INVALID:						
Date:	5/13/98	OON DEBHUK VIS AND AND A DIALEK STATUTA	AN TIMAN DIPERTIK (LISPANIS COMOLO)	dan talah karya sebelah karaya (Kona seba	NY DIA MARAKATRA DIA MARAKATRA (PADA	
RESOLUTION:	First disposition: NU has concluded identified a condit requires correctio in NRC letter B16 20 criteria and fou concerns and met has been written t RP-4. Conclusion: NU has concluded identified a condit requires correctio	tion not prev n. This discr 901 and 170 and to have ets the Unit to develop a d that Discretion not prev n. This discr	epancy mee 10 It has be no operabilit 3 deferral cri nd track reso epancy Repo iously discover epancy mee	rt, DR-MP3-f vered by NU ts the criteria en screened y or reportab teria. CR M3 olution of this olution of this vered by NU ts the criteria	which a specified per U3 PI- bility 3-98-0495 s item per 0832, has which a specified	
	in NRC letter B16 20 criteria and for concerns and me	901 and 170 und to have ets the Unit	010 It has be no operabilit 3 deferral cri	en screened y or reportat teria. CR M3	per U3 Pl- pility 3-98-0495	
	has been written t RP-4. Second dispositio		no track rest			

Northeast Utilities	ICA	VP	DR	No. DR-N	AP3-0832	
Millstone Unit 3	Discrepan	cy Repo	ort			
	NU has concluded that the new issue reported in Discrepancy Report, DR-MP3-0832 does not represent a discrepant condition CR M3-98-0495 was closed to CR M3-98-0217. Bin CR M3-98- 0217 corrective actions will correct PDDS, post startup. NU considers the overall classification of this DR as significance level 4. The original DR description was; Regarding P&ID EM-177A, Rev.10, Pipe line numbers 3-EGF- 001-057-3 through 3-EGF-001-060-3, there is a discrepency in that the applicable pipe design table, CL 0152, requires schedul 40 weight pipe, but the PDDS system shows the pipe as schedule 10 weight. The isometric drawings are not definitive in that they show 10s, 40s and 80s information. The isometric drawings are CP-360530 (9&11) and CP-36053 (18&20).					
	Also, for pipe line i 031-3, PDDS show whereas pipe table isometrics CP-360 the wall schedule.	pipr 11	EGF-002-028-3 thickness as sta hows schedule 0519 and CP-3	ndard weig 80. The pip	ht, be	
	For line numbers 3 schedule 10 piping a one time deviation schedule 40 or 80. The isometric draw that the approximal attaches to the equipart match that equipart action is required.	was instal on from the PDDS corn vings clearl tely last 6" upment cha	led as per E&DO specifications of ectly lists the pil y show the pipe at the end of th anges to schedu	CR N-ME-0 requirement pe as schei as schedu e pipe run ule 40 or 80	1582 as t of dule 10. le 10 and that ) to	
	For line numbers 3 material take off is discrepancy exists PDDS is incorrect schedule 80 by the startup.	ometrics cl no correcti for 3-EGF-	early shows the ve action is req	pipe class uired. will be revis	. No sed to	
	Conclusion: NU has concluded Report, DR-MP3-0 CR M3-98-0495 wa 0217 corrective ac considers the over level 4.	832 does n as closed to tions will co	ot represent a c CR M3-98-021 prrect PDDS, po	liscrepant of 7. Bin CR ost startup.	M3-98- NU	
Previously identified by NU?	🔿 Yes 🔘 No	Non D	iscrepant Conditio	n?() Yes	No No	
Resolution Pendin	g? Yes 🖲 No	Re	solution Unresolve	d? Yes	No	
VT Lead:	Obersnel,Bojan. Neri, Anthony A	Acceptable	Not Acceptable	Review Needed	Date 5/13/98 5/14/98	
	Schopfer, Don K Singh, Anand K				5/14/98	
Date:	5/13/98		hand	housed		

Iortheast Utilities Aillstone Unit 3	ICAVP Discrepancy Report	DR No. DR-MP3-0832
SL Comments:	S&L comments on the first MU dispondent of the second seco	since it fails to identify what
	S&L comments on the second NU d	lisposition:

DR RES				
DR RES				
	OLUTION ACCEPT	TED		
	Potential Operability Issue			
	Yes			
	No			
0.10				
	Date FAXed to N	IU:		
	Date Publishe	ed: 1/17/98		
<ul> <li>Puct Support Discrepancy</li> <li>We have reviewed the Misc. Platform calculation no C29.347, Rev.0, dated 12/14/81.</li> <li>Based on this review we have noted the following discussion</li> </ul>				
	bolts used to co t been addresse			
Invalid	Review	Dete		
invano	Needed	12/22/07		
	1	12/22/97		
	L L	12/20/97		
Ц	Ц	12/23/97		
LJ		1/13/98		
an and the state of the state o		NE CONCEMPTORIANTO PARAMANANA		
eviously dis crepancy m 7010 It has e no operab it 3 deferral	eport, DR-MP3-( covered by NU neets the criteria been screened bility or reportab I criteria. CR M3 resolution of this	which a specified per U3 Pl bility 3-98-0515		
IGNIFICAN prrection of the the the correction of the mew issue real is identified a current equation the calculation this platform and 3EGD-S	n is 3EGD-P1A SP1A Oil Separa were supplied to -241 by the dies	AP3-0871 EPANT INP3-0871 EPANT Inuration is Pent rm design. ator. Both the sel		
	e calculation this platform and 3EGD-s on QA and w in 2447.300	e calculation for the platfor this platform is 3EGD-P1A and 3EGD-SP1A Oil Sepan on QA and were supplied to in 2447.300-241 by the dies ntial seismic interaction cor		

Northeast Utilities Millstone Unit 3	ICA Discrepar	AVP ncy Repo		No. DR-N	1P3-0871
	hazards program. NU considers DR- corrective actions MP3 startup.				
Previously Identified by NU?	🔿 Yes 🔘 No	Non D	iscrepant Conditio	m? Yes	No
Resolution Pending	g? Yes 🖲 No	Rei	solution Unresolve	d? Yes	No No
VT Mgr: IRC Chmn: Date:	Klaic, N Neri, Anthony A Schopfer, Don K Singh, Anand K 5/12/98 To defer this DR, anchored to the ex				Date 5/12/98 5/12/98 5/12/98

S & L concurs with NU that the mounting of non-safety related item is a deferrable issue.

1.4

10

],

0

Northeast	t Utilities
Millstone	Unit 3

## ICAVP **Discrepancy Report**

Review Group:	Configuration
<b>Review Element:</b>	System Design
Discipline:	Electrical Design
Discrepancy Type:	Drawing
System/Process:	HVX
RC Significance level:	4

#### DR RESOLUTION ACCEPTED

Potential Operability Issue ) Yes

No No

Date FAXed to NU: Date Published: 1/18/98

Discrepancy: Miscellaneous Drawing Errors

Description: The following design document (drawing) anomalies were noted during the preparation for and conduct of system walkdowns

> 1. P&ID EM-148E, Rev. 10 (Boundary Document Revision) indicates that the heater elements within filter units 3HVR\*FLT3A and B have control switches located on control room panel VP1. These switches are not shown on the elementary diagram (ESK-6AHB, Rev. 4), the vendor drawing (2170,430-065-070 Rev. C) nor on the control panel drawings. These switches were not observed on the Panel VP1.

> 2. The Cable and Raceway Control Program (TSO2) indicates a service function of "spare" for cables 3HVRAOC700 and 703, however the cable is not tagged with an asterisk ("\*") indicating it is spare and the cable appears on circuit drawings as used.

> 3. The Cable and Raceway Control Program (TSO2) lists incorrect connection diagrams for the following cables: 3HVROX298, 3HVRAOX252, 3HVRBPX246, and 3HVRBPC215.

4. Drawing EE-12J Rev. 4, lists cable 3HVPCOC521 at junction box 3HVP\*JB20C going to junction box 3JB\*8609. At junction box 3JB\*8609 the cable is identified as 3HVPAOC521.

5. Drawing 3HVP-029B-1 Rev. 3 has cable 3HVPDPX220 shown twice. The cable at 3HVP\*JB20B should be 3HVPBPX220.

6. Drawing EE-6AX, Rev. 4 shows both cable 3RMSNPC101 and 3RMSNPX420 with the same designator "G" at the terminal block/points. It is not feasible for two different cables to have the same internal continuation designator.

7. Drawing EE-18BF, Rev. 5 incorrectly shows cable 3HVRAOK010 at panel 3HVR\*PNL-FLT-3A (correct number is 3HVRAOK011). Additionally, the drawings incorrectly shows cable 3HVRBPL010 at panel 3HVR\*PNL-FLT-3B (correct number is 3HVRBPL011).

8. Conduit 3CX987NS8 is installed between equipment 3HVR\*RIV10A AND 3HVR\*RIV10B. This conduit is routed completely within the Auxiliary building at elevation 66'-6". The Cable and Raceway Control Program (TSO2) manual indicates that conduits with numbers in the range of 986 to 989 (i.e., this conduit) are located in the Main Steam Valve Building. This conduit number appear to violate the number standards.

9. The Cable and Raceway Control Program (TSO2) incipates

Northeast Utilities Millstone Unit 3	IC/ Discrepar	AVP ncy Repo		DR No. DR-	MP3-0925
	one of the connect "68F," the correct			3RMSNNX63	8 is
	10. Connection D the cables enterin and 504. The cor	g junction b	ox 3JB*2015	as 3HVRCA	OC503
	11. P&ID EM1488 indicates that term indicating (i.e., ter indication). Field have local indicat with the P&ID. Th and TIS tags. Th drawings as well a (TSO2). This use these drawings. I 099 Rev. B, ident show that the inst the description do	perature sw mperature in verification ion and then hese instrum e TS tag is t as in the Cal of the TS is However, the ifies the inst rument also	itches TIS-10 dicating swit verified that efore the ins nents were for used on the I ble and Race s consistent e vendor dra ruments as ' carries the T	09A, B, and C tches that pro these switch tallation is co ound to have cop and layo eway Control with the funct wing, 2472.9 'TS"s only an TIS tag.; it is	C are by ide local es do onsistent both TS ut Program tion and 00-609- od fails to
		Mallat	Investid	Review	Data
Initiatory	Caput T I	Valid	Invalid	Needed	Date 1/6/98
	Sarver, T. L.		Ц	Ц	1/5/98
	Neri, Anthony A		Ц	H	1/12/98
	Schopfer, Don K Singh, Anand K		Ц	Ц	1/14/98
	Singh, Anano K				1/1-9-20
Date:					
INVALID:					
Date:	5/13/98	COMENTAL CONTRACTOR OF CONT		ALV LANDA AVAILATION AVAILATION AVAILATION	OLUTION STATE & ALL MERCHARD
RESOLUTION:	FIRST RESPONS	SE:			
	Disposition:				
		d that Disor	Dancy Deno	H DR.MP2	025 has

NU has concluded that Discrepancy Report, DR-MP3-0925, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17010. It has been screened per U3 PI-20 criteria and found to have no operability or reportability concerns and meets the Unit 3 deferral criteria. CR M3-98-0971 has been written to develop and track resolution of this item per RP-4.

### Conclusion:

NU has concluded that Discrepancy Report, DR-MP3-0925, has identified a condition not previously discovered by NU which requires correction. This discrepancy meets the criteria specified in NRC letter B16901 and 17C10. It has been screened per U3 PI-20 criteria and found to have no operability or reportability concerns and meets the Unit 3 deferral criteria. CR M3-98-0971 has been written to develop and track resolution of this item per RP-4. SECOND RESPONSE:

Disposition:

NU has concluded that the issues reported in DR-MP3-0925 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction.

After further review, NU concurs with S&L's opinion that the corrective action for Item 1 does not meet the deferral criteria for "Operations Critical Drawings". Therefore, CR M3-98-2383 has been initiated to document this condition for resolution and the corrective actions for this CR will correct P&ID EM-148E prior to startup.

Conclusion:

NU has concluded that the issues reported in DR-MP3-0925 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. After further investigation, NU concurs with S&L's opinion that the corrective action for Item 1 does not meet the deferral criteria for "Operations Critical Drawings". The corrective actions for CR M3-98-2383 will correct P&ID EM-148E prior to startup.

Previously Identified by NU? Resolution Pendir	-	<ul><li>No</li><li>No</li></ul>		iscrepant Conditio	-	<ul><li>No</li><li>No</li></ul>
<b>initiat</b> ce*	Morton, R.		Acceptable	Not Acceptable	Review Needed	Date
VT Leao VT Mar:	Neri, Anthony A Schopfer, Don H					5/13/98 5/13/98
	Singh, Anand K			R	R	5/14/98
Date:	5/13/98		-	-		

SL Comments: FIRST RESPONSE:

Item 1: S&L's opinion is that this item does not meet the deferral criteria for "Operations Critical Drawings" as defined in the Project Instructions PI-MP3-11, Attachment 6.9. The handswitch shown on P&ID EM-148E "may ... mislead the user".

Items 2 - 11: S&L agrees with NU's response.

SECOND RESPONSE:

S&L agrees with NU's response.

Northeast Utilities Millstone Unit 3	ICA Discrepan		ort	DR No. DR-	MP3-0983
Review Group:	System	ANNERS A MET SCHOOL STATISTICS AND STATISTICS	DR RESOL	UTION ACCEPT	ED
Review Element: Discipline: Discrepancy Type: System/Process:	Piping Design Calculation			Potential Operal Ves No	bility Issue
NRC Significance level:	4			Date FAXed to N	U:
				Date Publishe	d: 1/25/98
Discrepancy:	Mounting detail qu be verified	alification f	or ductmour	nted radmonit	or can no
Description:	Calculations for the 3HVR-006039-3, 3 be located. These monitor sample po Sketches B-313A-3 Qualification of the shown on the above	HVR-750-4 lines are us ints in duct 5 and B-313 e connectio	6-3 and 3H sed to protect work. The li 3B-6, Specifi n of these lin	VR-750-49-3 ct leak tight rances are identification SP-M nes to the due not be verifie	could not adiation fied on E-573. ctwork, as
		Valid	Invalid	Review	Date
Initiator:	Prakash, A.				1/16/98
VT Lead:	Neri, Anthony A		Ē	H	1/16/98
VT Mgr:	Schopfer, Don K		Ē	Ē	1/20/98
IRC Chmn:	Singh, Anand K				1/22/98
Date:					
INVALID:					
Date:	5/12/98	and an	IN INCOMENDATION OF A DESCRIPTION OF A DESC		NAR DELEMINENTIK MENNEN OMMEN (MENNEN)
RESOLUTION:	First Response				

### ID: M3-IRF-01838

### Disposition

NU has concluded that Discrepancy Report DR-MP3-0983 has identified a condition not previously discovered by NU for which corrective action is complete. As a result of investigation into Condition Report (CR) M3-98-0666, standard calculation 12179-NM(S)-767-CZC has been located. Results of this calculation were translated during plant design into the document of origin for these connections, which is SWEC specification 2280.000-627, pages 105 and 106.

The drawings in the SWEC specification were later translated into Sketches B-313A-5 and B-313B-6, Specification SP-ME-573. Since the document of origin has been available to the station, and only the supporting calculation was needed, this issue is considered a level 4 significance.

#### Conclusion:

NU has concluded that Discrepancy Report DR-MP3-0983 has identified a condition not previously discovered by NU for which corrective action is complete. As a result of investigation into Condition Report (CR) M3-98-0666, standard calculation 12179-NM(S)-767-CZC has been located. Since the Engineer's design drawings have been available and the installation is consistent

Northeast	Utilities
Millstone L	Jnit 3

# ICAVP Discrepancy Report

with the drawings, only the source calculation was needed. Therefore this issue is a level 4 significance.

Attachments:

Condition Report M3-98-0666 Calculation 12179-NM(S)-767-CZC SWEC Specification 2280.000-627, pages 105 and 103

Second Response

ID: M3 - IRF - 02313.

#### Disposition:

NU has concluded that this issue reported in DR-MP3-0983 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. The approved corrective action plan for condition report (CR) M3-98-2271 will revise calculation 12179-NM(S)-767-CZC to include the remaining lines in question. Action will be completed post startup.

### Conclusion:

NU has concluded that the issue reported in DR-MP3-0983 has identified a CONFIRMED SIGNIFICANCE LEVEL 4 condition which requires correction. The approved corrective action plan for CR M3-98-2271 will revise calculation 12179-NM(S)-767-CZC to include the remaining lines in question. Action will be completed post startup.

### Attachment:

Condition Report M3-98-2271 with approved corrective action plan Non Discrepant Condition? Yes Previously Identified by NU? () No O Yes No Resolution Pending? Yes No No Resolution Unresolved? Yes (B) No Review Acceptable Not Acceptable Date Needed Initiator: Olson, P.R. 5/12/98  $\boxtimes$ VT Lead: Neri, Anthony A  $\boxtimes$ 5/12/98 VT Mgr: Schopfer, Don K  $\boxtimes$ 5/12/98 IRC Chmn: Singh, Anand K Date: 5/12/98 SL Comments: First Response ID: M3-IRF-01838 Calculation 12179-NM(S)-767-CZC Rev.0 was performed to qualify nozzles for 3CMS\*RE22A/B and 3HVR\*RE19 B. This addresses line 3HVR-006-039-3 but nothing has been mentioned about the qualification of lines 3HVR-006-36-3, 3HVR-750-46-3 and 3HVR-750-49-3. The qualification of these lines is presumably similar to those addressed by the calculation, therefore we concur with NU that this issue is a level 4 significance. The calculation should be revised to include the gualification of these lines.

# ICAVP Discrepancy Report

Second Response ID: M3-IRF-02313

The corrective action plan, revising the subject calculation to address the qualification of the additional lines, is acceptable.

ortheast Utilities	ICA\	/P		DR No. DR-MP3-101			
Aillstone Unit 3	Discrepancy Report						
Review Group:	System	Lift. III ann far bann tha an ann an	DR RESOLU	TION ACCEPTE	D		
Review Element:	System Design		P	otential Operab	ility lecus		
	Mechanical Design		Potential Operability Issue				
Discrepancy Type:			No				
System/Process:							
NRC Significance level:	4	ite FAXed to NU	1:				
				Date Published	1: 2/7/98		
Discrepancy:	Revision of Calculat	ion US(B)	273 for DCF	R M3-97045			
Description:	The purpose of US( containment pressur design basis LOCAs	re and tem			tulated		
	Two discrepancies v	vere identi	fied in US(B	)-273:			
	US(B)-273. US(E delay, ZSTART, of the US(B)-273 QSS effective tin a. For a pump dise ESF, the seque that a CDA sign but that QSS do into the event b. For a 0.6 pump ESF, the seque that a CDA sign but that QSS do into the event c. For a 3 ft2 pum	to 68.6 se analysis a me: charge dou ence of eve hal is gene bes not be suction do ence of eve hal is gene bes not be bes not be a time de p suction to	c after a CD. are not consi uble-ended r ents (Table 7 rated 1.4 sec come effecti lay of 70.1 s puble ended ents (Table 8 rated 2.0 sec come effecti lay 69.5 sec preak with M	A. Three results stent with this upture with N (, p. 20) state c into the eve ve until 71.5 sec. rupture with I (, p. 21) state c into the eve ve until 71.5 c. c into the eve ve until 71.5 c.	ults s Min. s ent, s ec Min s ent, sec		
	sequence of ev				DA		
	signal is genera QSS does not t event a time	become ef	fective until	ent, but that 71.5 sec into			
	QSS does not b	ecome eff delay of 6 events in ates that Q ion double , p. 18). Th y level set culation wa	the results s SS spray sto ended rupto his 10,000 se point require as reference	71.5 sec into ection of ops 10,000 se ure event with ec time to rea s an analytic d. The ICAVE	the ec n ch al o		
	<ul> <li>QSS does not to event a time</li> <li>2. The sequence of US(B)-273 indicatinto a pump suct Min. ESF (Tbl. 5 the RWST empty basis, but no call reviewer could not a sequence of the court of</li></ul>	become eff delay of 6 events in ates that Q ion double , p. 18). Th y level set culation wa ot locate a	fective until 8.5 sec. the results s SS spray sto ended rupto his 10,000 se point require as reference calculation	71.5 sec into ection of ops 10,000 se are event with ec time to rea s an analytic d. The ICAVF which compu- usions of US	the ec ach al s utes		
	QSS does not t event a time 2. The sequence of US(B)-273 indica into a pump suct Min. ESF (Tbl. 5 the RWST empty basis, but no call reviewer could n this quantity. These errors have lit	ecome eff delay of 6 events in ates that Q ion double , p. 18). Th y level set culation wa ot locate a	fective until 8.5 sec. the results s SS spray sto ended rupto his 10,000 se point require as reference calculation on the concl	71.5 sec into ection of ops 10,000 se ure event with ec time to rea s an analytic d. The ICAVF which compu- usions of US Review	the ec nch al otes (B)-273,		
	QSS does not the event a time 2. The sequence of US(B)-273 indicatinto a pump such Min. ESF (Tbl. 5 the RWST empty basis, but no call reviewer could neviewer could not this quantity. These errors have like Rev. 6.	vecome eff delay of 6 events in ates that Q ion double , p. 18). Th y level set culation we ot locate a ittle effect	fective until 8.5 sec. the results s SS spray sto ended rupto his 10,000 se point require as reference calculation	71.5 sec into ection of ops 10,000 se are event with ec time to rea s an analytic d. The ICAVF which compu- usions of US	the ec n al och al o ttes (B)-273, Date		
	QSS does not the event a time 2. The sequence of US(B)-273 indication into a pump such Min. ESF (Tbl. 5) the RWST empty basis, but no call reviewer could not this quantity. These errors have like Rev. 6.	ecome eff delay of 6 events in ates that Q ion double , p. 18). Th y level set culation wa ot locate a ittle effect Valid	fective until 8.5 sec. the results s SS spray sto ended rupto his 10,000 se point require as reference calculation on the concl	71.5 sec into ection of ops 10,000 se ure event with ec time to rea s an analytic d. The ICAVF which compu- usions of US Review	the ec n al oth al ottes (B)-273, Date 2/2/98		
VT Lead:	QSS does not t event a time 2. The sequence of US(B)-273 indica into a pump suct Min. ESF (Tbl. 5 the RWST empty basis, but no call reviewer could n this quantity. These errors have li Rev. 6. Wakeland, J. F. Neri, Anthony A	ecome eff delay of 6 events in ates that Q ion double , p. 18). Th y level set culation wa ot locate a ittle effect Valid	fective until 8.5 sec. the results s SS spray sto ended rupto his 10,000 se point require as reference calculation on the concl	71.5 sec into ection of ops 10,000 se ure event with ec time to rea s an analytic d. The ICAVF which compu- usions of US Review	the ec al och al o vites (B)-273, (B)-273, Date 2/2/96 2/2/98		
VT Lead: VT Mgr:	QSS does not the event a time 2. The sequence of US(B)-273 indication into a pump such Min. ESF (Tbl. 5) the RWST empty basis, but no call reviewer could not this quantity. These errors have like Rev. 6.	vecome eff delay of 6 events in ates that Q ion double , p. 18). Th y level set culation we ot locate a ittle effect	fective until 8.5 sec. the results s SS spray sto ended rupto his 10,000 se point require as reference calculation on the concl	71.5 sec into ection of ops 10,000 se ure event with ec time to rea s an analytic d. The ICAVF which compu- usions of US Review	the ec n al oth al ottes (B)-273, Date 2/2/98		

Printed 5/14/98 9:40:27 AM

## ICAVP Discrepancy Report

NVACIO:

#### Date: 5/12/98

RESOLUTION: DISPOSITION:

NU has concluded that Discrepancy Report DR-MP3-1015 has identified issues not previously discovered by NU which require correction. The approved corrective action plan for CR M3-98-1054 (attached) will correct C alation US(B)-273 with respect to each of the discrepancies identified after startup. The revised results will then be carried forward into the calculations and documents which use results from US(B)-273 as an input.

CR M3-98-0619 (attached) contains the corrective action plan to complete the review of all RSS and QSS related calculation discrepancies identified by the ICAVP program. This corrective action will be completed after startup and will ensure that the errors in US(B)-273 are clearly identified and addressed. The corrective action plant for CR M3-98-1504 is tied to CR M3-98-0619 by AR 98002805.

As part of the ICAVP program, trending CR M3-98-1132 has been written to ensure that any process-related issues related to these calculations are clearly identified and are being dealt with. This assessment is scheduled to be completed prior to startup.

Each of the discrepancies in DR-MP3-1015 has been reviewed by NU design engineers, who have determined that none of the discrepancies impacts the operability of the RSS system. As such there is no effect on the license or design basis.

### CONCLUSION:

NU has concluded that Discrepancy Report DR-MP3-1015 has identified issues not previously discovered by NU which require correction. The approved corrective action plan for CR M3-98-1054 (attached) will correct Calculation US(B)-273 with respect to each of the discrepancies identified after startup. In addition, an assessment will be performed, prior to startup, of the issues related to calculational discrepancies. This will ensure that these issues are clearly identified and addressed. Each of the discrepancies identified in DR MP3-1015 has been reviewed by NU, and none of them affect the conclusion that the RSS system meets its design basis. As such there is no effect on the license or design basis.

Previously Identified by NU?	0	Yes	۲	No	Non D	iscrepant Conditio	on? Yes	<ul><li>No</li></ul>
Resolution Pending	g?()	Yes	۲	No	Re	solution Unresolve	d? Yes	No
initiator: VT Lead: VT Mgr: IRC Chmn: Date:	Neri, Schoj Singh	Anthon pfer, Do	y A on K d K		Acceptable	Not Acceptable	Review Needed	Date 5/12/98 5/12/98 5/12/98

Printed 5/14/98 9:40:30 AM

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report	DR No. DR-MP3-1015
	Sargent & Lundy agrees that CR M issues identified in DR-MP3-1015.	

The discrepancies in QSS pump effective times are no more than 1.5 seconds. For all of the post-LOCA QSS effective times modeled, QSS spray commences after the peak containment temperature and pressure is reached. The discrepancy in QSS pump stop time occurs well after the minimum NPSHa condition for the RSS pumps. Therefore Sargent & Lundy concludes that the errors identified in DR-MP3-1015 do not place the QSS or containment systems outside of their design and licensing bases, and they may be corrected after Unit 3 restart.

neast Utilities	ICAVP		C	DR No. DR-M	P3-1018
one Unit 3	Discrepancy F	Report			
Review Group:	System	D	RRESOLUT	TION ACCEPTE	D
Review Element: Discipline: Discrepancy Type: System/Process: NRC Significance level:	Mechanical Design Calculation NEW			otential Operabil Ves No te FAXed to NU:	
				Date Published:	
61	De delas el Osta dation	110(0) 00			21100
	Revision of Calculation The purpose of US(B)-2 containment pressure a design basis main stear	66, Rev. nd tempe	3 is to det rature resp	ermine the	ulated
	Three discrepancies we	re identifi	ed in US(I	B)-266:	
	<ol> <li>The QSS effective ti 7, pp. 1 and 8, Attac US(B)-253 changed sec after CDA. The rather than 73.7 sec (Table 2, p. 31), and 72.6 sec, after the p p. 32).</li> <li>The inputs for HHSI with Max. ESF (p. 4 The correct source of US(B) 254 Payr 0:</li> </ol>	hment 8, the QSS conseque , after the i QSS init ostulated injection of Att. 7,	pp. 1 and effective to nces are 0 postulate iates 75.2 MSLB at 3 mode flow and p. 4 o	8), but Rev. time, ZSTAR QSS initiates d MSLB at 75 seconds, rati 25% power (1 v for postulate of Att. 8) are i	5 of 76.3 sec, 5% power her than Table 3, ed MSLB: ncorrect.
	US(B)-361, Rev. 0:	Incom	art	Correct	
	Head	Flov		Flow	
	(psid)	(gpn		(gpm)	
	-23.4	1707		1467	
	0.0	1698		1458	
	500	1466		1250	
	1000	1181		990	
	1500	657		434	
	2000	407		322	
	2400	256	•	190	
	<ol> <li>The inputs for HHSI MSLBs with Max. E incorrect. This flow correct source of thi pp. 61 and 62 of US</li> </ol>	SF (p. 4 c should be is input is	of Att. 7, a 1553 gpr Case 5 of	nd p. 4 of Att n, not 2734 g	. 8) are pm. The
				lucione of LIC	(B)-266,
	These errors have little Rev. 3.	effect or	the concl		
	Rev. 3.			Review	
	Rev. 3.	Valić	Invalid		Date
	Rev. 3. Wakeland, J. F.	Valić	Invalid	Review	Date 1/31/98
	Rev. 3.	Valić		Review	Date 1/31/98 2/2/98
VT Lead	Rev. 3. Wakeland, J. F.		Invalid	Review	Date 1/31/98

Printed 5/14/98 9:40:53 AM

Page 1 of 3

# ICAVP **Discrepancy Report**

#### Date: 5/12/98

ISTY ALL DU

RESOLUTION: DISPOSITION:

NU has concluded that the issues reported in Discrepancy Report, DR-MP3-1018, have identified conditions not previously discovered by NU which require correction. The approved corrective action plan for CR M3-98-1505 (attached) will correct Calculation US(B)-266 with respect to each of the discrepancies identified after startup. The revised results will then be carried forward into the calculations and documents which use results from US(B)-266 as an input.

CR M3-98-0619 (attached) contains the corrective action plan to complete the review of all RSS and QSS related calculation discrepancies identified by the ICAVP program. This corrective action will be completed after Startup, and will ensure that the errors in US(B)-266 are clearly identified and addressed. The corrective action plan for CR M3-98-1505 is tied to CR M3-98-0619 by AR 98002805.

As part of the ICAVP program, trending CR M3-98-1132 has been written to ensure that any process-related issues related to these calculations are clearly identified and are being dealt with. This assessment is scheduled to be completed prior to Startup.

Each of the discrepancies in DR-MP3-1018 has been reviewed by NU design engineers, who have determined that none of the discrepancies impacts the operability of the RSS system. As such there is no effect on the license or design basis.

### CONCLUSION:

NU has concluded that the issues reported in Discrepancy Report, DR-MP3-1018, have identified conditions not previously discovered by NU which require correction. The approved corrective action plan for CR M3-98-1505 (attached) will correct Calculation US(B)-266 with respect to each of the discrepancies identified after Startup. In addition, an assessment will be performed prior to Startup of the issues related to calculational discrepancies. This will ensure that these issues are clearly identified and addressed. Each of the discrepancies identified in DR MP3-98-1018 has been reviewed by NU, and none of them affect the conclusion that the RSS system meets its design basis. As such there is no effect on the license or design basis.

Previously Identified by NU?	0	Yes	۲	No	Non D	iscrepant Conditio	m? Yes	No
Resolution Pending	9?0	Yes	۲	No	Rea	solution Unresolve	d? Yes	No No
initiator: VT Lead: VT Mgr: IRC Chmn:	Neri, J Schop	Anthon ofer, Do	y A on K		Acceptable	Not Acceptable	Review Needed	Date 5/12/98 5/13/98 5/14/98

Printed 5/14/98 9:40:56 AM

Page 2 of 3

Northeast Utilities Millstone Unit 3	ICAVP Discrepancy Report	DR No. DR-MP3-1018
NC CHINE: Date:	5/12/98	
SL Comments:	Sargent & Lundy agrees that CR I issues identified in DR-MP3-1018	
	Sargent & Lundy has concluded the not a discrepant condition. Item # to model the ECCS cold leg recirc suction switchover is completed. design basis created by modificat US(B)-266, Rev. 3 is that the RSS take suction from the containment operates in its recirculation mode	A identifies the flow to be used culation flow once ECCS manual However, the containment ion M3-97045 and modeled in 5 pumps never actuate, never t sump, and ECCS never
	For the design basis MSLBs which containment pressure and the wo QSS is modeled to commence sp results in less RWST water spray duration of the containment trans Rev. 3. This is a conservative en- mode, the model for SIH and CH4 injection of RWST water into the results in a reduction in the calcul containment transients modeled in conservative error. Therefore, Sa the errors identified in Items #1 and place the QSS or containment sy and licensing bases. These error restart.	rst-case peak temperature, the oray 2.6 seconds too late. This ed into containment over the ients modeled in US(B)-266, rcr. For the ECCS injection G flows overestimates the vessel by up to 240 gpm. This lated mass released during the n US(B)-266, Rev. 3. This is a argent & Lundy concludes that nd #2 of DR-MP3-1018 do not stems outside of their design

# ICAVP Discrepancy Report

DR No.	<b>DR-MP3-1</b>	051
--------	-----------------	-----

Review Group: System	DR RESOLUTION ACCEPTED
Review Element: Corrective Action Process Discipline: Mechanical Design	Potential Operability Issue
Discrepancy Type: Corrective Action Implementation System/Process: RSS	No Yes
NRC Significance level: NA	Date FAXed to NU:
	Date Published: 2/23/98

#### Discrepancy: UIR 1035

Description: UIR 1035 describes the sump compliance with RG 1.82, Position 10. Calculation PE-029 does not address all the requirements of Position 10. The calculation only considers the RSS spray nozzles, but should include all functions and systems which are served by the sump including SIH, CHS and RCS for recirculation mode. The SIH throttle valves are open less than the screen mesh size resulting in possible blockage.

The UIR Close Out Report concludes that CCN 2 to Calculation PE-029, Rev. 0 was approved, thus completing the necessary actions for closure. The CCN provides a resolution to the problem with the sump screens, but leaves compliance 'pending on the implementation of DCR # M3-96-077.' The DCR installs new orifices in the ECCS injection lines allowing a larger opening in the throttle valves; satisfying RG 1.82, Position 10.

Review

This is an administrative error. There is no mechanism for tracking the DCR closure to the calculation.

		Valid	Invalid	Needed	Date
Initiator:	Langel, D.				2/17/98
VT Lead:	Neri, Anthony A				2/17/98
VT Mgr:	Schopfer, Don K				2/18/98
IRC Chmn:	Singh, Anand K				2/19/98

Date:

INVALID:

Date: 5/13/98

**RESOLUTION:** Disposition:

NU has concluded that the issue reported in Discrepancy Report, DR-MP3-1051, does not represent a discrepant condition.

CCN #2 was submitted as part of the UIR 1035 Closure Package to document how compliance to RG 1.82 position 10 would be satisfied. After submitting UIR 1035 Closure Package, the original CCN was lost prior to entry into Nuclear Records. Several months later, the CCN was recreated for submittal to Nuclear Records and was reissued with some minor changes being made to the text to account for actions taken between 3/97 and 11/97. The attached Record Copy of CCN #2 does not condition its closure on the completion of DCR # M3-96077. In order to update UIR 1035 with the record copy of CCN #2, CR M3-98-1684 was initiated to correct the documentation. No technical changes had occurred as a result of this change. The

# ICAVP Discrepancy Report

statement "pending on the implementation of DCR # M3-96077" has been removed from CCN #2. The Design Engineer did not make changes to calculation PE-029 to support DCR # 96077 "ECCS Orifices and Throttle Valves" and therefore the PE-029 would not be listed in the turnover transmittal, Form 3-2H. CCN #2 to PE-029 was a stand alone change that was initiated outside of the changes made by DCR M3-96077 and, therefore no direct link between the DCR closure and the calculation should exist.

"The Design Control Manual (DCM) Chapter 5 provides the administrative controls for the process of closing out calculation changes associated with plant modifications. Revision 6 of the DCM now requires that when a plant modification is completed and turned over to Operations, a new box on the Calculation Title Sheet or CCN form, entitled "Installation Verified;, is signed signifying that the calculation or CCN may become or complement the "calculation record." The intent of this procedure change was to enhance the closure mechanisms to the calculations associated with plant design changes. CCNs which are entered into the system become part of the calculation record whereby the CCNs are included with the requested calculation. New guidelines have been developed to establish the number of CCNs that can be posted agrinst a calculation prior to formal revision of the calculation (refer to A/R 97029822-11) which have been incorporated into revision 6 to the DCM. The purpose of this revision was to provide the user with an improved understanding of the calculation and DCR process as well as making it easier to follow. To ensure proper closure to CCNs associated with key calculations, A/R 97029822-10 will implement a review of key calculations to establish the installation verified status for changes made to calculations prior to the effective date of DCM rev 6. Based on the more recent revisions made to the design control program, in recognition of past weaknesses in the control of calculation changes, NU does not consider this to be a discrepant condition.

CCN #2 revised Calculation PE-029 to update the current ECCS strainer mesh opening size. The mesh opening for the fine screen is 3/32 inch (0.094"). ACR 8897 identified throttled valves on the cold leg safety infection lines where the disc-to-seat clearance was less than 0.094". DCR M3-96077 corrected the clearance issue through the addition of a flow restriction orifice in each injection line that will allow increasing the throttle valves' opening to greater than 0.094". The actions performed under DCR M3-96077 satisfies the requirements of RG 1.82, Position 10.

Significance Level Criteria do not apply here as this is not discrepant condition.

Conclusion:

NU has concluded that the issue reported in Discrepancy Report, DR-MP3-1051, does not represent a discrepant condition.

The design change closure process requires design engineering

Northeast Utilities Millstone Unit 3	Disc		AVP ncy Repo		No. DR-M	1P3-1051
	Request pro CCNs asso incorporate calculation process wh of any asso question w remain as exist which Therefore,	rior to c ociated ed in th h have I hich colociated vas mac an atta h will wi NU do	close-out. The with design e revision are been recondentrols the clo- calculation. de independent chment to the arrant a full in es not considered	ciated with the l his review assur- changes made and that all chang iled. The DCM Soure of the DCF Since the Calc ent of the DCR, he calculation un revision to the c der this to be a not apply here	es that all a by the DCF ges to the contains the R and recor- culation Cha the CCN w ntil sufficient alculation. discrepant	active R are nciliation ange in vill nt CCNs condition
Previously Identified by NU?	() Yes	() No		iscrepant Conditio	n?® Yes	O No
Previously Identified by NU? Resolution Pendin	0	<ul><li>No</li><li>No</li></ul>	Non D	iscrepant Conditio	-	No No
Resolution Pendin Initiator: VT Lead: VT Mgr:	0	No  No  No  No  K	Non D		-	0

Northeast Utilities	ICAVI	P		DR No. DR-	MP3-1068
Millstone Unit 3	Discrepancy	Repo	ort		
Review Group:	System	and defense of the second s	DR RESOLU	TION ACCEPT	ED
	Modification Design			otential Operat	hility lesue
	Mechanical Design			() Yes	sincy issue
	Procedure Implementation			No No	
System/Process: NRC Significance level:					
NRC significance level.	NA		D	ate FAXed to NI	U:
				Date Publishe	d: 2/28/98
Discrepancy:	Incomplete document Specification SP-ME-		plementing o	changes to	
Description:	In the process of revie associated DCN-00-1				3 and
	DCN-00-1122-97 state Changes Required,				
	"Add snubber mark no PSSP460 to the snub ME-570."				
	Based on a review of the subject DCN, no change paper incorporating the changes to Appendix U of Specification SP-ME- 570 could be identified.				
	In addition, the subject new pipe supports and these cases should be supports contained in The subject DCN does specification or includ implementation.	d the del e reflecte Append s not me	etion of one ed by change ix M of Spec ention this po	support. It is to the listin ification SP- otential change	believed ng of pipe ME-570.
	Discrepancy:				
	DCN DM3-00-1122-97 implement the noted of Appendix U and does changes to Appendix	changes not ider	to specificat tify or imple	tion SP-ME-5 ment potenti	570
		Valid	Invalid	Review Needed	Date
Initiator:	Oison, P.R.				Date 2/20/98
	Neri, Anthony A	M	H	Н	2/21/98
	Schopfer, Don K	M	Н	H	2/21/98
	Singh, Anand K		П	П	2/25/98
Date:					
INVALID:					
Date:	5/12/98	NA CALONCOM REPORT DOMIN	ACAM SECOND FOR STOLEN SECOND	an antina ann an Anna a	an and an incomplete set they
RESOLUTION:	Response ID: M3-IRF	-02231			
	Disposition:				
	NU has concluded that DR-MP3-1068, does n				

DM3-00-1122-97 lists SP-ME-570 as an affected document to

Northeast Utilities Millstone Unit 3	ICA Discrepan			NO. DR-	/P3-1068
	add the new snubb issued to suppleme information concer update to Appendio seismic supports w specification is for credited, not to list	ent DM3-00 ming the ne x 'M' of SP- vere affecte seismic sup	-1122-97 to add w snubbers. Ad ME-570 is requ d. This Append oports on Class	d all the pe dditionally, ired as no lix to the 4 lines wh	rtinent no interface
	Significance Level discrepant conditio		es not apply as	this is not	a
	Attachments:1)	DCN DM3-0	5-1122-97		
	Conclusion:NU has Discrepancy Report discrepant condition included in DCN D required to Append	rt, DR-MP3 on. The upd M3-05-112	-0987, does not ate to Appendix 2-97 and there i	represent	a E-570 is
	required to Append		inc oro.		
	Significance Level discrepant conditio	Criteria do		this is not	а
Previously Identified by NU?	Significance Level discrepant conditio	Criteria do on. Non D	es not apply as	m? () Yes	a O No
Previously Identified by NU? Resolution Pending	Significance Level discrepant conditio	Criteria do on. Non D	es not apply as	n?® Yes d?O Yes	
Resolution Pending	Significance Level discrepant conditio Ves No Yes No	Criteria do on. Non D	es not apply as	m? () Yes	() No
Resolution Pending	Significance Level discrepant conditio Yes No Yes No Olson, P.R.	Criteria do on. Non D Rei Acceptable	es not apply as iscrepant Conditio iolution Unresolve	n? () Yes d? Yes Review Needed	<ul> <li>No</li> <li>No</li> <li>Date</li> <li>5/12/98</li> </ul>
Resolution Pending Initiator: VT Lead:	Significance Level discrepant conditio Ves No Yes No Olson, P.R. Neri, Anthony A	Criteria do on. Non D Rei Acceptable	es not apply as iscrepant Conditio iolution Unresolve	n? () Yes d? Yes Review Needed	<ul> <li>No</li> <li>No</li> <li>Date</li> <li>5/12/98</li> <li>5/12/98</li> </ul>
Resolution Pending Initiator: VT Lead: VT Mgr:	Significance Level discrepant conditio Yes No Yes No No Olson, P.R. Neri, Anthony A Schopfer, Don K	Criteria do on. Non D Rei Acceptable	es not apply as iscrepant Conditio iolution Unresolve	n? () Yes d? Yes Review Needed	<ul> <li>No</li> <li>No</li> <li>Date</li> <li>5/12/98</li> </ul>
Resolution Pending Initiator: VT Lead: VT Mgr: IRC Chmn:	Significance Level discrepant conditio Yes No Yes No Olson, P.R. Neri, Anthony A Schopfer, Don K Singh, Anand K	Criteria do on. Non D Ret	es not apply as iscrepant Conditio iolution Unresolve	n?® Yes d?O Yes Review	<ul> <li>No</li> <li>No</li> <li>Date</li> <li>5/12/98</li> <li>5/12/98</li> </ul>
Resolution Pending Initiator: VT Lead: VT Mgr: IRC Chmn: Date:	Significance Level discrepant conditio Yes No Yes No No Olson, P.R. Neri, Anthony A Schopfer, Don K	Criteria do on. Non D Res Acceptable	es not apply as iscrepant Conditio colution Unresolve Not Acceptable	n? () Yes d? Yes Review Needed	<ul> <li>No</li> <li>No</li> <li>Date</li> <li>5/12/98</li> <li>5/12/98</li> <li>5/12/98</li> </ul>

Northeast Utilities	ICA	VP		DR No. DR-	MP3-1076	
Millstone Unit 3	Discrepar	ncy Repo	ort			
Review Group:	System	akian markan na panalaki na di	DR RESOLU	TION ACCEPT	ED	
Review Element: Modification Design Discipline: 1 & C Design Discrepancy Type: Drawing System/Process: NEW		Discipline: I & C Design crepancy Type: Drawing		Potential Operability Ves No		
NRC Significance level:			D	ate FAXed to NI	J:	
				Date Published		
Discrepancy:	Incorrect markup Modification DCR	the second s	awing depict	ed in Plant		
Initiator: VT Lead:	The change to LS pages 5 and 6 of 1 Only one logic dra configuration) is a and 8 should be m Pages 5 and 6 of show the modifica Reed,William. Neri, Anthony A Schopfer, Don K	K-27-11H R DCN DM3-0 awing (which ffected by the emoved from DCN DM3-0 thion correct Valid	0-0079-98. details the The modificati n DCN DM3- 00-0079-98 s	Train A logic on, therefore -00-0080-98.	, pages 7	
	Singh, Anand K		H	H	3/9/98	
Date: INVALID:						
Date: RESOLUTION:	5/12/98 Disposition: NU has concluded DR-MP3-1076 ha					

DCNs DM3-00-0079-98 and DM3-00-0080-98 were issued to implement DCR M3-97045 design changes related to the control logic of valves 3RSS\*MOV38A and 3RSS\*MOV38B, respectively. Contrary to Discrepancy Report DR-MP3-1076, drawing 12179-LSK-27-11H details both Train A and B logic configurations for valves 3RSS\*MOV38A and 3RSS\*MOV38B. Note 3 on drawing 12179-LSK-27-11H indicates the control logic for containment recirculation pump miniflow valve 3RSS\*MOV38A is shown and the control logic for 3RSS\*MOV38B is similar. Both DCN DM3-00-0079-98 and DM3-00-0080-98 implemented logic changes that affected drawing 12179-LSK-27-11H. However, since each of these DCNs implemented changes to the plant at different times that affected only one train, they only document the changes made to the affected train on drawing 12179-LSK-27-11H.

Page 7 of DCN DM3-00-0080-98 shows drawing 12179-LSK-27-11H before the control logic changes to valve 3RSS\*MOV38B are implemented and page 8 shows the drawing after the changes are made. Since this DCN only affected Train B, the

Northeast Utilities	ICAVP DR No. DR-MP3-1076
Millstone Unit 3	Discrepancy Report
	changes on the drawing correctly reference Note 8 which indicates they are applicable to Train B only. It should be noted that this DCN was implemented and turned over to operations prior to DCN DM3-00-0079-98.
	Block 7 of DCN DM3-00-C079-98 indicates it was issued as a supplement to DCN DM3-00-0080-98. Page 5 of DCN DM3-00-0079-98 shows drawing 12179-LSK-27-11H before the control iogic changes to valve 3RSS*MOV38A are implemented but reflects the changes made to the control logic for valve 3RSS*MOV38B by DCN DM3-00-0080-98. Page 6 of DCN DM3 00-0079-98 shows drawing 12179-LSK-27-11H after the control logic changes to valve 3RSS*MOV38A and reflects the changes made to the control logic changes to valve 3RSS*MOV38A and reflects the changes made to the control logic for valve 3RSS*MOV38B by DCN DM3 00-0080-98. A review of pages 5 and 6 of DCN DM3-00-0079-98 found they accurately depict the changes made to the control logic of valve 3RSS*MOV38A. Since DCN DM3-00-0079-98 wa issued as a supplement to DCN DM3-00-0080-98, pages 5 and 6 also reflect changes made to the control logic of valve 3RSS*MOV38B by DCN DM3-00-0080-98.
	Significance level criteria do not apply as this is not a discrepant condition.
	Conclusion:
	NU has concluded that this issue reported in Discrepancy Repor DR-MP3-1076 has identified a NON-DISCREPANT condition.
	DCNs DM3-00-0079-98 and DM3-00-0080-98 were issued to
	implement DCR M3-97045 design changes related to the control logic of valves 3RSS*MOV38A and 3RSS*MOV38B, respectively. Contrary to Discrepancy Report DR-MP3-1076, drawing 12179-LSK-27-11H details both Train A and B logic configurations for valves 3RSS*MOV38A and 3RSS*MOV38B. Note 4 on drawing 12179-LSK- 27-11H indicates the control logic for containment recirculation pump miniflow valve 3RSS*MOV38A is shown and the control logic for 3RSS*MOV38B is similar. Both DCN DM3-00-0079-98 and DM3-00-0080-98 implemented logic changes that affected drawing 12179-LSK-27-11H. However, since each of these DCNs implemented changes that affected only one train, they only document the changes made to the affected train on drawing 12179-LSK-27-11H.
	Pages 5 and 6 of DCN DM3-00-0079-98 accurately depict the changes made to the control logic of valve 3RSS*MOV38A. Since DCN DM3-00-0079-98 was issued as a supplement to DCN DM3-00-0080-98, pages 5 and 6 also reflect changes mad to the control logic of valve 3RSS*MOV38B by DCN DM3-00-0080-98.
	Significance level criteria do not apply as this is not a discrepan condition.

Northeast Utilities Millstone Unit 3	ICA Discrepar	VP Icy Repo		No. DR-N	NP3-1076
Resolution Pendin	9?) Yes 🖲 No		solution Unresolve	-	No
initiator: VT Lead: VT Mgr:	DeMarco, J. Neri, Anthony A Schopfer, Don K Singh, Anand K 5/12/98	Acceptable	Not Acceptable	Review Needed	Date 5/12/98 5/12/98 5/12/98
SL Comments:	Sequence of imple 97045 has been a			nges per Do	CR M3-

# ICAVP Discrepancy Report

DR No. DR-MP3-1081

Review Group:	System	DR RESOLUTION ACCEPTED			
Discipline: Discrepancy Type:			Potential Operability Iss Yes No		
System/Process: NRC Significance level:					
rance organicance reven.			D	ate FAXed to N	U:
				Date Publishe	d: 3/14/98
Discrepancy:	Incomplete Failur to DCR M3-98000		alysis in S3-	EV-98-0021	attached
Description:	Safety Evaluation S3-EV-98-0021, Modification of RSS Pumps' Seal Water Coolers, is the safety evaluation for DCR M3-98008 Section 2.0 of the safety evaluation identifies two failure modes analyzed. They are:				
	1. Failure of RSS pump outboard seal.				
	2. Failure of new tubing.				
	z. i onaro or non taonig.				
	The safety evaluation does not address the three following				
	failure modes:				
	<ol> <li>Failure of the RSS pump inboard seal.</li> <li>Failure of the pressure chamber on the RSS pump mechanical seal.</li> <li>Failure of the new valves to maintain the RSS pump seal pressure boundary.</li> </ol>				
	Therefore, the failure modes analysis in the safety evaluation is considered to be incomplete.				
		Valid	Invalid	Review Needed	Date
	Feingold, D. J.				3/10/98
	Neri, Anthony A				3/10/9
	Schopfer, Don K				3/11/9
IRC Chmn:	Singh, Anand K				3/11/9
Date:					
INVALID:					

Date: 5/13/98

**RESOLUTION:** Disposition:

NU has concluded that this issue reported in Discrepancy Report DR-MP3-1081 has identified a NON-DISCREPANT condition.

DCR M3-98-008 did not implement any changes that would introduce failures to the RSS pump outboard seal or the pressure chamber that had not been previously evaluated and found acceptable. The DCR did install a new tubing configuration for each RSS pump mechanical seal to separate the seal cooling loop from the pressure chamber. This new configuration included a normally closed manual vent valve in the seal cooling loop to ensure it is properly vented during system fill. As part of the new tubing configuration, although not explicitly stated, the failure of the new vent valve was considered in Safety

## ICAVP Discrepancy Report

Evaluation S3-EV-98-0021, Revision 0, when evaluating a failure of the tubing. The normally closed QA Category I, ASME Class 2, manual needle valve, like the tubing, was designed and installed to the same standards and criteria that were used to construct the original outboard seal water cooling and pressurizing equipment. Therefore, as stated in the safety evaluation, there is no increase in the probability of occurrence of previously evaluated malfunction of equipment important to safety.

The mechanical seals for the RSS pumps are a tandom style. The lower seal uses process fluid as the coolant for the seal and the upper seal uses a closed loop cooling system initially filled with demineralized water to cool the seal. To ensure no process fluid escapes through a pump seal (for the first seven days of pump operation following a LOCA), the upper seal cavity is maintained at a higher pressure relative to the lower seal cavity. This is accomplished by the use of a pressure chamber (seal tank). The lower seal chamber is connected to the top chamber of the pressure chamber and the upper seal cavity is connected to the bottom of the pressure chamber via tubing. This ensures the pressure in the bottom chamber of the pressure chamber equals the pressure in the top chamber plus the pressure applied by the cylinder that divides the pressure chamber.

Prior to the implementation of DCR M3-98-008, a portion of the tubing between the outboard seal cavity and the bottom chamber of the pressure chamber served two functions; it allowed for the application of pressure from the bottom chamber of the pressure chamber to the outboard seal cavity and it served as a flow path for the closed seal cooling loop. As the flow in the closed seal cooling loop was found to induce an undesirable pressure loss in the pressure being applied to the outboard seal assembly, DCR M3-98-008 reconfigured the tubing to separate the two functions. This DCR removed the tubing that connected the pressure chamber to the seal cooling loop and installed tubing directly from the bottom chamber of the pressure chamber to a different connection on the outboard seal cavity completely separate from the seal cooling loop.

Safety Evaluation S3-EV-98-0021, Revision 0, evaluated the changes implemented by DCR M3-98-008 and found the changes do not alter the function or performance of any of the equipment affected by the modification. The safety evaluation correctly indicates that since the seals are not being changed, it is not credible for a seal failure to occur other than one previously evaluated and determined acceptable. This conclusion can also be applied to the pressure chamber.

Significance level criteria do not apply as this is not a discrepant condition.

Conclusion:

NU has concluded that this issue reported in Discrepancy Report DR-MP3-1081 has identified a NON-DISCREPANT condition.

DCR M3-98-008 did not implement any changes that would introduce failures to the RSS pump outboard seal or the pressure chamber that had not been previously evaluated and found acceptable. The DCR did install a new tubing configuration for each RSS pump mechanical seal to separate the seal cooling loop from the pressure chamber. This new configuration included a normally closed manual vent valve in the seal cooling loop to ensure it is properly vented during system fill. As part of the new tubing configuration, although not explicitly stated, the failure of the new vent valve was considered in Safety Evaluation S3-EV-98-0021, Revision 0, when evaluating a failure of the tubing. The normally closed QA Category I, ASME Class 2, manual needle valve, like the tubing, was designed and installed to the same standards and criteria that were used to construct the original outboard seal water cooling and pressurizing equipment. Therefore, as stated in the safety evaluation, there is no increase in the probability of occurrence of previously evaluated malfunction of equipment important to safety.

Significance level criteria do not apply as this is not a discrepant condition.

	oonstion.					
Previ	ously Identified by NU? Resolution Pending	Yes ()		iscrepant Conditions	-	No No
					Review	
	Initiator:	Feingold, D. J.	Acceptable	Not Acceptable	Needed	Date
	VT Lead:	Neri, Anthony A				5/13/98
	VT Mor:	Schopfer, Don K				5/13/98
		Singh, Anand K		R		5/14/98
	Date:	5/13/98	-	-	L	
	SL Comments:	<ol> <li>According to there are no perpendence co Even though to seal from its line does address</li> <li>According to installed as Que specification Se constructed are the existing se address failure safety evaluat</li> </ol>	to section 2.1.2 ortions of the se nditions that the he safety evalu st of malfunction a failure of both to page 2 of DC A Category 1, A SP-EE-212. The he installed to e easily system value of the new value ion does addres	theast Utilities' e following reas of the subject s eals that will be ey were not des ation excludes in the inboard an CR M3-98008, th SME Class 2 in erefore, the new quivalent stand es. The safety lves. However, ss failure of the that the new tub	ons: safety evalua required to igned to exp failure the ini- s in section 2 d outboard s ne new valve n accordance v valves are ards and crit evaluation do section 2.1.2 new tubing,	ation, erience. boad .1.2 eeals. es are e with NU eria as oes not 2 of the

Northeast Utilities Milistone Unit 3

# ICAVP Discrepancy Report

and installed to the same standards and criteria as the existing seal system tubing. The evaluation of the new tubing in the safety evaluation could be interpreted to include the new valves.

3. The new tubing configuration between the pressure chamber and the pump seal ensures that the outboard seal cavity is pressurized as intended by the original seal system design. This modification does not change the current failure mode(s) of the pressure chamber. Therefore, the probability of a failure of the pressure chamber and the consequences of a failure of the pressure chamber have not changed as a result of this modification.

Even though the subject malfunctions NOT addressed in the safety evaluation are bounded by the malfunctions that were addressed, Sargent & Lundy recommends that future safety evaluations address all failure modes to ensure all failure modes are bounded.

Northeast Utilities	ICAVP		1	DR No. DR-M	AP3-1082	
Millstone Unit 3	Discrepancy F	Report	t			
Review Group:	Programmatic	FRANKLING AND	DR RESOLU	TION ACCEPTE	D	
Discipline:	Corrective Action Implementation	n	P	otential Operab Ves No	ility Issue	
NRC Significance level:	4		De	ate FAXed to NU	1:	
				Date Published	1: 3/14/98	
Discrepancy:	Insufficient Documentati 97-0729.	ion to Ve	erify Corre	ctive Action f	or CR M3-	
Description:	In the implementation re was noted:	eview of	CR M3-97	-0729 the foi	lowing	
	1. Corrective action #1 for CR M3-97-0729 was to "revise applicable drawings".					
	2. AR No. 97005927-02 assignment completion notes state "revised applicable drawings to correct the drafting error and added EDG ratings under DCN #DM3-00-0372-97 as part of the corrective action plan." This DCN No. is also indicated on CR Form RP4-1, page 5 of 9 in the CR package.					
	3. CR M3-97-0729 Action Closeout Form RP4-4 (for AR 97005927-02) also indicates in part, under steps 5 & 6 that DCN #DM3-00-0372-97 is the DCN which addresses the concern in the CR.					
	Contrary to the above, o (copy which was include that this DCN did not ad CR.	ed in the	CR close	out package)	indicates	
	L.	alid	Invalid	Review Needed	Date	
Initiator					3/11/98	
			П	H	3/10/98	
	Schopfer, Don K				3/11/98	
					3/11/98	

#### Date:

INVALID:

Date: 5/13/98

**RESOLUTION:** Disposition:

NU has concluded that Discrepancy Report, DR-MP3-1082, has identified a condition not previously discovered by NU which requires correction. DCN DM3-00-0372-97 was incorrectly referenced in the CR Action Closeout Form and in the Corrective Action Plan in M3-97-0729 as well as in the AR # 97005927-02 completion notes. The correct DCN reference is DCN DM3-00-0509. Changes have been processed to correct the CR Action Closeout Form and the Corrective Action Plan in M3-97-0729. The approved Corrective Action Plan for M3-98-1952 will update the DCN reference in the AR closure notes post startup.

Northeast	Utilities
Millstone	Unit 3

Conclusion:

NU has concluded that Discrepancy Report, DR-MP3-1082, has identified a condition not previously discovered by NU which requires correction. DCN DM3-00-0372-97 was incorrectly referenced in the CR Action Closeout Form and in the Corrective Action Plan in M3-97-0729 as well as in the AR # 97005927-02 completion notes. The correct DCN reference is DCN DM3-00-0509. Changes have been processed to correct the CR Action Closeout Form and the Corrective Action Plan in M3-97-0729. The approved Corrective Action Plan for M3-98-1952 will update the DCN reference in the AR closure notes post startup.

Attachments - Corrected CR Action Closeout Form and Corrective Action Plan for M3-97-0729, CR M3-98-1952, DCN DM3-00-0509-97

Previously Identified by NU? () Yes () Resolution Pending? () Yes ()		iscrepant Conditio	-	<ul><li>No</li><li>No</li></ul>
Initiator: Caruso, A. VT Lead: Ryan, Thomas J VT Mgr: Schopfer, Don K IKC Chmn: Singh, Anand K Date: 5/13/98	Acceptable	Not Acceptable	Review Needed	Date 5/13/98 5/13/98 5/14/98

SL Comments: NU's response is acceptable.

As noted in the above attachment, NU issued CR M3-98-1952 which correctly referenced DCN DM3-00-0509-97 in the CR M3-97-0729 Action Closeout Form and in the Corrective Action Plan as well as in the AR # 97005927-02 completion notes. [Note: DCN DM3-00-0372-97 was incorrectly referenced in CR M3-97-0729.]

As noted in the above attachment, DCN DM3-00-509-97 did implement the applicable drawing changes requested in the CR M3-97-0729 Corrective Action #1.

DR-MP3-1082 is discrepant.

### Northeast Utilities Millstone Unit 3

Review Group: System

n

# ICAVP

#### DR No. DR-MP3-1083

sue

	D	iscr	epa	ncy	Repo	rt
--	---	------	-----	-----	------	----

#### DR RESOLUTION ACCEPTED

<b>Review Element:</b>	Corrective Action Process	Potential Operability Is
Discipline:	Mechanical Design	
Discrepancy Type:	Corrective Action Implementation	( No
System/Process:	RSS	( NO
NRC Significance level:	4	Date FAXed to NU:

Date Published: 3/16/98

Discrepancy: ACR M3-97-0314 Corrective Action Implementation

Description: ACR M3-97-0314 addressed problems with the material condition and cleanliness of the containment sump, sump screens and sump cover. This ACR enumerated 13 of these issues with the RSS containment sump.

> AR 97002740 was issued to implement the corrective actions for ACR M3-97-0314. The following documents were traceable from ACR M3-97-0314 and AR 97002740: 3DE-96-0009, AR 96033643, LER 96-039-00, AWO M3-96-13395, DCR M3-97580, DCN DM3-00-0490-97, NSE-97-01, AR 97009899, TR 20M3151214, AWO M3-97-10839, AWO M3-13728, AWO M3-97-02630, TR21M3100340, AWO 97-10840, AWO M3-96-09729, AR 97002435, AR 96036350, AR 97015361, TR 12M33095400, AWO M3-96-13395, ACR M3-96-1372, AR 96036350, 97003665, DCN DM3-S-903-96, and DCR M3-97045.

According to ACR M3-97-0314, AR 97002740-03 address the corrective actions for ACR M3-97-0314 Issues #3 and #5. AR 97002740-03 was closed to TR 20M3151214, and TR 20M3151214 was closed to AWO M3-97-10839. TR 20M3151214 and AWO M3-97-10839 correct Item #5, the missing lower grating clip. Neither of these corrective action documents address Item #3, various deck plate screws missing or not flush with deck plating. No documentation of the correction of Item #3 was found among the corrective action documents listed above.

According to ACR M3-97-0314, AR 97002740-03 address the corrective actions for ACR M3-97-0314 Issue #10. AR 97002740-03 was closed to AWO M3-97-02630. This work order is for the removal of trash grates for a surveillance to measure the coarse mesh screens, and to remove debris found between the trash grates and fine mesh screens and debris found in the sump behind the screens. This work onler does not address Item #10. to clean debris found in the sump trench outside the trash grates and screens. No documentation of the correction of Item #10 was found among the corrective action documents listed above.

The documents referenced for closure of corrective action implementation for Items #3 and #10 of ACR M3-97-0314 did not address these issues. Documentation for the closure of Items #3 or #10 was not found in ACR M3-97-0314, in AR 97002740, or in any other documents directly associated with ACR M3-97-0314 or AR 97002740.

	Valid	Invalid	Needed	Date
Initiator: Wakeland J.F.				3/12/98
Printed 5/14/98 9:45:01 AM				Page 1 of 3

Northeast Utilities Millstone Unit 3	ICA Discrepar	DR No. DR-MP3-1083		
Initiator:	Wakeland, J. F.			3/12/98
VT Lead:	Neri, Anthony A			3/12/98
VT Mgr:	Schopfer, Don K			3/12/98
IRC Chmn:	Singh, Anand K			3/13/98
Date:				
INVALID:				

Date: 5/13/98

RESOLUTION: DISPOSITION:

NU has concluded that Discrepancy Report, DR-MP3-1083, has identified a condition not previously discovered by NU which requires correction.

Ð

In response to item #10 of ACR M3-97-0314, the record copy of AWO M3-97-02630 (attached) was reviewed and verified that the completion remarks documented the removal of debris from the sump screens and trench area. Item #10 of the ACR was to clean the sump screens by removing foreign materials. The AWO had a Foriegn Material Exclusion (FME) Log associated with work. AWO M3-97-02630 references FME activities under AWO M3-97-02627 (attached) which documents that the sump area was cleaned and verified to be free of debris. NU does not consider item #10 of ACR M3-97-0314 to be a discrepant condition.

In response to item #3 of ACR M3-97-0314, the record copy of AWO M3-97-10839 (attached) was reviewed against Trouble Report TR 20M3151214. The problem description of the Trouble Report was not adequately transferred to the AWO such that deck plate fasteners were not identified in the task description. Although the AWO did not specifically call out to tighten or refasten the deck plate bolting, these activities were completed. The RSS System Engineer performed a walkdown of the RSS sump area and verified cleanliness of the sump and trench areas and that all decking was properly secured as part of MMOD M3-97580 closure inspection (attached). CR M3-98-2135 was initiated to identify the failure of the planning for AWO M3-97-10839 to specifically identify the deck plate fastners which were required to be tightened. The approved corrective action plan for CR M3-98-2135 will add documentation into the AWO M3-97-10839 package to verify that the deck plate fasteners associated with the RSS sump are installed. AR 98008317 will track this item to completion post startup. Since the AWO was the only document referenced on Corrective Action Item #3 of ACR M3-97-0314. NU concurs with the conclusion that item #3 of the ACR is a discrepant condition. Without the documentation provided by MMOD M3-97580 closure inspection, there would have been less than adequate documentation to verify that Item #3 was properly completed.

#### CONCLUSION:

NU has concluded that Discrepancy Report, DR-MP3-1083, has Page 2 of 3

ortheast Utilities	ICA\	/P	DR	No. DR-MI	P3-1083			
lillstone Unit 3	Discrepand	y Repo	ort					
CONTRACTOR OF THE CONTRACTOR	identified a condition not previously discovered by NU which requires correction.							
	Based the work pac and TR20M3151214 to support completic ACR M3-97-0314. C failure of the plannin identify the deck pla tightened. The app 2135 will add docum package to verify th the RSS sump are in completion post sta assignment of signi condition. Based the work pac M3-97-02627) there of corrective action	4) there is on of corre CR M3-98- ng for AW ate fastnen roved corr nentation i at the dec installed. A rtup. NU ficance lev ckage doct is sufficie	less than adequ ctive action iten 2135 was initiate O M3-97-10839 s which were rec ective action pla nto the AWO M k plate fastenen R 98008317 wil concurs with Sa yel 4 to item #3	ate docume n #3 identifi ed to identifi to specifica quired to be an for CR M 3-97-10839 s associate Il track this ingent & Lui as a discre Os M3-97-6	entation ied in fy the ally 13-98- ) d with item to ndy's pant 02630, npletion			
	of corrective action Therefore NU does condition.							
Previously Identified by NU?	Yes No	Non	iscrepant Conditio	n? Yes	No No			
VT Lead:		Re Acceptable	Not Acceptable	d? Yes Review Needed	<ul> <li>No</li> <li>Date</li> <li>5/13/98</li> <li>5/13/98</li> <li>5/14/98</li> </ul>			
IRC Chmn:	Singh, Anand K		H	E .				
Date: SL Comments:	5/13/98 Sargent & Lundy or related to Item #10 that the sump trend was completed via was used to suppor Sargent & Lundy or documentation of the replacement of mis plate screws. MMM closure plates and inspection of the si that the deck platin deficiency associa Thus, the discrepand discrepancy is income	of ACR M ch outside AWO M3 rt ACR M3 oncurs that he completes sing deck OE M3-97 around so ump enclo ng was pro- ted with the nt condition omplete do	12-97-0314. Iter of the trash sce 97-02627 and A -97-0314 correct tt CR M3-98-213 tion of Item #3 plate screws ar 580, which elim reen penetration sure boundary ( perly secured), e deck plate scr is not a hardw	m #10, veri ens is free AWO M3 97 ctive action 35 addresse of ACR M3 nd tightenin inated gaps ns, included including v and no han rews was id vare deficie the work w	fication of debris, 7-02627 s. -97-0314 g of deck s between d deck s between d entification dware lentified. ncy. The hich was			

Northeast Utilities	IC	AVP		DR No. DR-	MP3-1084	
Millstone Unit 3	Discrepa	ncy Repo	ort			
Review Group:	System	MANUT LANAN PROCESSION DISONALIYA DISONALIYA DIS	DR RESOLU	TION ACCEPT	ED	
	Modification Design		F	otential Operal	bility lasue	
Discipline: Discrepancy Type:	Mechanical Design			O Yes		
System/Process:				No		
NRC Significance level:			D	ate FAXed to N	u.	
				Date Publishe		
Discrepancy:	Safety Evaluation DCR M3-97045	of RSS/HH	SI NPSH Inte			
Бевсприон:	Modification DCR discharge of each output from the H two changes redu cold leg and hot leg	RSS pump HSI pump since the NPSI	and diverts upply to the la to the HH	part of the Rispray header	SS pump These	
	The integrated safety evaluation, E3-EV-97-0043, Rev. 0, for Modification DCR M3-97045 did not address the RSS/HHSI NPSH interface requirement for the ECCS recirculation modes of operation.					
	This RSS/HHSI in Westinghouse Ca NEU-0079 found the NPSHa and th discrepancy is a l 10CFR50.59 safe	that a substance of the second	E/FSE-C-NE antial margin of the HHSI p of appropriate	EU-0079. SA still exists b pumps. Then	E/FSE-C- etween efore this	
		Valid	Invalid	Review	Date	
initiator	Wakeland, J. F.				3/13/98	
	Neri, Anthony A		Н	H	3/16/98	
NAMES OF TAXABLE AND ADDRESS OF TAXABLE AND ADDRESS OF TAXABLE	Schopfer, Don K		- H		3/16/98	
IRC Chmn:	Singh, Anand K		ō		3/17/98	
Date:						
INVALID:						
Date:	5/13/98	a la la publicación de la del la dela del	na maja 144 n da kalanga ngangangangangangangangangangangangangan	NGCONDERVER AND INVESTIGATION OF	nang in the constraints and a su	
	DISPOSITION:					
	NU has conclude Report DR-MP3-1				ancy	
	Contrary to the st					

Contrary to the statement made in Discrepancy Report DR-MP3-1084, Integrated Safety Evaluation E3-EV-97-0043, Revision 0, addressed the impact of the modifications made by DCR M3-97045 on the NPSH available to the ECCS pumps during recirculation which includes the RSS/HHSI NPSH interface. (Note: There are several different sets of terminology used to refer to the two sets of high head safety injection pumps at Millstone Unit 3. The first set of pumps are designated as 3SIH\*P1A and \*P1B and are referred to as the Intermediate High Head Safety Injection Pumps by NNECo and the High Head Safety Injection (HHSI) Pumps by Westinghouse. The second set of pumps are designated as 3CHS\*P3A, \*P3B, and \*P3C and

Northe	ast	Util	ities
Millsto	ne l	Jnit	3

are referred to as the Charging Pumps and High Head Safety Injection Pumps by NNECo and as the ECCS (Emergency Core Cooling System) Pumps by NNECo and Westinghouse. S&L has apparently used HHSI to describe both sets of pumps. The various sets of terminology are intermixed within this text due to their extraction from various sources. The DR is interpreted to address both sets of pumps.)

Section 1.2 of the ISE describes the aspects of changes that are evaluated and indicates they include minimum NPSH / pump runout for the ECCS pumps used for recirculation. Section 2.1.2 of the ISE evaluates the effect of the modification on the probablity of occurrence of a previously evaluated malfunction of equipment important to safety. This section of the ISE refers to Westinghouse Letter NEU-97-278 (Reference 23 of the ISE) and states that Westinghouse and Stone and Webster have independently performed an evaluation of all ECCS branch flows and an evaluation of the available NPSH for the ECCS pumps as a result of all the modifications, including orifice installation in the pump discharge and ECCS branch lines, new valve positioning, spray nozzle capping, and increased flow to the RCF seals supplied by the CHS pumps. The ISE states that both analyses indicated that the branch flows exceed the minimum flow required for the core. The ISE also indicates the available pump NPSH is far in excess of the minimum required for successful operation of the ECCS pumps in recirculation mode. Based in part on the Westinghouse Letter, the ISE concludes there is no increase in the probablity of malfunction of the ECCS pumps as a result of the changes. The latest revision of the Integrated Safety Evaluation E3-EV-97-0043 (Revision 3) also contains the above discussion and conclusion although it now references Westinghouse calculation SAE/FSE-C-NEU-0079 in lieu of the Westinghouse Letter.

#### CONCLUSION:

NU has concluded that the issued identified in Discrepancy Report DR-MP3-1084 is a non-discrepant condition.

Integrated Safety Evaluation E3-EV-97-0043, Revision 0, does address the impact of the modifications made by DCR M3-97045 on the NPSH available to the ECCS pumps during recirculation including the RSS/HHSI NPSH interface. Revision 0 of the ISE indicates that Westinghouse and Stone and Webster have independently performed an evaluation of all ECCS branch flows and an evaluation of the available NPSH for the ECCS pumps as a result of all the modifications, including orifice installation in the pump discharge and ECCS branch lines, new valve positioning, spray nozzle capping, and increased flow to the RCP seals supplied by the CHS pumps. The ISE states that both analyses indicated that the branch flows exceed the minimum flow required for the core. The ISE also indicates the available pump NPSH is far in excess of the minimum required for successful operation of the ECCS pumps in recirculation mode. The ISE concludes there is no increase in the probablity of

Northeast Utilities Millstone Unit 3	ICA Discrepan			No. DR-M	/P3-1084
	malfunction of the latest revision of the 0043 (Revision 3) conclusion.	ne Integrate	d Safety Evaluation	ation E3-E	V-97-
	Significance level condition.	criteria do r	not apply as this	s is not a di	screpant
Previously Identified by NU?	🔿 Yes 🔘 No	Non D	iscrepant Conditio	n? Yes	O No
Resolution Pendin	g? Yes 💿 No	Re	solution Unresolve	nd? Yes	No No
VT Lead: VT Mgr:	Wakeland, J. F. Neri, Anthony A Schopfer, Don K Singh, Anand K 5/13/98	Acceptable	Not Acceptable	Review Needed	Date 5/13/98 5/13/98 5/14/98
SL Comments:	Sargent & Lundy a not a discrepant of E3-EV-97-0043, R 278 (Reference 23 NPSHa exists for recirculation, give EV-97-0043, Rev conclusion and ref NEU-0079. NU's for the old RSS of discrepancy in the recirculation prior	ondition. Si lev. 0 refere b) and reach the SIH and n worst-case . 3 (the curr response to onfiguration NPSHa ev	ection 2.1.2.c or ences Westingh the conclusion of CHG pumps d e conditions. S rent revision) re estinghouse Ca DR-MP3-0712 and demonstra aluation for EC	f Safety Ev ouse Lette ion that add uring ECC afety Evalu aches the s loulation S addressed ted that the	valuation r NEU-97- equate S cold leg uation E3- same AE/FSE-C this issue ere was no

DR No. DR-MP3-1085 ICAVP Northeast Utilities **Discrepancy Report** Millstone Unit 3 DR RESOLUTION ACCEPTED **Review Group:** System **Review Element: System Design** Potential Operability Issue Discipline: 1 & C Design O Yes **Discrepancy Type:** Calculation No No System/Process: NEW NRC Significance level: 4 Date FAXed to NU: Date Published: 3/20/98 Discrepancy: 3QSS\*LS56A.B.C.D low tolerance values are below the QSS pump suction minimum requirement. Description: Regarding the Instrument Setpoint for level switches 3QSS\*LS56A.B.C.D (the RWST 'empty' setpoint): CCN-2 to calculation 3451B03-01232E3, Rev. 0 uses the process setpoint value of 40.7 inches above the bottom of the RWST as specified in US(B)-295, Rev. 7. This value, per US(B)-295, Rev. 7, is supposed to encompass the total loop uncertainty (TLU) of the level measuring instrumentation used to trip the QSS pumps before the RWST 'empty' level (for vortex considerations) of 28 inches above the tank bottom is exceeded. Since the TLU is +12.7 inches, -13.8 inches, the level switches may not actuate until 26.9 inches above the tank bottom (40.7" -13.8" = 26.9"). The proper process setpoint is 41.8 inches above the bottom of the tank as was used in CCN-1 of calculation 3451B03-01232E3. Rev. 0: this value would ensure actuation of the level switches on, or before, the RWST level decreases to 28 inches above the tank bottom. Regarding the Process Setpoint for the RWST 'empty' level: US(B)-295, Rev. 7 uses a RWST empty level setpoint of 40.7 inches with an uncertainty of +13.8 inches, -12.7 inches. The setpoint should have been identified as 41.8 inches with an uncertainty of +12.7 inches, -13.8 inches. This would have made the minimum RWST empty level setpoint 28.0 inches (and the maximum RWST empty level setpoint 54.5 inches). Calculation HYD-H39, Rev. 1/CCN 1 determined that an RWST level of 28 inches is required to suppress vortexing and air entrainment in the QSS pump suction. The error in the setpoint and the setpoint uncertainty used in US(B)-295, Rev. 7 results in a minimum RWST empty level trip setpoint of only 26.9 inches. This does not conform with the QSS design requirement in HYD-H39, Rev. 1/CCN 1. This error does not have any safety significance because the RWST level requirement for QSS suction is determined in a conservative manner. Even if there was an onset of air ingestion, the QSS pumps would experience it for less than a minute immediately before they are tripped. After they are tripped, the QSS pumps would not be restarted: they perform no safety function after the RWST is empty. The error in the setpoint and the setpoint uncertainty used in

The error in the setpoint and the setpoint uncertainty used in US(B)-295, Rev. 7 results in a maximum RWST empty level trip Page 1 of 3

Iortheast Utilities Aillstone Unit 3	Discrepar	AVP ncy Repo		DR No. DR-	MP3-1085	
	setpoint for use in the containment pressurization analyses of 54.5 inches. This is the correct value to use in determining the duration of QSS spray for use in the design basis containment pressurization analyses. Therefore correction of the error in the setpoint does not affect inputs to calculations US(B)-253, US(B)-273, or US(B)-266.					
		Malla	Investig	Review	Data	
1-101-4	Deed Milliam	Valid	Invalid	Needed	Date 3/13/98	
	Reed,William.		Ц	H	3/16/98	
	Neri, Anthony A				3/16/98	
	: Schopfer, Don K		Ц	Ц	3/17/98	
IRC Chimn	Singh, Anand K				3/1//90	
Date	:					
	:					

**RESOLUTION:** Disposition:

NU has concluded that the issues reported in DR-MP3-1085 have identified CONFIRMED SIGNIFICANCE LEVEL 4 conditions which require correction. These discrepancies meet the criteria specified in NRC letters B16901 and 17010. They have been screened per attachment 11 of U3 PI-20 criteria and found to have no operability or reportability concerns and meet section 1.3.2.e of U3 PI-20 deferral criteria.

An error exists regarding the +12.7 TLU when -13.8 should have been used. This error does not violate the LB/DB. Even if there was an onset of air ingestion, the QSS pumps would complete their safety function before they are tripped. They perform no safety function after the RWST is empty. Calculation 3451B03-01232E3 and US(B)-295 will be revised to show the correct setpoint. Condition Report M3-98-2313 will be closed out to Bin CR M3-98-0138. The corrective actions for bin CR M3-98-0138 will correct calculations 3451B03-01232E3 and US(B)-295 post startup.

#### Conclusion:

NU has concluded that the issues reported in DR-MP3-1085 have identified CONFIRMED SIGNIFICANCE LEVEL 4 conditions which require correction. These discrepancies meet the criteria specified in NRC letters B16901 and 17010. They have been screened per attachment 11 of U3 PI-20 criteria and found to have no operability or reportability concerns and meet section 1.3.2.e of U3 PI-20 deferral criteria. Condition Report M3-98-2313 will be closed out to Bin CR M3-98-0138. Bin CR M3-98-0138 corrective actions will correct calculations 3451B03-01232E3 and US(B)-295 post startup.

Previously Identified by NU?	0	Yes	۲	No	Non Discrepant Condition? Yes	۲	No
Resolution Pending?	0	Yes	۲	No	Resolution Unresolved? Yes	۲	No
					Review		
NAME & A DESCRIPTION OF THE OTHER DESCRIPTION OF THE OTHER DESCRIPTION OF THE OTHER DESCRIPTION OF THE						-	0 -1 1

Printed 5/14/98 9:46:04 AM

Northeast Utilities Millstone Unit 3		ICAVP Discrepancy Report			DR No. DR-MP3-1085		
VT Lea VT Mg	r: DeMarco, J. d: Neri, Anthony A r: Schopfer, Don K n: Singh, Anand K e: 5/12/98	Acceptable	Not Acceptable	Needed	Date 5/12/98 5/12/98 5/12/98		
SL Comment	CR M3-98-2313 Completion of p						

the concerns of this DR.

Northeast Utilities Millstone Unit 3

# ICAVP Discrepancy Report

stone Unit 3	Discrepancy Repo	on
Review Group:	System	DR RESOLUTION ACCEPTED
Review Element:	Corrective Action Process	Potential Operability Issue
Discipline:	Mechanical Design	Potential Operability Issue
Discrepancy Type: System/Process:	Corrective Action Implementation HVX	<ul><li>Yes</li><li>No</li></ul>
NRC Significance level:	4	Date FAXed to NU:
		Date Published: 3/30/98
Discrepancy:	CR M3-96-1222 Corrective Ac	ction Implementation
Description:	Ventilation Requirements for A	, Rev. 0 'Charging Pump Area Appendix R' was reviewed as part mentation review of CR M3-96- lation identified the following
	since the exhaust fan is not op airflow of about 26,600 cfm in temperature. This assumption position of outside air balancin fan performance and resulting of operation, 3HVR*DMP32 is	Charles and the second s
	one train of unit heaters. The	alue for Qt include the capacity of capacity of the heaters could be the resulting temperature is above unit heaters.
	ft/min which does not seem re temperature differential. Using	n an air velocity of approx 730
	Cd = .40 + 0.0025(Ti - To) = 0 Ti = $570^{\circ}R$ = charging pump To = $542^{\circ}R$ = ccw area tempe A = 7 ft <sup>2</sup> = one-half of the doo NPL = 3.5 ft = one half of the dHnpl = 3.5 ft / 2 = 1.75 ft = di of lower half of door opening g = 32.2	cubicle temperature erature or opening area
	the airflow was found to be cfm = 60(0.47)(7)[2(32.2)(1.7	5)(28/570)]^.5 = 464 cfm
	from the door midpoint (NPL) distance between NPL and mi opening. The 464 cfm estimat	culation used the 12'-7" distance to the ceiling instead of the

Printed 5/14/98 9:46:40 AM

Northeast Utilities	ICAV	P		DR No. DR	MP3-1087	
Millstone Unit 3	Discrepancy	y Repo	ort		ALIMAN DISTRICTION OF A CONTRACT AND	
	4) The 1990 ASHRAI provides a method for exchange through op 27.3, a 82°F RPCCW pump area temperate was estimated to be lower than the 91,370 is expected that with charging pump room before sufficient airfle Btu/hr load.	or calcula ben doorw V area ter ure, the h 18,166 B 0 Btu/hr li a 82°F R tempera	ting the cooli ways. Using emperature an leat transfer to Tu/hr. This v oad in the ch RPCCW area ture would no	ing load due equation 10 or ad a 110°F ch through the or alue is signif arging pump temperature eed to appro-	to air on page harging open door ficantly o room. It e the ach 170°F	
				Review		
		Valid	Invalid	Needed	Date	
	Stout, M. D.	$\boxtimes$			3/20/98	
	Neri, Anthony A	$\boxtimes$			3/20/98	
	Schopfer, Don K	$\boxtimes$			3/23/98	
IRC Chmn:	Singh, Anand K				3/26/98	
Date:						
INVALID:						
Date:	5/13/98	INVERSE AND A DESCRIPTION OF THE OWNER OF THE	NANGARANG AMERIKAN MENGENARAN PERSONA P	NAMES AND AND AND ADDRESS OF A DESCRIPTION	SZANI ANDRONOMIA SZUMET BOUND	
RESOLUTION:						
	First Response					
		at Discre	pancy Repo	rt DR-MP3-1	087 has	
	NU has concluded the identified a condition requires correction. ( Attached ) was writte actions to resolve this this issue are as follo	onot prev Condition on to prov is issue.	Report ( CR	vered by NU ) M3-98-169 ssary correct	which 90 ( See tive	
	NU has concluded th identified a condition requires correction. ( Attached ) was writte actions to resolve thi	not prev Condition en to prov is issue. hws: No. 97-9 ed in DR- D No. MP	iously discov Report ( CR vide the nece The correction SCS-01471-MP3-1087. 3-042-98 to a	Vered by NU 1) M3-98-169 Issary correct ve actions to M3 to incorpo a fully qualifi	which 90 ( See tive correct prate the ed status.	
	NU has concluded the identified a condition requires correction. Of Attached ) was written actions to resolve the this issue are as follow 1. Revise calculation inaccuracies identifie 2. Revise / Close OD 3. Provide results to	not prev Condition en to prov is issue. nws: No. 97-5 ed in DR- D No. MP the Appe Calculati dy of the stigative of ined that charging ure range y and qui discussion crepancy.	iously discov Report ( CR ride the nece The correctiv SCS-01471-M MP3-1087. 3-042-98 to a andix R Program on No. 97-S0 calculation d computer and the conclusion pump cubic e during an A alification is in n, the LB / D therefore NL	vered by NU ) M3-98-168 ssary correct ve actions to M3 to incorpo a fully qualifi- ram owner for CS-01471-M3 loes require alysis (Gothio on of the calo les will rema Appendix R fi- not affected. B of MP3 is in J considers t	which 90 ( See tive correct orate the ed status. or 3 indicates c), by NU culation in within ire and Based not his issue	
	NU has concluded the identified a condition requires correction. Of Attached ) was written actions to resolve the this issue are as follow 1. Revise calculation inaccuracies identifie 2. Revise / Close OD 3. Provide results to incorporation. NU's assessment of that although the boo corrections, an invest engineering, determine will not change. The acceptable temperate equipment operability upon the preceding of impacted by this discont to be a level 4 discret These corrective act	not prev Condition en to prov is issue. nws: No. 97-5 ed in DR- D No. MP the Appe Calculati dy of the stigative of ined that charging ure range y and qui discussion crepancy.	iously discov Report ( CR ride the nece The correctiv SCS-01471-M MP3-1087. 3-042-98 to a andix R Program on No. 97-S0 calculation d computer and the conclusion pump cubic e during an A alification is in n, the LB / D therefore NL	vered by NU ) M3-98-168 ssary correct ve actions to M3 to incorpo a fully qualifi- ram owner for CS-01471-M3 loes require alysis (Gothio on of the calo les will rema Appendix R fi- not affected. B of MP3 is in J considers t	which 90 ( See tive correct orate the ed status. or 3 indicates c), by NU culation in within ire and Based not his issue	

Northeast Utilities Millstone Unit 3		CAVP bancy Rep		No. DR-N	/P3-1087
	NU has concluidentified a CC which has bee	ONFIRMED SIG	sue, reported in	DR-MP3-1 EVEL 4 con	087, has dition
	calculation 97- attached to thi stated in M3-IF temperatures of Appendix R fin Charging Pum plant operation that temperatur Appendix R fin EEQ limits of Attachments: Calculation 97	SCS-01471-M s transmission. RF-02100 that ( will remain with e in the Contro p Cubicle will r h. Calculation f rres in the Char e (122 °F. after 170 °F. during a -SCS-01471-M	3, Rev. 1, Ch	sed. A cop n NU's pos Cubicle mits during ipment in t in all mode M3, Rev. 1 icles during ot challeng	y is ition an he es of indicates g an e the
Previously Identified by NU?		quirements for No Non E	Appendix R Discrepant Conditio	m?) Yes	No
Resolution Pendin	g?) Yes 🔘	No Re	solution Unresolve	d?O Yes	No
VT Lead: VT Mgr:	Stout, M. D. Neri, Anthony A Schopfer, Don K Singh, Anand K 5/13/98	Acceptable	Not Acceptable	Review Needed	Date 5/13/98 5/13/98 5/14/98
SL Comments:	Comments on	First Response			
	The response		le sufficient info Level 4 calculat		

CR M3-98-1609 evaluation summary states "An investigative (scoping) computer analysis (Gothic) has been performed for the charging pump cubicle. The analysis concluded that the temperatures within the charging pump cubicles will remain within acceptable temperature limits during an Appendix R fire in the Control Room and the charging pump cubicle equipment qualification is not affected. Therefore, there is assurance that the charging pump cubicle and equipment is operable in all modes of plant operation". The results of the scoping analysis that provide the temperatures expected in the charging pump cubicle and what was considered to be acceptable temperature limits is needed to complete the review of DR resolution.

#### Comments on Second Response

This is considereded to be a significance level 4 discrepancy since the revised calculation provided with NU's response shows that the temperature rise in the charging pump rooms is within the maximum EQ temperature limits.

Northeast Utilities Millstone Unit 3 Disc

# ICAVP Discrepancy Report

Milistone Unit 3	Discrepan	icy Repo	ort		
Review Group: Review Element: Discipline: Discrepancy Type: System/Process: NRC Significance level: Discrepancy:	System System Design Mechanical Design Calculation NEW	DR onditioning L alculation T ilure in RSS eling of the conditioning on page 9 a S2A/B) oper rated cond	RESOLUTION F D D D D D D D D D D D D D D D D D D	Rev. 0 "Evalu cle" discrepa d latent coolir identified. t the air cond n conditions of ect-expansio	J: 4: 4/9/98 28-S3 Jation of ancies 10 litioning during the n
	a sensible capacity 104°Fdb/70.4°Fwb capacity of the coi temperature and th content of the enter (sensible capacity this is accounted fi Pump Cubicle tem 2) The results of th temperatures are a the capacity of the conditions. Calcula conditioning units loading.	y of 355,000 (at 18% RH I is a function the moisture ering air incr /total capact or in the GC aperature is the GOTHIC approx 120° cooling coi ation should	D Btu/hr at er H). The sension of the entry content of the reases the sec city) for the co DTHIC mode expected to model show F and 100 % Is is significat address the	tering air con- ible and later ering dry-bulk he air. As the ensible heat r coil decreases I the resulting increase. That the room RH. At this con- antly higher the ability of the	nditions of nt cooling moisture atio s. When g RSS m condition nan rated air
VT Lead: VT Mgr:	Stout, M. D. Neri, Anthony A Schopfer, Don K Singh, Anand K	Valid	Invalid	Review Needed	Date 4/1/98 4/3/98 4/3/98 4/4/98
Date: RESOLUTION:	5/13/98 First Response (M NU has concluded identified a conditi requires correction Attached) was writ to resolve this issu to revise calculatio conditions as spec reached in calcula discrepant conditio	that Discre on not previous Condition ten to provious The como on T-01528- ified in DR- tion T-0152	pancy Repo iously discov Report (CR) de the neces ective action S3 to correc MP3-1094. 8-S3 will not	vered by NU M3-98-1851 ssary correct in to correct the the assume The conclusion change. This	which (See ve action is issue is d inlet air on s

Printed 5/14/98 9:47:15 AM

	AVP ncy Rep		R No. DR-N	ИР3-1094
ders DR-MF	23-1094 to b	e a level 4 disc	repancy.	Elans, des site des ministrations des sons de
corrective ad	ction will be	completed post	MP3 resta	rt.
hments: ition Report	M3-98-1851			
emental Re	esponse (M3	-IRF-2341)		
elephone co nce support -IRF-02140.	ing NU's con	5/1/98, S&L re inclusion on DR-	 equested ad -MP3-1094,	iditional stated
fied a CONF	d that the is FIRMED SIC	sue reported in SNIFICANCE L corrected.	DR-MP3-10 EVEL 4	)94 has
B-S3 has been iched to this area room to	en complete s transmissio	98-1851 to revis d. A copy of th on. The conclus are bounded v IS2A/B.	ne revised c sion remain	alculation s that the
nments: lation T-015	528-S3, Rev	.1		
res 🖲 No		iscrepant Condition	on? Yes	No
res 🖲 No	Re	solution Unresolve	ed? Yes Review	No
1. D. hthony A	Acceptable	Not Acceptable	Needed	Date 5/13/98
e	er, Don K Anand K 13/98	er, Don K	er, Don K	er, Don K

SL Comments: Based on the results of Calculation T-01528-S3, Rev. 1 agree that this is a level 4 discrepancy

Northeast Utilities	ICA	VP		DR No. DR-	MP3-0667
Millstone Unit 3	<b>Discrepancy Report</b>				
Review Group:	System	INT DAMA ISBORIANI AND AND AND	DR RESOL	UTION REJECT	ED
Review Element:				Potential Onesa	billion to prove
Discipline:	Mechanical Design			Potential Opera	Dinty issue
Discrepancy Type:				Yes     No	
System/Process:				() NO	
NRC Significance level:	3		D	ate FAXed to N	U:
				Date Publishe	d: 12/8/97
Discrepancy	Coloulation D/D) 1	120 Tomos	son Montilet		
	Calculation P(B)-1 Calculation P(B)-1				
	ventilation requirer component cooling primary ventilation in the auxiliary built following discrepan 1) Calculation P(B) heat loads. The MC used in P(B)-1130 2) Calculation uses temporary fan but o 3) Calculation selec	nents for te water (CC resulting fi ding. Durin ncies were -900 is us CC and mis are lower to a supply a does not pr	emporary ver P) pumps ar- rom a fire on ig review of the identified: ed as the so- sc. electrical han those for air temperatures rovide a basing orary fan but	ntilation in the rea due to a l El 43'-6" or l the calculation urce for the in equipment he und in P(B)-9 ure of 86°F in s for using the	e oss of EL 66'-6" in the nternal eat loads 000. sizing the is value.
	basis for the fan pr	essure rati	ng selected.	Review	
		Valid	Invalid	Needed	Date
Initiator:	Stout, M. D.	$\boxtimes$			11/12/97
VT Lead:	Neri, Anthony A				11/18/97
VT Mgr:	Schopfer, Don K				12/1/97
IRC Chmn:	Singh, Anand K				12/4/97
Date:	and a strategic state of the last of the strategic				
INVALID:					
ning all any party and the state of the stat	Semantinumber a subset of the subset	NAME A COLORADOR AND POSSIBLE READ OF	NALOSEAN/GRANKSOA URBERINA	A & CARANTELINOS REGISTRATICE AND CONTINUE	and a state of the
Date:	5/12/98				
RESOLUTION:	First Response (M3	3-IRF-1302	:)		
	NU has determined Report DR-MP3-06	that the is 67 does no	sue reported	on Discrepa a discrepant	ince condition.
	1. The heat loads of from calculation P( Calculation 95-052 diverse plant condit comparable. CCN- temperatures than and concludes that	B)-900, and However tions and the to P(B)-1 those cons the addition	d augmented , these calcu heir total hea 1130 evaluat idered in the onal heat load	d by inputs fro ilations repre- at load values es the effect original calc d is within de	om SGCS sent s are not of higher ulation sign limits
	Calculation P(B)-90 conditions with both and the charging pu	the comp	onent coolin	g water syste	
	Calculation P(B)-11 fans which are rese	30 determ	ines the cap se in the eve	acity of the p nt of a fire in	fire area

Northeast	Utilities
Millstone	Unit 3

AB-1 to cool the CCP area assuming the operation of CCP equipment only. This condition is postulated to arise due to the loss of the ventilation system by a fire at elevation 66'-6" or by a fire on the south side of the fire sprinkler curtain that separates the charging pumps area from the CCP area. This scenario is described in Appendix R Compliance Report.

2. Per FSAR Section 9.4.0, 86°F is the outdoor summer design temperature used for ventilation equipment sizing at Millstone Unit 3. According to the 1973 ASHRAE. Handbook of Fundamentals, this 86°F outdoor temperature value will be exceeded for 21/2 % of the summer hours every summer on a statistical basis. Concurrent with the outdoor temperature excursions beyond 86°F, there will be indoor temperature excursions of almost the same magnitude beyond the indoor design of 110°F.

3. The fan is used in a free delivery application, therefore a pressure loss calculation is not necessary. It is installed in the frame of door A-24-2 in the Northwest corner of CCP area and the single panel Northeast door A-24-9 is opened to let the air out. The specified 1/8" i.w.g. fan static head thus provides a margin of safety.

Significance Level Criteria do not apply since this is not a discrepant condition.

#### Second Response (M3-IRF-01922)

NU has concluded that Item 1 of the follow-up issues on Discrepancy Report DR-MP3-0667 has identified a condition not previously discovered by NU which requires correction. CCN-02 for Calc. P(B)-1130, Rev. 00, was issued as a result of the approved corrective actions associated with CR-M3-98-1231 to revise the results to be consistent with the data in the latest revision of associated calculations P(B)-900, 3-92-103-191M3, and 92-LOE-189E3.

As requested, a copy of CCN-01 to calculation P(B)-1130 is attached. This CCN addresses the impact on the Temporary Ventilation System, which serves the Component Cooling Pump & Heat Exchanger area during loss of primary ventilation, of higher temperatures of CCP piping caused by Safety Grade Cold Shutdown operation, the revised electrical heat loads from Calc P(B)-900, and operation with a single CCP pump. Additional heat loads from piping (53,800 Btuh), utilized in CCN-01 to P(B)-1130, were taken from CCN-01 (copy attached) to Calculation P(B)-900, Rev. 1. CCN-01 to Calc P(B)-1130 is being revised/updated by CCN-02 to P(B)-1130 to utilize data from Rev. 1 of P(B)-900, including CCN-01.

1. The electrical equipment loads in P(B)-1130, Rev. 0, were originally taken from calculation P(B)-900. Rev. 0, with the discrepancies as noted in the DR. Page 6 of the current Revision of Calculation P(B)-900, (Rev. 1, copy attached), shows the Normal Condition heat load from electrical

Northeast Utilities	ICAVP	DR No. DR-MP3-0667
Millstone Unit 3	Discrepancy Report	
	equipment and lighting for the Com Heat Exchanger area as 95,660 Dtu/ based on electrical load inputs from 92-LOE-189E3, Rev. 0, was taken 103-191M3, Rev. 1.	Hr. This heat load, which is Electrical Calculation No.
	Calculation SGCS 95-052 is reference Calculation P(B)-900, Rev. 1, and we expected rise in temperature of the	as used to obtain the
	The revisions to calculation P(B)-11: calculation's conclusions that the ten have sufficient capacity to perform to Therefore NU concludes that design affected and this issue is considered	nporary ventilation fans their function. basis/licensing basis are not
	NU has concluded that the follow-up & 3 of DR-MP3-0667 do not represe	issues identified in Items 2 nt a discrepant conditions.
	2. Per Procedure OP 3314J, Rev. 4, attached), the outside stainwell door corner, door A-24-9, in the northeast of the HP trailer (outside of door A-2 the inside stainwell door in the northw removed and fans 3HVR-FN18A/B ( 1130) are installed in the door frame outside. Outdoor air is thus drawn in via the HP trailer, in the northeast co exhausted through doors A-24 -2 and corner. Reference Section 4.1 and 4 installation and operation of the fans	A-24-1, in the northwest corner, and the outer door 4-9) are blocked open, while vest corner, A-24-2, is as shown in Calc. P(B)- directing air to the through doorway A-24-9, orner of the Aux. Bldg., and A-24-1, in the northwest 2 of OP 3314J for
	3. In accordance with standard indust of fans for free blow applications, the from Buffalo Forge Co. Breezo Mode the following specifications: 5393 Cl 3/4 HP Motor, 220 VAC Single Phase upstream or downstream, is attache pressure losses associated with the through the building are negligible. T included in Technical Evaluation No indicates that the fans were functional design requirements.	hese units were selected el Catalog, each meeting FM @ 1/8" WG; 1140 RPM, se. No ductwork, either d to these fans. The air intake and discharge fests for Fans 18A & B, M3-EV-98-0030, Rev. 0,
	Attachments: CR-M3-98-1231 with approved correct CCN-01 to Calculation P(B)-1130, Re CCN-02 to Calculation P(B)-1130, Re Calculation P(B)-900, Rev. 1 CCN-01 to Calc P(B)-900, Rev. 1 Procedure OP 3314J, Rev. 4, Chang Technical Evaluation M3-EV-98-0030	ev. 0 ev. 0
	Supplemental Response (M3-IRF-22	60)
	The following information is provided	to S&L supplementing NU's

response to DR-MP3-0667 as stated in M3-IRF-01922:

During an NRC BTP 9.5-1 compliance inspection at MP3, no records could be located that confirmed flow testing of fans 3HVR-FN18A/18B. CR M3-97-3182 was initiated on 9/19/97 to provide the corrective actions. As part of the corrective actions for CR M3-97-3182, steps were added to OP 3314J, Rev. 4, to block open door A-24-9 in the Northeast corner of EL. 24'-6" the Auxiliary Building and a door of the RCA access point trailer, to provide a flow path for the fans. The fans are installed in door A-24-2 in the Northwest corner of EL. 24'-6" the Auxiliary Building. Outdoor air is thus drawn in through doorway A-24-9, via the RCA access point trailer, in the northeast corner of the Aux. Bidg., and exhausted through doors A-24-2 and A-24-1 (outer stairwell door), in the northwest corner. The procedure change was approved 1/28/98, and the flow test performed on 2/3/98. This supplemental information to the follow-up issue identified as Item 2 of DR-MP3-0667, which was concluded not to represent a discrepant condition.

#### Attachments:

CR-M3-97-3182 with approved corrective action plan Procedure OP 3314J, Rev. 4

#### Supplemental Response (M3-IRF-2336)

NU has concluded that the issues reported in DR-MP3-00667 has identified CONFIRMED SIGNIFICANCE LEVEL 4 conditions which have been corrected. During an NRC BTP 9.5-1 compliance inspection at MP3, no records could be located that confirmed flow testing of fans 3HVR-FN18A/18B. CR M3-97-3182 was initiated on 9/19/97 to provide the corrective actions. As part of the corrective actions for CR M3-97-3182, Change No. 3 to OP 3314J, Rev. 4 was issued to add steps to block open door A-24-9 in the Northeast corner of EL. 24'-6" the Auxiliary Building and a door of the RCA access point trailer, to provide a flow path for the fans. The fans are installed in door A-24-2 in the Northwest corner of EL. 24'-6" the Auxiliary Building. Change No. 3 to OP 3314J, Rev. 4 was approved 1/28/98. Change No. 3 to OP 3314J, Rev. 4, which added steps for blocking open door A-24-9 in the Northeast corner of EL. 24'-6" of the Auxiliary Building and a door of the RCA access point trailer, to ensure a flow path for fans 3HVR-FN18A/18B, was initiated and approved after 5/27/98, the date of completion of discovery of the CMP process. This is supplemental information to Item 2 of the followup issues of DR-MP3-0667. See M3-IRF-1922 and M3-IRF-2260 for additional information.

NU has concluded that although opening the auxiliary building and RCA access point trailer doors to allow supply air to enter the building was not previously proceduralized (Ref. procedure OP 3314J), it is considered that based on operator experience, the fact that the Technical Support Center (TSC) will be in operation and manned with experienced engineers and operators, and the time required to install the temporary ventilation fans, a reasonable assumption would be that the Northeast Utilities Millstone Unit 3

### ICAVP Discrepancy Report

doors would be opened to allow cooling air flow to the area even in the absence of specific procedural guidance. NU, therefore, considers this issue to be Significance Level 4. **Previously identified by NU?** () Yes No Non Discrepant Condition? Yes No Resolution Pending? Yes No Resolution Unresolved? () Yes O No Review Acceptable Not Acceptable Date Needed Initiator: Stout, M. D. 5/12/98  $\boxtimes$ VT Lead: Neri, Anthony A  $\boxtimes$ 5/12/98 VT Mgr: Schopfer, Don K  $\boxtimes$ 5/12/98 IRC Chron: Singh, Anand K 5/13/98 Date: 5/12/98 SL Comments: Comments on First Response NU is requested to provide a copy of CCN-1 to P(B)-1130 which is required to complete the review of NU's response. 1) Electrical Heat Loads NU's response does not adequately address the differences in the electrical equipment, cable, and lighting heat gains used in calculations P(B)-1130 and P(B)-900. The electrical equipment loads in calculation P(B)-1130 are lighting at 25,600 Btu/hr, MCC and misc. electrical equipment at 14,450 Btu/hr and cables at 4,200 Btu/hr for a total of 44,250 Btu/hr. The electrical equipment loads in calculation P(B)-900 are motor control centers at 13,200 Btu/hr, miscellaneous electrical equipment at 8,450 Btu/hr, cable loads at 4,200 Btu/hr, and lighting at 25,600 Btu/hr for a total of 51,450 Btu/hr. Inaddition calculation 3-92-103-191M3 has a different value for normal condition electrical loads. The electrical equipment loads shown on page 15 of calculation 3-92-103-191M3 for normal operation is 95,660 Btu/hr and was based on calculation 92-LOE-189E3. NU's response indicates that the heat loads of calculation P(B)-1130 were augmented by inputs from SGCS Calculation 95-052. Describe what information from 95-052 was used and address why it was not documented in calculation P(B)-1130. 2) Supply Air Temperature Agree with NU's response that the design summer outdoor air temperature is 86°F. Per NU's response the temporary fans draw air from the northwest stairwell at door A-24-2 and discharges to the elevation 24'-6" in the auxiliary building. The air is relieved to outdoors thru door A-24-9. Provide the basis for assuming that the temperature of the air drawn from the stairwell is the same as the outdoor air

temperature.

Northeast	t Utilities
Millstone	Unit 3

Discrepancy Report

Note that System Operating Procedure OP 3314J, Rev. 4 'Auxiliary Building Emergency Ventilation and Exhaust' describes using the temporary fans at door A-24-2 as exhaust fans but does not address what door(s) are opened to allow outside air into the area for cooling.

3) Fan Pressure

While the fan is not connected to ductwork, there are still pressure losses associated with the air intake into the auxiliary building and outlet from the auxiliary building. These losses should be addressed in the calculation.

Comments on Second and Supplemental Responses

Agree with NU's response for items 1 and 3.

Agree that Procedure OP 3314J Rev. 4, Change No. 3, dated 1/28/98 addresses the outdoor air intake path of item 2. As the need to change the procedure was identified after the CMP completion date this is considered to be a Level 3 discrepancy. FPER Section 8.5 states that portable ventilation is provided to cool the CCP pumps should all auxiliary building ventilation be lost. Failure to open a door to provide an outside air intake path for the temporary fans does not agree with the FPER and would have resulted in the area temperature being higher than that determined in calculation P(B)-1130. Disagree with NU's response that it is reasonable to rely on operator action not contained in the procedure to the open doors needed to provide an outside air intake path at the time the temporary fans are installed.

The significance level of this DR is unresolved.