



ARKANSAS POWER & LIGHT COMPANY

May 21, 1989

2CAN058906

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Mail Station P1-137  
Washington, D.C. 20555

SUBJECT: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report No. 50-368/89-007-00

Gentlemen:

In accordance with 10CFR50.73(a)(2)(i), attached is the subject report concerning the failure to reinstall a snubber following maintenance work due to inadequate work controls which resulted in operation prohibited by Technical Specifications.

Very truly yours,

*E.C. EWING / [Signature]*

E. C. Ewing  
General Manager,  
Plant Support

ECE:DAH:sgw  
attachment

cc w/att: Regional Administrator  
Region IV  
U. S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX 76011

INPO Records Center  
1500 Circle 75 Parkway  
Atlanta, GA 30339-3064

8906010194 890521  
PDR ADOCK 05000368  
S PNU

NRC Form 366  
(9-83)U.S. Nuclear Regulatory Commission  
Approved OMB No. 3150-0104  
Expires: 8/31/85

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Arkansas Nuclear One, Unit Two DOCKET NUMBER (2) PAGE (3)  
050003 61810F013TITLE (4) Failure to Reinstall Snubber Following Maintenance Work Due to Inadequate  
Work Controls Results in Operation Prohibited by Technical Specifications

EVENT DATE (5)			LER NUMBER (6)		REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)													
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names												
0	4	2	4	8	9	8	9	--	0	0	7	--	0	0	0	5	2	1	8	9	050003
OPERATING MODE (9) 5										THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)											
POWER LEVEL (10)		0		0		0		0		20.402(b)		20.405(a)(1)(i)		50.36(c)(1)		50.73(a)(2)(iv)		73.71(b)			
										20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(v)		50.73(a)(2)(vii)		73.71(c)			
										20.405(a)(1)(iii)		X 50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		Other (Specify in		Abstract below and			
										20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)		in Text, NRC Form		366A			
										20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x)							

## LICENSEE CONTACT FOR THIS LER (12)

Name	Telephone Number
Larry A. Taylor, Nuclear Safety and Licensing Specialist	Area Code 501 964-1310

## COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

Cause	System	Component	Manufacturer	Reportable to NPRDS	Cause	System	Component	Manufacturer	Reportable to NPRDS

## SUPPLEMENT REPORT EXPECTED (14)

Yes (If yes, complete Expected Submission Date)	No	EXPECTED SUBMISSION DATE (15)	Month	Day	Year
X					

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On April 24, 1989, while performing inservice inspections of mechanical snubbers as required by the plant's Technical Specifications (TS), it was identified that a snubber on a valve (2CV-4653) on the pressurizer spray line was disconnected. A review of past work on the valve revealed that the snubber was most probably left disconnected during maintenance work performed in May 1988 while ANO-2 was shutdown in a refueling outage. Following the discovery of this event, the snubber on 2CV-4653 was replaced. An engineering evaluation of the disconnected snubber was completed on April 25, 1989, which concluded that the pressurizer spray system would have remained operable during the time the snubber was removed. The cause of this event was determined to be inadequate work controls. The job order which was issued to accomplish the valve repair did not contain enough detail to ensure proper completion of the job considering the potential impact of the work on plant safety equipment. As a result of a previous event, procedure changes have been implemented addressing work control improvements. These changes include written logs for turnover of job activities and improved criteria for requirements of work plan development or increased detail in job instructions. Additionally, management has reemphasized the overall responsibilities of maintenance to properly complete work before release and return to service. These actions should minimize the recurrence of an event of this type.

JEDD

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Arkansas Nuclear One, Unit Two		Year	Sequential	Revision	
		Number	Number	Number	
	05000368	89	007	00	0120103

TEXT (If more space is required, use additional NRC Form 366A's) (17)

A. Plant Status

At the time of discovery of this event on April 24, 1989, Arkansas Nuclear One, Unit 2 (ANO-2) was in Operational Mode 5 (Cold Shutdown) with Reactor Coolant System (RCS) temperature at approximately 123 degrees Fahrenheit and RCS pressure at approximately 18 psia.

B. Event Description

On April 24, 1989, while performing inservice inspections of mechanical snubbers as required by the plants's Technical Specifications (TS), it was identified that snubber [SNB] 2CCA-15-H34 was disconnected from valve 2CV-4653 on the pressurizer [AB] spray line. A review of past work on the valve revealed that the snubber was most probably left disconnected during maintenance work performed in May 1988, while ANO-2 was shutdown in a refueling outage. The snubber had been disconnected to replace the packing on valve 2CV-4653 and then apparently was never reconnected. Three other snubbers on three valves had also been removed under the same maintenance job order.

Removal of the snubbers to replace the packing on these valves was not identified as being necessary to perform the activity during the initial planning of the job order. However, once work was begun in accordance with the job order, it was identified that the snubbers would have to be removed to gain access to the valve packing. The removal and replacement of the snubbers was added to the scope of the job order and work proceeded. Apparently, following the completion of work on valve 2CV-4653, the snubber was not replaced and this was not recognized prior to closing the job order. Additionally, a review of the job order identified that visual inspections required by the job order were not performed for any of the snubbers removed.

C. Safety Significance

The valves and snubbers involved in this event are located on the pressurizer spray system. The pressurizer spray system is part of the RCS and supplies RCS water to the pressurizer spray nozzle from either of two reactor coolant pumps. The engineering evaluation performed as a result of the disconnected snubber determined that the pressurizer spray system remained operable and the RCS piping seismic qualification was not significantly affected. Therefore, this event is not considered safety significant.

D. Root Cause

The cause of this event was determined to be inadequate work controls. The job order which was issued to accomplish the valve repair did not contain enough detail to ensure proper completion of the job considering the potential impact of the work on plant safety equipment. The critical steps to ensure that the snubbers were properly installed at the completion of the job were not adequately controlled by the job order.

E. Basis for Reportability

TS 3.7.8 requires that all snubbers be Operable. With a snubber inoperable, within 72 hours the inoperable snubber must be replaced or restored to Operable status and an engineering evaluation performed, or the attached system must be declared inoperable and the appropriate Action Statement for the system must be followed. As a result of this event, the snubber had been unknowingly disconnected for almost one year. Therefore, the snubber was not restored to Operable status within 72 hours and the pressurizer spray line had not been declared inoperable.

F. Corrective Actions

Following the discovery of this event, the snubber on 2CV-4653 was replaced and the other three snubbers were inspected. Additionally, an engineering evaluation of the disconnected snubber was completed on April 25, 1989, which concluded that the pressurizer spray system would have remained operable during the time the snubber was removed.

As a result of a previous event (see Additional Information), procedure changes have been implemented addressing work control improvements. These changes include written logs for turnover of job activities and improved criteria for requirements of work plan development or increased detail in job instructions. Additionally, management has reemphasized the overall responsibilities of maintenance of properly complete work before release and return to service. These actions should minimize the recurrence of an event of this type.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Arkansas Nuclear One, Unit Two			Sequential	Revision	
		Year	Number	Number	
		05000368	89--	007--	0003OF03

TEXT (If more space is required, use additional NRC Form 366A's) (17)

G. Additional Information

A previous event involving inadequate work controls was documented by LER 50-313/88-023. On December 16, 1988, during the performance of a post maintenance leak test on a manual isolation valve, a non-isolable RCS leak developed due to the failure to tighten the valve packing retainer. The root cause of this event was determined to be inadequate work controls. The job orders which were issued to accomplish the valve repair did not contain enough detail to ensure proper completion of the job without incident considering the plant conditions during performance of the activity, the potential impact of the work on plant and personnel safety, and the type of personnel involved in the activity.

Energy Industry Identification System (EIIS) codes are identified in the text a [XX].