

FERMONT YANKEE NUCLEAR POWER CORPORATION

P. O. BOX 157 GOVERNOR HUNT ROAD VERNON, VERMONT 05354

> May 24, 1989 VYV 89-105

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

REFERENCE: Operating License DPR-28 Docket No. 50-271 Reportable Occurrence No. LER 89-19

Dear Sirs:

As defined by 10CFR50.73, we are reporting the attached Reportable Occurrence as LER 89-19.

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

James Pellitie

James P. Pelletier Plant Manager

cc: Regional Administrator USNRC Region I 475 Allendale Road King of Prussia, PA 19406



NRC Form. 384	U.S. NUCLEAR REGULATORY COMMISSION							
(9-83)	APPROVED OMS NO.3150-0104							
	EXPIRES 8/31/96							
LICENSEE EVENT REPORT	(LER)							
FACILITY NAME 1	DOCKET NO. 2 PAGE 3							
VERMONT YANKEE NUCLEAR POWER STATION	0 5 0 0 0 2 7 1 0 1 OF 0 3							
TITLE 4 Inadvertent Primary Containment Isolation Syst	tem Acutations Due to a Malfunction							
EVENT DATE \$ 1 LEP NUMBER 6 REPORT DA	ATE 7 OTHER FACILITIES INVOLVED 6							
MONTH DAY YEAR YEAR SEQ. # REV# MONTH DAY	YEAR FACILITY NAMES DOCKET NO. (S)							
0 5 0 1 8 9	N/A 0 5 0 0 0							
0 5 0 1 8 9 8 9 -0 1 9 -0 0 0 5 2 4	8 9 N/A 0 5 0 0 0							
OPERATING THIS REPORT IS SUBMITTED PURSUANT TO RE	EQUIREMENTS OF 10 CFR X ONE OR MORE							
POWER 20.405(a)(1)(I) 50.36(a)(1)	50.73(a)(2)(V) $73.71(c)$							
LEVEL 1º 1 0 0 20.405(a)(1)(II) 50.36(a)(2)	50.73(a)(2)(vii) OTHER:							
20.405(a)(1)(III) 50.73(a)(2)(I)	50.73(a)(2)(viii)(A)							
20.405(a)(1)(iv)50.73(a)(2)(II) 50.73(a)(2)(viii)(B)							
20.405(a)(1)(V) 50.73(a)(2)(11)	[) 50.73(a)(2)(x)							
LICENSEE CONTACT FOR TH.	TELEPHONE NO.							
	AREA							
	CODE							
JAMES P. PELLETIER, PLANT MANAGER	8 0 2 2 5 7 - 7 7 1 1							
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE	E DESCRIBED IN THIS REPORT 13							
TO NPRDS	TO NPROS							
X IL DET G080 NO N/A	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							
SUPPLEMENTAL REPORT EXPECTED 1*	SUBMISSION							
YES (IF you complete EXPECTED SUBMISSION DATE)	NO DATE 15							
ABSTRACT (Limit to 1400 spaces, i.e. fifteen single-	space typewritten lines 16							
At approximately 1705 and 1822 on 5/01/89, with	the reactor operating at approxima-							
Standby Gas Treatment System (SBGTS) initiations occu	urred. The PCIS isolation, which							
isolates the primary and secondary containment venti	lation, initiated when the "B"							
Reactor Building Ventilation Radiation Monitor (EIIS=MON) signal was noisy and drifted								
high enough such that the noise component of the signal exceeded its trip set-point.								
The inclusions were promptly posst and systems	were restored to permal exercise							
The isolations were promptly reset and systems were restored to normal operation								
LCO operability requirements were satisfied at all times.								
Technicians investigated and replaced the sense Reactor Building Ventilation Radiation Monitor System	or/converter, (EIIS=DET) in the "B" m, following the second event.							
The root cause for the sensor/converter misoper but is being investigated.	ration has not yet been determined							

L

NRC Form, 384A (9-83)

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMS NO.3150-0104 EXPIRES 8-31-96

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

UTILITY NAME (1)	DOCKET	NO. (2)	l	LER	NUMBE	R (6)	PAC	GE (3)
			YEAR		SEQ.	#	REV#			
VERMONT YANKEE NUCLEAR POWER STATION	0 5 0 0	0 0 2 7 1	819	_	0 1 1	191	- 010	0 2	OF	0 3
TEXT (If more space is required, use a	dditiona	al NRC For	m 384A) (1	17)					

DESCRIPTION OF EVENTS

At approximately 1705 hours and 1822 hours on 5/01/89, with the reactor operating at approximately 100% power, two Primary Containment Isolation System (PCIS) Group III and subsequent Standby Gas Treatment System (SBGTS) initiations occurred. The PCIS isolation, which isolates the primary and secondary containment ventilation, initiated when the Reactor Building Ventilation Radiation Monitor "B" signal was noisy and drifted high enough such that the noise component of the signal exceeded its trip setpoint. At that time, the Reactor Building Radiation Monitor "A" was reading normal.

At approximately 1719 and 1827 respectively, after verifying normal radiation levels, Control Room personnel promptly reset the isolation and returned all systems to normal operation.

The "B" Reactor Building Ventilation Radiation Monitor was declared inoperative by Control Room personnel, however, the Technical Specification LCO condition was met.

The I&C Department investigated the problem and confirmed that the system signal was noisy and had drifted high enough such that the noise component of the signal exceeded the trip setpoint. At that time the sensor/converter was replaced with a spare unit. No additional trips have occurred to date.

At 1332 on 5/02/89, the "B" Reactor Building Ventilation Monitor was repaired and declared operable.

There are two radiation detectors monitoring the Reactor Building Ventilation Exhaust Duct. A signal from either detector will cause the system to trip and generate an isolation signal and a signal to start the Standby Gas Treatment System.

CAUSE OF THE EVENTS

The immediate cause of the upscale drifting is assumed to be a faulty sensor/converter in the "B" Reactor Building Ventilation Radiation Monitoring System.

The root cause of the sensor/converter failure can not be determined at this time. Exterior inspection of the device revealed no notable defects.

ANALYSIS OF EVENT

The events that occurred as a result of the isolations did not have any safety implications to plant equipment or the public.

The PCIS Group III and SBGTS operated as designed and successfully isolated the primary and secondary containment ventilation. A PCIS Group III isolation and SBGTS initiation are the expected result of a trip of one side of the Reactor Building Ventilation Radiation Monitoring System. NRC Form 384A (9-83)

U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMS NO.3150-0104 EXPIRES 8-31-96

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

UTILITY NAME (')	DOCKET NO. (2)	LER NUMBER (°)	PAGE (3)
		YEAR SEQ. # F	EV#
VERMONT YANKEE NUCLEAR POWER STATION	0 5 0 0 0 2 7 1	8 9 - 0 1 9 - 0	0 0 3 0 5 0 3

ANALYSIS OF EVENT (Cont.)

After closely reviewing the Reactor Building Ventilation Radiation Monitor recorder chart, it was determined that a very gradual upward trend had developed over a period of time due to a fault in the monitor. This upward trend, coupled with the noise signal that was present was of sufficient magnitude to trip the system.

No surveillances or unusual activities were in progress at or near either the detectors or the panels that hold the electronics.

Detector Technical Specifications Operability Requirements were satisfied at all times.

CORRECTIVE ACTIONS

1. Once radiological conditions were determined to be normal, the isolation was reset and systems returned to normal operation.

2. After the second trip the I&C Department replaced the sensor/converter and the equipment was subsequently declared operable. The sensor/converter that was replaced was a GE Model No. 194X927G012.

3. The I & C Department has discussed the problem with the vendor (GE/Reuter Stokes). The vendor was not aware of any similar sensor/converter problems experienced in other plants. No potential root cause of our failure could be determined from this effort.

4. Nuclear Network and NPRDS have also been queried, however, no responses have been received to date.

5. The sensor/converter that was replaced will be autopsied by the vendor to determine the cause of the failure.

ADDITIONAL INFORMATION

A similar incident occurred on 1/31/89. The sensor/converter in the "B" Reactor Building Ventilation Radiation Monitoring System was replaced after an apparent failure.

At the time of that incident, the failed sensor/converter had its detector replaced and was bench tested for 100 hours without failure.