

*Limitorque Actuation Systems*

U.S. Nuclear Regulatory Commission  
Document Control Desk  
11555 Rockville Pike  
Rockville, MD 20852

facsimile #301-816-5151

LIMDOC-2021-001  
February 4, 2021

**Subject: Interim Report of the Evaluation of a Deviation Pursuant to 10 CFR 21.21(a)(2)**

**Description of the Deviation**

Flowserve – Limitorque was informed by OPG Darlington Nuclear Plant that during testing of a SMB-0 actuator prior to installation, the actuator failed to return from manual handwheel mode to motor operation mode. Site personnel removed the electric motor from the actuator and discovered that the worm shaft gear cam pin had become detached from the worm shaft clutch gear. The actuator was one of six identical actuators supplied to OPG by Limitorque in January 2020. Subsequent site inspection of five other actuators received on the order revealed that the cam pins were loose in the worm shaft clutch gear. The issue was discovered prior to placing any of the actuators into service.

Although no other occurrences of this issue have been reported, Flowserve is continuing to evaluate this issue regarding the potential extent of condition. Currently, there are no recommended actions for the nuclear plants concerning this Part 21 notification.

**10 CFR21.21 Interim Report Details**

- (i) *Name and address of the individual or individuals informing the Commission.*

Tyler Thompson  
Director, Plant Manager  
Flowserve, Limitorque Actuation Systems  
Lynchburg VA, 24502

- (ii) *Identification of the facility, the activity, or the basic component supplied for such facility or such activity within the United States which fails to comply or contains a defect.*

The basic component containing the defect is worm shaft clutch gear  
Limitorque part # 60-420-0130-1



### *Limitorque Actuation Systems*

- (iii) *Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.*

Flowserve Corporation, Limitorque Actuation Systems  
Lynchburg VA, 24502

- (iv) *Nature of the defect or failure to comply and the safety hazard which is created or could be created by such defect or failure to comply.*

The defect was the result of improper assembly of the worm shaft clutch gear. The cause of the defect was attributed to human error. The investigation revealed that during installation of the cam pin into the gear the machinist manufacturing the component failed to complete the process step required to permanently retain the cam pin in position.

A safety related function of the SMB/SB/SBD actuator is to automatically return from manual handwheel mode to motor operation mode. The function of the cam pin in this transition is to contact the clutch trippers, pushing them outward, until the declutch fork is released which allows the clutch to reengage with the worm shaft gear restoring motor operation. If the cam pin becomes detached from the worm shaft clutch gear, the actuator cannot return to motor operation. Therefore, the deviation described above constitutes a reportable defect.

- (v) *The date on which the information of such defect or failure to comply was obtained.*

Flowserve was initially notified by OPG December 9, 2020.

- (v) *In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, being supplied for, or may be supplied for, manufactured, or being manufactured for one or more facilities or activities subject to the regulations in this part.*

A quantity of six worm shaft gears with the defect were supplied to OPG in SMB-0 actuators on Limitorque Order # 176325.001 (Actuator Serial # L1231918, L1231919, L1231920, L1231921, L1231922, & L1231923).

- (vii) *The corrective action which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action.*

Containment actions related to this issue consist of the following. The six gears affected were returned from OPG to Limitorque for evaluation and replacement. All SMB worm shaft gears of similar design in stock in Lynchburg were placed on temporary QC hold for enhanced inspection. No defective parts were found. For



*Limitorque Actuation Systems*

worm shaft gears currently being manufactured, an additional QC inspection point has been added for verification of proper cam pin installation.

The details and schedule for permanent corrective actions remains pending.

- (viii) *Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees.*

Currently there is no action required by the nuclear plants in response to this Part 21 notification.

- (ix) *In the case of an early site permit, the entities to whom an early site permit was transferred.*

N/A

**Evaluation Completion Date**

Flowserve – Limitorque expects to complete its 10 CFR Part 21 evaluation on or before April 20, 2021.

Technical questions concerning this notification can be directed to:

Kyle Ramsey, Senior Product Engineer, Flowserve – Limitorque

[kramsey@flowserve.com](mailto:kramsey@flowserve.com)

A handwritten signature in black ink, appearing to read "Tyler Thompson". The signature is written in a cursive style with a horizontal line underneath it.

Tyler Thompson

Director, Plant Manager

Flowserve. Limitorque Actuation Systems

Email: [TyThompson@flowserve.com](mailto:TyThompson@flowserve.com)

Cc: Zachary Cox, Flowserve Limitorque Engineering Manager  
Christopher Shaffer, Flowserve Limitorque Quality Assurance Supervisor