



HEAF Workshop

Oct 20, 2021

Robert Rishel
Director, Nuclear Engineering PRA – Duke Energy

High Energy Arc Fault (HEAF) Operating Experience

- Two events at Duke Energy indicate the current guidance on HEAF Zone of Influence (ZOI) overstates the impact on targets in the ZOI
 - Both events the damage to Structures Systems and
 Components was limited to the associated cabinet/ enclosure
 - Close proximity cables (both thermoplastic and thermoset) showed evidence of heat damage but did not fail (remained functional) or catch fire as predicted.
 - In Harris event nearby cable tray was degraded but functional



HEAF Operating Experience – Harris Event

- Harris HEAF did involve Aluminum
- ZOI of damage was less than predicted by current guidance
 - Event was an HEAF connected to generator
 - Cables within 1.5 feet from center of HEAF were not faulted as predicted (6 inches from encloser)
 - Sprinklers in vicinity of HEAF were activated by event
 - Water flowed after the HEAF event was completed
 - Fault duration was estimated at 100ms
 - Interior of bus cubicle was consumed by the fire



HEAF Operating Experience – Robinson Event

- Robinson HEAF did not involve Aluminum but is of interest to this topic because:
 - ZOI of damage was less than predicted by current guidance
 - Long duration event as protective relaying did not stop the event
 - Cable within 3-6 inches were not faulted as predicted
 - SSCs within 3 feet of faulted cabinet were not faulted as predicted
 - Horizonal splatter of hot debris was evident for some distance where the HEAF event melted a hole in the cabinet
 - Interior of cubicle was consumed by the fire



Questions?

