NRC FORM 591M PA (07-2012) 10 CFR 2.201	RT 1 SAFETY INSPECTION	REPORT AN	ID COI		CLEAR REGULATORY	COMMISSION	
1. LICENSEE/LOCATIO	N INSPECTED:	- Marion II	2. NRC/R	REGIONAL OFFICE			
Wallace & Associates, LLC 1005 S. 8th Street Suite B Kalamazoo, MI 49009 REPORT NUMBER(S) 2021001			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352				
3. DOCKET NUMBER(S		4. LICENSE NUMBE	R(S)		5. DATE(S) OF INSPECTI	ON	
030-36875		21-32557-01	-32557-01		December 1 & 3, 2 office review thru		
J. Based on 2. Previous 3. The violation-repet discretion 4. During the cited in at with 10 C (Violation License be tested certification certification on the certification on the certification on the certification of	is inspection, certain of your activities, coordance with NRC Enforcement Polific FR 19.11. Is and Corrective Actions) Condition 13.A of Amendment of registration NC-646-D-12 to the above, between May 29. Troxler Electronic Laboratorie te of registration, NC-646-D-12 to leak tested again as of Decemimmediately performed the leak interest of the second and the leak interest and the second and the second and the second action of the second and the second action of the	as described below by the inspector as reing taken, and the sed involving the formation at intervals 26-S. 9, 2020 and Deces, Model 3216 26-S. Specification at intervals 26-S.	and/or attorice or and/or attorice or and/or attorice or and/or attorice or and to expend to exp	ached, were in violation VIOLATION, which make gauge every 12 mast leak test was dexceeding 12 more occember 3, 2021.	n of NRC requirements a say be subject to posting uired that the sealed the as specified in the failed to perform the failed to perf	e self-identified roise and are being in accordance sources to the the leak in the 20, and had	
	Sta	atement of Corr	ective Ad	ctions			
I hereby state that, w		me to the Inspecto	r will be ta	ken to correct the viola	ations identified. This sta	atement of	
corrective actions is r	within 30 days, the actions described by made in accordance with the requirement fance will be achieved). I understand t	ents of 10 CFR 2.20	1 (correct	ive steps already taker	n, corrective steps which	will be taken.	
corrective actions is r	oithin 30 days, the actions described by made in accordance with the requirement	ents of 10 CFR 2.20	1 (correct	ive steps already taker	n, corrective steps which	will be taken.	
corrective actions is r date when full compli	ithin 30 days, the actions described by made in accordance with the requirem iance will be achieved). I understand the PRINTED NAME	ents of 10 CFR 2.20 hat no further writte	1 (correct	ive steps already taker e to NRC will be requir	n, corrective steps which	will be taken, equested DATE	
corrective actions is r date when full compli TITLE LICENSEE'S	of thin 30 days, the actions described by made in accordance with the requirementance will be achieved). I understand t	ents of 10 CFR 2.20 hat no further writte President	on (correction response	ive steps already taker e to NRC will be requir SIGNATURE	n, corrective steps which	will be taken, equested	

(07-2012) 10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

LICENSEE/LOCATION INSPECTED:

Wallace & Associates, LLC 1005 S. 8th Street

Suite B

Kalamazoo, MI 49009

REPORT NUMBER(S) 2021001

2. NRC/REGIONAL OFFICE

Region III

U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210

Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-36875

4. LICENSE NUMBER(S)

21-32557-01

5. DATE(S) OF INSPECTION

December 1 & 3, 2021 with inoffice review thru Jan 5, 2022

(Continued)

Title 10 CFR 71.5(a) requires, in part, that a licensee who transports licensed material where transport is on public highways comply with the applicable requirements of the regulations of the Department of Transportation (DOT) in 49 CFR Part 172. Title 49 CFR 172.704(c) requires, in part, that a hazmat employee receive initial training and recurrent training at least once every 3 years.

Contrary to the above, between November 8, 2015 and December 1, 2021, the licensee failed to provide recurrent training once every 3 years for its hazmat employees that satisfies the requirements in Subpart H to 49 CFR Part 172. As corrective action, the licensee will contact the gauge manufacturer or the vendor to schedule the DOT Hazmat training.

NRC FORM 592M (10-2020)	Mate	erials Insp	oection	n Record	U.S. NU	JCLEAR REGULATORY COMMISSION			
1. Licensee Name:	2. Docket Number(s):			3. License Number(s)					
Wallace & Associates, LLC	030-36875			21-32557-01					
4. Report Number(s):			5. Date(s) of Inspection:						
2021001				December 1 & 3, 2021 with in-office review thru Jan 5, 2022					
6. Inspector(s):			7. Program Code(s):		8. Priority:	9. Inspection Guidance Used:			
Zahid Sulaiman, Health Physicist			03121		5	87124			
10. Licensee Contact Name(s): 11. Licensee E-mail Ad			dress:		12. Licensee Telephone Number(s):				
Jillian Fraze, RSO	rtageps.org nowethroofing.com		(313) 378-8885						
13. Inspection Type: Initial 14	Locations Inspected:			15. Next Inspection Date (MM/DD/YYYY):					
Routine Announced	_		d Office	12/01/20		Normal Extended			
Non-Routine ✓ Unannounced	Temporary Job	Site Rem	note			Reduced No change			

16. Scope and Observations:

This was an unannounced routine inspection of a constructing testing company authorized to possess and use portable gauges at its main office in Kalamzoo, Michigan, and at a satellite office in Three Rivers, Michigan. The licensee possess a Troxler Electronic Laboratories, Model 3612 portable gauge for measuring the physical properties of materials. The licensee employed two authorized gauge users who have completed the manufacturer and the initial DOT hazmat training. The licensee secured the gauge in accordance with two barrier rule in the storage vault which is locked inside the cabinet inside the licensee facility, and in the vehicle. The licensee's main office located in Kalamazoo, Michigan is the only active location of use. The licensee had moved from the Three Rivers, Michigan location approximately eight years ago and from the satellite storage facility in Kalamazoo, Michigan about three years ago. The licensee will submit an amendment request to remove these two locations of use from the license. The licensee will also submit an amendment request to change the license to storage only.

PERFORMANCE OBSERVATIONS

This inspection was consisted of tour of the facilities, interview with select licensee personnel, a review of select records, an observation of security of the materials, and independent measurement. The inspector visited the Three Rivers, Michigan facility and found that the licensee had moved from this location over eight years ago. The inspector toured the main office in Kalamazoo, Michigan. The portable gauge were adequately secured with two independent physical barriers while in storage at the main office or during transportation. The inspector had the licensee staff described gauge use, storage of gauge at temporary job site and during transportation, emergency procedure, placement of shipping papers in the vehicle, and other procedures. The inspector reviewed selection of licensee records including leak tests, inventory, package receipts, utilization log, annual audit, training records, and emergency response procedure. Through these demonstrations, observation, and discussion, the inspector found that the licensee staff was knowledgeable of radiation protection principles and licensee procedures. The inspector performed independent and confirmatory radiation measurements which indicated no residual contamination or exposures to members of the public in excess of regulatory limits.

The inspector identified two violations. The first was a violation of License Condition 13.A of Amendment No. 4 of NRC license 21-32557-01 for failure to perform the leak test of a portable gauge every 12 months, as specified in the certificate of registration, NC-646-D-126-S. Specifically, the last leak test of the gauge was done on May 29, 2020, and had not been leak tested again as of December 1, 2021, an interval exceeding 12 months.

The second violation was of 10 CFR 71.5(a), the licensee failed to provide recurrent training once every 3 years for

NRC Form 592M (10-2020) Page 1 of 2

NRC Form 592M (10-2020) Page 2 of 2