Kevin Cimorelli Site Vice President Susquehanna Nuclear, LLC 769 Salem Boulevard Berwick, PA 18603 Tel. 570.542.3795 Fax 570.542.1504 Kevin.Cimorelli@TalenEnergy.com



March 30, 2022

Attn: Document Control Desk U. S. Nuclear Regulatory Commission Washington, DC 20555-0001

SUSQUEHANNA STEAM ELECTRIC STATION LICENSEE EVENT REPORT 50-387/2021-005-01 UNIT 1 LICENSE NO. NPF-14 PLA-7992

10 CFR 50.73

Docket No. 50-387

Attached is Licensee Event Report (LER) 50-387/2021-005-01. The LER supplement reports an event involving an automatic scram due to a Reactor Protection System actuation as a result of Turbine Valve fast closure and subsequent Electro-hydraulic Control Fluid pressure perturbation. The condition is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in automatic actuation of a system listed in 10 CFR 50.73(a)(2)(iv)(B).

There were no actual consequences to the health and safety of the public as a result of this event.

This letter contains no new or revised regulatory commitments.

K. Cimorelli

Attachment: LER 50-387/2021-005-01

Copy: NRC Region I Mr. C. Highley, NRC Senior Resident Inspector Ms. A. Klett, NRC Project Manager Mr. M. Shields, PA DEP/BRP

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION						SION	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 08/31/2023										
(U8-2020)								Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported									
NULAR HEQUID								lessons learned are incorporated into the licensing process and fed back to industry. Send									
	LICENSEE EVENT REPORT (LER)								comments regarding burden estimate to the POIA, Library, and Information Collections Branch (1-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to								
2 2		(See Pag	e 3 for requ	uired number of	digits/cha	aracters	for each l	olock)	Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs (3150-0104) Atta: Desk all: oirs submission@omb eop gov. The NRC may not conduct or								
****	* ****	(See NURI	EG-1022, F //www.prc.a	R.3 for instruction	and gui	dance to ns/nureo	r complet s/staff/sr1i	ting this 022/r3/)	sponsor, a	and a person is not	required to respond t	o, a collection	of inforr	mation unl	ess the document		
		ionin <u>mapon</u>						······································	requesting	g or requiring the col	lection displays a cur	renily valid O	MR COUL	ol number			
1. Facilit	1. Facility Name								2. Doc	2. Docket Number							
Susq	ueha	nna Ste	am Ele	m Electric Station, Unit 1					05000387				1 of 3				
4. Title																	
Auto	matic	Reacto	or Scrar	n due to T	urbine	e Con	trol Va	alve F	Fast C	losure							
5. E	5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved							
Month	Day	Year	Year	Sequential	Rev	Month	Day	Yea	r Fac	ility Name				Docket	Number		
				Number					Fac	ility Name				Docket	Number		
11	30	2021	2021	- 005 -	01	03	30	202	2	anty Nume			Ċ	05000			
9. Opera	ting M	ode		I	1	I		10.	Power	Level							
1 080																	
		11	I. This Re	port is Subm	itted P	irsuant	to the l	Requir	ements	of 10 CFR §:	(Check all	that app	'y)				
10 0	CFR	Part 20	□ 20).2203(a)(2)(vi)		50.36(c)((2)		⊠ 50.73(a	a)(2)(iv)(A)	□ 5	0.73(a	a)(2)(x)			
□ 20.22	01(b)		□ 20	□ 20.2203(a)(3)(i) □				50.46(a)(3)(ii)			□ 50.73(a)(2)(v)(A)			10 CFR Part 73			
□ 20.22	01(d)		□ 20	□ 20.2203(a)(3)(ii) □			50.69(g)			□ 50.73(a	□ 50.73(a)(2)(v)(B)			□ 73.71(a)(4)			
□ 20.22	03(a)(1)	□ 20	□ 20.2203(a)(4) □] 50.73(a)(2)(i)(A)			□ 50.73(a	□ 50.73(a)(2)(v)(C)			□ 73.71(a)(5)			
□ 20,22	03(a)(2	2)(i)	1	10 CFR Part 21				50.73(a)(2)(i)(B)		□ 50.73(a	□ 50.73(a)(2)(v)(D)			□ 73.77(a)(1)(i)			
□ 20.2203(a)(2)(ii)			□ 21	□ 21.2(c) □ !				50.73(a)(2)(i)(C)			□ 50.73(a)(2)(vii)			□ 73.77(a)(2)(i)			
□ 20.2203(a)(2)(iii)			1	10 CFR Part 50 🗆 5				i0.73(a)(2)(ii)(A)		□ 50.73(a	□ 50.73(a)(2)(viii)(A)			□ 73.77(a)(2)(ii)			
□ 20.2203(a)(2)(iv)			□ 50	□ 50.36(c)(1)(i)(A) □] 50.73(a)(2)(ii)(B)		□ 50.73(a	□ 50.73(a)(2)(viii)(B)						
□ 20.2203(a)(2)(v)			□ 50	□ 50.36(c)(1)(ii)(A) □ !				50.73(a)(2)(iii)			□ 50.73(a)(2)(ix)(A)						
Other	□ Other (Specify here, in Abstract, or in NRC 366A).																
						12. Lic	ensee (Contac	t for th	is LER							
Licensee	Contac	t										Phone N	umber	(Include	Area Code)		
Peggy	Kran	ner, Reg	gulatory	/ Affairs Ei	ngine	er						(570)	542-	3131			
		-	-	13. Complete	One Li	ne for e	each Co	mpone	ent Fail	ure Described	in this Repor	Manufa	turor	Banar	table to IRIS		
Cause		System	Compone	nt Manufact	o	керопа		15 (Lause	System	Component	Wallula	sture	Kepoi			
В		IA	FCV	P07	0		Ϋ́				<u> </u>	Month			Voor		
		14. S		to 15 Export E	od Subr	niceion	Data)		15. Ex	pected Subm	ission Date	WOTH		Jay	1641		
16 Abet	⊔⊔ ract (Li	mit to 156	n snaces	ie annrovim	ately 15	sinale-	snaced	tvnewri	itten line	es)							
At ann	ovima	telv 12.5	4 on Nov	ember 30_2	021. Si	isqueh	anna S	Steam	Electric	c Station. Uni	t 1. experienc	ed an au	utoma	tic read	tor scram		
during	Turbin	e Valve (Cycling s	urveillance te	esting.	During	the fas	st closu	ure por	tion of the su	rveillance tes	t on Mair	n Stop	Valve	4		
(MSV-́-́	1), a cl	osure of	Turbine (Control Valve	e 4 (ČV	-4) осс	curred,	resulti	ng in a	Division II R	eactor Protec	tion Syst	em (F	RPS) a	ctuation.		
While t	he Div	ision II ha	alf scram	signal was a	actuate	d, a Di v shut (vision I town	RPS	actuation	on occurred,	resulting in a	full react	or scr	ram. A	II control		
1003 11	senteu		ators pic			onace											
Event	Votifica	ation 556	16 report	ed this even	t in acc	ordanc	ce with	10 CF	R 50.7	2(b)(2)(iv)(B)	and 10 CFR	50.72(b)	(3)(iv))(A). Th	nis event		
IS Also	report R 50.7	able in ac 3(a)(2)(iv	cordanc)(B).	e with 10 CF	R 50,7	3(a)(2)	(IV)(A) i	as an i	eventi	nat resulted i	n automatic a	cuation	oras	system	111		
											nrevious						
I he CV-4 tast closed due to transient voltage from a ground fault on the CV-4 Fast Acting Solehold (FASV) field wiring. The previous single point vulnerability review for the system failed to identify and mitigate this failure mechanism. The Electro-hydraulic Control																	
fluid pressure perturbation from the simultaneous closure of MSV-4 and CV-4 resulted in the Division II RPS actuation. Further																	
review identified a recommended modification to dampen pressure in the system was never installed based on vendor																	
recommendation. Key corrective actions include, in part, replacement of the CV-4 FASV wire and installation of orffices in accordance with the General Electric Technical Information Letter 1212-2 guidance.																	
The second second second to the health and sefety of the within second second of this system.																	
There were no actual consequences to the health and safety of the public as a result of this event.																	

NRC FORM 366A U. S. NUCLE	AR REGULATORY COMMISSIO	LATORY COMMISSION APPROVED BY OMB: NO. 3150-0			104 EXPIRES: 08/31/2023				
(See NUREG-1022, R.3 for instruction and https://www.nrc.gov/reading-rm/doc-colle	VENT REPORT (LER) NUATION SHEET guidance for completing this form actions/nuregs/staff/sr1022/r3/)	Esumated burden per response to comply with this mandatory collection request: 80 hours. Iessons learned are incorporated into the licensing process and fed back to industry. Send corregarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 Atl Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e- Infocollects.Resource@nc.gov, and the OMB reviewer at: OMB Office of Information and R Affairs, (3150-0104), Attn: Desk all: <u>oira_submission@omb.eop.gov</u> . The NRC may not correquesting or requiring the collection displays a currently valid OMB control number.							
1. FACILITY NAME	2, DOCKET NUN	2. DOCKET NUMBER			3. LER NUMBER				
Susquehanna Steam Electric Stati	on, 05000-387	05000-387			- REV NO.				
Unit 1					- 01				
NARRATIVE									
CONDITIONS PRIOR TO) EVENT								
Unit 1 – Mode 1, approximately Unit 2 – Mode 1, approximately	80 percent Rated Therm 100 percent RTP	al Power (RTP)							
Unit 1 Turbine Valve Cvcling sur	veillance testing was in	progress at the time of the	event.						

EVENT DESCRIPTION

At approximately 12:54 on November 30, 2021, Susquehanna Steam Electric Station, Unit 1, experienced an automatic scram due to a Reactor Protection System (RPS) [EIIS System Code: JC] actuation during Turbine Valve Cycling surveillance testing. During the fast closure portion of the surveillance test on Main Stop Valve 4 (MSV-4) [EIIS System/Component Codes: TA/SHV], Control Valve 4 (CV-4) [TA/FCV] unexpectedly fast closed, thereby generating a Turbine Control Valve fast closure on Division II RPS. Fast closure of CV-4 and MSV-4 caused an Emergency Trip System (ETS) pressure perturbation in the Electro-hydraulic Control (EHC) [TG] system which actuated one of the two Division I RPS low pressure switches. The Division I signal combined with the Division II signal resulted in a full scram. All control rods inserted, and operators placed mode switch to shut down. Reactor water level was maintained at the normal operating band using the Reactor Feed Water system [SJ]. All safety systems responded properly during the event.

Event Notification 55616 reported this event in accordance with 10 CFR 50.72(b)(2)(iv)(B) and 10 CFR 50.72(b)(3)(iv)(A). This event is also reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in automatic actuation of a system listed in 10 CFR 50.73(a)(2)(iv)(B).

CAUSE OF EVENT

Transient voltage from a ground fault on the CV-4 Fast Acting Solenoid, SV10150D, field wiring energized the solenoid causing CV-4 to unexpectedly fast close. The EHC Single Point Vulnerability Assessment did not identify failure modes necessary to develop bridging and mitigation strategies on a passive component (i.e., wiring) located in a severe service environment and ultimately contributed to a reactor scram.

ETS header pressure drop from simultaneous fast closure of CV-4 and MSV-4 actuated one of the two Division I RPS control valve ETS low pressure switches (PSLC721N005A/C) [JJ/PS]. Operating Experience General Electric Technical Information Letter (TIL) 1212-2, which provided recommendations for controlling ETS pressure/flow via installation of orifices [OR], was previously evaluated with an inadequate conclusion resulting in the orifices not being installed as recommended.

ANALYSIS/SAFETY SIGNIFICANCE

The actual consequence of this event was a Unit 1 Reactor scram. The scram did not require or result in the actuation of Emergency Core Cooling System and no main steam relief valves [SB/RV] opened. Reactor Core Isolation Cooling system [BN] initiated as designed. All safety systems responded properly during the event. The condition described herein did not result in a safety system functional failure. Accordingly, this

NRC FORM 366A U. S. NUCLEAR REGU	LATORY COMMISSION	APPROVED BY OMB: NO. 3150-01	04	EXPIRES:	08/31/2023					
	REPORT (LER) IN SHEET	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Litrary, and Information Collections Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory								
(See NUREG-1022, R.3 for instruction and guidance for completing this form https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/) Affairs, (3150-0104), Attn: Desk ail: https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)										
1. FACILITY NAME	2. DOCKET NUME	BER 3. LER NUMBER								
Susquehanna Steam Electric Station, Unit 1	05000-387		2021	SEQUENTIAL NUMBER	REV NO. 01					
NARRATIVE				000						
event will not be counted as a safety system functional failure in the Reactor Oversight Process Performance Indicators. There were no actual consequences to the health and safety of the public as a result of this event.										
CORRECTIVE ACTIONS	CORRECTIVE ACTIONS									
 Key Corrective Actions Included: Replace damaged wiring for CV-4. Install orifices in accordance with General Electric TIL 1212-2 guidance. Perform Extent of Condition, as required, for Unit 1 and 2 main turbine steam valves. Develop preventative maintenance tasks for critical wiring on main turbine steam valves. Revise, as required, the EHC Single Point Vulnerability Mitigation Plan to address any vulnerabilities and associated mitigation strategies on passive components (e.g. wiring). 										
COMPONENT FAILURE INFORMATION										
Component Identification – SV10150D Wiring Component Name – Control Valve 4 Fasting Acting Solenoid Component Model Number – D3W4BVY13X1555 Manufacturer – Parker Hannifin										
PREVIOUS OCCURRENCES										
None.										
	4									