

10 CFR 50.73

RA22-027

July 18, 2022

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

LaSalle County Station, Units 1 and 2
Renewed Facility Operating License No. NPF-11 and NPF-18
NRC Docket Nos. 50-373 and 50-374

Subject: Licensee Event Report 2022-003-00, Main Control Room and Auxiliary
Electric Room HVAC Declared Inoperable Due to Multiple Component
Failures

In accordance with 10 CFR 50.73(a)(2)(v)(D), Exelon Generation Company, LLC
(EGC) is submitting Licensee Event Report (LER) Number 2022-003-00 for LaSalle
County Station, Units 1 and 2.

There are no regulatory commitments in this letter. Should you have any questions
concerning this report, please contact Mr. Dan Mearhoff, Regulatory Assurance
Manager, at (815) 415-2800.

Respectfully,



John Van Fleet Jr
Plant Manager
LaSalle County Station

Enclosure: Licensee Event Report

cc: Regional Administrator – NRC Region III
NRC Senior Resident Inspector – LaSalle County Station



LICENSEE EVENT REPORT (LER)

(See Page 3 for required number of digits/characters for each block)
(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk at: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name

LaSalle County Station, Unit 1

2. Docket Number

05000 - 373

3. Page

1 OF 3

4. Title

Main Control Room and Auxiliary Electric Room HVAC Declared Inoperable Due to Multiple Component Failures.

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	Docket Number
05	20	2022	2022	- 003 -	00	07	18	2022	LaSalle County Station, Unit 2	05000-374
									Facility Name NA	Docket Number NA

9. Operating Mode

1

10. Power Level

100 percent

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

<input type="checkbox"/> 10 CFR Part 20	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 10 CFR Part 73
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.69(g)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(4)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 10 CFR Part 21	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 73.77(a)(1)(i)
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 21.2(c)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 73.77(a)(2)(i)
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 10 CFR Part 50	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 73.77(a)(2)(ii)
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	

OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

Licensee Contact

CJ Smith, Operations Director

Phone Number (Include area code)

(815) 415-2200

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS

14. Supplemental Report Expected

No Yes (If yes, complete 15. Expected Submission Date)

15. Expected Submission Date

Month: 10, Day: 01, Year: 2022

6. Abstract (Limit to 1560 spaces, i.e., approximately 15 single-spaced typewritten lines)

On May 20, 2022, both Units 1 and 2 were in Mode 1 and at 100% power. The B train of the Main Control Room Ventilation (VC) and Auxiliary Electric Room Ventilation (VE) was inoperable due to a planned maintenance window. The Main Control Room ventilation envelope consists of both the Main Control Room and the Auxiliary Electric Equipment Room. Both trains of VC and VE were required to be operable at the time of these events.

On 5/20/22 at 0905 and again on 5/23/22 at 1256, various equipment on the A VC/VE train tripped following train swaps to support ongoing maintenance activities. This resulted in the A VC/VE train being declared inoperable. With both the A and B trains being simultaneously inoperable, the system was in a condition that could have prevented fulfillment of a safety function.

A causal evaluation is in progress to determine cause of the equipment failures on the A VC/VE train.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
LaSalle County Station, Unit 1	05000- 373	2022	- 003	- 00

NARRATIVE

Plant and System Identification

LaSalle Country Station Unit 1 and 2 is a General Electric Boiling Water Reactor with 3546 Megawatts Thermal Rated Core Power. The affected system was the Main Control Room Area Ventilation system (VC) and the Auxiliary Equipment Room Ventilation System (VE).

Condition Prior to Event

Unit(s): 1/2 Date: May 20, 2022 Time: 0905 CDT
 Reactor Mode(s): 1/1 Mode(s) Name: Power Operation Power Level: 100%/100%

Description

On May 20, 2022 the station was executing a B VC/VE work window and in the following TS actions: 3.7.4 A.1, restore B train to operable status (expires 5/23/22 at 0500) and 3.7.5 A.1, restore B train to operable (expires 6/15/2022 at 0300). The station began procedures to swap to the A train to allow repairs identified during post maintenance testing on the B train. After swapping to A VC/VE, the A VE return fan tripped and immediately tripped after a second attempt to start.

At 0905, the A train was declared inoperable for both TS 3.7.4 (CRAF) and 3.7.5 (MCR ventilation). With both trains of VC/VE inoperable, the Station entered TS 3.7.4 RA E.1 be in mode 3 within 12 hours, TS 3.7.5 RA B.1 to verify control room area temperature less than 90 degrees once per four hours, and RA B.2 to restore one control room area ventilation air conditioning subsystem to operable status within 72 hours.

The Electrical Maintenance department performed basic troubleshooting. The fan was restarted and following sufficient run time of the A VE return fan, the A VC/VE train was declared operable at 1200. TS actions 3.7.5 E.1 and 3.7.4 B.1 and B.2 were exited.

On 5/23/2022 the station began activities to swap to A VC/VE to allow for system restoration on B VC/VE. After swapping to A VC/VE, the A VE return fan tripped at 1256. Operations reset the breaker and restarted the fan. The A VC/VE train was declared inoperable for CRAF (3.7.4) and MCR ventilation (3.7.5). The station entered the following time clocks: 3.7.4 A.1, restore A train to operable status within 7 days, 3.7.5 RA B.1 to verify control room area temperature less than 90 degrees once per four hours, and RA B.2 to restore one control room area ventilation air conditioning subsystem to operable status within 72 hours. (Note: The B train was declared operable for CRAF on 5/20/22 at 1841 following repairs, but the B train remained in the 3.7.5 MCR ventilation LCO for continued maintenance activities from the previous week that resulted in the condition discussed above on 5/23.)

The B train was fully restored to operable status at 1755 on 5/23/22. TS action 3.7.5 B.1/B.2 were exited. The station declared the A train operable on 5/24/22 at 2230 after completion of an Operability evaluation and subsequent run time.

Cause

A causal evaluation is currently in progress to determine the causes of the various trips that resulted in A train being inoperable.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
LaSalle County Station, Unit 1	05000- 373	2022	- 003	- 00

NARRATIVE

Reportability and Safety Analysis

The A and B VC/VE trains of the simultaneous inoperability is reportable under 10 CFR 50.73(a)(2)(v)(D) as an event or condition that could have prevented the fulfillment of the safety function of the structures or systems that are needed to mitigate the consequences of an accident. Two ENS reports were made to the NRC at 1639 CDT on May 20, 2022 (EN# 55905) and at 1815 CDT on May 23, 2022 (EN# 55908). Both reports were pursuant to 10 CFR 50.72(b)(3)(v)(D).

The safety significance of this event was minimal. For approximately 3 hours on 5/20/22, both VC/VE trains were inoperable for CRAF and HVAC (TS 3.7.4 and TS 3.7.5). For approximately 5 hours on 5/23/22, both trains were inoperable for HVAC only (TS 3.7.5). Main Control temperature did not exceed 90 degrees and online risk remained Green throughout the event.

Corrective Actions

Corrective actions taken in response to the conditions were:

- Basic troubleshooting was performed.
- Operability evaluation was performed prior to declaring VC/VE operable after failure of the VC return fan.
- Initiated a causal evaluation (currently in progress)

Previous Occurrences

LER 373-2014-004

On August 28, 2014, both Units 1 and 2 were in Mode 1 at 100% power. The 'B' train of Auxiliary Electric Equipment Room ventilation (VE) was inoperable due to a planned repair of an oil leak. At 1227 hours CDT, the A VE compressor was not found to be cycling on and off resulting in the 'A' train of VC/VE being declared inoperable. With both trains of VC/VE inoperable, this resulted in an event or condition that could have prevented the fulfillment of a safety function. The cause of the event was a shorted wire on liquid line solenoid valve 0RG053A that caused the solenoid valve to close, resulting in the compressor shutting down on low suction pressure. The corrective action was to repair the wiring problem and return the compressor to service.

LER 373-2013-008

On November 22, 2013, both Units 1 and 2 were in Mode 1 at 100% power. The 'A' train of Main Control Room ventilation (VC) was inoperable due to an emergent repair of a Freon leak. At 1920 hours CST, the 'B' AEER Cooler Condenser Fan tripped. An acrid smell was detected coming from the fan motor breaker compartment. The 'B' train of VC and VE was declared inoperable. With both trains of VC/VE inoperable, this resulted in an event or condition that could have prevented the fulfillment of a safety function. The cause of the event was a winding failure of the 'B' AEER Cooler Condenser fan motor. Corrective actions included replacing the failed fan motor and performing a failure analysis to determine the cause of the winding failure.

Component Failure Data

No component failures identified at this time. Causal Evaluation is in progress.