

Kevin Cimorelli
Site Vice President

Susquehanna Nuclear, LLC
769 Salem Boulevard
Berwick, PA 18603
Tel. 570.542.3795 Fax 570.542.1504
Kevin.Cimorelli@TalenEnergy.com



December 05, 2022

Attn: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001

10 CFR 50.73

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-387/2022-002-01
UNIT 1 LICENSE NO. NPF-14
PLA-8037

Docket No. 50-387

Attached is Licensee Event Report (LER) 50-387/2022-002-01. The LER supplement reports an event involving an automatic scram due to a Reactor Protection System actuation on high reactor pressure as a result of a Main Steam Isolation Valve closure. The condition is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in automatic actuation of a system listed in 10 CFR 50.73(a)(2)(iv)(B).

There were no actual consequences to the health and safety of the public as a result of this event.

This letter contains no new or revised regulatory commitments.

 D LAMARCA FOR K CIMORELLI
K. Cimorelli

Attachment: LER 50-387/2022-002-01

Copy: NRC Region I
Mr. C. Highley, NRC Senior Resident Inspector
Ms. A. Klett, NRC Project Manager
Mr. M. Shields, PA DEP/BRP



LICENSEE EVENT REPORT (LER)

(See Page 3 for required number of digits/characters for each block)
(See NUREG-1022, R.3 for instruction and guidance for completing this form <https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk all: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name Susquehanna Steam Electric Station, Unit 1	2. Docket Number 05000387	3. Page 1 of 3
---	-------------------------------------	--------------------------

4. Title
Automatic Reactor Scram Due to Reactor Protection System Actuation on High Reactor Vessel Pressure Signal Following Inadvertent Closure of Inboard Main Steam Isolation Valve

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved	
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	Docket Number
05	23	2022	2022	- 002 -	01	12	05	2022	Facility Name	Docket Number
										05000
										05000

9. Operating Mode 1	10. Power Level 100
-------------------------------	-------------------------------

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

<input checked="" type="checkbox"/> 10 CFR Part 20	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.36(c)(2)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	10 CFR Part 73
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.69(g)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(4)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(i)	10 CFR Part 21	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 73.77(a)(1)(i)
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 21.2(c)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 73.77(a)(2)(i)
<input type="checkbox"/> 20.2203(a)(2)(iii)	10 CFR Part 50	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 73.77(a)(2)(ii)
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	

Other (Specify here, in Abstract, or in NRC 366A).

12. Licensee Contact for this LER

Licensee Contact Peggy Kramer, Regulatory Affairs Engineer	Phone Number (Include Area Code) (570) 542-3131
--	---

13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
X	LK	TBG	Swagelok	Y					

14. Supplemental Report Expected				15. Expected Submission Date		
<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes (If yes, complete 15. Expected Submission Date)			Month	Day	Year

16. Abstract (Limit to 1560 spaces, i.e., approximately 15 single-spaced typewritten lines)

At approximately 17:16 on May 23, 2022, Susquehanna Steam Electric Station, Unit 1, experienced an automatic reactor scram. Reactor Protection System (RPS) was actuated on a high reactor vessel pressure signal due to inadvertent closure of an inboard Main Steam Isolation Valve (MSIV) (HV141F022D). All control rods inserted, and operators placed the mode switch to shut down. All safety systems responded as designed during this event.

Event Notification 55909 reported this event in accordance with 10 CFR 50.72(b)(2)(iv)(A), 10 CFR 50.72(b)(2)(iv)(B), and 10 CFR 50.72(b)(3)(iv)(A). This event is also reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in automatic actuation of a system listed in 10 CFR 50.73(a)(2)(iv)(B).

The cause of the scram was due to a loss of pneumatic pressure resulting in closure of an inboard MSIV (HV141F022D) which resulted in a high reactor vessel pressure signal and valid RPS actuation. The loss of pneumatic pressure occurred due to high cycle fatigue induced failure, most likely from vibration, of the 3/8" Containment Instrument Gas tubing. Affected tubing was replaced and the weld on 3/8" tubing to HV141F022D was repaired.

There were no actual consequences to the health and safety of the public as a result of this event.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk ail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Susquehanna Steam Electric Station, Unit 1	05000-387	YEAR 2022	SEQUENTIAL NUMBER - 002 -	REV NO. 01

NARRATIVE

CONDITIONS PRIOR TO EVENT

Unit 1 – Mode 1, approximately 100 percent Rated Thermal Power (RTP)
Unit 2 – Mode 1, approximately 100 percent RTP

EVENT DESCRIPTION

At approximately 17:16 on May 23, 2022, Susquehanna Steam Electric Station, Unit 1, experienced an automatic reactor scram. Reactor Protection System (RPS) [EIS System Code: JC] was actuated on a high reactor vessel pressure signal due to inadvertent closure of an inboard Main Steam Isolation Valve (MSIV) (HV141F022D) [EIS System/Component Codes: SB/ISV] following loss of pneumatic pressure. All control rods inserted, and operators placed the mode switch to shut down.

Containment isolations [JM] and both Reactor Recirculation Pump [AD/P] trips occurred as reactor water level dropped below the Anticipated Transient Without Scram – Reactor Pump Trip logic setpoint. High Pressure Coolant Injection [BJ] and Reactor Core Isolation Cooling [BN] initiated as designed when the reactor water level lowered. Subsequently, operators maintained reactor water level within normal band using Reactor Feedwater [SJ]. All other safety systems responded as designed.

Event Notification 55909 reported this event in accordance with 10 CFR 50.72(b)(2)(iv)(A), 10 CFR 50.72(b)(2)(iv)(B) and 10 CFR 50.72(b)(3)(iv)(A). This event is also reportable in accordance with 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in automatic actuation of a system listed in 10 CFR 50.73(a)(2)(iv)(B).

CAUSE OF EVENT

The cause of the scram was due to a loss of pneumatic pressure resulting in inadvertent closure of an inboard MSIV (HV141F022D) which resulted in a high reactor vessel pressure signal and valid RPS actuation. The loss of pneumatic pressure occurred due to high cycle fatigue induced failure, most likely from vibration, of the 3/8” Containment Instrument Gas [LK] tubing [TBG].

ANALYSIS/SAFETY SIGNIFICANCE

The actual consequence of this event was an automatic reactor scram. All safety systems responded as designed during this event. Residual Heat Removal [BO] and Residual Heat Removal Service Water [BI] remained available to remove residual heat. No fuel or clad damage occurred during the scram, as evidenced by Main Steam Line and Off-Gas radiation levels decreasing post-scram. All applicable systems were available to control the release of any radioactive material. All safety systems were available to mitigate the consequences of an accident.

The condition described herein did not result in a safety system functional failure. Accordingly, this event will not be counted as a safety system functional failure in the Reactor Oversight Process Performance Indicator. There were no actual consequences to the health and safety of the public as a result of this event.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk ail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Susquehanna Steam Electric Station, Unit 1	05000-387	YEAR 2022	SEQUENTIAL NUMBER - 002 -	REV NO. 01

NARRATIVE

CORRECTIVE ACTIONS

The sheared tubing was replaced, and pneumatic control restored to the inboard MSIV (HV141F022D). Additionally, an extent of condition visual exam and liquid penetrant examination were completed on the other three (3) Unit 1 inboard MSIVs. The outboard MSIVs are a different configuration, as such this failure mode is not applicable. Additional actions will be taken to perform an extent of condition review on the Unit 2 applicable MSIVs as well.

Additionally, Susquehanna will develop and implement, as needed, a Passive Single Point Vulnerability Mitigation Strategy for inboard MSIV Containment Instrument Gas tubing.

COMPONENT FAILURE INFORMATION

Component Name – Containment Instrument Gas supply line from header JCD-115 to line HCC-137
Component Identification – JCD-118
Part Number – SS-600-6
Manufacturer - Swagelok

PREVIOUS OCCURRENCES

None.