



John A. Krakuszeski  
Vice President  
Brunswick Nuclear Plant  
8470 River Rd SE  
Southport, NC 28461  
o: 910.832.3698

10 CFR 50.73

June 15, 2023

Serial: RA-23-0116

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

Subject: Brunswick Steam Electric Plant, Unit No. 1  
Renewed Facility Operating License No. DPR-71  
Docket No. 50-325  
Licensee Event Report 1-2023-001

In accordance with the Code of Federal Regulations, Title 10, Part 50.73, Duke Energy Progress, LLC, is submitting the enclosed Licensee Event Report (LER). This report fulfills the requirement for a written report within sixty (60) days of a reportable occurrence.

This document contains no regulatory commitments.

Please refer any questions regarding this submittal to Mr. Mark DeWire, Manager – Nuclear Support Services, at (910) 832-6641.

Sincerely,

A handwritten signature in black ink that reads "John A. Krakuszeski". The signature is fluid and cursive.

John A. Krakuszeski

Enclosure: Licensee Event Report

cc (with enclosure):

Ms. Laura Dudes, NRC Regional Administrator, Region II  
Mr. Luke Haeg, NRC Project Manager  
Mr. Gale Smith, NRC Senior Resident Inspector



# LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)  
(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to [Infocollections.Resource@nrc.gov](mailto:Infocollections.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: [oir\\_submission@omb.eop.gov](mailto:oir_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

<b>1. Facility Name</b> Brunswick Steam Electric Plant (BSEP), Unit 1	<input checked="" type="checkbox"/> <b>050</b> <input type="checkbox"/> <b>052</b>	<b>2. Docket Number</b> 00325	<b>3. Page</b> 1 OF 3
--	---	----------------------------------	--------------------------

**4. Title**  
Loss of Redundant Power Supply Operation Causes Turbine Trip and Subsequent Reactor Scram

5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved		
Month	Day	Year	Year	Sequential Number	Revision No.	Month	Day	Year	Facility Name	<input type="checkbox"/> 050	Docket Number
04	20	2023	2023	- 001 -	00	06	15	2023	Facility Name	<input type="checkbox"/> 052	Docket Number

**9. Operating Mode** 1      **10. Power Level** 100

**11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)**

<b>10 CFR Part 20</b>	<input type="checkbox"/> 20.2203(a)(2)(vi)	<b>10 CFR Part 50</b>	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 73.1200(a)
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	<input type="checkbox"/> 73.1200(b)
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 73.1200(c)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.36(c)(2)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 73.1200(d)
<input type="checkbox"/> 20.2203(a)(2)(i)	<b>10 CFR Part 21</b>	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<b>10 CFR Part 73</b>	<input type="checkbox"/> 73.1200(e)
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 21.2(c)	<input type="checkbox"/> 50.69(g)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.77(a)(1)	<input type="checkbox"/> 73.1200(f)
<input type="checkbox"/> 20.2203(a)(2)(iii)		<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> 73.77(a)(2)(i)	<input type="checkbox"/> 73.1200(g)
<input type="checkbox"/> 20.2203(a)(2)(iv)		<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 73.77(a)(2)(ii)	<input type="checkbox"/> 73.1200(h)
<input type="checkbox"/> 20.2203(a)(2)(v)		<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)		

**OTHER** (Specify here, in abstract, or NRC 366A).

**12. Licensee Contact for this LER**

<b>Licensee Contact</b> Mark DeWire, Manager – Nuclear Support Services	<b>Phone Number (Include area code)</b> (910) 832-6641
--	---

**13. Complete One Line for each Component Failure Described in this Report**

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
B	JJ	RJX	K078	Y					

<b>14. Supplemental Report Expected</b>	<b>15. Expected Submission Date</b>
<input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (If yes, complete 15. Expected Submission Date)	Month:      Day:      Year:

**16. Abstract** (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

At 01:48 Eastern Daylight Time (EDT) on April 20, 2023, with Unit 1 in Mode 1 at approximately 100% power, an automatic reactor scram occurred due to a turbine trip. All control rods inserted as expected. Turbine bypass valves did not open on the scram; Safety Relief Valves (SRVs) opened automatically to control reactor pressure. Reactor Pressure reached approximately 1100 psig on the scram, exceeding the Reactor Protection System (RPS) setpoint. Reactor water level reached low level 1 following the scram resulting in automatic actuation of Primary Containment Isolation System (PCIS) Group 2, 6, and 8 isolation valves, by design.

Operations responded and stabilized the plant. Operations transitioned pressure control from SRVs to main steam line drains to the condenser. Following the scram, reactor water level was maintained via the condensate and feedwater systems.

The turbine trip and subsequent inoperative turbine bypass valves resulted from a complete loss of 24 Vdc power to the Turbine Protection system. The power supplies were replaced prior to restart.

There was no impact on the health and safety of the public or plant personnel. This event is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) due to valid actuation of the RPS and PCIS.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: [oir\\_submission@omb.eop.gov](mailto:oir_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME  Brunswick Steam Electric Plant (BSEP), Unit 1	<input checked="" type="checkbox"/> 050	2. DOCKET NUMBER  00325	3. LER NUMBER		
	<input type="checkbox"/> 052		YEAR 2023	SEQUENTIAL NUMBER - 001	REV NO. - 00

**NARRATIVE**

Energy Industry Identification System (EIIIS) codes are identified in the text as [XX].

**Background**

*Initial Conditions*

At the time of the event, Unit 1 was in Mode 1 (i.e., Power Operation), at approximately 100 percent rated thermal power.

*Reportability Criteria*

This event is being reported in accordance with 10 CFR 50.73(a)(2)(iv)(A) because it involved actuation of systems listed in 10 CFR 50.73(a)(2)(iv)(B). Specifically, the Reactor Protection System [JC] and Primary Containment Isolation System [JM] actuated during this event.

The NRC was notified of this event per 10 CFR 50.72(b)(2)(iv)(B) and 10 CFR 50.72(b)(3)(iv)(A) via Event Notification 56478 at 05:24 Eastern Daylight Time (EDT) on April 20, 2023.

**Event Description**

At 01:48 Eastern Daylight Time (EDT) on April 20, 2023, with Unit 1 in Mode 1 at approximately 100% power, an automatic reactor scram occurred due to a turbine trip. All control rods inserted as expected.

The turbine bypass valves [JI] did not open on the scram; main steam [SB] Safety Relief Valves (SRVs) 1C, 1F, 1G, 1K, and 1L cycled open automatically to control reactor pressure. Reactor pressure reached approximately 1100 psig on the scram; exceeding the 1060 psig Reactor Protection System (RPS) setpoint.

Reactor water level reached the low level 1 (LL1) setpoint following the scram. Per design, the LL1 signal resulted in Primary Containment Isolation System Group 2 (i.e., floor and equipment drain isolation valves), Group 6 (i.e., monitoring and sampling isolation valves) and Group 8 (i.e., shutdown cooling isolation valves) isolations.

Operations responded and stabilized the plant. Operations manually cycled open SRV 1B then transitioned pressure control from SRVs to the main steam line drains [SB] to the condenser [SG]. Following the scram, reactor water level was maintained via the condensate [SD] and feedwater [SJ] systems.

**Event Cause**

The direct cause of the turbine trip and subsequent inoperative turbine bypass valves was a complete loss of 24 Vdc power to the Turbine Protection system [JJ]. When 24 Vdc power was lost, Turbine Protection system data inputs for required pressure and flow transmitters were lost. With the loss of monitoring capability, the Turbine Protection system responded as designed by initiating a turbine trip to protect the turbine and inhibiting the opening of the turbine bypass valves to protect the condenser.

24 Vdc power is supplied to the Turbine Protection system via redundant power supplies [RJX]. Due to inadequacies in the vendor design, a unique combination of internal component failures on one power supply impacted the operation of the redundant power supply. As a result, both power supplies failed/shutdown within a short timeframe of one another resulting in a total loss of 24 Vdc power.



**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: [oir\\_submission@omb.eop.gov](mailto:oir_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME  Brunswick Steam Electric Plant (BSEP), Unit 1	<input checked="" type="checkbox"/> 050	2. DOCKET NUMBER  00325	3. LER NUMBER		
	<input type="checkbox"/> 052		YEAR	SEQUENTIAL NUMBER	REV NO.
			2023	- 001	- 00

**NARRATIVE**

Prior to this event the power supplies had operated successfully with no indication of deficiencies for approximately five years.

**Safety Assessment**

There was no adverse impact on the health and safety of the public or plant personnel. The safety significance of this event is minimal. The condenser remained available for pressure control. The condensate and feedwater systems remained available for level control.

**Corrective Actions**

Prior to restart from this event, the 24 Vdc Turbine Protection system power supplies were replaced.

The site is planning to implement changes to the current 24Vdc power supply functionality that will prevent a power supply internal failure from impacting the redundant power supply.

Any changes to corrective actions or completion schedules will be made in accordance with the site's corrective action program.

**Previous Similar Events**

No previous similar events have occurred within the past three years in which inadequate vendor design resulted in a turbine trip and reactor scram.

**Commitments**

No regulatory commitments are contained in this report.