



Post Office Box 2000, Decatur, Alabama 35609-2000

July 19, 2023

10 CFR 50.73
10 CFR 50.4(a)

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555-0001

Browns Ferry Nuclear Plant, Unit 1
Renewed Facility Operating License No. DPR-33
NRC Docket No. 50-259

Subject: **Licensee Event Report 50-259/2023-002-00 – Full Reactor Scram due to an Oscillation Power Range Monitor (OPRM) Confirmation Density Algorithm (CDA) Trip**

The enclosed Licensee Event Report provides the details of the full reactor scram from 80% power due to an Oscillation Power Range Monitor (OPRM) Confirmation Density Algorithm (CDA) trip . The Tennessee Valley Authority is submitting this report in accordance with Title 10 of the Code of Federal Regulations (10 CFR) 50.73(a)(2)(iv)(A), as any event or condition that resulted in a manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B).

There are no new regulatory commitments contained in this letter. Should you have any questions concerning this submittal, please contact Michael W. Oliver, Acting Site Licensing Manager, at (256) 729-7874.

Respectfully,

A handwritten signature in black ink, appearing to read 'Manu Sivaraman', is written over a white background.

Manu Sivaraman
BFN Site Vice President

Enclosure: Licensee Event Report 50-259/2023-002-00 – Full Reactor Scram due to an Oscillation Power Range Monitor (OPRM) Confirmation Density Algorithm (CDA) Trip

U.S. Nuclear Regulatory Commission

Page 2

July 19, 2023

cc (w/ Enclosure):

NRC Regional Administrator - Region II

NRC Senior Resident Inspector - Browns Ferry Nuclear Plant

NRC Project Manager - Browns Ferry Nuclear Plant



LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)
(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk ail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

| | | |
|---|-------------------------------------|--------------------------|
| 1. Facility Name Browns Ferry Nuclear Plant, Unit 1 | 2. Docket Number 05000259 | 3. Page 1 OF 7 |
|---|-------------------------------------|--------------------------|

4. Title
Full Reactor Scram due to an Oscillation Power Range Monitor Confirmation Density Algorithm Trip

| 5. Event Date | | | 6. LER Number | | | 7. Report Date | | | 8. Other Facilities Involved | |
|---------------|-----|------|---------------|-------------------|--------------|----------------|-----|------|------------------------------|---------------|
| Month | Day | Year | Year | Sequential Number | Revision No. | Month | Day | Year | Facility Name | Docket Number |
| 05 | 20 | 2023 | 2023 | 002 | 00 | 07 | 19 | 2023 | N/A | 05000 N/A |
| | | | | | | | | | Facility Name | Docket Number |
| | | | | | | | | | N/A | 05000 N/A |

| | |
|-------------------------------|-------------------------------|
| 9. Operating Mode 1 | 10. Power Level 080 |
|-------------------------------|-------------------------------|

11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

| | | | | |
|---|--|---|--|---|
| <input type="checkbox"/> 10 CFR Part 20 | <input type="checkbox"/> 20.2203(a)(2)(vi) | <input type="checkbox"/> 10 CFR Part 50 | <input type="checkbox"/> 50.73(a)(2)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(viii)(A) |
| <input type="checkbox"/> 20.2201(b) | <input type="checkbox"/> 20.2203(a)(3)(i) | <input type="checkbox"/> 50.36(c)(1)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(ii)(B) | <input type="checkbox"/> 50.73(a)(2)(viii)(B) |
| <input type="checkbox"/> 20.2201(d) | <input type="checkbox"/> 20.2203(a)(3)(ii) | <input type="checkbox"/> 50.36(c)(1)(ii)(A) | <input type="checkbox"/> 50.73(a)(2)(iii) | <input type="checkbox"/> 50.73(a)(2)(ix)(A) |
| <input type="checkbox"/> 20.2203(a)(1) | <input type="checkbox"/> 20.2203(a)(4) | <input type="checkbox"/> 50.36(c)(2) | <input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A) | <input type="checkbox"/> 50.73(a)(2)(x) |
| <input type="checkbox"/> 20.2203(a)(2)(i) | <input type="checkbox"/> 10 CFR Part 21 | <input type="checkbox"/> 50.46(a)(3)(ii) | <input type="checkbox"/> 50.73(a)(2)(v)(A) | <input type="checkbox"/> 10 CFR Part 73 |
| <input type="checkbox"/> 20.2203(a)(2)(ii) | <input type="checkbox"/> 21.2(c) | <input type="checkbox"/> 50.69(g) | <input type="checkbox"/> 50.73(a)(2)(v)(B) | <input type="checkbox"/> 73.77(a)(1) |
| <input type="checkbox"/> 20.2203(a)(2)(iii) | | <input type="checkbox"/> 50.73(a)(2)(i)(A) | <input type="checkbox"/> 50.73(a)(2)(v)(C) | <input type="checkbox"/> 73.77(a)(2)(i) |
| <input type="checkbox"/> 20.2203(a)(2)(iv) | | <input type="checkbox"/> 50.73(a)(2)(i)(B) | <input type="checkbox"/> 50.73(a)(2)(v)(D) | <input type="checkbox"/> 73.77(a)(2)(ii) |
| <input type="checkbox"/> 20.2203(a)(2)(v) | | <input type="checkbox"/> 50.73(a)(2)(i)(C) | <input type="checkbox"/> 50.73(a)(2)(vii) | |

OTHER (Specify here, in abstract, or NRC 366A).

12. Licensee Contact for this LER

| | |
|--|--|
| Licensee Contact Justin K. Garner, Licensing Engineer | Phone Number (Include area code) 256-729-7955 |
|--|--|

13. Complete One Line for each Component Failure Described in this Report

| Cause | System | Component | Manufacturer | Reportable to IRIS | Cause | System | Component | Manufacturer | Reportable to IRIS |
|-------|--------|-----------|--------------|--------------------|-------|--------|-----------|--------------|--------------------|
| N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A | N/A |

| | | | | | |
|--|---|--|-------------------------------------|-----|------|
| 14. Supplemental Report Expected) | | | 15. Expected Submission Date | | |
| <input checked="" type="checkbox"/> No | <input type="checkbox"/> Yes (If yes, complete 15. Expected Submission Date | | Month | Day | Year |
| | | | N/A | N/A | N/A |

16. Abstract (Limit to 1560 spaces, i.e., approximately 15 single-spaced typewritten lines)

On May 20, 2023, at 0315 Central Daylight Time (CDT), while performing quarterly turbine control valve (TCV) testing at 80 percent reactor thermal power (RTP) and 70 percent core flow, Unit 1 automatically scrammed due to an Oscillation Power Range Monitor (OPRM) Confirmation Density Algorithm (CDA) trip. The plant responded to the reactor scram as expected and there were no human performance challenges during the turbine control valve testing or subsequent plant shutdown.

The root cause of the event was determined to be that the sensitivity of the CDA trip during off-normal plant conditions was not embedded into processes or procedures, thus preventing development of appropriate risk elimination or mitigation actions.

The Corrective Actions to Prevent Recurrence are to revise Surveillance Requirements for the Turbine Control Valve Fast Closure on Turbine Trip and RPT Initiate Logic to specify the appropriate power level and associated valve position for performing the test to ensure no control valve oscillations and that conditions remain outside of the OPRM trip enabled region when possible; revise Technical Instructions for the Reactivity Control Plan Development and Implementation to increase awareness of entry into the OPRM trip enabled region due to the risk of spurious scrams from the CDA instability detection method; revise Design Criteria for the Turbine Electro Hydraulic Control System (EHC) systems to add details with regards to the interrelationship between EHC and OPRM; and revise Design Criteria for Neutron Monitoring Systems to add details on OPRM Algorithms.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

| | | | | | |
|--|---|-------------------------------|---------------|-------------------|---------|
| 1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 1 | <input checked="" type="checkbox"/> 050 | 2. DOCKET NUMBER 00259 | 3. LER NUMBER | | |
| | <input type="checkbox"/> 052 | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| | | | 2023 | - 002 | - 00 |

NARRATIVE

I. Plant Operating Conditions before the Event

At the time of discovery, Browns Ferry Nuclear Plant (BFN) Unit 1 was in Mode 1 at approximately 80 percent power.

II. Description of Event

A. Event Summary

On May 20, 2023, at 0315 Central Daylight Time (CDT), while performing quarterly turbine control valve (TCV) testing at 80 percent Reactor Thermal Power (RTP) and 70 percent core flow, Unit 1 automatically scrammed due to an Oscillating Power Range Monitor (OPRM) Confirmation Density Algorithm (CDA) trip. The plant responded to the reactor scram as expected and there were no human performance challenges during the TCV testing or subsequent plant shutdown.

The Tennessee Valley Authority (TVA) is submitting this report in accordance with Title 10 of the Code of Federal Regulations (10 CFR) 50.73(a)(2)(iv)(A), as any event or condition that resulted in a manual or automatic actuation of any of the systems listed in paragraph (a)(2)(iv)(B), including: the reactor protection system (RPS) [EIIS: JC] which includes a reactor scram or a reactor trip, and general containment isolation signals affecting containment isolation valves in more than one system.

B. Status of structures, components, or systems that were inoperable at the start of the event and that contributed to the event

There were no structures, systems, or components (SSCs) whose inoperability contributed to this event.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

| | | | | | |
|--|---|-------------------------------|---------------|----------------------------|-----------------|
| 1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 1 | <input checked="" type="checkbox"/> 050 | 2. DOCKET NUMBER 00259 | 3. LER NUMBER | | |
| | <input type="checkbox"/> 052 | | YEAR 2023 | SEQUENTIAL NUMBER - 002 | REV NO. - 00 |

NARRATIVE

C. Dates and approximate times of occurrences

| Dates and Approximate Times | Occurrence |
|-----------------------------|---|
| October 2018 | Implementation of Confirmation Density Algorithm (CDA) Option 3. CDA initiated and inhibited during Unit 1 Refueling Outage 12 (U1R12) [Engineering Change Package (ECP) 72409] |
| Approximately June 2020 | Initiated ECP for TCVs and Turbine Stop Valves (TSV) linear variable differential transformers (LVDTs). ECP issued. (ECP BFN-20-1688) |
| October 2020 | CDA was enabled during 1R13 (ECP BFN-20-1688, Stages 28-31) |
| October 2022 | Implemented ECP for U1 during U1R14 to install redundant LVDTs to the U1 stop valves and control valves (ECP BFN-20-1688, Stage 1) |
| February – March 2023 | ECP BFN-20-1688, Stage 2, revised to address concerns with installing redundant LVDT on the U2 stop valves and control valves. (ECP BFN-20-1688, Stage 2) |
| March 2023 | ECP BFN-20-1688, Stage 2, implemented for installing redundant LVDTs during U2R22 (ECP BFN-20-1688, Stage 2) |
| May 20, 2023, at 0315 | Unit 1 Reactor Scram due to an OPRM CDA trip |

D. Manufacturer and model number of each component that failed during the event

No components failed during this event.

E. Other systems or secondary functions affected

No other systems or secondary functions were affected.

F. Method of discovery of each component or system failure or procedural error

On May 20, 2023, at 0315, while performing quarterly turbine control valve surveillance testing, the Unit 1 RPS received an OPRM CDA trip resulting in an automatic scram.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

| | | | | | |
|--|---|-------------------------------|---------------|-------------------|---------|
| 1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 1 | <input checked="" type="checkbox"/> 050 | 2. DOCKET NUMBER 00259 | 3. LER NUMBER | | |
| | <input type="checkbox"/> 052 | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| | | | 2023 | - 002 | - 00 |

NARRATIVE

G. The failure mode, mechanism, and effect of each failed component

No components failed during this event.

H. Operator actions

There were no operator actions associated with this event.

I. Automatically and manually initiated safety system responses

The Unit 1 RPS received an OPRM CDA trip resulting in an automatic scram. The plant responded to the reactor scram as expected, and there were no human performance challenges during the TCV testing or subsequent plant shutdown.

III. Cause of the event

The BFN Unit 1 OPRM SCRAM occurred as a result of the sensitivity of the CDA trip during off-normal plant conditions not being embedded into TVA processes or procedures, thus preventing development of appropriate risk elimination or mitigation actions.

IV. Analysis of the event

During 1R14 (October 2022), redundant 'B' LVDTs were installed on all TCVs via ECP BFN-20-1688-01. The redundant LVDTs were a different manufacturer and style than the original (Alliance versus GE Kavlico) but performed the same function. Internal manufacturer wiring errors in the LVDTs caused discrepancies in indicated valve position. During the quarterly TCV test, these deviations caused the three TCVs that remained open to operate in an unstable region of the valve curve and resulted in control system instabilities that manifested as TCV oscillations. These oscillations resulted in reactor pressure swings, which in turn, caused reactor power fluctuations. The OPRM CDA detected these power oscillations and tripped the reactor.

ECP BFN-20-1688-04 was installed to re-configure the redundant LVDTs to a three-wire configuration during the Unit 1 Forced Outage (F110) to match the original LVDTs [Interim Action (INTR) 1857715-003]. This resolved issues with position indication discrepancies between the two different styles of LVDTs despite internal wiring errors and restored the sensed position to the tuned condition. Additionally, 1-SR-3.3.1.1.8(9), Turbine Control Valve Fast Closure or Turbine Trip and RPT Initiate Logic, was revised to change the maximum power level to perform testing from 84 percent to 72 percent to ensure no TCV oscillations would occur during testing [INTR / Procedure Change Request (PCR) 1857840-001].

The OPRM system has four (4) channels, each channel consisting of 33 core cells for monitoring



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

| | | | | | |
|--|---|-------------------------------|---------------|-------------------|---------|
| 1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 1 | <input checked="" type="checkbox"/> 050 | 2. DOCKET NUMBER 00259 | 3. LER NUMBER | | |
| | <input type="checkbox"/> 052 | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| | | | 2023 | - 002 | - 00 |

NARRATIVE

core thermal-hydraulic instabilities. Thermal-hydraulic core instabilities can exist during periods of high power with low core flow. OPRMs provide indications and alarms at low levels of thermal-hydraulic instabilities and an automatic reactor scram function trip at higher levels of thermal-hydraulic instability.

Oscillations are detected using any one of four algorithms, Confirmation Density Algorithm (CDA), Period-Based Algorithm (PBA), Growth-Rate Based Algorithm (GRBA), and Amplitude-Based Algorithm (ABA). The CDA trip is the licensed algorithm for Detect and Suppress Solution – Confirmation Density (DSS-CD). The CDA is designed to detect oscillations when they begin and generate a trip signal earlier than the other algorithms. The OPRM CDA trip is enabled when reactor power is >23 percent RTP and recirc flow is <75 percent of rated flow (Unit 1<90 percent).

The CDA Amplitude Discriminator Setpoint of 1.10 is just above noise level. The system prevents invalid scrams by requiring five (5) cells to confirm the oscillation. A true oscillation will affect many cells. CDA counts oscillations with a period of 1.2 to 4 seconds and looks for a value exceeding the setpoint of 1.10. The OPRM output for a reactor scram requires two CDA trips or two Defense in Depth Algorithm (DIDA) trips. PBA, GRBA, and ABA are grouped together as DIDAs, and provide a backup to CDA, but are not required by Technical Specifications.

Following the Unit 1 scram on May 20, 2023, an evaluation for thermal hydraulic stability was conducted by GEH. GEH stated the OPRM trip was not due to a Thermal Hydraulic Instability (THI) event but from TCV oscillations that fell within the frequency range of the CDA algorithm for the OPRM trip signal. The results revealed that the plant was inherently stable from a thermal hydraulic instability perspective. The CDA trip of the Unit 1 OPRM system was initiated by power changes driven by control valve oscillations experienced during the performance of 1-SR-3.3.1.1.8(9), Turbine Control Valve Fast Closure or Turbine Trip and RPT Initiate Logic (DC).

V. Assessment of Safety Consequences

Defense-in-depth to Nuclear Safety was not compromised by this event. The RPS system worked as designed to automatically shut down the reactor once the CDA trip setpoint was exceeded on the OPRMs. No loss of safety function occurred, nor were there any equipment failures as a result of the event.

This event did not reduce Defense-in-Depth to Industrial, Radiological, or Environmental safety. There were no new radioactive effluent pathways, nor were any new Radiation, Airborne, or Contamination Areas created. There was no release, nor potential to release, unmonitored gasses or liquids to the environment in excess of established limits of reportability.



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

| | | | | | |
|--|---|-------------------------------|---------------|-------------------|---------|
| 1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 1 | <input checked="" type="checkbox"/> 050 | 2. DOCKET NUMBER 00259 | 3. LER NUMBER | | |
| | <input type="checkbox"/> 052 | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| | | | 2023 | - 002 | - 00 |

NARRATIVE

VI. Corrective Actions

Corrective Actions are being managed by the TVA's corrective action program under Condition Report (CR) 1857715.

A. Immediate Corrective Actions

The Immediate Corrective Actions for this event were:

- A three-wire modification (ECP BFN-20-1688-04) was implemented during F110 to resolve issues with position indication discrepancies between the two different style LVDTs.
- The TCV LVDTs were calibrated during hot conditions during F110 to ensure accuracy.
- 1-SR-3.3.1.1.8(9), Turbine Control Valve Fast Closure or Turbine Trip and RPT Initiate Logic, was revised to change the maximum power level to perform testing from 84 percent to 72 percent to ensure no TCV oscillations would occur during testing.
- Extent of condition actions were taken to determine the appropriate power level to perform control valve testing for Unit 2 on June 3, 2023. The U3 LVDT mod is scheduled for March 2024.

B. Corrective Actions to Prevent Recurrence or to reduce the probability of similar events occurring in the future

Six (6) Corrective Actions to Prevent Recurrence were generated for this event:

- Revise 1-SR-3.3.1.1.8(9), Turbine Control Valve Fast Closure or Turbine Trip and RPT Initiate Logic, to specify the appropriate power level and associated valve position for performing the test to ensure no control valve oscillations [based on Engineering Work Request (EWR) completed in CR action 1857715-013] and outside of the OPRM trip enabled region if required.
- Revise 2-SR-3.3.1.1.8(9), Turbine Control Valve Fast Closure or Turbine Trip and RPT Initiate Logic, to specify the appropriate power level and associated valve position for performing the test to ensure no control valve oscillations (based on EWR completed in action 1857715-013) and outside of the OPRM trip enabled region if required.
- Revise 3-SR-3.3.1.1.8(9), Turbine Control Valve Fast Closure or Turbine Trip and RPT Initiate Logic, to specify the appropriate power level and associated valve position for performing the test to ensure no control valve oscillations (based on EWR completed in action 1857715-013) and outside of the OPRM trip enabled region if required.
- Revise 0-TI-464, Reactivity Control Plan Development and Implementation, to increase awareness of entry into the OPRM trip enabled region due to the risk of spurious scrams from the CDA instability detection method.
- Revise Design Criteria BFN-50-7047 – Turbine Electro Hydraulic Control System (EHC) systems to add details with regards to interrelationship between EHC and



**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

| | | | | | |
|--|---|-------------------------------|---------------|-------------------|---------|
| 1. FACILITY NAME Browns Ferry Nuclear Plant, Unit 1 | <input checked="" type="checkbox"/> 050 | 2. DOCKET NUMBER 00259 | 3. LER NUMBER | | |
| | <input type="checkbox"/> 052 | | YEAR | SEQUENTIAL NUMBER | REV NO. |
| | | | 2023 | - 002 | - 00 |

NARRATIVE

OPRM. Details should include a precaution that incorporates changes to the turbine control EHC system (including testing methodologies) could cause periodic perturbations. These periodic perturbations can be introduced into the thermal-hydraulic behavior of the reactor system (e.g., from control system feedback, System gains including controller settings and mechanical components like the diode function generator or valve flow position, deviation of process monitoring such as pressure or signals between two LVDTs). These changes can impact delay or combined control and mechanical gains to create perturbations that can potentially drive prolonged neutron flux oscillations within a frequency range expected for reactor instability. The presence of these oscillations is recognized by the CDA as reactor instability, independent of the actual stability of the reactor.

- Revise Design Criteria BFN-50-7092 - Neutron Monitoring Systems to add details on OPRM Algorithms. Details should include different types of OPRM Trip Algorithms: a) CDA, b) PBA, c) GRBA, and d) ABA and an explanation about each. It should also include guidance on the sensitivities of CDA trip, GEH information about susceptibility to spurious scrams, and discussion about changes to Turbine Control EHC can impact OPRM Trip Algorithms.

VII. Previous Similar Events at the Same Site

The BFN Unit 1 OPRM scram is not considered to be a Repeat Event or Operating Experience (OE) Preventable. The CDA trip was added to the OPRM system with the implementation of Maximum Extended Load Line Limit Analysis Plus (MELLLA+) in 2018. Since its implementation, this is the first time BFN has received the OPRM CDA trip, which resulted in an automatic reactor scram. A search of LERs from BFN Units 1, 2, and 3 over the last five years identified no similar events.

A review of OE and IRIS reports associated with MELLLA+, CDA, EHC Systems, and LVDTs did not identify any that would have prevented or mitigated the event, as the CDA trip is relatively new to the industry with no known previous SCRAMs.

All plants in the industry that have implemented MELLLA+ (and therefore CDA logic) were benchmarked and determined that none have restrictions on performing either TCV or Scram Time Testing inside the OPRM trip enabled region.

VIII. Additional Information

There is no additional information.

IX. Commitments

There are no new commitments.